



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Washington, D.C. 20240

<http://www.blm.gov>

JUN - 3 2011

The Honorable Edward J. Markey  
Committee on Natural Resources  
House of Representatives  
Washington, DC 20515

Dear Representative Markey:


Thank you for your February 28, 2011, letter to Secretary of the Interior Ken Salazar regarding hydraulic fracturing and other issues relating to oil and natural gas development. Secretary Salazar asked me to respond to your letter. I appreciate your concerns regarding environmentally responsible energy development on the public lands.

Enclosed are answers to your questions. Please note that, based on follow-up meetings and discussions among staff of the Committee, the Department, and the Bureau of Land Management, additional information will be provided under separate cover.

Specifically, in addition to this response, the Department will deliver a second document containing answers to questions 2d and 4 for which we requested more time in order to compile information held by multiple Department of the Interior bureaus. Finally, a third document will contain our responses to questions 8, 11, and 13.

Please do not hesitate to contact me at 202-208-3801 if you need additional information, or your staff may contact Patrick Wilkinson, BLM Division Chief of Legislative Affairs, at 202-912-7421. A similar letter is being sent to Representative Holt.

Sincerely,

  
Robert V. Abbey  
Director

Enclosures

- 1. How many acres of land does the Department of the Interior (DOI) manage for the purposes of fossil fuel development? What percentage of this land is currently used for natural gas development? What percentage is currently used for oil production? How much of this land could be expected to be tapped for oil and gas development in the next 10 years?*

**Answer:** Within the DOI, the Bureau of Land Management (BLM) is responsible for the management of 700 million acres of Federal onshore mineral estate. The BLM has leased approximately 42 million acres for oil and gas development, essentially 6 percent of the entire Federal onshore mineral estate. Of these 42 million acres, about 12.2 million acres are in production. Based on a trend in the data for the last 10 years, the BLM estimates that about 1 million additional acres will come into production during the next 10 years. The BLM issues leases for oil and gas together – these acreage amounts reflect both oil and natural gas activity as they are not tracked separately and are often produced from the same lease.

- 2. What percentage of U.S. undiscovered, technically recoverable oil and gas resources are located on federal lands?*

**Answer (2a):** Section 604 of the Energy Policy and Conservation Act (EPCA) of 2000, as amended by Section 364 of the Energy Policy Act of 2005, required an inventory of all onshore Federal lands to identify estimates of the oil and gas resources underlying these lands; and the extent and nature of any restrictions or impediments to the development of the resources. These reports, released in three phases (most recently in 2008), are known as the EPCA Reports. The BLM led the interagency effort to complete these reports.

According to the EPCA Phase III Report, 34 percent of the technically recoverable oil resources within the United States are on Federal lands, and 35 percent of the technically recoverable natural gas resources within the United States are on Federal lands. These percentages do not include offshore resources.

*How much oil and gas is estimated to be present in these areas?*

**Answer (2b):** According to the EPCA Phase III Report, there are an estimated 30.6 billion barrels of oil and 231.0 trillion cubic feet of natural gas that are technically recoverable in the Federal onshore mineral estate.

*Based on current projections of natural gas prices, how much of this gas is believed to be economically recoverable?*

**Answer (2c):** The U.S. Geological Survey (USGS) assesses undiscovered technically recoverable resources in the U.S. and worldwide. The USGS does not factor economic considerations, only technical and geologic considerations. The exception to this is in the North Slope of Alaska, where the Federal Government is the dominant owner of land and mineral rights. The USGS does not assess economics in the lower 48 states because

industry activity by its nature indicates economic recoverability. There is extensive and diverse industry infrastructure to facilitate this. Such data are generally reported under certain SEC regulations. The USGS does collect technical data from industry to perform its assessments, but "proven reserve" data is not normally required, solicited, or volunteered.

*Please provide documentation that indicates the location of deposits on federal lands, the type of gas or oil formation, the quantity of estimated oil or gas, and whether the deposit is located in, near of below an underground source of drinking water (as defined in the Safe Drinking Water Act).*

Answer (2d): The DOI will address this portion of the question under a separate cover.

*Also, please indicate whether the locations of these deposits are in protected or other areas that are unavailable for energy development by law or regulation.*

Answer (2e): The table below taken from the EPCA Phase III Report provides a more specific response. The EPCA Report provides percentage and acreage totals of Federal lands that are unavailable for oil and gas development or have other surface use restrictions on oil and gas development. The individual sections of the EPCA Report discuss the particular conditions on development on a basin-by-basin basis.

Access Category	Area		Resources*				
	(acres x 1000)	Percent of Federal	Total Oil <sup>b</sup>		Total Gas <sup>c</sup>		
			(MMbbls) <sup>d</sup>	Percent of Federal	(BCF) <sup>e</sup>	Percent of Federal	
More Constrained	1. No Leasing (Statutory/Executive Order) (NLS)	39,945	14.3%	9,054	29.7%	19,449	8.4%
	2. No Leasing (Administrative) (NLA)	50,414	18.1%	2,461	8.1%	16,618	7.2%
	3. No Leasing (Administrative) Pending Land Use Planning or NEPA Compliance (NLA/LUP)	55,278	19.8%	6,684	21.9%	49,814	21.6%
	4. Leasing, No Surface Occupancy (NSO) (Net NSO for D&G Resources)	20,245	7.3%	777	2.5%	8,621	3.7%
	5. Leasing, Cumulative Timing Limitations (TLs) of >9 Months	283	0.1%	32	0.1%	430	0.2%
	6. Leasing, Cumulative Timing Limitations (TLs) of >6 to ≤9 Months	11,883	4.3%	5,198	17.0%	40,021	17.3%
	7. Leasing, Cumulative Timing Limitations (TLs) of >3 to ≤6 Months	18,389	6.6%	1,799	5.9%	35,751	15.5%
	8. Leasing, Controlled Surface Use (CSU) <sup>f</sup>	34,631	12.4%	2,231	7.3%	36,716	15.9%
	9. Leasing, Standard Lease Terms (SLTs)	47,972	17.2%	2,268	7.5%	23,554	10.2%
<b>Total, Federal Lands Including Split Estate</b>		<b>279,039</b>	<b>100%</b>	<b>30,503</b>	<b>100%</b>	<b>230,975</b>	<b>100%</b>
<b>Total Non-Federal</b>		<b>936,414</b>		<b>58,056</b>		<b>423,282</b>	
<b>Total Inventory Area</b>		<b>1,215,453</b>		<b>88,560</b>		<b>654,256</b>	
<b>Summary</b>							
Inaccessible (Categories 1-4)		165,882	60%	18,976	62%	94,502	41%
Accessible with Restrictions (Categories 5-8)		65,186	23%	9,260	30%	112,919	49%
Accessible under Standard Lease Terms (Category 9)		47,972	17%	2,268	8%	23,554	10%
<b>Total, Federal Lands Including Split Estate</b>		<b>279,039</b>	<b>100%</b>	<b>30,503</b>	<b>100%</b>	<b>230,975</b>	<b>100%</b>

3. *Which oil and gas production companies currently have leases to drill on public lands? Out of these companies, which, if any, have been cited for safety or drilling violations on federal lands? Please provide a list that contains the leaseholders in each State, and whether each leaseholder has been cited by the Department for any such violations (and if so, the nature of the violation and the remedy therefore) in the past 10 years.*

Answer: Attachment 1 contains a listing of all companies that currently hold a Federal oil and gas lease. Attachment 2 contains a listing of oil and gas operators that have received an incident of noncompliance (INC) for safety or drilling reasons in the last 10 years and the nature of the INC.

4. *Of the wells located on public lands that are currently used for natural gas development, how many have been hydraulically fractured? Of these wells located on public lands currently used for oil development, how many have been hydraulically fractured? Please provide data indicating for each leased area in which hydraulic fracturing occurred whether fracturing occurred in, near or below an underground source of drinking water (as defined in the Safe Drinking Water Act).*

Answer: The DOI will address this portion of the question under a separate cover.

5. *Please describe the type of information that an oil and gas producer must provide to DOI prior to the approval of a federal land lease for oil or gas development.*

Answer (5a): Prior to receiving an approved competitive onshore Federal oil and gas lease, a potential lessee must:

- Provide a valid government-issued photo identification (ID) to verify identity.
- Sign a statement to confirm that any bid cast at the oil and gas lease sale will represent a good-faith intention to acquire an oil and gas lease and that any winning bid will constitute a legally binding commitment to accept the lease and pay monies owed.
- Sign a statement to acknowledge that the bidder understands that it is a crime under 18 U.S.C. § 1001 and 43 U.S.C. § 1212 to knowingly and willfully make any false, fictitious, or fraudulent statements or representations regarding qualifications; bidder registration and intent to bid; acceptance of a lease; or payment of monies owed; and that any such offense may result in a fine or imprisonment for not more than 5 years or both. The bidder must also sign a statement that the bidder understands that it is a crime under 30 U.S.C. § 195 (a) and (b) to organize or participate in any scheme to defeat provisions of the mineral leasing regulations. Any person who knowingly violates this provision will be punished by a fine of not more than \$500,000, imprisonment for not more than 5 years, or both.

- The successful bidder must provide a properly completed and signed competitive bid form (Form 3000-2, January 2007) with the required payment. This form is a legally binding offer by the prospective lessee to accept a lease and all its terms and conditions. The completed bid form certifies that:
  - (1) The prospective lessee is qualified to hold an oil and gas lease under BLM regulations at 43 CFR 3102.5-2; and
  - (2) The prospective lessee has complied with 18 U.S.C. § 1860, a law that prohibits unlawful combinations, intimidation of, and collusion among bidders.

*As a part of the leasing and permitting process, does DOI perform an environmental analysis for each individual drilling plan? If yes, please describe what factors are considered and what process is followed during the environmental analysis. If not, why not?*

Answer (5b): The BLM analyzes oil and gas leasing through the National Environmental Policy Act (NEPA) Environmental Impact Statement/Record of Decision (EIS/ROD) process conducted for development of a Resource Management Plan (RMP). On May 17, 2010, the BLM issued a Leasing Reform policy outlining a process for conducting supplemental Environmental Assessment (EA) analysis of individual parcels proposed for lease. The BLM uses an Interdisciplinary Review Team made up of specialists from different resource programs when analyzing a proposed parcel for lease. All NEPA documents for leasing have a 30-day public comment period.

Once the lease is issued and a lessee proposes to drill a well, the BLM conducts a site-specific environmental analysis based on the oil and gas operator's proposal(s) for drilling and producing one or more wells. The operator's proposal is outlined in the Application for Permit to Drill (APD) which contains a drilling plan and a surface use plan of operations in conformance with the requirements of Onshore Oil and Gas Order No. 1. The analysis can take the form of an EIS or EA and considers the operator's proposal(s), any reasonable alternatives, and the environmental effect(s) development may have on resource values. Where there is an existing EIS or EA that adequately addresses the site-specific impacts of the proposed project, such as a full field development EIS, the BLM may document its conclusion through a Categorical Exclusion (CX) or a Determination of NEPA Adequacy (DNA). The BLM uses an Interdisciplinary Review Team made up of specialists from different resource programs when analyzing a proposed project. Depending on the size of the project proposal, the BLM may also provide for a public comment period. The impacts assessed depend on the environmental resources present at the site that could be affected by the proposed action, such as, but not limited to, air quality, surface and groundwater quality and

quantity, wildlife, scenic resources, or recreation. When there are unresolved resource conflicts, the BLM will look at alternatives to the operator's proposal that may reduce environmental impacts. When analyzing development proposals, the BLM will typically identify and require additional environmental protection measures beyond those that the operator has proposed.

6. *How have environmental impact statements (EIS's) or environmental assessments (EA's) for hydraulic fracturing on public lands analyzed the potential environmental and public health risks associated with hydraulic fracturing? Have such EIS's or EA's evaluated the threat of radioactive or toxic materials being released into waterways that serve as sources of drinking water?*

**Answer (6a):** The BLM's analysis of environmental impacts and public health risks associated with oil and gas development takes into account effects that may occur during the construction, drilling, completion, production, and abandonment phase of an oil and gas well. Hydraulic fracturing is only one component of the completion phase of an oil and gas well.

When developing EISs and EAs, the BLM seeks input from the public as well as other government agencies with special expertise or regulatory jurisdiction over resources that may be impacted by oil and gas development. Under the Clean Water Act, the Environmental Protection Agency (EPA) or the state (where applicable) has special expertise as well as regulatory jurisdiction over U.S. waterways, including those that serve as drinking water sources. The BLM has not received any comments from these agencies regarding threats of radioactive or toxic materials being released into waterways that serve as sources of drinking water when preparing environmental documents.

As previously mentioned, the EPA or the state (where applicable) has primacy over water quality, which includes the discharge into water associated with hydraulic fracturing operations. As required by the Clean Water Act, discharges into waterways require prior approval from the EPA or the state (where applicable) through a National Pollutant Discharge Elimination System permit. To date, the BLM has not been notified of any concerns from these agencies regarding threats of radioactive or toxic materials being released into waterways that serve as sources of drinking water.

*Have they evaluated the threat associated with the release of toxics such as benzene or toluene into the air?*

**Answer (6b):** In many cases, the BLM uses models to analyze the potential effects oil and gas development will have on air quality. These models take into consideration the potential emission of hazardous air pollutants (HAP) associated with the development of oil and gas resources, which include benzene and toluene. However, the EPA or the state (where applicable) has primacy for regulating HAPs. The BLM has identified Best Management Practices (BMP) for reducing HAPs. Where there is a potential for violations of the Clean Air Act, the BLM coordinates with the applicable regulatory agency (EPA or the state) to ensure emissions are reduced.

*In light of the revelations in The New York Times article, do you believe such EIS's and EA's need to be updated or revised?*

Answer (6c): If there are situations on BLM-managed public lands where toxic chemicals and radioactive fluids associated with hydraulic fracturing operations are discharged into waterways, the BLM will coordinate with the applicable regulatory agency (EPA or the state) to resolve the noncompliance issue.

7. *It is our understanding that the DOI is considering mandating disclosure of chemicals used in fracturing fluids. We commend the DOI for considering this important step in ensuring public confidence in this technique, since many concerns about hydraulic fracturing center on the potential public health impacts of fracturing fluids. Recently, we learned that several production companies have used diesel fluid as part of their fracturing process despite absence of the appropriate permits. Is DOI aware of any instances in which diesel fluid was used on federal lands as part of a hydraulic fracturing operation? If yes, please provide documentation about where the well was located and whether the well was in, near or below an underground source of drinking water (as defined in the Safe Drinking Water Act). Has DOI ever been requested to issue or issued a permit for the use of diesel in hydraulic fracturing fluids? If yes, please provide supporting documentation for each such permit.*

Answer: The BLM's current regulations do not require prior approval of routine fracturing procedures performed on public lands. Additionally, the BLM's regulations do not contain explicit provisions mandating an operator to disclose the constituents in hydraulic fracturing fluids used in wells on public lands. Information from the BLM field offices with oil and gas management responsibilities indicate that the BLM is only aware of two instances where diesel was used in the hydraulic fracturing fluid for a well on public lands. The first is a well in Wyoming's Rawlins Field Office area at T25N, R87W, Sec 1, NWNW. The BLM became aware of the use of diesel through conversations with the operator after the well was hydraulically fractured. The well was completed on May 1, 2008.

In 2001, a Notice of Intent Sundry was filed for the hydraulic fracture of the Beaver Creek well BCU 6S at T7N, R10W, Sec 34, NENW in Alaska. The proposed procedure that was submitted with the sundry stated that diesel was going to be used. The sundry was approved on March 5, 2001.

Attachment 3 contains the supporting documentation for the BCU 6S case.

8. *Please provide copies of all documents (including reports, emails, correspondence, memos, phone or meeting minutes or other materials, and including materials in the possession of all Departmental Bureaus and Offices) relating to any allegations submitted to or other information in the possession of the Department that the products used in hydraulic fracturing fluids on public lands have caused harm to human health or the environment.*

Answer: The DOI will address this portion of the question under a separate cover.

9. *In the wake of the deepwater Horizon catastrophe, the Bureau of Ocean Energy Management, Regulation and Enforcement (BOEMRE) launched aggressive and much needed reforms to enhance the safety of offshore oil and gas drilling operations. The new safety rules address the appropriate use of drilling fluids, well bore casing and cementing, well control equipment and procedures, and puts in place number of environmental safeguards. Do similar prescriptive and protective regulations exist for onshore drilling for oil and natural gas extraction on public lands, including extraction using hydraulic fracturing?*

Answer (9a): Yes. 43 CFR 3162.3-1 outlines what an operator is required to submit before any oil or gas well is drilled and 43 CFR 3162.3-2 gives the requirements for operations on an oil or gas well after it has been drilled. In addition to these regulations, the BLM's Onshore Oil and Gas Orders No. 1 and No. 2 give detailed guidance on what is required for an APD and what well control equipment the BLM requires, respectively.

Onshore Oil and Gas Order No. 1 requires the operator to submit detailed information on the drilling fluids to be used, design of all casing strings being proposed, cementing programs for each casing string, well control equipment to be used, and environmental safeguards being taken to protect surface resources as well as the down hole environment. All of this information is reviewed by BLM oil and gas resource specialists (including petroleum engineers, geologists, and natural resource specialists) to ensure the drilling program will adequately protect the environment, both on the surface and down hole, during drilling and production. The BLM requires all usable water zones to be isolated from the effects of drilling and production whenever they are found. The BLM's current regulations state that, unless additional surface disturbance is involved, prior approval of routine hydraulic fracturing operations is not required if the operations conform to the standard of prudent operating practice.

Onshore Oil and Gas Order No. 2 sets the minimum requirements for different pressure ratings of well control equipment, minimum casing string design factors, minimum standards for cementing of casing strings, drilling mud program minimum requirements, and the minimum requirements for the placing of cement plugs for the abandonment of a nonproductive well bore. The BLM uses these requirements during the review of an APD's drilling plan. The operator must commit to meeting the minimum standards for well control equipment, casing strings, cementing of casing strings, and the drilling mud program before the BLM will approve an APD.

During the fall of 2010, the BLM held refresher courses for all BLM petroleum engineers to ensure every APD is fully reviewed for drilling and environmental safety.

*Does DOI have plans to revise existing onshore regulations to provide for more rigorous minimum requirements for well design and construction, as well as for enhanced oversight and enforcement of these activities? If so, please provide a detailed schedule. If not, why not, and when were these regulations last revised?*

Answer (9b): The Federal onshore regulations and Onshore Oil and Gas Orders provide standards for the safe drilling and production of oil and gas. Specifically, Onshore Oil and Gas Orders No. 1 and No. 2 include minimum requirements for well design, construction, and well control. On March 7, 2007, the BLM updated Onshore Oil and Gas Order No. 1 to reflect current changes in laws, environmental requirements, and current policy.

The Secretary of the Interior held a forum on natural gas production and hydraulic fracturing on public lands on November 30, 2010, which helped initiate the public dialogue on this important issue. That dialogue and public engagement continues; the BLM held community forums on hydraulic fracturing in Bismarck, North Dakota, on April 20; Little Rock, Arkansas, on April 22; and Golden, Colorado, on April 25, 2011. The BLM is also monitoring changes to state laws and regulations regarding hydraulic fracturing.

10. *The New York Times recently reported that in Pennsylvania, response plans for drilling activities, which detail how a company would respond to an accident or spill, appear to be in violation of the law. In fact, in one well in Pennsylvania, Cabot Oil and Gas filed a spill response plan that states that a spill would not enter waterways, even though it subsequently experienced three spills, some of which did enter waterways. Even after these three spills, the company filed a revised spill response plan that still maintained that spills into nearby surface water are not likely. As we saw during the Deepwater Horizon incident, when companies fail to anticipate or prepare for a realistic worst case accident, there can be devastating impacts on the environment and the economy. Does DOI review spill response plans for every drilling permit on federal lands? If not, why not? Has DOI ever found a spill response to be inadequate for the type of drilling project? If so, for each such instance, please provide documentation that details the problems. How does DOI evaluate response plans to ensure that companies are taking into consideration site specific risks such as possibility of a spill to enter a waterway?*

Answer: The BLM does not review or approve spill response plans. In accordance with Title 40 CFR 112, the EPA is the agency with authority and responsibility for reviewing and approving Spill Prevention, Control, and Countermeasure Plans developed by operators. These plans identify procedures operators will implement to prevent, control, and respond to spills, including proper agency (i.e., U.S. EPA) notification. However, the BLM does have the authority to require copies of the plan so that it is aware of the

operator's plan in the event of a spill, and who within the company has authority to expend funds to prevent, control, and perform cleanup operations.

For purposes of ensuring conservation of Federal oil and gas resources and protection of public lands under BLM jurisdiction, operators are also required to report to the appropriate BLM field office spills that are attributed to operations on Federal and Indian lands, or state and fee lands within federally approved communitized areas. If these spills affect surface waterways regulated by other agencies, such as the EPA or the state, the BLM would notify the appropriate agency to ensure the operator responds to the spill accordingly.

Also, through the APD review process, the BLM ensures the operator takes actions necessary to minimize the risk of spills entering waterways. This includes, but is not limited to, not allowing drilling activities to take place in close proximity to waterways, installing properly sized containment dikes around tank facilities, and requiring pits to be properly engineered and constructed in a manner that would reduce the risk of containment failure. The BLM also inspects facilities to ensure all operations are conducted as approved and facilities are maintained in a prudent manner. If conditions are unacceptable, the BLM will direct the operator to resolve the issue and may issue an INC to ensure compliance.

11. *The New York Times also reported that certain drilling sites in Wyoming failed to meet air quality standards due in part to emissions from drilling activities that contribute to higher ozone levels. Does the DOI monitor or analyze air pollution impacts associated with natural gas drilling activities on federal lands? If yes, please provide all documents that are related this analysis. If not, why not? Does DOI monitor for fugitive methane emissions from hydraulic fracturing activities? If yes, please provide relevant documentation. If not, why not?*

Answer: The DOI will address this question under a separate cover.

12. *The proper handling and disposal of used hydraulic fracturing fluids and wastewater is also important for minimizing threats to water supplies. Is DOI contemplating the development of rules or best management practices for the handling, disposal and recycling of hydraulic fracturing fluids and wastewater? If so, please provide a detailed schedule and description of activities DOI is undertaking in this area. If not, why not?*

Answer (12a): The BLM held community forums on hydraulic fracturing in Bismarck, ND on April 20, Little Rock, AR on April 22, and Golden, CO on April 25, 2011. The comments gathered at these forums are an important component to the Department's and the BLM's continued public engagement on this issue.

*What actions has DOI taken to ensure that radioactive wastewater is not discharged into U.S. waterways? Please provide documents related to monitoring activities or any reports of discharges of radium or any other toxic substance typically found in wastewater from hydraulic fracturing operations.*

Answer (12b): During the development of Federal or Indian oil and gas resources, which includes the drilling, completion (i.e., hydraulic fracturing), production, and abandonment of a well, the BLM requires operators to comply with its regulations as well as all other applicable laws and regulations that pertain to waste disposal. This includes compliance with Onshore Oil and Gas Order 4 addressing disposal of produced water. The disposal of water associated with the hydraulic fracturing operations into waterways is an activity regulated by the U.S. EPA or the state (where it has primacy). If there are situations on public lands managed by the BLM where fluids associated with hydraulic fracturing operations are radioactive or toxic and are being discharged into waterways, the BLM will coordinate with the applicable regulatory agency (EPA or the state) to ensure the operator responds to the spill accordingly.

13. *Please provide copies of all documents (including reports, emails, correspondence, memos, phone or meeting minutes or other materials, and including materials in the possession of all Departmental Bureaus and Offices) relating to:*

- a. *The presence of naturally occurring radioactive materials in drilling wastes;*
- b. *Earthquakes or other seismic events caused or thought to be caused by oil or gas drilling activities, including hydraulic fracturing;*
- c. *The migration of natural gas or the substances used in hydraulic fracturing beyond the shale formations that are the target of the fracturing activities.*
- d. *Correspondence between the Department and representatives of the natural gas industry (since January 1, 2010).*

Answer: The DOI will address this question under a separate cover.

Current BLM Oil and Gas Lessees:

R M RESOURCES INC	A & B INTERESTS LLC
#13 ENTERPRISES LLC	A & M OIL CO
1031 INC	A & R ROYALTIES INC
123 TEC LP	A & W CO INC
12TH STREET APARTMENT	A B PRODUCTION CO
18-31 INC	A E P
1987 VI-STEAM LTD PRT	A G & RKPLS RES INC
1987-I STEAM LTD PTNR	A G HILL PTNRSHP
1987-I STEAM LTD PTRS	A J OIL CO
1987-VI STEAM LTD PTN	A R DILLARD JR TRST
1995 INCOME PROG LLC	A S HORNER CONSTR CO
1995 INCOME PROG LTD LIAB CO	AA DEV CORP
1996 MURDOCK	AABY JAMES V
1996 MURDOCK HACK	AAMOT ARTHUR EST
1997 JOHN P ALBANESE LVNG TRST	AAMOTH HILMER S
1ST NATL BANK TRST	AARACO EXPLORATION INC
1ST NATL BK DENVER	AARDVARK OIL CO
1ST NATL BK OF CHICAGO	AARON EQUITY & RESOURCE
1ST SEC BANK & TRUST	AARON JO ANN
2005 LUFT FAMILY REVOC TRST	AARON JOHN LESLIE
219 CORP	AARON TODD
25 HILL PROPERTIES INC	AARON WESLEY B
375 ENERGY INC	AARVAK SVCS INC
3-D EXPLORATION PARTNERS	AB PROD CO
3-M ENERGY CO	AB PRODUCTION CO
3MB OIL & GAS LLC	AB RESOURCES OH LLC
3RS-LLC	ABARTA OIL AND GAS CO INC
3TEC ENERGY CORP	ABBY CORP
4 D ENERGY INC	ABERCROMBIE ENERGY
4-W PETROLEUM INC	ABERCROMBIE JOHN L
5 STATES 1997-A LTD	ABERNATHY EVA F
53 HYDE PARK	ABERNATHY LOA
53 HYDE PARK LLC	ABERNATHY W MARCUS
550 11TH AVENUE INC	ABO PETRO CORP
5B OG CO INC	ABO PETROLEUM CORP
5-B OG CO INC	ABOCO INVESTMENTS LLC
7 O'S OIL CORP	ABOGADO PETRO INC
7777 DRLG CORP	ABRAMS ALVIN
8 WAY OG INC	ABRAMS ESTELLE
801 LLC	ABRAXAS OPER LLC
820MT OG NM LLC	ABRAXAS OPERATING LLC
8600 VENTURE PROP	ABRAXAS PETRO CORP
9600 VENTURE PROP	ABRAXAS PETROLEUM CORP
99 OIL & GAS LLC	ABRIGO OIL CO
99 OPERATING LLC	ABRON PROD CO

Current BLM Oil and Gas Lessees:

ABRONS RICHARD	ADAMS SUSAN
ABS ENERGY	ADAMS THOMAS T
ABSHIER WAYNE	ADAMSON DWIGHT
ACCESS RES INC	ADAMSON JAMES D
ACCORD RESOURCES LTD	ADAMSON JOHN D
ACE CO	ADCO PROD CO INC
ACE CO III	ADDISON OIL LLC
ACE CO IV	ADELANTE BARNES TRUST
ACE PROD CO	ADELANTE O&G LLC
ACE V	ADELANTE OIL & GAS
ACF HOLDING LLC	ADEX RESOURCES CORP
ACF PETROLEUM CO INC	ADKINS GERALD
ACF PETROLEUM INC	ADKINS MARGARET
ACHEN JOHN	ADOBE OILFIELD SERVICES
ACHEN OIL & GAS INC	ADOBE RESOURCES CORP
ACHEN SANDERS	ADVANTAGE RES INC
ACHEN THOMAS H	ADVANTAGE RESOURCES
ACHEN-THROWER GAY	ADVENTURE EXPL PARTNERS LLC
ACKAT LLC	AE INVESTMENTS INC
ACKERMAN ALAN R	AE INVST INC
ACKERMAN R J	AE INVSTMNT INC
ACKMAN EDWARD J	AEJH '87 LTD PTNRSHP
ACKMAN OIL PROPERTIES LLC	AENEAS ENERGY CORP
ACME LAND CO	AEP LIMITED PTNRSHP
ACORN RESOURCES INC	AERA ENERGY LLC
ACT OPERATING CO	AETNA PETRO CORP
ACTION ENERGY LP	AETNA PETROLEUM
ACTON ENE LP	AETNA PETROLEUM CORP
ACTS INC	AEXCO PETRO INC
A-D HOLDINGS LP	AEXCO PETROLEUM INC
ADA LND CO 1972-D	AF GILMORE CO
ADA LND CO 1973-A	AFTAG INC
ADA LND CO 1973-B	AG ANDRIKOPOLOS
ADAMS BESS L	AG ANDRIKOPOULOS RES
ADAMS CAROLYN B	AG ANDRIKOPOULOS RES INC
ADAMS CHARLES W	AGK ENERGY LLC
ADAMS FAMILY TRUST	AGNES OIL LLC
ADAMS H D	AGS O&G HOLDINGS INC
ADAMS HELEN B	AGS OG 2005 LLLP
ADAMS JONYE C	AGS OG HOLDINGS #2 INC
ADAMS K S JR	AGS OG HOLDINGS INC
ADAMS LA OIL AND GAS PROP LLC	AGS OG VENTURES INC
ADAMS LEWIS F TRST	AGS OIL & GAS HOLDINGS #2 INC
ADAMS OIL & GAS	AGS RESOURCES 2007 LLLP
ADAMS RESOURCES & ENERGY	AGUA SUCIA LLC
ADAMS RESOURCES EXP CORP	AH 1980 PROGRAM INC

Current BLM Oil and Gas Lessees:

AHB BILL C BURNS TR	ALEXANDER JOHN
AHLEN JACK	ALEXANDER KEITH JR
AHMAD GHULAM	ALEXANDER RES INC
AHS LLC	ALEXANDER RESOURCES INC
AIDES HARRY A	ALEXANDER ROBERT L
AIKMAN BROTHERS	ALFORD JAMES L JR
AIKMAN OIL & GAS CO	ALFREDO DORETA T
AIN JOHN	ALFSON ENERGY LAND SVCS INC
AITKEN L L	ALI ERAM
AIX ENERGY INC	ALI ERAM
AJAX IS PETRO INC	ALINDA HILL HUNT TR
AJAX ISLAND PETRO	ALISTAR CORP
AJAX OIL CO	ALKER EXPLORATION LLC
AJM LLC	ALKER HENRY A
AKANE SHELBY L	ALL ABOARD DEV CORP
AKRE CHEERI	ALL ENERGY INC
AL & BB OWEN TRST	ALLEN & ALLEN RESOURCES LTD
AL ABERCROMBIE TTEE	ALLEN & KIRMSE LTD
ALAMEDA ENE INC	ALLEN ANGELA K
ALAMO PRTNRS	ALLEN B W
ALAMO PTNRS	ALLEN CO INC
ALAMO RESOURCES II LLC	ALLEN DEBRA G
ALAN WAXMAN LLC 1	ALLEN E E
ALAN WAXMAN LLC 2	ALLEN JAMES L
ALARADO RESOURCES	ALLEN JERRY L
ALASCO OIL & GAS INC	ALLEN MAX D
ALASKAN OFFSHORE PET	ALLEN O&G TRST
ALBANESE EVELYN G	ALLEN OIL CO INC
ALBANESE JOHN P	ALLEN ROBERT W
ALBANO LOUISE S	ALLEN TRAVIS
ALBERDING CHARLES H	ALLIANCE INCOME FUND
ALBERT HILL TRST	ALLIANCE WELL SERVICE
ALBERT JACK H	ALLIE KAT LLC
ALBERTA GAS CO	ALLIED CHEMICAL CORP
ALBO INC	ALLIED OIL & GAS CO
ALBRACHT WILLIAM	ALLISON ANN D
ALBRIGHT CHARLES C	ALLISON BROS DRLG
ALBRIGHT O D III	ALLISON FRED M
ALBRITTON BRINT	ALLISON FRED M III
ALBUS JOSEPH	ALLRED ARAL W
ALCO PETROLEUM INC	ALLRED S ELAINE
ALDRIDGE OPERATING CO LLC	ALLRED WILLIAM WALLA
ALERION GAS SA LLC	ALLSPAUGH ROGER J
ALEXANDER & NORMA NASH TRUST	ALMAC HOLDINGS LLC
ALEXANDER BEN B	ALMON GEORGE DANIEL
ALEXANDER DON D	ALMOND ENERGY LLC

Current BLM Oil and Gas Lessees:

ALPAR RESOURCES INC	AMELUNXEN C
ALPHA DEV CORP	AMELUNXEN CAROLINA
ALPHA EXPL INC	AMELUNXEN ROBERT B
ALPHA PETRO EXPL CORP	AMER BANNER RES INC
ALPINE GAS INVESTORS LP	AMER ENERGIES CORP
ALPINE KING INC	AMER ENRG INDP ROY II LLC
ALPINE OIL CO	AMER EXPL DRILL PRGM 1974 SPEC
ALPINE RESOURCES LLC	AMER EXPL DRILL PRGM 1974-1
ALTA ENERGY CORP	AMER EXPL DRLG
ALTAMONT OG INC	AMER HAWAIIAN PETRO CO
ALTEX ENE CORP	AMER HUNTER EXPL LTD
ALTEX INC	AMER INS & INVST CORP
ALTEX OIL CORP	AMER JULES DR
ALTHEIRS OIL INC	AMER NAT PETRO CO
ALTMAN CHILDREN TRST	AMER NATL PETRO CO
ALTMAN RONNY G	AMER OG CORP
ALTON CLARK ESTATE	AMER OG INC
ALTON HOWARD SR	AMER PENN ENE INC
ALTROGGE R C	AMER PENN ENERGY INC
ALTURA ENERGY LTD	AMER PROD PTNRSHP
ALTUS EXPL CO	AMER PROD PTNRSHP VII
ALUMINUM FLOW LINES INC	AMER PROD PTNRSHP IV
ALVIN M IVERSON JR TRUST	AMER PROD PTNRSHP VI
ALVRONE SATER TRUST	AMER PROD PTNRSHP-V LTD
ALWEIS ELLEN	AMER STATES PROD INC
ALWEIS JODY	AMER TRADING & PROD
AM PROD PTNRSHP III	AMER WARRIOR INC
AM PROD PTNRSHP IV	AMERADA HESS CORP
AMADEUS PETRO INC	AMERADA PETRO CO
AMALGAMATED EXPL INC	AMERCN ENGRY INDPDNC ROY II LL
AMANDA JANE KELLING TRUST NO 1	AMERCN ENGRY INDPDNC ROY LLC
AMANDA JANE PARTNERS LP	AMERICA WEST OIL & GAS CORP
AMARICEN G P	AMERICAN AIRLINES
AMARICEN HOLDINGS LP	AMERICAN EXPL ACQ CO
AMAX OIL & GAS INC	AMERICAN INLAND RES CO LLC
AMBASSADOR PETROLEUM INC	AMERICAN NATL PETRO
AMBER RICHARD D	AMERICAN OIL & GAS CORP
AMBLER ALAN C	AMERICAN OIL & GAS INC
AMBRA OIL & GAS CO	AMERICAN OIL & GAS LLC
AMBRIT ENERGY CORP	AMERICAN PETROEL INC
AMBROSE JOHN P JR	AMERICAN WARRIOR INC
AMCO INC	AMERICAN WEST GAS 93
AMCON RESOURCES INC	AMERICAN WEST OG CORP
AME LTD	AMERICANA EXPL LLC
AME PRODUCTION CO	AMERICO OIL & GAS PROD CO LTD
AMELL ARTHUR W	AMERIND OIL CO LTD

Current BLM Oil and Gas Lessees:

AMERISTATE EXPL LLC	ANDERSON ADA A
AMERISTATE EXPLORATION	ANDERSON ANNA R
AMERITRUST TX NATL	ANDERSON ARDEN A
AMETEX CORP	ANDERSON BRUCE
AMINOIL INC	ANDERSON BRUCE EST
AMITY OIL CO INC	ANDERSON BRUCE O
AMKAN ACQUISITION	ANDERSON CAROL
AMOCO PETROLEUM CO	ANDERSON CURTIS A
AMOCO PRODUCTION CO	ANDERSON DONALD B
AMODEI RUTH SNYDE	ANDERSON E T III
AMOVEN OIL CO INC	ANDERSON EXPL CO
AMOY MINERALS CORP	ANDERSON G W
AMPOLEX (USA)	ANDERSON GEORGE S
AMPOLEX TX INC	ANDERSON GLENN V
AMR ENERGY CORP	ANDERSON HAROLD H
AMSBARY GORDON K	ANDERSON J STEVE III
AMSBAUGH TED E	ANDERSON JAMES R
AMTEX ENERGY	ANDERSON JOHN OLIVER
AM-WEST PETROLEUM	ANDERSON JOHN R
AMWEST PETROLEUM INC	ANDERSON JOHN R EST
ANADARKO E&P CO LP	ANDERSON JOSEPH C
ANADARKO E & P COMPANY LP	ANDERSON KAREN
ANADARKO E&P CO LP	ANDERSON KATHERINE
ANADARKO E&P COMPANY LP	ANDERSON KENNETH D
ANADARKO EXPL & PROD CO LP	ANDERSON LAND LTD
ANADARKO MINERALS	ANDERSON M C
ANADARKO MINERALS INC	ANDERSON M H
ANADARKO MINES INC	ANDERSON MARTIN
ANADARKO PETRO CORP	ANDERSON MARY P EST
ANADARKO PETROLEUM CORP	ANDERSON MILTON B
ANADARKO PETROLEUM	ANDERSON OIL CO
CORPORATION	ANDERSON OIL CORP
ANADARKO PROD CORP	ANDERSON OIL LTD
ANBAY LTD	ANDERSON PAUL D
ANCHOR BAY CORP	ANDERSON PAYTON V
ANCHOR EXPL CO	ANDERSON PETER S
ANCHOR LAND & EXPL CO	ANDERSON PETRO INC
ANCHOR LAND AND EXPL CO	ANDERSON PHELPS
ANCHOR PRODUCTION LLC	ANDERSON ROBERT C
ANCON PTNRSHP LTD	ANDERSON ROBERT G
ANCON PTRSHP LTD	ANDERSON ROBERT M
ANDERMAN & CO	ANDERSON ROBERT W
ANDERMAN GEORGE G	ANDERSON STEPHEN H
ANDERMAN OIL CORP	ANDERSON THOMAS W
ANDERMAN OILS HLDGS INC	ANDERSON TRACY
ANDERMAN OILS UTAH	ANDERSON W D & SONS

Current BLM Oil and Gas Lessees:

ANDERSON W O	ANTELOPE RES INC
ANDERSON WARREN D	ANTERO RES CORP
ANDEX RESOURCES LLC	ANTERO RES PICEANCE CORP
ANDOVER OIL CO	ANTERO RESOURCES CORP
ANDRAU WILLIAM E	ANTERO RESOURCES II CORP
ANDRESEN JANE MILLS	ANTHONY ENERGY LTD
ANDRESS THURMON	ANTOCO INC
ANDREW & PAULETTE LASZIO TRUST	ANTWEIL MORRIS
ANDREWS & CORKRAN LLC	AOM GROUP INC
ANDREWS DAVID	APACE CORP
ANDREWS DAVID J	APACHE 1996 A TRUST
ANDREWS OIL LP	APACHE CORP
ANDRIKOPOULOS A G	APACHE PERMIAN EXPL & PROD LLC
ANDRIKOPOULOS AG RES	APAPAHOE GAS LTD
ANDRIKOPOULOS K C	APC OPER
ANDRIKOPOULOS RESOURCES	APC OPER PTNRSHP
ANERSON STEVE J III	APC OPTR PTNRSHP
ANGEL LLC	APD ENERGY CO LP
ANGERMAN ASSOC INC	APEX ENE LLC
ANGEVINE ROBERT	APEX ENERGY INC
ANGLE DON	APOLLO DRILLING & EXPL
ANGLE GLADYS	APOLLO ENERGY LLC
ANGUS PETRO CORP	APOLLO ENERGY LP
ANIMAS ENERGY LLC	APOLLO OPERATING LLC
ANIMAS PROPERTIES LLC	APOLLO SMITH EXPL
ANN B BEATTY TRST	APPLE CREEK LLC
ANN CARROL LIVING TRUST	APPLEGATE RALPH W JR
ANN L R ZELIGSON REV MGMT TRST	APPLING J B
ANN WALKER TRUST	APPLING JOHN B
ANNA A PROCTOR	AQUARIUS II INC
ANNE W PHILLIPS TR	AQUILA ENE RES CORP
ANOIL CO	AR & ARKLA EXPL
ANR PRODUCTION CO	ARAKAKI GENE Y
ANSCHUTZ CORP	ARAPAHO LAND CO
ANSCHUTZ EXPLORATION CORP	ARAPAHOE RES LLC
ANSCHUTZ PINEDALE CORP	ARAPAHOE RESOURCES LLC
ANSELMI JOHN M	ARBOR PETROLEUM CORP
AN-SON CORP	ARBUCKLE FLOYD S KAY
ANT HILL PROD CO	ARBUCKLE W CLIFTON
ANTARES EXPL FUND LP	ARBUCKLE WALTER K
ANTARES OIL CORP	ARCADIA EXPL & PROD CO
ANTELOPE BUTTE OG CO	ARCARO EDWARD
ANTELOPE COAL LLC	ARCH OIL & GAS CO
ANTELOPE ENERGY CO	ARCHER DAN E
ANTELOPE ENERGY CO LLC	ARCHER J D
ANTELOPE ENERGY COMPANY LLC	ARCHER JOHN D

Current BLM Oil and Gas Lessees:

ARCHER LEE C	ARMSTRONG ANNA C
ARCHER OPAL T	ARMSTRONG CORP
ARCHER REX D	ARMSTRONG DAVE
ARCHER SCOTT T	ARMSTRONG ENERGY CORP
ARCHIE E GROFF TRUST	ARMSTRONG ERVIN S
ARCO OIL & GAS CO	ARMSTRONG EUGENE M
ARCOTEX OIL & GAS INC	ARMSTRONG JAY K
ARD ENERGY GROUP LP	ARMSTRONG JERRY D
ARD JULIAN	ARMSTRONG M J
ARD MARY H	ARMSTRONG OG INC
ARD MARY HUDSON	ARMSTRONG OIL & GAS INC
ARD OIL LP	ARMSTRONG PHILLIP D
AREA PETROLEUM LLC	ARMSTRONG RESOURCES
ARENA RESOURCES INC	ARMSTRONG RESOURCES LLC
ARES PRODUCTION CO	ARMSTRONG REX H
ARES SAM D	ARMSTRONG ROBERT
ARGALI EXPL CO	ARMSTRONG STEVEN D
ARGENTIA CORP	ARMSTRONG WILLIAM D
ARGO ENERGY PARTNERSHIP LTD	ARMSTRONG WYOMING LLC
ARGONAUT OG CO	ARMSTRONG, LEILA
ARGONAUT OIL & GAS	ARNELL OIL CO
ARGUS OIL CO	ARNOLD ANTONETTE T
ARIES INVESTMENTS LLC	ARNOLD CLAUDE
ARIES OIL & GAS INC	ARNOLD CORP
ARIES RESOURCES	ARNOLD ISAAC JR
ARISTOTLE RESOURCES LLC	ARNOLD LARRY
ARK LAND CO	ARNOLD MARY JAYNE
ARKANSAS WESTERN GAS	ARNOLD OIL PROPERTIES INC
ARKLA ACQUISITION CO LLC	ARNOTT BERNARD
ARKLA EXPLORATION CO	ARNOTT JOHN EVERETT
ARKLAND INC	AROC (TEXAS) INC
ARKLAND PRODUCING CO INC	AROC ENERGY
ARK-LA-TEX PROPERTIES	AROC ENERGY LP
ARKOMA BASIN EXPL CO	AROC OIL & GAS LLC
ARKOMA HOLDING CORP	AROC TEXAS INC
ARKOMA PRODUCTION	ARRIBA CO LTD
ARKOMA PRODUCTION CO	ARRINGTON DAVID H
AR-LA GAS CO	ARRINGTON GEORGE W
ARLENE G ROSEN TRUST	ARRINGTON J H
ARLOMA CORP	ARRINGTON MARGARETA
ARM OPERATING LLC	ARRINGTON W H JR
ARMADA PROD CO	ARROW OIL & GAS INC
ARMAND G ERPF EST	ARROWHEAD ASSOC
ARMOR PETROLEUM INC	ARROWHEAD OIL CORP
ARMOR WILLIAM C JR	ARROWHEAD OPERATING INC
ARMOUR LOURANCE H JR	ARROWHEAD RES USA

Current BLM Oil and Gas Lessees:

ARROYO ODETTE M	ASSENT ENERGY LLC
ARSENAL ENE USA INC	ASTON BEAN AUDREY
ARTHAUD JAMES R	ASTON CHARLES A III
ARTHUR CAMERON TRUST	ASTON ENERGY INV LTD
ARTHUR HILL ESTATE	ASTON FAM LTD PTNRS
ARTHUR W WINTER TRST	ASTON FAMILY
ARTUS SHERWIN D	ASTON KOBAL VALERIE
ARTZIS ALVIN	ASTON LINCOLN
ARTZIS ALVIN TRUST	ASTON MARY E
ARVON I JOHNSON TR	ASTON PARTNERSHIP
ASAM FRANK J	ASTON PAUL ELLEN
ASH MINES & MINERALS INC	ASTON PAULL ELLEN
ASHBY DRILLING CORP	ASTON RALPH L
ASHBY WILLIAM H JR	ASTON ROBERT W
ASHDLA LLC	ASTON ROGERS
ASHER CHERYL K	ASTON WELDON
ASHER ENTERPRISES LTD CO	ATCHEE CBM LLC
ASHER OIL CO	ATCHLEY RESOURCES INC
ASHER RESOURCES	ATEC SAN JUAN BASIN
ASHLAND EXPL INC	ATER ROBERT F
ASHLAND OIL INC	ATHENA ENERGY INC
ASHLAWN ENERGY INC	ATHENA ENERGY LLC
ASHLEY JIM	ATHENS/ALPHA GAS CORP
ASHMORE DELBERT	ATKINSON J V
ASHTON RALPH	ATLANTA OIL COMPANY
ASHTON ROBERT W	ATLANTIC OIL CORP
ASHTON STUART L MRS	ATLANTIC RICHFIELD
ASHWORTH DAVID B	ATLANTIC RICHFIELD CO
ASHWORTH MICHAEL R	ATLANTIC RICHFIELD COMPANY
ASHWORTH PENNY	ATLER LAWRENCE A
ASHWORTH PETER P	ATOFINA PETROCHEMICALS INC
ASHWORTH STEPHEN S	ATOMIC OIL & GAS LLC
ASHWORTH TIMOTHY A	ATROPOS PRODUCTION CORP
ASHWORTH TIMOTHY TRUST	ATTWELL INTEREST INC
ASHY DOUGLAS E SR ET UX	ATTWELL CHARLES S
ASPECT ENERGY LLC	AUBOL HAZEL L
ASPECT RESOURCES LLC	AUDREY FOSTER TRST
ASPEN DISCOVERY LP	AUGUSTUS ENERGY PARTNERS LLC
ASPEN DRILLING	AULTMAN LESTER W
ASPEN ENRGY INC	AURORA OIL & GAS CORPORATION
ASPEN EXPL CORP	AUSTIN DRILLING 1978
ASPEN NATURAL GAS LLC	AUSTIN PROD CO INC
ASPEN OIL INC	AUSTIN ROBERT L
ASPEN OPERATING CO LLC	AUSTIN ROBERT S ET UX
ASPEN PUMPING	AUVENSHINE CATHIE
ASPEN RESOURCES CO	AUVENSHINE CHILDREN'S TRUST

Current BLM Oil and Gas Lessees:

AVALON CONSULTING INC	B G COCHENER TRST
AVALON ENERGY CORP	B J INVESTMENTS
AVEN GAS & OIL INC	B K PETROLEUM INC
AVERA, LANCE F	B KENNETH CARLYLE INC
AVERA, MARK A	B L OIL & GAS CO
AVERY EDWIN M	B O F B LTD
AVERY HERBERT R	B W PARTNERSHIP
AVERY ROSEMARY T	B&B OIL VENTURES INC
AVIEN CORP	B&B PROD CO
AVIS ENE CORP	B&B RESOURCES INC
AVIVA AMERICA INC	B&C OIL INC
AVIVA USA INC	B&J RES LLC
AXEL JOHNSON EXPL	B&N CO LP
AXEM ENERGY CO	B&P RES INC
AXIA ENERGY LLC	B&W EXPL INC
AXIS ENERGY CORP	B&W SOUTHERN PETROLEUM
AXKO INC	B/S PRODUCTION CO
AYCO ENERGY LLC	B2 ENERGY LLC
AZ OIL INC	BAALMAN LYNNE M
AZALEA OIL CO LLC	BAALMAN MARK E
AZIMUTH ENERGY LLC	BABE DEVELOPMENT CO INC
AZTEC ENERGY CORP	BABER GUY A
AZTEC GAS & OIL CORP	BABER SUZANNE L
AZTEC PRODUCING COMPANY	BABER WELL SERVICING
AZTEC WELL SERVICE CO INC	BABINGTON CHARLES J
AZTEC WELL SERVICING CO INC	BACHSCHMID BYRON
B & B DRILLING CO INC	BACIL TED E
B & B PARTNERSHIP	BACK STONE NATURAL RES II-B LP
B & D DRILLING CO	BACKER RESOURCES INC
B & E INC	BACON FAMILY TRUST
B & E PINKERTON LLC	BACON JANE V
B & G PRODUCTION INC	BACON KARL W
B & H RESOURCES INC	BACON PROPERTY LTD
B & J OPERATING INC	BAD WATER LLC
B & L OIL CO INC	BADER CHILDREN TRST
B & L OIL CO LTD	BADGER ENERGY INC
B & M CONSTR CORP	BADGER JOHN
B & S WELL SERVICES INC	BADGER OIL CORP
B & W OIL CO INC	BADGER SERVICES INC
B A G A M LTD	BADLANDS GAS INC
B A LINGARD & CO INC	BAER JANE B
B B BROOKS CO	BAGBY ENERGY LLC
B C & D OPERATING	BAGSHAW JOHN J
B D DEANS LLC	BAGWELL #6 FAMILY LTD PTNRSHP
B E CONWAY ENERGY INC	BAGWELL DONALD
B F ALBRITTON LLC	BAGWELL DONALD L

Current BLM Oil and Gas Lessees:

BAGWELL GARY	BALLANTYNE OIL
BAHLBURG WILLIAM C	BALLARD A L (LES)
BAIANO GREGORY F	BALLARD CO
BAILEY BEVERLY D	BALLARD LYNDA M
BAILEY THOMAS ASSOC	BALLARD PETRO HOLDINGS LLC
BAILLIO R H JR	BALLARD PETRO LLC
BAIN DELORIS	BALLARD PETROLEUM HOLDINGS
BAIRD DOYLE H	LLC
BAKER ALVIN B	BALLARD PETROLEUM LLC
BAKER BARBARA M	BALLARD THEODORE J
BAKER BRAD	BALLEN SAM B
BAKER ENERGY CO	BALLEW RONALD
BAKER GAS INC	BALLEW SHIRLEY
BAKER GEORGE F III	BALOG FAMILY TRUST
BAKER GEORGE W	BALOG GAIL
BAKER GLORIA	BALOG PETE T
BAKER HAROLD D	BALSAM PRDCNG PROPERTIES LLC
BAKER NEAL	BALSAM PRODUCING PROP LLC
BAKER OG DEV LLC	BALVANT PATEL
BAKER ORIN M	BANAS EDWARD J
BAKER PAUL R	BANCEQUITY CORP
BAKER R S JR	BANCORP INC
BAKER RUBY	BANDER J H
BAKER SUSAN	BANDERA ENERGY CO
BAKER WILLARD	BANDERA PETROLEUM INC
BAKKEN ENE PARTNERS LLC	BANDY LLC
BAKKEN RES LLC	BANE BIGBIE INC
BALCRON OIL	BANK OF AMERICA
BALCRON OIL CO	BANK OF AMERICA TRUSTEE
BALD EAGLE RES INC	BANK OF CA TRUST
BALD EAGLE RESOURCES INC	BANK ONE TRST PHILIP SHARPLES
BALDAUF ROBERT J	BANK ONE TRUSTEE
BALDWIN HAZEL SIMS	BANKHEAD ADMIN ACCT TRUST
BALDWIN J H	BANKHEAD CHAS C JR
BALDWIN LYNCH ENE CORP	BANKHEAD GRACE K
BALDWIN LYNCH ENERGY CORP	BANKS ENTERPRISES
BALES STEPHEN	BANKS JOE D
BALK OIL CO INC	BANKS LEE
BALKO INC	BANKS R C
BALL CARROLL O	BANNON ENE PROG 88B
BALL LUCILLE	BANNON ENE PROG 89A
BALL NIKKI S	BANNON ENERGY INC
BALL W J	BANNON EXPL CO
BALL WILLIAM J	BANTA & HAIGH
BALL WILLIAM J JR	BANTA E S
BALLANTYNE BRENDA A	BANTA FAMILY TRST

Current BLM Oil and Gas Lessees:

BANTA HAZEL R	BARNUM CHERYL R
BAR MESA RESOURCES INC	BAROID DIV NATL LEAD
BARASH MAX	BARON EXPLORATION CO
BARBARA DEKEATER LIVING TRUST	BARON OIL CORP
BARBARA HARDESTY FORTNEY ENE	BARON WALTER R
BARBARA HILLYARD TR	BAROVICH JOHN S
BARBARA L MEYER REVOC TRUST	BAROVICH JOHN S JR
BARBARA M INC	BAROVICH MARNY J
BARBE KENNETH JR	BAROVICH MARY
BARBEE BILL J	BAROVICH MICHAEL J
BARBER FAMILY TRUST THE	BARR CRAIG W
BARBRICK INVESTMENT CO	BARR DAVID
BARD FAMILY TRUST	BARR LAURIE B FAMILY TRUST
BARD RALPH AUSTIN JR	BARR LISA
BARD ROY E	BARR RICHARD
BARFIELD ANNE T	BARR RICHARD K
BARFIELD JAMES W	BARR TAYLOR
BARFIELD OIL CORP	BARR THOMAS R
BARHAM E	BARRETT BUD E
BARK PRODUCTION CO	BARRETT BURDICK W
BARKER D KEATON & GLENDA SUE	BARRETT CHARLOTTE
BARKER EXPL CO	BARRETT DAMIAN G
BARKLEY JEFFREY R	BARRETT FRANK A
BARLOW & HAUN INC	BARRETT KIMSLEE
BARNARD COLLEEN	BARRETT M B ACCOUNT
BARNARD DONALD	BARRETT MARCUS T III
BARNARD ENE LLC	BARRETT OK INTS LTD
BARNARD ROBERT	BARRETT OSBORN W
BARNES J C	BARRETT REV TRUST
BARNES J C JR	BARRETT W OSBORN
BARNES JULIE ELLEN	BARRETT WILLIAM D
BARNES MICHAEL A	BARRETT WILLIAM O
BARNES PETRO CORP	BARRETT WY INTRSTS
BARNES STEVEN	BARRON O J
BARNES TIP	BARRON PROPERTY MGMT
BARNES V ELAINE	BARRY MARY E
BARNES VIOLA S	BARRY WHITE & CO INC
BARNETT EXPL INC	BARSTOW ELIZABETH M
BARNETT JACK	BARSTOW J & W TRST
BARNETT PATRICIA J	BARSTOW LJ & BJ TRST
BARNETT PROPERTIES INC	BARSTOW NANCY TRST
BARNHART JOE EST	BARSTOW R R TRST
BARNHART ROBERT J	BARTEK BRAD
BARNHILL CLAYTON M	BARTEL JAMES R
BARNHILL M CLAYTON	BARTELL C F
BARNHILL WILLIAM B	BARTELL J D

Current BLM Oil and Gas Lessees:

BARTELL MADELINE O	BAYLESS RL PROD LLC
BARTON CLAUDIA R	BAYLESS ROBERT L
BARTON ROY G	BAYLESS ROBERT L JR
BARTON ROY G JR	BAYNE BARBARA GAIL
BASA RESOURCES INC	BAYNE OIL CO
BASE PETROLEUM	BAYNE OIL COMPANY
BASELINE MINERALS INC	BAYNE WILLIAM W
BASF CORPORATION	BAYOU RESOURCES INC
BASIN MINERALS INC	BAYSHORE PROD CO
BASIN OPERATING CO	BAYSWATER EXPL & PROD LLC
BASIN PETROLEUM CO	BAYTECH INC
BASIX AZ ENERGY CORP	BAYTECH LLP
BASS ENERGY INC	BAYTEX ENERGY USA LTD
BASS HASKELL H JR	BAYTIDE PETRO INC
BASS JAMES C	BAYUQUE RES INC
BASS LEE M INC	BBE HOLDINGS LLC
BASS PAUL	BBI CO
BASS PERRY R	BBL LTD
BASS PETROLEUM INC	BC OPERATING INCORP
BASS SID R	BC&D OG CORP
BASSHAM RICHARD A JR	BC&D OPERATING INC
BASSORE BRAD D	BCA MEDICAL ASSOC
BATAA OIL INC	BCS NAT RES CORP
BATES BRADLEY S	BDOL 1978 PROG LTD
BATES GILBERT L	BEACH CARL C
BATES OIL CORP	BEACH EXPL INC
BATES READING OIL CO	BEACH EXPLORATION
BATTALINO BARBARA B	BEACH USA INC
BATTLECAT OIL & GAS LTD PTNRS	BEACH WILLIAM N
BATTSON RESIDUAL TRUST	BEAKLEY ROYALTY LLC
BAUDAT RENE F	BEAL E PAULA REV TRUST
BAUER ARTHUR C	BEALL CAROLYN
BAUER OIL & GAS LLC	BEALL CAROLYN READ
BAUERDORF G F	BEALL THOMAS M
BAUMGARTNER F W	BEAMGUARD H GORDON
BAUMGARTNER OIL CO	BEAMON JAMES R
BAUMGARTNER RES LTD	BEAMON ROBERT
BAUMGARTNER RESOURCES LLC	BEAMS ROBERT J
BAWDEN GERTRUDE D	BEAN FAMILY LTD CO
BAXTER DOYLE E	BEAN RESOURCES INC
BAXTER ROYALTY CO	BEAR ENERGY INC
BAY ENERGY PARTNERS LLC	BEAR OIL & GAS INC
BAY GAS LLC	BEAR PEAK RESOURCES LLC
BAYHORSE PETROLEUM LLC	BEARCAT INC
BAYLESS BERNICE M	BEARD CO
BAYLESS RANCHES LLC	BEARD ELLY B 2007 TRUST

Current BLM Oil and Gas Lessees:

BEARD JOHN M	BEETEN JOHN K
BEARD JOHN M TRST	BEGALLE DONALD
BEARD JOHN M TRUSTEE	BEHLING RICHARD W
BEARD OIL CO	BEHM ENERGY INC
BEARD OIL COMPANY	BEHRENS JAMES L
BEARING SERVICE SUPPLY	BEILHARZ VIRGINIA G
BEARTOOTH ENE LLC	BEILHARZ W R
BEARTOOTH O&G CO	BELCO 1972 O&G FUND
BEARTOOTH OG CO	BELCO ENERGY CORP
BEARTOOTH OIL & GAS CO	BELCO ENERGY ILP
BEASLEY OIL CO	BELCO PETRO CORP
BEASON JENNIFER ANN	BELDEN & BLAKE CORP
BEATY JUDITH L	BELDON DORR C
BEAVER OIL CO	BELFER RENEE E
BEAVER PAUL J	BELFER ROBERT A
BEAVER ROMENA S	BELL & FAUDREE II
BEAVER SHARON	BELL BRYAN
BEAVER VALLEY GAS	BELL ENERGY CORP
BEAVER WALTER N	BELL J MICHAEL
BEAVERS W R	BELL LEROY
BECHTEL ENERGY PTNRS	BELL RESOURCES INC
BECK ENERGY CORP	BELL RUBIE C
BECK LISA	BELL RUBIE LEE
BECK PUMP & SUPPLY INC	BELL T J
BECK ROBERT H	BELLAH C
BECKER BRIGHAM OIL	BELLAH CARROLL
BECKER BUNNY	BELLAIRE OIL CO
BECKER DONALD G JR	BELLAMY SIDNEY E
BECKER STEVE	BELLE EXPLORATION
BECKER TIM D	BELLEVUE CAPITAL CO
BECKER VALENNNA L	BELLEVUE RESOURCES INC
BECKHAM OIL CO	BELLPORT OG INC
BECKMAN KAL J	BELLWETHER EXPL CO
BECKMAN LEMOIN	BELMONT OIL & GAS CORP
BECKMAN PHYLLIS	BELWEST OIL & GAS LTD
BECKMAN TAMARA	BEMISS FITZGERALD
BEDFORD EXPL INC	BEN F & J L SMITH TRUST
BEDFORD PTNRS LTD	BEN F PETRIE HEIRS
BEDFORD RESOURCES LLC	BEN F SMITH OIL CO
BEDROCK ENERGY DEVELOPMENT	BEN JOHNSTON EST TR
INC	BEN S INC
BEDROCK ENERGY INC	BENCH RACHEL D
BEDROCK LTD PTNRSHP	BENCH STEVE D
BEE HIVE OIL LLC	BENCO PETROLEUM LLC
BEEMAN OIL & GAS LLC	BENEDICT GEORGE
BEESON JOHN S	BENEDUM PAUL G JR

Current BLM Oil and Gas Lessees:

BENESCO PROPERTIES  
BENGSON MERRILL  
BENHAM DAVID B  
BENJAMIN EDWARD B JR  
BENJAMIN SMELTZER CO  
BENKOSKI FRANK J  
BENNER SHERRIN  
BENNETT H S  
BENNETT M BRAD  
BENNETT O&G PROJECTS  
BENSCHTER DON L  
BENSON D H  
BENSON DONALD H  
BENSON J A  
BENSON MINERAL GROUP  
BENSON MONTIN GREER  
BENSON MONTIN GREER DRILLING  
BENSON OIL PROP INC  
BENSON REVOCABLE TR  
BENSON THELMA JEAN  
BENSON W M  
BENSON-MONTIN-GREER  
BENT GROVE LLC  
BENTALL GWYNETH  
BENTLEY DEE  
BENTLEY RANCH HOLDINGS LLC  
BENZLEY CECIL VERL  
BEPCO LP  
BERCO RES LLC  
BERCO RESOURCES INC  
BERCO RESOURCES LLC  
BEREN ADOLPH  
BEREN CORP  
BEREN H H  
BEREN I H  
BEREN ROBERT M  
BEREN SHELDON K  
BERENERGY CORP  
BERENERGY CORPORATION  
BEREXCO INC  
BERG CHARLES R  
BERG RACHAEL ANN SMITH  
BERGE EXPL INC  
BERGER KENT H  
BERGER MARCIA  
BERGERON IVEN J JR

BERGET SHARON K  
BERGMAN GERALD K  
BERGMAN PETRO CORP  
BERGMAN WILLIAM R  
BERGQUIST WALLACE  
BERGSTROM NELLIE K  
BERGSTROM OLIVER C W  
BERI I GEN PTNRSHP  
BERNARD J SEEMAN TRS  
BERNHARDT OIL CORP  
BERNHARDT RICHARD  
BERNICE J BRADSHAW MAR TRST  
BERNICK BETTY R  
BERNICK ROBERT W  
BERRY DAN C  
BERRY ENERGY INC  
BERRY MILTON H  
BERRY O H  
BERRY ORAN H III  
BERRY PETRO CO  
BERRY PETROLEUM CO  
BERRY PETROLEUM CORP  
BERRY THOMAS E  
BERRY VENTURES INC  
BERRY W T  
BERRY WM A  
BERRYMAN WILLIAM M  
BERRYMAN, WILLIAM M  
BERT FIELDS ESTATE  
BERTOLET BOB  
BERTOLET YVONNE P  
BEST EXPLORATION INC  
BEST YET LLC  
BESTOSO EDWARD J  
BESTOSO OIL & GAS COMPANY  
BESTOSO OIL & GAS COMPANY INC  
BESTOSO OIL AND GAS COMPANY  
BETELGEUSE PROD  
BETELGEUSE TRUST  
BETHEL EDWARD V  
BETHEL OLLIE B EST  
BETHEL VIRGINIA LEE  
BETHOL CORP  
BETHUNE KARMA S  
BETSWEST RESOURCES LP  
BETTIS BROTHERS INC

Current BLM Oil and Gas Lessees:

BETWELL OIL & GAS	BIGLER ROGER A TRST
BETWELL OIL & GAS CO	BILL BARRETT CBM CORPORATION
BETZ KAREN NICHOLSON	BILL BARRETT CORP
BEUTNAGEL ANITA L	BILL BARRETT CORPORATION
BEVERIDGE CO	BILL BARRETT PROD CO
BEVO PROD CO	BILL BARRETT PROPERTIES INC
BEVO PRODUCTION CO	BILL D FARLEIGH REVOCABLE TRST
BEWLEY THOMAS W	BILL D FARLEIGH TRUSTEE
BGI TUCUMCARI LLC	BILL FENN INC
BHP PETRO (AMER) INC	BILL HODGES TRUCK CO
BHP PETRO AM INC	BILLINGSLEY DAVID L
BHP PETRO AMER INC	BILLS GEORGE F
BHP PETRO CO INC	BILLUPS FORD L JR
BIBEAULT DONALD B	BINDER SARAH
BIBLER CAROL J	BINDER RICHARD
BIBLER RES CO	BINNING GENE H
BIBLER RESOURCES CO	BIRD CREEK LLC
BICKEL ROSS TREVETT	BIRD CREEK RESOURCES INC
BICKERSTAFF ASSOC INC	BIRD OIL CORP
BICKERSTAFF DOUGLAS	BIRD SCOTT
BIELER JOHN W	BIRD WHITWORTH F MD
BIENVILLE INVESTMENTS	BIRDSONG ROBERT T
BIG CHIEF DRILLING CO	BISCO INC
BIG CHIEF EXPL INC	BISHOP PETRO CORP
BIG ESOX INC	BISON ASSOC 1987-A
BIG HORN DEVELOPMENT	BISON BASIN LLC
BIG HORN SERVICES INC	BISON ENERGY INC
BIG HORN SVCS INC	BISON PETROLEUM CORP
BIG LIME ENE LTD	BISSELL OIL
BIG SANDY OIL CO	BISSELL OIL OPERATING CO INC
BIG SINKS JOINT VENTURE	BISSETT WAYNE A
BIG SKY ENE LLC	BISTATE OIL CO
BIG SNOWY EXPL LP	BIXLER WILLIAM P
BIG SNOWY EXPL LTD PTNRSHP	BIZZLE VAL G
BIG SNOWY EXPLORATION LP	BJR PROPERTIES INC
BIG SNOWY RESOURCES CO	BK ENERGY CO
BIG WELLS ENERGY CO	BK EXPLORATION CORP
BIG WEST OG INC	BLACK BEAR OIL CORP
BIG WEST OIL & GAS	BLACK BOW EXPL LTD
BIG WEST OIL & GAS INC	BLACK CORAL LIMITED LIABILITY
BIGBEE HARRY L	BLACK CROWN ENERGY PARTNERS
BIGGIE BANE	LP
BIGGELN ROGER	BLACK DIAMOND ENERGY INC
BIGGERS JOHN C	BLACK DIAMOND ENERGY OF DE INC
BIGGS ADELAIDE E	BLACK DIAMOND MINERALS LLC
BIGHORN INVESTMENTS INC	BLACK DIAMOND RESOURCES LLC

Current BLM Oil and Gas Lessees:

BLACK FAMILY LLC	BLAIR SYLVIA
BLACK FAMILY PTNRSHP LTD	BLAIR W W
BLACK GOLD PROD INC	BLAKE ARNOLD O&G PROP LLC
BLACK HAROLD	BLAKE CLARK
BLACK HAWK OIL CO	BLAKE HARRY
BLACK HAWK RES LLC	BLAKE MARK
BLACK HILLS EXPL & PROD	BLAKEFIELD ENERGY CO
BLACK HILLS EXPL & PROD INC	BLAKEMORE BRUCE A
BLACK HILLS GAS RESOURCES INC	BLAKEMORE PAGE P JR
BLACK HILLS PLATEAU PROD LLC	BLAKEMORE PAGE P SR EST
BLACK ISLAND RESOURCES(USA)INC	BLAKEMORE WARREN
BLACK JACK OIL CO INC	BLAKENEY FLOYD
BLACK JOSEPH H	BLAKENEY FLOYD A
BLACK MESA PETROLUuem	BLANCA PEAK ENE LLC
BLACK MICHAEL E	BLANCO CO
BLACK RAVEN ENERGY INC	BLANCO COMPANY THE
BLACK RESOURCES INC	BLANCO ENGINEERING
BLACK RIVER CORP	BLANCO HOLDINGS I LTD
BLACK ROCK ARKANSAS LLC	BLANCO OIL CO
BLACK SAMMY MAX	BLANEY DEXTER
BLACK STONE MINERALS CO LP	BLANEY MARYLAND
BLACK STONE NAT RES II-B LP	BLANKENSHIP OIL VENT
BLACK STONE NATRL RES II LP	BLANKENSHIP WAYNE A JR
BLACK STONE NATRL RES II-B LP	BLAUSER WELL SER INC
BLACK STONE NTRL RESRC II-B LP	BLAUW ALFRED S
BLACK TRIANGLE PROD CO	BLAYLOCK M A
BLACK WILLIAM D	BLAYLOCK S L
BLACKBEAR O&G LLC	BLAYLOCK STEVE
BLACKBEAR OIL & GAS LLC	BLEDSOE BILL L TRUSTEE
BLACKBIRD CO	BLEDSOE ENERGY CORP
BLACKBIRD LLC	BLEDSOE PARTNERS INC
BLACKBIRD OIL	BLEDSOE PETRO CORP
BLACKBIRD PARTNERS LLC	BLENHEIM NATURAL RES FUND LLC
BLACKBURN JOHN	BLICHFELDT J P EST
BLACKBURN OIL & GAS LLC	BLIGH PETRO INC
BLACKBURN W T	BLIGH PETROLEUM INC
BLACKFORD KEN	BLIGHT HERBERT E
BLACKJACK OIL INC	BLISS ANTHONY A
BLACKLAND PETROLEUM LLC	BLISS C STANLEY JR
BLACKMAR DONALD E	BLISS JOHN W
BLACKNER A E	BLISS JOHN WILLIAM
BLACKSTONE ENERGY CO LLC	BLISS JUDITH C
BLACKSTONE MINERALS CO LP	BLISS JUDITH CAROLYN
BLACKWATER NATURAL GAS	BLISSCO PARTNERSHIP
BLACKWELL BMC LP	BLM
BLAIR ALBERT	BLM EASTERN STATES

Current BLM Oil and Gas Lessees:

BLM FARMINGTON FO	BOARDMAN ALEX C
BLM JACKSON FO	BOB BEEMAN DRLG CO
BLM MILWAUKEE FO	BOBB EULA
BLM NMSO	BOBBITT ROBERT L JR
BLM-MONTANA SO	BOCOR HOLDINGS LLC/BCR PROD
BLM-WYOMING SO	BODKIN J D
BLOCK DAVID A	BODZY INVESTMENTS PTNRSHP LTD
BLOCK GAY SHLENKER	BOEDECKER BROOKS J
BLOCO INC	BOEDECKER RES
BLOMQUIST DALE E	BOEHMER ARLENE
BLOMQUIST GWEN D	BOEKEL ENERGY LLC
BLOMQUIST ROGER D	BOEKEL, PATRICIA ANN TRST
BLOOMER & ASSOCIATES	BOERNE LAND & CATTLE
BLOOMER LARRY	BOERNE LAND & CATTLE CO INC
BLOOMER PARKER E	BOERNE LAND AND CATTLE INC
BLOOMFIELD OIL & GAS	BOERSMA BARBARA
BLOOMQUIST CHARLES W	BOESE LEROY DEAN
BLUE & GRAY RESOURCES INC	BOGDANOVICH PETER
BLUE ARCHIE J	BOGEHOLZ MARTHA
BLUE CHRISTINA	BOGERT OIL CO
BLUE DIAM PETRO INC	BOGGIO LINDA G
BLUE DOLPHIN ENERGY LLC	BOGGY CREEK PROD
BLUE DOOR INC	BOHN SYBIL M
BLUE DUNN LLC	BOIS D ARC RESOURCES LTD
BLUE FLAME ENERGY CORP	BOLACK DUANE THOMAS
BLUE HERON PETROLEUM	BOLACK MINERALS CO
BLUE HIL OIL & GAS CO	BOLAND ARDEN R
BLUE MOON RES INC	BOLAND EDWARD M
BLUE ROBERT M	BOLAND EXPL CO
BLUE SKY GAS STORAGE LLC	BOLAND MICHAEL R
BLUE STAR RESOURCES INC	BOLAND THOMAS J
BLUE TIP CASTLEGATE INC	BOLD ENERGY LP
BLUE WALLACE S	BOLD RESOURCES LLC
BLUE WHALE PARTNERSHIP	BOLEY JACK W
BLUEBONNET ENE CORP	BOLEY KURT W
BLUMA HENRIETTA A	BOLEY TIMMY
BLUMENTHAL ELLIS	BOLGER PERRY
BLUNDELL BOB	BOLIN C W
BLYWISE ROBERT	BOLIN D P
BMB BILL C BURNS TRUST	BOLIN D PHIL
BMS ROYALTY FUND	BOLIN DAN H
BMT O&G MULTI-STATE LLC	BOLIN DOLORES
BN COAL LLC	BOLIN PAT S
BN NON-COAL LLC	BOLIN PHIL D
BNC INC	BOLIN R L
BNR VENTURES II LLC	BOLIN RESOURCES LP

Current BLM Oil and Gas Lessees:

BOLING MARY L	BOSWELL-KIRK MARY
BOLING ROBERT E	BOTT P J
BOLING ROBERT M	BOUDREAUX G SHELL
BOMA INVESTMENT CO	BOULDERS RLTY CORP
BO-MC RESOURCE CORP	BOULDERS ROY CORP
BOMHOLT KATHRYN O	BOULDERS ROYALIY COR
BONANZA CREEK ENER OPER CO LLC	BOULDERS ROYALTY
BONANZA CREEK ENERGY OPERATING	BOULET CARRIE ANN
BONANZA CREEK OPER CO LLC	BOU-MATAR TERESA T
BONANZA CRK ENE OPER CO LLC	BOU-MATAR WALID
BONANZA OIL COMPANY LLC THE	BOUNTY HOLDINGS INC
BOND CATHERINE	BOURQUIN FAMILY TRUST
BOND JAMES	BOVAIRD SUPPLY CO
BOND JOHN H	BOVINA LTD LIABILITY
BOND MARGARET ANN	BOW OIL CO LTD
BOND THOMAS W	BOWATER LAURIE WHITE
BOND W C ESTATE	BOWDEN ENERGY CO INC
BONDURANT KATHLEEN	BOWDLE MARGARET B
BONDURANT WILLIAM	BOWEN A B
BONEFISH LLC	BOWEN B H
BONNER J B ESTATE	BOWEN C E
BONNETERRE ASSOC	BOWEN GAS CORPORATION
BOOCO'S CONTRACT SVC	BOWEN I B
BOOK CLIFFS O&G CO	BOWEN-EDWARDS ASSOC
BOOKCLIFF OPERATING INC	BOWER PROPERTIES LLC
BOONE JOHN W	BOWERS O&G INC
BOONE PHILIP S JR	BOWERS OG INC
BOONE RONALD D	BOWERS R S
BOONENBERG W G	BOWKER CARL WILLARD
BOPCO LP	BOWKER DARWIN L
BORCHERT R V	BOWLES ROBERT D
BORDEAUX TRADING CO	BOWMAN OIL CO LTD
BORDER EXPL CORP	BOYCE ALBERT G JR
BORDER TO BORDER #1 LP	BOYD & MCWILLIAMS
BORELLI MARGUERITE J	BOYD & MCWILLIAMS ENERGY
BORGAARD ELIZABETH S	GROUP
BORGER FLORENCE A	BOYD K
BORGNA GARY	BOYD KATHARINE
BORICA OIL INC	BOYD LAUGHIN TESTAMENTARY
BORICK LOUIS L	TRST
BOROS EDNA K	BOYD LAUGHLIN
BOSS JAMES A	BOYD T II
BOSTWICK DUNBAR W	BOYD T K II
BOSWELL INTERESTS LTD	BOYD THOMAS K II
BOSWELL MARY	BOYD THOMAS M
	BOYD WILLIAM TRST

Current BLM Oil and Gas Lessees:

BOYLE JOHN W R TRUST	BRADSTAR HOLDINGS INC
BOYLE W T	BRADY JACK MORGAN
BOYSE VELMA C	BRADY NADENE S
BOZMAN MARY KATHERINE	BRAGA GEORGE A
BOZMAN RUTH L	BRAGG WILLIAM F
BOZMAN-MOSS BARBARA	BRAILLE INSTITUTE
BP AMERICA PROD CO	BRAINARD GUY R JR
BP AMERICA PRODUCTION	BRAINERD ANDREW W
BP AMERICA PRODUCTION CO	BRAMMER-KEYSTONE ENE
BP AMERICA PRODUCTION COMPANY	BRANCH COLBY L
BP EXPL & PROD INC	BRANCH DEBBIE
BP EXPL INC	BRANCH JERRY L
BP EXPLORATION INC	BRANCH JOHN D TRUSTEE
BP PRODUCTION CORP	BRANCH OIL & GAS
BPI	BRANDT JOHN E
BPJ INC A TX CORP	BRANDT LINDA
BRACERO OIL CO	BRANDT TOM
BRACK HENRY B	BRANDT TOM M
BRACK LELAND E	BRANEX RESOURCES INC
BRACKEN BRETT K	BRANKO INC
BRACKEN OPERATING LLC	BRANNER SOLANO
BRACKLA RESOURCE PARTNERS LLC	BRANNON DWAIN
BRADEN EXPL LLC	BRANNON M J
BRADEN EXPLORATION	BRANSON JOHN BRUCE
BRADEN JOHN W JR TST	BRANSON PATSY A
BRADFORD BARRY LEE	BRANUM M W
BRADFORD CARYL M	BRAUSE DON
BRADFORD FRANCES F	BRAVO ENERGY INC
BRADFORD MICHAEL R	BRAVO I LTD CO
BRADLEY ALBERT	BRAVO I LTD LIAB CO
BRADLEY BROUSSARD LAND SERVICE	BRAVO III LTD CO
BRADMAR PETRO CORP	BRAXTON O&G CORP
BRADSHAW B J	BRAZIL DONALD
BRADSHAW BERNICE J	BRAZOS DRILLING 1978
BRADSHAW DON F TRST	BRAZOS LP
BRADSHAW F J TRUST	BRAZOS LTD PNTRSHP
BRADSHAW F J ESTATE	BRAZOS LTD PTNRSHP
BRADSHAW FRANKLIN J FAMILY	BRAZOS OIL AND GAS CO
BRADSHAW L J TRUST	BRAZOS PETROLEUM INC
BRADSHAW LAWRENCE J ESTATE OF	BRAZOS RESOURCES
BRADSHAW R D	BRECK ENERGY (NEVADA) LLC
BRADSHAW SAM C	BRECK ENERGY NEVADA
BRADSHAW WILLIAM A	BRECKENRIDGE PARTNERSHIP LTD
BRADSHAW WM A III	BREEDLOVE JOHN H
	BREEDLOVE JOHN JR
	BREENE JAMES O JR

Current BLM Oil and Gas Lessees:

BREENE JAS O JR	BRIGHT & CO
BREHM INVST GRP INC	BRIGHT & COMPANY I LTD
BREIPOHL ROBERT P	BRIGHT HAWK BURKARD VENTURE
BREITBURN ENERGY CO LLC	BRIGHT ROCK PARTNERS LLC
BREITBURN ENERGY CO LP	BRIGHT SKY ENERGY & MNRLS INC
BREITBURN OPER LTD PRTNRSHP	BRIGHTON ENERGY LLC
BREITBURN OPERATING LP	BRIGHTWELL THOMAS P
BREK PETROLEUM INC	BRIGMAN A LEONE
BRELAND LEON	BRIGMAN EDWARD S
BRENDALL ENERGY LLC	BRIMMER GEORGE E
BRENNAN MARIAN	BRINKERHOFF & SONS
BRENNAN RAYMOND H	BRINKERHOFF ENTPR
BRENNAND ENERGY LTD	BRINKERHOFF JOHN
BRENT EXPL INC	BRINKERHOFF R W JR
BRENT EXPLORATIONS INC	BRINKMAN JOHN L
BRENTLINGER JAMES H ESTATE	BRINSON DOLAN ARTWELL
BRET HARTE REALTY CO	BRINSON H L
BRETON SOUND RESOURC	BRINSON HOMER VAUGHN
BREUER G W	BRISCOE OIL OPER CO
BREWER MARK	BRISTOL RESOURCES
BREWER MARK T	BRITAIN JACK
BREWER NONA M	BRITE RALPH W
BREWER REBECCA J	BRITISH-BORNEO N SEA
BREWER ROBERT PAINE III EST	BRITOIL VENTURES INC
BREWER THOMAS	BRITT CAROL M
BREWER THOMAS J	BRITT HARRY M
BREWER TIM	BRITZ HELEN
BREWINGTON ROBERT L	BRO ENERGY LLC
BRG PETROLEUM CORP	BROADBENT LORNA S
BRICKER LEE A	BROADHURST WILLIAM
BRICKER NEAL DR	BROCK CHRISTINE
BRICKYARD EXPL FUND LLC	BROCK DRILLING CO
BRICKYARD EXPLORATION FUND	BROCK EXPL CORP
BRIDGE ENERGY INC	BROCK FRANK
BRIDGE OIL CO LP	BROCK IRENE G
BRIDGEFARMER LARRY J	BROCK JAMES W
BRIDWELL OIL CO	BROCK RESOURCES INC
BRIDWELL OIL MANG OF AL LLC	BROCK ROBERT S
BRIGGS ADELAIDE E	BROCKMAN JAMES C
BRIGGS HERBERT R	BRODY PEGGY
BRIGGS KERRY S	BROECK CLAUDE VANDEN
BRIGGS RICHARD S	BROME CHARLES L
BRIGGS WILLIAM C	BRONCO OG CO
BRIGHAM OG LP	BRONFMAN ANN
BRIGHAM OIL & GAS LP	BRONSON NOLAN H
BRIGHAM TRUST	BROOKIE FRED P

Current BLM Oil and Gas Lessees:

BROOKIE G LEONE	BROWN JAMES D JR
BROOKIE G WILLIAM	BROWN JAMES L
BROOKOVER ENTPR	BROWN JAMES M JR
BROOKS ANNIE M TRUST	BROWN JOHN O
BROOKS BILL J	BROWN JOHN S
BROOKS EXPL INC	BROWN JOHN S JR
BROOKS FAMILY TRUST	BROWN KARA F
BROOKS HALL OIL CORP	BROWN L Z
BROOKS OIL & GAS	BROWN LARITA
BROOKS OIL & GAS INTERESTS	BROWN MARK T
BROOKS OIL & GAS INTERESTS LTD	BROWN MATTHEW D
BROOKSTON RESOURCES INC	BROWN MAURICE W
BROOME FAMILY LP	BROWN MELVIN A
BROOME GEORGE B	BROWN MELVIN A TRUST
BROTHERS PROD PROPERTIES LTD	BROWN MITCHELL PROPERTIES INC
BROTHERSEN REBECCA	BROWN PATRICIA S
BROTHERTON FRED J	BROWN R C
BROUGHTON PETRO INC	BROWN RANGER PROP LLC
BROUGHTON PETROLEUM INC	BROWN RICHARD
BROUN ALICE	BROWN RICHARD I
BROWER OIL & GAS INC	BROWN ROBERT
BROWER ROBERT C	BROWN ROBERT E
BROWN A M	BROWN ROSEMARY E
BROWN A W TRUST	BROWN ROY
BROWN ALICIA J	BROWN ROYALTIES
BROWN BONNIE J	BROWN SPENCER
BROWN BROTHERS TRUST	BROWN WALTER F
BROWN BURTON M	BROWN WALTER F JR
BROWN C MICHAEL	BROWN WILLIAM
BROWN DAVID BURNS	BROWN WILLIAM L
BROWN DONALDSON TRUST	BROWNING INVESTMENT
BROWN DONNIE E	BROWNING INVESTMENT CO
BROWN DOROTHY L	BROWNING OIL CO
BROWN DOUGLAS	BROWNING W FLEMING
BROWN DUANE	BROWNIE RAY O
BROWN EDITH L EST	BROWNIE WALLACE ETC
BROWN EDWARD	BROWNSTONE VENTURES (US) INC
BROWN EDWARD M	BROXTERMAN MARK J
BROWN ENERGY CO	BRS EXPL CO INC
BROWN FRANK D	BRUBAKER JAMES L
BROWN GAIL WHITE ESTATE	BRUCE CLADER INC
BROWN H KIRK III	BRUCE G COCHENER TRUST EST
BROWN H L JR	BRUCE JAMES
BROWN HAYWARD	BRUCE RICHARD W
BROWN IRENE	BRUMARK CORP
BROWN JAMES C	BRUMFIELD RONNY

Current BLM Oil and Gas Lessees:

BRUMFIELD TANZA	BULLINGTON RALPH E
BRUMLEY CLARENCE W	BULLION J W
BRUNEL JOHN H	BULLOCK CORP
BRUNER ARNOLD	BULLOCK CORPORATION
BRUNER GLEN WOOD	BULLOCK VAN K
BRUNER STEPHEN E	BULTMAN MARVIN G II TRUSTEE
BRUNO & MARSHALL INV	BUMMER BRUCE L
BRUNO EARL R	BUMP DAVID L
BRUNO EARL R JR	BUMPAS GLOBAL HOLDINGS
BRUNSON KATHRYN C	BUMS LORAINE C
BRUNSON PATRICIA A	BUNCE THOMAS C
BRUNSON VIVIAN C	BUNIGER ELLEN
BRUSCHWEIN DEAN A	BUNIGER ELLEN SUE
BRUSS BARBARA ANN TRUSTEE	BUNIGER WILLIAM
BRYAN BELL FAMILY	BUNIGER WILLIAM H
BRYAN J MANLY	BUNIGER WILLIAM III
BRYANT DONNA C	BUNKER CLYDE
BRYANT MICHAEL B	BUNKER HILL PROSPECT
BRYNJOLFSON MORRIS	BUNKER LINDA
BRYSON CANYON PTNRSHP 87-5	BUNN FRANCIS B
BRYSON KIRBY SUE	BUNN ROBERT B
BRYSON PHILIP L	BUNNETT ANDREA M
BRYSON RALPH H	BUNTING DAVID RABE
BRYSON ROBERT A	BURBACH HOMES
BSAP II INC	BURBACH HOMES INC
BT FAMILY PARTNERSHIP LTD	BURCH BENJAMIN D
BTA OIL PRODUCERS	BURCH CLAUDIA R
BTA OIL PRODUCERS LLC	BURCH SAMUEL A
BUCHANAN THOMAS E	BURCHAM MARILYN
BUCHHOLZ OIL & GAS CO INC	BURCHAM NEIL
BUCHNER G LESLIE	BURFORD JAMES F
BUCHOLTZ WILLIAM	BURGENER PATRICIA W
BUCK CREEK OIL CO	BURGER W D
BUCKEYE ENERGY INC	BURGESS JOYCE
BUCKHORN ENTERPRISES	BURGESS TRUSTEES
BUCKSKIN PETROLEUM AT CA LLC	BURGUNDY OIL & GAS OF NM
BUCY PROPERTIES LLC	BURK BAKWIN & HENRY
BUDD CLIFF	BURK ROYALTY CO
BUDENDORF BOB E	BURK ROYALTY CO LTD
BUDZISZEK PATRICIA A	BURKE ALICIA J
BUENA VISTA HILLS LLC	BURKE EDWARD T
BUFFCO PRODUCTION INC	BURKE GLENN P
BUIE H C	BURKE GLORIA
BULK LINDA	BURKE HAROLD E
BULL MOOSE OIL & GAS INC	BURKE JACK
BULLER PAUL	BURKE PATRICIA JO

Current BLM Oil and Gas Lessees:

BURLESON LEWIS B	BUSH BRETT C
BURLESON PARTNERS	BUSH JERRY
BURLESON PETROLEUM INC	BUTLER CLAUDIA Z
BURLESON STEVEN L	BUTLER OIL LLC
BURLINGTON IND INC	BUTLER SAM J
BURLINGTON NORTHERN	BUTLER SAMUEL III
BURLINGTON NRN RR CO	BUTLER SAMUEL JR
BURLINGTON PRODUCTION CO	BUTLER SHERALD K
BURLINGTON RES O&G	BUTTOLPH WILLIAM R EST
BURLINGTON RES OG CO LP	BUTTONWOOD PETRO INC
BURLINGTON RES OG CO LP	BUXTON F M
BURLINGTON RES OG LP PTRRC	BWAB 84-86 JOINT VEN
BURLINGTON RES OIL & GAS CO LP	BWAB INC
BURLINGTON RES OIL & GAS LP	BWAB LLC
BURLINGTON RESOURCES O&G CO LP	BWAB LTD CO
BURMA LEE KERNAL	BWAB LTD LIABILITY CO
BURNETT OIL CO	BWB PARTNERS I
BURNETT OIL CO INC	BY OIL A PTNRSHP
BURNS BRAD T	BYERS VERA S
BURNS FRANKLIN L	BYRD HARL D
BURNS HAZEL	BYRD JIM BOB
BURNS JOHN J	BYRNE JOSEPH H
BURNS L D	BYRNE RICHARD M
BURNS PHIL	BYRNES MILDRED
BURNSED OIL CO INC	BYRON TUCK J
BURR JAMES E	C & C PARTNERS 1983 DRILLING
BURR OIL & GAS INC	C & H OIL & GAS INC
BURR ROBIN K	C & H WELL SERVICING INC
BURR SEAN C	C & J INVESTMENT CO
BURRO LAKE LLC	C & K 1975 EXPLORATION LTD
BURROW MARJORIE	C & N BLAUGRUND TRST SP
BURROW WILLIAM SR	C & PW CORP
BURSON JOHN	C + D GAS COMPANY
BURSON ROBERT CODY	C A COCHENER TRST
BURSON SUE	C BAR W OIL & GAS
BURTON FAMILY TRUST	C C ALBRIGHT TRST
BURTON FLAT INVESTMENTS	C D RAY LLC
BURTON GEORGE H	C E BREHM EST
BURTON HAWKS INC	C E LARUE CO
BURTON LUELLA C	C F C PARTNERS
BURTON WILLIAM C DR	C F CARTHEL TRUST
BURTON/HAWKS INC	C G CAMPBELL ESTATE
BUSBY LEONARD	C GARY MAMMEL FAMILY TRST
BUSCH ANDREW W	C GARY MAMMEL MARITAL TRST A
BUSH BARRY L	C GARY MAMMEL MARITAL TRST B
	C GAS LLC

Current BLM Oil and Gas Lessees:

C H TODD INC	CAIN N J
C HARRIS TRUST	CAIRN ENERGY USA INC
C L & F RESOURCES LP	CAL ROYALTY LLC
C L NEELEY MGMT TRUST	CALAIS RESOURCES INC
C L TANGNEY TRST	CALANA CORP
C M MAGUIRE JR TRUST	CALARK INC
C M MCKAY TRUST	CALCO INVESTMENTS
C M PARKER TRUST	CALCO LLC
C O BARRETT TRST	CALDER JOHN W
C P ACQUISITION LLC	CALDER SIDNEY
C R WILKINSON TRUST	CALDWELL DOROTHY
C S V OIL EXPL CO	CALEBS RESOURCES
C T & L M WATSON	CALEX RES INC
C T BARTON TRUST	CALEX RESOURCES INC
C V LYMAN ESTATE	CALIFORNIA CO
C W BOLIN PROPERTIES	CALIFORNIA NATURAL RESOURCES
C W CARSON ESTATE	CALIFORNIA PETRO HOLDINGS INC
C W PAINE CO	CALLAHAN HARRIETT A
C&D GAS CO	CALLAHAN JOHN M
C&J FIELD SERVICES	CALLAN R C
C&PW CORP	CALLAWAY ENERGY LLC
CABAL ENERGY CORP	CALLAWAY OIL LLC
CABALLO COAL CO	CALLAWAY PROD CO INC
CABEEN W ROSS	CALLINAN FAMILY
CABE-TOLES LINDA	CALLINAN MARGARET DIETZEN
CABOT CARBON CORP	CALLINAN THOMAS W
CABOT OG CORP	CALLISTER CO/CALCO
CABOT OIL & GAS CORP	CALLON CONSOLIDATED
CABOT OIL AND GAS CORP	CALLON INCOME FUND
CACTUS & CRUDE INC	CALLON PETROLEUM CO
CACTUS DRILLING CORP TX	CALLON PETROLEUM OPERATING CO
CACTUS ENERGY INC	CALLOWAY ELIZABETH T
CACTUS OPER CO LLC	CALMAR HOLDINGS LLC
CACTUS OPERATING CO	CALMETTO II LTD
CADE BAYLUS	CAL-MON OIL CO
CADENCE RESOURCES CORP	CALPETCO V
CADIGAN CORP	CALPINE CORP
CADIGAN JOHN D	CALSTAR ENERGY FUND LP
CADOR PETRO CORP	CALTO DEVELOPMNT INC
CAERUS BIG HORN LLC	CALTO OIL CO
CAERUS NORTHERN ROCKIES LLC	CALUMET OIL CO
CAFIERO NANCY B	CALVERT RUTH ANN
CAGGIANO SALVATORE	CALVERT RUTH ANN JEFFERS
CAGLE DIANA	CALVIN CYNTHIA
CAHILL JOHN T	CALVIN EDWARD M
CAIN A J	CALVIN JOHN R

Current BLM Oil and Gas Lessees:

CALVIN SEALY H JR	CANADIAN KENWOOD CO
CAM ENERGY LLC	CANER JUDITH B
CAMBERLEY RES LLC	CANFIELD W W
CAMBRIA FOREST INDUSTRIES	CANNELL ANN E
CAMBRIAN RESOURCES INC	CANNON ELAINE
CAMBRIDGE OIL CO	CANNON EXPL CO
CAMERON HELEN ET AL	CANNON EXPLORATION CO
CAMERON MOSELLE	CANNON ROBERT
CAMERON OIL & GAS CO	CANO PETRO OF NEW MEXICO INC
CAMERON OIL & GAS INC	CANSO OIL & GAS INC
CAMIO ENTERPRISES LLC	CANTER LORA
CAMMON TERRY J	CANTER LORA M
CAMOZZI CRAIG M	CANTER ROGER E
CAMP COLORADO INVSTMNTS LP	CANTERRA PETRO INC
CAMPBELL & CO LP	CANTERRA RESOURCES PRTNERS
CAMPBELL C G	LTD
CAMPBELL CATHERINE I	CANTRELL JAMES D
CAMPBELL GRILLEY C	CANYON E&P CO
CAMPBELL INVESTMENT	CANYON ENERGY LLC
CAMPBELL INVESTMENT CO	CANYON EXPLORATION CO
CAMPBELL JOE H	CANYON NATURAL GAS LLC
CAMPBELL JOHN H	CANYON OG CO
CAMPBELL KAREN	CAP OIL LTD
CAMPBELL LEWIS O	CAPCO RESOURCE CORP
CAMPBELL LILLIAN	CAPITAL LAND SERVICES
CAMPBELL MURRAY C	CAPITOL WIRELESS LP
CAMPBELL PARTNERS LP	CAPLIN MORTIMER
CAMPBELL PAULA	CAPLITZ JANE H
CAMPBELL ROBERT J	CAPMAC 82 LTD PTNRSP
CAMPBELL SHEETZ J	CAPMAC INC
CAMPBELL T K	CAPPEL S C
CAMPBELL THOMAS III	CAPPEL TRUST
CAMPBELL THOMAS K II	CAPPS RANDALL
CAMPBELL W T	CAPROCK EXPL INC
CAMPEN CONSULTANTS INC	CAPSHAW JIM
CAMPER JACK CASEY	CAPSTONE ENERGY PORTFOLIOS
CAMPOS M F	CAPSTONE ENERGY PORTFOLIOS LLC
CAMTERRA RES PTNRS	CAPSTONE OIL & GAS CO LP
CAMTERRA RES PTNRSHP	CAPTIVA ENERGY INC
CAMTERRA RESOURCES PARTNERS	CAPTIVA RES INC
LT	CAPTIVA RESOURCES INC
CAMWEST LTD PTNRSHP	CAPUCILLE TOM
CAMWEST VI LP	CARAM & SONS LTD
CANAAN RESOURCES LLC	CARANCAHUA LP
CANADEX RESOURCES INC	CARAS GEORGE
CANADIAN ENTPR INC	CARAWAY FRANK

Current BLM Oil and Gas Lessees:

CARBON ENE CORP (USA)	CARNELL E F
CARBON TECHS ENE INC	CARNELL MILLICENT C
CARD ELDON J	CARNEROS ENERGY INC
CARDEN OIL & GAS INC	CARNES GREG
CARDINAL RIVER ENERGY I LP	CARNES JIM
CARDINAL RIVER ENERGY INC	CARNES LES M JR
CARDO CO	CAROL-HOLLY OIL CORP
CAREY JAMES W	CAROLINA RES & DEV
CAREY ROSS	CAROLINE A COCHENER TRUST EST
CARGILL & CO LTD	CAROLYN CLARK OATMAN
CARGILL KEN	CAROUSEL ENERGY OPER LLC
CARGILL PARTNERS LTD	CARPENTER & SONS INC
CARGOIL & GAS CO LLC	CARPENTER CORP
CARIBAM RES INC	CARPENTER CRAIG
CARIBOU LAND & LVSTK MT LLC	CARPENTER WILLIAM H
CARIBOU OG LLC	CARR BINION
CARIBOU OIL & GAS LLC	CARR COLLETTE L
CARKEL ENERGY LLC	CARR LINDA
CARL B FIELD LLC	CARR W P
CARL D UNDERWOOD O&G INC	CARRELL ENTPR INC
CARL E GUNGOLL EXPL LLC	CARRELL JANET A
CARL E GUNGOLL EXPLORATION	CARRELL LARRY A
CARL E GUNGOLL EXPLORATION LLC	CARRELL OIL CO
CARL ENGALL TRUST	CARRIGAN BETH
CARL F OMAN TRUST	CARRIGAN WADE
CARL JAMES R TRUSTEE	CARRIGAN WADE P
CARL MAXEY ESTATE	CARRIZO OIL & GAS INC
CARL PFAFF LEGACY LLC	CARROL ANN E TRUSTEE
CARLETTA CO	CARSON DAVID RHEA
CARLISLE DEE ANN	CARSON EDWARD LEWIS
CARLISLE RICK	CARSON JERRY N
CARLISLE VERVENE	CARSON JOEL
CARLISLE WAYNE J	CARSON JOHN C
CARLOW CORP	CARSON W
CARLSBAD NATL BANK	CARSON WATER CO
CARLSON RONALD R	CARSON WILLIE M
CARLTON BARBARA JR	CARTEL PETROLEUM INC
CARLTON OIL CORP	CARTER ALBERT E
CARLYLE B KENNETH	CARTER CHARLES S
CARLYLE CO	CARTER ENERGY CORP
CARLYLE INC	CARTER FAMILY TRUST
CARMEN ACQUISITION CORP	CARTER FNND PROD CO
CARMEN FIELD LTD	CARTER GRANT B
CARMEN SCHMITT INC	CARTER HOLLY P
CARMONY EXPLORATION LLC	CARTER LELAND W
CARNEGIE HALL SOC	CARTER SUSIE A

Current BLM Oil and Gas Lessees:

CARTER-DUNAGAN JUNE	CAUTHEN JAMES E
CARTER-FRISKE CAROL	CAVAIUOLO JOHN P
CARTHEL THEODORE H	CAVALIER PETRO CORP
CARTHEL TRUSTS	CAVALIER PETRO INC
CASADA D E	CAVALLARO SHARON P
CASCARANO JOANNE W	CAVALRY LTD PTNRSHP
CASE POMEROY OIL	CAVALRY LTD PTNSHP
CASEY B H	CAVE RESOURCES LLC
CASEY JAMES J	CAVES RESOURCES LLC
CASEY JOHN E	CAVIN S H
CASEY MATHEW H EST	CAVIN SEALY H JR
CASEY WILLIAM J	CAYFOUR CORP
CASH RAY H	CAZA ENERGY LLC
CASHCO OIL CO	CAZA PETRO INC
CASKEY JOSEPH K	CAZA PETROLEUM INC
CASPEN OIL INC	CBASE CORP
CASRY JOHN E	CBM GAS COMPANY LLC
CASS DEBORAH H	CBM PARTNERS CORP
CASSANDRA KEYSER	CBM PROPERTIES LLC
CASSIDY PRODUCTION LLC	CBP SAN JUAN LP
CASTELLO JOHN	CBR LTD PARTNERSHIP
CASTLE EXPL CO INC	CBR OIL PROPERTIES LLC
CASTLE PEAK RESOURCES LLC	CBS OPERATING CORP
CASTLE STEPHEN N	CBS PTNRS LTD
CASTLE VALLEY HOLDINGS LLC	CCA 1990 JT VENTURE
CASTLE/TOWNER 1981-2	CDA FAMILY PARTNERSHIP LTD
CASTLE/TOWNER 1981-4	CDM OG
CASTLEGATE RESOURCES LLC	CDX GAS LLC
CATAMOUNT ROYALTY PARTNERS LTD	CEB OIL CO
CATAWBA ENERGY INC	CECIL DONALD
CATENA OG LLC	CEDAR CREEK OG CO
CATH CHURCH SOCIETY	CEDAR DRLG 1978-A
CATHEAD INVESTMENTS LLC	CEDAR RIDGE LLC
CATHER-HERLEY OIL CO	CEDAR RIDGE PETRO CORP
CATHERINE H RUML REV TRUST	CEDAR RIM LC
CATHERINE ONEILL EST	CEDAR STRAT
CATHERINE PRINCE BOND EST OF	CEDERLOF E R
CATHEY EMILY BESS	CEDERLOF L M TRUSTEE
CATHOLIC CHURCH SOC	CEDERLOF LUCILE M
CATOILAN CORP	CEEFAM LLC
CATT D L	CEJA CORP
CATT FAMILY TRUST	CELERO ENERGY II LP
CATTLE CALL INC	CELERO ENERGY LP
CATTS BARBARA A	CELERON OIL & GAS CO
CAUSEY MARION E	CELTIC RESOURCES LLC
	CENEX HARVEST STATES COOP

Current BLM Oil and Gas Lessees:

CENEX INC	CHALFANT WILLIAM A
CENTAUR CONSULTING LLC	CHALK HILL GAS INC
CENTAUR INVESTMENTS LLC	CHALLENGER MINS INC
CENTAUR RESOURCE CORP	CHAMBERS EVELYN
CENTENNIAL	CHAMBERS JERRY
CENTENNIAL ENERGY	CHAMBERS JERRY G EST
CENTENNIAL LLC	CHAMBERS JILL
CENTENNIAL NM PTNRS	CHAMBERS JOHN ED III
CENTENNIAL OIL AND GAS	CHAMBERS RONALD C
CENTENNIAL VENTURE III LLC	CHAMBLESS OIL INC
CENTRAL LEASE INC	CHAMPAGNE JOSEPH L
CENTRAL MONTANA RESOURCES LLC	CHAMPION VENTURES
CENTRAL NATL BANK OF CLEVELAND	CHAMPION W H
CENTRAL OPER INC	CHAMPLIN DAVID EUGENE
CENTRAL PACIFIC RES	CHAMPLIN DOUGLAS L
CENTRAL PETROLEUM	CHAMPLIN EXPLORATION INC
CENTRAL PETROLEUM INC	CHAMPLIN H H
CENTRAL RES INC	CHAMPLIN JOE N
CENTRAL RESOURCE INC	CHAMPLIN MARIANNE R
CENTRAL RESOURCES IN	CHAMPLIN STEPHEN C
CENTRAL RESOURCES INC	CHAMPLIN STEVE C EST
CENTRAL RESOURCES LLC	CHAMPLIN SUZANNE ELIZABETH
CENTRAL TRANS SYS CO	CHANCE JOE C
CENTRAL TX OPER	CHANCE PROPERTIES
CENTURY CHARTERING CO INC	CHANCELLOR C E
CENTURY EXPL RESOURCES INC	CHANCORP DRLG PTNRS
CENTURY O&G CORP	CHANDLER COLLIS P JR
CEP M PURCHASE LLC	CHANDLER DOUG
CES OIL OPERATIONS	CHANDLER DRILLING PARTNERS
CEVON ENERGY CORP (NV)	CHANDLER ENE LLC
CFM OIL CO	CHANDLER J H
C-GAS LLC	CHANDLER JAMES H
CH PARTNERS LLC	CHANDLER JUDITH E
CH4 EXPLORATION	CHANDLER LEWIS
CH4NET.COM LTD	CHANDLER OIL & GAS
CHABOT RONALD R J	CHANDLER TERRY
CHACO ENERGY CO	CHANAY ELIZABETH C
CHACO THREE INC	CHANG DAVID M
CHADCO INC	CHANNEL RESOURCES
CHAHTA PETROLEUM INC	CHAPARRAL (USA) ENERGY LLC
CHAISSON DOROTHY	CHAPARRAL CO2 LLC
CHALCAM EXPLORATION LLC	CHAPARRAL ENERGY LLC
CHALFANT INC	CHAPARRAL MINERALS INC
CHALFANT PROPERTIES INC	CHAPARRAL OIL & GAS
	CHAPARRAL RES INC
	CHAPARREL ENERGY INC

Current BLM Oil and Gas Lessees:

CHAPMAN ENERGY OK	CHE BOU-MATAR TRUST
CHAPMAN JAMES C	CHEESEMAN RILLA
CHAPMAN MARK A	CHEETAH GAS CO LTD
CHAPMAN VIRGIL H	CHEETAH RES INC
CHAPPELL FAMILY TRUST	CHEMICAL LIME COMPANY OF AZ
CHARCA EXPLORATION INC	CHEMILY MANAGEMENT CO
CHARCO EXPLORATION LP	CHEMILY MGT CO
CHARLES A GREER LIVING TRST	CHEENEY DIANA C
CHARLES A NEAL & CO	CHEENEY JESS C
CHARLES ALBERT BUTTOLPH EST	CHEENEY MITCHEL E
CHARLES COLWILL ESTATE	CHENIERE PETRO CORP
CHARLES MALONE TRUST	CHERIE HICKMAN TRUST
CHARLES R SWAIN EST	CHERNESKY HOLDINGS INC
CHARLES T LUPTON TR	CHEROKEE OPERATING CORP
CHARLES URSCHEL EST	CHERYL DAVIDSON TRUST
CHARLES W KEMP TRUST	CHESAPEAKE AEZ EXPLORATION
CHARLESWORTH ENTERPRISES	LLC
CHARLESWORTH FREDA E	CHESAPEAKE APPALACHIA LLC
CHARLESWORTH JIMMIE	CHESAPEAKE ENE EXPL LP
CHARLINE GREER EST	CHESAPEAKE ENERGY CORP
CHARLTON M T	CHESAPEAKE ENO ACQUISITON LLC
CHARLTON MARY C	CHESAPEAKE ENO ADQ CORP
CHARTER POST EXPLORATION LLC	CHESAPEAKE EP CORP
CHARTERHALL ENERGY LLC	CHESAPEAKE EXPL LLC
CHARUK LYNN S	CHESAPEAKE EXPL LIMITED
CHAS BANKHEAD JR INC	CHESAPEAKE EXPL LLC
CHASE BILL W	CHESAPEAKE EXPL LP
CHASE BILLY W	CHESAPEAKE EXPLORATION LLC
CHASE CROUCH GERENE	CHESAPEAKE EXPLRN LLC
CHASE DEB E	CHESAPEAKE INVESTMENTS
CHASE DIANNE	CHESAPEAKE KNAN ACQ CORP
CHASE FAMILY TRUST	CHESAPEAKE LOUISIANA LP
CHASE FERGUSON GERENE D	CHESAPEAKE MID-CON
CHASE GEORGE A	CHESAPEAKE MOUNTAIN FRONT LLC
CHASE GEORGE JR	CHESAPEAKE NFW LP
CHASE KARLA	CHESAPEAKE OPER INC
CHASE LENNA	CHESAPEAKE OPERATING
CHASE MARILYN	CHESAPEAKE OPERATING INC
CHASE OIL CORP	CHESAPEAKE ORC LLC
CHASE OIL CORPORATION	CHESAPEAKE PERMIAN LP
CHASE PETROLEUM	CHESAPEAKE PRH CORP
CHASE RICHARD L	CHESS OIL & GAS LLC
CHASE ROBERT C	CHESS OIL PROPERTIES
CHASE THOMAS D	CHESSIE EXPL INC
CHASEL JOHN D	CHESSMAN ENE LLC
CHATEAU OIL & GAS	CHESTNUT PETROLEUM INC

Current BLM Oil and Gas Lessees:

CHET & CLAIRE MARTIN LVNG TRST	CHORNEY OIL CO
CHEVRON INC	CHORNEY RAYMOND ESTATE
CHEVRON MIDCONTINENT LP	CHORNEY S A
CHEVRON USA	CHORNEY THOMAS A
CHEVRON USA HOLDINGS INC	CHOTZINOFF BLAIR
CHEVRON USA INC	CHRIS CORP II INC
CHEVRON USA PROD CO	CHRIS CRAFT JVT
CHEVRON USA PRODUCTION COMPANY	CHRIS CRAFT OIL CO
CHEYENNE OIL PROPERTIES INC	CHRISS GEORGE S
CHEYENNE PETRO CO	CHRIST RODNEY V
CHEYENNE PETROLEUM CO	CHRISTENSEN DOUG H
CHEYENNE PROPS	CHRISTENSEN MARCELLA
CHEYENNE PTNRS IV	CHRISTENSEN MARCELLA B
CHFOUR LLC	CHRISTENSEN PETRO
CHI ENERGY INC	CHRISTEVE OIL CO
CHI OPERATING INC	CHRISTIAN & WHITE PROPERTIES
CHIANG GLORIA	CHRISTIANSEN JENS
CHIARA JUDITH L	CHRISTIANSON LEROY D
CHICAGO ENERGY ASSOC LLC	CHRISTIANSON WILMA
CHICAGO TRUST CO OF CA	CHRISTMAN JOHN J
CHICKASAW O&G INC	CHRISTMAN OIL COMPANY
CHICKEN CREEK LLC	CHRISTMANN MINERALS CO
CHIEF EXPLRN DEV LLC	CHRISTY S B IV
CHIEFTAIN INTL (US) INC	CHRYsalis EXPL CORP
CHIEFTAIN INTL US INC	CHUDNOW JAMES M
CHILDRESS GERALD	CHUGASH EXPLORATION LP
CHILDRESS MARTHA	CHUMNEY BETTY BREWER
CHILDRESS ROYALTY CO	CHUMNEY DE MARIGNY I
CHILES PLUMMER TRUST	CHUMNEY ELIZABETH H
CHINOOK ENERGY CORP	CHUMNEY INDIA BREWER
CHIPCORE LLC	CHUZA OIL CO
CHISHOLM ELIZABETH G	CHUZA PETROLEUM
CHISHOLM TRAIL VENTURES LP	CIBOLA ENERGY CORP
CHISM L S	CICO OIL & GAS CO
CHISOS LTD	CIENAGA LLC
CHK LOUISIANA LLC	CIESZINSKI J E
CHM PETRO INC	CIG EXPL INC
CHOATE JACK H	CIG EXPLORATION INC
CHOCTAW GEOLOGICAL RESOURCES E	CIGNA
CHOCTAW II OG LTD	CIGNA PROP & CAS INS
CHOCTAW PARTNERS	CILLEY NYNA A
CHOLLA PROD LLC	CIM ENERGY PROPERTIES LLC
CHORNEY DOROTHY	CIMA PTNRS 1984-1
CHORNEY JOAN	CIMAREX ENE CO
	CIMAREX ENERGY CO
	CIMARRON CHEM INC

Current BLM Oil and Gas Lessees:

CIMARRON CHEMICAL IN	CLARK BRET W
CIMARRON EXPL CO	CLARK DAVID
CIMARRON ROYALTY CO	CLARK DONALD L
CINCO GENERAL PTNRSHP LLP	CLARK E B JR
CINCO LAND & EXPL INC	CLARK EDYTHE M
CINIZA PROD CO	CLARK ENERGY CO INC
CINIZA PRODUCTION CO	CLARK ETLEY EST
CINNAMON CREEK OIL & GAS	CLARK FAMILY LTD
CIRCLE RIDGE PROD CO	CLARK FLORA ELLEN
CIRQUE RES LP	CLARK FRED J
CIRQUE RESOURCES LP	CLARK JEANIE C
CIRRUS PROD CO	CLARK JOHN M
CISCO OPERATING LLC	CLARK M CRAIG
CITADEL ENERGY INC	CLARK MIKE
CITATION 1987-II	CLARK RANDALL M
CITATION 2002 INVST LTD PTNRSH	CLARK REB
CITATION 2002 INVSTMNT LP	CLARK ROBERT L
CITATION 2004 INVST LP	CLARK ROBERT R
CITATION 2004 INVST LTD PTNRSH	CLARK S A
CITATION 2004 INVST PTNRSHP	CLARK SHARON
CITATION O&G 2004 INVSTMNT LP	CLARK SHERRI B
CITATION OG CORP	CLARK TRACY P
CITATION OIL & GAS CORP	CLARK TRACY R
CITIES SER O&G CORP	CLARK VALERIA
CITIES SERVICE CO	CLARK WARREN TRUST
CITIES SERVICE OIL & GAS	CLARK WILLIAM S
CITIES SERVICE OIL & GAS CORP	CLARKE FLORA
CITKOWITZ ELENA TRST	CLARKE JAMES P
CITRUS ENERGY CORP	CLASSIC HYDROCARBONS OPER LLC
CKT ENERGY LLC	CLATO OIL CO
CKT LLC	CLAVEL C J
CL&F RESOURCES LP	CLAWSON MILLEN
CLACO OIL CO	CLAY A MUEGGE OPER
CLAIBORNE HARRY C	CLAYTON BRUCE LEE
CLANCY PITTS ENE GRP	CLAYTON INVESTMENT
CLAPP NORTON	CLAYTON JACK C
CLARA D GREEN TRUST	CLAYTON MACK L
CLARA SMITH TRUST	CLAYTON ROBYN DIANE
CLAREMONT CORP	CLAYTON STEVE EARL
CLARENCE HYDE ESTATE	CLAYTON WILLIAMS ENE
CLARJAC INVESTMENTS	CLAYTON WILLIAMS ENERGY INC
CLARK & OATMAN	CLAYTON WILLIAMS INC
CLARK & REED TRUST	CLAYTON WMS PTNSHP
CLARK A M	CLEARY PETRO CORP
CLARK A P JR	CLEARY PETROLEUM CORP
CLARK BILL	CLEES DIANE

Current BLM Oil and Gas Lessees:

CLEES HOMER	COASTAL RESOURCES INC
CLEMENTS CAPITAL LLC	COATS RICHARD H
CLEMENTS ENERGY INC	COBB DALTON H
CLEMENTS GEORGE L	COBB DALTON H JR
CLEMENTS PAUL	COBB LUCY BELL
CLEMENTS W T	COBB MICHAEL B
CLEMETSON ASORA	COBIE ROBERT B
CLICK JAMES H JR	COBRA DRILLING INC
CLIDE OIL CORP	COBRA EXPLORATION CO
CLIFFORD CONE FAMILY TRUST	COCEK BERNARD J
CLIFTON JOHN H	COCHARO LAURIE
CLIFTON THOMAS OIL	COCHRAN ENERGY INC
CLINE PROD CO	COCHRANE RES INC
CLINE PRODUCTION CO	COCKBURN JOHNNY
CLINE W GEOFFREY	COCKBURN MAGGIE S
CLINT S INC	COCKRAN ENERGY LP
CLINT YOUNG INC	COCKRELL PROD CO INC
CLINTON MINERALS	COCKSPUR INC
CLINTON OIL CO	CODA ENERGY INC
CLIPPINGER JOHN	CODAK LAND CO LLC
CLM PRODUCTION CO	CODVINGTON OG INC
CLOE JESSIE DARLENE	CODY ENERGY INC
CLOPTON JAMES	CODY MCARTHUR WIKERT TRUST
CLOVELLY EXPL CO INC	CODY MCARTHUR WILKERT TRUST
CLUB O&G LTD	CODY OIL & GAS CORP
CLUB OG LTD	CODY OIL CO
CLUB OIL & GAS LTD	COE
CLX ENERGY INC	COE RICHARD C
CM PRODUCTION LLC	COENERGY CENTRAL EXP
CMI ENERGY PROPERTIES LLC	COFFIELD FAY M
CML EXPLORATION LLC	COFFIN LEONARD S
CMM RESOURCES LLC	COFFIN ORLO R
CMS NOMEKO O & G CO	COFFMAN MILTON
CMS NOMEKO OIL & GAS	COG OPER LLC
CMW INTEREST INC	COG OPERATING LLC
CMW INTERESTS INC	COG PTNRSHP
CN ENERGY LLC	COGBURN M L
CNR RES INC	COGGIN BILL E
CO INTERSTATE GAS CO	COHAN EDNA G
COACHMAN ENE LLC	COHEN & ROSEN 77 & 83 TRUSTS
COALEUM CORP	COHEN CYRIL
COASTAL LAND SERVICES INC	COHEN H PAUL BNFCL TRST
COASTAL LLC	COHEN NANCY LIBERMAN
COASTAL OIL & GAS CORP	COHEN NORMAN
COASTAL PETRO CO	COHN JOSEPH JUDSON EST OF
COASTAL PLAINS ENERGY INC	COHORT ENE CO

Current BLM Oil and Gas Lessees:

COHORT ENERGY CO	COLORADO OG CORP
COHORT ENERGY COMPANY	COLORADO WYO RES CO
COINS EARNET C	COLORADO WYOMING RES CO
COKELAN CORP	COLOUR CORPORATION US
COKINOS ENERGY CORP	COLT OIL INC
COLA PETROLEUM INC	COLTCH RESOURCES LLC
COLE JACK A	COLTON CO
COLE JAMES J	COLTON DON J
COLE JIMMIE	COLTON EXPL CO
COLE SHEILA	COLTON FRANK E
COLE SHEILA C	COLTON GREGG B
COLE SHELIA C	COLTON KATIE
COLEMAN JESS A	COLUMBIA GAS TRANSMISSION
COLEMAN OIL & GAS INC	CORP
COLEMAN OIL 1986-1	COLUMBIA GAS TRANSMISSION LLC
COLEMAN OIL INC	COLUMBIA GROUP LTD
COLETTE J STANLEY TRUST	COLUMBIA NAT RES INC
COLGATE ROBERT B	COLUMBIA NATURAL RESOURCES
COLIN CYNTHIA G	LLC
COLIN JUSTIN S	COLUMBIA PROD CO
COLKELAN CORP	COLUMBIAN CARBON CO
COLL BROTHERS OIL	COLUMBIAN FUEL CORP
COLL CHARLES H	COLUMBINE EXPL CORP
COLL CLARKE C	COLUMBINE LTD 1978 B
COLL ERIC J	COLUMBINE RES LLC
COLL JAMES N	COLWELL DOROTHY
COLL JON F	COMANCHE
COLL JON F II	COMANCHE EXPL CO
COLL MAX W	COMANCHE EXPL CO LLC
COLL MAX W III	COMANCHE O&G CO
COLLEGE OF SW	COMANCHE OIL CO
COLLIER DAVID C	COMANCHE RESOURCE CO
COLLIER DIAMOND OILS	COMBINED RES CORP
COLLIER ENERGY INC	COMBINED RESOURCES
COLLIER TIMOTHY D	COMET ENERGY SERVICES LLC
COLLINS & WARE INC	COMET PETRO INC
COLLINS G F JR EST	COMGAS INC
COLLINS LEN	COMMERCERCE BANK OF KC TRUST
COLLINS REED G	COMMNLTH ENERGY INC
COLLINS SMITH	COMMON ENERGY INC
COLLINS TED JR	COMO PETROLEUM CORP
COLLIS P CHANDLER JR TRUST	COMPASS BANK TRUSTEE
COLONIA ENE INC	COMPASS EXPL INC
COLORADO ENERGY MINERALS INC	COMPTON TROY V
COLORADO INTERSTATE	COMSTOCK DR II O&G
COLORADO LAND DEV CO	COMSTOCK OIL & GAS

Current BLM Oil and Gas Lessees:

COMSTOCK OIL & GAS LA LLC	CONQUISTADOR VENTURES LTD
COMSTOCK OIL & GAS LP	CONRAD CLAYTON
CON TREND RESOURCE INC	CONRAD HELEN S
CONCHO LAND CO LLC	CONROW NANCY T
CONCORDE PROD CO LLP	CONSOLIDATED ENERGY
CONCORDE PRODUCTION CO LLP	INVESTMENT
CONCORDIA RESOURCES	CONSOLIDATED INTERESTS
CONDEVCO INC	CONSOLIDATED OG INC
CONDOR OIL CORP	CONSOLIDATED OIL & GAS INC
CONDOR PETRO INC	CONSOLIDATED OPERATING
CONDOR PETROLEUM INC	CONSOLIDATED PROD
CONE CLIFFORD	CONSORTIUM MUNDI ENERGY LLC
CONE DOUGLAS L	CONSTANT ENERGY INC
CONE KATHLEEN	CONSTITUTION PETRO
CONE KATHLEEN DESCENDANTS	CONSUMERS ENERGY COMPANY
TRST	CONTEX ENERGY CO
CONE KENNETH	CONTEX ENERGY COMPANY
CONE KENNETH G	CONTINENTAL INDUSTRIES LC
CONE S E JR	CONTINENTAL LAND RESOURCES
CONE THOMAS R	LLC
CONE TOM R	CONTINENTAL RES INC
CONEJO INVEST INC	CONTINENTAL RESERVES
CONEJO INVST INC	CONTINENTAL RESERVES OIL
CONESTOGA ENERGY RES LLC	CONTINENTAL RESOURCE CORP
CONKLIN ELLEN	CONTINENTAL RESOURCE INC
CONKLIN GARY	CONTINENTAL RESOURCES INC
CONLEY P SMITH LLC	CONTINENTAL T23935
CONLEY P SMITH LTD	CONTINENTAL T23949
CONLEY RES LLC	CONTINENTAL TREND RES INC
CONLEY RESOURCES LLC	CONTL GAS LTD
CONLON CLIFFORD G	CONTL IL ENERGY DEV
CONLON JAY G	CONTL RES 1981-8
CONNAGHAN LUCILLE	CONTOUR ENERGY INC
CONNAGHAN MARY R	COOK BILLY J
CONNAGHAN ROBERT J	COOK C DEAN
CONNELL RALPH M	COOK D L
CONNELLY MARY F	COOK GEORGE A
CONNELLY THOMAS H	COOK J D JR
CONNOR SUZANNE I	COOK JESSICA WILMA
CONOCO INC	COOK R A DECEDENT TR
CONOCO PHILLIPS CO	COOLEY RALPH S
CONOCOPHILLIPS	COOLEY TRUST
CONOCOPHILLIPS CO	COOLIDGE DANIEL
CONOCOPHILLIPS CO PTRRC	COOLIDGE G B INC
CONOCOPHILLIPS COMPANY	COOLIDGE TIMOTHY J
CONQUISTADOR PETROLEUM LLC	COON EVERETT JR

Current BLM Oil and Gas Lessees:

COONEY CLINTON J	CORNERSTONE L&P CO
COONS CLIFFORD V	CORNERSTONE NATURAL RES LLC
CO-OP 91 PARTNERS	CORONA CENTRAL PETRO
COOPER GLENN H	CORONADO ARKANSAS LLC
COOPER PATRICIA J TR	CORONADO ENERGY E&P CO LLC
COOPER PHILIP J	CORONADO EXPL
COOPER SAM S	CORONADO EXPLORATION CORP
COOPER SUSAN G	CORONADO OIL CO
COOPER T A	CORPUS CHRISTI GAS LP
COOPER THOMAS S	CORRAL INC
COORS ENERGY CO	CORRIDA OILS INC
COPPERHEAD CORP	CORTERRA CORP TRUST
COQUINA OIL CORP	CORTEZ EXPLORATION LLC
CORAL ENERGY RESERVES CORP	CORY KENNETH W
CORAL INC	COSARA ENERGY CORP
CORAL PROD CORP	COSO OPERATING CO
CORAL PRODUCTION CORP	COSSMAN VAUGHN S
CORBIN BEVERLY J	COSTILLA ENERGY
CORBIN REX J	COSTILLA ENERGY INC
CORDELL FRANK	COSTILLA ENERGY LLC
CORDELL JAMES C	COSTILLA PETROLEUM
CORDELL MICHAEL	COSTIN MITZI
CORDILLERA CORP	COSTON GARY
CORDILLERA ENE PRTNRS III LLC	COTNER BILL C
CORDILLERA ENE PTNRS II LLC	COTTEN EXPL INC
CORDILLERA ENERGY II LLC	COTTER OIL CO
CORDILLERA ENERGY PARTNERS	COTTER R HUGO C
LLC	COTTON CREEK INV CO LTD
CORDILLERA ENERGY PRTNRS LLC	COTTON EXPL CO
CORDILLERA RESOURCES INC	COUCH OIL & GAS
CORE ENERGY LLC	COUGAR CAPITAL LLC
CORE MINERALS OPERATING CO I	COUGHLIN WILLIAM M
CORE PETROLEUM LTD	COULTER MIKE J
CORELL MARCELLA TRST	COULTER WILLIAM J
COREXCAL INC	COULTHURST MGT & INV
COREY FRED C	COUNTRY CHURCH OF CRIST
CORFF OIL CO	COUNTRYMARK ENERGY
CORKRAN DENNIS	RESOURCES
CORKRAN DENNIS D	COUNTS KATHRYN OCONNOR
CORKRAN ENE LP	COUROIL INC
CORKRAN ENERGY LP	COURTNEY Q PETER III
CORLENA OIL CO	COVE CREEK RESOURCES INC
CORLEY J ROBERT	COVERT MARCIA R
CORN LEE KATHI	COW RUN OIL CO INC
CORN W E	COWAN SID
CORNELL OIL CO	COWDEN CAROLYN G

Current BLM Oil and Gas Lessees:

COWDEN LYNN	CRAMER TRUST
COWDEN WRIGHT JR	CRAMPTON TODD A
COWEN TIMOTHY M	CRANBERRY METHANE
COWING JAMES H	CRANK JAMES F
COWRY ENTERPRISES	CRANMER ALLEN A
COWRY ENTPR LTD	CRANMER BRUCE K
COX & PERKINS EXPL	CRANMER ROBERT L
COX BEN	CRANMER W H ESTATE
COX BERRY R	CRANSTON CORP
COX EDWIN L	CRANSTON EARL M
COX JOHN L	CRANSTON EARL M ESTATE
COX LESLIE C	CRAPO FAMILY TRUST
COX MARK S	CRAVEN CLINTON D
COX OIL PTNRS LTD	CRAVENS VERNELL T
COX PAUL L	CRAVENS WILLIAM
COX ROBERT	CRAVEY HERMAN
COX VICKI B	CRAVEY JOHN R
COX WILLIAM	CRAWFORD CLARK JAMES
COY BETTY J	CRAWFORD JOHN P
COY CALVIN	CRAWFORD WALTER J
COYOTE EXPL CO	CRAWLEY PETRO CORP
CP ACQUISITION LLC	CRAZY MOUNTAIN GROUP
CP EXPLORATION #2 LP	CRC COMMUNITY TRST
CP EXPLORATION #3 LP	CRCONE LLC
CP EXPLORATION #4 LP	CREBBS ELEANOR S
CP EXPLORATION LP	CREDO PETRO CORP
CPC MINERAL LLC	CREDO PETROLEUM CORP
CPR OPERATIONS LP	CREE IRA J
CQ ACQUISITION PTNRS I LP	CREEDE OIL AND GAS
CR SHORE LLC	CREEK OIL CO
CRA INTL LTD	CRENSHAW DOUG
CRABTREE OIL & GAS CO	CRESCENDO RESOURCES LP
CRADDOCK VIVA	CRESCENT EXPLORATION
CRADY DAVIS CO	CRESCENT INVESTMENTS
CRADY DAVIS CORP	CRESCENT PETRO CORP
CRAFT LEO OTTO	CRESCENT POINTENE US CORP
CРАГHEAD CARL R	CRESCENT PORTER HALE
CRAGWOOD ESTATES INC	CRESON PAUL
CRAIG INTL INC	CREST RESOURCES INC
CRAIG LTD	CRESTON PARTNERS L P
Craighead T C	CRESTONE ENERGY CORP
CRAIN M G	CRESWELL AUDREY L
CRAMER JOSEPH	CRETACEOUS ENERGY INC
CRAMER MAUDE	CRETACEOUS OIL CO
CRAMER MERCADE A	CREWS KATHERINE D
CRAMER OIL CO	CREWS SUSIE

Current BLM Oil and Gas Lessees:

CRIMSON PIPELINE, LP	CRUTCHFIELD FORREST
CRIST JAY K	CRW CORP
CRITELLI FAMILY TRUST	CRYSTAL J WILLIAMS
CRITES KEITH	CRYSTAL OIL CO
CROCKER NATL BANK TRST	CS OG LTD
CROFF OIL CO	CS OIL & GAS LTD
CROFT PETRO CO	CSC LLC
CROFT TONI W	CSG EXPL CO
CROFTS LINDA	CSM INC
CROMWELL D V	CTD INC
CROMWELL DAVID W	CTV O&G CO LLC
CRONIN THOMAS F	CTV O&G MULTI-STATE LLC
CROSBY HARRY L JR	CTV OG NM LLC
CROSBY HOWARD	CUCCIA L JAY
CROSBY STANLEY W III	CUERVO EXPL LLC
CROSSBOW CORP	CULBERTSON VERNE L
CROSSBOW RES LTD	CULBREATH FRED
CROSSLAND OIL CORP	CULLEN HARRY H
CROSSROADS HORIZON LLC	CULLEN LOIS ANN
CROUCH GERENE D C	CULLEN RICHARD P
CROW CREEK ENERGY II LLC	CULLEN ROY H
CROW DAVID	CULLINAN KATHLEEN
CROW REYNOLDS LTD	CULLINS CHRIS L
CROW ROY L	CULLINS HENRY L
CROWELL H J	CULLUM MAX
CROWELL JOHN H	CULLUM OIL & GAS INC
CROWN CENTRAL PETRO	CULTRERI JASHA
CROWN ENERGY PARTNERS LLC	CULTRERI SUSAN
CROWN FINANCIAL OIL & GAS LLC	CUMBERLAND PROP INC
CROWN OIL & GAS COMPANY INC	CUMMING IAN M
CROWN OIL CO INC	CUMMINGS DOUGLAS R
CROWN OIL PARTNERS III LP	CUMMINGS JAMES L JR
CROWN OIL PARTNERS LP	CUMMINGS OIL CO
CROWN OIL PTNRS II LP	CUNEO PETER J
CROWNPOINTE RESOURCE INC	CUNNINGHAM WILLIAM F
CROWNQUEST OPERATING LLC	CURLEE ALFRED T
CROWNROCK LP	CURNUTT JAMES W
CROWSON WELL SER INC	CURRENT ERNIE R
CRUMP FAMILY PARTNERSHIP LTD	CURRENT RESOURCES INC
CRUMP PETRO CORP	CURRY FLORENCE
CRUSADER ENERGY GROUP INC	CURRY & THORNTON
CRUSADER ENERGY GROUP LLC	CURRY DENISE A
CRUSADER ENERGY II LLC	CURRY FLORENCE
CRUSADER HOLDINGS LLC	CURRY JOHN SKEEN
CRUTCHER O&G-II LP	CURRY MAX E
CRUTCHFIELD EARL	CURTIS L NEELY MGMT

Current BLM Oil and Gas Lessees:

CURTIS LONETA S	D L INC
CURTISS-LUSHER BARRY	D M ALPHA INC
CURTISS-LUSHER GAY M	D M ROYALTIES LTD
CURTON CAPITAL CORP	D MCCLANE TRUST
CUSTER & WRIGHT	D NARREL TRUST
CUTBIRTH JACK	D O COCHENER TRST
CUTHBERT POWELL TRST	D P PROPERTIES INC
CUTHBERT RESOURCES LLC	D R FOUR BEAT ALLIANCE LLC
CUTLER EXPL	D R PENROSE TRUST
CUYAMA OIL & GAS CO	D Y EXPLORATION INC
CW BOLIN PROP LTD	D&G ROUSTABOUT SVC
CWF ENERGY INC	D2 RESOURCES LLC
CWM 2000-B LTD	D-4 RESOURCES CO
CWM 2000-C LTD	DAB INVESTMENTS
CXY ENERGY INC	DAB RES
CY OPERATING CO	DAB RESOURCES
CYBEROIL CORPORATION	DABBS WILLIAM M JR
CYPRESS INVESTORS LLC	DAC INTERESTS LLC
CYPRESS LAND ACQUISITIONS LLC	DAE-II
CYPRESS OPERATING INC	DAES OIL WELL SERVICE
CYPRESS PRODUCTION INC	DAESUNG ENERGY RES INC
CYPRUS GAS CORP	DAESUNG ENERGY RESOURCES INC
CYPRUS POWER CORP	DAGES J C
CYTON INC	DAHD INC
CZOR OG INC	DAHLBERG DOUGLAS JOANN TRST
D & B OIL INC	DAHLIN MERLYN W
D & D PTNRSHP	DAHLIN RUTH G
D & G ROUSTABOUT SVC	DAIL C WEST LP
D & J OIL CO	DAIL C WEST LTD PARTNERSHIP
D & M SNELSON PROPERTIES LP	DAILY MURPHY ANN
D A S RESOURCE VENTURES INC	DAKAKE LLC
D C H LP	DAKOTA GAS COMPANY LLC THE
D C TURNER TRUSTEE	DAKOTA MINERALS INC
D H ARRINGTON OIL & GAS INC	DAKOTA RESOURCES INC
D H INVESTMENT CO	DAKOTA WELLS LLC
D H INVESTMENT INC	DAKURAS PETER
D J INVESTMENT CO	DAL PTNRSHP
D J O'SHAUGHNESSY TRST	DALBRE CONSULTING
D J SIMMONS CO	DALE FRANK
D J SIMMONS CO LP	DALE HELEN B
D J SIMMONS CO LTD PRTNRSHP	DALE ROBERT L
D J SIMMONS CO LTD PTNRSHP	DALE SMITH TRUST
D J SIMMONS INC	DALMATIA ENERGY LLC
D K BOYD OIL & GAS CO INC	DALMORE LLC
D L COOK OIL PROP	DALPORT OIL CORP
D L HANNIFIN TRUST	DALSIN MARY JANE

Current BLM Oil and Gas Lessees:

DALTON JAMES F	DANNEBERG KENNETH I
DALTON TRUST THE	DANNIC ENERGY CORP
DAMAC DRILLING INC	DANSK PIPELINE LP
DAMAR ENERGY INC	DANVERS DAVID W
DAMON VICTOR L	DANVERS DON
DAMRON G W	DANVERS WILLIAM K
DAMRON GARY	DAR ENERGY INC
DAMRON LYNNE	DAR LLC
DAMSON 78-79 79-1	DARDANELLES PARTNERSHIP LTD
DAMSON 78-79 79-2	DARDEN JOAN
DAMSON 78-79 79-3	DARK PROPERTIES LLC
DAMSON 83-84 OG 84-1	DARNELL, BENTON
DAMSON 83-84 OG 84-3	DARRAH JOHN JAY JR
DAMSON 83-84 OG 84-4	DARROW FAMILY LLC
DAMSON 83-84 OG 84-5	DARRYL RABIDEAU FAMILY TRUST
DAMSON ENERGY A	DART ENERGY CORP
DAMSON ENERGY A LP	DART OIL&GAS CORP
DAMSON ENERGY B	DAS RESOURCE VENTURE
DAMSON ENERGY B LP	DASTARAC INC
DAMSON INST 82E-1	DAUBE COMPANY THE
DAMSON INST 83E-1	DAUBE PTNRSHP LTD
DAMSON INST 83E-3	DAUER ANN O'NEIL
DAMSON INST 84E-1	DAUGHERTY PETROLEUM INC
DAMSON INST OG	DAVE FITZGERALD INC
DAMSON OG 1984-1	DAVE R SYLVAN TRUST
DAMSON OG 1984-3	DAVEN CORP
DAMSON OG 1984-4	DAVENPORT-CARPENTER
DAMSON OG 1984-5	DAVID A WALDRON & ASSOC INC
DAMSON OIL CORP	DAVID ARRINGTON OIL & GAS
DAMSON SERIES 82E-1	DAVID B GOODSTEIN REVOCABLE TR
DAMSON SERIES 83E-1	DAVID BONNIE L
DAN A HUGHES CO	DAVID C TURNER FAMILY TRUST
DAN A HUGHES CO LP	DAVID C TURNER III REV TRUST
DAN H BOLIN TRUST	DAVID C TURNER TRST
DANA WILLIAM	DAVID E KANNENSTINE TESTA TRST
DANCE CREEK LLC	DAVID EDWARD KANNENSTINE
DANCING WATER LLC	TRUST
DANFORTH THEODORE H	DAVID EDWARD N
DANFORTH WM H JR	DAVID H ARRINGTON OG INC
DANIEL A NEEDHAM ESTATE	DAVID L GORDON ESTATE OF
DANIEL ENERGY INC	DAVID L HERBALY REVOCABLE TRST
DANIEL JACK	DAVID L HERBALY TRUST
DANIEL MICHAEL J	DAVID M LYTLE TRUST
DANIEL-PRICE EXPL CO	DAVID PETROLEUM CORP
DANIELS JOHN W ESTATE OF	DAVID R HILL INC
DANIELS PETROLEUM CO	DAVID ROBERT W

Current BLM Oil and Gas Lessees:

DAVID T RUSSELL LIVING TRUST	DAVIS WILLIAM B
DAVIDSON CHARLES JR	DAVOIL INC
DAVIDSON CHARLES W	DAVON CORP
DAVIDSON J A	DAVON DRILLING CO
DAVIDSON JAMES A	DAWSON ARTHUR CORP
DAVIDSON RUTH H	DAWSON FAMILY TRUST
DAVIDSON STEPHANIE	DAWURSK RONALD R
DAVIS BOB	DAY CAROL
DAVIS BOBBIE E	DAY W S
DAVIS BOBBY GALE	DAYBREAK OIL AND GAS INC
DAVIS BROTHERS	DAYNES MINA R
DAVIS C CRADY	DC ENERGY
DAVIS CHARLES B	DC ENERGY INC
DAVIS CHAS F	DC OIL & GAS I LLC
DAVIS DANIEL T	DC OIL & GAS II LLC
DAVIS DELMER	DCB OIL & GAS INC
DAVIS DONNA W	DCD OPERATING INC
DAVIS ED	DCOR LLC
DAVIS EDWARD MIKE	DCX RESOURCES LTD
DAVIS ENERGY LLC	DE LOACHE PRODUCING
DAVIS EVELYN C	DE LOYD (D L) COOK ESTATE OF
DAVIS FRANCIS H	DE PEREZ LOPEZ J H
DAVIS FRANK C III	DE&SK BARRET TRUSTEE
DAVIS GARY W	DEAN BETTY M
DAVIS H S	DEAN CHARLES A
DAVIS HENRY G	DEAN HAL S
DAVIS HUBERT	DEAN HARVEY
DAVIS IMOGENE	DEAN M ERICKSON TRST
DAVIS J B	DEAN SANDITEN MARITAL TRST
DAVIS J L	DEANS A J
DAVIS JOE D	DEATON LEON
DAVIS JOHN E	DEBBIE SCHMITT LLC
DAVIS LTD	DEBENHAM PETER
DAVIS MARK J	DEBETHIZY CYNTHIA L
DAVIS MARY	DEBOLT JERRY K
DAVIS OIL CO	DEBORAH S FAABORG SEP PROP TRS
DAVIS PETRO CO	DECALTA INTL CORP
DAVIS PETROLEUM CORP	DECCHANT EUGENE L
DAVIS R E	DECK OIL CO
DAVIS RESOURCES	DECKER ENE INVST LP
DAVIS ROCKY	DECKER OPERATING CO LLC
DAVIS ROGER H	DECLEVA PAUL
DAVIS THOMAS L	DECORDOVA EDWIN
DAVIS TOOL CO INC	DEE BENTLEY INC
DAVIS TRUST	DEE L T
DAVIS WALTER G	DEEMAR IRVING R

Current BLM Oil and Gas Lessees:

DEEP CRK ADVENTURES CO	DEMMING LESLIE B
DEEP GAS EXPL INC	DENALI DRILL SVC INC
DEER JAMES K	DENBURY ONSHORE LLC
DEER JOHN L	DENIS DAVID R
DEER JOSEPH H	DENISE HALE FAMILY TRUST
DEER TRACI C	DENIUS HOMER R
DEER TRUSTS	DENMAN GILBERT JR
DEER VALLEY LTD	DENMAN LEROY G JR
DEER VALLEY RESRCS LLC	DENNETT MINOT S
DEFALCO ALFRED JR	DENNIS BOB
DEGOLYER TRUST	DENNIS D
DEGROAT STEVE	DENNIS GEORGE S
DEHEKKER GLENN	DENNIS J RUE INC
DEHLINGER MARK T	DENNIS JAMIE
DEHLINGER REBECCA B	DENNIS W
DEJOUR ENERGY (USA) CORP	DENNY DONNA L K TRST
DEJOURNETTE DAUN T	DENNY ELLA NORA A
DEJOURNETTE RICHARD	DENOMA BAZLE L
DEK ENERGY CO	DENOMA HENRY A
DEK ENERGY COMPANY	DENOMA HENRY E
DEKALB ENERGY CO	DENOMA JAMES A EST
DEL RIO ENE LLC	DENOMA JAMES L
DEL RIO RESOURCES INC	DENTON CHARLES A
DELANEY DEAN KAY	DENTON DOUGLAS
DELAPHIN ENE RESOURCES I LLC	DENTON OIL CO
DELAWARE ROYALTY CO	DENVER AMER PETRO
DELAWARE VALLEY OG LLC	DEOSH LTD PTNRSHP
DELBARCO	DEP MINERAL SERVICES INC
DELBASIN CORP	DEP MINERAL SVCS INC
DELHI TRADING INC	DEPEW SPENCER L
DELLE DONNE ENERGY LLC	DEPOSIT GUARANTY
DELMAN ASSOCIATES	DEPUTY ROBERT W
DELMAR HUDSON LEWIS	DERBY ENERGY LLC
DELMAR HUDSON LEWIS LIV TRST	DEREK RESOURCES (USA) INC
DELMAR'S LIVING TRUST	DERKSEN DANIEL J
DELTA DRILLING CO	DERNBACH TIMOTHY A
DELTA ENE LLC	DERNICK HARRY
DELTA ENERGY LLC	DERNICK LAND & CO
DELTA LANDS EXPL INC	DERNICK RESOURCE INC
DELTA OIL CO	DERNICK RESOURCES
DELTA PETRO CORP	DERNICK RESOURCES INC
DELTA PETROLEUM CORP	DERNOCOEUR KATHARINE
DELTA ROYALTY CO INC	DERNOCOEUR KATHERINE
DELTAUS CORP	DERRICK PETROLEUM
DEMARET MARTHA C	DERRICK WILLIAM J
DEMEREEL PHILIP G	DERVISH ENERGY LLC

Current BLM Oil and Gas Lessees:

DESANDERS ALICE J	DIAMOND HEAD PROP
DESBROW LUNDA (GILL)	DIAMOND M DRILLING & EXPL CO
DESERET HOLDNG LLC	DIAMOND OIL LLC
DESERT DISCOVERIES LLC	DIAMOND PETRO GROUP
DESERT MOON GAS COMPANY	DIAMOND PETROLEUM CORP
DESERT RAINBOW LLC	DIAMOND RES CO
DESERT SPRINGS II LLC	DIAMOND RES INC
DESHAW LISA MORRISS	DIAMOND S ENERGY CO
DESJARLAIS JAMES P	DIAMOND STAR PRODUCTION CO
DESKIN RAY	LLC
DESTEC FUEL RES INC	DIAMONDBACK OIL PARTNERS LLP
DETEMPE-COLL MELANIE	DIAMONDBACK OIL PTNR
DEUEL ARCH W	DIANA O COCHENER TRUST EST
DEVER JOHN L	DIASU OG CO INC
DEVEREUX ALICE	DIASU OIL & GAS CORP
DEVEREUX ALICE F	DICE EXPL CO INC
DEVEREUX L H	DICKERSON HENRY H JR
DEVEREUX LAWRENCE	DICKINSON ENERGY LTD
DEVEREUX LAWRENCE F	DICKMAN NORBERT J
DEVILBISS GLEN	DICKSON ENERGY INC
DEVILS TOWER ENTPR	DICKSON ROBERT
DEVLIEGER CARL L	DIEFENDERFER MICHAEL
DEVNEY JOHN B	DIEFENDERFER MICHAEL R
DEVON CORP & EASON	DIETRICH PETRO CORP
DEVON ENE OPER CO LP	DIGRAPPA F S
DEVON ENE PROD CO LP	DILDA CLAUDIS J
DEVON ENERGY CORP	DILLARD A R JR
DEVON ENERGY CORP (NV)	DILLARD DARRELL M
DEVON ENERGY CORP NV	DILLARD FISHER & HEASLEY PTNRS
DEVON ENERGY OPER CO LP	DILL-KNOX WINNIE
DEVON ENERGY PROD CO LP	DILLMAN EARL
DEVON ENERGY PRODUCTION CO LP	DILLON HOLDING INC
DEVON ENERGY PTNRS	DIMIT CHARLES E
DEVON SFS OPERATING INC	DIMMITT JANIS GREEN
DEVON UNTA BASIN CORP	DIMOND GLENDA K
DEWEY STRINGER INTS	DIMOND MATTHEW
DEXTER RESOURCES CO	DIMOND MICHAEL R
DGM SUPPLY INC	DIMOND MINERALS LLC
DGQ PASSIVE INCOME	DIMOND ONE LLC
DH ESSEX AGENCY ACCT	DIMOND REVA
DH RESOURCE PARTNERS LTD	DIMOND SAMUEL R
DHB PTNRSHP	DINERO OPERATING CO
DHS DRILLING CO	DINERO PRODUCTION CO LLC
DIABLO OG CO	DINES T A
DIAKAN MINERALS LLC	DINGMAN OIL & GAS HOLDINGS
DIAMOND ENERGY LLC	

Current BLM Oil and Gas Lessees:

DINGUS INVESTMENT INC	DLB OIL & GAS INC
DINSMORE I W	DLD ENTERPRISES LLC
DIRT WORKS SERVICES	DLD ENTPR LLC
DISCOVERY ENTERPRISES LLC	DLYNN BRASWELL ASSOC
DISCOVERY EXPLORATION INC	DMA CO
DISCOVERY EXPLORER	DMF RESOURCES INC
DISCOVERY OIL LTD	D-MIL PROD INC
DISCOVERY OPERATING	DMK EXPLORATION INC
DITIRRO DAVE G	DMS OIL CO
DITTMER J C	DND LAND SERVICES LLC
DITTO A H	DNR O&G INC
DIVERSE ENERGY INC	DOBBS SOPHIA E
DIVERSE GP III	DOBSON EXPLORATION LLC
DIVERSE GROUP III	DODGE THECLA J
DIVERSIFIED ENE GP INC	DODSON EXPLORATION CO LLC
DIVERSIFIED ENERGY INVESTMENTS	DOELGER MARK J
DIVERSIFIED OPER	DOERR OPERATING LLC
DIVERSIFIED OPER COR	DOGGETT GLEN
DIVERSIFIED RES LTD	DOGGETT JAMES D
DIVIDE RES LLC	DOGGETT MARGARET
DIVINE JEREMY G	DOH OIL CO
DIVINE TEDDI C	DOHM CLARK HATHAWAY
DIX JOHN O SR	DOHM RICHARD RYLAND
DIX M W	DOL RESOURCES
DIXEY KENNETH M	DOL RESOURCES INC
DIXIE GEN BELL TRUST	DOLAR ENERGY LLC
DIXIE OIL & GAS CO	DOLAR MARK S
DIXIE PIPE CO	DOLAR OIL PROP LC
DIXIE-SHAMROCK O&G	DOLECEK RICHARD D
DIXON FRED L ESTATE	DOLESE ROGER M
DIXON JIM	DOLEZAL GEORGE JR
DIXON MABEL V	DOLLEY CHESTER F
DIXON VIOLET LONG	DOLORES BOLIN TRUST
DIXON W G	DOLPHIN ENE CORP
DIXON W PALMER	DOLPHIN ENERGY CORP
DJ INVESTMENT CO LTD	DOMAIN EXPL CO
DJ INVST CO LTD	DOME PETROLEUM CORP
DJ SIMMONS CO LP	DOME RSC INC
DJ SIMMONS CO LTD PARTNERSHIP	DOMINION APPALACHIAN
DJ SIMMONS CO LTD PTNRSHP	DOMINION BLACK WARRIOR BASIN
DJ SIMMONS CO PARTNERS	DOMINION EXPL & PROD INC
DJB & L LLC	DOMINION EXPLRN & PRODN INC
DK LAND SERVICES LLC	DOMINION MIDWEST
DKD PETRO LLC	DOMINION OK TX EXPL & PROD INC
DL CONE CHILDRENS TR	DOMINION RES INC
DL RESOURCES INC	DOMINION RESERVES

Current BLM Oil and Gas Lessees:

DOMINION TRANSMISSION INC  
DOMINO WY OIL CO  
DON BRADSHAW FAM TR  
DON F BRADSHAW FAMILY TRUST  
DON J LEEMAN REVOCABLE TR 1998  
DON LEEMAN TRUST  
DON O CHAPELL INC  
DON YOHE ENTERPR INC  
DONALD B ANDERSON FAMILY LP  
DONALD B ANDERSON LTD  
DONALD G PARSONS TR  
DONALD G PARSONS TRUST  
DONALD L TAUBERT TR  
DONALD PARSONS TRUST  
DONEGAN BEN  
DONEGAN LLC  
DONEGAN RUBY  
DONLIN EILEEN  
DONOSKY DAVID  
DONOVAN RUTH ELAINE TRUST B  
DOOLEY FLORENCE M  
DOOLIN MICHAEL  
DOOLITTLE TRUST  
DORAL ENERGY CORP  
DORALEX ENERGY INC  
DORAN EDWARD F JR  
DORAN JR EDWARD F  
DORCHESTER MASTER  
DORCHESTER MINERALS OPER LP  
DORCY OIL CO  
DORFMAN LOUIS  
DORFMAN SAM JR TST  
DOROTHY H STARRETT TRST  
DOROTHY T LEEDS TRUST  
DOROUGH T G TRUST  
DOROUGH THOMAS G  
DOROUGH THOMAS G JR  
DORSEY WILLIAM D  
DOS EQUIS OIL & GAS  
DOSS A K  
DOTSON LYNN ARDEN  
DOUBLE D NEVADA LLC  
DOUBLE DIAMOND ENERGY CORP  
DOUBLE EAGLE PETRO  
DOUBLE EAGLE PETRO & MINING CO  
DOUBLE EAGLE PETRO CO

DOUBLE EAGLE PETROLEUM CO  
DOUBLE EE PTNRSHP  
DOUBLE R PIPE & SUPPLY INC  
DOUBLE T RES LLC  
DOUBLE U OIL CO  
DOUBLE"D"GAS&OIL DARRELL  
YODER  
DOUD LAND CO LLC  
DOUG NIX FARMS INC  
DOUGHERTY FAMILY TRUST  
DOUGHERTY H W  
DOUGHERTY H W TRST  
DOUGHERTY SALLY J  
DOUGHERTY VIOLETA R  
DOUGLAS ARNOLD D  
DOUGLAS DALE  
DOUGLAS EARL E  
DOUGLAS L CONE TRUST  
DOUGLAS OIL & GAS LP  
DOUGLAS TATUM PETRO  
DOUGLAS WESTMORELAND LP  
DOUGLASS H HOWRT TRS  
DOW ALFRED P  
DOW ARTHUR  
DOW ARTHUR JAMES  
DOW DOUGLAS R  
DOW ORLANDO W  
DOW TATE ENERGY LLC  
DOWCO INC  
DOWDS JOHN P  
DOWDS JOHN S  
DOWLING SELMA  
DOWNING RICHARD  
DOYCO INC  
DOYLE BILL M  
DOYLE HARTMAN  
DOYLE HARTMAN OIL  
DOYLE HARTMAN OIL OPERATOR  
DRACO GAS PTNRS LTD  
DRAIN VINCENT E  
DRAIZEN GARY A  
DRAKE CAROLE J  
DRAKE JOE B  
DRAKE RAMSEY W  
DRAPKIN DONALD  
DREILING DRILLING

Current BLM Oil and Gas Lessees:

DREYFOUS JAMES C	DUNCAN ENTERPRISES INC
DREYFOUS JULES S	DUNCAN EXPL CO
DRIBER KRISTINE	DUNCAN GENE
DRILLMOR INC	DUNCAN GENE L
DRILMOR INC	DUNCAN J WALTER JR
DRIOC ACQUISITION LLC	DUNCAN JAMES O
DRM ENERGY CORPORATION	DUNCAN JOAN R
DRM PROPERTIES INC	DUNCAN MILLER LIQ TR
DROEGE ALBERT F	DUNCAN MILLER LQD TRUST
DROEGE FRANK M EST	DUNCAN NEEL L
DROEGE IRENE	DUNCAN OIL INC
DROEGE LEROY J	DUNCAN OIL PARTNERS
DROMEDIS SHIRLEE	DUNCAN OIL PROP
DRUKMAN PROPERTIES	DUNCAN P L
DRUKMAN PROPERTIES LLC	DUNCAN R T INC
DRW HOLDING CO LLC	DUNCAN RAYMOND T
DRX INC	DUNCAN VINCENT J
DRY CREEK INVESTMENTS	DUNCAN WALTER
DRY PINEY OIL CO	DUNCAN WALTER J JR
DUBITZKY ROY H	DUNDAS FAMILY CA PROP TRUST
DUBLIN JOHN JR	DUNE RESOURCES INC
DUCHARME OIL LLC	DUNHAM RICHARD E
DUDLEY & ASSOC LLC	DUNHAM TED JR
DUDLEY & ASSOCIATES	DUNHAM TED SR
DUDLEY J HUGHES LLC	DUNIGAN JOSEPH L
DUER WAGNER & CO	DUNLAP CHARLES T
DUER WAGNER III	DUNLAVEY J N
DUER WAGNER JR	DUNN AUBREY L SR
DUFF ARTHUR J TRUST	DUNN BETTY
DUFFIELD O F	DUNN FAMILY LTD PTNRSHP I
DUFFIELD SUE ANN	DUNN FRED B TRST
DUFRENE WELDON J SR UT EX	DUNN HELEN JANE
DUGAN A W	DUNN JEFFREY ALLEN
DUGAN C G	DUNN STEVEN S
DUGAN MARY D	DUNNAVANT L N
DUGAN PROD CORP	DUNWAY INVESTMENT CO
DUGAN PRODUCTION CORP	DUPERIER FRANK D
DUGAN THOMAS A	DUPONT NICHOLAS R
DUGGAN GLADYS A	DURAN ELOY S
DUGGAN MARY D	DURAN PROPERTIES LLC
DUGGAN SHIRLEY N	DURANGO CORP
DUGGAN-MCGEHEARTY SHIRLEY N	DURANGO PROD CORP
DUKE ADA MAXINE	DURANGO PRODUCTION CORP
DUNAGAN OIL CO INC	DURBAN LISA L
DUNBAR ROBERT	DURHAM DAVID A
DUNBAR WELL SVC INC	DURHAM FRED C

Current BLM Oil and Gas Lessees:

DURHAM FREDDA T	E KNOWLES TRUST
DURHAM INC	E L DOHENY INC
DURHAM KEVIN D	E M JOHNSTON TRUST
DUSTY MAC RESOURCES	E M NOMINEE PTNRSHP
DUTCH PETROLEUM LLC	E P C TRUST
DUTHIE JAMES H	E R HUDSON TRST 1
DUVALL BARBARA	E R HUDSON TRUST #4
DUVALL JACK	E R HUDSON TRUSTEE
DVORACEK JOHN	E S BIDDY TRUST
DWELLE PEGGY O	E TIMBERS PTNRSHP
DWG LLC	E TROMPETER TRST
DWIGHT G VEDDER CO	E&B NATURAL RES MGMT CORP
DWINNELL MICHAEL J	EAB OIL CO
DWYRE EDNA GAY H	EAC ENERGY CORP
DY EXPLORATION INC	EADS GRACE M
DYAD PETROLEUM CO	EAGLE ENERGY EXPLORATION INC
DYCO PETRO CORP	EAGLE ENERGY INC
DYCO PETROLEUM CORP	EAGLE OIL & GAS CO
DYE ANN	EAGLE OPER INC
DYE DANIEL	EAGLE-K PROD CO
DYE RICHARD J	EAGLESTONE ENERGY PARTNERS LP
DYER J G	EAKO LLC
DYK ENG	EARL A BENSON ESTATE
DYK ENGINEERING	EARL SCHWARTZ CO
DYK GWEN M	EARLEYWINE MOLLY
DYK WILLIAM A	EARLEYWINE ROD
DYKEMAN PETER B	EARLSBORO ENERGIES CORP
DYMATIC AMERICA INC	EARLSBORO ENERGY CORP
DYMOND SHIRLEY M	EARNEST PRODUCING CORP
DYNA OG CO INC	EARTH BOUNTY LP
DYNASTY OIL CORP	EARTHSTONE ENE INC
DYSART DOROTHY C	EARTHSTONE ENERGY INC
DZURIK INTERESTS INC	EAS OIL & GAS LLC
E & R INC	EASLEY JAY
E & S	EASLEY LOLA
E & S PETROLEUM LLC	EASLEY VERNON O
E C OHARA TRUST	EASON OIL CO
E DOYLE HUCKABAY LTD	EAST HELPER COALBED NATL GAS
E F STUCKY REV TRUST	EAST RESOURCES MANAGEMENT
E FORMAN ESTATE	LLC
E G L RESOURCES INC	EASTERN AMER ENERGY
E H S INC	EASTERN ENE CORP
E H WHITE TRUST	EASTERN STATES O&G
E HERRICK LOW TRUST	EASTEX III ENERGY PTNRS LLC
E J MCCURDY ESTATE	EASTEX VI ENERGY PARTNERS LLC
E J SULLIVAN TRST	EASTLAND OIL CO

Current BLM Oil and Gas Lessees:

EASTLAND RESOURCE INC	EDMONDS MGT CO
EASTMAN DILLON OG	EDMONDSON BEVERLY
EASTON BENNETT NICHOLAS	EDWARD A STUBER ESTATE
EASTON ELIZABETH RAGNHILD	EDWARD H EVERETT CO
EASTON LAURA ARMSTRONG	EDWARD HUNDSON TRUST
EASTON ROBERT L JR	EDWARD OIL CO
EATON ELIZABETH	EDWARD R HUDSON TRUST
EATON GILBERT J	EDWARD R HUDSON TRUST 1
EATON JEAN A	EDWARD R HUDSON TRUST 2
EATON ROBERT W	EDWARD R HUDSON TRUST 3
EATON VIRGINIA E	EDWARD R HUDSON TRUST 4
EAVES EVERETT	EDWARDS & DAVIS EN
EAVES LEA ANN	EDWARDS & HARDING PETROLEUM
EAVES MARIE	CO
EBEID RUSSELL J	EDWARDS DAVID T
EBERSTADT FREDERICK	EDWARDS ENERGY CORP
EBERT JUANITA M	EDWARDS KATE N
EBLEN F SYND INC	EDWARDS OIL CO
EBZERY THOMAS E	EDWIN R WALSH TRST
ECHO PROD INC	EDWIN R WALSH TRUST
ECHOLS HEATHER W	EEH NEWCO LLC
ECKELS C R F	EEX E&P CO LP
ECKELS CHRISTOPHER R	EEX OPER LP
ECKELS MILDRED P	EEX OPERATING LP
ECKELS R E	EG OPERATING
ECKELS RICHARD INC	EG3 INC
ECKELS ROBERT MAR TR	EGAN EMMA E
ECKERT EDWIN	EGAN JOHN P
ECLIPSE EXPL CORP	EGL RESOURCES INC
ECT ECOENE ENTER II	EHLERS MURRAY F
ED MAYS & ASSOC INC	EHRLICH GP LTD THE
ED MCQUEEN & CO INC	EHRLICH HAROLD B
ED N HARRISON TRST	EHW LLC
ED NOBLE TRUST	EI DUPONT DE NEMOURS
EDDY JERROLD W	EILAND GUY M
EDDY JOHN N	EILAND WILLIAM C
EDDY ROXIE M	EILEEN GREVEY LLC
EDELSTEIN DAVID H	EISENBERG LANCE
EDGE PETRO EXPL CO	EJF LTD
EDGE PETRO OPERATING INC	EKBLAD ROBERT L
EDGE PETROLEUM CORP	EL DORADO CORP
EDGE PETROLEUM EXPL CO	EL DORADO INVST AZ GEN PTNRSHP
EDGERTON HELENE	EL NORTE RESOURCES
EDINBURG INVESTMENT CO INC	EL PASO E & P CO LP
EDISTO RESOURCES	EL PASO E & P COMPANY LP
EDMONDS ENERGY CORP	EL PASO E&P CO LP

Current BLM Oil and Gas Lessees:

EL PASO E&P COMPANY LP	ELLEDGE OG LLC
EL PASO NATURAL GAS	ELLEDGE RANDY
EL PASO NATURAL GAS CO	ELLEN CRITTENDEN EST
EL PASO PROD O&G USA LP	ELLERTSON JON
EL PASO PROD OG CO	ELLERTSON WENDY
EL PASO PROD OIL & GAS USA LP	ELLIG KATHLEEN A
EL PASO PRODUCTION	ELLIMAN MARY FOWLER
EL PASO PRODUCTION CO	ELLINGFORD RUDY
EL PASO PRODUCTION COMPANY	ELLINGTON FREDERICK
EL PASO PRODUCTS CO	ELLIOTT & WALDRON
ELAN MINS LLC	ELLIOTT A RIGGS TRST
ELAND ENERGY INC	ELLIOTT ANNIE L
ELDER TOM	ELLIOTT FAMILY PARTNERSHIP
ELDREDGE KARY	ELLIOTT HALL CO
ELDRIDGE	ELLIOTT HALL CO LTD PTNRSHP
ELECTRA ENERGY CO	ELLIOTT HALL CO UT LP
ELECTRA INVESTMENT	ELLIOTT HOLLY L
ELEXO LAND SERVICES INC	ELLIOTT INDUST LTD PRTNRSHP
ELF AQUITAINE INC	ELLIOTT INDUSTRIES CO LP
ELGER EXPL INC	ELLIOTT INDUSTRIES LP
ELGER JERRY B	ELLIOTT INDUSTRIES LTD PTNRSHP
ELGIAR MILDRED	ELLIOTT INDUSTRIES NM LP
ELI PUBLISHING LLC	ELLIOTT IRA L
ELISA MARGARET HILL TRUST	ELLIOTT MGT CO
ELIZABETH KNOWLES REC TRUST	ELLIOTT ROGER T
ELIZABETH RAGNHILD EASTON TRST	ELLIOTT TED M
ELIZABETH W ALFORD	ELLIOTT-HALL CO
ELIZABETH WHITE TRUST	ELLIOTT-HALL CO LP
ELK ENERGY CORP	ELLIS EARL E
ELK EXPLORATION INC	ELLIS GLEN J JR
ELK HILLS HEAVY OIL LLC	ELLIS J RALPH JR
ELK HORSESHOE LLC	ELLIS MANNING TRST
ELK OIL CO	ELLIS OIL & GAS LLC
ELK OIL COMPANY	ELLIS RALPH D
ELK PETROLEUM INC	ELLISON BRUCE
ELK PRODUCTION LLC	ELLISON DOYLE G
ELK RESOURCES LLC	ELLORA LAND HOLDINGS LP
ELKHORN OIL & GAS	ELLSWORTH HELENE W
ELKINS CAMPBELL H	ELLWADE CORP
ELKINS DARRELL E	ELLWOOD EXPL LLC
ELLBOGEN CO II LLC	ELLWOOD EXPLORATION
ELLBOGEN COMPANY II LLC THE	ELLWOOD EXPLORATION LLC
ELLBOGEN PROP MGMT LTD	ELLWOOD OIL CO
ELLBOGEN PROP MGT LTD	ELLY B BEARD 2007 TRUST
ELLEDGE JOE	ELLY BEARD TRUSTEE
ELLEDGE LINDA	ELM RIDGE EXPL CO

Current BLM Oil and Gas Lessees:

ELM RIDGE EXPL CO LLC	ENCORE ENERGY INC
ELM RIDGE EXPLORATION CO LLC	ENCORE ENERGY PARTNERS
ELM RIDGE OPER CO INC	OPERATI
ELMER L HERBALY REVOCABLE	ENCORE ENERGY PRTNRS OPER LLC
TRST	ENCORE EX LLC
ELMIRA ANTRIM CO	ENCORE OPER LLC
ELMYRA MCKAY TRUST	ENCORE OPER LP
ELSON OIL CO	ENCORE OPERATING LA LLC
ELYSIUM ENTERPRISES LP	ENCORE OPERATING LP
ELYSIUM NATURAL RESOURCES LLC	ENDEAVER ENERGY RES LP
ELYSIUM RUSSELL LLC	ENDEAVOR ENE RES LP
ELYSIUM WEST LLC	ENDEAVOR ENERGY LLC
EMC ENERGIES INC	ENDEAVOR ENERGY RESOURCES LP
EMEFCO PETRO INC	ENDEAVOR EXPL
EMENAHA LEO	ENDEAVOR NATURAZL GAS II LLC
EMERALD GAS CO	ENDEAVOUR OPERATING CORP
EMERALD OIL & MINING CO	ENDURANCE RESOURCES LLC
EMERALD OPERATING CO	ENDURING RESOURCES LLC
EMERALD PETRO CO	ENDURING STBU LLC
EMERALD RES INC	ENE RES OF ND
EMERALD SAN JUAN CO	ENER CORP
EMERGENT VALUE GROUP LLC	ENERCORP RES INC
EMERGENT VALUE GROUP LLC SER A	ENERDYNE CORP
EMERGENT VALVE GROUP LLC SER A	ENERDYNE LLC
EMERY JAYNN M	ENERGCORP INC
EMERY PAM	ENERGEN RES CORP
EMG OIL PROPERTIES INC	ENERGEN RESOURCES CO
EMILY A KANNENSTINE TESTA TRST	ENERGEN RESOURCES CORP
EMILY ANN KANNENSTINE TRUST	ENERGEN RESOURCES MAQ INC
EMJAYCO LP	ENERGETICS 1988 LP
EMMA P MERKLEY TRUST	ENERGETICS 78 LTD
EMPIRE ENERGY CORPORATION	ENERGETICS 81 LTD
EMPIRE ENERGY E&P LLC	ENERGETICS CAPITAL LP
EMPIRE GAS CORP	ENERGETICS INC
EMPIRE OIL CO	ENERGETICS OPER CO
EMPIRE PETROLEUM CORP	ENERGEX CO
EMPL OF CRW CORP	ENERGY & EXPL PARTNERS LLC
EMPRISE INTERNATIONAL INC	ENERGY ACQUISITION
ENCANA O&G (USA) INC	ENERGY ASSOCIATES INC
ENCANA OG USA INC	ENERGY CONSULTANTS LLC
ENCANA OIL & GAS (USA) INC	ENERGY CORP OF AMERICA
ENCANA OIL & GAS CORPORATION	ENERGY CORPORATION OF AMERICA
ENCANA OIL & GAS USA INC	ENERGY DEV CORP
ENCLAVE OPERATING LLC	ENERGY EQUITIES INC
ENCORE ACQUISITION CO	ENERGY EQUITY CO
ENCORE ENE PTNRS OP LLC	ENERGY EQUITY COMPANY

Current BLM Oil and Gas Lessees:

ENERGY EXPLORATION OF NV LLC	ENERVEST ENE INSTNL FUND X-WI
ENERGY INVESTMENT 1986	ENERVEST ENERGY LP
ENERGY INVESTMENTS	ENERVEST HOLDING LP
ENERGY INVESTMENTS INC	ENERVEST MESA LLC
ENERGY INVSTS INC	ENERVEST MGT CO
ENERGY MINERALS CORP	ENERVEST OPER LLC
ENERGY MINERALS INC	ENERVEST PRODUCTION PARTNERS
ENERGY OIL & GAS EXP	ENERVEST PRODUCTION PTNRS LTD
ENERGY OIL INC	ENERVEST SAN JUAN
ENERGY OPERATIONS NV LP	ENERVEST WACHOVIA CO-INVSTMNT
ENERGY PRODUCTION LLC	ENERVEST WV LP
ENERGY PROP 2000-I LLC	ENERVST E LTD PTNRSP
ENERGY PROPERTIES 2006-1 LLC	ENEX RESOURCES CORP
ENERGY PROPERTIES 2006-I LLC	ENFIELD MONA L
ENERGY PROPERTIES 2006-I LLC	ENFIELD ROBERT N
ENERGY PTNRS NOMINEE	ENGLAND ENERGY LLC
ENERGY PTNRS NOMINEE CO	ENGLAND OPERATING LLC
ENERGY RES GROUP INC	ENGLAND RES CORP
ENERGY RESERVE GROUP	ENGLE FRED L
ENERGY RESOURCE GROUP ONE INC	ENGLERT MICHAEL W
ENERGY RESOURCE LLC	ENGLISH O B
ENERGY RESOURCES INC	ENGWALL CARL
ENERGY SEARCH	ENGWALL LIVING TRUST
ENERGY SEARCH INC	ENGWALL RUTH
ENERGY WEST CORP	ENLINE RESOURCES LTD PTNRS
ENERGY WEST CORPORATION	ENLOW JEWELL
ENERGY WEST DEV INC	ENNEX COS
ENERGY WEST RES	ENOGEK EXPL CORP
ENERGYONE PARTNERS LLC	ENRIGHT DONALD F
ENERGYQUEST II LLC	ENSCO RESOURCES CO
ENERLOC RES INC	ENSCO TOOL & SUPPLY
ENERPLUS RESOURCES (USA) CORP	ENSERCH CORP
ENERQUEST O&G LTD	ENSERCH EXPL INC
ENERQUEST OIL & GAS LTD	ENSIGN OPER CO
ENERSTAR RES LTD CO	ENSIGN OPERATING
ENERSTAR RESOURCES OG LLC	ENSIGN OPERATING CO
ENERTREE LLC	ENSTAR CORP
ENERVEST ENE INST FUND X-A LP	ENSTOR GRAMA RIDGE S&T LLC
ENERVEST ENE INST FUND XI-A LP	ENTECH ENTERPRISES
ENERVEST ENE INST FUND XIWI LP	ENTEK GRB LLC
ENERVEST ENE INST FUND X-WI LP	ENTERPRISE 1987 LTD
ENERVEST ENE INSTNL FUND IX LP	ENTERPRISE ENE INC
ENERVEST ENE INSTNL FUND IX-WI	ENTERPRISE GAS CO
ENERVEST ENE INSTNL FUND X-A	ENTERPRISE RES INC
ENERVEST ENE INSTNL FUND XI-A	
ENERVEST ENE INSTNL FUND XI-WI	

Current BLM Oil and Gas Lessees:

ENTRADA ENTERPRISES LLC	ERNEST E HEISER TRST
ENTRAL RES TRUST	ERNEST KANZLER TRUST
ENVIROSEARCH 82 O&G	ERPF ARMAND G
ENVIROSEARCH CORP	ERVIN EDWARD L
ENVY ENERGY LLC	ERVIN MARILYN JOY
EOG RES INC	ERYNOIL PARTNERS
EOG RESOURCES INC	ESCO EXPL EMPLOYEES
EOG RESOURCES CALIF LLC	ESCO EXPL USA LTD
EOG RESOURCES INC	ESCO EXPLORATION INC
EOG RESOURCES LLC	ESCOR INC
EOG RESOURCES, INC.	ESCUE NELSON B
EOR LLC	ESPERANZA CORP
EP OIL VENTURES GP	ESPERANZA ENE CORP
EP SAN JUAN LP	ESPESETH JOHN H
EPC ENERGY PARTNERS LTD	ESSEX DAVID H
EPIC RESOURCES LLC	ESSEX EXPL INC
EPLY JOHN CAPERTON TRUST	ESSEX PETROLEUM CORP
EPLY SAMUEL CANNON TRUST	ESSIA A NEAL TRUST
EPLY SCOTT W	ESSLINGER JON
EPOCH RES INC	ESSLINGER LOUISE J
EPS RES INC	ESSMAN JAMES W
EPX CO	ESTABROOK J E EST
EQ ENERGY LLC	ESTABROOK LOUISE ORR
EQT PRODUCTION COMPANY	ESTANCIA PETRO CORP
EQUITABLE GAS CO	ESTATE OF HEWITT B FOX
EQUITABLE PROD CO	ESTATE OF TIMOTHY T LEONARD
EQUITABLE PRODUCTION CO	ESTELLE EYERLY EST
EQUITABLE PRODUCTION COMPANY	ESTELLE H YATES 1976 TRUST
EQUITABLE RES ENE CO	ESTHER ASTON ESTATE
EQUITABLE RES EXPL INC	ESTORIL PROD CORP
EQUITABLE ROYALTY CORP	ESTORIL PRODUCING
EQUITRANS	ETHREDGE WILLIAM D
EQUITRANS INC	ETKIND GAS CORP
EQUITY OIL CO	ETKIND OIL LLP
EQUUS ENERGY CORP	EUBANKS ROBERT E
ERC IND INC	EUCKER WILLIAM III
ERC INDUSTRIES INC	EUGENE H DOBBS TRUST
ERFURDT JAMES H	EULA M JOHNSTON TR
ERG RESOURCES LLC	EUNICE WELL SVC CO
ERGON OIL PURCHASING INC	EURAMPEX INDUSTRIES
ERICKSON E TRUSTEE	EURATEX CORP
ERICKSON ELEANOR J	EUREKA GAS CO INC
ERICKSON THOMAS	EURO AMERICAN OIL LLP LLC
ERICSON REBECCA S	EUROPA ENERGY INC
ERNEST A HANSON ESTATE	EV PROPERTIES LP
ERNEST DOW & SONS	EVANGELICAL CENTER

Current BLM Oil and Gas Lessees:

EVANS ANTONY C	EXXON MOBIL CORP
EVANS DAN	EXXON CORP
EVANS DAVID M	EXXON MOBIL CORP
EVANS DUANE	EXXON MOBIL LAND RESOURCES
EVANS HAROLD	EXXON MOBIL OIL CORP
EVANS RAYMOND	EXXONMOBIL CORPORATION
EVANS S LAVON JR OPE	EXXONMOBIL OIL CORP
EVANS STEPHEN B	EYNON RICHARD R
EVANS SUE	EZZELL CALDER T
EVANS TERRENCE D	F & H SCHULTZ TRST
EVELYN G BROWN TRST	F & J ENERGY CORP
EVENINGSLIDE CO LC	F & M OIL & GAS CO
EVERETT DRLG VENTURE	F M TARPLEY TRUST
EVERETT FRERICHS OIL PROD	F P OMAN TRUST
EVERETT JESSE	F PETROLEUM INC
EVERFLOW EASTERN INC	FA UTAH PARTNERS
EVERFLOW ESTN PTR LP	FABIAN F G JR
EVERGREEN ENERGY INC	FAGAN HELEN
EVERGREEN PETROLEUM CO LLC	FAGAN PAUL I III
EVERGREEN RESOURCES INC	FAGEN NANCY
EVERLAST ENERGY LLC	FAHRNY DAVID L
EVERTSON ENERGY PARTNERS LLC	FAILS THOMAS G
EVERTSON EXPL LLC	FAIR JAMES W
EVERTSON OIL CO	FAIR OIL LTD
EVERTSON OIL CO INC	FAIR W Y
EVERTSON OPER CO INC	FAIRCHILD OIL CORP
EVERVEST ACQUISITION	FAIRMON MAYBELLE
EWALT ROBERT E	FAIRVIEW PRODUCTION
EWING OLA B	FAIRWAY ENERGY LLC
EWING TOMMYE G	FAIRWAY EXPL CO INC
EXBY LTD	FAIRWAY RES INC
EXCALIBER ENERGY CO	FAIRWAY RESOURCES OPER LLC
EXCALIBUR ENE CO	FAIRWAY RESOURCES PARTNERS LP
EXCEL ENERGY CORP	FAIRWAYS EXPLORATION & PROD
EXCHANGE OIL INC	FAITH DRILLING INC
EXCO N COAST ENERGY EASTERN	FALCK ROY
EXCO RESOURCES INC	FALCON ACQUISITIONS
EXCOA OIL & GAS INC	FALCON ENERGY LLC
EXOK INC	FALCON ENG CO INC
EXPLORERS PETRO CORP	FALCON OG CO INC
EXPRESS AIR DRILLING	FALCON PETROLEUM CO
EXPRESS ENERGY LLC	FALCON SEABOARD INC
EXTERRA RESOURCES LLC	FALCON SEABOARD OIL & GAS
EXXEL ENERGY (USA) INC	FALCON SEABOARD OIL & GAS LLC
EXXEL ENERGY (USA) INC.	FALKOWSKI BRENDA A
EXXEL ENERGY USA INC	FALL CREEK

Current BLM Oil and Gas Lessees:

FALLS DISTRIBUTING	FASKEN NEVADA 1 LLC
FAMCOR OIL INC	FASKEN OIL & RANCH LTD
FAMEL YVONNE #1	FAUGHT JR JESSE A
FAMEL YVONNE #2	FAULCONER 1996 LTD PRTNRSHP
FANCHER GEORGE H JR	FAULCONER 2005 LP
FANCHER OIL CO	FAULCONER ENERGY
FANCHER OIL LLC	FAULCONER RES 1992 LP
FANCHER RESOURCES LLC	FAULCONER RES 2000 LP LLP
FANCHER RESOURCES LLC	FAULCONER RES 2009 LTD
FANTE STEVEN	FAULCONER RESOURCES 1999 LP
FANTE SUSAN	FAULCONER RESOURCES 2000 LP LLC
FAR WEST MINERALS	FAULCONER RESOURCES 2001 LP
FARGO WESTERN OIL CO	FAULCONER RESOURCES 2007 LP LL
FARINHOLT MARGARET M	FAULKINBERRY JOHN L
FARIS PETROLEUM INC	FAY CORP
FARLEIGH BILL D	F-CO HOLDINGS DOMESTIC LLC
FARLEIGH BILL D TRUST	FDIC
FARLEIGH CORP	FEAR HERBERT E
FARLEIGH OIL PROP	FEATHERSTONE ANGELA
FARLEIGH SUZANNA G	FEATHERSTONE CHARLA M
FARLEY THOMAS H JR	FEATHERSTONE DEV
FARLEY WAYNE L	FEATHERSTONE DEV CORP
FARMAN HARRIET JANE	FEATHERSTONE DEVELOPMENT
FARMAN RICHARD J	FEATHERSTONE FARMS
FARMER DAVID	FEATHERSTONE MARTHA
FARMER KENNETH K	FEATHERSTONE OLEN F
FARMER MINERALS LLC	FEATHERSTONE OLEN II
FARMERS OIL CO	FEATHERSTONE TRES
FARMS FRED M NELSON	FEDCO MANAGEMENT CO
FARNHAM CHARLES W	FEDERAL DEPOSIT INS CORP
FARNSWORTH ENERGY LLC	FEDERATED GAS & OIL
FARNSWORTH TRUST	FEDERATED NAT RES
FARNSWORTH&KAISER DRILL CO	FEDERATED O&G PROPERTIES INC
INC	FEDERATED OIL & GAS PROPERTIES
FARRAR OIL CO	FEDRIC DON M
FARRELL THOMAS G	FEELIN FIT PRODUCTS
FARRIS & ASSOCIATES PC	FEES INTERVIVOS TR 1
FARRIS MADGE	FEES MARCEIL TRST
FARRIS MARGARET	FEES REVOCABLE TRUST
FARWEST CORP	FEES W S JR TRST
FASKEN ACQ 95-1 LTD	FEES WALTER S III
FASKEN ACQUISITIONS 02 LTD	FEES WALTER S JR
FASKEN BARBARA	FEES WALTER S TRST
FASKEN LAND & MINERA	FEES-KREY INC
FASKEN LAND & MINERALS LTD	FELDMANN ALLEN W
FASKEN LTD	FELDT C L

Current BLM Oil and Gas Lessees:

FELL & WOLFE OIL CO	FIKE KAY L
FELL GREGORY L	FILAN ARNE B
FELLHOELTER HERMAN H JR	FILAN ARNE L
FELLOWS ENERGY LTD	FINA OIL & CHEMICAL CO
FELMONT OIL CO	FINAL FOUR
FELTER JACK L	FINCH WILLIAM J
FENDER PATRICIA O	FIND OIL & GAS CO
FENN BILL	FIND OIL & GAS CO A PARTNERSHP
FENSTER HARVEY	FINDERS OG CO
FERDIG OIL COMPANY, INC	FINE LINE OG NM LLC
FERGUSON & BOSWORTH	FINK H B
FERGUSON 1978 DRLG	FINK JEAN SNYDE
FERGUSON CHASE GERENE DIANE	FINK RUTH G
FERGUSON DOUGLAS W	FINKBEINER W KURT
FERGUSON FLOYD J	FINKENBINE CHARLES
FERGUSON JACK	FINKLEMAN STEVE
FERGUSON JACQUELINE	FINLAY RICHARD R
FERGUSON JIM G	FINLEY CO
FERGUSON ROBERT B	FINLEY JAMES D
FERGUSON ROBERT B TRUSTEE	FINLEY PETRO INC
FERGUSTON SEARCY M	FINLEY RESOURCES INC
FERRARA DIAN	FINLEY ROYCE
FERREBEE	FINN LAWRENCE J
FERREBEE FAMILY TRUST	FINNEY DARREL
FERRET EXPL CO INC	FINNEY JACK
FERRIS FAMILY REVOC TRST	FINNEY MARY
FERRIS JOHN L	FINNEY SHIRLEE
FERRY LAKE OIL CO INC	FINSTERWALD D SOPHIA
FETNER WILLIAM W	FINWING CORP
FGP GASS LLC	FIREWATER INC
FIDELITY EXPL & PROD CO	FIRST CALGARY USA
FIDELITY EXPL & PROD COMPANY	FIRST CENTURY OIL
FIDELITY EXPL & PROD INC	FIRST CENTURY OIL INC
FIDELITY EXPL & PRODUCTION CO	FIRST CHR NAZARENE
FIDELITY EXPLORATION & PROD CO	FIRST CITY OIL & GAS LLC
FIDELITY OIL CO	FIRST CITY TEXAS
FIDELITY OIL CO TRUSTEE	FIRST ENE CORP
FIDLER A	FIRST GRIFFIN GROUP, LLC
FIDLER D A	FIRST INTERSTATE BANK
FIDLER J	FIRST INTL BK OF AZ
FIELD CARL B	FIRST INTST SW INC
FIELD DONALD L	FIRST NATIONAL BANK
FIELD DONALD L JR	FIRST NATIONAL CO OF MARSHALL
FIGEL PATTY	FIRST NATL BANK
FIGENSHAW MARY C	FIRST NATL BANK TRST
FIGGIE INTERNATIONAL INC	FIRST PRESBYTERIAN

Current BLM Oil and Gas Lessees:

FIRST ROSWELL CO	FIVE TALENTS LTD
FIRST ROSWELL CO LTD	FIXELL SHIRLEY
FIRST SOURCENERGY WYOMING INC	FLAG REDFERN OIL CO
FIRST STATE BK TRUST	FLAME ROALTIES INC
FIRST ZONE PROD INC	FLARE ENE CORP
FISCHER JAMES	FLARE PETRO INC
FISCHER RICHARD	FLATIROS DEVELOPMENT
FISCHGRUND BEVERLY	FLATIROS RESOURCES LLC
FISCHGRUND JAMES	FLEHMER PROP LLC
FISCHMAN H O	FLEHMER PROPERTIES LLC
FISCO	FLEISCHAKER FAMILY
FISCO INC	FLEMING REV TRUST
FISHER DENNIS J	FLEMING TRUST
FISHER ENTERPRISES	FLETCHER JACK
FISHER KATHLEEN	FLETCHER L
FISHER MARY R	FLETCHER LOY C
FISHMAN ROBERTA J	FLETCHER LOY G
FISHMAN WILLIAM R	FLICK JUDY J
FISKE ENERGY LTD	FLIGINGER MARK
FITCH CHARLES D	FLINN SANDRA
FITE OIL & GAS INC	FLINT-BOYD EMILY
FITKIN PETRO CORP	FLINT-WAYTE ROSEMARY
FITTING RALPH U JR	FLOOS INC
FITTING ROBERT D	FLORENCE FAMILY TRST
FITZGERALD KEVIN M	FLORENCE MAYO ESTATE
FITZGERALD MARY J	FLORENCE MIKE E JR
FITZGERALD TEXAS	FLORES JOHN V
FITZPATRICK FRANK W	FLORES LLC
FITZPATRICK J	FLORY DARLENE G
FITZPATRICK JOHN WM	FLORY TED L
FITZPATRICK REVOCABLE TRUST	FLOW PRODUCTION CO
FITZSIMMONS LLC	FLOWER CHRISTOPHER
FIVE 30'S OIL & GAS	FLOWER WILLIAM S
FIVE STAR ENERGY LLC	FLOYD E SAGELY PROPERTIES LTD
FIVE STAR ROYALTY PARTNERS LTD	FLOYD ENERGY LTD
FIVE STATES 1991-A LTD	FLOYD F M
FIVE STATES 1993-C	FLOYD JAY E
FIVE STATES 1994-B	FLOYD KAY A
FIVE STATES 1995-B	FLOYD MURRAY & CO
FIVE STATES 1996-C	FLOYD OIL CO
FIVE STATES 1997-A	FLOYD OIL INC
FIVE STATES CONSOLIDATED I LTD	FLUDE JOHN W JR
FIVE STATES CONSOLIDATED II	FLUID POWER PUMP CO
FIVE STATES ENERGY CO	FLYING J OIL & GAS
FIVE STATES EXPL	FMC CORP
FIVE STATES TRADING	FMC OIL PROPERTIES

Current BLM Oil and Gas Lessees:

FMWI LLC	FORT R F
FOCUS ENERGY LLC	FORT SMITH
FOCUS EXPLORATION INC	FORT WILLIAM R
FOLEY ROBERT	FORT WORTH MINERALS
FOLGER ENERGY CO	FORT WORTH OPERATING CO LLC
FOLMAR WENDALL	FORTE ENERGY CORP
FOLSON C CRAIG	FORTE OIL PARTNERS
FOLSON CRAIG	FORTE ROBIN A
FONAY OIL & GAS LLC	FORTIN ENTERPRISES
FOOTE OIL AND GAS PROPERTIES	FORTIN ENTERPRISES INC
FORAN JOSEPH W	FORTIN MARY ALICE
FORAN OIL CO	FORTITUDE EXPL
FORAN SPECIAL PARTNERSHIP	FORTSON BEN J
FORBES MADELINE W	FORTSON OIL CO
FORBES PROPERTIES LLC	FORTUNA (US) LP
FORCE ANTRIM DEV INC	FORTUNA INVESTMENTS LLC
FORCE LARRY A	FORTUNA US LP
FORCENERGY GAS EXPL	FORTUNE NATURAL RESOURCES
FORCENERGY INC	CORP
FORCENERGY OFFSHORE	FORTUNE NATURAL RESRCS CORP
FORCENERGY ONSHORE	FORTUNE OIL LTD
FORCENERGY ONSHORE INC	FORWARD ENE LLC
FORD DON H	FOSNER L E
FORD GERALD R	FOSSIL CREEK ENERGY CO
FORD LOUIS M	FOSSIL CREEK RESOURCES LLC
FORD OIL & GAS LLC	FOSSIL ENERGY INC
FORD RANCH	FOSTER ALFRED F
FORD RANDELL K	FOSTER BARBARA H
FORD RUSSELL J	FOSTER CREEK CORP
FORD WILLIAM J	FOSTER DALE W
FORDE THOMAS JR	FOSTER HUGH K
FOREMAN ENTERPRISE	FOSTER KATHLEEN B
FOREMAN LOGAN N	FOSTER NORMAN H
FOREST ENERGY RESOURCES INC	FOSTER RANDALL R
FOREST OIL CORP	FOSTER ROSEMARY C
FOREST OIL CORPORATION	FOSTER-BROWN CO
FOREST OIL PERMIAN CORP	FOULSTON EXPL INC
FORMAN E ESTATE	FOUNDATION EN FUN IIIB HLD LLC
FORMAN ENERGY CORP	FOUNDATION ENE FUND 111-B LLC
FORREST R J JR	FOUNDATION ENE MGT LLC
FORREST RICHARD	FOUR G OIL CO
FORREST RICHARD J JR	FOUR G OIL PROPERTIES LLC
FORREST RICHARD JR	FOUR M CO
FORREST ROBERT H JR	FOUR STAR O&G CO
FORSTER THELMA	FOUR STAR OG CO
FORT OPERATING CO	FOUR STAR OIL & GAS

Current BLM Oil and Gas Lessees:

FOUR STAR OIL & GAS CO	FRANK NILSEN ENERGY
FOURMILE OIL CORP	FRANK W WINEGAR TRST
FOURNIER BEATRICE D	FRANKEL MORRIS S
FOURNIER PAUL	FRANKLEY LAWRENCE R
FOUR-TEN EXPL	FRANKLEY LAWRENCE W
FOUR-TEN EXPLORATION	FRANKLEY SUE C
FOUTS RONNIE	FRANKLIN RES INC
FOUTS TOM	FRANKLIN RESOURCES INC
FOUTS WILLIAM BRUCE	FRANKLIN RESOURCES LP
FOWLER ANTHONY P	FRANKS CASING CREW & RENTAL
FOWLER HENRY DRURY	FRANKS PETROLEUM INC
FOWLER JAMES E	FRANKTOWN COMM CHURC
FOWLER JOHN RBT JR	FRANZHEIM INVESTMENT
FOWLER JOSEPH T	FRAPART LEWIS
FOWLER LEONARD S	FRARRAR OIL COMPANY
FOWLER MICHAEL M	FRARY G S
FOWLER NICHOLAS N	FRASER ROBERT B
FOWLER ROBERT G	FRAZEY RICHARD E
FOWLER SARAH B	FRAZIER KENNETH S
FOX ENE & MINERALS	FRAZIER L S III
FOX ERNEST F FOX JR	FRAZIER ROBERT H
FOX F A	FRAZIER S LANHAM III
FOX HARRIET K C TRST	FRAZIER SHEILAH
FOXPARK O&G	FRED BOWMAN INC
FOY MICHAEL J	FRED BRAINARD ESTATE
FOY STEVEN R	FRED C TURNER ESTATE
FOYE-BUTLER JT VEN	FRED E TURNER LLC
FRAKER CARL W	FRED G YATES INC
FRALEY J B	FRED GOODSTEIN EST
FRALEY THOMAS H JR	FRED M NELSON FARMS
FRAM AMERICAS LLC	FRED MURPHY EST
FRAM GEORGE	FRED POOL TRUST
FRAM OPERATING LLC	FRED REYNOLDS ASSOC
FRAN FOX TRUST	FRED TURNER JR TRUST
FRAN FOX TRUST DATED 1/1/80	FREDDIE WHEELER H MOORE TRST
FRANCES A HENDRICKSON	FREDERICK JOHN
FRANCIS JOSEPH F	FREDERICKSON H M
FRANCO SERVICES INC	FREDLUND JOHN
FRANK & HENRIETTA SCHULTZ TRST	FREDONIA RESOURCE INC
FRANK C SIMS TRUST	FREED PETER
FRANK D BROWN TRUST	FREEDMAN HARRY M
FRANK G W	FREEDMAN O&G CO
FRANK GEORGE W JR	FREEDOM ENERGY INC
FRANK H GOWER TRUST	FREEDOM ENERGY LLC
FRANK J LEWIS	FREEDOM OIL & GAS INC
FRANK JENI L	FREEMAN EDNA J

Current BLM Oil and Gas Lessees:

FREEMAN INVESTMENTS	FULFER OIL & CATTLE CO LLC
FREEMAN PHILIP M	FULLER ANDREW P
FREEMAN W MERLE	FULLER IRENE S
FREEMAN WILLIAM E	FULLER PETRO INC
FREEPORT MCMORAN OIL & GAS	FULLER R P
FREESE LEE B	FULLER REX P
FREEWAY ENERGY PARTNERS LLC	FULLER RICHARD J
FREEWAY LANDS INC	FULLER W M
FRENCH DONALD E	FULLERTON JAMES B
FRENCH L R JR	FULTON COLLINS TRUST
FRENCH MARCIA FULLER	FULTON FUEL CO
FRICKEY INVSTMNT MGMT CO LLC	FULTON JOE K
FRICKEY NORTON	FULTON LOUIS
FRICKEY NORTON II	FULTON LOUIS F
FRIEDMAN DON	FULTON PRODUCING CO
FRIEDMAN J ROGER	FULTON R H
FRIEDMAN NANCY S	FULTON WILLIAM M
FRIEDMAN PATRICIA M	FUNDINGSLAND E L
FRIEDMAN ROGER J	FUSSEL BARBARA TRUST
FRIKON ENE CORP	FUSSEL ROY TRUSTEE
FRISON PAUL PETER	FUTURE ACQUISITION I LP
FRITZLER H H	FX ENERGY
FRIZELL JACK Q	FX NEVADA LLC
FROGVILLE EXPLOR & DEVELOP LLC	FX PROD CO INC
FRONT RANGE OIL & GAS LLC	FX PRODUCING CO INC
FRONTIER ACQ CORP	G & H BARBER TRUST
FRONTIER EXPL CO	G & H MINERALS LLC
FRONTIER OIL & GAS CO	G & H PRODUCTION COMPANY LLC
FRONTIER PARTNERSHIP	G & N OIL CO
FROST MARTHA T	G &G OG LLC
FROST NATIONAL BANK TRUSTEE	G A W OIL CO
FROST NATL BANK TRUSTEE NO 2	G B COOLIDGE INC
FROST NORMAN B	G C MAYFIELD ESTATE
FROSTMAN OIL CORP	G D PARKINSON EST
FRY TERRY E	G E OPERATING INC
FRYE DAVID	G E ROGERS LLC
FRYE DAVID E	G E STEVENS TRUST
FRYE RALPH M	G F BAUERDORF TRUST
FUCHS PAULA	G F COLLINS JR TRUST
FUEL EXPL INC	G G & P NM PTNRSHP
FUEL EXPLORATION LLC	G G Q PTNRSHP
FUEL PRODUCTS INC	G H EXPL INC
FUEL RES DEV CO	G H GOTTLIEB ESTATE
FUEL RESOURCES INC	G H LAND CO LLC
FULFER GREGG	G M LEWIS TRUST
FULFER OIL & CATTLE	G NICOLAYSEN SR TRST

Current BLM Oil and Gas Lessees:

G P II ENERGY INC	GAMMILL
G R OIL & GAS	GAMMILL-STRANAHAN
G R SCOTT TRUST	GANN A
G R TUCKER TRUSTEE	GANNAWAY DAVID
G SCHNEIDER OG LLC	GANNAWAY DAVID R
G SHANNON TRUSTEE	GAP EXPLORATION LTD
G SNOWDEN JR ESTATE	GARBER WILFRED F
G T EXPLORATION INC	GARCIA CHRISTINA O
G T KIMBELL ESTATE	GARCIA DAVID V
G W PETRO INC	GARCIA LORETTA J
G WILLIAM HURLEY REVOC TRUST	GARCIA STEPHEN T
G2 PETROLEUM	GARCO INC
G3 ENERGY LLC	GARD DON ALLAN
GABEL C H	GARDENIA INVESTMENTS LTD
GAC ENERGY CO	GARDINER ANNIE L
GACKLE ERNEST	GARDINER FRANK P
GACKLE ROBERT	GARDINER SAM D
GADDIS CALVIN P	GARDNER A A
GADDY RICHARD MICHAEL	GARDNER AILEEN
GADECO LLC	GARDNER DONALD W
GADOMSKI THERESE	GARDNER JOYCE K
GAERTNER EARL E	GARDNER RANDAL J
GAFFOLD C M	GARDNER ZORA
GAGER BARRY R	GAREL R WESTALL TRUST
GAHR J M	GAREY DONALD L
GAIL REDIN	GAREY SUSAN E
GAJH 1989 LTD PTNRS	GARFF BETTY
GALAXY OIL CO	GARFIELD COAL SALES
GALEY JOHN N	GARFIELD PATRICIA ANN
GALLAGHER C R JR	GARFIELD PATRICIA S
GALLAGHER CHERIE H	GARFINKLE ALLAN J
GALLASPY OIL PROP	GARG OIL
GALLATIN CO THE	GARLAND EVELYN W
GALLAWAY MARTH	GARLAND MAY ANN
GALLAWAY W M	GARLETT D W & CO
GALLAWAY WILLIAM	GARMAN M B
GALLEGOS JAKE E JR	GARMAN ROBERT D
GALLEGOS L MAX	GARNER BILLE
GALLIVAN LYLE B	GARNER BOB
GALLIVAN MARY B	GARNER PHILLIP M
GALLIVAN ROBERT J JR	GARNER TUCKER
GALLOUPE HATTIE ADMI	GARNER WELL SERVICE LLC
GALT TOM	GARONMER JOYCE K
GALUSKA GEORGE	GARRETT ALLEN
GALVEST INC	GARRETT DAN N SR
GAMBLE F R	GARRETT GAVIN R

Current BLM Oil and Gas Lessees:

GARRETT JERRY	GAY C MILLER TRUST
GARRETT JOHN P	GAY CORRINE M TRUST
GARRETT JOHN PATRICK	GAY MILLER TRUST
GARRETT JOHN R	GAYDEN WILLIAM K
GARRETT KEVIN WADE	GAYLORD EDWARD K II
GARRETT PETRO CORP	GAYLORD EDWARD L
GARRETT PETRO INC	GAYNO INC
GARRINGER REV TRUST	GAYNOR ARNOLD M
GARTH TALLMAN & ASSOC	GAZ LOUIS A
GARVEY JAMES S	GCM LTD LIABILITY CO
GARVEY JEAN K	GCRL ENE LTD
GARVEY JOHN REV TRST	GDANSK PETROLEUM INV
GARVEY OLIVE W	GEBIANO OIL & GAS CO
GARVEY SHIRLEY F	GEER D
GARVEY WILLARD W	GEERLINGS H J
GARVIN ROBERT F	GEESAMAN RICHARD C
GARY & SUZAN SMITH TRUST	GEESAMAN RICHARD E
GARY J LAMB INC	GEIMER THOMAS
GARY NANCY	GEIS HILDEGARD C
GARY S JR & ASSOC	GEITGEY JAMES E
GARY SAMUEL	GEJU OIL & GAS
GARY SAMUEL JR & ASSOC INC	GELINAS MARILYN C
GARY WILLIAMS CO THE	GEM & EYE UT GEN PRTNRSHP
GARY-WILLIAMS CO	GEM EXPLORATION WYOMING LLC
GARY-WILLIAMS OIL	GEM OIL INC
GARY-WILLIAMS PRODUCTION CO	GEMINI NATL RES INC
GAS ENTERPRISE CO	GEN PROD SVC INC
GAS FUTURES LTD	GENE COOK INC
GAS HOLDINGS INC	GENECOV A S ESTATE
GAS PRODUCTION ENTERPRISES	GENECOV A S TRUST
GAS VENTURES LLC	GENERAL ATLA RES INC
GAS WELL SERVICES INC	GENERAL CRUDE CO INC
GASCO	GENERAL MINERALS
GASCO ENERGY INC	GENERAL OIL CO
GASCO LTD PARTNERSHIP	GENERAL OPERATING CO
GASCO PRODUCTION CO	GENESIS GAS & OIL
GASCONADE OIL CO	GENESIS GAS & OIL CO LLC
GASH ROGER	GENESIS GAS & OIL LLC
GASPER RICE & ASSOC	GENESIS LTD
GASPER RICE RESOURCES LTD	GENESIS PETROLEUM US INC
GASTAR EXPLORATION USA INC	GENIUSZ A P TRUST
GASTON EXPL INC	GENIUSZ FAMILY TRUST
GATES MICHAEL W	GENIUSZ JAMES M
GATES-O'BRIEN INC	GENIUSZ TRUST
GATHERS INVESTMENT	GENIUSZ TRUST 8-89
GAVLICK DON	GENOA INC

Current BLM Oil and Gas Lessees:

GEO EXPLORATION INC	GERLACH CHARLES
GEO FINANCE INC	GERMANN GARY I
GEODYNE ENE INCOME PROD PA I-E	GERMANN THERESA J
GEODYNE ENE INCOME PROD PA I-F	GERMANY OIL CO
GEODYNE NOMINEE CORP	GERONIMO HOLDING CORP
GEODYNE PROD PRTNRSHP II-A	GEROR OIL LTD 1962
GEODYNE RES INC	GETTER THOMAS I
GEODYNE RESOURCES	GETTY OIL CO
GEODYNE RESOURCES INC	GETTY OIL EXPLORATION CO
GEO-FINANCE INC	GETTY RESERVE OIL INC
GEOLINEAR OG PGM 81	GETTY SARAH ESTATE
GEOMET INC	GETZLER CHARLES
GEO-PARTNERS LTD	GEYERMAN FAMILY LTD PTNRSHP
GEORESOURCES INC	GEYSER PETROLEUM
GEORGE B KENT TRUST	GG ROSE LLC
GEORGE BETTY S	GGM EXPLORATION INC
GEORGE CLEM E	GHK EXPL CO LP
GEORGE COLLINS TRUST	GHK POTATO HILLS LP
GEORGE DOLEZAL JR LP ONE LLLP	GIANETTI CHARLES D
GEORGE DOLEZAL JR LTD PTNRSHP	GIANOLA JOSEPH M
GEORGE DOLEZAL JR TRUST THE	GIANT EXPL & PROD CO
GEORGE E KENNEY TR	GIANT MID-CONTINENT
GEORGE F MADDOX & CO	GIBBARD VEVA JEAN
GEORGE KENN S	GIBBENS ELIZABETH C
GEORGE MEREDITH K	GIBBENS WAYNE
GEORGE PARKER EXPLS	GIBBONS J P
GEORGE R BAKER TRUST	GIBBS JAMES A
GEORGE RANDOLPH SCOTT TRUST	GIBRALTAR ENERGY CO
GEORGE S ECCLES EST	GIBSON BRIAN D
GEORGE SCOTT L JR	GIBSON FAMILY TRUST
GEORGE W PLANT DRILLING	GIBSON MARY C
GEORGE WALTER C	GIBSON RICHARD H
GEORGETOWN EXPL INC	GIBSON TOM C
GEORGETOWN EXPLORATION INC	GIBSON W R
GEOSEARCH INC	GID OIL CO
GEOSOUTHERN DEWITT PROP LLC	GIEBEL PETRO LTD
GEOSPECTRUM INC	GIETEMA WILLIAM JR
GEOSURVEYS INC	GIIC INC
GEOTECH PROD INC	GILBREATH LORETTA E
GEOVEST ENERGY INC	GILBREATH NORMAN L
GERAGHTY JERRIE B	GILCHRIST GEORGE C
GERALD E HARRINGTON TRUST	GILFORD ENERGY INC
GERALD FRIEDMAN FMLY TRST	GILFORD FIN CORP
GERARD C H C	GILL FAMILY TRUST 07/28/09
GERBER TRAVIS	GILL PRESS
GERHARD W HILL JR	GILLAN SILAS L

Current BLM Oil and Gas Lessees:

GILLAND ANDREW H	GM PROPERTIES
GILLEN COLLEEN	GMQ LLC
GILLEN DENNIS	GMT ENERGY CORP
GILLESPIE CHARLES B	GMT EXPL CO LLC
GILLESPIE COMPANY	GMT EXPLORATION COMPANY LLC
GILLESPIE JOHN W	GMX RESOURCES INC
GILLESPIE MARGERY	GNC ENERGY CORP
GILLILAND ALICE H	GNG LLC
GILLILAND MARY ALICE	GNK INC
GILLILAND WILLIAM R	GNR SAN JUAN LTD
GILLILAND ZACH	GODFREY T B
GILLIS JOYCE H	GOEDERT JEANNE K
GILLIS JOYCE TTEE	GOFF D C
GILMER BARBARA	GOLD CITY MINERAL PARTNERS LP
GILMORE DAVID W	GOLD CITY PARTNERS
GILMORE OIL & GAS	GOLD CITY PARTNERS VIII LP
GILMORE RESOURCES INC	GOLD COAST RESOURCES INC
GILMORE WILLIAM C	GOLD DAVID B
GILREATH CONTRACT SERV INC	GOLDBLATT ARNOLD L
GILSTER JUNIE OCONNOR TRUST	GOLDEN A G
GILSTER KATHRYN CARLISLE TRUST	GOLDEN ENERGY PARTNERS LLC
GINGER OIL COMPANY	GOLDEN GAS ENERGY
GIST RHETT	GOLDEN PARACHUTE INVSTMNT LLC
GKM OIL CO	GOLDEN PARADOX INC A DE CORP
GLACIER PARK CO	GOLDEN STATE OIL & GAS LP
GLADE CHRIS S	GOLDEN STONE RESOURCES LLC
GLADYS SHANNON TRST	GOLDKING ENE CORP
GLANTZ TOPSY JEAN	GOLDMAN A D
GLANVILLE JAMES	GOLDMAN JOSEPH TRST
GLASS W F	GOLDMAN M H
GLEASON LAILA M	GOLDMAN SALLY JO
GLENN BERNADINE	GOLDSMITH GERALD
GLENN LACKEY ESTATE	GOLIAD O&G NM LLC
GLENN MARY E	GOLIAD PARTNERSHIP
GLENN PAUL F	GOLIAD PTNRS
GLENN W PELL ESTATE	GOLOB DAVID JEREMY
GLENNAN JOHN JR	GOLOB ELIZABETH M
GLENWOOD RESOURCES INC	GOLTZ DENNIS J
GLESS&BULLIS CO-EX	GOMER & GOOBER INC
GLG ENERGY LP	GONZALES CHARLES B
GLICK WILLIAM L	GONZALES DANIEL E
GLICKMAN MILTON	GOOD RIDGE RES INC
GLNA LLC	GOODALE ENTERPRISES
GLOBAL ENE TECH LTD	GOODALL DEBORAH
GLOBAL METHANE	GOODALL GREGG E
GM OIL PROP INC	GOODMAN BEVERLY B

Current BLM Oil and Gas Lessees:

GOODMAN CAL	GOTTSTEIN J
GOODMAN ESTHER L	GOULD JOSEPH B
GOODMAN HENRY C	GOURLEY JOHN D
GOODMAN LINDA	GOWAN PETER A
GOODMAN MICHAEL	GOWER F H
GOODMAN NELSON	GOYER FRANCOIS J
GOODMAN RICHARD L	GPE ENERGY INC
GOODMAN-WALDMAN NANCY	GPM INC
GOODRICH JOHN S	G-R CONTRACTORS INC
GOODRICH PETRO CO OF LA	GRABLE ROBERT C
GOODRICH PETROLEUM	GRACE CORINNE B
GOODRICH PETROLEUM CO LLC	GRACE JOSEPH P
GOODSTEIN DAVID B	GRACE LEE M
GOODSTEIN INC	GRACE MICHAEL P II
GOODSTEIN LEAH	GRACE PETROLEUM CORP
GOODSTEIN MEYER	GRACE STEPHEN J
GOODSTEIN-EASTMAN FAMILY TRUST	GRADY FAMILY TRUST
GOODWIN SHERRAL	GRAFFION PETRO ETAL
GOODYEAR ZAIDEE B	GRAFFT DAVID HUNTER
GOOLSBY & ASSOCIATES LLC	GRAGG LAND & CATTLE
GOP INC	GRAHAM A T JR
GOP LLC	GRAHAM ACQ 1984-II
GORDON BALCH	GRAHAM ACQ 84-II
GORDON ENGINEERING	GRAHAM ENERGY INC
GORDON GENE	GRAHAM FAMILY INVESTEMENTS LLC
GORDON JOHN I	GRAHAM G
GORDY GAS CORP	GRAHAM JENNIFER
GORDY OIL COMPANY	GRAHAM JR A T
GORE PAUL	GRAHAM M
GOREE OIL & GAS LLC	GRAHAM RALPH E
GORHAM FRANK D	GRAHAM REALTY LTD
GORHAM FRANK D JR	GRAHAM RESOURCES INC
GORNICK ALAN L	GRAHAM ROBERT L
GOSE MATT	GRAHAM ROSALYNN S
GOSS CHARLES B	GRAHAM ROYALTY LTD
GOSS ROBERTA B	GRAHAM SUE S
GOTHIC ENE LLC	GRAHAM WILLIAM J
GOTHIC ENERGY CORP	GRAHAM-MICHAELIS CO
GOTHIC PRODUCTION CORP	GRAIG INTL INC
GOTT JIMALU IRENE	GRAMA RIDGE S & T LLC
GOTT THOMAS GARY	GRAMMAR JAMES L
GOTTESMAN DAVID S	GRAMMAR MARLENE
GOTTLIEB OYGAR P	GRAMMAR OIL/GAS LLC
GOTTLIEB TRUST FBO	GRANATELLI ANTHONY
GOTTSTEIN G L	GRANBERRY WALTER

Current BLM Oil and Gas Lessees:

GRANBERRY WALTER JR	GREAT NORTHERN GAS
GRAND VALLEY GAS CO	GREAT NORTHERN PETRO
GRANDE DRILLING CORP	GREAT NRN DRLG CO INC
GRANDE ENERGY COMPANY	GREAT NRN DRLNG CO
GRANDPRE MARY	GREAT NRN GAS CO
GRANGER DAVID	GREAT PLAINS OPTNG LLC
GRANGER JEFFREY S	GREAT RIVER O&G CORP
GRANITE ALFA CORP	GREAT WESTERN COAL
GRANITE CORP	GREAT WESTERN DRILLING LTD
GRANITE CORP LTD PTNRSHP	GREAT WESTERN DRLG
GRANITE OPERATING CO	GREAT WESTERN DRLG CO
GRANITE PACIFIC	GREAT WESTERN ONSHOR
GRANNICK RAE	GREAT WTN DRLG CO
GRANT CANYON OIL & GAS	GREEN DEBRA
GRANT CANYON OIL & GAS LLC	GREEN DIAMOND OIL LLC
GRANT JAMES B	GREEN DONALD C
GRANT LUCILLE B	GREEN GARY
GRANT STANLEY R	GREEN JOHN F
GRASS CREEK OIL CO	GREEN RIBBON INC
GRATTON PATRICK J F	GREEN RIVER BASIN
GRAUTEN JOHN S	GREEN RIVER EXPL
GRAVES JERRY	GREEN RIVER OG PTNR
GRAY CAROLYN	GREEN RIVER PETRO (USA) INC.
GRAY EDWARD F	GREEN RIVER RES INC
GRAY GARY M	GREEN RON
GRAY JAMES H	GREEN RUTH H
GRAY JOHN R	GREEN S WILLIAM
GRAY JOHN R TRUST	GREEN TWO INC
GRAY JOHNNY C	GREEN WILLIAM J
GRAY LISA CURRY	GREENBERG MCADAMS LLC
GRAY MARJORIE M	GREENBERG Z TRUST
GRAY MARTHA	GREENBRIAR ENERGY LP IV
GRAY TERRY E	GREENBRIER 93 LTD
GRAY WILFRED L	GREENBRIER ENERGY
GRAYHORSE ENERGY LLC	GREENE ROBERT W
GRAYROCK CORP	GREENFIELD OIL CO
GRD RESOURCES INC	GREENLAND PETROLEUM
GREAT AM EXPL CORP	GREENRIDGE ENERGY GROUP
GREAT AMER DRILLING	GREENSTAR ENERGY PROD LLC
GREAT EASTERN ENERGY	GREENVILLE PARTNERS
GREAT EASTERN-1978	GREENVILLE TRADING CO
GREAT LAKES ENERGY PTNRS LLC	GREENWADE OIL LTD
GREAT NATIONAL CORP	GREENWOOD ENERGY INC
GREAT NORTHERN DRILLING CO INC	GREENWOOD JAMES W
GREAT NORTHERN DRLG	GREENWOOD SHIRLEY
GREAT NORTHERN ENE INC	GREER ALBERT R

Current BLM Oil and Gas Lessees:

GREER ALTHEA L	GROVER ROSALIND R
GREER CHARLENE K	GROVES MURIEL C
GREER CHARLES A	GROVES OLIN E
GREER ENTPR LTD	GRUBBS D PATRICK
GREER NATHAN C	GRUBITZ GENE III TRUST
GREGORY & MERRION TRUST	GRUNSTEAD ROLAND
GREGORY A LUX TRUST	GRUSS PETRO CORP
GREGORY J D	GRUY
GREGORY JERRY D	GRUY WILLIAM A
GREGORY LOUIS K II	GRYNBERG CELESTE
GREGORY MERRION TRUST	GRYNBERG CELESTE C
GREMLIN OIL CO	GRYNBERG JACK J
GREVEY JACK	GRYNBERG PETROLEUM
GREVEY JOANNE	GRYSBOK LP
GREY HORSE HOLDINGS LLC	GS O&G CO 76
GREYSTAR USA INC	GT WYOMING LLC
GREYSTONE ENERGY INC	GTL OIL & GAS CORP
GREYSTONE PETROLEUM LLC	GUADALUPE ENERGY LTD
GREYSTONE RESOURCES INC	GUADALUPE OPERATING LP
GRIFFEN LEE	GUARANTY ENE GP 1981
GRIFFEN RESOURCES	GUARD EXPL LTD PARTNERSHIP
GRIFFIN & GRIFFIN EXPL LLC	GUARDIAN ENERGY MNFT CO
GRIFFIN BOB D	GUARDIAN OIL & GAS INC
GRIFFIN OILFIELD DEVELOPERS	GUFFEY WILLIAM R
GRIFFIN PETROLEUM CO	GUINN ESTATE
GRIFFIN RESOURCES LLC	GUION GRACE
GRIFFITH LAWRENCE	GULF COAST O&G CO
GRIFFITH WESLEY	GULF COAST WATER CO
GRIFFON & ASSOC LLC	GULF OIL CORP
GRIFFON & GRIFFON ENTPR INC	GULF PARTNERS
GRIGGS BURT	GULF PROD CORP
GRISCOM ELIZABETH S	GULF WESTERN GEOPHYSICAL LLC
GRISCOM RODMAN E	GULF WTN ENE CO
GRIZZLY ENERGY LLC	GULFPORT ENE CORP
GRIZZLY TRADING CO	GULFPORT ENERGY CORP
GROFF ARCHIE E	GUNDLACH KAY BARD
GRONINGER MABEL	GUNGOLL THELMA J
GRONINGER WM M	GUNLIKSON PETRO INC
GRONVOLD A F	GUNLIKSON PETROLEUM INC
GROSS FAMILY LTD	GUNLIKSON RICHARD D
GROSS FLORENCE	GUNNISON ENERGY CORP
GROSS MARVIN C	GUNSIGHT LP
GROSS OIL DE CORP	GUNSMOKE ENERGY COMPANY
GROVE ENERGY GROUP	GUREN JACK JR
GROVER ARDEN R	GURLEY LAKE LAND & CATTLE CO
GROVER FAMILY LTD PTNRSHP	GUTHRIE A K

Current BLM Oil and Gas Lessees:

GUTHRIE C W ESTATE	H WRIGHT TRUST
GUTHRIE MICHAEL T	H&R ENERGY LLC
GUTIERREZ ABSALON	HAAG WILLIAM L
GUTIERREZ CARMEL T	HAAS JAMES E
GUTTERMAN SCOTT	HAAS RAYMOND
GUY CLYDE	HABBIT ROBERT D
GUY JAMES E	HACIENDA ENERGY LLC
GUY JERRY W	HACKATHORN H A
GUYS OG LTD CO	HACKENSACK STEEL CRP
GUYTON STEVE	HACKING MARVA B
GVM TRUST	HADLEY HERBERT D
GW HOLDINGS INC	HADLOCK ELLEN K U
GW MERGER CORP	HAERTLEIN AL
GWINN MCMAHAN LEWIS INVES	HAFEMAN WILLIAM C
TRST	HAGAN CRISTINA E
GWJ EXPLORATION LLC	HAGEN SIDNEY I
GWR OPERATING CO	HAGER & ASSOCIATES
GXG INC	HAGER JOSEPH H
GYRODYNE PETRO INC	HAGGART KENNETH C
H & H O&G CO	HAGOOD HUGH
H & H STAR ENERGY INC	HAGOOD L N
H & L OPERATING CO	HAIGH ROBERT S
H & M OIL PRODUCERS INC	HAIL RESOURCES LLC
H & R O&G CO	HAIL TOM L
H & S OIL	HAINSWORTH TANYA A
H B HILLMAN TRUST	HAK PARTNERS - V
H C OIL CO INC	HAK V L
H H MCCOY TRUST	HAL J RASMUSSEN OPER
H HUBBARD TRUST	HALBERT JACK
H J FREEDE INC	HALBOUTY MICHAEL T
H L BIGLER TRUST	HALBOUTY MICHEL T
H L HALL & SONS	HALCYON NATURAL GAS
H M BETTIS INC	HALE DENISE TRUSTEE
H M REED TRUSTEE	HALE PRENTIS C III
H PAUL COHEN BENEFICIAL TRST	HALEY DONNA LEA
H PAUL COHEN BENEFICIAL TRUST	HALEY DUANE
H PAUL COHEN TRUST	HALEY W E
H PHILLIPS SR ESTATE	HALEY WENDALL E
H R CLAY III TRUST	HALF SHELL OIL CO
H R ROWLEY INC	HALL BILL P
H R STASNEY & SON	HALL ENERGY CO
H S & B LTD PTNRSHP	HALL GEORGE E
H SISK ESTATE	HALL KIM L MERKLEY
H W ALLEN CO	HALL PHEBE JANE
H W DOUGHERTY & CO	HALL THOMAS J III
H W GRINDALL ESTATE	HALLADOR PETRO CO

Current BLM Oil and Gas Lessees:

HALLADOR PETRO LLP	HANCOCK TRUST B
HALLIBURTON ENERGY SCV INC	HANCOCK WILLIAM J
HALLIBURTON ENERGY SVC INC	HANDEL STEVEN J
HALLIBURTON OIL PROD	HANDLE DANIEL
HALLS RUTH N	HANDLE PAUL
HALTER RICHARD F	HANDLE THOMAS A
HALVERSON CHARLES P	HANDO RONALD E
HALWELL CO INC	HANESCO INC
HAM MABEL G	HANEY JOHN R
HAMBLIN LIVING TRUST	HANEY W B
HAMILL ENERGY CO	HANFELD CO
HAMILL FNDTN	HANGER STEPHEN P
HAMILL FOUNDATION THE	HANKS CONSTANCE
HAMILL RESOURCES INC	HANKS PETROLEUM CORP
HAMILTON ARDIS NORTH	HANLEY PETRO INC
HAMILTON DEBRA J	HANLEY PETROLEUM INC
HAMILTON INT #3 INC	HANLEY ROBERT T
HAMILTON LEONARD	HANLEY W L JR
HAMILTON THOMAS J	HANNA JIM L
HAMILTON WILLSON C	HANNA O&G CO
HAMM MARY JANE	HANNA OG CO
HAMMACK JOHN A	HANNA OG CO A CORP
HAMMAN OIL & REFINING	HANNA OIL & GAS CO
HAMMER JR LEONARD H	HANNA OIL AND GAS
HAMMER REALTY GROUP INC	HANNIFAN PATRICK J
HAMMERSMITH REALTY	HANNIFIN BARBARA E
HAMMIT TRUMAN	HANNIFIN DANIELLE
HAMMOND DAVID G	HANNIFIN MARK A
HAMMOND EULA	HANNIFIN PATRICK J
HAMMOND WILLA B	HANNIFIN ROBERT H
HAMON OPERATING CO	HANNIFIN SHAWN P
HANAGAN HUGH E	HANNON & ASSOC INC
HANAGAN MICHAEL G	HANNON & ASSOCIATES INC
HANAGAN OIL PROP INC	HANOVER ENERGY CORP
HANAGAN PETROLEUM CORP	HANOVER PETRO CORP
HANAGAN PROP PTNRSHP	HAN-SAN INC
HANAGAN PROPERTIES	HANSEN LYNDA S
HANAGAN ROBERT G	HANSEN VELDA N
HANAGAN ROBERT W	HANSON & STRAHN INC
HANAHO	HANSON BRIAN
HANAU FRIEDRICH	HANSON DARYL J
HANCOCK BURTON W	HANSON DORIS E
HANCOCK CAROL E TRST	HANSON ELMER
HANCOCK ENTERPRISES	HANSON ENERGY CO
HANCOCK J MUTUAL LIFE INS CO	HANSON ERIC K
HANCOCK TRUST A	HANSON G V

Current BLM Oil and Gas Lessees:

HANSON GENE S	HARKEN GEN PTRNSHP
HANSON JAMES R	HARKEY ENERGY INC
HANSON JAMES WARREN	HARKINS LAURA L
HANSON KEVIN J	HARKINS T I
HANSON LORETTA	HARLE INC
HANSON MARY L	HARLOW ENTERPRISES
HANSON OPERATING CO	HARNER ROBERT C
HANSON RUTH	HAROLD & EVA HOLDEN LIVING TR
HANSON STUART D	HAROLD & EVA HOLDEN TRUST
HANSON WARREN	HAROLD KENTTA
HANSON-MCBRIDE PETROLEUM	HAROLD KOCH TRUST
HANTZ HOSEA M	HAROLD SHORE TRUST
HARADINE CARL	HAROLDSON HUNT JR
HARAKINS LAURA L	HARPEL JAMES W
HARBERT BILL L	HARPER MARY E
HARBOUR FREDERICK D	HARPER WAYNE
HARCO EXPLORATION	HARPEX INC
HARCO LP	HARRELL ELDON L
HARCO PTNRSHP	HARRELL ENERGY CO
HARCO TEXAS LLC	HARRELL JAMES S L
HARCOR ENERGY INC	HARRELL PATTI J
HARDEN JAMES	HARRELL PETROLEUM INC
HARDEN JAMES III	HARRELL PROD CO
HARDEN JAMES L III	HARRELL RUTH
HARDEN JOHN W	HARRELL VERLAN W
HARDEN MARY R	HARRIET K C FOX TR
HARDIN CECILE FLUDE	HARRINGTON & BIBLER
HARDING & SHELTON	HARRINGTON BILL
HARDING & SHELTON INC	HARRINGTON ENERGY RESOURCES
HARDING CO	HARRINGTON F EUGENE
HARDING ENERGY PARTNERS LLC	HARRINGTON G E E & P
HARDING FAMILY LLC	HARRINGTON GERALD
HARDING MARGO	HARRINGTON JOSEPH
HARDROCK OIL CO	HARRINGTON KELLY S
HARDROCK PARTNERS LTD	HARRINGTON RITA M
HARDWICK JOHN H JR	HARRINGTON SOUTHWEST ENERGY
HARDY BEVERLY	HARRINGTON TRUST
HARDY OG USA INC	HARRINGTON WILLIAM S
HARDY PETRO CORP	HARRIS ANN LEE
HARE PRODUCTION CO	HARRIS BARBARA
HARISON MARK F	HARRIS CLAUDIA K
HARISON PATRICIA	HARRIS EVELYN B
HARISON PROPERTIES LLC	HARRIS JAY & C TRUST
HARJU MICHAEL	HARRIS L ROBERT
HARKEN ENERGY INC	HARRIS LAWRENCE C
HARKEN EXPLORATION CO	HARRIS NEVA L

Current BLM Oil and Gas Lessees:

HARRIS OIL &LND CORP	HAR-VEST PTNRSHP
HARRIS RANDALL	HARVEY CATHERINE B
HARRIS STEVEN H	HARVEY CATHERINE M
HARRIS VIRGINIA	HARVEY E YATES CO
HARRIS VIRGINIA M	HARVEY F HENRY
HARRIS WILLIAM P	HARVEY HELEN L
HARRISON ED M	HARVEY III MICHAEL J
HARRISON JAMES M	HARVEY JOHN L
HARRISON JEDEL	HARVEY LAURA NOEL
HARRISON JOHN W	HARVEY M J JR
HARRISON L D	HARVEY MINERAL PARTNERS LP
HARRISON MYRTLE	HARVEY MINERAL PTNRS LP
HARRISON R W	HARVEY MINERALS LP
HARRISON REV TRUST	HARVEY NANCY DILLARD
HARRISON ROBERT F	HARVEY NANCY JANE
HARRISON SAM G	HARVEY PAUL
HARRISON THOMAS D	HARVEY SAM
HARRISON THOMAS S JR	HARVEY YATES TRUST
HARRITY WILLIAM F	HARWOOD CAPITAL INC
HARROUN ENTERPRISES INC	HARWOOD O&G INC
HARRY &VERA BIRKELO REV TRS T	HASKINS JOHN
HARRY A ELLIS TRUST	HASKINS-BERSON NANCY
HARRY BERSNER ESTATE	HASSBAUM ERNEST F III
HARRY TAYLOR	HASSBAUM ERNEST P
HARRY&NOLA PTASYNSKI JNT LIV T	HASSBAUM EVELYN C
HART BARBARA M	HASSIE HUNT EXPL CO
HART ETAL REVOCABLE TRST	HASSIE HUNT PROD CO
HART RICHARD M	HASTINGS J P
HART ROLAND W	HAT CREEK ENERGY
HARTH LENORA F	HAT CREEK ENERGY LLC
HARTLEY SHELLEY S	HAT MESA OIL CO
HARTMAN DOYLE	HATHAWAY LLC
HARTMAN EDWARD M	HAUGE JAMES R
HARTMAN IRVING	HAUGEN DORIS JEAN
HARTMAN MICHAEL F	HAUKOM HILMA E
HARTMAN OIL CO INC	HAUKOM J M (JOHN)
HARTSE OIL INC	HAUNSCHILD CHARLES
HARTWELL CORP 83	HAUNSCHILD DOUG
HARVARD & LEMAY 77-A	HAUPTMAN KIM K
HARVARD & LEMAY 78-A	HAUPTMAN RESOURCES INC
HARVARD & LEMAY EXPL	HAUPTMAN THOMAS M
HARVARD ENERGY PTNRS	HAVEL KATHLEEN A
HARVARD H LEE	HAVEL MICHAEL J
HARVARD JANE	HAVEN ENERGY OF SW
HARVARD JEFF	HAVIG RESOURCES INC
HARVARD PETROLEUM CO LLC	HAWK ENERGY FUND I LP

Current BLM Oil and Gas Lessees:

HAWK PETRO INC	HAZEL LEWIS
HAWKEYE DRILLING COMPANY	HAZEL M KENT TRUST
HAWKEYE O&G INC	HAZEL M LINDL TESTAMENT TR #1
HAWKINS & HAWKINS	HAZLEWOOD INC
HAWKINS 1990 ACQUIRED	HAZLEWOOD JAMES R
HAWKINS ACQUISITIONS I	HBOP LTD
HAWKINS ACQUISITIONS II	HEADINGTON CANADA CORP
HAWKINS CHARLES R	HEADINGTON MINERALS INC
HAWKINS ENERGY CORP	HEADINGTON OIL CO LLC
HAWKINS EXPL	HEADINGTON OIL CO LP
HAWKINS EXPL INC	HEADINGTON OIL COMPANY
HAWKINS H L JR	HEADINGTON OIL COMPANY LLC
HAWKINS OIL & GAS INC	HEADINGTON OIL PROP
HAWKINS PTNRSHP I	HEADINGTON PENN CORP
HAWKINS PTNRSHP II	HEADINGTON RLTY INC
HAWKINS WILLARD A	HEADINGTON ROYALTY
HAWKS CO LTD PTNRSHP	HEADINGTON ROYALTY INC
HAWKS INDUSTRIES INC	HEAFITZ ENE MGMT INC
HAWKS JEFF	HEALOW JESSIE P
HAWN C F	HEARD ANTHONY B
HAWN CHARLES A	HEART MOUNTAIN ENERGY LLC
HAWTHORN OIL CO	HEARTLAND EXPL INC
HAY CANYON LLC	HEARTLAND OIL & GAS CO
HAYDEL CARRIE A	HEATH DOUG A
HAYES BETTY F	HEATH FAMILY TRUST
HAYES BRYCE F	HEATH LIMITED PARTNERSHIP
HAYES CHARLES F	HEATH MILTON
HAYES GERALD A	HEATH RODNEY
HAYES LAND & PROD CO	HEATH THERESIA
HAYES LAND CORP	HEATH WILLIAM D
HAYES LAND LP	HEATHER VICTORIA HILL TRUST
HAYES LINDA PERRY	HEBERT & SONS
HAYES MICHAEL D	HEBERT BUDD H
HAYES NANCY B	HECHT LEON M JR
HAYES NANCY E	HECKER I HERMAN
HAYES PARTNERS I	HEDGES E W
HAYES PROPERTIES INC	HEDGES MARY
HAYES ROBERT H	HEDGES SPENCER B
HAYMAN JAMES F	HEDRICK ADA M
HAYMAN PAT	HEDRICK OLEY F
HAYMAN WILLIAM F	HEEB CAMILLE S
HAYMANS GEORGE S	HEEP MINNIE BELLE
HAYNES OVIDIA A	HEF-LIN ENERGY CORP
HAYNIE OIL CO INC	HEFNER ENTPR
HAYS AL T	HEFNER JACK E
HAYWARD CAROL M	HEFNER ROBERT A III

Current BLM Oil and Gas Lessees:

HEGARTY PATRICK	HENDERSON PROD STOCKHOLDERS
HEINRICH CARL	HENDERSON ROBERT
HEINRICH PRODUCTION LLC	HENDERSON STKHOLDERS
HEINRICHS DAWN TS TR	HENDRICK JEANNE R
HEINRICHS JEFF TS TR	HENDRICKSON DOYLE D
HEINZ DAVID M	HENRIETTA SCHULTZ TRUST
HEINZ EXPLORATION COMPANY LLC	HENRY A COLGATE EST
HEINZE JAXCENE L	HENRY BILLIE JEAN TRUSTEE
HEISEY PROP TRUST	HENRY C LANDERS EST
HEISEY VENTURES INC	HENRY F WANGER EST
HEIT GLEN L	HENRY GUNGOLL ASSOC
HELBING & PODPECHAN	HENRY GUNGOLL ASSOC LLC
HELBING STEPHEN C	HENRY HOLDING LP
HELEN A GREVEY LLC	HENRY JAQUEZ HEIRS
HELEN S BECKER TRUST	HENRY LINDA SUE
HELENA RESOURCES INC	HENRY M O
HELENE HEWETT B POWELL TRST #1	HENRY PRODUCTION CO
HELENE HEWETT B POWELL TRST #2	HENSCHEL MARGARET
HELIS O&G CO LLC	HENSLEY FRED
HELIS OG CO LLC	HEP OIL CO LLC
HELLBERG DOROTHY M	HEP OIL CO LTD
HELLER ALFONCE H	HEP OIL GP LLC
HELM ENE LLC	HEP PARTNERS LP
HELM ENERGY LLC	HEPCO RESOURCES LLC
HELM LESREY G	HEPPE DAVID L
HELMAN CARL H III	HERBALY DAVID L
HELMERICH & PAYNE	HERBALY EXPLORATION LLC
HELMERICH CADIJAH C	HERBALY PETROLEUM CORP
HELMERICH WM III	HERBEL FAMILY INTERESTS LLC
HELMMCO INC	HERCHER DONALD E
HELMS MICHAEL VON	HERCHER RALPH H JR
HELZEL SCHWARZHOF B	HERCO
HEMENWAY MICHAEL	HERD BOB
HEMWALL RICHARD A	HERD PARTNERS LTD
HENDERSON & ERICKSON	HERD PROD CO INC
HENDERSON ANDREA	HERD PRODUCING CO
HENDERSON DAVID K	HERINGER C J JR
HENDERSON DAVID L	HERINGER ENERGY LLC
HENDERSON DAWN	HERITAGE ENERGY RESOURCES INC
HENDERSON DONNA	HERITAGE ENERGY RESOURCES INC
HENDERSON DOROTHY H	HERITAGE ROYAL PALMS BUS TRUST
HENDERSON JAMES HENRY	HERITAGE STANDARD CORP
HENDERSON JOE R	HERKENHUFF GORDON E
HENDERSON JON	HERKENHUFF PHILLIP G
HENDERSON KATHLEEN P	HERMAN F HEEP TRUST
HENDERSON LORA E	

Current BLM Oil and Gas Lessees:

HERMAN JEFF	HIGGINS BRUCE
HERNDON DRILLING	HIGH ALPINE PRODUCTION LLC
HERNDON HAROLD D	HIGH COUNTRY EXPL
HERREN AGNES C	HIGH HOPE OIL & GAS INC
HERRIN EXPLORATION LLC	HIGH PLAINS NM LLC
HERSHEY OIL CORP	HIGH PLAINS ASSOC
HERTZ OIL	HIGH PLAINS INC
HERZIG MYRTIE	HIGH PLAINS NORTH DAKOTA LLC
HESS BLAINE	HIGH PLAINS PETROLEUM CORP
HESS CORP	HIGH PLAINS UTAH LLC
HESS CORPORATION	HIGH PRAIRIE GEOTECHNICAL LLC
HESSE FRED G S	HIGH SIERRA EXPLORATION LLC
HEWETT CALVIN J	HIGH STORY VENTURES
HEWITT ENERGY GROUP LLC	HIGHLAND OIL & GAS LLC
HEWITT MINERAL CORP	HIGHLAND OIL & GAS LLC
HEWITT PAULINE F	HIGHLAND PROD CO
HEWITT PRODUCING CO	HIGHLINE EXPL INC
HEWITT ROBERT J	HIGHMOUNT BLACK WARRIOR
HEXAD OIL CO	BASIN
HEYCO DEVELOPMENT CORP	HIGHMOUNT EXP & PROD MICHIGAN
HEYCO EMPLOYEES LTD	HIGHMOUNT MIDWEST ENERGY LLC
HEYNE MIKE	HIGHT ELIZABETH B
HEYSER GAS FIELD INC	HIGHT THOMAS J
HGB LAND SERVICES CO INC	HIGHTOWER EARL V
HGB OIL CORPORATION	HIGHTOWER J N
HHB LTD PTNRSHP	HIGHTOWER JAMES ROSS
HHE ENERGY CO	HIGHTOWER JOSEPH BLAIR
HI ANN OIL CO	HIGHTOWER WARREN B
HIBBERT R E	HILCORP ENERGY
HIBERNIA ENERGY INC	HILCORP ENERGY I LP
HIBERNIA NATL BANK	HILCORP ENERGY X LP
HICKEY DEBORAH L	HILDA O'BERG TRUST
HICKEY THERESA H	HILL A G
HICKEY THOMAS E	HILL AL R
HICKEY TIMOTHY D	HILL ALBERT G III TRUST
HICKMAN CLAUDE R	HILL ALBERT G TRUST
HICKOK FREDERICK R	HILL AUDREY
HICKOK WILLIAM C	HILL CORTLANDT T
HICKS LIVING TRST	HILL CRAIG S
HICKS LIVING TRUST	HILL ELSIE
HICKS MARGIE	HILL FOUNDATION TRST
HIDDEN RESOURCES INC	HILL GILMAN A
HIDEAWAY PARTNERSHIP	HILL HOUSTON
Hiestand Andrew	HILL HYDROCARBONS
HIGBEE EDWARD W & ELLEN M	HILL HYDROCARBONS INC
HIGDON BARBARA SMITH	HILL HYDROCARBONS LP

Current BLM Oil and Gas Lessees:

HILL JACK	HJJ RESOURCES INC
HILL JOHN H	HJORTH WILLIAM L
HILL LOUIS W JR	HLA ROYALTIES LLC
HILL MARGARET HUNT	HLAVIN WILLIAM J
HILL VIRGINIA W	HLP PRODUCTION CO
HILLCORPENERGY I LP	HLR TRUST
HILLER OG LTD	HM INVESTMENTS LTD
HILLER PAUL W JR	HOARE ESTHER
HILLHOUSE NANCY	HOBACK ENERGY PARTNERS LLC
HILLIARD PETRO INC	HOBBS HELEN T
HILLIER OIL & GAS	HOBE INC
HILLIER PAUL W JR	HOC 1982 ROCKIES OIL
HILLIN OIL CO	HOCKADY DONALD E JR
HILLIN PRODUCTION CO	HODGE MARK E
HILLIN ROBERT K	HODGES CHARLES F
HILLIN SIMON OIL CO	HODGES LELAND A
HILLIN-SIMON OIL CO	HODGES WARREN F
HILLMAN D B 10-27-71	HODGES WILLIAM V
HILLMAN D B 8-25-68	HODGKINS STEPHEN W
HILLMAN H B 8-28-68	HOEFLER RICHARD C
HILLS EXPL CORP	HOESLY DONA A
HILLSIDE SYNDICATE	HOFFERT KERMIT TRST
HILLSTROM BRYAN	HOFFMAN J F TRST
HILLSTROM-MASI SUSAN	HOFFMAN JOSEPH F
HILSEWECK HELEN M	HOFLAND JAMES D
HILSEWECK O&G CO	HOFMAN DON
HILSWECK PARTNERSHIP	HOFMANN LILLIAN
HINCHCLIFF DOROTHY	HOFMANN T D
HINES E R JR	HOG PARTNERSHIP LP
HINES MARY D	HOG PRTNRSHP LP
HINES SCOTT	HOGAN R D
HINGELINE RESRC LLC	HOGBACK EXPLORATION
HINKLE B F	HOHLY ROBERT
HINKLE HARRY B	HOLCOLM OIL & GAS
HINSDALE CARROLL	HOLCOMB E H
HINSON DAVID	HOLCOMB EDWIN
HINTON LOTTIE J	HOLCOMB EDWIN H
HIRSCHFIELD ALAN J	HOLCOMB H R
HIRZEL FRED R JR	HOLCOMB OIL & GAS
HISSEM TRUST EL AL	HOLCOMB OIL & GAS INC
HITCH H C JR	HOLCOMB REVOCABLE LIVING
HITCHENS ALBERT	TRUST
HITZEL HARRY	HOLCOMB ROSEMARY
HIXON GEORGE C	HOLDEN 1995 LVG TR
HIXON JOSEPH M III	HOLDEN EVA L
HJ LEDBETTER TRUST	HOLDEN HAROLD & EVA

Current BLM Oil and Gas Lessees:

HOLDEN HAROLD & EVA 95 TRUST	HOLVECK NORVELL
HOLDEN HAROLD B	HOLYOAK PROPERTIES LLC
HOLFELTZ MELBA M	HOMAN GLENN J
HOLIFIELD STEVE L SR	HOME ANN LOU
HOLKAN JEFFERY M	HOME PETRO CORP
HOLLAND HOLDING INC	HOME PETROLEM CORP
HOLLAND JOHN G	HOME TERESA
HOLLAND MARTHA	HOME-EMMERSON ANN
HOLLAND P J	HOMER A JACOBS EST
HOLLAND-GRIEVES PAULA	HOMER GLOVER ESTATE
HOLLAND-HICKEY JAN	HOMESTAKE OG CO
HOLLBERG JUDITH A	HOMME ORRIN R
HOLLBERG ROBERT M	HONDO DRILLING CO
HOLLBERG RONALD J JR	HONDO O&G CO
HOLLBERG THOMAS K	HONEA B N ESTATE
HOLLENKAMP RODNEY	HONEA BERT N JR
HOLLENSHEAD C THOMAS	HONEA-PENN VIRGINIA
HOLLIS O&G CO	HONNOLD ELAINE B
HOLLIS STEPHEN H	HOOD BEN A
HOLLOWAY A ODEANE	HOOD H C
HOLLOWAY MARVIN L	HOOKER ANDREW C
HOLLOWAY SHIRLEY V	HOOPER & SONS INV CO INC
HOLLOWELL DOLORES N	HOOPER JERRY L
HOLLY P SMITH TRUST	HOOPER-KIMBALL-WMS
HOLLY T ELLIOTT FAMILY LP	HOOSER STEVEN W
HOLLYHOCK CORP	HOOVER & BETTY WRIGHT LIV TRST
HOLLYHOCK CORP GP	HOOVER & STACY INC
HOLMAN ANN C	HOOVER ROBERT M JR
HOLMAN OIL CO	HOPCO LTD
HOLMES BRUCE A TRUSTEE	HOPE CLYDE E
HOLMES CAROLYN G TRUSTEE	HOPKINS ALBERT L JR ET UX
HOLMES JACK	HOPKINS B H
HOLMES JOSEPHINE M	HOPP VERGIL O
HOLMES KENNETH	HOPPER BARNETT INC
HOLMES WESTERN OIL	HOPPER-BARNETT INC
HOLMES-JONES PETROLEUM CO	HORIZON GAS PARTNERS LP
HOLMSTROM RUTH E P	HORIZON NATURAL RES
HOLSER RESOURCES LLC	HORIZON O&G CO
HOLST LARRY	HORIZON OG CO OF TX
HOLSTROM G W	HORIZON PROPS GRP
HOLSTUN PAUL DAVID	HORN CHARLES
HOLSUM INC	HORN RICHARD A
HOLSUM INC HEIRS	HORN STEVEN W
HOLT REED E	HORNING RONALD E
HOLTEMANN FRANK G	HORNSBY NANCY
HOLTON CORP	HORNSBY OG CO

Current BLM Oil and Gas Lessees:

HORSESHOE OPER INC	HOWELL ROBERTS SPEAR EST OF
HORSESHOE OPERATING	HOWELL STUART
HORTON DICK S	HOWELLS OIL & GAS
HORTON PETROLEUM CORP	HOWEY ROBERT S
HORTON W R	HOYER JOSEPH S
HORTON WADE	HOYT MYRON S
HORWITZ EDUC TRUST	HPC ENE INC
HORWITZ JULIAN V	HPC ENERGY INC
HOST OIL INC	HPC INC
HOT ROD OIL	HR ENERGY LLC
HOT SPRINGS RESOURCES LTD	HRB OIL & GAS LTD
HOTT MONTY PROD CORP	HRK PTNRSHP
HOUCK ENE RES	HRM RESOURCES LLC
HOUCK OIL CO	HS RESOURCES INC
HOULTON BAND OF MALISEET INDNS	HSRTW INC
HOUNSELL B	HUANG ANTHONY Y
HOUNSELL ENERGY	HUANG GRACE YI YU
HOUSE CHARLES L	HUBBARD OIL CORP
HOUSEKNECHT BETTY JC	HUBBARD WILMA J TRST
HOUSTON & EMMA HILL TRST EST	HUBER EMERICK M
HOUSTON & EMMA HILL TRUST EST	HUBER MICHAEL D
HOUSTON ALICE	HUBER VIOLA MCALLISTER
HOUSTON DARLENE P	HUDGEONS JERRY L
HOUSTON ENERGY LP	HUDSON & HUDSON TRUST
HOUSTON EXPLO CO INC	HUDSON ANN F
HOUSTON OIL & MIN	HUDSON E R
HOUSTON OIL PROD INC	HUDSON EDWARD R
HOUSTON SAMUEL	HUDSON EDWARD R JR
HOWARD BILL	HUDSON EDWARD R TRUST
HOWARD CHARLES III	HUDSON FRANCIS H
HOWARD E CAYWOOD INC	HUDSON GROUP LLC
HOWARD ENERGY CO INC	HUDSON JAMES ROBERT
HOWARD FRANK A	HUDSON JOHN G
HOWARD GEORGE A	HUDSON JOSEPH R
HOWARD JOHN	HUDSON JOSEPHINE T
HOWARD MAUDE C	HUDSON JR EDWARD R
HOWARD STEPHEN R	HUDSON KIRK W
HOWE C D	HUDSON LINDA GOODYEAR
HOWE DENNIS M	HUDSON OLGA R
HOWE E F	HUDSON R CRAIG
HOWE PHILIP F	HUDSON ROBERT E
HOWE ROBERT F	HUDSON W H
HOWELL KENNETH S	HUDSON WILLIAM A
HOWELL LINDA C	HUDSON WILLIAM A II
HOWELL PETRO CORP	HUDSON WILLIAM A III
HOWELL PETROLEUM CORP	HUDSON WM T TRST

Current BLM Oil and Gas Lessees:

HUERFANO RESOURCES INC	HUMPHREYS WILLIAM Y
HUFF JACK	HUNICUTT LARRY
HUFF WILLIAM GREGORY	HUNKER GEORGE H JR
HUFFMAN INVESTMENTS	HUNKER LORETTA
HUFFMAN-BOWERS INC	HUNKER WILLIAM W
HUFFORD I MEADE	HUNNICUTT LARRY
HUFFORD I MEADE ENG LAND SER	HUNT CARL G
HUGGINS W O	HUNT DONALD B
HUGH & NINA WYNIA TRST	HUNT ENERGY CORP
HUGH K BROOKIE ESTATE	HUNT ESTATE
HUGH W PARRY	HUNT HOUSTON B
HUGHES & HUGHES	HUNT INDUSTRIES
HUGHES C C	HUNT LAMAR
HUGHES CHARLES C	HUNT N B TRUST B
HUGHES CLIFFORD B	HUNT NELSON B
HUGHES DALE	HUNT OIL CO
HUGHES EASTERN CORP	HUNT OIL COMPANY
HUGHES LOYD	HUNT OIL USA INC
HUGHES OIL INC	HUNT PETROLEUM
HUGHES PATRICIA G	HUNT PETROLEUM (AEC) INC
HUGHES RAWLS CORP	HUNT PETROLEUM CORP
HUGHES RICHARD L	HUNT RENEE
HUGHES RITA	HUNT STUART
HUGHES SARAH B	HUNT WILLIAM H
HUGHES SCOTT J	HUNT WOODY L
HUGHES SERVICES INC	HUNTER DAVID JAMES
HUGHES SIDNEY M	HUNTER DOS TRES CORP
HUGHES WARREN B	HUNTER DOUGLAS A ESTATE
HUGHES-MYERS ANNE	HUNTER ENERGY LLC
HUGOTON CAPITAL LTD	HUNTER GLADYS H
HUGOTON VENTURES	HUNTER HAMILTON L M
HUGUS INVST CO INC	HUNTER HUGH M
HULL JOSEPH P D	HUNTER JOHN P
HULL LESLIE T	HUNTER KERRY D
HULLINGER DENNIS A	HUNTER RESOURCES INC
HULSIZER W E	HUNTER ROY A
HUMBLE OIL & REF CO	HUNTINGTON CANYON LARGO LLC
HUMBLE OIL&REFINING	HUNTINGTON ENERGY LLC
HUMMEL PETER W	HUNTINGTON MORTGAGE
HUMPHREY CASS D	HUNTINGTON RES INC
HUMPHREY J A	HUNTINGTON RESOURCES INC
HUMPHREY LAYTON A JR	HUNTZE RAYMOND D
HUMPHREY OIL CORP	HUR
HUMPHREYS LAWRENCE	HURLEY G WILLIAM
HUMPHREYS RONALD K	HURLEY OIL PROPERTIES INC
HUMPHREYS SUSAN	HURT CECILE

Current BLM Oil and Gas Lessees:

HURT ELEANOR C G	IEF 3 & 4 EVEN CORP
HURT INTERESTS	IEF TEXAS-I
HURT JAMES R	III EXPLORATION CO
HURT JAMES R JR	III EXPLORATION II LP
HURT JOHN CLINT	IKARD JIM
HURT PROPERTIES LP	IKARD LISA J
HURT SAM F JR	IKARD PATRICIA
HUSKY EXPLORATION (CRB) INC	IKARD PATRICIA K
HUSSEY MARY E	ILLINOIS TOOL WORKS
HUSTON & HAYDEN	ILORETA ALFREDO T
HUTCHINGS OIL CO	IMPACT ENERGY RESOURCES LLC
HUTCHINSON JEANNE	IMPERIAL OIL CO
HUTCHISON ENERGY LTD	IMPERIAL RES INC
HUTCHISON W L	IMPROVISATION PARTNERS LP
HYDE FRANCES W INC	IMPROVISATION PTRS LP
HYDE OIL & GAS CORP	INDEN RICHARD F
HYDEN ERIC F SR	INDEPENDENT PROD CO
HYDER PAULINE L	INDIAN COUNTRY
HYLAND HARLOW TRUST	INDIGO HYDROCARBON PARTNERS
HYLTIN TONI MASTERS	LP
HYMCO VENTURES LLC	INDIGO MINERALS LLC
HYPERION OIL & GAS LLC	INDUSTRIAL ENE PTNRS
I & L DEVELOPMENT CO	INDUSTRIAL GAS SALES
I C GAS AMCANA INC	INEXCO OIL CO
I P PETROLEUM CO INC	INFINITY CANYON LARGO LLC
I RUDMAN TRUST	INFINITY EXPL
I T PROPERTIES	INFINITY EXPL INC
I&L DEV COMPANY	INFINITY O&G INC
IAT RESOURCES INC	INFINITY OIL & GAS INC
IBEX PARTNERSHIP LTD	INFINITY OIL & GAS OF WY INC
IBEX PTNRSHP LTD	INFINITY OIL & GAS OF WYOMING
IBEX RES IX LP	INFLOW PETRO RESOURCES LP
IBEX RES V LP	INGERSOLL GEORGE F ESTATE
IBEX RESOURCES CO LLC	INGLE ALLESANDRA
ICA ENERGY INC	INGRAM DWIGHT A
ICENINE PROPERTIES LLC	INGRAM JOHN
ICCG PETROLEUM INC	INGRAM TOM L
ICHOR EXPL INC	INLAND O&G CORP
ICHOR EXPLORATION INC	INLAND OG CORP
ICHTER IV JOSEPH THOMPSON	INLAND PROD CO
ICON PETRO INC	INMAN CYRENE L
IDAHO OIL & MINERALS	INMAN TOMMY D
IDC ENERGY CORP	INNERARITY L EDWARD
IDC ENTERPRISES LTD	INNEX CALIFORNIA INC
IDLER L A	INNOVATIVE O&G DEV & TRADING
IDZIG LTD	INNOVENTIONS INC

Current BLM Oil and Gas Lessees:

INTEGRITY O&G CO	ISAACS FAMILY LTD LIABILITY LP
INTER AMERICAN CORP	ISAACS MAX
INTERAMERICAN CORP	ISAAK DAVID
INTERFIRST BANK EXECTR	ISBELL JAMES H
INTERFIRST BANK TRUST	ISBRANDTSEN O&G CO
INTERMOUNTAIN LEASING INC	ISENSEE EARL H A JR
INTERMOUNTAIN O&G	ISHAM ELEANOR
INTERMOUNTAIN PETRO	ISHAM GEORGE S
INTERMOUNTAIN REFINING CO INC	ISHAM HENRY P JR
INTERNATIONAL DRILLING INC	ISHAM NELSON R
INTERNATIONAL MINERAL MGMT	ISHAM ROBERT T
INTERNATIONAL PETROLEUM	ISIS LLC
INTERNATIONAL PETROLEUM LLC	ISLEY ARLEE
INTERNATIONAL TECH RES PETRO	ISLEY NORMA
INTERPOL 78	ISOM LISABETH W
INTERSTATE DRLG INC	ISRAMCO ENERGY LLC
INTERSTATE EXPL	ISRAMCO RESOURCES INC
INTERSTATE EXPL INC	IT PROPERTIES
INTERSTATE INVST CO	ITALLIE H F VAN
INTERVENTION ENERGY LLC	IVERS OIL COMPANY LLC
INTEX OIL CO	IVERSON C J
INTEX OIL COMPANY	IVERSON CAROLYN N
INTOIL INC	IVERSON CLAIRE ANN
INTREPID ENE LLC	IVERSON DOROTHY C
INTREPID ENERGY	IVERSON FMLY INTER-VIVOS TRUST
INTREPID O&G LLC	IVERSON INC
INTREPID PROD CORP	IVERSON JEWELL D
INVERSON-PAGE PATSY	IVERSON MARJORIE
INVESTORS FIN SVC	IVERSON SIEGFRIED JAMES III
INYAN KARA GROUP LLC	IVERSON WENDELL W
IOFINA NATURAL GAS INC	IVERN-PAGE PATSY
IOFINA RESOURCES LLC	IVERSTON H R
IONA OIL CO	IVEY BEN E III
IONIAN INC	IVEY MERCER T JR
IP PETROLEUM CO INC	IVINS LEAH P G TRST
IPR LAY CREEK LLC	J & B PTNRSHP
IRELL LAWRENCE E	J & E BEARD TTEE
IREX CORP	J & F PRODUCTION
IRION RONALD L	J & G ENTERPRISE LTD
IRIS TOLLETT EST	J & J SERVICES INC
IRISH FAMILY TRUST	J & L EXPLORATION LLC
IRON CREEK PROPERTIES INC	J & L OG INC
IRON LAND LLC	J & L OIL & GAS INC
IRON MTN ENERGY LLC	J & L RESOURCES INC
IRVIN W E	J & M INVESTMENT CO
IRWIN DAN W	J & M RAYMOND LTD

Current BLM Oil and Gas Lessees:

J & R MERRION TRUST	J L LYCURGUS JOHNSTON MEM TRST
J & T OIL COMPANY LLC	J L MARTIN JR TRUST
J & V SHAW TRUST	J M BLAIR INC
J 5 INCORPORATED	J M HUBER CORP
J A CLAY JR TRUST	J M PARRISH JR TRUST
J A HUMPHREY TRUST	J M WELBORN TRUST
J A MULL EST	J M WOODS CO INC
J A N CO	J MELTON DRILLING CO INC
J ANDERSON ESTATE	J N DAVIS & CO
J B ABERCROMBIE MINERALS	J N O&G
J B GURLEY OIL & GAS	J NORTON CO
J B STEPHENSEN ESTATE	J P OIL CO LLC
J B TUBB TRUST	J PHILLIP BOYLE TRUSTEE
J BAR CANE INC	J R ANDERSON ESTATE
J BURNS BROWN	J R BACON DRILLING
J C & J C JR THOMPSON PTNRSHP	J R GAS INC
J C BARNES TRUST	J R GLENNON LLC
J C OIL CO	J R GUINN FAMILY TRUST A
J C PETRO INC	J R GUINN FAMILY TRUST M
J C PETROLEUM INC	J R RESOURCES LP
J C WILLIAMSON ESTATE	J S ABERCROMBIE MINS
J E ATTEBURY TRUST	J S ATTEBURY TRUST
J E ATTEBURY TRUST B	J S HOLMBERG TRUST #1
J F HOFFMAN TRUST	J SHAW JR TRUST
J F PARTRIDGE JR TR	J SHAW TRUST
J F WEST ESTATE	J SUGAR CO INC
J F WILBUR JR INC	J T JACKSON & ASSOC
J G & R MERRION TRUST	J THOMPSON & J THOMPSON JR LP
J G MERRION TRUST	J V WALKER TRUST
J GLENN TURNER JR LLC	J W DUNCAN JR INC
J GREGORY&R MERRION	J W PEERY ESTATE
J GREVEY TRUST	J&D PETROLEUM
J GUINN FAMILY TRUST A	J&K PROPERTIES INC
J GUINN FAMILY TRUST M	J&L O&G INC
J GUNGOLL TRUST	J&M RAYMOND LTD
J H COX PTNRS	J&R MERRION TRUST
J H MARSHALL II TRST	J&S TAYLOR U/A TR
J H MOORE TRUST	JACARANDA OILS LLC
J HIRAM MOORE	JACK & SHIRLEY TAYLOR TRUST
J HIRAM MOORE LTD	JACK A COLE TRUST
J I ROBERTS ESTATE	JACK ABNER M
J J BUNKIRT OG CORP	JACK CO PTNRSHP
J J O'NEILL FOUNDATION	JACK ENERGY LLC
J K EDWARDS & ASSOC	JACK EXPLORATION INC
J K MINERALS INC	JACK GUY JR ESTATE
J L JOHNSON FAM CORP	JACK H EDWARDS INC

Current BLM Oil and Gas Lessees:

JACK HOWARD B	JAMES H BORGERDING TRST
JACK HUFF ENERGY LTD	JAMES H YATES INC
JACK JAMES	JAMES IVERS FAMILY TRUST
JACK JEAN	JAMES IVY WIEDEMER TRUST
JACK WALKER TRUST	JAMES K DEER TRUST
JACKAL OIL CO	JAMES K LUSK TRUST
JACKFORK LAND INC	JAMES L ALFORD III
JACKIE BARNES ESTATE	JAMES L WALKER & CO
JACKSOCO OIL CO INC	JAMES M KRAMER TRUST
JACKSON DAURIS R	JAMES MANSDORFER TRUST
JACKSON DON W	JAMES P GARMAN ESTATE
JACKSON EVANS A III	JAMES R BORMAN TRUST
JACKSON J T	JAMES R GUINN ESTATE
JACKSON J T JR	JAMES TEDDY
JACKSON JOHN H	JAMEX INC
JACKSON THOMAS INGLE	JAMISON JANICE E
JACOBS IRREVOC TRUST	JAMISON ROBERT
JACOBS JIM L	JANE B RAMSLAND OG PRTNSHP LTD
JACOBS ROSS	JANE DILLARD TRUST
JACOBS SHARON B	JANE GROSS TRUST
JACOBSEN ANNE	JANE L TANNER LIVING TRUST
JACOBSEN STEPHEN	JANE P MOSBACHER EST
JACOBSON JOEL	JANEX OIL RES FND 89
JACOBSON JOSEPHINE C	JANICE W HUDSON REVOCABLE TRST
JACOBSON ROBERT J JR	JANKLOW ANGELA TRUST
JACQUE OIL & GAS LTD	JANKLOW LUCAS TRUST
JACQUELINE M HARRISON TRUSTEE	JANUS O&G LTD PTRS I
JADE ROSE LLC	JAPEX (U S) CORP
JAEGGLI LINDA M	JAQUEZ RUDY P SR
JAG OIL LTD PTNRSHP	JAR MAC PIPE & SUPL
JAKE OIL LLC	JARCEEDE PARTNERS LTD
JAKE ROOSTH TRUST	JARRARD KARAN
JALAPENO CORP	JARRETT BOBBY L
JAM OIL CO	JARUSSI GENE R
JAMES & PATRICIA ALLEN FAMILY	JARVIS WAYNE
JAMES A MCGEHEE PRODUCTION CO	JASDEC OIL PARTNERS
JAMES A WALTON TRST 1992 GST	JASPER RESOURCES INC
JAMES B HENRY TRUSTEE	JATON CORP
JAMES BARLOW FAM LP	JAVELINA PARTNERS
JAMES C DITTMER TRST	JAXCENE L HEINZE TRUST
JAMES C HAYES ESTATE	JAY HARRIS TRUST
JAMES CLEO THOMPSON JR LP	JAY K ARMSTRONG LP
JAMES CONNIE KAY	JAY OIL CORP
JAMES E HIBBERT EXECUTOR	JAY PETROLEUM
JAMES E MCELVAIN CO	JAY PETROLEUM LLC
JAMES G ROUTSON TRUST	JAYHAWK OIL & GAS CORP

Current BLM Oil and Gas Lessees:

JB & CM COCHRAN REV LGV TRST	JENNINGS PATRICIA K
JB PETROLEUM	JENNINGS PRODUCTION CO LTD
JB RICH MERCANTILE	JENNINGS THOMAS E
J-BREX CO	JENNINGS TIMOTHY Z
JC & WF REYNOLDS PRTNRSHP	JENSEN BARBARA ANN
JC PETROLEUM HOLDING LLC	JENSEN JOANN
JCR JR OPERATING INC	JENSEN JOHN O
JCV CO INC	JEN-SON OIL
JD BUSH LLC	JENT INC
JDH INVESTMENTS INC	JEREMIA LLC
JDH OIL CO INC	JEREMIAH LLC
JDH RESOURCES LLC	JERRY CHAMBERS EXPL
JDT RESOURCES LLC	JERRY E SHAWVER EST
JDW INC	JERRY SANDEL TRUST
JEAN F VANDERSLICE REV TRUST	JERRY W SANDEL TRST
JEAN WAGGONER TRUST	JERRY W SANDEL TRUST
JEBITO FARMS LLC	JESUS SALAZAR FAMILY LP
JED OIL (USA) INC	JESUS SALAZAR TRUST
JEFFCOAT LEON	JE-TOO INC
JEFFERS B J	JETTA OPERATING CO
JEFFERS D L	JETTA OPERATING CO INC
JEFFERS DEBBIE	JETTA PROD CO INC
JEFFERS J BRAD	JETTA PRODUCTION CO INC
JEFFERS RUTH	JETTA X2 LP
JEFFER'S SON INC	JETTISON INC
JEFFERS WILLIAM E	JEWKES DALE M
JEFFERS WILLIAM E SR	JEWKES KATE ANN
JEFFREY LYNN TRUSTEE	JFS RESOURCES LP
JEFFREYS J BRADLEY	JG & RV MERRION TRST
JEKE INC	JG MINERALS LTD
JEM PETRO CORP	JG&R MERRION TRUST
JEM TRST	JG&RV MERRION REV TR
JEM TRUST	JG&RV MERRION TRUST
JEM TRUST 2-9-93	JGF INC
JENEX PETROLEUM CORP	JGI RESOURCES INC
JENKIN-GUERIN INC	JHS #1 LLC
JENKINS LAMAR	JICO INC
JENKINSON KATHLEEN J	JIL OIL CORP
JENNEMAN WALTER C	JILES DORIS JANE
JENNIFER S YATES 1976 TRUST	JIMMY ROBERSON ENE
JENNING JAMES	JIM'S WATER SERVICE
JENNINGS FAMILY LLC	JIM'S WATER SVC INC
JENNINGS GALAN	JINDAVIK PETROLEUM
JENNINGS HOWARD W	JIREH EXPL& CONSULTING LLC
JENNINGS JAMES	JJ BUNKIRT OIL & GAS CO
JENNINGS JOHN F	JJ COHN INVSTMNT PRTNRSHP

Current BLM Oil and Gas Lessees:

JJ-CC LTD	JOHN F RACHOU TRUST
JJK HOLDINGS LLC	JOHN F SULLIVAN TRUST
JJR INC	JOHN GARVEY TRUST
JK ENERGY INC	JOHN GRAUMAN INC
JK MINERALS INC	JOHN H HENDRIX CORP
JKG-LA INC	JOHN HANCOCK INSURANCE
JKJ LLC	JOHN J REDFERN EST
JKM ENERGY LLC	JOHN J REDFERN ESTATE
JKTS CORP	JOHN L DEER TRUST
JKX OIL & GAS LP	JOHN L FREEMAN EST
JM HUBER CORPORATION	JOHN L GOEDERT FAMILY TRUST
JM NEWMAN CO	JOHN L GOEDERT MARITAL TRUST
JMA ENERGY CO LLC	JOHN L JOHNSON TR
JMA RESOURCES INC	JOHN L KENNEDY REVOCABLE
JMAC RESOURCES LLC	TRUST
JMB DRILLING FUND 81	JOHN L ROBERTSON INC
JMC EXPLORATION INC	JOHN M BEARD TRUST
JMF ENTERPRISES	JOHN M PARRISH EST
JMG EXPL INC	JOHN OMELVENY TRUST
JMH OIL INC	JOHN P ELLBOGEN EST
JMI ENERGY INC	JOHN P OIL COMPANY
JMI ENERGY, INC.	JOHN P SHIELDS INC
JMK PETRO CORP	JOHN PARRISH JR EST
JMW ENTERPRISES LLC	JOHN Q MOSES REVOCABLE TRUST
JN EXPL & PROD LTD	JOHN Q MOSES TRUST
JN EXPLO & PROD LTD	JOHN R & LINDA M JAEGGLI TRUST
JN RESOURCES INC	JOHN R ANDERSON EST
JN RESOURCES, INC	JOHN R GRAY TRUST
JNG TRUSTEE	JOHN REDFERN JR EST
JOAN C B BEAN LIVING TRUST	JOHN S WOLD REVOCABLE TRUST
JOB INC	JOHN SIMMET MARITAL TRUST
JOC OIL EXPL CO INC	JOHN TAYLOR CO
JOC OIL EXPL INC	JOHN W BUFFINGTON INC
JOE & LINDA ELLEDGE ET UX	JOHN W HARRISON TRST
JOE MELTON DRLG CO	JOHN&ELLY BEARD TTII
JOECKEL ENTERPRISES LTD	JOHNNIE PAUL ROSE TRUST
JOECKEL EVELYN R	JOHNS WILLIAM
JOECKEL RAYMOND N	JOHNS WILLIAM C
JOEL MILLER TRUSTEE	JOHNSON A E
JOHN & ELLY BEARD TRUSTEE	JOHNSON BARBARA JO TRUST
JOHN A MASTERSON REV TRST	JOHNSON BARTON M.
JOHN C OXLEY LLC	JOHNSON BECKY BURNS
JOHN D MCALLISTER JR EST	JOHNSON BILLY R
JOHN D TRAUT LLC	JOHNSON COURTNEY C
JOHN D TRAUT TRUST	JOHNSON DAVID E A
JOHN DAVID WIEDEMER TRUST	JOHNSON DEIRDRE J

Current BLM Oil and Gas Lessees:

JOHNSON ENTPR LTD  
JOHNSON EVERETT L JR  
JOHNSON F T JR  
JOHNSON FAMILY TRUST  
JOHNSON GARY J  
JOHNSON GEORGIE E  
JOHNSON GRACE  
JOHNSON HELEN K  
JOHNSON HERBERT A  
JOHNSON JAMES C  
JOHNSON JANE DOHM  
JOHNSON KASOL  
JOHNSON LAWRENCE  
JOHNSON LIVING TRUST  
JOHNSON M C  
JOHNSON M S  
JOHNSON M T TRUSTEE  
JOHNSON MICHAEL C  
JOHNSON O S  
JOHNSON OLE C EST  
JOHNSON ORLAN L  
JOHNSON R C  
JOHNSON ROBERT E  
JOHNSON S H  
JOHNSON S P III  
JOHNSON TODD W  
JOHNSON TOM E  
JOHNSON TRUST  
JOHNSON VERNON A  
JOHNSON WALLACE H  
JOHNSON WARREN TRST  
JOHNSON WENDY K  
JOHNSON WILLIAM J  
JOHNSTON BETTY T TRUST  
JOHNSTON FAMILY TRUST  
JOHNSTON HUGH L JR  
JOHNSTON J A  
JOHNSTON JAMES M  
JOHNSTON JAMES W  
JOHNSTON JEFFREY M  
JOHNSTON JOYCE E  
JOHNSTON JUDITH A  
JOHNSTON L C  
JOHNSTON OG CO  
JOHNSTON RANDALL B  
JOHNSTON ROBERT J

JOHNSTON SHIRLEY A  
JOINT RESOURCES COMPANY  
JON DAVID LUFF REVOCABLE TRUST  
JON P TREVELISE TRST  
JONAH ENERGY CO LLC  
JONAH GAS CO LLC  
JONAH GAS COMPANY INC  
JONAH GAS COMPANY LLC  
JONATHAN FRYD  
JONES ANN  
JONES BEATRICE A  
JONES BERT  
JONES BRYAN  
JONES CARL W  
JONES CHARLES E  
JONES CHARLES H  
JONES CHRISTINE  
JONES CLYDE W  
JONES CO  
JONES COUNTRY MIN  
JONES DOROTHY  
JONES FRED  
JONES FRED G  
JONES FRED L  
JONES GEORGE R  
JONES HAROLD E  
JONES HUGH A  
JONES JAMES S  
JONES JAY F  
JONES JERRAL W  
JONES JOHN A  
JONES KATHLEEN B  
JONES KEITH L  
JONES LARRY  
JONES LAWAYNE E  
JONES LINDA K  
JONES M  
JONES MARY H  
JONES MICHAEL C  
JONES RICHARD C  
JONES ROBERT J  
JONES RUSSEL D  
JONES SUSAN R  
JONES U V  
JONES VERN  
JONES VERN K

Current BLM Oil and Gas Lessees:

JONES-HOLMES MARY	JSTM ENERGY INVESTMENTS LLC
JONS BETTY H TRUSTEEE	JSTM PROPERTIES LTD
JORDAN DEVELOPMENT CO LLC	JSWH LLC
JORDAN EXPLORATION CO LLC	JTB ENERGY
JORDAN OIL & GAS CO	JTD RESOURCES LLC
JORDANCE ENERGY INC	JTI INC
JORGENSEN GLENNIS L	JUDAH OIL
JOSEPH HOFFMAN TRUST	JUDD ANNA
JOSEPH S POLLARE LIVING TRUST	JUDITH LYNN ROSE TRUST
JOSEPHINE H BARNARD EXECUTOR	JUDITH R WOODRUFF FAMILY TRUST
JOSEPHSON EMANUEL	JUDITH SHAW TRUST
JOSHUA AND DAVID MINERALS LLC	JUDSON C BALL RECOVABLE TRUST
JOSLIN JANET S	JUDSON EDWARD H
JOUFLAS GEORGE P	JUDSON OPER INC
JOURNEY 2000 LP	JUDSON OPER LTD
JOURNEY ACQUISITION - I LP	JUDSON OPERATING LTD
JOURNEY ACQUISITION-I LP	JUDSON OPERATIONS
JOURNEY ACQUISITION-II LP	JUDSON OPERATIONS LTD
JOURNEY OIL & GAS LLC	JULANDER ENERGY CO
JOURNEY PROPERTIES LLC	JULANDER ROBERT C
JOURNEY'S END INC	JULANDER WELDON C
JURNIGAN TRUST	JULES CONSTANTIN EST
JURNIGAN TRUSTEES	JULIUS FOREST C
JOVET THOR W	JULIUS ROY GLENN
JOY HENRY B JR	JUPITER INVESTMENTS LC
JOY OIL CO	JURAN JOYCE E
JOY PARTNERS LTD THE	JURASSIC RES DEV NA LLC
JOYCE GILLIS TRUST	JURGENSEN TED L
JOYCE GILLIS TRUSTEE	JUSTICE ELOUISE H
JOYER FLOYD H	JUSTICE HAROLD D
JOYRAN CORP	JUSTICE OIL & GAS LLC
JP FURLONG CO	JUSTIN ENERGY LLC
JP OIL CO LLC	JUSTIN S POOLE TRUST
JP OIL COMPANY LLC	JUSTISS OIL CO INC
J-PAK #1 PTNRSHP	J-W OPER CO
JPC LLC	JWC RES LLC
JPG ENTERPRISES	JWD III INC
JR & ADAM SEITZ PRTNRSHP	JWF ENERGY PARTNERS 1985 LTD
JR OIL CO	K & A INC
JR OIL COMPANY	K & C PRODUCTION CO
JRF PROPERTIES INC	K & E PETRO INC
JRJ-1 LTD PTNRSHP	K & L 1980 EXPL PROG
JRP SAN JUAN L P	K & R OIL & GAS
JS GORDON & CO	K M PRODUCTION CO
JSL INVESTMENTS LTD CO	K MARJEAN MARTIN REV TRUST
JSM DRILLING	K P ACQUISITION CORP

Current BLM Oil and Gas Lessees:

K P KAUFFMAN CO INC	KANSAS NAT GAS INC
K S ADAMS ESTATE	KANTEX HOSPITALITY INC
KOBAL VALERIA	KANTOR JOSEPH S
K74 OIL CO	KAPPEL MARIE
KAB ACQ LP-II	KARBON COAL LTD
KAB ACQ LP-III	KARCHER PAUL J
KAB ACQUISITION LLCLP-V	KAREN & WILLIAM MARTIN ENE LTD
KAB ACQUISITION LLLP-IX	KAREN & WILLIAM MARTIN ENERGY
KAB ACQUISITION LLLP-V	KAREN ROSE DURRETT TRST
KAB ACQUISITION LLLP-VIII	KAREN V & WILLIAM H MARTIN ENE
KAB ACQUISITION LP-II	KAREN V & WM H MARTIN ENE LTD
KAB ACQUISITIONS LLLP V	KAREN V MARTIN H ENERGY LTD
KAB ACQUISITIONS LLLP-VI	KARL RICHARD F SR
KADANE EDWARD	KARLTON TERRY OIL CO
KADANE EDWARD G	KAROSEN HANNAH TRUST
KADANE OIL CO	KAROSEN JULIUS TRUST
KAHLIN MERLYN W	KARP CHARLES
KAHN DAVID J	KARP CHARLES L
KAHN EDWARD J	KASE ENERGY LLC
KAHN EDWARD K	KASTMAN BENTON A
KAHN LOUISE W	KASTMAN FAMILY TRUST
KAHN STEPHEN B	KASTMAN OIL CO
KAHN ZARIFF	KASTNER MONTY W
KAISER ED	KATHARINE BOYD DERNOCOEUR
KAISER ENERGY INC	TRST
KAISER FRANCIS	KATHERINE DEER TRST
KAISER FRANCIS ACT	KATHERMAN JUDITH TYLER
KAISER FRANCIS ACT C	KATHERMAN VANCE E
KAISER FRANCIS ANADARKO	KATIEBELL INC
KAISER FRANCIS MID CON LP	KATLEMAN HARRIS L
KAISER FRANCIS OIL	KATS RES LLC
KAISER FRANCIS OIL CO	KAUFMAN WENDY WOLF
KAISER FRANICS OIL	KAUVAR A J
KAISER-FRANCIS GULF COAST LTD	KAY JAY OIL
KAISER-FRANCIS MID-CONT LP	KAY JAY OIL CO
KAISER-FRANCIS OIL	KAY-JAY OIL CO
KAISER-FRANCIS OIL CO	KAYLEE PARTNERS
KAJ OIL & GAS LTD	KB RESOURCES INC
KALKMAN HABECK CO	KC OPERATING CO
KAMLOK OIL & GAS INC	KCM CO
KAMON KEN	KCS MTN RES INC
KANAWHA MINES LTD	KCS RESOURCES
KANDEX RES & DEV	KCS RESOURCES INC
KANEB OPERATING LTD	KCS RESOURCES LLC
KANEGAWA JAY T	KCW CORP
KANSAS CITY ROYALTY CO LLC	KD OIL & GAS INC

Current BLM Oil and Gas Lessees:

KDM PETRO MGT LLC	KELLY LIBBY A WALLA
KDP ENERGY LLC	KELLY LOIS L
KE&J ENTERPRISES LLC	KELLY MOLLY B
KEARNEY VICKIE	KELLY PROPERTIES
KEARNS CAMPBELL INVESTMENTS	KELLY ROBERT L
KEARNS CORP	KELLY RUTH D
KEARNS TRIBUNE CORP	KELLY SUSANNA P
KEAY JAMES W	KELT NM INC
KEBA ENERGY LLC	KELTON C DALE
KEC ACQUISITION CORP	KELTON CINDY
KECK KATHERINE CONE	KELTON CO
KEELEN GEORGE H	KELTON OPER CORP
KEELEN GWENDOLYN R	KELTON OPERATING
KEENAN-MITCHELL ANNE	KELTON OPERATING CORP
KEENE ROY J	KEMMERER MOON ENERGY PTNRS
KEESUN CORP	LLC
KEESUN CORPORATION	KEMMERER MOON ENRGY PRTNRS
KEFFLER DONNA	LLC
KEFFLER JOHN	KEMMERER-LABARGE ROYALTIES
KEIM JEFFREY L	LLC
KEISER C W	KEMMONS WILSON TRUST
KEISLER-MARATHON OIL	KEMP CHARLES W
KEITH DAVID IV	KEMP GARY D
KEITH F WALKER O&G CO LLC	KEMP LUCINDA
KEITH L MOHL TRST	KEMP MAURY KEMP
KEITH L MOHL TRUST	KEMP RONNIE G
KEITH NORVELL ESTATE	KEMP TERRY
KELLENBERGER B J	KEMPNER MARGARET L
KELLER JOSEPHINE	KEMPNER THOMAS L
KELLER LARRY	KEN FARMER OPERATING LLC
KELLER MARVIN A	KEN FARMER OPG LLC
KELLERMAN R E	KEN PERKINS O&G INC
KELLEX CO	KENAI PTNRS 1980
KELLEY CAROL J	KENDALL PRESTON G
KELLEY D SCOTT	KENDALL WARREN P
KELLEY GEORGE & LOIS	KENDELL PATRICIA V
KELLY ANDREW B JR	KENDRICK CARL B
KELLY B CELESTE	KENISA LLC
KELLY CHARLES E	KENNEDY & MITCHELL
KELLY DEE J	KENNEDY & MITCHELL INC
KELLY GEORGE H	KENNEDY GEORGE C
KELLY GLADYS	KENNEDY HOWARD L
KELLY HOPE S	KENNEDY JON P
KELLY JANE M	KENNEDY M JOHN
KELLY JOSEPH J	KENNEDY OIL
KELLY LAURENCE C	KENNEDY OIL CO

Current BLM Oil and Gas Lessees:

KENNEDY OIL PROPERTIES INC	KEYSTONE ENERGY OIL & GAS INC
KENNEDY W D	KEYSTONE EXPL INC
KENNETH A SCHLENKER	KEYSTONE GROUP LP
KENNETH D LUFF TRUST	KEYSTONE O&G CO LLC
KENNETH G CONE TRUST	KEYSTONE O&G MULTI-STATE LLC
KENNETH SUGETT TTEE	KEYSTONE OG NM LLC
KENNETH W CORY INC	KEYSTONE PETROLEUM NM LLC
KENOIL	KFC LLC
KENT ROBERT W	KG CONE CHILDRENS TR
KENTTA CORP	KG OIL INC
KENTTA HAROLD	KH LLC
KENWORTHY OPER CO	KHL INC
KENYON AUBREY F	KHODY LAND & MINERALS CO
KEOHANE INC	KHODY LAND & MINERALS
KEPCO ENERGY INC	COMPANY
KEPCO OPERATING INC	KIDD FAMILY PTNRSHP
KERN MARIAN R	KIDD OIL & GAS LLC
KERNAL BURMA LEE	KIECKHEFER PTNRSHP
KERNAN VIRGINIA A	KIEFER MABEL
KERNS JOHN R	KIESER C W
KEROGEN RESOURCES INC	KIESLING GEORGE E
KERR MCGEE CORP	KIESLING MYRON D
KERR MCGEE O & G ONSHORE LP	KIKER JR ORVILLE P
KERR MCGEE O&G ONSHORE LP	KILLEN JAN MAXWELL
KERR MCGEE OG ONSHORE LP	KILLION B K
KERRCO INC	KILLION RONALD J
KERR-MCGEE CORP	KILMAR OIL CO
KERR-MCGEE N AMER	KILROY CO
KERR-MCGEE OG ONSHORE LP	KILRUSH PETROLEUM INC
KERR-MCGEE OIL&GAS ONSHORE LP	KIMBALL & WILLIAMS
KERRY OIL & GAS INC	KIMBELL CHILDRENS TR
KERRY PETRO CO INC	KIMBELL D A
KERRY PETROLEUM CO	KIMBELL OIL CO OF TX
KERSEY & CO	KIMBELL RUTH A
KERSEY HAROLD	KIMBREL OIL CORP
KERSEY MARY ELLEN	KIMSEY ROY E JR
KES OIL & GAS LLC	KINCAID & WATSON
KESTREL PROPERTIES LLC	KINCAID DRU I
KEVIN BUTLER & ASSN	KINCAID GAIL I
KEY EXPLORATION	KINCHELOE DALTON
KEY PROD CO INC	KINDELSPIRE BYRON
KEY PRODUCTION CO	KINDELSPIRE CLINTON
KEY PRODUCTION CO INC	KINDELSPIRE WAYNE
KEYS THOMAS J	KINDER MORGAN CO2 CO
KEYSER CASSANDRA	KINDER MORGAN CO2 CO LP
KEYSER JEAN E	KINDERMAC LTD CO

Current BLM Oil and Gas Lessees:

KINDLER ARTHUR H	KISLAK PHIL
KINETIC ENERGY PARTNERS LLC	KISSACK WATER&OIL SERVICE INC
KING ALLAN C	KITTINGER BRUCE E
KING CAMP WATER DIS	KITTINGER NANCY L
KING CARL B	KITTRELL CHARLES J
KING F DAVID	KIVA EXPL 1 LTD
KING JAMES E	KK&R OIL & GAS COMPANY
KING JOE W	KLABZUBA BROS LLC
KING JOHN L	KLABZUBA JOE J
KING O J	KLABZUBA O&G
KING O&G OF TX LTD	KLABZUBA O&G FAMILY LTD
KING RANCH O&G INC	PTNRSH
KINGERY DRLG CO INC	KLABZUBA OIL & GAS
KINGERY M J	KLABZUBA OIL & GAS INC
KINGERY MARY JANICE	KLABZUBA OIL AND GAS
KINGERY PROD CO	KLABZUBA ROBERT
KINGFISHER RES INC	KLABZUBA ROYALTY CO
KINGS X OIL CO LLC	KLEBE BETTY ANN
KINGSWELL OG CORP	KLEBE JOHN
KINNEBREW LEE	KLEEN HAROLD J
KINNEY COASTAL OIL	KLEIN GROSSMAN TRUST
KINSOLVING DEAN	KLEIN MICHAEL L
KIOUS HAROLD	KLEIN OIL & GAS INC
KIPLING ENE INC	KLEIN SUZANE
KIRBY JACK	KLEINPETER JOHN B
KIRBY VERNON V JR	KLEMER JOHN N
KIRBY W S	KLICKER ROBERT A
KIRCH L J	KLINE HAYDEN B
KIRCH M S	KLING ROSE LEONARD
KIRCHER JOHN	KLJ INC
KIRCHHOF FRANCES	KLM PETRO CORP
KIRGAN ROBERT P	KLOBERDANZ PAUL E
KIRKPATRICK OG CO	KLONDIKE ENERGY
KIRKWOOD 1976 LTD	KLT RES LLC
KIRKWOOD OG LLC	KLUBAL JIRI
KIRKWOOD OIL & GAS	KLURFELD GREGOR
KIRKWOOD OIL & GAS LLC	KLURFELD GREGORY
KIRKWOOD ROBERT W	KLUTHE J G TRUST "A"
KIRKWOOD STEVEN C	KLYM DAVID W
KIRKWOOD STEVEN G	KMD OPERATING CO LLC
KIRKWOOD VIOLA J	KMI WHITTAKER 1983
KIRKWOOD W C	KN ENERGY INC
KIRKWOOD WILLIAM C	KNAPP OIL CORP
KIRN DOUGLAS J	KNAPP STANLEY
KIRN JOE	KNEZ OIL PROP INC
KIRWAN PHILIP J	KNG-CENTRAL LLC

Current BLM Oil and Gas Lessees:

KNIGHT CONSTANCE N	KONE JAMES S JR
KNIGHT ENERGY GROUP II LLC	KONSTANTINE GEORGE P
KNIGHT EVA	KOONTZ GLADYS A
KNIGHT INC	KOOTENAI RESOURCES CORP
KNIGHT L ROGER	KOPPEL ROSEMARY
KNIGHT REUBEN B	KOPSENG RYAN V
KNIGHT THOMAS H	KORB DONNA MAE
KNIPPENBERG ROSE	KORB JO ANN
KNOBLER WILLIAM M	KORNEGAY GARY L
KNOOP PAUL M	KOSANKE MARY LOU
KNOWLES E TRUST	KP ACQUISITION CORP
KNOWLES ELIZABETH W	KRAKER MARIE
KNOWLTON TOM E	KRAL VIVIAN M
KNOX GORDON S	KRAMER BARB
KNOX GWENDOLYN	KRAMER MOLLY M
KNOX INDUSTRIES INC	KRAMER TERRY S
KNOX JACK D	KRAUS GREGORY P
KNOX JANE O	KRAUSE LARRY D
KNOX-HELM THERYLENE	KRAUSE LINDA S
KNUTSEN ORVILLE M	KRAUSE ROBERT A
KNUTSON INGA	KRAVETZ LAWRENCE I
KNW OIL & GAS INC	KRAVETZ SYDNEY A
KOBERLEIN DONALD	KRAVIS RAYMOND F
KOBERLEIN LEONA	KRAVIS RAYMOND H
KOCH DOUGLAS C	KRB ENTERPRISES INC
KOCH EXPL CO	KREEGER DAVID L
KOCH EXPL CO LLC	KREJCI HARRY L
KOCH EXPLORATION CO LLC	KRESTERRA GROUP LLC
KOCH EXPLORATION COMPANY LLC	KREY MAX A
KOCH HERBERT A	KRIDLER NINA L
KOCH PRODUCTION CO	KRIEBEL GAS CO
KODAK PRODUCTION CO	KRIEGER DONNA M
KODIAK OIL AND GAS USA INC	KRINGEL TRUST
KODIAK OG CORP	KRINSKY MARK P
KODIAK OG USA INC	KRISHER EARLY DRILLING
KODIAK OIL & GAS (USA) INC	KRISLEN ENERGY LC
KODIAK PETROLEUM INC	KRITIKOS BE JO
KODIAK PRODUCTION CO	KROHN DAVID H
KOECHEL JOHN	KROLL OIL & GAS CO
KOHLER R HAGAN	KROLL SHERRY
KOHLMAN ANN E ESTATE	KROTTINGER IRA H JR
KOHLMAN PAUL C	KROTTINGER MARY L
KOHLMAN PTNRSHP	KRS ROYALTIES LPC
KOLOB LLC	KRUGER JOANNE
KONA LTD	KRUGER PETER
KONA OIL & GAS PROPERTIES LP	KRUSE ROBERT

Current BLM Oil and Gas Lessees:

KRYSTAL SIDNEY D	L ZWICK TRUST III
KSJR OIL LLC	L&J GAS PARTNERS INC
KTM ENERGY CO	LA CIMA EXPL LLC
KUCHERA A	LA PLATA GATHERING
KUCHERA M	LA VIDA ENERGY CORP
KUDO PETROLEUM LLC	LABARGE MINERALS INC
KUGELER H A JR	LABRADOR ENERGY LLC
KUGLER WILLIAM E	LABRADOR OIL CO
KUHN OIL CO INC	LACEY LAURENCE A
KUKN ROBERT L	LACEY LINDA S
KUKN WILLIAM D	LACKEY JOHN W
KUKUI INC	LACKEY MICHAEL J
KULIS RICHARD W	LACOS LAND CO
KULP ENERGY LTD CO	LACY OPERATIONS LTD
KUNDRIK KENNETH J	LACY PROPERTIES LTD
KUNDYSEK DAVID L	LADD JERRY D
KUNKEL KENNETH L	LADNER HILTON L
KURAN RESOURCES INC	LADORA LUCAS TRUST
KURT WISEMAN OIL & GAS LLC	LADOUCEUR JANE P
KURTZ SUSAN S	LADSON WILLIAM F
KUTZ DONALD	LADUE JACK W
KWA INC	LAFITTE DARRELL M
KWB INC	LAFORCE W W JR
KYGER E ROSS	LAFORCE-KEYES NANCY
KYKUIT RESOURCES LLC	LAHR GARY E
KY-WY OIL CO	LAHRMAN HELEN
L & J GAS PARTNERS INC	LAHRMAN MICHAEL W
L & J OPERATING INC	LAIRD DACON C III
L & M DRILLING INC	LAIRD MICHAEL L
L A GILLES ESTATE	LAIRD T ORR COAL CO
L A MCPEEK & COMPANY	LAJ CORP
L B INDUSTRIES INC	LAJ EXPLORATION
L B POOL TRUST	LAKE DONALD H TRST
L B SIMMONS ENE INC	LAKE FORK RES LLC
L C SCOTT TRUST	LAKESHORE ENERGY INC
L CROSS ENERGY LLC	LAKEWOOD INVST LLC
L E JONES PROD CO	LAM FINANCIAL HOLD
L H SMITH MGT TRUST	LAMAMCO DRILLING CO
L MACNAUGHTON TRUST	LAMAMCO DRLG CO
L N TAUBMAN TRUST	LAMAMCO PRODUCING II LP
L R COMPANY	LAMAR HUNT TRST EST
L T PARTNERS	LAMAR HUNT TRUST ESTATE
L W MONCRIEF TRUST	LAMAR LUNT TRUST
L W WINKLER & SON	LAMB ALAN L
L ZWICK TRUST I	LAMB GARLAND C
L ZWICK TRUST II	LAMB GARY L

Current BLM Oil and Gas Lessees:

LAMB GEORGE III	LANGFORD JEFFREY R
LAMB RAYMOND N	LANGHAM PETRO EXPL
LAMBERT LEXEY C TRST	LANGHAM PETROLEUM
LAMBERT MICHAEL W	ANGLEY DOROTHY
LAMBERT ROBERT B	ANGLEY ENERGY INC
LAMBERT ROBERT TRST	ANGLEY W J
LAMBERT THOMAS	LANGREHR & CO LLC
LAMBERT THOMAS J	LANGRUM OTTO S EST
LAMBIASE FRANCESCO	LANHAM FRAZIER S III
LAMBRECHT GAIL A	LANIER SIDNEY
LAMICQ JOHN JR	LANKFORD RAYMOND JR
LAMICQ JOHN SR	LANKFORD ROSS E
LAMMERTS ROBERT P	LANNON ELIZABETH M EST
LAMONT THOMAS S	LANSDALE WILLIAM M
LAMOTTE OIL CO	LANSFORD ROBERT W
LAMP INVESTMENTS	LANTANA OIL CO
LAMPERT LEON M	LAPLANTE DALE
LANCASTER ELISSA N	LARAMIDE CORP OF(ID)
LANCASTER WILLIAM D	LARAMIDE EXPL LLC
LANCE ALLAYNALEE K	LARAMIDE EXPLORATION LLC
LANCE OIL & GAS CO	LARAMIDE LLC
LANCE OIL & GAS CO INC	LARAMIDE RESOURCES LLC
LANCE OIL & GAS COMPANY INC	LARAMIE ENERGY II LLC
LAND COOPER B	LARAMIE ENERGY LLC
LAND ENERGY INC	LARCO DRILLING CO
LAND NAT RES DEV INC	LAREDO PETRO INC
LANDCASTER RES LLC	LARGO CANYON TRUST
LANDCASTER RESOURCES LLC	LARGO INVESTMENTS LLC
LANDIS BESS	LARGUS EXPL INC
LANDIS DRILLING	LARIAT PETROLEUM INC
LANDIS ILEAN M	LARIO O&G CO
LANDMARK GAS CORP	LARIO OG CO
LANDMARK RLTY INV CO	LARIO OIL & GAS CO
LANDRESS JAMES V	LARIO OIL AND GAS CO
LANDRETH DONNA P	LARK ACQUISITIONS LLC
LANDRETH ROBERT E	LARKIN SANDRA
LANDS ALLIANCE	LARMEE ERNEST W
LANDSTAR LLC	LARMON JIM S
LANDWEST UT GEN PTNR	LARO OIL & GAS COMPANY
LANE DEWEY	LARRY L SIBLEY OIL & GAS CO
LANEER RES LTD	LARSEN DAVID T
LANEXCO INC	LARSEN GLEN A
LANEY DAVID M	LARSEN VINCENT T
LANG WILLIAM EARL SR	LARSON BENJAMIN J
LANGA TRUST	LARSON CARRIE
LANGDON DEWEY HARRIS	LARSON FRANK A

Current BLM Oil and Gas Lessees:

LARSON IRV	LAVINIA SCHREUDER TRUST
LARSON PATSY	LAW CLARENCE
LARSON PETROLEUM LLC	LAW CREED
LARSON VIRGINIA COOK	LAW DONALD J
LARUE & MUNCY	LAW THEO N
LARUE C E	LAWRENCE CF & ASSOC
LARUE SAM	LAWRENCE DAVID F
LAS ANIMAS PROD CO	LAWRENCE J BRADSHAW ESTATE OF
LAS COLINAS ENE CORP	LAWRENCE SMITH OIL LLC
LAS COLINAS MINERALS LP	LAWSON HOMER
LAS PALMAS PETROLEUM CORP	LAWSON KYLE R
LASATER DAN	LAYTON DONALD R
LASER CHARLES	LAYTON G E
LASER EXPLORATION INC	LAYTON GUS
LASER GLENDA	LAYTON MARY L
LASER JEFF	LAZAR JOSEPH A JR
LASMO OIL & GAS INC.	LAZAR SEYMOUR
LASRICH BEVERLEY TST	LAZAR STEPHEN ET UX
LASRICH LANE	LAZY H LTD PTNRSHP
LASSETER DAVID H	LBO NEW MEXICO INC
LASSO OIL & GAS LLC	LBO NM INC
LAT INVESTMENTS LLC	LCS COMPANY INC
LATE F M	LCX ENERGY LLC
LATE OIL CO	LDH HOLDINGS LLC
LATEX PETRO CORP	LDNGC SERIES TRST
LATEX PETROLEUM CORP	LDP 1 LTD PTNRSHP
LATIGO ENERGY CO	LDRC ENERGY INC
LATIGO OIL & GAS INC	LEA CO NEW MEXICO EXPL & PROD
LATIGO PETROLEUM INC	LEA CORP
LATIMER EARL A II	LEA ROSS B
LATIMER EARL A III	LEA W ASSN
LATIMER KATHRYN S	LEACH DUFF FAMILY TRUST
LATTNER FREDERIC P	LEACO EXPL & PROD CO
LAUDERMILK BERNARD	LEACO NM EXPL & PROD LLC
LAUDERMILK PATRICIA	LEAF RIVER RESOURCES CORP
LAUFER DOUG	LEAF RIVER RESRC CORP
LAUGHLIN BOYD	LEAH GOODSTEIN TRUST
LAUGHLIN JOSEPHINE LIV TRUST	LEAR PETRO EXPL INC
LAURA C STEELE TRUST	LEAR PETRO PTNRS
LAURA I BRAGG ESTATE	LEAVITT DARWIN H II
LAUREL EXPLORATION CO	LEBER HARRY
LAUREL HILL TRUST	LEBOW DANIE M
LAUREL MINING CO INC	LEBSACK JAMES S
LAURELIND CORP	LEBUS KAREN I
LAUREN S YATES TRUST	LEDA R HEIMSATH TRST
LAUSTEN ENERGY LLC	LEDBETTER HUGH E

Current BLM Oil and Gas Lessees:

LEDBETTER RICHARD I	LEJEUNE FRANCIS E JR
LEDBETTER RODNEY	LEJEUNE JR FRANCIS E
LEE BARRY	LEMA PETRO INC
LEE CHIH YUAN	LEN A MAYER EST
LEE GENE	LEN MAYER INC
LEE GEORGETTE B	LENEXCO INC
LEE GLADYS B	LENORE RICHARDS TR
LEE JACK	LEONARD DAN M
LEE JENNETTE L	LEONARD J M
LEE M BASS TRUSTEE	LEONARD KEVIN K
LEE MARTIN	LEONARD ROBERT J
LEE ROBERT B	LEONARD ROBERT K
LEE ROBERT S	LEONARD TIM T
LEE RUBIE J	LEONARD TIMOTHY T
LEE WILEY MONCRIEF 1988 TRST	LEONARD TRST UTD
LEE WILEY MONCRIEF 1988 TRUST	LEONG PATRICK J
LEE WILEY MONCRIEF TRUST	LEOR ENERGY (HOUSTON) LP
LEEDE E H	LEP OPER INC
LEEDE EXPLORATION	LEPAKAST PROPERTIES LP
LEEDE OPERATING CO	LERBLANCE W P JR
LEEDE OPERATING CO LLC	LEROY BACON TRUST
LEEDE OPERATING COMPANY LLC	LEROY DAVID A
LEEMAN DON J	LERWICK I LTD
LEEMAN ENERGY CORP	LESCO INC
LEEMAN PATTI P	LESTER JOE K
LEESON INTEREST INC	LETT THOMAS W
LEETEX INC	LETT THOMAS W TRUSTEE
LEETON JAMES R JR	LEUTWYLER ROLF K
LEGACY ENERGY CO	LEVI OIL & GAS LLC
LEGACY ENERGY CORP	LEVIN FRANCIS
LEGACY ENERGY INC	LEVINSON MORRIS
LEGACY ENERGY ROYALTY	LEVINSON PTNRS CORP
LEGACY OIL LLC	LEVkulich oil co
LEGACY RESERVES LP	LEVY MARK
LEGACY RESERVES OPER LP	LEVY MARK H
LEGACY RESERVES OPERATING LP	LEVY NORMAN
LEGACY RESOURCES CO	LEWAllen RICHARD
LEGACY RESOURCES LLC	LEWAllen ROBERT D
LEGACY RESOURCES OPER LP	LEWIS & CLARK CORP
LEGADO INVESTMENTS LLC	LEWIS & CLARK EXPL
LEGEND NATURAL GAS IIII LP	LEWIS BILLIE BOB
LEGION LAND & EXPL	LEWIS BURLESON TRUST
LEHMAN JAMES	LEWIS DELMAR H
LEHDORFF/LGB MINERA	LEWIS DELMAR HUDSON
LEIGH C CRUEGER & ASSOC	LEWIS E DON
LEITRIM INC	LEWIS FLA JR

Current BLM Oil and Gas Lessees:

LEWIS GWINN M	LIEBER FRED
LEWIS H DELMAR LIVING TRUST	LIEBER MENACHEM ELIEZER
LEWIS LIVING TRUST	LIECHTY BROTHERS
LEWIS MACNAUGHTON TR	LIEN BRUCE H
LEWIS MICHAEL D	LIEN CHARLES H
LEWIS MILDRED	LIGHTFOOT WALKER A
LEWIS NANCY G	LIGHTHALL EARL H
LEWIS RICHARD L	LIGNUM OIL CO
LEWIS ROLAND	LILLIAN KAMPH TRUST
LEWIS S D	LILLIE M YATES EST
LEWIS S W	LILLY O J
LEWIS SUSAN C	LIM MANAGEMENT INC
LEWIS SUSANNE MILLS	LIME ROCK RESOURCES A LP
LEWIS YALE H	LIMESTONE INV CO
LEXACO INDUSTRIES	LINBECK PARTNERS LLC
LEXICO RES INTERNATIONAL CORP	LINC PETRO RES INC
LEXICON RES CORP	LINC PETROLEUM RESRCS INC
LEXICON RESOURCES	LINCOLN ASTON ESTATE
LEXINGTON GAS & MARINE INC	LINCOLN J D
LEYDA MARION N	LINCOLN OIL & GAS LLC
LFC #68 CORP	LINCOLN OLIVIA G
LFL JT VENT INVST	LINCOLN PETRO LLC
LFR LTD PTNRSHP	LINDE INC
LG&E NATURAL PIPELINE LLC	LINDEMANN JAMES D
LH ARMOUR JR 89 TRST	LINDEMOOD DAVID TRST
LHAH PROPERTIES LLC	LINDENMUTH & ASSOC
LHB CAPITAL PARTNERS LLC	LINDRITH CAPITAL LLC
LI MERRILY J	LINDSAY KEVIN D
LIAO STEVE K C	LINDSEY A YATES TRST
LIBERMAN KENNETH	LINDSEY BETH B
LIBERMAN MARGUERITE	LINDSTROM LARRY L
LIBERMAN MICHELE	LINDY'S LIVING TRUST
LIBERTY ENERGY CO	LINEHAM BETTY LOU
LIBERTY ENERGY CORP	LINK ALBERTA
LIBERTY ENERGY LLC	LINN BROS O&G INC
LIBERTY NATL INC	LINN BROTHERS O&G INC
LIBERTY OG 1982-2	LINN ENE MID CONT HOLDINGS LLC
LIBERTY OG CORP	LINN ENERGY HOLDINGS LLC
LIBERTY PETRO CORP	LINN EXPLORATION & PRODUCTION
LIBERTY PETRO INC	LINN JAMES P
LIBERTY PETROLEUM CORP	LINN MIDWEST ENERGY LLC
LIBERTY PETROLEUM CORPORATION	LINN OPERATING INC
LIBERTY PIONEER ENGRY SRC INC	LIO INVESTMENTS
LIBERTY SOUTHERN ENERGY LLC	LION OIL CO LLC
LIBERTY SOUTHERN PARTNERS LP	LIPPHARDT LUCILLE
LIEBER AVIVA SHIRA	LIPPMAN GEORGE A

Current BLM Oil and Gas Lessees:

LIPPMAN MARGE R	LOCO
LISA CURRY GRAY	LOCURZIO ANDREA
LISCO RICHARD K	LOCURZIO ENRICO
LISHBERG PETROLEUM	LOCUST ENERGY INC
LITT THOMAS W TRUSTE	LODES CLAYTON
LITTLE BEACH ENERGY PTNRS LLC	LODESTONE OPERATING INC
LITTLE CURTIS J	LOGEPOLE LAND SERVICES LLC
LITTLE OIL & GAS INC	LOEB CARL M JR
LITTLE RANDY	LOEB FRANCES L
LITTLE SNAKE RIVER GAS LLC	LOEB HENRY A
LITTLE SUSAN L	LOEB HERMAN L
LITTLE SYLVIA F	LOEB JOHN L
LITTLE SYLVIA TRST	LOEB JOHN L JR
LITZENBERGER EXPL	LOEX PROPERTIES 1983
LIVELY EXPLORATION CO	LOEX PROPERTIES 1984
LIVELY THOMAS W	LOFFLAND THOMAS R
LIVINGSTON CARRIE D	LOFLIN OIL CO
LIZARD OIL & GAS LLC	LOFTIN JOE G
LJLK HARRINGTON INC	LOG PARTNERS
LJR RESOURCES LTD CO	LOGA GLORIA JANE
LJS RESOURCES LLC	LOGAN ESTATE OF GEORGE L
LLANO LAND & EXPL	LOGO 1980 DRILLING
LLOYD H SMITH IRREVOCABLE TRST	LOGO 80 DRLG PTNR
LMBI LP	LOGO ENERGY
LMBI O&G CO LLC	LOGO INC
LMBI O&G MULTI-STATE LLC	LOGON JAMES E
LMBI OG NM LLC	LOGOS CAPITAL MANAGEMENT
LMS LIMITEDLBLTY CO	LOGRO CORP
LO IN ENERGY INC	LOGSDON JAMES F
LOBO ENERGY	LOGSDON MARTY
LOBO ENERGY INC	LOHOFF ELMA N
LOBO EXPL CO	LOIN ENE CORP
LOBO EXPLORATION CO	LOIN ENERGY CORP
LOBO OIL & GAS PTNRS	LOIN ENERGY INC
LOBO RESOURCES INC	LOMAK PRODUCTION CO
LOBRANO ALLEN L	LONDON JACK JR
LOBRANO ETHEL M F	LONDON PETROLEUM CORP
LOBRANO KAREN K	LONDON-MONTIN-HARBER
LOBRANO ROBERT LEO	LONE MOUNTAIN PRODUCTION CO
LOCATORS OG INC	LONE MTN PROD CO
LOCIN OIL CORP	LONE RIDER TRADING CO
LOCKE BRUCE D	LONE STAR GEOPHYSICAL LLC
LOCKE RUSH B	LONE TREE ENE LLC
LOCKER ELIZABETH M	LONE TREE ENERGY & ASSOC LLC
LOCKRIDGE JOHN P	LONESOME OIL LLC
LOCKRIDGE MARY LAURA	LONETREE ENE & ASSOC

Current BLM Oil and Gas Lessees:

LONETREE ENERGY & ASSOC LLC	LOUIS FABIAN KANNENSTINE TRUST
LONETREE PROSPECT LLC	LOUIS MAZZULLO INC
LONG ELIZABETH J	LOUIS S MADRID TRUST
LONG JOE R	LOUISIANA LAND & EXPL CO
LONG LARRY	LOUISIANA LAND & EXPLORATION
LONG LEAF TITLE LLC	LOUISIANA LAND EXPL
LONG LLC	LOUISIANA-HUNT PETRO
LONG MARTHA	LOUISVILLE GAS ELEC
LONG PAUL	LOUDAGIN CONSTANCE
LONG PAUL W	LOUDAGIN NICHOLAS B
LONG ROBERT D	LOVAN NORMAN A
LONG TRUSTS	LOVE JERRY M
LONGHORN PARTNERS	LOVELADY I W
LONGHORN PTNRS	LOVELESS LUCINDA
LONGLEAF ENE GROUP	LOVELESS NADINE P
LONGLEY HELEN K	LOVELETT FELICIA D
LONGRIFLE CO	LOVERIDGE JMS F EST
LONGWOOD EXPLORATION CO	LOW DELWYN J
LOOFBOURROW JAMES	LOWE IRENE
LOOFBOURROW SHERRY W	LOWE PARTNERS LP
LOONEY JOHN DON	LOWE PETROLEUM CO
LOPEZ ALEX	LOWE PTNRS LP
LORA CORP	LOWE THOMAS K
LORAC RESOURCES INC	LOWERY J J
LORAX INC	LOWRANCE MARVEL TRUST
LOREN B MEADERS EST	LOWRY EXPLORATION INC
LORENZEN MERCEDES	LOWRY JACK
LORO CORP	LOWRY LEWIS
LOS ALAMOS TOOL CO	LOWRY NED E
LOS ANGELES DEPT WTR & PWR	LOYD B R
LOS CHICOS	LOYD R S
LOS CINCOS PICADORES LLC	LOZANO JOE J
LOS GALLOS VENTURES LLC	LRF LTD PTNRSHP
LOS SIETE EXPL INC	LRM CORPORATION
LOSEE A J	LTC PARTNERS LTD
LOSEE ELIZABETH	LUALLIN ROGER W
LOSEE INVESTMENTS	LUBRICATION ENG INC
LOST CABIN LLC	LUBRICATION ENGINEERS INC
LOST SOLDIER DEV CO	LUCAS JOHN R
LOTHIAN OIL	LUCAS PATRICIA W
LOTHIAN OIL INC	LUCAS PHIL D
LOTO ENERGY LLC	LUCASFILM LTD
LOUBET JUDITH W	LUCHT CATHRYN M
LOUGH C SHANE	LUCKEN JOHN E
LOUIS DREYFUS NATURAL GAS CORP	LUCY WASHINGTON INC
LOUIS F KANNENSTINE TESTA TRST	LUDLOW OIL & GAS CO

Current BLM Oil and Gas Lessees:

LUDMAN ZELDA L	M & G DRILLING CO
LUFF KEVIN D	M & G DRILLING CO INC
LUKEN OIL CO	M & G OIL AND GAS INC
LUKENS SAM	M & K OIL CO INC
LUNA MARCUS WAYNE	M & L ENTERPRISES
LUND H T JR TRUSTEE	M & M O&G PROP LLC
LUNDBECK G H JR	M & M OIL & GAS PROPERTIES LLC
LUNDELL WILLIAM J	M & T INC
LUNGREN EDWARD W	M A MACHRIS TRUST
LUNING LEONARD	M BLAKEMORE TRUST
LUSK JAMES K	M BRAD BENNETT INC
LUXE ENERGY CORP	M D ABEL CO
LWJ PARTNERSHIP	M E KLEIN & ASSOCIATES INC
LYDA HILL TRUST EST	M E W ENTERPRISE
LYDA HUNT-BUNKER TRS	M F MCCOY TRUST
LYDA HUNT-HERBERT TR	M GRELLA LP
LYDA HUNT-LAMAR TRST	M H ROBINEAU ESTATE
LYDDON JOHN A	M HILL MARITAL TRUST
LYLE EARL R	M HUBBARD TRUST
LYMAN RACHEL	M J MITCHELL ESTATE
LYNCH HELEN S	M J MONCRIEF GRANTOR TRUST
LYNCH JUSTIN B	M J V ACQUISITIONS LLC
LYNCH RESOURCES LTD	M L S INC
LYNCH W W	M M RESOURCES INC
LYNCH, KENT M	M MCKENZIE TRUST
LYNDELL BUCK CO	M MILLER TRUST
LYNDEN USA INC	M P S INC
LYNN D DURHAM TRUST	M R BANDING INC
LYNN JOSEPH ROGER	M R JONES OG LLC
LYNN PATRICK	M REED TRUSTEE
LYNN ROGER J	M RICHARDSON OPER CO
LYNN WILLIAM R	M SIMPSON TRUST
LYNNHART CO INC	M T GOTTLIEB ESTATE
LYNS PETRO CONSULTANTS	M TRUST CORP
LYNX OIL & GAS LLC	M V TURNER TRUST
LYNX PETRO CONSULTANTS INC	M W IVERSON TRUST
LYON JEAN	M W PETROLEUM CORP
LYON JEFF	M W RODGERS ESTATE
LYON JOHN J EST	M WOHLFORD OIL LLC
LYON OIL	M&G DRILLING CO INC
LYONS & LYONS INC	M&M OG PROPERTIES LLC
LYONS PETROLEUM RESERVES INC	M&M OIL AND GAS PROPERTIES INC
LYSNE HENRY	M&M PROD
LYSTER BRANDON LEE	M&W OF LOVINGTON INC
LYSTER LARRY L	M-3 INDUSTRIES PTNRS
LYTM CO INC	MAAR CNTY LINE LP

Current BLM Oil and Gas Lessees:

MAB RESOURCES LLC	MADDOX VIRGINIA M
MABEL LLC	MADISON ELISE ANN SHULER
MABEL REED TRUSTEE	MADISON WILLIAM F
MABLE S BRIGHAM TRUST	MADRIDS COWBOYS INC
MAC PETROLEUM LP	MADRID'S COWBOYS INC
MAC T ANDERSON ESTATE	MADTSON ARLENE J
MACARTHUR FOUNDATION	MAEDGEN VIVIAN M
MACAULEYS OIL PROPERTIES	MAEDGEN WHITE & MAED
MACDANIEL ALGRED M	MAEDGEN WILLIAM F
MACDANIEL GIBBS JR	MAERSK ENERGY INC
MACDONALD 1996 REVOCABLE TRUST	MAGANATEX PETRO CO
MACDONALD HARRY F	MAGEE FRED T
MACDONALD MARGARET S	MAGEE JEROME
MACDONALD TIMOTHY R	MAGEE MAJORIE M
MACE CONSTRUCTION CO	MAGIC CIR ENE CORP
MACEDO FAMILY TRUST	MAGIC CIRCLE ENE CORP
MACEDO SIGRID L TRST	MAGIC DOG OIL & GAS LTD
MACEDO THOMAS A TRST	MAGNATEX PETRO CO
MACEY CHARLES P	MAGNOLIA PETROLEUM
MACFARLANE CO	MAGNOLIA STATE ROYALTY LLC
MACFEE OG LLC	MAGNUM HUNTER PETRO INC
MACH PETRO INC	MAGNUM HUNTER PROD UCTION INC
MACHO KEN	MAGNUM HUNTER PRODUCTION INC
MACHRIS M A	MAGNUM V ENERGY
MACK AARON L	MAGPIE OPER INC
MACK C CHASE TRUST	MAGRUDER GREGORY L
MACK C CHASE TRUSTEE	MAGUIRE ANN B TRUST
MACK ENERGY CO	MAGUIRE CARY JR TRST
MACK ENERGY CORP	MAGUIRE CARY M
MACK EZRA D	MAGUIRE CARY M OIL F
MACK GEORGE S	MAGUIRE MELINDA TRST
MACK INC	MAGUIRE OIL CO
MACK JOSHUA L	MAGUIRE ROY J
MACKENROTH INTERESTS LLC	MAHER PATRICK D
MACKENZIE STUART C	MAHONEY DOME CO
MACLONDON ENERGY LP	MAHONEY DRILLING CO
MACNAUGHTON BRUCE ALAN	MAIN ENERGY INC
MACNAUGHTON LEWIS E	MAIN STAR OIL CO
MACPHERSON DONALD R	MAIN STREET HOLDINGS CO
MACPHERSON OIL CO	MAJESTIC PETRO OPERATIONS LLC
MACQUEST PETRO INC	MAJID TAHIR
MACQUEST RES INC	MAJOR OIL INTERNATIONAL LLC
MACUM ENE INC	MAJORS JIMMY R
MADDOX DONOVAN	MAK ENERGY
MADDOX J F	MAK ENERGY INC
	MAK J ENERGY PARTNERS

Current BLM Oil and Gas Lessees:

MAK J ENERGY WYOMING LLC	MAP OIL CO
MAKOIL INC	MAPCO OIL & GAS CO
MALDONADO MARIO E	MAR OIL & GAS CORP
MALEDON ERNEST RAY	MAR/REG OIL CO
MALJAMAR DEV PRTNSHP	MARALEX DISPOSAL LLC
MALLARD CREEK OIL CO LLC	MARALEX RESOURCES
MALLIS NICHOLAS	MARALEX RESOURCES INC
MALLIS NICHOLAS M D	MARATHON OIL (EAST TEXAS) LP
MALLIS NICHOLAS MD	MARATHON OIL CO
MALLON GEORGE O JR	MARATHON OIL COMPANY
MALONE BAYNARD TRUST	MARBOB ENERGY CORP
MALONE BAYNARD W	MARBRUSAL PARTNERS
MALONE EARL L	MARCELLIN ROGER G
MALONEY ROSE ANN	MARES BEN E
MALOY FAMILY TRUST	MARGARET COUCH TRUST
MALPHUS MARY LOU	MARGARET DIETZEN CALLINAN
MALSON LEON	TRST
MALSON OIL CO	MARGARET HILL MARITAL TRUST
MAMMOTH 84	MARGARET J OMAN TRUST
MANANA GAS INC	MARGENE BLAKEMORE MGT TRST
MANASSAS LLC	MARGRETTA HILL WIKERT TRUST
MANATT JAMES JR	MARGRETTA HILL WILKERT TRUST
MANBRO ENERGY CORP	MARIA VIOLETA VAN ROZELEN
MANCLARK DARLEEN	MARIANNE FISHER LLC
MANCLARK WILLIAM R	MARICO EXPL INC
MANEWAL BRADLEY OIL	MARILYN B REAGAN TRUST
MANGUM A L JR	MARILYN MAXWELL TRUST
MANIX ENERGY	MARILYN Y CHASE TRUST
MANIX ENERGY LTD	MARINE & GAS INTL
MANN CLIFTON	MARINER ENERGY INC
MANNCO LLC	MARION ENERGY INC
MANNESS PETROLEUM CORP	MARION V TURNER TRST
MANNING ELLIS W JR	MARITAL M HILL TRUST
MANNING OIL PARTNERS	MARJO OPERATING CO INC
MANNING-PITKIN JANE	MARK I PHILLIPS
MANNIN-PARNELL ETHEL	MARK L SHIDLER INC
MANPART ASSN	MARK SHIDLER INC
MANSFIELD H	MARK V PETROLEUM CO
MANSFIELD J	MARK WEST TRUST
MANTA OIL & GAS CORP	MARKEA CORP
MANTI RESOURCES INC	MARKER PETROLEUM INC
MANTICORE RESOURCES	MARKHAM E D
MANVILLE SALES CORP	MARKHAM JACK
MANX OIL CORP	MARKHAM RODERICK A
MANZANO LLC	MARKHAM RODERICK ALLEN
MANZANO OIL CORP	MARKHAM STEVEN RAY

Current BLM Oil and Gas Lessees:

MARKS & GARNER PROD	MARTIN BUELL
MARKS OIL INC	MARTIN CLAIRE TRST
MARKS T KEITH	MARTIN DEAN
MARKUS FRITS	MARTIN E CECILE
MARKUS PROD INC	MARTIN EXPL MGT CORP
MARKUS PRODUCTION INC	MARTIN FRED G
MARKWEST RESOURCES INC	MARTIN FUELS CO INC
MARLIN OIL CO LLC	MARTIN HENRY C TRST
MARLIN OIL CORP	MARTIN III YATES EST OF
MARLIS E SMITH INC	MARTIN JAMES M
MARLIS E SMITH TRUST	MARTIN K V
MARMIK OIL CO	MARTIN LARREY C
MAROSKI WILLIAM P	MARTIN LIVING TRUST
MARPLE TERRY	MARTIN OG INVSTMNT
MARQUIS ALLRED ENGR	MARTIN RICHARD G
MARR EMMA D	MARTIN RONNIE
MARREG INVESTMENTS	MARTIN SANDY
MARRIOTT REBECCA S	MARTIN STEPHEN T
MARRS & SMITH PTNRSHP	MARTIN SYDNEY D
MARRS M W	MARTIN TRUST
MARRS MAYO	MARTIN WILLIAM H
MARSH OPER CO	MARTIN YATES III ESTATE
MARSHALL & WINSTON	MARTINEZ DOROTHY J
MARSHALL & WINSTON INC	MARTINEZ J B
MARSHALL 1987 MGMT	MARVIN JOHN B
MARSHALL 87 TRUST	MARVIN WHITNEY H REVCLBLE TRST
MARSHALL CULLEN EAST	MARY A HUDSON TRUSTEE
MARSHALL DOUGLAS B	MARY BETH YATES 1976 TRUST
MARSHALL EXPL CO	MARY F TURNER TRUST
MARSHALL GENEVIEVE	MARY JANE OMAN TRUST
MARSHALL HUGH ROY	MARY K FOWLES TRUST
MARSHALL J HOWARD	MARY KAY GROUP
MARSHALL J HOWARD II	MARY M BARBEE TRUST
MARSHALL OIL CORP	MARY PERRY ANDERSON EST TRST
MARSHALL RESOURCES LLC	MARY SHORE 1971 TRUST
MARSHALL THOMAS F	MARY SWENSON TRUST
MARSTON JAMES G III	MARY YATES DAVIS 1976 TRUST
MARTHA L LUSK TRUST	MARYAN KLINGER TRUST
MARTHA R SCHALK TRUST	MAS OPERATING CO
MARTIN ACQUISITIONS	MASEK JOHN A
MARTIN ADA C	MASHED O MINERAL
MARTIN ANDERSON TRUST	MASLAN HERBERT L
MARTIN BETTY J	MASON DIXON ENERGY INC
MARTIN BUCKLEY G	MASON RICHARD L
MARTIN BUCKSBAUM MARITAL TRST	MASON STUART D
	MASONIC HOMES OF CA

Current BLM Oil and Gas Lessees:

MASSAD RALPH ESTATE  
MASSAD REALTY  
MASSEY & HERELL  
MASSEY J E  
MASSEY JON G  
MASTER MIN HOLDING  
MASTER MIN HOLDINGS INC  
MASTER MINERAL BLDG  
MASTER MINERAL HOLDINGS  
MASTER PETRO & DEV  
MASTERS ELISE  
MASTERS NANCY  
MASTERS SIX TRUST  
MASTERS W W  
MASTERS WESLEY W JR  
MASTERSON RICHARD E  
MASTERSON W D  
MASTORAKOS D A  
MATADOR RESOURCES CO  
MATAGORDA ISLAND EXP  
MATAGORDA PROD CO  
MATCO 850 LTD  
MATESKI MARILYN  
MATHIS BETTY L  
MATHIS BILL  
MATHIS CARROLL M  
MATHIS E R ESTATE  
MATHIS KNIGHT MACHELLE  
MATHIS MARILYN F  
MATHIS MELANIE  
MATLOCK DENISE  
MATRIS EXPLORATION CO LP  
MATRIX DRILLING  
MATRIX ENERGY INC  
MATRIX ENERGY LLC  
MATRIX PRODUCTION CO  
MATRIX UTAH PROD CO LLC  
MATSON GEORGE J  
MATTER J E  
MATTHES RUTH H  
MATTHEWS JOAN  
MATTHEWS JOHN A  
MATTINGLY INC  
MATTLAGE GLENN  
MATTOX JOEL D  
MATTSON JEFFREY C

MATULA MARK C  
MATZ MIKE J  
MAUDE MACKEY ESTATE  
MAURICE L BROWN CO  
MAURINE TAUBMAN TRST  
MAUZY GREG  
MAVERICK O&G CO  
MAVERICK OG CO  
MAVERICK OIL & GAS CORP  
MAVERICK PETROLEUM INC  
MAX HARRY L JR  
MAXEY JOHN C  
MAXEY JOHN C II  
MAXEY JOHN C JR  
MAXIM DRLG & EXPL  
MAXIMA INTERNATIONAL LLC  
MAXIMILLIAN PROD CO  
MAXIMUM ENERGY CORP  
MAXSON VIRGINIA D  
MAXUS ENE CORP  
MAXUS ENERGY CORP  
MAXUS ENERGY CORPORATION  
MAXWELL O T  
MAXWELL PERRY C JR  
MAXWELL PETRO INC  
MAXWELL RESOURCES CO  
MAXWELL RESOURCES CORP  
MAXXAM INC  
MAY DANNY  
MAY GEORGE  
MAY JACK  
MAY JAMES  
MAY JIM  
MAY JOANNE  
MAY PETRO INC  
MAYBORN ENERGY CO  
MAYCO RESOURCES  
MAYDELL MILLER TRUST  
MAYER DANETTE T  
MAYFIELD CO  
MAYFIELD GIDEON C  
MAYFIELD WARREN P  
MAY-KULP APRIL  
MAYLAND BRENDA K  
MAYNARD OIL CO  
MAYNE & MERTZ INC

Current BLM Oil and Gas Lessees:

MAYO KATHLEEN PERRY	MCCARTNEY JACK A
MAYO MEDICAL RES	MCCARTY OLIVE FOSNER
MAYPOLE W E	MCCASLIN MAXINE S
MAYS ED	MCCAW JACK W
MAYS JOEL T	MCCLATCHY J A
MAYS L LOWRY	MCCLELLAN BARBARA A
MAZZULLO ENERGY CORP	MCCLELLAN LISA CAROL
MB EXPLORATION CORP	MCCLELLAN MARK HOWELL
MB EXPLORATION LLC	MCCLELLAN OIL CORP
MB OPERATING CO INC	MCCLELLAND CANDACE
MB SQUARED INC	MCCLELLAND CANDACE C
MBG TRUST LLC	MCCLINTOCK KAREN E
MBGV PARTITION LLC	MCCLUNG DONALD R
MBI OG LLC	MCCLURE ENTERPRISES
MBOE INC	MCCLURE MERLE L
MBR RESOURCES INC	MCCLURE OIL CO INC
MC RESERVES INC	MCCLURG MICHAEL R
MCADAMS C A	MCCLYMOND J L
MCADAMS JACKIE R	MCCOMB EDGAR
MCADAMS JAMES A	MCCOMBS ENERGY LLC
MCADAMS RAYMONA	MCCOMMONS OIL CO
MCAFEE K E	MCCONNELL BARBARA I
MCAFEE OIL & GAS LLC	MCCONNELL DRILLING
MCALESTER FUEL CO	MCCONNELL GEORGE
MCALLISTER DOROTHY	MCCONNELL KENNETH W
MCALLISTER DOROTHY E	MCCONNELL LTD CO
MCALLISTER JEAN M	MCCONNELL MARY ELLEN
MCALLISTER LEON	MCCOOL J M
MCALLISTER MARY JANE	MCCOOL JOHN E
MCB PROPERTIES	MCCORD FRANCES F
MCBRIDE HELEN A	MCCORMACK JOHN M
MCBRIDE OG CORP	MCCORMICK DON G
MCBRIDE OIL & GAS CORP	MCCORMICK RLTY TRST
MCBRIDE R A JR	MCCORMICK SONJA V
MCCABE FRANK	MCCORMICK WILLIAM P
MCCABE GREG	MCCOWN CATHIE CONE
MCCABE PETROLEUM CORP	MCCOY CHARLES F
MCCALL ROBERT J	MCCOY EXPLORATION CO
MCCALLISTER HOLWAY WESLYNN	MCCOY HARVEY H
MCCALLISTER MARK A	MCCOY JOHN ROGER
MCCAMPBELL MAURICE	MCCOY KEITH S
MCCANN D	MCCOY MARY FAYE
MCCANN GERT	MCCOY PETROLEUM CORP
MCCANN R	MCCRACKEN GERTRUDE
MCCARTHY L J ASSN	MCCULLISS RES CO INC
MCCARTHY LAWRENCE J	MCCULLISS RESOURCES

Current BLM Oil and Gas Lessees:

MCCULLISS RESOURCES CO INC  
MCCULLOCH ROBERT C  
MCCULLOUGH GOODALL W  
MCCULLOUGH GOODALL W III  
MCCULLOUGH MARYL MAR  
MCCULLOUGH RALPH H  
MCCULLOUGH ROBERT  
MCCULLY CHAPMAN EXPL INC  
MCCULLY CHAPMAN EXPLOR INC  
MCCULLY-CHAPMAN EXPL INC  
MCCULLY-CHAPMAN EXPLRN INC  
MCCRUDY GRACE  
MCCRUDY MARGARET  
MCCUTCHEON ENERGY CO  
MCCUTCHIN GENE  
MCCUTCHIN JERRY A JR  
MCDANIEL & BEECHERL  
MCDANIEL PAUL N  
MCDANIEL SHERMAN P  
MCDERMETT JOHN C  
MCDERMOTT EDWARD H  
MCDERMOTT JOHN R  
MCDERMOTT PATRICIA  
MCDONALD ELEANOR J  
MCDONALD G K  
MCDONALD G W  
MCDONALD MIKE  
MCDONALD SAM E  
MCDONNOLD CRAIG M  
MCDONNOLD M JR  
MCDONNOLD OPER INC  
MCDOUGALL CAROL J  
MCDOUGALL ROBERT E  
MCDUFFIE JOEL  
MCEKNZIE METHANE CO  
MCELVAIN DAVID P  
MCELVAIN EDITH S  
MCELVAIN ENERGY FUND 2010 LLC  
MCELVAIN GUY WM  
MCELVAIN JAMES E  
MCELVAIN O&G PTNRSHP  
MCELVAIN OIL & GAS  
MCELVAIN OIL CO  
MCELVAIN OIL CO LP  
MCELVAIN RALPH  
MCELVAIN RALPH C JR

MCELVAINE RUTH P  
MCELVAINE T H JR  
MCFARLAND ENERGY INC  
MCFARLAND JAMES P  
MCGARVEY RUTH  
MCGEE DRILLING CO  
MCGEE JANETTA L  
MCGEHEARTY SHIRLEY NELL  
MCGHEE CECILIA D  
MCGINTY DON  
MCGINTY L V SR  
MCGINTY-DURHAM INC  
MCGLASHAN JACQUELINE J  
MCGOVERN MICHAEL Y  
MCGOWEN JAMES A  
MCGOWEN RESOURCES CO  
MCGREGOR A A  
MCGUFFIN JOE JR  
MCHUGH CO  
MCHUGH JEROME P  
MCILNAY EDWARD W  
MCILNAY INVESTMENTS  
MCILWAIN ALEX  
MCINNES RES CO  
MCINROE BRADLEY  
MCINTOSH GAS CO  
MCINTOSH WALDO L  
MCK INVESTMENTS  
MCK INVESTMENTS LLC  
MCKAMEY KEITH E  
MCKAY CHILDRENS TRUST  
MCKAY HORACE F  
MCKAY LIVING TRUST  
MCKAY OIL CORP  
MCKAY PETROLEUM CORP  
MCKAY ROY L  
MCKEAGE B F  
MCKEAGE ERNEST  
MCKEAGE THOMAS  
MCKEE JACK W JR  
MCKENNA P A  
MCKENZIE METHANE CO  
MCKENZIE PETRO CO  
MCKEOWN EDITH S  
MCKINLEY RESOURCES LLC  
MCKINNEY GARY D

Current BLM Oil and Gas Lessees:

MCKINNEY GLENN M	MCMILLAN PROD CO INC
MCKNIGHT DORA L	MCMILLAN PRODUCTION CO INC
MCKUSH ED	MCMILLAN SUSAN
MCLANE ALFRED E EST	MCMILLAN SUSAN A
MCLANE D	MCMILLAN VENTURES LLC
MCLANE DAVID G	MCMILLAN-BALLARD L
MCLANE MONTY D	MCMORAN O&G CO
MCLANE S	MCMORAN OIL & GAS LLC
MCLAUGHLIN INVST INC	MCMULLEN MANON M
MCLEAN ELDEN	MCMULLEN MANON MARKHAM
MCLEAN INVESTMENTS GROUP LLC	MCMULLIN SHERI
MCLEAN J K	MCMURTRY WILBUR E
MCLEAN JAMES D	MCNALLY JAMES P
MCLEAN THOMAS RICHARD	MCNAUGHTON J
MCLELAND C M	MCNEILL DON T
MCLELAND CHARLES J	MCNIC O&G PROP INC
MCLELAND DEBORAH J	MCNIC O&G PROPERTIES
MCLELAND FLORENCE	MCNIC OG MIDCON INC
MCLELAND PEGGY L	MCOUGAL DANNY W
MCLEOD DOUGLAS C	MCP ORRION LLC
MCLISH FAMILY PTNRSHP LTD	MCPETERS K D
MCLISH HOLMES P	MCR LLC
MCLISH PETRO CO	MCRAE & HENRY LTD
MCLISH PETROLEUM CO	MCRAE NANCY TRST
MCLISH RESOURCES LLP	MCRAE W THOMAS
MCLISH RESOURCES LP	MCRAE WALTER THOMAS
MCLISH RESOURCES LP LLP	MCREYNOLDS ELIZABETH
MCLORAIN HELEN M	MCSWEYN NANCY
MCM OG LLC	MCTIERNAN J W
MCMAHAN BERYL B	MCTIERNAN JAMES W
MCMAHAN JOHN T	MCTIERNAN MICHAEL K
MCMAHAN THOMAS V	MCVAY DRILLING INC
MCMAHON JOHN L JR	MCVAY DRILLING CO
MCMAHON JOSEPH K	MCVEY HAL A
MCMAHON OPERATING CO	MCVEY HELEN D
MCMAHON-BULLINGTON	MCWILLIAMS DAVID
MCMANUS GREG	MCYO INDUSTRIES INC
MCMANUS VICKY	MCZ INC
MCMICHAEL DONNA LYNN	MD ENE HOLDINGS
MCMILLAN C R	MD WYOMING LLC
MCMILLAN C R III	MDU RES GROUP INC
MCMILLAN COLIN III	MEAD MARY S
MCMILLAN COLIN R	MEAD NELL
MCMILLAN KAY	MEADCO PROPERTIES
MCMILLAN MICHAEL A	MEADEN WINIFRED C
MCMILLAN PATRICIA A	MEADERS JOHN B

Current BLM Oil and Gas Lessees:

MEADERS LOREN B	MELNYCHENKO PAUL B
MEADERS THOMAS F	MELROE CAROLINE N
MEADOW DEEP LLC	MELROE DOROTHEA E
MEADOW OIL & GAS LLC	MELROE ROGER T
MEADOWS PAUL D	MELROE SYLVAN N
MEAGHER N J JR	MELROSE ENERGY CO
MEAGHER O&G PROPERTI	MELROSE RESOURCES
MEAGHER O&G PROPERTIES INC	MELTON EVAN
MEAGHER OG PROP INC	MELVIN RAY A
MEAGHER OIL & GAS PROP INC	MELZER EXPLORATION CO
MEANS ALAN D	MELZER L S
MEANS EMAREE	MEM 1984 DRLG FUND
MEANY LAND & EXPLORATION INC	MEMORIAL EXPL CO
MEC DEV LTD	MENDELL W T TRUSTEE
MEC DEVELOPMENT LTD	MENDICINO ANTHONY J
MEC PETROLEUM CORP	MENPART ASSOCIATES
MEDALLION EXPLORATION	MEP D III MICHIGAN LLC
MEDALLION PETRO INC	MEP III MICHIGAN LLC
MEDALLION PETROLEUM	MEPNA
MEDICINE BOW OPER CO	MERAMAR CO
MEEHAN SALLY	MERCER FRANCES W
MEEK DONALD	MERCER GP 1984 DRLG
MEEKS RANDY	MERCER REVOCABLE TRUST
MEERKAT WYOMING LLC	MERCHANT MOHAMMED Y
MEETEETSE GAS LLC	MERCHANT RESOURCES #1 LP
MEG OIL LTD 1981	MERCURY HOLDINGS LLC
MEG PETROLEUM CORP	MEREDITH FAMILY TRUST
MEGA PETRO INC	MERIDIAN EXPLOR CORP
MEGA WEST ENERGY MONTANA INC	MERIDIAN OIL PROD
MEGADON ENERGY CORP	MERIDIAN PTNRSHP
MEGAENERGY INC	MERILATT CRAIG C
MEGAS PROPERTIES LTD	MERIT ENE MGT PARTNERS I LP
MEHL ROBERT L	MERIT ENE MGT PARTNERS II LP
MEIER SELBY C	MERIT ENE PARTNERS E III LP
MEIHAUS GEORGE A JR	MERIT ENE PTNRS
MEINHART ARTHUR E	MERIT ENE PTNRS D III LP
MELANCON KRIS	MERIT ENE PTNRS D-III LP
MELANGE ASSOC INC	MERIT ENE PTNRS E III LP
MELANGE INTERNATIONAL LLC	MERIT ENE PTNRS F III LP
MELBA Y TROBAUGH ESTATE	MERIT ENE PTNRS III
MELBBY GAS IV LLC	MERIT ENE PTNRS III LP
MELGERHEL INC	MERIT ENE PTNRS IIIA
MELINDA MAGUIRE TRUST	MERIT ENE PTNRS VII
MELLENTHIN CHERYL	MERIT ENERGY PTNRS
MELLENTHIN CHERYL L	MERIT ENERGY PTRS D-III LP
MELLGREN DEE ANN	MERIT ENERGY CO

Current BLM Oil and Gas Lessees:

MERIT ENERGY COMPANY	MERRELL ALLEN W
MERIT ENERGY PARTNERS D-III LP	MERRICO OIL & GAS
MERIT ENERGY PARTNERS F-III LP	MERRIMAC OIL & GAS LLC
MERIT ENERGY PARTNERS III LP	MERRION GREG T
MERIT ENERGY PTNRS III	MERRION GREGORY J
MERIT ENERGY PTNRS III LP	MERRION MICHAEL K
MERIT ENERGY PTNRS IV LP	MERRION O&G CORP
MERIT ENERGY PTNRS LP	MERRION OIL & GAS CORP
MERIT ENERGY PTNRS VII	MERRION PETRO CORP
MERIT ENERGY PTNRS VII LP	MERRION T GREG
MERIT ENERGY PTNRSHP III	MERRION TRUST
MERIT HOLDING CORP	MERRITT MARGARET
MERIT MANAGEMENT PARTNERS I LP	MERRITT OIL & GAS
MERIT MANAGEMENT PRTNERS II LP	MERRYMAN JUDY
MERIT MANAGEMENT PTNR I LP	MERRYMAN ROBERT
MERIT MGMT PARTNERS I LP	MERTA ROBERT R
MERIT MGMT PARTNERS II LP	MESA GRANDE LTD
MERIT MGMT PARTNERS III LP	MESA MID-CONTINENT
MERIT MGMT PRTNR I LP	MESA OIL CO
MERIT MGT PARTNERS I LP	MESA OPERATING CO
MERIT MGT PARTNERS III LP	MESA OPERATING LTD PTNRSHP
MERIT PARTNERS III LP	MESA VERDE PTNRSHP
MERIT PARTNERS LP	MESAPRO LLC
MERIT PARTNERS MICHIGAN LLC	MESERVE EDWIN A
MERIT PETROLEUM COMPANY	MESERVE J ROBERT
MERITAGE ENERGY CO LLC	MESQUITE SWD INC
MERITAGE ENERGY LLC	MESSINA ISABEL B
MERITAGE ENERGY PARTNERS LLC	MESSINGER JOHN L
MERITNET PTNRS LP	MESSINGER R P
MERIWETHER J S JR	METCALF MICHAEL D
MERKLEY AMOS E	METCALFE ALBERT III
MERKLEY CLIFTON D	METCALFE DONALD T
MERKLEY DIANE D	METEX PIPE & SUPPLY
MERKLEY EMMA P TRST	METRO MINERALS CORP
MERKLEY G WARREN	MEW ENTERPRISE
MERKLEY GEORGE D	MEWBURNE CURTIS W
MERKLEY GLINDON M	MEWBURNE OIL CO
MERKLEY JEANNINE M	MEXCO ENERGY CORP
MERKLEY JUNIOR NEIL	MEYER B D
MERKLEY REED H JR	MEYER B L
MERKLEY SHIRLEY R	MEYER CARL D
MERKLEY THELMA	MEYER ELWOOD
MERLAND OG INC	MEYER GENE
MERLIN CORP	MEYER J R
MERMYR LARRY A	MEYER LOIS E
	MEYER OIL CO INC

Current BLM Oil and Gas Lessees:

MEYER OIL PROPERTIES	MIDDLEBROOK F E JR
MEYER ROBERT F	MIDDLETON BARBARA L
MEYER SOPHIA	MIDDLETON FRED W
MEYERS MELVA JEAN	MIDFORD INC
MEYERS REX THOMAS	MIDGARD TRANSFER CO
MFP PETRO LTD PTNRSH	MIDLAND EMPIRE VENTURES LLC
MG COHEN PROPERTIES LLC	MIDLAND GAS CORP
MGB ENERGY LTD CO	MIDLAND OPERATING INC
MGGINTY DON	MIDLAND SW CORP
MGM OIL & GAS CO	MIDNIGHT HOUR LLC
MGN INVESTMENTS INC	MIDROC OIL CO
MHB PROPERTIES	MIDSOUTHWEST CORP
MHBR ENERGY LLC	MIDSTATES OIL CO
MHM RESOURCES LP	MIDTHUN GERARD J
MHT PROPERTIES LTD	MIDWAY ROYALTY INC
MHW ENERGY LTD	MIDWEST ENT INC
MIC DAV INC	MIDWEST EXPL CO INC
MICHAEL FORREST R ESTATE OF	MIDWEST OIL CORP
MICHAEL HARRISON MOORE 06 TRST	MIDWEST RES 2001-1 O&G INCOME
MICHAEL HILL WISENBAKER TRUST	MIDWEST RES 2006-1 O&G INCOME
MICHAEL J MONCRIEF GRNTRS TRST	MIDWEST RES 98-1 O&G INCOME LP
MICHALSKI KRISTEN K	MIDWEST RES 99-1 O&G INCOME LP
MICHAUD INC	MIDWEST RESOURCES 2002-1
MICHEL CLIFFORD W	MIDWEST RESOURCES 2008-1 O&G
MICHEL T HALBOUTY ENERGY	MIDWEST WELL LOGGING
MICHELL CLIFFORD W	MIEDTKE HELGA M
MICHELSON PETER C JR	MIGHTY OAK ENERGY LLC
MICHIGAN ACQUISITION PROPERTIE	MIKA PETRO LLC
MICHIGAN O&G SER INC	MIKE GOLDEN INC
MICHIWEST ENERGY INC	MIKE KADANE TRUST
MID CONTINENT ENERGY	MIKE ROSS INC
MID-AMERICA PIPELINE	MILAM JAMES D
MIDCO MINERALS LLC	MILBANK ROBBINS
MIDCON CENTRAL EXPL	MILBANK SAMUEL R
MIDCON EXPL CO EXETR	MILBURN C L
MIDCON EXPL-EXETER	MILBURN PRISCILLA A
MID-CON GAS SERVICES CORP	MILE HI O&G INC
MIDCONTINENT ACQUISITION PROP	MILE HI OIL & GAS
MID-CONTINENT ENE	MILES R C
MIDCONTINENT ENE INC	MILES RONALD R
MID-CONTINENT ENERGY	MLESTONE ENERGY CORP
MIDCONTINENT II LLC	MILFORD CLIFF T
MID-CONTINENT II LLC	MILNOVICH LAND CO
MID-CONTINENT INVEST	MILL PETE
MID-CONTINENT RECOVERY INC	MILLAR HOLLY D
MIDDLE BAY OIL CO INC	MILLARD DECK ESTATE

Current BLM Oil and Gas Lessees:

MILLARD MARK J	MILLER OIL CORP
MILLENNIUM ENE CORP	MILLER OLGA E
MILLENNIUM O&G LLC	MILLER RAYE
MILLER & FLOYD	MILLER RAYE P
MILLER & KENNEDY INC	MILLER REAL ESTATE INVESTMENTS
MILLER ALFRED B	MILLER ROBERT B
MILLER ANN	MILLER ROBERT C
MILLER BARBARA J	MILLER RONNIE L
MILLER BERNARD	MILLER ROYALTY CORP
MILLER BILL L	MILLER SCARLETT
MILLER BRIAN K	MILLER SCOTT
MILLER CHARLES B	MILLER SEXE STACIE L
MILLER CHARLES P	MILLER TERRY S
MILLER DAVID	MILLER WILLIAM C
MILLER DUNCAN	MILLER WILLIAM D
MILLER DYER & CO	MILLETT JAMES A
MILLER ENERGY	MILLIARD LINDA K
MILLER ENERGY INC	MILLIKIN SEVERANCE A
MILLER ENERGY LLC	MILLS DAVID L
MILLER ESTELLE E	MILLS DRUMMOND
MILLER EVA C	MILLS FERNE
MILLER FAMILY TRUST	MILLS FLORENCE L
MILLER FORREST B	MILLS GORDON W
MILLER FORREST CHURCH	MILLS PETE
MILLER FRANKIE I	MILLS RICHARD L
MILLER FRED EST	MILLS ROBERT V
MILLER GEORGE C	MILLS WILLIAM A JR
MILLER GLEN DAVID	MILLS WILLIAM H
MILLER GRANT E JR	MILTON, CAROL R
MILLER GREG P	MIMS J DAVID
MILLER IRIS C LEMAY	MINDYANNE E MONCRIEF 1988 TRST
MILLER ISIDORE	MINDYANNE E MONCRIEF TRUST
MILLER JEANNE LEA	MINEL INC
MILLER JELENE EMILY	MINERAL INVESTMENT
MILLER JOEL R	MINERAL INVST CORP
MILLER JOHN WILLIAM	MINERAL RESOURCES INC
MILLER LAND PROFESSIONALS LLC	MINERAL TECH INC
MILLER LOIS DILLARD	MINIKES DIANNE C
MILLER MARY LOU	MINIKES STEPHAN M
MILLER MAST TRUST	MINNOCO INC
MILLER MIKE	MINNTEX OIL CO
MILLER OG ASSETS II LLC	MINTEER
MILLER OG ASSETS III LLC	MINTER ALAN H
MILLER OG ASSETS LLC	MINTER MERTON M JR
MILLER OIL & GAS ASSETS II LLC	MINTON ROBERT J
MILLER OIL & GAS ASSETS III LL	MINTZ DORA & CO

Current BLM Oil and Gas Lessees:

MINTZ MARVIN & CO	MIZEL EXPLORATION CO
MIocene MINERALS INC	MIZEL LARRY A
MIRACLE DAN	MIZEL RESOURCES A TRUST
MIRACLE L R	MIZEL RESOURCES TRUST
MIRADA ENE LLC	MIZEL STEVEN M
MIRADA PETROLEUM CORP	MIZZY SHIRLEY M
MIRAGE ENERGY INC	MJR INVESTMENTS LTD
MIRANDA EXPL LTD	MKB PROPERTIES LLC
MIRIAM FINDLEY TRUST	MKB ENERGY INC
MIRIAM GRYNBERG TRUST	MKL GAS & OIL LLC
MISSION E&P LTD PTNRSHP	MKM EXPL CO
MISSION ENE METHANE	MKR TRST CLAUDIA BORST TRUSTEE
MISSION ENERGY LLC	MMCP LEASING LTD
MISSION RESOURCES CORP	MMG INC
MISSISSIPPI LND&EXPL	MNA ENTERPRISES LTD CO
MISS-LOU PETROLEUM	MOBERLY HARRY R
MISSOURI BASIN WELL SER INC	MOBIL E&P NA INC
MISSOURI BASIN WELL SVC INC	MOBIL EXP & PROD INC
MISSOURI RIV RLTY CORP	MOBIL EXPL & PROD
MITCHELL & MITCHELL	MOBIL EXPL & PROD N AMER INC
MITCHELL BASCOM L	MOBIL EXPL & PROD NA
MITCHELL C D	MOBIL EXPL & PROD US
MITCHELL CHARLES L	MOBIL EXPL & PROD US DEV
MITCHELL DENNIS	MOBIL EXPL PROD SE
MITCHELL ENE CORP	MOBIL OIL CORP
MITCHELL ENERGY CORP	MOBIL OIL EXPL CO
MITCHELL ENERGY CORP LP	MOBIL OIL EXPL&PROD
MITCHELL EXPLORATION INC	MOBIL PIPELINE CO
MITCHELL GEORGE H	MOBIL PROD TX & NM
MITCHELL GROUP	MOBIL PROD TX & NM INC
MITCHELL HELEN S	MOBIL PRODUCING TX & NM INC
MITCHELL JOHN F	MOBIL ROCKY MTN INC
MITCHELL M J	MOBILE OPERATING LLC
MITCHELL MAX B	MOCKLER COLMAN M JR
MITCHELL MAX B TST	MOCKLER COLMAN M JR EST
MITCHELL PAYNE LIMITED	MOCKLER JOANNA S
MITCHELL ROYALTY LTD	MODERN GAS GROUP
MITCHELL SAMUEL A	MOE BARBARA B
MITCHELL SAMUEL A TRST	MOE WALTER S
MITCHELL STEPHEN	MOEBIUS BARBARA M
MITCHELL THOMAS L	MOEBIUS JOHN R
MITCHELL TRUST	MOFFAT GRANT R
MITCHELL VICTOR	MOFFETT BOBBY
MITCHELL VIDA	MOHAN DONA M
MITCHELL-SIMMONS MIA	MOHAN PETRO OK INC
MITCHEM ROBERT A	MOHAN PETRO WY INC

Current BLM Oil and Gas Lessees:

MOHEGAN INDIAN TRIBE	MONTEX EXPL CO
MOHICAN PETROLEUM INC	MONTGOMERY DON D
MOHRBACHER ROBERT J	MONTGOMERY EXPL CO
MOLK LEIZER	MONTGOMERY GEORGE H
MOMENTUM ENERGY CORP	MONTGOMERY JEAN
MOMENTUM OPERATING CO	MONTGOMERY PETROLEUM INC
MOMENTUM OPERATING CO INC	MONTGOMERY R F
MON OIL INC	MONTGOMERY WILLIAM
MONAGHAN ROBERT L	MONTGOMERY WILLIAM S JR
MONAHAN REX	MONTIN WILLIAM V
MONARCH GAS CORP	MONTIN-HARBERT
MONARCH OIL & GAS	MONTIN-HARBERT PIPELINE
MONARCH RES INC	MONTIN-HARBERT-BOLAC
MONARCH RESOURCE INC	MONTOUR PROP INC
MONCRIEF C B	MONTOUR PROPERTIES
MONCRIEF MICHAEL J	MONTY B MONCRIEF 1988 TRUST
MONCRIEF OIL & GAS MASTER LLC	MONTY BRENNAN MONCRIEF TRUST
MONCRIEF PARTNERS LP	MONUMENT GAS MARKETING INC
MONCRIEF R B	MOODY LTD PTNSHP
MONCRIEF RICHARD B	MOON & HINES
MONCRIEF RICHARD W	MOON BILL P
MONCRIEF W A	MOON GARY
MONCRIEF W A JR	MOON ROBERT M
MONCRIEF WILLIAM III	MOON ROYALTY LLC
MONDAY CREEK RESOURCES LTD	MOORE & SHELTON CO
MONITOR ENERGY PARTNERS LP	MOORE B J TRUST
MONO POWER CO	MOORE CHERYL A
MONROE BRUCE C	MOORE D ELIZABETH
MONROE GARY A	MOORE DAVID
MONSANTO OIL CO	MOORE ELIZABETH D
MONSON ROBERT M	MOORE ELLEN N B
MONT & WY OIL CO	MOORE ENERGY LLC
MONT ROUGE INC	MOORE FREDDIE W H
MONTANA & WY OIL CO	MOORE HIRAM J
MONTANA & WYOMING CO	MOORE HUGH A
MONTANA & WYOMING OIL CO	MOORE INVESTMENTS
MONTANA GAS INVESTMENTS LLC	MOORE J HIRAM
MONTANA LAND & EXPL INC	MOORE JAMES
MONTANA OIL PROPERTIES INC	MOORE JAMES S
MONTANA PETRO CO	MOORE JANE E
MONTANA RESOURCE	MOORE JOHN D
MANAGEMENT	MOORE JOHN P
MONTANA VAUGHEY FAM PTNSHP	MOORE KEITH R
LLP	MOORE LARRY
MONTANA-HEARTLAND LLC	MOORE LOYAL TRUST
MONTECITO OFFSHORE LLC	MOORE MADELEINE G

Current BLM Oil and Gas Lessees:

MOORE MARGARET F	MORGAN THOMAS H
MOORE MICHAEL H	MORGAN TRUST
MOORE R KEITH	MORGAN UNITED LLC
MOORE RICHARD L	MORIAH RESOURCES INC
MOORE STEPHEN S	MORITZ ENERGY CORP
MOORE SUSAN FLUDE	MORNING STAR EXPL
MOORE TERRY R	MORNING STAR OIL CO LLC
MOORE THOMAS E	MORNINGSTAR ENERGY INC
MOORE TOM E	MOROIL CO INC
MOORE TRUST	MORRILL PHILIP W
MOORE VIRGINIA L	MORRIS LESLIE R
MOORE WAYNE	MORRIS OIL & GAS CO INC
MOORES TERRY A	MORRIS WHEAT LLC
MOORHEAD SHERMAN EST	MORRIS WILLIAM J
MOOSE DIVIDE LAND INVSTRS LLC	MORRIS WILSON TRUST
MOOSE MOUNTAIN LAND CO A LLC	MORRISON CHARLES A
MOOSE OIL & GAS LLC	MORRISON EXPLORATION CO
MORAN JOHN E	MORRISON FOUNDATION
MORAN PTNRSHP	MORRISON MILTON L
MORDKA ENTERPRISES	MORRISON OILFIELD SERVICES INC
MORDKA M	MORRISON RICHARD
MORDKA MAURICE	MORRISON ROGER
MORELLI JOSEPH J	MORROW DAVID C
MORELLO PATRICK J	MORSE ACQ LLC
MORENERGY EXPL CO	MORSE ACQ PTNRS LTD
MOREXCO INC	MORSE CHARLES REV TS
MORGAN AGNES M	MORSE ENE PTNRS LLC
MORGAN BETTY	MORSE ENERGY PARTNERS II LLC
MORGAN CAPITAL GROUP	MORSE ENERGY PARTNERS LLC
MORGAN CAPITAL GRP	MORSE ENERGY PTNRS LLC
MORGAN CARL A	MORSE GEORGE
MORGAN CHARLES M	MORSE RICHARD A
MORGAN CHERYL L	MORSE WARREN
MORGAN CHUCK	MORTON BONNIE J
MORGAN ETHEL	MORTON DOUGLAS K
MORGAN EXPL LLC	MORTON GARY
MORGAN EXPLORATION LLC	MORTON H H
MORGAN FRANK	MORTON JULIE
MORGAN FRANK S	MORTON WARREN A
MORGAN KENT	MOSBACHER 1985C LTD
MORGAN LAURA K	MOSBACHER EMIL III
MORGAN MARATHON LLC	MOSBACHER ENERGY CO
MORGAN MARATHON LTD	MOSBACHER JOHN DAVID
MORGAN NANCY	MOSBACHER O&G INC
MORGAN OPERATING INC	MOSBACHER R BRUCE
MORGAN ROBIN	MOSBACHER ROBERT

Current BLM Oil and Gas Lessees:

MOSBACHER USA INC	MRL PARTNERS
MOSCETTI F E	MRT CO
MOSER EDNA L	MS BAPTIST FOUND
MOSER VICKY	MSC EXLPORATION LP
MOSER-RUNYAN	MT ESTN PPLN CO
MOSIER NANCY LEE	MT MARIAN ENTRPRS
MOSS MARY ANN	MT POSO COGENERATION
MOSS WILLIAM	MTA OIL INC
MOTE RESOURCES INC	MTD CORPORATION
MOTTO JUANITA I	MTN FUEL SUPPLY CO
MOTTO REV TRUST	MUCKEL DONALD L
MOTTO RUDY D	MUCKLEROY ENERGY CO
MOTYKA CHRISTY	MUDGY MINERAL EXPLORATION LLC
MOULTON EVERTS	MUDGE E W JR
MOULTON MARY ELLEN	MUEHLBRAD SCOTT E
MOUNGER WILLIAM B	MUELLER JERRY
MOUNGER WILLIAM D	MUELLER MELINDA
MOUNTAIN APPLE CO	MUELLER THOMAS C
MOUNTAIN ENERGY LLC	MUIRFIELD RESOURCES COMPANY
MOUNTAIN FUEL SUPPLY CO	MULBERRY PARTNERS II LP
MOUNTAIN HOME PETRO	MULBERRY PTNRS II LLP A NM LLP
MOUNTAIN MINERALS CORP	MULE WEST OIL LLC
MOUNTAIN O&G CO MT	MULL DRILLING CO INC
MOUNTAIN OG CO	MULL DRILLING COMPANY
MOUNTAIN OG CO OF MT	MULL LEWIS M
MOUNTAIN PAC GEN INC	MULL MARGARET A
MOUNTAIN PACIFIC GENERAL	MULLEN EXPLORATION
MOUNTAIN PETRO CORP	MULLEN LOUIS
MOUNTAIN STATE NATURAL GAS	MULLEN WILLIAM E
MOUNTAIN STATE PETROLEUM CO	MULLIGAN EXPLORATION LLC
MOUNTAIN STATES MGT	MULLINER PRINCE&MANGUM
MOUNTAIN STATES PETROLEUM CORP	PTNRSHP
MOUNTAIN WEST ENERGY LLC	MULLINGS DONALD K
MOUNTAINEER ENERGY	MULLINS & WHITE EXPLRN INC
MOURNE MARK J	MULTI-INVESTMENT CORP
MOURNE OIL & GAS	MUMPER-HEWLINGS TRST
MOUTRAY PROPERTIES INC	MUNCY B N JR
MOYER LARRY R	MUNICIPAL GAS AUTHORITY OF GA
MP SAN JUAN LP	MUNK HATTIE D
MPMC INC	MUNSON CHERRON
MPS INC DRILLING CO	MUNSON DAVID M JR
MR DRILLING CO	MUNSON E P JR
MR OIL CO	MURCHISON OIL & GAS INC
MRC PERMIAN CO	MURER CHISTIAN F
MRC ROCKIES COMPANY	MURER CHRISTIAN F
	MUREX PETRO CORP

Current BLM Oil and Gas Lessees:

MUREX PETROLEUM CORP	N D STOVALL & SON LTD ET AL
MURFIN DRILLING CO	N FAIR TRUST
MURFIN INC	N J GENIUSZ TRUST
MURJO OIL & ROYALTY	N P STRONG TRUSTEE
MURPHREE & MOORE	N ROUSSELOT & SONS
MURPHY 1987 IRREVOCABLE TRUST	N TIMBERS PTNRSHP
MURPHY DAVID L	NACOGDOCHES OIL & GAS INC
MURPHY MICHAEL W	NADALINI BETTY A TRUST
MURPHY MINERALS CORP	NADEL & GUSSMAN CAPITAN LLC
MURPHY OIL USA INC	NADEL & GUSSMAN ENERGY LLC
MURPHY OPERATING CORP	NADEL & GUSSMAN HEYCO LLC
MURPHY PETRO CORP	NADEL & GUSSMAN LLC
MURPHY SHELDON L	NADEL & GUSSMAN PERM
MURRAY JAMES H	NADEL & GUSSMAN PERMIAN LLC
MURREL JOHN H	NADEL & GUSSMAN ROCKIES LLC
MUSCHINSKE VICTORIA L	NADINE C BARRETT IRR TRST
MUSGRAVE ANNA E	NAE LLC
MUSGRAVE FAMILY LLL	NAFTEX SECTION 27 PARTNERS LP
MUSGRAVE FRANK L	NAHABEDIAN ARMEN
MUSKEGON DEV CO	NAHAMA NATURAL GAS
MUSKEGON DEVELOPMENT CO	NAIRN ROBERT
MUSLOW JAMES JR	NAJA ENERGY COMPANY LLC
MUSSETT DAVID R	NAKOTA ENERGY LLC
MUSSETT MARIAN	NALLY GRANT
MUSTANG DRLNG FLUIDS	NAMSON JAY S
MUSTANG FUEL CORP	NAMYAC ENE
MV PARTNERS LP	NANCE PETROLEUM CORP
MVC INC	NANCE RES INC
MW OIL INVST CO	NANCE ROBERT L
MWJ PRODUCTION CO	NANCO PARTNERSHIP
MWJR PETROLEUM CORP	NANCY G CHEEK TRUST
MXD LLC	NANCY M SANDEL TRUST
MYCO IND INC	NAOC PRODUCTION CO
MYCO INDUSTRIES INC	NAPOLITANO LARRY
MYDELL MILLER TRUST	NAPOLITANO TWYLLA
MYER CARL D	NARANJO ANGELA
MYER GOODSTEIN TRUST	NARANJO SHAWN
MYERS JACK M	NARENTA OIL CO
MYERS PARTNERS INC	NAREY HAZELLE
MYRON A SMITH ESTATE	NASH DIANE D
MYSTIC ENERGY LLC	NASH FRANCIS T
N & G ASSOCIATES	NASH SALLY
N & R RESOURCES INC	NASH WILLIAM A III
N B HUNT TRST EST	NAT GAS CORP OF UT
N B HUNT TRUST ESTATE	NATHAN OIL LLC
N B HUNT TRUST ESTATE-B	NATHAN SIM A JR EST OF

Current BLM Oil and Gas Lessees:

NATIONAL FUEL CORP	NEAL OIL INC
NATIONAL GRID PROD & DEV	NEAL W C
NATIONAL PETROLEUM ASSOC	NEARBURG CHARLES E
NATIONS BANK	NEARBURG EUGENE E
NATIONS PETROLEUM CALIFORNIA	NEARBURG EXL CO LLC
NATL COMPLETION 83A	NEARBURG EXPL CO LLC
NATL COMPLETION 83B	NEARBURG EXPLORATION CO LLC
NATL COOP REFINERY	NEARBURG GRETCHEN B
NATL FUEL CORP	NEARBURG MARK K
NATL PRIDE EXPL LC	NEARBURG PROD CO
NATL PRIDE OPER	NEARY BRIAN
NATSYN ENERGY CORP	NEBEL BILLIETTE M
NATURAL BUTTES GAS	NEEB H L
NATURAL GAS ANADARKO	NEECO INC
NATURAL GAS CO CORP	NEELEY CURTIS L
NATURAL GAS CORP	NEELEY L CURTIS TRST
NATURAL GAS DRLG	NEFF EDSEL B JR
NATURAL GAS PROC CO	NEG OPERATING LLC
NATURAL GAS PROCESSING CO	NEGAARD NORMAN H
NATURAL RES MGT CORP	NEHER MICHELLE
NATURES TREASURES	NEIL D SCHWED FAM TR
NAUMANN JACK H JR	NEIL M H
NAUMANN OG INC	NELDA C & H J LUTCHER STARK
NAUSHTON GERALD	NELLA PROPERTIES
NAUTILUS EXPLORATION LLC	NELSON ALBERT
NAUTILUS O&G CO	NELSON BETTY ANN
NAUTILUS OIL & GAS COMPANY LLC	NELSON BETTY JEAN
NAVAJO NATION OIL & GAS	NELSON BROKERAGE GROUP INC
NAVAJO NATION OIL & GAS CO INC	NELSON BUNKER HUNT
NAVE JOANNA C	NELSON CAPPIC
NAVIDAD RESOURCES LLC	NELSON CHARLES S
NAYLOR OPER CO	NELSON CLARENCE L
NB HUNT EST TRUST B	NELSON DONALD L
NB HUNT TRUST ESTATE	NELSON DOUGLAS D
NBB OG PTNRSHP	NELSON EARL W EST
NBH LIQ TRUST	NELSON ED
NBS CORP	NELSON GENEVIVE
NCI 1990 LTD	NELSON KENNETH C
NCI ENTERPRISES INC	NEMIDCO INC
NCNB TX NATL BK EST	NEMIRO BEVERLY A
NCNG EXPL CORP	NEMOURS CORPORATION
NDC OIL & GAS I LLC	NEOGA OIL CO INC
NDC OIL & GAS II LLC	NEON ENERGY CORPORATION
NDE HOLDINGS LLC	NERD GAS CO LLC
NEAL J W	NERD GAS COMPANY
NEAL KENNETH E	NERD GAS COMPANY LLC

Current BLM Oil and Gas Lessees:

NESBITT SAMUEL	NEWFIELD PRODUCTION COMPANY
NESRSTA LENA GRACE	NEWFIELD RMI LLC
NESTE OIL INC	NEWKUMET EXPL INC
NESTEGG ENERGY CORP	NEWLON ESTHER F
NETTLETON KEN	NEWLON W GIFFORD
NETZLY VERNON D	NEWMAN ANN M
NEUBIESER ROGER	NEWMONT MINING CORP
NEUHAUS EDWARD K	NEWPEK LLC
NEUHAUS LAURANCE B	NEWPORT MINERALS LTD
NEUHAUS V F	NEWPORT OIL CORP
NEUHAUS W O III	NEWTON OIL CO
NEUHOFF TAYLOR ROYALTY CO	NEXCO INC
NEUMANN FAMILY TRUST	NFC PETROLEUM CORP
NEUMILLER JOAN R	NFR BEAR PAW BASIN LLC
NEUMILLER MICHAEL J	NFR UNTA BASIN LLC
NEUMILLER WAYNE P	NFR WILLISTON BASIN LLC
NEUMIN OIL & GAS LLC	NG GAS PROP II INC
NEVADA EXPL CORP	NHM CO
NEVADA OIL VENTURES LLC	NI MODO ENERGY LLC
NEVILS DAVID L	NIBLO HAROLD EST
NEVITT MARY E	NICHOLAS CARTER R
NEW & HUGHES DRILL	NICHOLAS THOMAS S
NEW CENTURY EXPL INC	NICHOLS HAROLD M JR
NEW DAVID A	NICHOLS OIL CO
NEW ENGLAND ENE INC	NICHOLS THOMAS S
NEW ENGLAND ENERGY	NICKOLOFF THOMAS R
NEW ERA OIL & GAS CO	NICO RESOURCES LLC
NEW FRONTIER ENERGY	NICOL FAMILY TRUST DTD 8/24/92
NEW FRONTIER ENERGY INC	NICOLAYSEN JON C
NEW MEXICO EAGLE OIL CO LLC	NICOLAYSEN KATHRINE
NEW MEXICO OIL CORP	NICOLE H UNDERWOOD REV TRST
NEW MEXICO WESTERN MINERALS	NIEDERHOFFER GALT
NEW NM TEX OIL CO	NIEDERHOFFER INVST
NEWARD CORP	NIEDERHOFFER KATE
NEWBERN JOHN	NIEDERHOFFER ROY
NEWCAL ASSOC LTD	NIEDERHOFFER SUSAN C
NEWCOMB FRED	NIEDERHOFFER VICTOR
NEWELL CHARLES JR	NIELSEN ROGER B
NEWELL CHARLES O	NIELSON & ASSOC INC
NEWELL RETHA	NIELSON ENERGY GROUP LLC
NEWFIELD EXPL GULF COAST INC	NILSEN CARL A
NEWFIELD EXPL MID-CONTN INC	NINE IRON OG LTD
NEWFIELD EXPLORATION CO	NINIAN OIL CO
NEWFIELD MID-CONTINENT 2003	NISKU ROYALTY LP
NEWFIELD PROD CO	NISSLEY ELEANORE S
NEWFIELD PRODUCTION CO	NISSLEY WARREN W

Current BLM Oil and Gas Lessees:

NIWOT RES LLC	NORMAN D M
NIWOT RESOURCES LLC	NORMAN EXPL INC
NIX FRANCES	NORMAN L STEVENS JR REVOC TR
NJ NATURAL RES CO	NORMAN L STEVENS JR TR
NJRE OPERATING CO	NORMAN L STEVENS JR TRUST
NM & O OPERATING CO	NORMAN L STEVENS TR
NM & T RESOURCES LTD	NORMAN MARGARET M
NM BACK NINE EXPL PTNRS LLC	NORMAN ROBERT W
NM BAPTIST FOUNDATION	NORMIL JEFFRY
NM CO INC	NORRIS BYRON M
NM GAS INVESTMENTS	NORSE EXPL INC
NM OIL CORP	NORSWORTHY JASE O
NM OIL INC	NORTEX CORP
NM VENTURES	NORTEX GAS CORP
NMR INC	NOR-TEX GAS CORP
NMT OIL CO INC	NORTH AMER EXPLORER INC
NNG	NORTH AMERICAN EXPLORATION LLC
NOAH MIKE	NORTH AMERICAN PETRO CORP USA
NOARKO RESOURCES INC	NORTH AMERICAN RESERVE CORP
NOBLE A PARKER ESTATE OF	NORTH ARM RES INC
NOBLE ENE INC	NORTH CANADIAN RES
NOBLE ENE WYCO LLC	NORTH CENTRAL OIL
NOBLE ENERGY	NORTH CENTRAL OIL CORP
NOBLE ENERGY INC	NORTH CENTRAL OPER
NOBLE ENERGY PRODUCTION INC	NORTH COAST ENERGY EASTERN INC
NOBLE ENERGY WYCO LLC	NORTH COAST ENERGY INC
NOBLE GORDON E	NORTH CTL OIL CORP
NOBLE PETROLEUM COMPANY	NORTH FINN LLC
NOBLE-DUBOISE VIVIAN	NORTH PLAINS ENE LLC
NOE WESLEY K	NORTH RANCH ENERGY LLC
NOEL NALLY TRUSTEE	NORTH STAR PETRO INC
NOICE KAREN JOHNSON	NORTHCUTT B H
NOLAN LLC	NORTHEAST ENERGY MANAGEMENT IN
NOLL DAURINE	NORTHEASTERN OP CO
NOMAD HYDROCARBONS LLC	NORTHERN ENE CORP
NOONAN LAND SERVICES INC	NORTHERN ENERGY COMPANY
NOR JOANNE H	NORTHERN MI EXPL CO
NOR TEX GAS CORP	NORTHERN NAT GAS CO
NORAM PETROLEUM CORP	NORTHERN OG INC
NORBECK JANE M TRUST	NORTHERN PROD CO INC
NORCEN EXPLORER INC	NORTHERN SCOT D
NORDQUIST DON	NORTHLAND PROPERTIES LLC
NORDSTRAND CARL H	NORTHLAND RESOURCES CO
NORDSTRAND ENG INC	NORTHRANCH ENERGY LLC
NORDSTRAND ENGINEERING INC	
NOREX INC	

Current BLM Oil and Gas Lessees:

NORTH-SOUTH HOLDING CORP	NUCOR OIL & GAS INC
NORTHSTAR GAS CO	NUCORP ENERGY INC
NORTHSTAR GAS CO INC	NU-ENERGY OG INC
NORTHSTAR OG CORP	NUEVO ENERGY CO
NORTHSTAR OPERATING CO	NUEVO SEIS INC
NORTHSTAR RES	NUEVO SEIS LIMITED PTNRSHP
NORTHSTAR RESOURCES	NUGENT WILLIE B
NORTHWEST EXPL CO	NUGGET AVIATION INC
NORTHWEST EXPL CORP	NULOCHE AMERICA CORP
NORTHWEST PETRO CORP	NUNNELLEY MARION
NORTHWEST PPLN CORP	NUPETCO ASSOCIATES
NORTHWESTERN CORP	NUROC ENERGY INC
NORTHWESTERN LIFE INC	NW LOST HILLS PETRO HOLDINGS
NORTHWOOD ENERGY CORP.	NWR ENTERPRISES INC
NORTON CLAPP	NWTN MUTL LIFE
NORTON HOWARD S	NWTN MUTL LIFE INSUR
NORTON MICHAEL J	NWTN MUTUAL LIFE INS CO
NORTON MICHAEL J III	NX LLC
NORTON RONDA L	NY LIFE OG III C
NORTON SHERMAN H	NY LIFE OG III D
NORTON SHERMAN H JR	NY LIFE OG OPER PROD
NORTON T W	NY LIFE OG PROD 2-B
NORVELL SAM H JR	NY LIFE OG PROD 2-C
NORVELL-MARCUM CO	NY LIFE OG PROD 2-E
NORWOOD E EARL	NY LIFE OG PROD 2-F
NORWOOD EARL E	NY LIFE OG PROD 2-G
NORWOOD LAND SERVICE LLC	NY LIFE OG PROD 3-B
NORWOOD OIL CO	NYBO LOUIS A
NOSECO CORP	NYE POMPANO LLC
NOVA ENERGY CORP	NYE SEA FORD LLC
NOVA ENERGY INC	NYE SEA FORD LTD CO
NOVA LEASING LLC	O H B INC
NOVA NATURAL RES	O I L ENERGY CORP
NOVEMBER FIRST CO	O I L NIAGARAN LLC
NOVUS OPERATING LLC	O L BURNETT ESTATE
NOWITZKI OIL & GAS LP	OAG HOLDINGS LLC
NPC PROPERTIES LLC	OAK HILL ENERGY INC
NQUYEN A VAN	OAKASON JOHN ESTATE
NRC DEVELOPMENT LLC	OAKMONT CORP
NRM 84-D INCOME LTD	OAKRIDGE ENERGY INC
NRM OPER CO LP	OASIS PETRO LLC
NRM OPERATING CO	OASIS PETRO N AMERICA LLC
NRN OIL PROD INC	OATMAN CAROLYN CLARK
NS GAS PROP II INC	OBAL DOROTHY L
NTL PRIDE EXPL	O'BANNON JOYCE
NUCLEAR CORP OF NM	OBERG RUTH STILES

Current BLM Oil and Gas Lessees:

OBERMUELLER CRAIG	OGLE CORP
OBO INC	OGLE ROBERT E
OBOURN JEFF T	OGM PTNRSHP II
OBOURN JOHN L JR	OPG INC
OBRIEN DUNCAN M	OPG LLC
O'BRIEN ENE CO	OGX ACREAGE FUND LP
OBRIEN ENERGY CO	OGX PRODUCTION LTD
OBRIEN ENERGY RES CORP	OGX RESOURCES INC
O'BRIEN ENERGY RES CORP	OGX RESOURCES LLC
O'BRIEN ENRGY RESOURCES CORP	OHB INC
O'BRIEN GEORGE H	OHERI, EMMANUEL
O'BRIEN JAMES F	OHIO L & M CO INC
O'BRIEN JEROME J	OHIO OIL CO
O'BRIEN PAUL F JR	OHIO VALLEY ENERGY SYS O&G COR
O'BRIEN VIRGINIA B	OHMART WALTER A
O'BRIEN-GOINS	OIEN EMILY H EST
OBY GAS LLC	OIL & GAS INVESTMENTS
OCCIDENTAL ELK HILLS	OIL & GAS TITLE HOLD
OCCIDENTAL ELK HILLS INC	OIL & REALTY DEV INC
OCCIDENTAL PERMIAN LP	OIL CAPITAL 1985-A
OCCIDENTAL PERMIAN LTD PTNRSHP	OIL DEV CO OF UTAH
OCEAN ENERGY INC	OIL NIAGARAN LLC
OCEAN PERMIAN LLC	OIL PARTNERS
O'CONNELL HOLDING LLC	OIL PRODUCERS INC OF KANSAS
OCONNELL HOLDINGS LLC	OIL PROPERTIES HOLDING II LLC
O'CONNELL HOLDINGS LLC	OIL RES INC
O'CONNELL PARTNERS LP	OIL RITE CO
O'CONNELL R K	OIL SEARCH LEASING
O'CONNELL RICHARD E	OIL SHALE CORP
O'CONNOR EDMOND	OIL TECH FUND
O'CONNOR OG LTD	OILFIELD SALVAGE & SERVICE CO
ODEGARD RESOURCES	OK HOT OIL CO
O'DELL DEBRA A	OK NATURAL GAS CO
ODELL WILLIAM G	OK SWABBING INC
ODONNELL MARY P	OKERMAN MICHAEL B
ODYSSEY EXPL INC	OKIE CRUDE COMPANY
ODYSSEY PETRO CO	OKIE OPER CO LTD
OEDEKOVEN WATER & HOT OIL INC	OKLAHOMA & NORTHWESTERN
OFFSHORE SHELF LLC	OKLAHOMA IND ENE
OFFUTT TRACI L	OKLAHOMA SILURIAN
OFS 1981 YR UNTAH	OKLAND OIL CO
OFT EXPLORATION INC	OKMAR OIL CO
OGA 1994-1 LTD	OLAN LLC
OGA G P	OLD FORT OIL CORP
OGDEN JERRY P	OLD PINE ENE CORP
OGLE BURDETTE A	OLD WEST TOURS

Current BLM Oil and Gas Lessees:

OLEARY CATHERINE M	O'NEILL JOSEPH I JR
OLEUM INCORPORATED	ONEILL PROP LTD
OLHEISER LEONARD J	O'NEILL PROP LTD
OLIN CORPORATION	O'NEILL PROPERTIES LTD
OLIN PRATHER TRUST	ONEUNDER LLC
OLIVER DANNY	ONEY SANDRA
OLIVER JOHN E JR	ONEY TROY
OLIVER VIRGIL H	ONSHORE HOLDINGS LLC
OLIVIA LANEY FALL TRUST	OOPS INC
OLLIE L BURNETT TRUST	OPAL INVESTMENT LTD PTNR
OLMSTEAD JACQUELINE	OPPERMANN L E
O'LOUGHLIN PATRICIA	ORACLE GAS LLC
OLSEN CURTIS E	ORBIT ENERGY INC
OLSEN SHARON A TRUST	ORBIT ENTERPRISES
OLSON GORDON	ORBIT RESOURCE CORP
OLSON HELEN	ORCHARD PETROLEUM INC
OLSON HELEN P FAMILY TRST	ORECAT 1994 LTD PRTN
OLSON MAURICE C	ORECAT 1997 LP
OLSON R	ORION 84 PRIVATE ENE
OLTMANS JAMES R II	ORION ACQUISITION IN
OLTMANS JAMES R III	ORION ENERGY CORP
OLTMANS SALLY JANE	ORION ENERGY INVESTMENT INC
OLWICK CORP	ORION ENERGY PARTNERS LP
OLYMPIC OG CORP	ORION ETA DRILLING
OLYMPUS OIL VENTURES	ORION INVESTMENTS LLC
OMAR BOU-MATAR TRUST	ORION OG PROPERTIES
OMAR MILLIGAN ENTRP	ORION OG PROPERTIES TX
OMELVENY PATRICK	ORION PRODUCTION LLC
OMIMEX CANADA LTD	ORION PROPERTIES INC
OMIMEX ENERGY INC	ORION RESOURCES INC
OMIMEX INTL CORP	ORION SMITH OIL PROP
OMIMEX PETRO INC	ORION THETA DRILLING
OMIMEX PETROLEUM INC	ORO PETRO DRLG INC
OMOHUNDRO BETTY N	OROCO LLC
ONE BAR ELEVEN TRUST	ORR ED
ONE OIL CO	ORR EXPL LTD
ONE TEC OPERATING LLC	ORR EXPLORATION LTD
ONE WALTON PLACE LLC	ORR HOLDINGS LTD
ONEAL RESOURCES CORP	ORR PROD CORP
O'NEIL CATHERINE EST	ORSER JAMES B
O'NEIL JAMES J	ORTEGA JOSE R
O'NEIL JOSEPH I JR	ORTON EILEEN G
O'NEIL VIOLA D	ORYAN PROD & EXPL LTD
O'NEILL DAN	ORYX ENERGY CO
O'NEILL J FOUNDATION	OSAGE PETROLEUM LLC
O'NEILL JOSEPH I JR	OSBOME MELBA M

Current BLM Oil and Gas Lessees:

OSBORN BARRETT PETRO	OWENS RICHARD
OSBORN CALVIN W	OXBOW PROPERTIES INC
OSBORN HEIRS CO	OXFORD OIL CO
OSBORN HEIRS CO (NOMINEE)	OXFORD OIL COMPANY THE
OSBORN HEIRS COMPANY	OXLEY CAROL ANNE
OSBORN HEIRS COMPANY LTD	OXLEY JOHN C
OSBORN OIL & GAS OPE	OXTEC INC
OSBORN RUBEN L	OXY USA INC
OSBORNE KENNETH	OXY USA INC DEL
OSBORNE MINERALS LLC	OXY USA WTP LP
OSBORNE SANDRA E	OXY Y 1 COMPANY
OSBORNE SONJA	OXY Y-1 CO
OSCURA RESOURCES INC	OXY Y-1 COMPANY
OSE MONTANA CORP	OYGER A E TRUST
O'SHAUGHNESSY DANIEL J	OZARK ENERGY INC
OSO O&G PROPERTIES LLC	OZARK EXPLORATION INC
OSTAS TED	OZARK EXPLORATION LLC
OSTERMILLER RONALD	P & D ENERGY LLC
OSTLUND MARY V	P & M PETRO MGMT LLC
OSTMANN ARTHUR A	P D VALENTINE OIL & GAS CO
OSTRANDER CONST CO	P D BOSWELL TRUST
OTEX RESOURCES LLC	P D M INC
OTTAWA ENE INC	P H GREER CO INC
OTTAWA ENERGY INC	P I ENTERPRISES
OTTER CREEK LLC	P J GUY FAMILY TRUST
OUR PLUM LLC	P L ACKERMAN TRST
OURADA AUSTIN	P MCCUTCHEON TRUST
OUTLAND KAREN	P O & G RES - TEXAS LLC
OVATION ENE LP	P P SCHIEFFER TRUST
OVER THE HILL LAND SVCS LLC	P SIMPSON TRUST
OVER THE HILL LND SERVICES LLC	P SISK ESTATE
OVERBECK MARGARET	P&M PETRO MGT
OVERFELT LEE	P&P ENERGY LLC
OVERLAND RESOURCES LTD	P&P PRODUCING INC
OVERTHRUST OIL ROYAL	PA PROSPECT LLC
OVERTHRUST RESOURCES	PABLO ENERGY II LLC
OVERTON DIANE C	PABLO ENERGY INC
OVERTON KAREN N	PABO OIL & GAS
OWEN JOHN GREG	PAC ENTERPRISES
OWEN LAURA P	PAC ENTPR OIL CO USA
OWEN MARK T	PAC ENTPRS RLTY CO
OWEN STEVE D	PAC PROD CO
OWEN WILLIAM B	PACE DAVID H
OWEN WILLIAM W	PACE DIVERSIFIED CORP
OWENS KENNETH R	PACER ENERGY ACQUISITIONS LLC
OWENS PETROLEUM INC	PACIFIC ENERGY & MINING CO

Current BLM Oil and Gas Lessees:

PACIFIC ENTERPRISES	PALM THOMAS A
PACIFIC ENTERPRISES ABC CORP	PALM WILLIAM F
PACIFIC ENTPR OIL CO	PALMER GARY W
PACIFIC ENTPR RLTY	PALMER LAURA B
PACIFIC ENTPRS (USA)	PALMER MITCH
PACIFIC ENTPRS OIL A	PALMER PETRO LLC
PACIFIC ENTRPRISES OIL CO USA	PALMER PETROLEUM LLC
PACIFIC HOLDING CO	PALMER WESLEY
PACIFIC INTL PROD CO	PALMER WILLIAM V
PACIFIC UNION CORP	PALO PETROLEUM
PADCO LLC	PALO PRODUCTION CORP
PADFIELD NEVILLE	PALOMA BLANCA WELL SERVICE INC
PADGETT P DAVID	PALOMA PARTNERS II LLC
PADON DAVID A	PALOMA PETRO INC
PADON J A	PALOMA RESOURCE INC
PADON J A JR	PALOMINO INVESTMENTS LLC
PAGE EXPLORATION	PALOMINO PROD CO
PAGE F M	PALONE BILLY JIM
PAGE J H	PAMCO INVESTMENTS CORP
PAGE ROBERT A	PAMELA C HARRIMAN TRUST
PAGEDAS ANTHONY C	PAN AMER PETRO CORP
PAGEDAS FRANCES S	PAN AMERICAN PETRO
PAGETT JAMES R	PAN ENERGY FIELD SVC
PAGETT LARRY M	PAN ENTPR INC
PAGLEE ROBERT M	PAN OKLAHOMA CORP
PAGUYO ELLA KEAUOLIONALANI	PANADA EXPLORATION
PAINE JOSEPH J C	PANADA PIPE & EQMT
PAINE JOSEPH JC	PANAN ENERGY INC
PAINE WEBBER GEO I D	PANENERGY FILD SERV
PAINT CREEK INC	PANGEA CORP
PALACE ECPL CO	PANHANDLE ESTN PPLN
PALACE EXPL CO	PANNELL FRANK
PALACE EXPLORATION CO	PANNELL JAMES M
PALADIN ENERGY CORP	PANNELL RITA
PALADIN ENERGY PARTNERS LLC	PANNONIAN ENERGY INC
PALADIN INC	PANORAMIC ENERGY INC
PALADIN INC AN ARIZONA CORP	PANSAM TRUST
PALADIN INC AN AZ CORP	PANTERA ENERGY CO
PALEOZOIC PETRO LLC	PANTHER CRK RES LLC
PALERMO JANET W	PANTHER ENERGY CO LLC
PALISADES ASSET HOLDING CO	PANTHER VENTURES INC
PALM CARLIE A	PAPER TIME INC
PALM HERMAN B	PAPULAK KAY
PALM LAURA M	PAR FIVE EXPLORATION LLC
PALM MARY A	PAR III INC
PALM PHILIP R	PAR MINERALS CORP

Current BLM Oil and Gas Lessees:

PAR OIL CO	PARKER MARY E
PAR OIL CO INC	PARKER OIL & GAS CO
PARADEE W CHARLES JR	PARKER RUSSELL
PARADIS INVESTOR	PARKER WILLIAM A
PARADISE ENTERPRISES INC	PARKES FRANK
PARADISE ROBERT E	PARKIN VEDA N
PARAGON AVIATION CORP	PARKMAN HOWARD
PARAGON ENERGY CORP	PARKO INC
PARAGON ENERGY INC	PARKS & LUTTRELL INC
PARAGON OG LLC	PARKS & PARKS
PARALLEL PETROLEUM LLC	PARKS INA M
PARAMAX ENERGY INC	PARKS JAMES C
PARAMORE EDWIN L	PARKS KEVIN R
PARAMOUNT PETRO CORP	PARKS SUE E
PARAWON OPERATING LLC	PARRISH CO
PARCELL CHARLES L	PARRISH GRACE M
PARK HILL RESOURCES LLC	PARROT HEAD PROPERTIES LLC
PARK JEAN L TRST	PARRY HUGH W
PARKE RANDEE LAYNE	PARSELL R W
PARKER & PARKER OG	PARSLEY JOE M
PARKER & PARSLEY DEV	PARSON OIL LLC
PARKER ALICIA M	PARSONS DON
PARKER CAMILLA B	PARSONS DONALD G
PARKER DAVID	PARSONS DONALD G TRUST
PARKER EMILY S	PARSONS KYLE CRAIG
PARKER ENE CO	PARSONS WALDO
PARKER ENERGY TECH	PARTIN PETROLEUM INC
PARKER ERVIE T	PARTNERS LONGHORN
PARKER GEORGE JR	PARTNERSHIP MANAGEMENT INC
PARKER GEORGE LEWIS	PARTNERSHIP PROP CO
PARKER HARRY J	PASEO RESOURCES LLC
PARKER HOWARD W	PASMAS ART
PARKER JAMES A	PASTERNAK IRVING
PARKER JAMES M	PATARA OIL & GAS LLC
PARKER JANE ELLEN	PATARA OIL AND GAS LLC
PARKER JANE S	PATCO LTD
PARKER JIMMIE R JR	PATE JOE B JR
PARKER JOHN M	PATE RALPH
PARKER JOSEPH B	PATE TERRY
PARKER JOSEPHINE SELZE	PATHFINDER ENE INC
PARKER KATHRYN B TST	PATHFINDER ENERGY
PARKER MARGARITE	PATHFINDER ENERGY INC
PARKER MARGARITE B	PATHFINDER EXPL CO
PARKER MARK S	PATHFINDER EXPL INC
PARKER MARY ALMA	PATHFINDER EXPLORATION CO
PARKER MARY CHITTIM	PATIN MICHAEL J

Current BLM Oil and Gas Lessees:

PATIN OG CO INC	PAYNE THOMAS W
PATINA OK CORP	PAYNE WILLIAM F
PATMOS ENERGY LLC	PBI GAS RESOURCES
PATRICIA DEAN BOSWELL TRUSTEE	PBR PROP JOINT VENT
PATRICIA FENDER TRST	PBR PROP JOINT VENTURE
PATRICIA HARRINGTON TRUST	PBS ENERGY PROD INC
PATRICK CLAIRE J	PC EXPLORATION INC
PATRIOT ENERGY RESOURCES LLC	PC LTD
PATRIOT LAND LLC	PCEC 1984-A LTD
PATRIOT RESOURCES LLC	PCEC 1984-B LTD
PATTERSON AMY S	PCEC 1985-B LTD
PATTERSON ANTHONY R	PDI INC
PATTERSON LEO JR	P-E PARTNERSHIP
PATTERSON PETROLEUM INC	PEABODY WILLIAM W
PATTERSON PETROLEUM LLC	PEAGLER JULIAN JR
PATTERSON PETROLEUM LP	PEAK 9 PRODUCTION CO
PATTERSON RICKY	PEAK ENERGY CO
PATTILLO VICKI	PEAK ENERGY OPERATING LLC
PATTON BELLE	PEAK ENTPR CORP
PATTON DEANNE J	PEAK OIL TOOL
PAUL A THOMAS TRUST	PEAK PRODUCTION CO
PAUL ABBEY CONSULTING INC	PEAK PRODUCTION CORP
PAUL MESSINGER & CO	PEAK ROYALTY
PAUL S HERNE TRUST	PEAK ROYALTY HOLDINGS LLC
PAUL SERGENT ESTATE	PEAKE MERWIN W
PAUL&LYNN SAWYER REV LVNG	PEANUT OIL CO
TRST	PEAR RESOURCES
PAULINGON LORRAINE	PEARCE LEONARD D
PAULLUS REX JR	PEARCY DAVID B
PAULOS CLAY	PEARL MT EXPL & PROD LTD
PAULOS VICTOR E	PEARL PETRO INC
PAULSON ROY E	PEARLSTONE ENE PTNRS LLC
PAULSON ROY E JR	PEARLSTONE ENERGY PARTNERS
PAULSON WALTER A	LLC
PAUPERS DREAM COMPANY	PEARLSTONE ENERGY PRTNR LLC
PAW PRINTS OIL & GAS	PEARLSTONE ENGRY PRTNR LLC
PAXTON RESOURCES LLC	PEARSON DARLENE
PAYNE FRANCES	PEARSON SIBERT OIL
PAYNE JAMES R	PEASE OIL & GAS CO
PAYNE JEAN	PEASE OIL PTNRSHP
PAYNE JIM G	PEASE WILLIAM L
PAYNE JOHN W III	PEBBLE OIL CO LLC
PAYNE L K	PECK BARBARA A
PAYNE MARY T	PECK BARBARA ANDRAU
PAYNE OIL&GAS J SMITHBERGER	PECK POWELL BARBARA A
PAYNE ROBERT G	PECO RESOURCES INC

Current BLM Oil and Gas Lessees:

PECOS AIR INC	PENN VIRGINIA OIL & GAS CO
PECOS BEND ROYALTIES INC	PENN VIRGINIA OIL & GAS LP
PECOS ENERGY PARTNERS LP	PENNACO ENERGY INC
PECOS RIVER OPER INC	PENNANT PETRO INC
PECOS SLOPE PARTNERS LP	PENNECO OIL COMPANY INC
PECOS VALLEY TOOLS INC	PENNELL JACK
PEDCO 87 ENERGY DEV	PENNIES FROM HEAVEN LLC
PEDCO RES CO	PENNINGTON WAYNE
PEDCO RESOURCES CO	PENNOCK C A ESTATE
PEDEN ANN	PENNOCK MAUDE
PEDERSEN OIL & GAS INC LLC	PENNSYLVANIA CASTLE ENE CORP
PEDLEY T A JR	PENNSYLVANIA CASTLE ENRGY CORP
PEDLEY TIMOTHY A	PENNSYLVANIA GENERAL ENERGY CO
PEDRY JOHN J	PENNZENERGY CO
PEEGEE GAS LLC	PENNZENERGY EXP & PRO LLC
PEEL HERBERT L	PENNZENERGY EXPL & PROD LLC
PEEL WENDELL C	PENNZOIL CO
PEERY DAVID R	PENNZOIL EXPL&PROD
PEGASUS ENERGY CORP	PENNZOIL PROD CO
PEGASUS HOLDING CORP	PENNZOIL PRODUCTS CO
PEGASUS INC	PENROC OIL CORP
PEGASUS PETRO CORP	PENROD JOHN M
PEGGY A YATES ESTATE	PENROSE NEVILLE G
PEGGY A YATES TRST	PENROSE PATRICIA
PEGGY E YATES Q TRUST	PENTA PETROLEUM CO
PEKAREK ALFRED	PENTA POOL TRUST
PEL-TEX OIL COMPANY LLC	PENWELL DAVID J
PENA BLANCA CORP	PENWELL ENERGY INC
PENDRAGON ENERGY PARTNERS INC	PENWELL GEORGE S
PENDRAGON ENERGY PTNRS INC	PENWELL INGER
PENDRAGON RES II LP	PENWELL PROP LLC
PENDRAGON RES LP	PENWELL PROPERTIES
PENDRAGON RESOURCES	PENWELL PROPERTIES LLC
PENDRAGON RESOURCES II LP	PENWRIGHT JOAN
PENDRAGON RESOURCES LP	PEOPLES DAN
PENERGY	PEOPLES ENERGY PROD-TEXAS LP
PENHOUSE INC	PEOPLES ENERGY PRODTX LP
PENINSULA OA INC	PEPCO INC
PENINSULA OWNERS ASSOC INC	PEPPER DAVID E
PENKO ALICE M	PEPPER MORTON M
PENN BRISTOL CORP	PEREGRINE PRODUCTION LLC
PENN VA O&G CORP	PERENCO INC
PENN VA RES CORP	PERGAMOS LP
PENN VIRGINIA MC ENERGY LLC	PERGANDE F HUDSON
PENN VIRGINIA OG CORP	
PENN VIRGINIA OG LP	

Current BLM Oil and Gas Lessees:

PERKINS TERENCE P	PETERSON ROBERT W
PERLMAN WILLIAM	PETERSON SCOT CARL
PERMIAN BASIN INV CO	PETERSON TAMRA T
PERMIAN BASIN JOINT VENTURE	PETERSON VIRGIL V
PERMIAN DEVELOPMENT CORP	PETRA ENERGY INC
PERMIAN EXPL CORP	PETRA ENERGY MILLERSVIEW LLC
PERMIAN HUNTER CORP	PETRA OLEUM CORP
PERMIAN RESOURCE INC	PETRA PARTNERS LLC
PERMIAN RESOURCES HOLDINGS INC	PETRA PETRO INC
PERMITS WEST INC	PETRAITIS OG INC
PERMOK OIL INC	PETRAL EXPL LLC
PERRIN DOWNING A	PETRO ACQUISITIONS
PERRY & PERRY INC	PETRO ACQUISITIONS LLLP
PERRY DRILLING 1982	PETRO ATLAS CORP
PERRY HARRY R	PETRO CANADA RES (USA) INC
PERRY HELEN M	PETRO CONSULT ENERGY
PERRY NANCY B	PETRO CORP OF AMER
PERRY R BASS INC	PETRO CORP OF NV
PERRY RICHARD O	PETRO EAGLE L C
PERRY WESLEY W	PETRO EAGLE LC
PERSON CLAUDE	PETRO ENE INC
PESCA UNLIMITED CORP	PETRO ENERGY INC
PETCO LTD	PETRO EQUITIES INC
PETE SCHERER OIL & GAS LP	PETRO FUEGO LLC
PETER NEUMANN TRUST	PETRO GRANDE INC
PETER PAUL PETRO	PETRO HUNT LLC
PETER PAUL PETRO CO	PETRO INVST SVC INC
PETERS CORP	PETRO LEWIS FUNDS
PETERSON BENJAMIN L	PETRO LEWIS INC ETAL
PETERSON C M ESTATE	PETRO LND PTNRSHP II
PETERSON DAVID D	PETRO MEX LLC
PETERSON DONALD S	PETRO PARTNERS INC
PETERSON EDWINA	PETRO RESOURCES CORP
PETERSON ENERGY MGMT	PETRO RESOURCES INC
PETERSON F G	PETRO SEARCH INC
PETERSON F JEFFREY	PETRO SHORE LLC
PETERSON GERALDINE S	PETRO STATEGIES INC
PETERSON JAMES H	PETRO SYNERGY
PETERSON JOSEPH L	PETRO SYNERGY GROUP INC
PETERSON L J	PETRO TECHNICAL SERVICES
PETERSON LESLIE ANN	PETRO UNO RES LTD-ND
PETERSON MARGARETE J	PETRO YATES INC
PETERSON MARK L	PETRO-AMERICA LLC
PETERSON OSCAR A	PETRO-CANADA RES (USA) INC
PETERSON RICHARD A	PETROCARBON ENE TRST
PETERSON RICHARD L	PETROCARBONS LTD

Current BLM Oil and Gas Lessees:

PETRO-CHEM OPERATING CO INC	PETROMINERALS CORP
PETROCO INC	PETROMONT RES LLC
PETROCON AMER CORP	PETRO-PRO LLC
PETROCOPR INC LAND DEPT	PETROQUEST EXPL INC
PETRO-ENE EXPL INC	PETROREP INC
PETROFINA DELAWARE	PETRO-RES SVC INC
PETROFINA DELAWARE INC	PETROROCK, LLC
PETROGLYPH ENERGY INC	PETROROYALTIES LLC
PETRO-GUARD CO INC	PETROSAKH USA
PETROGULF CORP	PETRO-SENTINEL LLC
PETROGULF II LTD	PETROSPEC CORP
PETROHAWK ENERGY CORP	PETROSTAR LLC
PETROHAWK OPER CO	PETROSTATES RESOURCES INC
PETROHAWK OPERATING COMPANY	PETROSUN OILS INC
PETROHAWK PROPERTIES A TX LP	PETROTECH ENERGY 76-2
PETROHAWK PROPERTIES LP	PETROTECH INC
PETRO-HUNT CORP	PETROUTSON PETER C
PETRO-HUNT LLC	PETROVAUGHN INC
PETRO-HUNT, LLC	PETROVEN INC
PETROHUNTER OPER CO	PETROX CONSULTING
PETROJARL INC	PETRO-X CORP
PETROL FUEGO LLC	PETROX INC
PETROL INDUSTRIES INC	PETROX RES INC
PETROLERO CORP	PETROX RESOURCES INC
PETROLERO INV FUND	PETROYATES INC
PETROLEUM ACQUISITIONS LLLP	PETRUS MGT
PETROLEUM ACQUISITIONS LLP	PETRUST CORP OF AMERICA
PETROLEUM CORP	PETTIT WILLIAM O
PETROLEUM DEV CO	PETTY & HOLMES PTNRS
PETROLEUM DEV CORP	PETTY SCOTT JR
PETROLEUM DEVELOPMENT CORP	PETTYJOHN DON J
PETROLEUM ENERGY DRLG	PEVEHOUSE INC
PETROLEUM INC	PEVERLEY GEO C III
PETROLEUM INTL INC	PEVERLEY GEORGE III
PETROLEUM INVESTMENT LLC	PEYTON W YATES DAVIS 1976 TRST
PETROLEUM PARTNERS	PFANENSTIEL COMPANY LLC THE
PETROLEUM PROD MGT	PFISTER ARTHUR O
PETROLEUM QUEST EXPL	PFUHLMAN A ESTATE
PETROLEUM RESOURCES	PG & E RESOURCE CO
PETROLEUM SYNERGY	PGC LLC
PETROLEUM SYNERGY GROUP INC	PGP GAS SUPPLY POOL #1 LLC
PETROLEUM TECH SER	PGP GAS SUPPLY POOL #2 LLC
PETROLEUM WTN ENE	PHANTOM INVESTMENTS
PETROLEUM YATES INC	PHANTOM INVESTMENTS INC
PETROLEX USA INC	PHARIS JACK L
PETROLUX INC	PHARIS JAMES J

Current BLM Oil and Gas Lessees:

PHARISS NANCY A	PIERCE DOUGLAS L
PHEIFFER JOE	PIERCE EUGENIA L
PHELPS JOSEPH	PIERCE JIM
PHELPS K L	PIERCE MICHAEL L
PHELPS KERRY L	PIERCE-SMALLING ALMA
PHIL T SHARPLES TR	PIERSALL MARIETTA J
PHIL THOMPSON EST	PIERSON REGINALD J
PHILBRICK BRETT	PIETENPOL DAVID
PHILBRICK RENEE	PIETENPOL MARLEA J
PHILIP L YECKEL EST	PIETTE CARL R
PHILIP T SHARPLES TRUST	PIETTE WAYNE A
PHILLIPS 66 NAT GAS	PIGFORD SHERRY
PHILLIPS ALEX E	PIKE JANET BAYSINGER
PHILLIPS ANNE P TRUST	PIKE PETRO CORP
PHILLIPS CHRISTOPHER	PILGRIM PTNRSHP
PHILLIPS FRUITLAND	PILLAR ENE LLC
PHILLIPS HOWARD	PILOT ENE 1985 LTD
PHILLIPS JOHN D	PILOT KNOLL MINERALS LTD
PHILLIPS M M	PIN OAK PETRO INC
PHILLIPS MARION B	PINE CLYDE A
PHILLIPS MARK I	PINE MOUNTAIN OIL & GAS INC
PHILLIPS NM PTNRS	PINE RIDGE O&G LLC
PHILLIPS PETRO CO	PINEY FORK PRODN CO
PHILLIPS PETROLEUM	PINEY FORK PRODUCTION CO
PHILLIPS RUTH J	PINGO OIL & GAS IP
PHILLIPS-SAN JUAN	PINGO OIL & GAS LP
PHILLIS KATHRYN L	PINKERTON BRUCE
PHILPY ERVIN C	PINNACLE ENE GROUP
PHIPPS TOMMY	PINNACLE ENE GROUP LLC
PHOENIX ENE INC	PINNACLE GAS RES INC
PHOENIX ENERGY LLC	PINNACLE GAS RESOURCES INC
PHOENIX HYDROCARBONS	PINNACLE LEASING LLC
PHOENIX HYDROCARBONS OPER	PINNACLE OPERATING CO
CORP	PINNACLE OPERATING CO INC
PHOENIX OIL AND GAS LLC	PINNACLE PETRO CORP
PHOENIX OIL RES LLC	PINNACLE PROD PROP
PHOENIX PETROCORP INC	PINNACLE RESOURCE CORP
PHOENIX PRODUCTION COMPANY	PINNELL MICHAEL L
PHOENIX RESOURCES CO	PINON PETROLEUM LLC
PIC PROD CO INC	PINTADO OIL & GAS LLC
PICKENS JOHN T	PINTAIL PROD CO INC
PICKENS R H	PIONEER EXPL CO
PICKERING RONALD L	PIONEER EXPLORATION LTD
PICKLE INC	PIONEER KETTLEMAN CO
PIEDMONT EXPL CO INC	PIONEER NAT RES USA INC
PIERCE CALVIN E	PIONEER NATL RESOURCES USA

Current BLM Oil and Gas Lessees:

PIONEER NATURAL RES USA INC	PLAINS RADIO PETRO
PIONEER NATURAL RESOURCES	PLAINS RESOURCES INC
PIONEER NATURAL RESOURCES INC	PLAINSMEN LAND LLC
PIONEER O&G	PLAINSMEN PARTNERS LLC
PIONEER OG	PLANET ASSOC INC
PIONEER OIL & GAS	PLANO PETROLEUM LLC
PIONEER OIL CO	PLANTATION OPERATING LLC
PIONEER RESOURCES PR	PLANTATION PETRO ACQ LLC
PIONERR ASSOC	PLANTATION PETROLEUM CORP
PIP 1990 TRUST	PLANTEFABER MARGARET
PIP ENERGY IV-80	PLAYA O&G LP
PIP ENERGY V-80	PLAZA RES CO
PIP ENERGY XII-81	PLAZA RESOURCES CO
PIPER PETRO CO	PLEMONS GLEN
PIPKIN LUCILLE H	PLEMONS JACK
PITCH ENE CORP	PLEXUS INC
PITCH ENERGY CORP	PLEXUS O&G VENTURE
PITCO PRODUCTION CO	PLIHA BARBARA JANE
PITKIN COUNTY ASSOC	PLOMIS WILFRED LIVING TRUST
PITMAN MARSH	PLYMOUTH RESOURCE INC
PITOT OG LLC	PMC 1988-WI ACQ LTD
PITOT OIL & GAS LLC	PMC 1990 EQ ACQ
PITTENCRIEF AMER INC	PMC 1990-EQ ACQ LTD
PITTMAN ENERGY LP	PMC 1990-WI ACQ LTD
PITTS DAVID J	PMC 1990-WI ACQ PRTS
PITTS ENERGY CO	PMC RESERVE ACQ CO
PITTS FRANK L	PMC RESERVE ACQ II
PITTS GERALD S	PMC RESOURCE ACQ CO II
PITTS GREGORY S	PMC RESOURCE ACQ CO III
PITTS JANICE K	PO & G RESOURCES TEXAS LLC
PITTS L FRANK	PO & G RESOURCES-TEXAS LLC
PITTS LLC	PO&G RESOURCES TX LLC
PITTS MALCOLM J	POCAHONTAS OIL CO INC
PITTS OIL CO LLC	POE NANCY
PITTS STEVEN L	POGAR PETROLEUM LTD
PIUTE ENERGY CO	POGO PRDCNG (SAN JUAN) CO
PIZZANO PEPPi	POGO PRODUCING (SAN JUAN) CO
PJC LIMITED PARTNERSHIP	POGO PRODUCING CO
PJC REV TRUST	POGO PRODUCING CO LLC
PLACERITA PARTNERS	POGO PRODUCING COMPANY
PLACID OIL C/O OXY	POGO PRODUCING COMPANY LLC
PLAINS ENE INVESTMENTS INC	POINDEXTER MARY A P
PLAINS EXPL & PROD CO	POINDEXTER MARY P
PLAINS EXPLRN & PRODN CO	POINDEXTER R D
PLAINS PETRO OPER	POINT MGT CO
PLAINS PRODUCTION INC	POINT PETRO CORP

Current BLM Oil and Gas Lessees:

POIRIOR RUTHANN	POULSON ROBERT D
POISON SPIDER PETROLEUM LLC	POUSETTE PATRICIA C
POLARIS PROD CORP	POWDER HORN INVESTMENTS LLC
POLER MARIE	POWDER RIVER COAL LLC
POLFAM EXPL CO	POWDER RIVER METHANE INC
POLLAK IRVING TRUSTEE	POWDER RIVER O&G VENTURES LLC
POLLARD O MILES JR	POWDER RIVER OIL CO
POLLARE JOSEPH S	POWDERHORN RES INC
POLO OIL & GAS CO	POWE WALKER H III
POLUMBUS E A JR	POWELL BARBARA
POMEROY BEATRICE C	POWELL BARBARA A
POMEROY PROD PTNRSHP	POWELL CITY OF
POMEROY RUSSELL A	POWELL CUTHBERT
POMEROY WESLEY A	POWELL EXPL CO
POMOCO LTD LIBIL CO	POWELL EXPLORATION COMPANY
MONTEREY RES CORP	POWELL KATHLEEN J
PONTOTOC PROD INC	POWER RESOURCES LLC
PONTOTOC PRODUCTION CO INC	POWERLINE ENE CORP
POOL FRED F III	POWERS CAYCE JR TRST
POOL FRED III	POWERS ENE CORP
POOL H O	POWERS RAY B JR
POOL JOHN D	PP&G OIL CO
POOL O&G	PRADERA DEL NORTE INC
POOL OIL & GAS	PRAIRIE OF THE SOUTH LLC
POOLE DOROTHY B	PRAIRIE OIL CO
POOLE MARY K	PRAIRIE PETRO INC
POOLE WILLARD C III	PRAIRIE STATES EXPL
POOS OIL LLC	PRAIRIE SUN INC
POPE JULIAN C	PRATT LE ROI D
POPLAR ENE CO LLC	PRB PETROLEUM LLC
POPOVICH GLENN	PRC WILLISTON LLC
PORTER JR ROBERT B	PRE RESOURCES INC
PORTER ROBERT B JR	PRECISION WELL SVC
PORTER, CATHERINE J	PREFERRED ENDEAVORS
POSADA LAND & CATTLE CO	PREMCO WESTERN INC
POSITRON ENERGY RESOURCES INC	PREMIER OG INC
POSO CREEK ENERGY LLC	PREMIER RES LTD
POSSE ENE LTD	PREMIUM OIL CO
POSSE ENERGY LTD	PRENDERGAST MARY ALICE
POST OAK PRODUCTION	PRENTICE NAPIER
POTASHNICK R B	PRESCO INC
POTENZIANI CHERYL L	PRESCO WESTERN LLC
POTENZIANI FAMILY PARTNERS	PREScott RICHARD H JR
POTESTIO FRANK S	PRESLEY CHARLES
POTOCO LLC	PRESLEY OIL CO
POTTER SARA TYLER	PRESTON OIL CO

Current BLM Oil and Gas Lessees:

PRESTON REYNOLDS & CO INC	PRINCIPAL PROPERTIES
PRESTWICH SUSAN MIRA	PRINGLE CHESTER L
PREVEHOUSE INC	PRINSTER SALLY L
PRIAM ENERGY CO	PRINTZ DARREN K
PRIAM OIL CO	PRINTZ LTD
PRICE JONAN	PRIOR OIL CO
PRICE LAUGHLIN & CO INC	PRIORITY ENERGY LLC
PRICE OG INVESTMENT TRUST	PRIORITY O&G LLC
PRICHARD MELODY B	PRISCO PETRO CO
PRIDE ENE CO	PRISCO PETROLEUM CO
PRIDE ENERGY CO	PRITCHARD J A
PRIDE ENERGY COMPANY	PRITCHARD R L
PRIDE PIPELINE CO	PRITCHETT FRANK I JR
PRIDE VENTURES LLC	PRITCHETT JOE P
PRIDE WAYNE	PRITCHETT KENNETH G
PRIDGEN JESS	PRIZE ENE RES LP
PRIEST JOHN W	PRIZE ENERGY RESOURCES
PRIM CHILDRENS FNDTN	PRIZE ENERGY RESOURCES LP
PRIMA ENERGY CORP	PRIZE PETRO LLC
PRIMA EXPL INC	PRM 96 LLC
PRIMA EXPLORATION INC	PRO AMER CO
PRIMAL ENERGY CORP	PRO NM ENERGY INC
PRIMARY FUELS INC	PRO OIL INC
PRIMARY NATURAL RES INC	PROBE RESOURCES INC
PRIMARY PETRO CO LLC	PROD PTNRSHP VP-20
PRIMAVERA RESOURCE INC	PROD PTNRSHP VP-21
PRIME ENERGY CORP	PROD PTNRSHP VP-22
PRIME ENERGY MGT CORP	PRODCO INC
PRIME RESOURCES CORP	PRODUCTION GATHERING
PRIMEENERGY CORP	PRODUCTION GATHERING CO LP
PRIMEENERGY MGT CORP	PROFESSIONAL DRLG
PRIMERO OPERATING INC	PROFESSIONAL PLANNERS INC
PRIMEXX OPERATING CORP	PRONGHORN ENE LLC
PRIMO OIL PROPERTIES LLC	PRONGHORN ENERGY LLC
PRIMOS ANGELO K	PRONGHORN GROUP
PRIMOS GUS A	PRONGHORN MGT CORP
PRIMUS RESOURCES LC	PRONTO PETROLEUM
PRINCE DIANE C	PROPEL ENERGY CO
PRINCE DON	PROPERTY MANAGEMENT
PRINCE F IV	PROPERTY MGT & CONSULTING INC
PRINCE FREDERICK IV	PROPETROCO INC
PRINCE JOANN	PROPOLANIS PATRICIA
PRINCESS THREE CORP	PROPPS JACK
PRINCETON RES LTD	PROSPECTIVE INVESTMENT
PRINCETON RESOURCES LTD	PROSPECTIVE INVSTS & TRADE CO
PRINCETON UNIVERSITY	PROSPECTIVE TRADING

Current BLM Oil and Gas Lessees:

PROSPECTOR LLC	PUBLIC SERVICE CO OF CO
PROSPER ENERGY CORP	PUBLIC SVC CO OF OK
PROTHRO CHARLES	PUBLISHERS PETROLEUM
PROVEN RESERVES MGT INC	PUCKETT INVESTMENT CO
PROVIDANCE ENER CORP	PUCKETT LAND CO
PROVIDENCE CORP	PUCKETT R E
PROVIDENCE ENE CO	PUCKETT ROBERT E
PROVIDENCE ENE CORP	PUGH PATRICIA
PROVIDENCE ENERGY CORP	PULLIAM BONNIE
PROVIDENCE EXP & PROD INC	PUMA OPERATING CORP
PROVIDENCE MINERALS LLC	PUMA PETROLEUM CO
PROVIDENT RESOURCES	PUNTER CLANCEE DEE
PROVIDENT RESOURCES INC	PUNTER NORMAN
PROVINCE ENERGY CORP	PUNTER PANDORA
PROVINSE DAVID D	PUNTO DE LUZ LLC
PROYECT CAROL	PURDY FRANCES P
PROYECT MARTIN	PURE ENERGY GROUP INC
PRU-BACHE ENE IIIP12	PURE PETROLEUM LLC
PRU-BACHE ENE IIIP13	PURE RESOURCES LP
PRU-BACHE ENE IIIP14	PURE VIDA ENERGY LLC
PRU-BACHE ENE IIIP15	PURVIS JAMES R
PRU-BACHE ENE IIP10	PURVIS MARGARET M
PRU-BACHE ENE IIP11	PURVIS OIL CORP
PRU-BACHE ENE INC	PURVIS OPER CO
PRU-BACHE ENE IVP16	PUTNAM FREDERIC
PRU-BACHE ENE IVP17	PUTNAM FREDERIC P
PRU-BACHE ENE PROD	PUTNAM WILLIAM H
PRU-BACHE ENE VP18	PUTUMAYO PRODUCTION CO
PRUDENTIAL BACHE ENE	PVB OIL CO
PRUDENTIAL ENERGY CO	PW/GEODYNE PROD II-C
PRUDENTIAL FUNDS INC	PW/GEODYNE PROD II-D
PRUDENTIAL GROUP INC	PW/GEODYNE PRODUCTION 11-C
PRUDENTIAL-BACHE ENE	PW/GEODYNE PRODUCTION 11-D
PRUDENTIAL-BACHE-V20	PWG PARTNERSHIP
PRUDENTIAL-BACHE-V21	PXP GULF COAST INC
PRUDENTIAL-BACHE-V22	PXP LOUISIANA LLC
PRUET OIL CO	PXP PICEANCE LLC
PRUITT DELMUS C	PYR ENE CORP
PRUITT EULA M	PYR ENERGY CORP
PRUITT PAT	PYR MALLARD LLC
PRYOR VICTOR W JR	PYRAMID ENERGY INC
PT ENE LLC	PYRAMID OIL CO
PTASYNISKI HARRY	PYRAMID PETRO CO
PTASYNISKI HARRY	PYRITE INVESTMENTS LTD
PTASYNISKI NOLA G	Q & C LOU FAMILY LTD PTNRSHP
PTASYNISKI NOLA GRACE	Q G & WENNER PTNRSHP

Current BLM Oil and Gas Lessees:

Q2 NOMINEE PTNRSHP	QUICKSILVER RES INC
QAB CARRIED WI LP	QUICKSILVER RESOURCES INC
QAC CARRIED WI LP	QUIGLEY W DON
QEP ENE CO	QUINEX ENERGY CORP
QEP ENERGY CO	QUINLIN MEANY ELIZABETH
QEP ENERGY COMPANY	QUINLIN PORTER LLC
QEP UNTA BASIN INC	QUINLIN WILLIAM J
QUADRA OIL & GAS INC	QUINN KATHLEEN
QUAGLINO JOANN	QUINN VRANNA
QUALITAS INC	QUINQUE OPERATING CO
QUALITY PRODUCTION CORP	QUINTANA PETRO SVC
QUALLS JOHN W	R & G DRILLING CO INC
QUAM JEAN	R & G RES LLC
QUAM O M	R & H ELLIOTT FAM LTD PTNRSHP
QUANAH EXPLORATION LP	R & M O&G LTD
QUANECO LLC	R & M OIL & GAS LTD
QUANTUM CORP	R & P O & G PROP
QUANTUM ENERGIES CO	R & R INVESTMENTS
QUANTUM ENERGY	R & R ROYALTY LTD
QUANTUM ENERGY INC	R A BELFER 1990 TRUST
QUANTUM EQUITIES	R B C EXPL CO
QUANTUM RES MGMT LLC	R B MONCRIEF TRUST
QUANTUM RESOURCES	R B OIL CO
QUANTUM RESOURCES A1 LP	R BAYLESS PRODUCER
QUANTUM RESOURCES A1, LP	R BELFER FAMILY TRUST
QUARLES DRLG CORP	R C BELL FAMILY
QUATRO FINALE II LLC	R C BRADLEY TRUST
QUATRO FINALE III LLC	R C MICHAEL CO INC
QUATRO FINALE LLC	R D POINDEXTER EST
QUATRO FINALE V LLC	R D V INC
QUAY VALLEY INC	R D WILLIAMS & COMPANY
QUEEN BILL	R DEAN WRIGHT GAS PTNRSHP
QUENTIN OIL ASSOC	R E LEE TRUST
QUESTAR ENE TRADING	R F WINDFOHR ESTATE
QUESTAR EXPL & PROD	R F WINDFOHR TRUST
QUESTAR EXPL & PROD CO	R G BARTON JR TRUST
QUESTAR GAS MGT CORP	R G KELLY ESTATE
QUESTAR PIPELINE CO	R G MARTIN TRUST
QUIAT DANIEL P	R H & S A RITCHIE REV TRUST
QUIAT G & R PTNRSHP	R HUBBARD JR TRUST
QUIAT GERALD M & CO	R J ENERGY PTNRSHP
QUIAT ILANA L TRST #1	R J G CO
QUIAT LEONARD E	R L B ENTERPRISES INC
QUIAT MEG G	R L BOLIN PROPERTIES LTD
QUIAT MELINDA	R L JACOBS OIL & GAS
QUIAT ROBERTA N & CO	R L TOLLETT TRUST

Current BLM Oil and Gas Lessees:

R L VESCO INC	RALPH E FAIR TESTAMENTARY TRST
R M REAGAN TRUST	RALPH H SMITH TR
R P BREWER III ESTATE	RALPH H SMITH TRSTEE
R P HARGRAVE ESTATE	RALPH HARTZELL TRUST
R P SMALL CORP	RALPH NIX ESTATE
R P TINNIN SR TRUSTEE	RALPH NIX PARTNERSHIP
R P VERNON TRUST	RALPH S JACKSON TRUST
R R HERRELL PROP LTD	RALPH U MADDOX EST
R S & M LANELL SWEET TRUST	RALPH&CAROLYN THOMPSON LIV
R S ANDERSON INC	TRS
R T & H L ELLIOTT FAMILY LP	RAM ENERGY INC
R T DUNCAN INC	RAM OIL & GAS LLC
R T LUND OIL TRUST	RAM RES CONS INC
R THOMAS WATSON 1993 TRST	RAMAGE THOMAS D
R V MERRION TRUST	RAMATI ALEXANDER
R W HART TRUST	RAMCO NYL 1987 LTD
R&H OIL AND GAS INC	RAMONA SWEET REVOCABLE TRUST
R&P OIL&GAS PROP LTD	RAMONA SWEET TRUST
R&R ROYALTY LTD	RAMPART ENERGY FUND LLC
R&S LTD	RAMPART RES INC
R&S OIL & GAS	RAMSAY KEITH
RACHALK PROD INC	RAMSEY G D JR
RACHEL GRYNBERG TRUST	RAMSEY PETROLEUM LP
RACHEL NICOLE COCHRAN ED TRST	RAMSEY STEVE
RAD F N	RAMSEY WILLIAM SCOTT
RADDATZ MAUDE W	RAMSHORN INVESTMENTS INC
RADELLA FRANK & PATRICIA TRST	RAMSHORN INVSTMNTS INC
RADELLA FRANK A	RAMSING THOR H
RADENTZ WILLIAM H	RAMSLAND JANE B MARITAL TRUST
RADER TERRY	RAMSLAND RUSSELL JR
RAFFAGHELLO DALAN I	RANCH OIL CO
RAFFERTY C B	RANCH OIL COMPANY
RAFFERTY PATRICIA C	RANCHER ENERGY CORP
RAGLAND RONALD D	RANCHO LOS ALAMOS LLC
RAGSDALE ANN S	RANCK BARBARA J
RAGSDALE GEORGE M TRUSTEE	RANCK LESLIE C
RAGSDALE TOM M	RANCK OIL CO INC
RAHLL GENE	RANCK W W
RAHLL ROBERT J	RAND PHILLIP
RAIGORODSKY PAUL M	RANDALL D SCHULTZ SEP PROP TRS
RAINBOW ENE MARKETING CORP	RANDEL O H
RAINBOW GAS CO	RANDOLPH REX L
RAINS & WILLIAMS OIL	RANDOLPH REX L TRUSTEE
RALPH E FAIR INC	RANES BETTY S
RALPH E FAIR JR FAMILY TRST	RANES ROBERT C
RALPH E FAIR JR TRST	

Current BLM Oil and Gas Lessees:

RANGE OPERATING NEW MEXICO LLC	RAYDON PRODUCTION CO
RANGE PRODUCTION CO	RAYGOR PAUL M
RANGE PRODUCTION I LP	RAYMOND CHORNEY EST
RANGE RESOURCES - APPALACHIA	RAYMOND CHORNEY ESTATE
RANGE RESOURCES LLC	RAYMOND G STONE TRUST
RANGER EXPLORATION CO	RAYMOND JAMES M
RANGER OIL CO	RAYMOND T DUNCAN OIL
RANKEN ENE CORP	RAYMOND T DUNCAN OIL PROP
RANKEN ENERGY CORP	RAYMOND T DUNCAN OIL PROP LTD
RANKIN PAUL	RAYMOND T DUNCAN TRUST
RANKIN W D ESTATE	RAYMOND TWOMEY DUNCAN TR
RANNEY NORA T	RAYMOND TWOMEY DUNCAN TRST
RANOLA OIL CO	RAYNOR WALLACE
RANSOME-LOSEE ANNE	RB OIL CO
RAPADA 81 LTD PTNRS	RBC EXPL CO
RAPADA 81A LTD PTNRS	RBC EXPLORATION CO
RAPP OIL FOUNDATION	RBCM INC
RAPTOR RESOURCES INC	RBJ OIL LLC
RASBACH JANE P	RBM CO
RASH ENERGY CO	RC MICHAEL CO INC
RASMUSSEN HAL J OPER	RC RESOURCES CORP
RASMUSSEN LOWELL A	RCH UPLAND ACQUISITION LLC
RAT HOLE DRILLING	RCJ ENTERPRISES
RATCLIFF SAM R	RCWI, LP
RATHBONE MARY E	RDG OIL AND GAS LLC
RATHBUN RANDALL K	RDH ENTERPRISES INC
RATHPRO INC	RDR OPERATING INC
RATLIFF BARBARA J	RE & CJ LC
RATLIFF DRILLING	REACH INC
RAULT PETROLEUM CORP	READ & STEVENS INC
RAVEN OIL PROP INC	READ BEALL CAROLYN
RAVEN OIL PROPERTIES INC	READ CHARLES B
RAVEN RES INC	READ JAMES B
RAVEN RESOURCES LLC	READ JAMES B OPERATING INC
RAVEN WING RESOURCES INC	READ LAURA K
RAWITSCHER JACK J	READ WILLIAM E
RAY CHARLES D	READING & BATES
RAY JAMES C	READ-YOUNG BETTY
RAY RICHEY & CO INC	REAL WELL SERVICE
RAY RICHEY MGT CO	REALEZA DEL SPEAR LP
RAY ROBERT B	REARDON GENE F
RAY WESTALL OPER INC	REATA RESOURCES INC
RAYA ENERGY CORP	REAVIS DAVID M
RAYBOURN W B	REBEL DRILLING CO LP
RAYDON EXPLORATION INC	REBER-GARRETT ASSOC PTNRSHP
	RED BIRD OIL PROPERTIES LLC

Current BLM Oil and Gas Lessees:

RED BLUFF WATER	REELY JOHN
RED DIRT ENERGY LLC	REELY WILLIAM
RED EAGLE EXPL CO	REES W N
RED EAGLE RES CORP	REESE KATHRYN J
RED FORK DRLG PROG	REESE KURTIS K
RED HORN ENERGY LLC	REESE LILA
RED OAK CATTLE CO	REESE LIVING TRST
RED OAK PETRO CORP	REESE MARY LEE S
RED OAK WISE COUNTY LP	REESE SMITH R
RED RIVER OIL AND GAS LLC	REESER WAYNE F
RED TECHNOLOGY ALLIANCE LLC	REEVE O J
RED WILLOW OFFSHORE LLC	REEVE RICHARD P
RED WILLOW PRODUCTION CO	REFUGE RESOURCES LLC
RED WILLOW PRODUCTION LLC	REGER JANE L
REDCLIFF RESOURCES LC	REGER OIL LLC
REDDING DANIEL H	REGER STEVEN L
REDEKER JOHN A	REGIONS MORGAN KEEGAN TRUST
REDEPENNING BYRON	REICHERT TED L
REDEPENNING JUDITH	REID BRIAN C
REDEPENNING ROGER	REID DANIEL
REDEPENNING TRUMAN	REID ELLEN
REDFERN ENTERPRISES	REID IRVIN M
REDFERN GROVER R	REID KATHERINE
REDFERN OIL CO	REID LUCILLE J
REDFERN ROSALIND	REID VIRGINIA I
REDGATE PETROLEUM INC	REID ZACHARIAH J
REDHORN ENERGY	REILLY SIDNEY
REDIN GAIL	REIMERS DENNIS R
REDLAND RESOURCE INC	REIMERS TERESA M
REDROCK OPERATING LTD CO	REINHART JOHN B
REDSTONE INVESTMENTS	REISCHMAN ANNA A
REDSTONE OIL & GAS CO	REISCHMAN GENE
REDSTONE RESOURCES INC	REISCHMAN L J HEIRS
REDWINE RESOURCES	REISCHMAN MARGARET L
REDWINE RESOURCES INC	REISHMAN ANNA A
REDWOLF PRODUCTION INC	RELCO EXPL CO INC
REED & REED TRUST	RELIANCE EAGLEFORD UPSTREAM
REED BRUCE F	LP
REED CHARLES B	RELIANCE ENERGY INC
REED JAMES	RELIANCE OIL COMPANY LLC
REEDER ENERGY LTD	RELIANCE OPERATING CO
REEDER J A	RELIASTAR LIFE INSURANCE CO
REEF EXPL INC	REMORA OIL CO
REEF EXPLORATION INC	REMUDA ENE DEV LLC
REEF OPERATING COMPANY LLC	REMUDA ENERGY DEVELOPMENT
REEF PARTNERS HOLDING CO LLC	LLC

Current BLM Oil and Gas Lessees:

RENAISSANCE PETRO CO LLC	REYNOLDS FAMILY TRUST
RENAUD OIL CORP	REYNOLDS H W JR
RENDEZVOUS RESOURCES CORP	REYNOLDS JAMES H
RENDEZVOUS RESOURCES INC	REYNOLDS JOE J
RENEGADE OIL & GAS CO, LLC	REYNOLDS KENNETH D
RENOR EXPLOR LTD	REYNOLDS KENNETH J
RENWICK TRUST	REYNOLDS METALS CO
REPUBLIC NATURAL GAS CO	REYNOLDS RANDY
REPUBLIC RES LTD	REYNOLDS SARAH
RES EXEMP EQUIV TR	REYNOLDS W JR
RES O&G LTD PTRNSHP	RG AMERICAN INTERESTS LLC
RESACA EXPL LP	RG OIL VENTURE INC
RESERVE ACQUISITION	RGB CO
RESERVE EQUIPMENT SVC CORP	RGB CONSULTING INC
RESERVE MANAGEMENT INC	RGKH MIN & RLTY TRST
RESERVE OIL INC	RHEES F H
RESERVE OPER CORP	RHINO RESOURCES CO LLC
RESERVE OPERATING CORP	RHOADS ISABELLE
RESLER DALE	RHODES AMER RES INC
RESOLUTE ANETH LLC	RHODES CECIL J
RESOLUTE WYOMING INC	RHODES GRACE R
RESOURCE CAPITAL MGMT CO INC	RHODES INTERESTS LTD
RESOURCE DEV TECHLGY LLC	RHODES LISA L
RESOURCE DEV TECHNOLOGY LLC	RHODES ROBERT B JR
RESOURCE DEVELOPMENT TECH LLC	RHOLYN LTD
RESOURCE INVESTMENT CORP	RHOMBUS ENERGY CO
RESOURCE LEGACY INVSTMNT LLC	RHOTENBERRY CLAIRE C
RESOURCE STRATEGIES	RHOTENBERRY JAMES R
RESOURCE STRATEGIES LLC	RHUDY LESTER G
RESOURCE TRUST CO	RHUMBA OPERATING LLC
RESOURCES INVST CORP	RIAL SUZANNE D
RESOURCES LEGACY INVESTMENTS	RIALTO ENERGY INC
L	RIALTO PRODUCTION CO
RESOURCES MGT CORP	RIATA ENERGY INC
RESTANA OG INC	RICE BROTHERS
RETAMCO OPER INC	RICE CARROLL A TRST
RETAMCO OPERATING INC	RICE CHARLES G
RETCO RESOURCES INC	RICE CLINTON P
REUNION ENE CO	RICE HAROLD F
REUNION ENERGY CO	RICE OIL CO LLC
REV TRUST OF GENE&CATHY	RICE R R
GEORGE	RICE SALLY E
REVERE CORP	RICH BILL
REX ENERGY I LLC	RICH PATSY
REX LUMBER CO	RICH ROYAL PROPERTIES LLC
REXNORD EXPL LTD	RICH SHIRLEY R

Current BLM Oil and Gas Lessees:

RICH SHIRLEY RUNYAN	RICKS EXPLORATION
RICHARD A MORSE REVOCABLE	RICKS EXPLORATION CO
TRST	RICKS RAN JR
RICHARD ALTMAN & CO	RICKY SMITH OG LTD
RICHARD ANDERSON INC	RIDDLE FRANK H & FLORENCE
RICHARD B MONCRIEF TRUST	RIDDLE HAL G
RICHARD D HUGHES TRUST	RIDDLE M A
RICHARD FREDERICK GESSION TRUS	RIDDLE W H
RICHARD J MONCRIEF 1988 TRST	RIDGELAND OPER CO LLC
RICHARD J MONCRIEF 1988 TRUST	RIDGELAND WYOMING INC
RICHARD JASON MONCRIEF TRUST	RIDGEWAY AZ OIL CORP
RICHARD L PETERSON TRUST	RIEK ROBERT R
RICHARD LYONS MOORE 2006 TRUST	RIENER CAREN
RICHARD TULLY TRUST	RIENER MARK
RICHARDS CLARK G	RIGGS DAN B
RICHARDS DAMON	RIGGS ELLIOTT A
RICHARDS GARY L	RIGGS OG CORP
RICHARDS LYNN S	RIGGS OIL & GAS CORP
RICHARDSON BLAIR	RIGGS ROY D JR
RICHARDSON JACK K	RIGGS/CREIGHTON
RICHARDSON JAMES P	ROGO RICHARD J
RICHARDSON JOE C JR	RILEY JENNIFER ANN
RICHARDSON OIL CO	RILEY MARION
RICHARDSON OPER CO	RILEY MARION P
RICHARDSON OPERATING CO	RILEY MAX L
RICHARDSON PROD CO	RILEY RIDGE LLC
RICHARDSON PRODUCTION CO	RIM CBM LLC
RICHARDSON PRODUCTION CO	RIM LLP
RICHARDSON R M	RIM OFFSHORE INC
RICHARDSON RANDOLPH	RIM OPERATING INC
RICHARDSON REX H	RIMCO ENERGY INC
RICHARDSON S S	RIMCO EXPLORATION PTNRS I
RICHARDSON SUSAN S	RIMCO EXPLORATION PTNRS II
RICHARDSON WINIFRED	RIMCO EXPLORATION PTNRS LP
RICHIE CYNTHIA D	RIMCO PROD CO INC
RICHIE DAVID R II	RIMCO ROYALTY CO
RICHINS LAWRENCE D	RIMROCK COLONY INC
RICHMOND MARTHA L	RINARD RICHARD
RICHMOND PETROLEUM INC	RINCON OG LLC
RICHMOND RES INC	RIO ARRIBA INVESTMENT LLC CO
RICHMOND RESOURCE INC	RIO AUERO LLC
RICK CARUTHER CONSTR	RIO BLANCO ENE INC
RICKEY HOWARD	RIO BLANCO NATURAL GAS
RICKEY RITA	RIO BRAVO POSO PTNR
RICKEY SMITH OG LTD	RIO CHALLENGER LLC
RICKS EXPL CO	RIO CHAMA PETROLEUM

Current BLM Oil and Gas Lessees:

RIO CHAMA PETROLEUM INC	ROACH LA ENERGY
RIO CO O&G INC	ROADRUNNER OIL & GAS (USA) INC
RIO DE VIENTO INC	ROADRUNNER OIL& GAS (USA) INC
RIO GRANDE EXPL CO	ROBB E A
RIO GRANDE EXPL CO	ROBB MARIA A
RIO GRANDE EXPLRN CO	ROBBINS CRAIG
RIO GRANDE OFFSHORE	ROBBINS KAREN
RIO LOBO RESOURCES	ROBBINS L D
RIO MESA RESOURCES INC	ROBBINS R W
RIO PECOS CORP	ROBEREN PROPERTIES
RIO PETROLEUM INC	ROBERSON JOE
RIO PETROLEUM LTD	ROBERSON OIL CO INC
RIOKERN PETROLEUM	ROBERSON RALPH G
RIPPY JANET LEGGETT	ROBERT A BELFER TRST
RISP INC	ROBERT A GLICK TRUST
RITCHIE BROTHERS INC	ROBERT ANDREW WIEDEMER TRUST
RITCHIE EXPLORATION INC	ROBERT B FERGUSON TRUST
RITCHIE ROBERT H	ROBERT BRAGG ESTATE
RITCHIE SCOTT A TRST	ROBERT C LITTLEFIELD TEST TRST
RITCHIE SUSAN A	ROBERT D GARMAN REVOC TRUST
RIVA OIL & GAS LLC	ROBERT D GARMAN TRUST
RIVER PROD CO INC	ROBERT E HUDSON REVOCABLE
RIVER PRODUCTION CO	TRST
RIVERBEND EXPL & PROD LLC	ROBERT E HUDSON TRST
RIVERBEND EXPL & PROD, LLC	ROBERT E TAUBERT TR
RIVERBEND PRODUCTION LP	ROBERT ECKELS FAMILY TRST
RIVERHILL ENERGY CO	ROBERT ECKELS MARITAL TRUST
RIVERHILL ENERGY CORP	ROBERT HALL INVESTORS II
RIVERTON EXPLORATION	ROBERT HAWKINS INC
RIVIERA DRILL & EXPL	ROBERT HOWARD TRUST
RIVIERA DRLG & EXPL CO	ROBERT J GRUNDY & ASSOC LLC
RJG CO	ROBERT J GUTRU LP
RJL OG INC	ROBERT L AUSTIN TRUST
RJR RESOURCES	ROBERT L BAYLESS LLC
RKC INC	ROBERT L BAYLESS PROD LLC
RKW ENERGY LLC	ROBERT L BAYLESS PRODR LLC
RL RAY LTD	ROBERT L BAYLESS PRODUCER
RM ENERGY CO	ROBERT L BAYLESS PRODUCER LLC
RMB OG NM LLC	ROBERT L HAYNIE REVOC TRST
RME OG CO	ROBERT L NADES TRUST
RME OIL & GAS CO	ROBERT L PARKER SR LTD PTNRSHP
RME PETROLEUM CO	ROBERT L SMITH & ASSOCIATES
RMOC HOLDINGS LLC	ROBERT M BASS GROUP INC
RMPG LLC	ROBERT M DOW REVOCABLE TRUST
RMS MONTE CHRISTO	ROBERT O LITTLE TRST
RO CO	ROBERT O LITTLE TRUST

Current BLM Oil and Gas Lessees:

ROBERT S BREWER TRST	ROBINSON LEE
ROBERT S HAIGH TRUST	ROBINSON OIL INC
ROBERT S HAWKINS EST	ROBINSON ROBERT R
ROBERT S HAWKINS INC	ROBINSON'S BEND OPERATING LLC
ROBERT SCOTT SCHULTZ TRUST	ROBISON COLEMAN L
ROBERTS & MURPHY INC	ROBISON WILLIAM A
ROBERTS ANNIE A	ROBLEDO HENRY G
ROBERTS BAYLESS PROD	ROCA EXPL LTD
ROBERTS BRUCE	ROCANVILLE CORP
ROBERTS BRUCE G	ROCK CREEK LND & ENE
ROBERTS CAROLYN R	ROCK CREEK OIL CO
ROBERTS CHARLES	ROCK EAGLE RANCH CORP
ROBERTS ELIZABETH G	ROCK HILL INVESTMENTS LLC
ROBERTS J I	ROCK ISLAND 1979 EXPL
ROBERTS MARGARET G	ROCK ISLAND 79 EXPL
ROBERTS MARGARET S	ROCK RESOURCES LLC
ROBERTS REBECCA JANE TEEL	ROCK RESOURCES PETRO LLC
ROBERTS SUSAN M	ROCK RIVER OPER INC
ROBERTS SUZANNE	ROCK SALA
ROBERTS VERNON	ROCK TREE LLC
ROBERTS VICTOR	ROCK WELL PETROLEUM (US) INC
ROBERTS-MCCELLAN CLARISSA S	ROCKET OIL & GAS CO
ROBERTSON 1982 EXPL	ROCKETT MARJORIE A W
ROBERTSON BALDWIN	ROCKEX CO
ROBERTSON CAROLINE F	ROCKFORD ENERGY PARTNERS III L
ROBERTSON CORBIN J	ROCKHILL RES INC
ROBERTSON F CAROLINE	ROCKIES STND OIL CO LLC
ROBERTSON FINLEY	ROCKMONT OIL PROPERTIES LLC
ROBERTSON FINLEY RES	ROCK-ON OIL & GAS LLC
ROBERTSON KAYLA	ROCKSOURCE ENE CORP
ROBERTSON LISA	ROCKSOURCE ENERGY
ROBERTSON RES INC	ROCKSOURCE ENERGY CORP
ROBERTSON TARYN	ROCKWELL ENERGY CORP
ROBERTSON W E	ROCKWELL GEORGINA E
ROBERTSON WILHELMINA	ROCKWELL RES INC
ROBICHAUD STEPHEN R	ROCKY MOUNTAIN LTD
ROBIN RESOURCES INC	ROCKY MOUNTAIN OPER CO INC
ROBINEAU M H	ROCKY MOUNTAIN RESOURCES INC
ROBINETTE LAWRENCE W	ROCKY MTN EXPL INC
ROBINSON C W	ROCKY MTN EXPL OF CO INC
ROBINSON DAVID L	ROCKY MTN LAND & LEASING LLC
ROBINSON F GEORGE	ROCKY MTN OILFINDERS
ROBINSON G ROSS	RODA DRILLING LP
ROBINSON GEORGE J	RODDY NANCY K
ROBINSON HERMAN G	RODDY PROD CO LLC
ROBINSON INC	RODEN JOHN B JR

Current BLM Oil and Gas Lessees:

RODEN W F	ROOD C M ESTATE
RODERICK JONATHAN S	ROOKIE O&G LLC
RODESSA OPERATING CO INC	ROOKS C ROSS
RODGERS MORTIMER W	ROOKS EDEMIA
RODGERS WILLIAM H JR	ROOKS JOSEPH LRAY
RODRIGUE SUSAN M	ROONEY L F
RODRIGUEZ EDDIE	ROONEY OPERATING CO
RODRIGUEZ JOSE E	ROOSEVELT ELLIOTT JR
RODRIGUEZ SUSAN M	ROOSEVELT PETER K
ROEC INC	ROOSTH BENNIE ESTATE
ROEHR'S ROBERT C	ROOSTH BENNIE TRUST
ROELOFS HARVEY TRSTE	ROOSTH HAROLD
ROEMER LAMAR B	ROOSTH HYMAN P
ROEMER OIL CO	ROOSTH ISADORE
ROEMER SWANSON ENE	ROOSTH SOLOMAN
ROEMER-SWANSON ENERGY CORP	ROOSTH WILEY
ROGER D SHAW JR TRUST	ROSCY LTD
ROGER K GRAY TRUST	ROSE ALBERT
ROGERS DAVID Y	ROSE J P
ROGERS DONNA J	ROSE OIL CORP
ROGERS ELIZABETH H	ROSELAND EXPLORATION
ROGERS ENERGY MANAGEMENT LLC	ROSELEE ENERGY LLC
ROGERS FAMILY LTD PRTNRSHP	ROSEN ARLENE G
ROGERS J A	ROSEN BEVERLY
ROGERS JAMES E	ROSEN CAROL LVG TST
ROGERS JAMES E JR	ROSEN JANE LOGEMANN
ROGERS JAMES W	ROSEN MARK
ROGERS JANELL S REV TRUST	ROSEN RICHARD J
ROGERS JOHN E	ROSENLU ND TERESA R
ROGERS MARVIN W	ROSENQUIST JUDITH V
ROGERS ORVILL CURTIS	ROSENQUIST WARREN N
ROGERS PATRICIA A	ROSENSTEIN C H
ROGERS VICTORIA A	ROSENSTEIN ROBERT H
ROGERT T ELLIOTT FAMILY LP	ROSETTA ENERGY PTRS LP
ROIL MINERAL & LAND CO	ROSETTA RESOURCES INC
ROJAS RAFAEL H	ROSETTA RESOURCES OPER LP
ROJO LLC	ROSETTA RESOURCES OPERATING LP
ROMANO NEIL	ROSETTA RESRC OPG LP
ROMANO NEIL V	ROSEWEB PARTNERS LP
ROMERE PASS ACQUISITION LLC	ROSEWOOD CORP
ROMERO FAMILY LP	ROSEWOOD RESOURCES CORP
ROMONA SWEET TRUST	ROSEWOOD RESOURCES INC
RONADERO CO INC	ROSKI GAYLE
RONADERO COMPANY INC	ROSLEY CORP
RONALD G MERCER TRUSTEE	ROSS & WHARTON GAS
RONALD TAYLOR	ROSS BARBARA O

Current BLM Oil and Gas Lessees:

ROSS EXPLORATION INC	ROYAL OIL LLC
ROSS EXPLORATIONS INC	ROYAL PROPERTIES INC
ROSS H EDWARD	ROYAL RES CORP
ROSS OIL CO	ROYAL RES EXPL INC
ROSS R BICKEL ESTATE	ROYALE DRILLING
ROSS R BICKEL TRUST	ROYALE DRILLING PROG
ROSS STEVEN 94-1 ACQ	ROYALE ENERGY CORP
ROSS T BICKEL TRUST	ROYALE ENERGY INC
ROSS TERRY	ROYALL JOHN R
ROSS WILLIAM G	ROYALL JOHN RICHARD
ROSSMERE LTD	ROYALTIES UNLIMITED INC
ROSS-STEVEN 1994-1	ROYALTY ACQUISITIONS LLC
ROSS-STEVEN 94-1 LLC	ROYALTY ACQUISITIONS LLP
ROST ENERGY CO INC	ROYALTY HOLDING CO
ROTER OIL CO	ROYALTY INTERESTS PTNRSHP LP
ROTHAERMEL LUCILLE	ROYALTY INVESTMENT LTD INC
ROTHWELL JACK C JR	ROYCE C J
ROTHWELL PAUL A	ROYCE ERLA
ROUBIDOUX LLC	ROYE CHARLES D TRUST
ROUNDS DWIGHT	ROZE ENERGY INC
ROUDTREE & ASSOC	ROZGONYI DAVID
ROURKE ANTHONY JJ JR	ROZGONYI TIBOR G
ROUSE JOHN E TRUST	ROZZELL ANGIE
ROUSE ROMA M	RP UFO INTERNATIONL LLC
ROUSSELOT N R	RRS OIL INC
ROUTSON JACK C	RSC RESOURCES LP
ROUTSON JACK C LIVING TRST	RSE PARTNERS I LP
ROUTSON JAMES G	RSR ENERGY LLP
ROUTSON MARY K	RSRJV LLC
ROVER RESOURCES INC	RTEX INC
ROVIG DAVID B	RTG CO
ROWAN BARBARA D	RUBENSTEIN IRWIN
ROWE FREDERICK M	RUBENSTEIN KATHLEEN A
ROWELL DEAN W	RUBICON ENERGY PARTNERS LLC
ROWLAND DAVID A	RUBICON OIL & GAS I LP
ROWLAND ROGER L	RUBICON OIL & GAS II LLP
ROWLAND WANDA	RUBICON OIL & GAS LLC
ROWLETT JOHN T	RUBIO JOHN G
ROWLEY H L	RUBOW JAMES J
ROXSTAR INVESTMENTS LLP	RUBSAMEN RILLINS S
ROY DONALD	RUDD FAMILY TRUST
ROY G SR&OPAL BARTON REV TRUST	RUDE GLADYS
ROY H DUBITZKY TRUST	RUDMAN M B
ROYAL ENERGY CORP	RUDMAN PARTNERSHIP
ROYAL ENERGY RESOURCES INC	RUDMAN PTNRSHP
ROYAL INVESTMENT CO	RUDMAN WOLFE

Current BLM Oil and Gas Lessees:

RUDY CLIFFORD K	RUTTER ENTERPRISES
RUDY M SHIRLEY	RUTTER ENTERPRISES LP
RUDY NAROD TRUST	RUTTER PAUL W
RUFFIN ROBERT H	RUTTER VIRGINIA S
RUFUS G CLAY TRUST	RWB OIL CORP
RUGGLES FLORA A	RW-DC #1-13 LLC
RUHL DAVID H	RWM 1988 TRUST
RULLA LOREN J	RWP OIL CORP
RUMWELL ARNOLD	RWW ENERGY FUND LLC
RUNDELL DAVID H	RYALL CHARLES O TRST
RUNDELL VIRGINIA H	RYAN CATHERINE G
RUNNING FOXES PETRO INC	RYAN EXPL INC
RUNNING HORSE PROD CO LLC	RYAN FAMILY MINERAL PTNRSHP
RUNYAN PEGGY	RYAN G POOLE TRUST
RUNYAN SHIRLEY	RYAN JERRY
RUNYAN TOM W	RYAN JO ANN
RUPE OIL CO INC	RYAN THOMAS C
RUSH ANN H	RYAN WILLIAM S
RUSH BRUCE A	RYDER STILWELL OIL
RUSH ENERGY LLC	RYERSON EDWARD L JR
RUSHFORD WILLIAM A	S & B OIL PROPERTIES
RUSHING R E	S & C CONSTR INC
RUSSELL LUND OIL TR	S & J OPERATING CO
RUSSELL PAUL ROSE TRST	S & L ENE INC
RUSSELL ROYALTY CO	S & M OIL OPERATIONS
RUSSELL SPENCER & CO	S & P CO
RUSSELL T LUND TRUST	S & S ENERGY CORPORATION
RUSSELL WALTON S	S & S ENERGY INC
RUSSO EXPL LLC	S A OIL & GAS CORP
RUTER & WILBANKS	S B CUMMINGS TRUST
RUTH ENGALL TRUST	S B OIL PROPERTIES
RUTH L WATERS TRUST	S B P LIMITED
RUTH OIL LLC	S B STREET & CO
RUTH P HARRISON TRST	S CUMMING TRUST
RUTHERFORD VIVIAN I	S E S OG INC
RUTKOWSKI MARION L	S E S OIL & GAS INC
RUTLAND JR J W	S GARY JR & ASSOC
RUTLEDGE JODIE	S J IVERSON TRUST
RUTLEDGE PAUL F	S K WARREN RESOURCES LLC
RUTLEDGE ROBERT D	S MCLANE TRUST
RUTTER & WILBANKS	S P YATES 1976 TRUST
RUTTER A W ESTATE	S REGER FAMILY MINERAL PTNRSHP
RUTTER A W III	S T GRYNBERG TRUST
RUTTER A W JR	S T OIL CO
RUTTER ALBERT W JR	S W ENERGY CORP
RUTTER AND WILBANKS CORP	S&E INVESTMENTS LTD

Current BLM Oil and Gas Lessees:

S&J OPERATING CO	SALES RENO H
S/GE-I LLC	SALMON BETTYE JEAN
SAATHOFF PETRO LLC	SALMON DONNA
SABA ENE OF TX INC	SALMON JOE C
SABA ENERGY INC	SALMON RAYMOND JR
SABA ENERGY TX INC	SALOGA EUGENE
SABADA US INC	SALT CREEK OIL LLC
SABER OIL & GAS VENTURES LLC	SALT MINE INVSTMENT PTNRSHP LTD
SABRE EXPLORATION INC	SALTSMAN CORNELIA J
SABRE MANAGEMENT LLC	SALTSMAN RALPH JR
SABRE OPERATING INC	SAM A B
SACHEM RESOURCES CORP	SAM JANET D
SACKO WALTER F	SAMEDAN OIL CORP
SACRAMENTO MNCPL UTILITY DIST	SAMIN I SIRMAN EST
SACRAMENTO PARTNERS LP	SAMIS OIL CO INC
SADDLE RIM ENERGY LLC	SAMMONS MABEL D
SAE OIL & GAS COMPANY LLC	SAMPSEL WILLIAM H
SAGA HOLDING CO LLC	SAMSON 3000 LLC
SAGA HOLDING COMPANY LLC	SAMSON CONTOUR ENERGY E&P LLC
SAGA PETRO CORP	SAMSON CONTOUR ENERGY E&P LP
SAGA PETROLEUM CORP	SAMSON GAS PROD CO
SAGA PETROLEUM LLC	SAMSON HYDROCARBON CO
SAGA PETROLEUM LTD	SAMSON HYDROCARBONS
SAGAMORE CBM LLC	SAMSON HYDROCARBONS CO
SAGE ELEANOR G	SAMSON LONE STAR LLC
SAGE JIMMIE NEIL	SAMSON LONE STAR LP
SAGE PETRO LLC	SAMSON LONESTAR LP
SAGEBRUSH OIL INC	SAMSON NAT GAS CO
SAGEBRUSH OILWELLS	SAMSON OIL AND GAS USA INC
SAGEBRUSH RES II LLC	SAMSON OIL CO
SAGLE&SCHWAB&MCLEAN	SAMSON PROP 1983-B
SAGUINE LTD	SAMSON RES CO
SAHARA DEV CO INC	SAMSON RESOURCES CO
SAHARA OPERATING CO	SAMSON RESOURCES COMPANY
SAINT RES LLC	SAMUEL GARY JR & ASSOC INC
SAITO ERIC T	SAMUEL GARY JR & ASSOC INC
SAITO KAREN D	SAMUEL L STEDMAN EST
SAKCO LTD	SAN ANDRES HORZ DRLG
SALA ROCK	SAN JACINTO CORP
SALAZAR FAMILY TRUST	SAN JUAN BASIN CONS
SALAZAR JULIA	SAN JUAN BASIN PROP LLC
SALAZAR LUPE	SAN JUAN BASIN PROPERTIES
SALAZAR MINERALS LLC	SAN JUAN BASIN PROPERTIES LLC
SALE RELDA BRINSON	SAN JUAN BASIN PTNRS
SALE RELDA MAE	SAN JUAN EXPL PTNRS
SALEM OIL LTD PTNRSP	SAN JUAN MINERALS EX

Current BLM Oil and Gas Lessees:

SAN JUAN PROP INC	SANTA FE ENE OPER LP
SAN JUAN RESOURCES INC	SANTA FE ENE RES INC
SAN JUAN-UNOCAL	SANTA FE ENERGY CO
SAN SIMONE RES LLC	SANTA FE ENGRY OPG PRTNR LP
SANCHEZ & O'BRIEN OG	SANTA FE EXPL CO
SANCHEZ ELOY F	SANTA FE INTL CORP
SANCHEZ OIL & GAS CORP	SANTA FE MIN INC
SANCHEZ-O'BRIEN OG	SANTA FE MINS INC
SANDBAR OIL & GAS COMPANY	SANTA FE MNRLS INC
SANDBERG J THEODORE	SANTA FE NATURAL RESOURCES INC
SANDEFER J D III	SANTA FE OP PTNR LP
SANDEL ENERGY INC	SANTA FE PETROLEUM LLC
SANDEL JERRY	SANTA FE PROD CO
SANDEL JERRY W TRST	SANTA FE SNYDER CORP
SANDEL NANCY M	SANTANA INC
SANDEL NANCY M TRST	SANTOS TOG CORP
SANDERER OG INC	SANTOS USA CORP
SANDERS LAURA K	SANZENBACHER W O
SANDERS ROBERT L	SAP ACQUISITION CORP
SANDERS TRUMAN T JR	SAPPINGTON ENE INT LTD
SANDERSON BILLY M	SAPPINGTON ENERGY INTERESTS
SANDERSON DANA	SAPPINGTON JACK L
SANDERSON DUSTY	SAPPINGTON JOHN
SANDERSON GIRVIN H	SARAH B HUGHES TRUST
SANDFLY INC	SARATOGA OIL LTD
SANDLIN OIL CORP	SARATOGA ROYALTY CORP
SANDRA DAVIDSON TRST	SARCO INC
SANDRIDGE ENERGY INC	SARDIS E LLC
SANDRIDGE EXPL & PROD LLC	SARGON INVS ONE LTD
SANDS OIL CO	SARITA ENERGY RESOURCES LTD
SANDS RESERVE CO	SARTOR OLIVER
SANDS-AMERICAN CORP	SASS DONALD B
SANDSTONE ENERGY ACQSTN CORP	SATERDAL AL
SANDSTONE LAND LLC	SATORI INVST SYSTEMS
SANDSTONE OG 1985	SAUER W E
SANDSTONE PROPERTIES LLC	SAUL JAMES W
SANDTANA INC	SAULSBURY C R
SANFORD&SHIRLEY STARMAN TRUST	SAUNDERS WILLIAM W
SANGUINE GAS EXPLORATION LLC	SAUNDERS WOODLAN P
SANGUINE HOLDINGS LLC	SAUTER J RALPH A JR
SANGUINE LTD	SAUVAGE GAS SERVICE
SANNES MARGARET ANN	SAVANNAH EXPLORATION INC
SANNES RONALD M	SAVANNAH OIL & GAS
SANTA FE ENE OP PTSW	SAVANNAH OIL & GAS I LP
SANTA FE ENE OPER	SAVANNAH OIL AND GAS LLC
	SAVANT RESOURCES LLC

Current BLM Oil and Gas Lessees:

SAVOY ENERGY LLC  
SAVOY ENERGY LP  
SAWTELL ISABEL E  
SAWTOOTH OIL CO  
SAWYER PAUL  
SAWYER PAUL F  
SAWYER RICHARD D  
SAXIFRAGE SUMMIT PTNRSHP LLLP  
SAYCO INC  
SAYE OIL COMPANY  
SB BECKLEY & ASSOC  
SBE PTNRS LP  
SBG FOREVER INC  
SBP LTD  
SCA OIL & GAS CO  
SCANA PETRO RES INC  
SCANLON TRUST  
SCARCELLI CARMINE  
SCARLETT ENE ENTERPRISES LLC  
SCENIC MESA RANCH  
SCENIC MESA RANCH LLC  
SCHACHT HERBERT E  
SCHACKELFORD WILBUR  
SCHAFF MARY J  
SCHALK DEV CO  
SCHALK FAMILY TRUST  
SCHALK JOHN E  
SCHALK JOHN T  
SCHALK MARTHA R  
SCHALLA ROBERT A  
SCHATZMAN JOHN R  
SCHEELE WILLIAM E  
SCHELLINGER CARL A  
SCHERBA MARSHAL  
SCHERER JOHN  
SCHERLIN JOHN M  
SCHERTZ MORRIS E  
SCHETTLER PAUL D  
SCHIFF & JACKSON  
SCHIFF EDITH B  
SCHIFF STEVEN S  
SCHILLER BRADLEY R  
SCHINDLER J HOLLIS  
SCHLICHER CAROLYN L  
SCHLICHER FRED J  
SCHLICKEISEN RANCH LLC

SCHMID OILFIELD SERVICES INC  
SCHMID PROP INC  
SCHMID PROPERTIES  
SCHMID W A JR  
SCHMIDT CLAYTON J JR  
SCHMIDT EDMUND J  
SCHMIDT HARRY O  
SCHMIDT INEZ M  
SCHMIDT JOANN  
SCHMIDT PAT J  
SCHMIDT ROBERT  
SCHMIDT VIRGINIA  
SCHMIT WILLIAM H  
SCHMITT CARMEN  
SCHMITT DEBBIE S  
SCHMITZ C J  
SCHNEIDAU KARL  
SCHNEIDER JOHN  
SCHNEIDER N H  
SCHNEIDER OIL CORP  
SCHNEIDER RUSSELL  
SCHNEIDER RUTH  
SCHNEIDER TOM  
SCHOELLKOPF CAROLINE  
SCHOENBERGER C WENDE  
SCHOENBERGER WENDEL  
SCHOENFELD PENINA CHAVA  
SCHOETTLER JOHN H  
SCHOLL R G  
SCHOWALTER TIMOTHY T TRST  
SCHRAMM R RAY  
SCHREFFLER DENNIS  
SCHREUDER LAVINA TRUST  
SCHREUDER LAVINIA TRUST  
SCHROEDER FAM TST  
SCHROTH EDGAR J  
SCHUH & ASSOC INC  
SCHULTHEIS R V  
SCHULTHEIS-WILLIAMS OIL & GAS  
SCHULTS PATRICIA H  
SCHULTZ M SMITHWICK  
SCHULTZ MGMT LTD  
SCHULTZ MGT LTD  
SCHULZE VIRGINIA T  
SCHUMACHER R J  
SCHURICHT KENNETH M

Current BLM Oil and Gas Lessees:

SCHUSTER HOMES INC	SCULLY LEON F JR
SCHUSTER KATHLEEN IRWIN	SCYTHIAN LTD
SCHUSTERMAR CHARLES	SDC RESOURCES INC
SCHUTZ DOUG J	SDH PROPERTIES INC
SCHWARTZ EARL	SDX NATURAL GAS PARTNERS
SCHWARTZ THOMAS A	SDX PROPERTIES INC
SCHWECKE BARBARA	SDX RESOURCES INC
SCHWECKE ESTON	SEA BEE LLC
SCHWED WALTER E (SR)	SEABOARD OIL CO
SCHWINDT MARY TAULE	SEACOAST INC
SCOBOCO INC	SEACOAST OIL & GAS INC
SCOLADO	SEAFIRST AMER CORP
SCOLADO LLC	SEAGULL ENERGY E&P INC
SCOPE EXPL INC	SEAGULL MID-SOUTH
SCOPE INDUSTRIES	SEAGULL OIL CORP
SCOTT 2006 IRREV TRUST	SEAHAWK OIL INTL
SCOTT ALEXIS	SEAL WILLIAM G
SCOTT DAVID L	SEALY H CAVIN INC
SCOTT DOLORES	SEAMAN MARK
SCOTT EXPL INC	SEAMAN ROBERT
SCOTT EXPLORATION INC	SEARS BILL
SCOTT FAMILY TRST	SEARS FAMILY TRUST
SCOTT GEORGE L	SEARS R BONNER
SCOTT GEORGE L III	SEARS RICHARD P
SCOTT GEORGE L JR	SEARS VIRGINIA
SCOTT INVST CORP	SEAY EXPLORATION CO
SCOTT JEFFREY J	SEAY JOHN
SCOTT JOHN E	SEAY JOHN R
SCOTT LUCILLE M	SEBASTIAN RES USA
SCOTT MOLLYANN W	SECAN OIL COMPANY, INC.
SCOTT NICOLE T	SECO ENERGY CORP
SCOTT O V JR	SECONDARY OIL CORP
SCOTT ROBERT H	SECREST DAVE L
SCOTT ROYCE A	SECURITY EXPL INC
SCOTT SHARON W	SECURITY RES CORP
SCOTT WARREN	SECURITY RESOURCES CORP
SCOTT WARREN C	SEDBERRY CAROLYN N
SCOTT WINN LCC	SEDCO ENERGY CORP
SCOUT INVESTMENTS LLP	SEDNA ENERGY INC
SCOUT OIL CO	SEE CASE FILE
SCOW HILDA	SEECO INC
SCR EXPL INC	SEEGERS DRILLING CO
SCROGGIN DONNA	SEEKS PETRO INC
SCROGGIN THOMAS K	SEEL DEV CO LLC
SCRUGGS FRANK A	SEELEY B K JR
SCULLY LEON F	SEELEY OIL CO LLC

Current BLM Oil and Gas Lessees:

SEELIGSON OIL CO	SETHRE LISBETH
SEELY C W	SETTLE CRAIG
SEELY INA B	SEVEN W RESOURCES
SEELY OIL CO	SEVENWAYS VENTURE
SEER ENERGY LLC	SEVENWOOD INC
SEEWALD O KENNETH	SEVERY CHARLES L
SEGERLAND GLEN	SEVIER EXPLORATION LLC
SEGURO O&G INC	SEVIGNEY KATHRYN A
SEIGENTHALER W	SEWELL EUGENE R
SEK OIL & GAS COMPANY LLC	SEXE STACIE M
SELBY BOB I	SEXTON ANGELA
SELIGMAN KEN	SEYMOUR DAVID L
SELL RICK	SEYMOUR OG
SELL STEVE	SFC INC
SELLARS ROBERT T JR	SFD OIL & GAS CO
SELTZER BILL	SFOG INC
SELTZER NATHAN	SFT LLC
SENDERO OIL CO	SG INTERESTS I LTD
SENDERO PETRO INC	SG INTERESTS II LTD
SENECA RES CORP	SG INTERESTS III LTD
SENECA RESOURCES	SG INTERESTS INC
SENECA RESOURCES CORP	SG INTERESTS IV LTD
SENECA WESTERN MINERALS CORP	SG INTERESTS VI LLC
SENECA-UPSHUR PETRO	SG INTERESTS VII LTD
SENIOR CLAIR M	SGH ENTERPRISES INC
SENIOR LILLIAN W	SGH ENTPR INC
SENIOR RAYMOND T	SHACKELFORD BOB L
SENSOR OIL & GAS INC	SHACKELFORD DON G
SENTER ALBERT M JR	SHACKELFORD DONALD G
SENTER CLARIS B	SHACKELFORD OIL CO
SENTRY ENERGY LLC	SHACKELFORD OIL PROPERTIES INC
SEP MONTEZUMA CREEK LLC	SHACKELFORD WILBUR L
SEP ROCKHOUSE LLC	SHADCO
SEP SAND RIDGE LLC	SHAEFFER S B
SEP-RANGELY LLC	SHAFFER HARRIET HEEP
SEP-SEEP RIDGE LLC	SHAHARA OIL CORP
SEQUEL ENE PARTNERS LP	SHAHLAPOUR CALANDRA
SEQUEL ENE PTNRS II LP	SHAKER ENERGY INVESTMENTS
SEQUOYAH RESOURCES PTNRS LP	SHAKESPEARE OIL CO
SERGEANT ANN	SHAKESPEARE OIL CO INC
SERIGSTAD SAM I	SHALOM D B
SERIO BARNETT S	SHALOM ROSALIE
SERVICE CORPORATION INTL	SHAMA ZOE LTD PTNRSH
SES OIL & GAS INC	SHAMBURGER ANNE D
SESNON OIL CO	SHAMBURGER JAMES D
SETHRE EARL	SHAMROCK O&G INC

Current BLM Oil and Gas Lessees:

SHAMROCK OG INC	SHAWVER JOHN C
SHANK SANDRA	SHAWVER MARTHA H
SHANK SANDRA W	SHAW-WOOD VIRGINIA
SHANLEY-MONTARA	SHC-INC LTD PTNRSHP
SHANNON F S	SHEA EDWARD L
SHANNON GLADYS	SHEAR CHARLES A
SHANNON MIN RES INC	SHEAR INC
SHANNON OIL CO	SHEAR WARREN
SHANNON R S (RICHARD STOLL) SR	SHEARMAN THOMAS B
SHANNON WASTE MGMT	SHEARN MICHAEL
SHAPARD GEORGE W	SHEEHAN WILLIAM F
SHAPLEY ROBERT L	SHEEHY & RICHARDSON
SHARBO OIL LTD CO	SHEFFIELD PTNRSHP
SHARBRO OIL LTD CO	SHEFFIELD WARD THOMAS
SHARKTOOTH RESOURCES LTD	SHELBY ACQUISITIONS LLC
SHARON A OLSEN TRST	SHELBY DRILLING INC
SHARON A OLSEN TRUST	SHELBY PROD CO
SHARON OLSEN TRUST	SHELDON ALWEIS
SHARP ALICE	SHELDON VILAS P
SHARP GAIL E	SHELL EVEREST INC
SHARP J R	SHELL GULF OF MEXICO INC
SHARP JAMES L 111	SHELL O&G INV LTD
SHARP JIM L III	SHELL OIL & GAS INVESTMENT
SHARP JOHN	SHELL OIL CO
SHARP KENNETH D	SHELL ONSHORE VENT
SHARP RAYMON NEWTON	SHELL ONSHORE VENTURE
SHARP SEED FARMS LLC	SHELL WESTERN E & P
SHARPE ENE CO	SHELL WESTERN E&P
SHARPE ENERGY CO	SHELL WTN E&P INC
SHARPE GEORGE F	SHELLENBERG THOMAS F
SHARPLES L P	SHELLY ENERGY INC
SHARPLES PHILIP T TRST	SHELRO PETRO CORP
SHARPLES PHILIP T TRUST	SHELTON ELIZABETH
SHAUNA SELTZER REDWINE TRUST	SHELTON MICHAEL V
SHAW ARCH W II TRUST	SHELTON PHOEBE
SHAW BRUCE P TRUST	SHELTON SHARON R
SHAW INTERESTS INC	SHENANDOAH OPER CO LLC
SHAW ISHAM & CO	SHENKER MORRIS A
SHAW JAMES M	SHEPHEN SCOTT
SHAW LYNN	SHEPHERD KENT L
SHAW ROBERT R	SHEPPARD KEITH D
SHAW W C	SHERIDAN CALIFORNIA ENERGY INC
SHAWNEE MISSION EXPLRN LLC	SHERIDAN HOLDING CO I LLC
SHAWNEE OIL & DEV CO	SHERIDAN JOHN F
SHAWVER DON D	SHERIDAN VENTURE CAPITAL LLC
SHAWVER JERRY E	SHERMAN OIL & GAS

Current BLM Oil and Gas Lessees:

SHERMAN ROSELLA H	SIBLEY W R (TREY) III
SHERPERED WARREN	SIDDOWAY EZMA H
SHERRILL MARGARET	SIDDOWAY MARSALE E
SHERRILL MARGARET T	SIDENER GWENDOLYN B
SHIDLER MARK L	SIDENER LAWRENCE
SHIELD DEVELOPMENT CORP	SIDENER MARK R
SHIELDS ENERGY INC	SIDWELL DONALD W
SHIELDS JAMES M	SIDWELL OIL & GAS INC
SHIELDS JOHN P	SIEBEL/SCHREIBER LLC
SHIFFLETT OPER CO	SIEGFUS STANLEY S
SHILLANDER H E	SIEGLER FAMILY TRST NO 1
SHILLINGTON BARBARA STARR	SIEGLER FAMILY TRST NO 2
SHILOH EXPLORATION LLC	SIERCHIO JOSEPH
SHILOH PETRO RES	SIERRA 1996-I LTD PARTNERSHIP
SHILOH PETROLEUM RESOURCES	SIERRA BLANCA OPER
SHIMMIN JOHN R	SIERRA HARRIS 1996
SHINY ONE USA LLC	SIERRA MADRE EXPLORATION LLC
SHIPLEY BETTY	SIERRA PACIFIC LLC
SHIPLEY W W	SIERRA PROD CO
SHIPROCK HELIUM LLC	SIERRA RES INC
SHLENKER B A	SIETE OIL & GAS CORP
SHLENKER S	SIGMAR INC
SHOFF BETTY R	SIGNAL PETROLEUM CO
SHOFF S T	SIGNATURE CONSULTING INC
SHOGOIL & GAS CO II LLC	SIGRID M MARTIN REV TRUST
SHOGOIL & GAS CO LLC	SILBERBERG DANIEL
SHOGRIN FRANK L	SILVER ARTHUR
SHORE ENERGY LLC	SILVER BERNARD
SHORE MARY	SILVER DOE O&G LLC
SHORELINE CO LLC	SILVER DOLLAR RES
SHORELINE ENE PARTNERS LLC	SILVER KING GROUP
SHORES GARY H	SILVER PETROLEUM CORP
SHORT GREG	SILVER ST RES CORP
SHORT MICHAEL A	SILVER TIP ENE LLC
SHORT WILLIAM H JR	SILVERHORN INC
SHRINERS HOSPITAL	SILVERTON PETROLEUM INC
SHUMATE CAROL	SIMBA ENERGY CORP
SHUMATE CLIFTON E	SIMBA ENERGY CORPORA
SHUMATE GENE	SIMKINS LEROY H JR
SHUSTERMAN CHARLES	SIMMONS CHARLES
SIAL EXPL INC	SIMMONS DOROTHY G
SIAN PROPERTIES	SIMMONS MCCARTNEY LLC
SIANA OIL & GAS CO	SIMMONS MELVIN
SIANA OPERATING LLC	SIMON PAT M
SIBBERT ROBERTA	SIMON WILLIAM E
SIBBERT WALTER	SIMONE GREVEY TRUST

Current BLM Oil and Gas Lessees:

SIMPAUG LTD	SKH ENERGY PARTNERS II LP
SIMPSON JAMES JR	SKINNER & ASSOC
SIMPSON JOHN	SKINNER CORP
SIMPSON LARRY R	SKINNER INVESTMENTS
SIMPSON WILLIAM	SKINNER JACK D
SIMS SARA WARD	SKINNER MICHAEL L
SIMSON WILLIAM A	SKINNER OIL & GAS LLC
SIMUNEK STEVE	SKINNERS RES & EXPL
SINBAD PARTNERSHIP	SKLAR ALBERT
SINCLAIR JOHN W	SKLARCO LLC
SINCLAIR O&G	SKOLER SAUL
SINCLAIR OG CO	SKYHAWK PRODUCTION LLC
SINCLAIR OIL & GAS	SKYLINE EXPLORATION LLC
SINCLAIR OIL & GAS COMPANY	SLACK PAUL B
SINCLAIR OIL CORP	SLADE ARCHIE C
SINCLAIR OIL CORPORATION	SLADE BOB
SINCLAIR PHILIP	SLADE JEFF
SINCLAIR WILMA I	SLADE JEFF G
SING WELL SVC CO INC	SLADE KAREN R
SINGER BROTHERS	SLADE KAREN RALSTON
SINGER OIL CO	SLAGEL AMY EST
SINGER VIRGINIA C	SLAGLE ALLEN E
SINGLETON FLORA M	SLASH EXPLORATION LP
SION EXPL INC	SLASH FOUR ENTERPRISES INC
SION EXPLOR INC	SLATE RIVER RESOURCES LLC
SIPPEL FREEMAN LLC	SLAUGHTER J M OIL CO
SIRGO BROTHERS INC	SLAUGHTER ORVILLE S
SIRGO VICTOR J	SLAWSON CHARLES TST
SISBRO OIL & GAS LLC	SLAWSON CRAIG A
SISK FLOY ROSE	SLAWSON DONALD C
SISSON NEIL S	SLAWSON EXPL CO INC
SISTRUNK W E	SLAWSON EXPLORATION CO INC
SITTA RAY	SLAWSON EXPLORATION COMPANY
SIVLEY T J	SLAWSON RES CO
SIVLEY TRUST	SLAWSON RESOURCES CO
SIX AECHES CO	SLAWSON ROBERT TODD
SIX GOLD OIL LLC	SLAY MELVA
SIXJAY ENTERPRISES	SLAYMAKER HAZEL V
SIXTH RIDGE CORP	SLAYTON PAUL
SIZEMORE MELINDA	SLAYTON RESOURCES INC
SIZEMORE WILLIAM C	SLB F L P LTD
SJI JR 1990 TRUST	SLEDGE ROBERT C
SJR ENTERPRISES INC	SLEEPER ELIZABETH S
SKALA HELEN G	SLEEPING BONANZA LLC
SKEES W A	SLEEPING INDIAN RANCH INC
SKELTON BOBBIE O	SLEEPY HOLLOW OG LLC

Current BLM Oil and Gas Lessees:

SLEETER CLARE E	SMITH KENNETH J
SLICK ROCK LP	SMITH LEE A
SLINGERLAND SUSAN F	SMITH LEIGH AUSTIN
SLOAN PETROLEUM INC	SMITH LESTER H
SLOAT BENJAMIN F III	SMITH MAE
SLOGO OIL CO INC	SMITH MARILYN
SLOVER A D	SMITH MARTIN I III
SLOVER RON	SMITH MARVIN L
SLOVER RONALD E	SMITH MARY A
SMENE CO	SMITH MAURICE C
SM ENERGY CO	SMITH MICHAEL K
SM ENERGY COMPANY	SMITH MIGNON C
SMALL GEOSERVICES INC	SMITH NORMAN E
SMALL JAMES R	SMITH OPER & MGT CO
SMITH & MARRS INC	SMITH OPERATING & MGT CO
SMITH ALBERT C	SMITH PATRICIA J
SMITH ALBERT G	SMITH R E
SMITH BEN F TRUSTEE	SMITH R ERNEST TRUST
SMITH C C	SMITH RALPH H
SMITH CHARLES A	SMITH RICHARD C
SMITH COLLIN S	SMITH ROBERT H
SMITH CONLEY P	SMITH ROBERT L
SMITH CYRUS P	SMITH ROBERT L JR
SMITH DAN C	SMITH RODNEY L
SMITH DAVID A	SMITH SARA JANE
SMITH DAVID HARLAN	SMITH SEYMOUR S
SMITH DOUGLAS V	SMITH SHIRLEY
SMITH ED A	SMITH STEPHEN
SMITH EDEL P	SMITH STEPHEN J
SMITH EDGAR E	SMITH STEPHEN O
SMITHENE INVSTS LLC	SMITH SUZANNE E
SMITHENE LTD PTNSHP	SMITH TERRY
SMITH ENERGY INVESTMENTS LLC	SMITH THOMAS R
SMITH FRANK	SMITH VICTOR P
SMITH FRANK A	SMITH W BRETT
SMITH FREDA	SMITH WAYNE J
SMITH FREDERICK L	SMITH WINSTON G
SMITH GLENN J	SMITHBERGER JOHN D
SMITH GREGORY G	SMITHCO PROP INC
SMITH H C TRST #1&2	SMITH-GORDY METHANE
SMITH HOWARD	SMITH-RANGELY PTNSHP
SMITH IRVIN C	SML CREEK LLC
SMITH JAMES G	SMOOT MICHAEL C
SMITH JANET C	SMOOT RICHARD P
SMITH JEFFREY A	SMOOT S CARL
SMITH JORDAN R	SMOOT WENDELL M JR

Current BLM Oil and Gas Lessees:

SMR ENERGY LLC	SOJOURNER DRILLING CORP
SMR NATURAL GAS VENTURES INC	SOL WEST III
SNADEFER OG INC	SOLDOW MARY G
SNAKE OIL CO	SOLEIL KANSAS ENERGY LLC
SND ENERGY ACQ LP	SOLEM WILLIAM M
SNEE & EBERLY	SOLENEX LLC
SNEED DISTRIBUTION I LLC	SOLID ROCK ENERGY
SNEED DISTRIBUTION LLC	SOLIMAR ENERGY LLC
SNELLMAN DONALD L	SOLIS ENERGY LLC
SNELSON STEPHEN W	SOLMONSON D W
SNG PRODUCTION CO	SOLOMON THEODORE
SNODDY SAM H	SOLTEX OIL & GAS INC
SNOW DONALD J	SOMERS II JOHN B
SNOW ELLEN L	SOMERS JOHN B II
SNOW OIL & GAS INC	SOMONT OIL CO INC
SNOW OPERATING CO	SONAT ANADARKO
SNOW OPERATING CO INC	SONAT EXPL CO
SNOW ROBERT D	SONAT EXPLORATION CO
SNOWCAP LIMITED PARTNERSHIP	SONEM PARTNERS LTD
SNOWDEN GEORGE G	SONETEX INC
SNOWDEN JAMES	SONETEX LLC
SNOWDEN JAMES M	SONIC OG LP
SNOWDEN JANET	SONIC OIL & GAS INC
SNOWDY MARK S	SONIC OIL & GAS LP
SNOWMASS ENERGY PARTNERS	SONNERS ORA
SNS OG PROP INC	SONOITA MGT INC
SNUFFY OIL FIELD SVC	SONORA SW PTNRSHP
SNYDER BARRY L	SONORA SW PTRSP
SNYDER JEANNE	SONORIN HOLDINGS LLC
SNYDER KATHERINE	SONORIN II LLC
SNYDER OIL CORP	SONORIN III LLC
SNYDER OPER PTNRSHP	SONORIN IV LLC
SNYDER PETRO CORP	SONORIN LLC
SNYDER PTNRS	SONORIN MANAGEMENT LLC
SNYDER S E	SONORIN V LLC
SOBECK CHARLES	SONOSKY MARVIN
SOBECK NANCY	SONTERRA ENERGY LLC
SOC RESOURCES INC	SONTERRA RESOURCES LP
SOCCORO PROPERTIES LLC	SOOL LTD
SOCHOR LUANN	SOONER OPERATING CO INC
SOCO 81 EXPL & DEV	SORDS GEORGE
SOCO WATTENBERG CORP	SORELLE CARROLL V
SOCORRO PROPERTIES LLC	SORENSEN CO LLC
SOG 1981 LTD	SORENSEN MIKE
SOG INVESTORS LLC	SORENSEN BONNIE J
SOJOURN ENERGY LLC	SORENSEN DAVID J

Current BLM Oil and Gas Lessees:

SORENSEN EVERETT EST	SOUTHWESTERN EAGLE
SORENSEN MAYMIE S	SOUTHWESTERN ENE
SOROCO INC	SOUTHWESTERN ENE PROD CO
SOROCO WELL SVC INC	SOUTHWESTERN ENERGY
SOROS GEORGE	SOUTHWESTERN ENERGY CO
SOURCE ENERGY 1983	SOUTHWESTERN ENERGY PROD CO
SOURCE ENERGY LLC	SOUTHWESTERN EXPL CONSLNTS
SOURCEGAS DISTRIBUTION LLC	INC
SOURCEGAS ENE SVC CO	SOUTHWESTERN RES INC
SOUTH CENTRAL ENTPR	SOUTHWSTRN ENE PROD
SOUTH COAST OIL CORP	SOVEREIGN EAGLE LLC
SOUTH CORBIN LTD	SOVEREIGN INVSTMNTS INC
SOUTH DAK NAT GAS	SOWERS JOHN L
SOUTH HIGHWAY 14 BUS CO	SP JOHNSON III TRUST
SOUTH MOUNTAIN RESOURCES	SPALDING MICHAEL S
SOUTH OIL INC	SPALDING PHILIP H
SOUTH PASS RES INC	SPANN JAY
SOUTH PENN OIL CO	SPANN PAT
SOUTHBRIDGE PROD CO	SPARCO PRODUCING INC
SOUTHEAST ROYALTIES	SPARKS BILL J
SOUTHEASTERN O&G CO	SPARKS DON L
SOUTHEASTERN PETRO	SPARTAN RESOURCES
SOUTHERN BAY ENERGY LLC	SPEAKS MICHAEL
SOUTHERN CA PETRO	SPEAR G W
SOUTHERN CALIFORNIA GAS CO	SPEAR HOWELL
SOUTHERN MANAGEMENT SVCS INC	SPEAR HOWELL R
SOUTHERN PLAINS CORP	SPEAR LAZY S LAND CO
SOUTHERN STATES OIL PROD LLC	SPEARS CATHLEEN
SOUTHERN UNION EXPL	SPEARS DAVID
SOUTHERN UNION GAS	SPEARS HARRELL
SOUTHERN UTE INDIAN TRIBE	SPEARS JONATHAN
SOUTHLAND ROYALTY CO	SPEARS MARTHA
SOUTHPORT EXPL INC	SPECHT CAROL L
SOUTHSIDE O&G LTD	SPECHT RALPH W
SOUTHWEST DATA TECH	SPECKMAN GARY
SOUTHWEST DEV DRLG	SPEC-TECH
SOUTHWEST DRLG SVCS	SPECTRA ENERGY CORP
SOUTHWEST GAS SYSTEM	SPECTRUM ENE INC
SOUTHWEST LAND & PIPELINE CO	SPECTRUM GAS SYSTEMS
SOUTHWEST OG FUND	SPEED INVESTMENT INC
SOUTHWEST OIL & LAND INC	SPEER WILLIAM R
SOUTHWEST PETRO CO	SPEEREX LTD
SOUTHWEST PETRO CORP	SPEEREX LTD PTNRSHP
SOUTHWEST RESERVES	SPELL INC
SOUTHWEST ROYALTIES	SPENCE ACCOUNTS INC
SOUTHWEST ROYALTIES INC	SPENCE ENERGY CO

Current BLM Oil and Gas Lessees:

SPENCE RALPH EST	SQUARE LAKE PTNR LLC
SPENCE RALPH JR	SQUARE LAKE PTNRS
SPENCER ANGELA ESSMAN	SQUARE LAKE PTRNS
SPENCER B E TRUST	SQUIRES BILLY
SPENCER RUSSELL A	SRBI LP
SPENCER SAMUEL S JR	SRBI O&G CO LLC
SPENERGY CORP	SRBI O&G MULTI-STATE LLC
SPERRY EXPL INC	SRBI OG NM LLC
SPESS OIL CO INC	SRBMT OG NM LLC
SPHERE OKLAHOMA INC	SRT TRUST #1
SPIEGEL ROBERT	SRW INC
SPIKE BOX LAND & CATTLE CO INC	SSI OIL & GAS INC
SPINDLETOP DRILLING CO	SSS ENTERPRISES LLC
SPINDLETOP ENERGY LLC	SST ENERGY CORP
SPINDLETOP O&G CO	SSV&H ASSOCIATES
SPINDLETOP OG CO	ST ANSELM 99-A PARTNERS
SPINDLETOP OIL & GAS CO	ST ANSELM EXPL CO
SPIRAL INC	ST CLAIR PEYTON YATES JR
SPIRE INTL CORP	ST CROIX CORP
SPIRE Verna	ST CROIX EXPL CO
SPIRES WILLIAM H	ST CROIX RESOURCES
SPOON VALLEY ENERGY LLC	ST CYR EXPLORATION CO
SPOONER BRENT	ST GEORGE COAL CO
SPOONER ENERGY INC	ST JAMES HIGH SCHOOL
SPOONER HARRY V	ST JOHN INST INV
SPOONER MICHAL	ST JOHNS OPERATING #1 LP
SPOONER PETROLEUM CO	ST MARY ENERGY CO
SPOONER WADE	ST MARY LAND & EXPL
SPORT RESOURCES INC	ST MARY LAND & EXPL CO
SPRADLIN BILLY G	ST MARY LAND & EXPLORATION CO
SPRING CRK RANCH LLC	ST MARY LAND & EXPLRN CO
SPRING CREEK E&P CO LLC	ST MARYS CHURCH
SPRING CREEK RANCH	ST MICHAELS ROMAN
SPRING CRK RANCH LLC	ST OIL COMPANY
SPRING RESOURCES INC	STACEY CALVIN J
SPRING THOMAS L	STACK J E JR
SPRING VALLEY OG INC	STACK J L
SPRINGER LOWELL	STACY DRAYTON
SPRINGER MAYRE	STACY FAMILY TRUST
SPROUSE CLIVE	STADELMAN DIANA L
SPROUSE GARY	STADELMAN JOSEPH R
SPURGIN VIRDA M	STAFSHOLT RUTH E
SPURLOCK & SPINES	STAG OIL PRODUCERS
SPYDE FRED W JR	STAGHORN RES LLC
SPYGLASS CEDAR CREEK LP	STAGHORN RESOURCE
SPYGLASS NSPH, LLC	STAGHORN RESOURCES LLC

Current BLM Oil and Gas Lessees:

STAGNER LEONA	STEAD H W (TRUSTEE)
STAHL SUSAN B	STEADMAN ESTATE
STAINES FRED C	STEALTH ENERGY INC
STALDER TED R	STEALTH ENERGY USA INC
STALEY JACK C	STEARNS JOHN R
STALEY JEAN R	STECHER MICHAEL J
STALLION PANHANDLE 2001 LP	STEED DARRIN
STALLS CLARK F	STEED LEOTA K
STANDARD ENERGY	STEEL HOLDINGS INC
STANDARD ENERGY CORP	STEEL LEONARD
STANDARD PETRO CORP	STEELE GLADYS
STANDARD SILVER CORP	STEELE M H (WARREN)
STANDARD STEEL	STEELE PRODUCTION LLC
STANFORD PETRO INC	STEGER INVESTMENTS LTD
STANICH JEFFREY L SR	STEHLE CARY L
STANLEY ENERGY INC	STEHLE PRODUCTION CO
STANLEY ENERGY W INC	STEIN KERRY W
STANLEY JESSIE R	STEIN SYDNEY JR
STANOLIND OG CO	STEINBERG ASSOC 1977
STANS MAURICE	STEINBERGER GEORGE
STAPLETON ELIZABETH	STEINBERGER STEPHEN
STAPLETON SAM P	STEINBERGER TIMOTHY
STAPP D SCOTT	STEINERT BARBARA A
STAPP ROBERT MICHAEL	STELARON INC
STAPP ROBERT W	STELBAR ENERGY CO
STAR ACQUIS III LLC	STELBAR OIL CORP INC
STAR OF TEXAS ENERGY SVC INC	STELL LEONARD
STAR PROD INC	STELLIOS EXPLORATION COMPANY
STAR PRODUCTION INC	STENDAL BERTHA
STARCK JOHN A	STENSKE DAVID
STARDUST LEASING INC	STENSKE LYNN
STARK FAMILY LTD	STEPHEN HAGER ESTATE
STARK JANET GALE	STEPHEN SMITH INC
STARKEY ERNEST JR	STEPHENS & JOHNSON OPER CO
STARKEY ERNEST JR	STEPHENS A G
STARKEY ERNEST JR	STEPHENS AUTRY C
STARKEY ERNEST JR	STEPHENS DANIEL G
STARKEY ERNEST JR	STEPHENS DANNY
STARKEY ERNEST JR	STEPHENS ENE CO LLC
STARKEY ERNEST JR	STEPHENS ENERGY CO LLC
STARKEY ERNEST JR	STEPHENS ENERGY COMPANY LLC
STARKEY ERNEST JR	STEPHENS EXPL INC
STARKEY ERNEST JR	STEPHENS HARRY R
STARKEY ERNEST JR	STEPHENS LOUISE
STARKEY ERNEST JR	STEPHENS N JR
STARKEY ERNEST JR	STEPHENS PROD CO

Current BLM Oil and Gas Lessees:

STEPHENS PRODUCTION CO	STILLINGS MARK W
STEPHENS RICHARD E	STILLWATER INVESTMENTS
STEPHENS TOM P	STINSON BRIDGET
STEPHENSON DONNAN	STINSON RES DEV TRST
STEPHENSON JOE	STINSON SHANE
STERLING EVELYN H	STIPE GENE
STERLING OIL OF OK	STIRTON DAVID L
STERLING THEODORE K	STIVASON JAMES R
STETTNER ROD	STOABS OIL CORP
STEVE CARTER INC	STOABS VIRGIL
STEVE FRANKAMP TRUST	STOABS VIRGIL L
STEVEN & KATHY KELLENAERS	STOCK WALTER F
TRUS	STOCKDALE OIL & GAS
STEVEN S TUROFF TRST	STOCKER ROBERT A
STEVEN W HORN & ASSOC INC	STOCKER STAN
STEVENS & CO INC	STOCKGROWERS TRUST
STEVENS & JOHNSON	STOCKMAN OIL INC
STEVENS & TULL DEVELOPMENT LTD	STOCKMEYER CAROLYN C
STEVENS BOB	STOCKTON JAMES M
STEVENS CURTIS	STODDARD CHARLES JR
STEVENS DONALD G	STODDARD DENNIS
STEVENS H J JR TRUST #8136	STODDARD JAMES M
STEVENS NORMAN L III	STODDARD JEFFREY A
STEVENS NORMAN L JR	STODDARD JOSEPH E JR
STEVENS OIL & GAS	STODDARD JOYCE
STEVENS RESOURCES	STOFAM LTD
STEVENS REVOCABLE TRUST	STOLZENBACH ROBERT D
STEVENS VERNON	STONE & WOLF LLC
STEVENSON EDWARD R	STONE CAROL A
STEVENSON JACK J	STONE CREEK EXPL CO
STEVENSON L C EST	STONE DAVID CHARLES
STEVENSON LELAND JR	STONE DEBORAH KIM
STEWART GEOLOGICAL INC	STONE ELIZABETH
STEWART J M	STONE ENE CORP
STEWART PETROLEUM CORP	STONE ENERGY CORP
STHRN CA PUB PWR AUTH BURBANK	STONE ENERGY CORPORATION
STHRN CA PUB PWR AUTH ANAHEIM	STONE EXPL INC
STHRN CA PUB PWR AUTH COLTON	STONE JAMES A
STHRN CA PUB PWR AUTH GLENDALE	STONE JAMES H
STHRN CA PUB PWR AUTH PASADENA	STONE JUDSON
STICKLEY DORIS	STONE JUDSON F
STIDGER WILLIS	STONE OIL CO
STILES WILLIAM E JR	STONE RAYMOND G
	STONE SANDRA J
	STONE SARA MICHELLE
	STONE WILLIAM F JR

Current BLM Oil and Gas Lessees:

STONEBRIDGE OPERATING CO LLC	STRINGER O&G CO
STONEGATE RESOURCES LLC	STRINGHAM U/D/T TR
STONEHAVEN RESOURCES INC	STRIPER OIL INC
STONEHOCKER W L	STRIPPER OPERATOR'S INC
STONELEIGH INV LTD	STROEHER H GLENN
STONESTREET HARDEMAN	STROM RUTH G
STONETEX OIL CORP	STRONG DOROTHY JUNE
STORM CAT ENE (POWDER RVR) LLC	STRONG JOE E
STORM CAT ENERGY (USA) CORP	STRONG ROBINSON G
STORM RICHARD P	STRONG ST CLAIR G
STOTT STANLEY & BEVERLY TRST	STROOCK THOMAS F
STOUT ENERGY INC	STRUB ROBERT P
STOUT MERLE E	STRUCK ERVIN T ESTATE OF
STOVALL B J	STRUTHERS OG CORP
STOVALL ENERGY LTD	STUART DANIEL B
STOVALL INVESTMENTS INC	STUART DOUGLAS R
STOVALL NORMAN D JR	STUART JOHN
STOVALL OIL CO	STUART ROBERT D JR
STRACHAN EXPL INC	STUBBS BRUCE A
STRAIN DARRELL L	STUBER EDWARD
STRAIN STEVE	STUBER EDWARD A
STRAIN WARREN EST	STUDENT CONSRV ASSOC
STRAKE GEORGE W JR	STUMHOFFER C W
STRANAHAN LTD PRTNRS	STUMHOFFER ELLA
STRANAHAN MARY E T	STUMHOFFER F T
STRAND SHERMAN O	STZ PETRO INC
STRANG JOHN P	SUBSURFACE INVESTMENTS LP
STRANGE PROPERTIES LLC	SUCHORS W W
STRATA OIL & GAS COMPANY LLC	SUDDUTH CANDACE L
STRATA PRODUCTION CO	SUDDUTH LAURA E
STRATCO OPERATING CO INC	SUDDUTH MARION L
STRATEX LP	SUDDUTH RICHARD A JR
STRAUS LEE J	SUDLOW ROY
STREET E BRUCE JR	SUDNERLAND E S
STREET M BOYD	SUEX CORP
STREET SPENCER B JR	SULIMAR LP
STREICH ETHEL BENSON	SULLIVAN ART
STREICH HERMAN M	SULLIVAN E J
STREICH R C	SULLIVAN GERALD T
STRICKLER CNTY LINE LP	SULLIVAN NANO
STRICKLER WILLIAM J	SULLIVAN PHYLLIS A
STRICKLIN & CO	SULPHUR CREEK ROYALTY
STRICKLING JOE	SULPHUR RIVER EXPL
STRIDER OIL CO	SULTAN ISAAC
STRIDER RESOURCES CO	SUMATRA OIL CORP
STRINGER JOINT VENT	SUMATRA OIL INC

Current BLM Oil and Gas Lessees:

SUMMERHILL PROPERTIES INC	SUNSET INTERNATIONAL
SUMMERS EXPL CO	SUNSET PROP LTD
SUMMERS R L	SUNSET WELL SERVICE INC
SUMMIT DRLG FLUIDS	SUNSHINE VALLEY PETRO CORP
SUMMIT ENERGY COMPANY LLC	SUNTERRA PETRO LLC
SUMMIT ENERGY LLC	SUNVALLEY ENERGY CORP
SUMMIT ENERGY PARTNERS 3 LLC	SUNWEST BANK OF ALBQ
SUMMIT ENERGY RESRC LLC	SUN-WEST OIL & GAS INC
SUMMIT ENGRY PRTNR GRND GAS	SUNWEST PETROLEUM CO
SUMMIT ENRGY PRTNR SAND RDG	SUNWEST RES LTD
SUMMIT EXPLO LLC	SUPERIOR OIL CO
SUMMIT OVERSEAS EXPL	SUPREME PETRO US CORP
SUMMIT PARTNERS LLC	SURF OIL & GAS INC
SUMMIT PETRO CORP	SURGE GLOBAL ENERGY INC
SUMMIT PETROLEUM INC	SURGENT DEVON
SUMMIT RES INC	SURGENT JIM
SUMMIT RESOURCES	SURKALO CAROL DEE
SUMMIT RESOURCES INC	SURKALO HARRY
SUMMITT VENTURES INC	SURKO JOHN J
SUMPF BYPASS TRUST	SURVANT JOHN
SUN CAL ENERGY INC	SURVANT JOHN F
SUN CEMENTING OF WY	SURVIVOR O&G CO
SUN DELTA INC	SURYA PETROLEUM
SUN EXPL & PROD CO	SUSAN K CLAY TRUST
SUN INDUSTRIES INC	SUSAN L LITTLE TRUST
SUN OIL CO	SUSANNE SHAW TRUST
SUN OPER LTD PRTS	SUTHERLAND FAMLY LLC
SUN OPERATING LTD	SUTTER WILLIAM P
SUN VALLEY ENERGY CORP	SUTTLES FRANK
SUNBEHM GAS INC	SUTTON HOWARD E
SUNBIRD ENGINEERING	SUTTON R
SUNBURST EXPL INC	S-W CO
SUNBURST RES INC	SW COMM INCOME-DRILL
SUNCOR ENE NAT GAS AMERICA INC	SW CROSBY III
SUNDANCE ENE INC	SW DEV DRLG 93
SUNDANCE ENERGY INC	SW DEV DRLG FUND 92A
SUNDANCE RESOURCES LLC	SW ESPERO INC
SUNDERLAND E S	SW EXPL & PROD LLC
SUNDERLAND JACK B	SW OIL & GAS INCOME
SUNDOWN ENE INC	SW ROYALTIES 1987-1
SUNDOWN ENERGY LP	SW ROYALTIES INC
SUN-KEY OIL CO	SWANCO RESOURCES
SUNLAND RFNG CORP	SWANEY KATHERINE A
SUNLITE INTL INC	SWANK DAVID L III
SUNRISE ENERGY PTNRS	SWANSON DEAN A
SUNSET ELI ESTATE	SWANSON ENERGY COMPANY LLC

Current BLM Oil and Gas Lessees:

SWANSON PRODUCTION CO LLC	T & R HOWARD TRUST
SWANSON STEVEN J	T A CHORNEY EXPL CO INC
SWANSON TOM E	T BAR S OIL INC
SWANSON VIRGIL M	T BOB AMTHOR CO
SWARTZ FAMILY TRUST	T BROWN INC
SWARTZ JACOB	T C CRAIGHEAD & CO
SWEATT CONSTRUCTION INC	T C CRAIGHEAD & COMPANY
SWEENEY BARBARA B	T C ENERGY LLC
SWEENEY BARBARA B TRUST	T E DUFF TRUST
SWEET CRAMONA TRUST	T E F CORP
SWEET MARY	T F STROOCK TRUST
SWEET REAGAN	T H MCELVAIN O & G LTD PTNRSHP
SWEETMAN R K	T H MCELVAIN O&G LP
SWEETWATER DRLG EXPL	T H MCELVAIN OG LTD PTNRSHP
SWEETWATER REVOCABLE TRST	T H MCELVAIN OIL & GAS LP
SWENCO WESTERN INC	T K CAMPBELL II
SWENDSEID FAMILY TRUST	T K PRODUCTION CO
SWEPI LP	T O MONCRIEF TRUST
SWEPI LP. SWEPI LP	T R PARKER ESTATE
SWERER DAVID G	T R PARKER TRUST
SWERER RICHARD R	T REX INC
SWETT DAVID W	T S DUDLEY LAND CO INC
SWIDERSKI TED J	T S DUDLEY LAND COMPANY INC
SWIFT ENERGY CO	T SHELDON-SHOFF TRST
SWIFT ENERGY OPERATING LLC	T V MCMAHAN TRUST
SWIG ESTATE	T W PHILLIPS G&O CO
SWIG INVESTMENT CO	T&F EXPLORATION
SWO PETROLEUM INC	T&G ENERGY LLC
SWTN ENE PROD CO	TABER PHIL
SYDSON ENERGY INC	TAC RESOURCES INC
SYDTRAN LP	TACK OPERATING
SYENERGY OPERATING LLC	TACONIC CORP
SYLVAN DAVID R	TADPOLE OIL & GAS
SYLVIA F LITTLE TRST	TAG TEAM RESOURCES
SYLVIA F LITTLE TTEE	TAHOE ENERGY INC
SYLVIA L LITTLE TRST	TAHOE OIL & CATTLE
SYLVIA LITTLE TRSTEE	TAHOSA HOLDING LLC
SYND OIL & GAS ASSN	TAK MOUNTAIN LLC
SYNDER JAMES D	TAK WELL ONE
SYNDER OIL CO	TALADRO RESOURCES INC
SYNERGY CORP	TALBOT A G
SYNERGY EXPL CO	TALBOT CHARLES
SYNERGY OPERATING LLC	TALBOTT ANITA
SYNERGY RESOURCES CORP	TALBOTT STACY
SZYMANSKI MAUREEN	TALENTO BARBARA N
T & E INVESTMENTS	TALICH BRENT

Current BLM Oil and Gas Lessees:

TALISMAN ENERGY USA INC	TAUBMAN LOUIS
TALKINGTON J T	TAUBMAN M B
TALLGRASS ENERGY LLC	TAUBMAN M I
TALUS INC	TAUBMAN ROBERT M
TALUS PROPERTIES LTD	TAUBMAN ROSALIE S
TAMMEN H H MRS	TAUBMAN RUTHE S
TAMPICO TRADING GROUP LTD	TAUREN EXPL INC
TANA OIL & GAS CORP	TAURUS EXPL INC
TANBERG SCOTT W	TAYLOE/TAYLOE JR TRUST ESTATE
TANDEM ENERGY CORP	TAYLOR ANN H
TANDEM OIL CO	TAYLOR BARBARA B
TANDY ANNE B ESTATE	TAYLOR BETTY JUNE
TANGO PETRO CO	TAYLOR BILL G JR
TANKERSLEY A L	TAYLOR BRETT G
TANKERSLEY TERESA J	TAYLOR CECIL E
TANNER G H	TAYLOR EDWARD P
TAOKA GEORGE	TAYLOR ERIC T
TAP ENERGY INC	TAYLOR EUNICE B
TAPOIL INC	TAYLOR FRED W
TAQA NORTH USA INC	TAYLOR HARVEY R
TARA - JON CORP	TAYLOR HELEN
TARA ENE INC	TAYLOR JAMES A
TARA ENERGY INC	TAYLOR JAMES R
TARA JON CORP	TAYLOR JUNE
TARA-JON CORP	TAYLOR KELLY M
TAREX INC	TAYLOR MARVIN E
TARGE ENE EXPL & PROD LLC	TAYLOR NEAL A ESTATE
TARGET DRILLING CO	TAYLOR RAY R
TARH E & P HOLDINGS LP	TAYLOR REUBEN C JR
TARPON ENGINEERING CORP	TAYLOR SIDNEY S
TARPON OIL CO	TAYLOR WELL OPER INC
TARVER WILLIAM BLAKE	TBA PETROLEUM
TAS ROYALTY CO	T-BAR O&G LTD OF CO
TASHLEIN CHRISTOPHER	T-BAR X LIMITED CO
TATANKA RESOURCES LLC	TBIRD LC
TATE JON P	TBN EXPL INC
TATEX ENERGY	TBN EXPLO INC
TATONKA OIL & GAS CO LLC	TC CRAIGHEAD
TATONKA OIL & GAS INC	TC CRAIGHEAD & CO
TATUM TOM	TC CRAIGHEAD CO
TAU VENTURES	TC OPER LLC
TAUBER EXPL & PROD	TCBG LTD
TAUBERT J E	TDB RESOURCES LP
TAUBMAN CHARLES	T-DO LLC
TAUBMAN JANICE	TDT RESOURCES INC
TAUBMAN L	TEAGUE HARRY

Current BLM Oil and Gas Lessees:

TEAPOT OIL & REFINING CO	TESELLE ROGER D
TECHNICAL ENE SVC	TESTAMENTARY TRUST
TECOVAS PARTNERS III LP	TETON DJCO LLC
TECOVAS PARTNERS II LP	TETON RESOURCES USA LLC
TECOVAS PARTNERS LLP	TETRA OIL CO
TECTON ENE LLC	TETUAN RESOURCES CORP
TEDRICK JOHN R	TEX/CON OIL & GAS CO
TEECOMP INC	TEXACAL OG INC
TEEL MARY NELL REED	TEXACO EXPL & PROD
TEEL R GARY	TEXACO INC
TEETER G HOWARD	TEXACO PRODUCING INC
TEG OIL AND GAS USA INC	TEXAKOMA EXPL & PROD LLC
TEIKOKU OIL USA CO	TEXAKOTA OIL CO
TEIXEIRA OIL & GAS LP	TEXAS AMER RESOURCES CO
TEJAS RESOURCES INC	TEXAS AMERICAN RES HLDNGS LLC
TEKXON ONSHORE OG LLC	TEXAS CRUDE ENERGY INC
TELEDYNE IND INC	TEXAS EASTERN TRANS
TELLUS OPERATION GROUP LLC	TEXAS ENE SUPPLY INC
TELLAG LLC	TEXAS ENERGY SUPPLY INC
TEMPE LTD PTNRSHP	TEXAS INTL OIL CO
TEMPLE PETER G	TEXAS INTL PETRO CORP
TEMPO ENERGY INC	TEXAS KEYSTONE INC
TENDY MANAGEMENT LLC	TEXAS MINERAL TRST
TENEXCO INC	TEXAS PACIFIC OIL CO
TENISON OIL CO	TEXAS PETRO PTNRS
TENKAY RESOURCES INC	TEXAS PETROLEUM INVESTMENT CO
TENNANT L L	TEXAS REEXPLORATION LTD 01
TENNANT WALTER	TEXAS REFINING & EXPL LP
TENNECO OIL CO	TEXAS REPUBLIC ENE
TENNIN ROBERT P	TEXAS ROALTIES
TENNISON ALMA	TEXAS STANDARD OIL CO
TENNISON CALVIN	TEXAS VANGUARD OIL CO
TENSION OIL CO	TEXLAND PETROLEUM LP
TE-RAY ENERGY INC	TEXLAND PETROLEUM HOBBS LLC
TE-RAY RESOURCES INC	TEXLAND PETROLEUM-HOBBS LLC
TERLINGUA OIL ASSOC	TEXOIL INTL CORP
TERMAC OIL & GAS LLC	TEX-OK ENERGY LP
TERMO CO	TEX-OK OIL PROD INC
TERMO CO THE	TEXOMA OIL TOOLS INC
TERRA ENERGY LTD	TEXON ENERGY CORP
TERRA RESOURCES	TEXONA ACQUIRED CO
TERRA RESOURCES INC	TEXONA ACQUISITION
TERRELL DAVID K	TEXONA ASSOC LTD
TERRY ALVIN L JR	TEXONA PETROLEUM CORP
TERRY ORLYN	TEX-SPEC VENTURES
TESELLE EXPL & PROD CO	TEXTANA INC

Current BLM Oil and Gas Lessees:

TEXTANA USA	THE RSG TRUST
TFS TRUST	THE RUDMAN PTNRSHP
TH MCELVAIN O&G LTD	THE SALVATION ARMY
THACKER MICHAEL M	THE SATER FAMILY PTNRSHP LP
THAMES JOSEPH W	THE SHAW TRUST
THAMES RIVER LLC	THE SOUTHEAST AL GAS DIST
THAREL CARMEN	THE TERMO CO
THAREL T L	THE TINMIL A NM LTD CO
THE STARMAN 1991 REV TRUST	THE TOLES CO
THE ALLAR CO	THE TUSKET WEDGE CO
THE ALLAR COMPANY	THE TX CO
THE ARMSTRONG CORP	THE WECHAL CO
THE ASTON FAMILY LP	THE WISER OIL CO
THE ASTON PTNRSHP	THE WOODWARD GROUP
THE BEARD CO	THELMA F SIMMONS EST
THE BETELGEUSE TRUST	THELMA GUNGOLL TRUST
THE BETTYE JEAN SALMON TRUST	THELMA KEMP TRUST
THE BLANCO CO	TERESA M LYNN EST
THE BLANCO COMPANY	THIEGS BERNARD J
THE BROOKS TRUST	THIEGS FRANCIS J
THE COOLEY TRUST	THIEGS RICHARD T
THE DAKOTA GAS CO LLC	THOMA J
THE DANIELS CORP	THOMAS A HEWEL TRUST
THE EASTLAND OIL CO	THOMAS D S ET AL
THE EL DORADO REFINING	THOMAS DAVE M JR
THE FOURTH NATIONAL BANK	THOMAS DM & BL TRST
THE FRANK M HENRY REV LIV TRST	THOMAS DOROUGH TRST
THE GRANATELLI TRST	THOMAS FAMILY LIMITED PTNR
THE GRAY EXPLORATION CO	THOMAS FAMILY LP
THE HOUSTON EXPLO CO	THOMAS FAMILY LTD PRTNRSHP
THE JC WILLIAMSON FAMILY TRUST	THOMAS FELIX BOLACK REV TRST
THE JOY PARTNERS LTD	THOMAS GLEN E
THE KMC TRUST	THOMAS HANLY
THE LEONARD TRUST	THOMAS J KAREN TR
THE MARKER TRUST	THOMAS JEFF
THE MOORE TRUST	THOMAS JOHN C
THE NATURE CONSERVANCY	THOMAS L MOODY EST
THE NEW MEXICO CO INC	THOMAS LINNA RAE U
THE NINETY-SIX CORP	THOMAS LORA JANE
THE PETE & KAY GIFFORD TRUST	THOMAS LTD
THE PETRO SYNERGY	THOMAS M BOYD TRUST
THE PETROLEUM SYNERGY GROUP	THOMAS MARILYN J EST
THE PROSPECTIVE INVSTMNT CO	THOMAS MAX L
THE RIVER GAS CORPORATION	THOMAS N BERRY & CO
THE ROCK INVESTMENT GROUP INC	THOMAS OIL & GAS LLC
THE ROGER T ELLIOT FAMILY LP	THOMAS OPER CO INC

Current BLM Oil and Gas Lessees:

THOMAS OPERATING CO INC	THOMPSON R N
THOMAS P PIKE OPER	THOMPSON RANDALL C
THOMAS PROD CO LLC	THOMPSON SAMUEL G
THOMAS PROD LLC	THOMPSON SAMUEL GLEN
THOMAS R BARR TRUSTE	THOMPSON VICTORIA F
THOMAS ROSE M	THORNBROUGH ALBERT
THOMAS T SANDERS EST	THORNBURY P L
THOMAS T SANDERS ESTATE	THORNE JOAN
THOMAS W CALLINAN REVOC TRST	THORNHILL J E
THOMAS W HOLLEY TRST	THORNTON OPER CORP
THOMAS WILLIAM S	THORNTON VIRGINIA
THOMASSON PARTNER ASSOC	THORNWOOD GAS INC
THOMASSON PARTNER ASSOC INC	THOROFARE RESOURCES INC
THOMASSON PTNR ASSOC	THORP MARCIE
THOME GREG R	THORP MICHAEL R
THOMPS0N CLEO J	THORP OIL AND GAS LLC
THOMPSON BARBARA	THORP RICHARD L
THOMPSON BROS VENT LLC	THORSEN DAN F
THOMPSON CHRISTINE	THRASH JAMES
THOMPSON CLEO J	THRASH JAMES LLOYD
THOMPSON CLEO J JR	THRASH VESTA
THOMPSON CLEO J SR	THREE FORKS ENE PARTNERS LLC
THOMPSON CLYDE R	THREE FORKS RESOURCES LLC
THOMPSON DIANE	THREE LAIN CORP
THOMPSON DIANE TRST	THREE M OIL CO
THOMPSON E CRAIG	THREE M OIL COMPANY
THOMPSON ENGINEERING	THREE RIVERS ACQUISITION LLC
THOMPSON ENGINERRING	THREE SPAN OIL AND GAS
THOMPSON FRANCES	THREE STATE WELL SVC
THOMPSON GLENN E	THREE STATES OIL CO
THOMPSON GRADY	THRESHOLD DEVELOPMENT CO
THOMPSON J C	THROCKMORTON DOROTHY ANN
THOMPSON J CLEO	THROCKMORTON TERRY
THOMPSON J CLEO & J CLEO JR LP	THROCKMORTON TIM N
THOMPSON J CLEO & JR	THRU LINE INC
THOMPSON J CLEO SR	THRU LINE LP
THOMPSON J T	THRU LINE O&G CO LLC
THOMPSON JAMES CLEO JR	THRU LINE O&G MULTI-STATE LLC
THOMPSON JAMES CLEO JR LP	THRU LINE OG NM LLC
THOMPSON JAMES JR	THUNDER HILL EXPLORATION LLC
THOMPSON L W	THUNDER RES LLC
THOMPSON MARJORIE B	THUNDER RESOURCES
THOMPSON MARJORIE G	THUNDERBIRD ENERGY INC
THOMPSON MARK F	THUNDERBIRD MGT LTD
THOMPSON PAUL C	THUNDERBOLD PETRO
THOMPSON PETROLEUM CORP	THUNDERBOLT PETRO

Current BLM Oil and Gas Lessees:

THUNDERBOLT PETROLEUM INC	TIPTON RAY
THURSTON DOUGLAS J	TITAN ENERGY RESOURCES
THURSTON ENERGY LLC	TITAN OIL CO
THURSTON FAMILY TRST	TITAN OIL INC
THURSTON JENNIFER J	TITAN RESOURCES LTD
THURSTON MARK P	TITUS CONSULTING INC
THURSTON RUTH ANNA	TJ & 4K PARTNERSHIP
THURSTON STEPHEN P	TJ QUINLIN FAMILY LLC
THURSTON WILLIAM R	TK OPERATING
THURSTON WM R TRST	T-K PROD CO
TIBBET BERTON M III	T-K PRODUCTION CO
TIBBET NANCY E	TKL OIL PROP INC
TICE RUN OIL & GAS CO	TKM RES LLC
TIDE WATER ASSOCIATED OIL CO	TKM RESOURCES LLC
TIDELANDS ENERGY CO	TLAPEK JOHN W
TIDEMARK CORP	TLW INVESTMENTS LLC
TIDEWATER OG CO LLC	TMBR/SHARP DRILLING INC
TIDEWATER OIL & GAS CO	TOBIN OIL CO
TIDEWATER OIL & GAS CO LLC	TOBON GILBERT H
TIDEWATER OIL AND GAS CO LLC	TOC - ROCKY MTNS INC
TIDEWATER OIL CO	TOC ROCKY MOUNTAINS
TIDEWATER OIL COMPANY	TOC ROCKY MTNS INC
TIERNAY GRACE	TOCE ANDRE F
TIERNEY MARGARET	TOCE OIL CO INC
TIERRA OIL CO	TOC-MID-CONTINENT INC
TIERRA OIL CO LLC	TOC-ROCKY MTN INC
TIERRA POBRE LLC	TOC-ROCKY MTNS INC
TIFFANY GAS CO	TODD CECILLE B
TIGER OIL CO	TODD DEBRA K
TILLETT W C	TODD HARRY L JR
TIM HOWARD TRST	TODD MARY ANNE
TIMBERLINE PROD CO LLC	TODD RAYMOND L
TIMBERLINE PRODUCTION CO LLC	TODD THOMAS E JR
TIMCO INVESTMENTS	TODD TOMMY T
TIMOTHY M DOHENY INC	TODD WANDA A
TINKER MIKE A	TOGA PETRO CORP
TINNIN FAMILY PROPERTIES X LLC	TOGA PETROLEUM
TINNIN ROBERT P	TOGA PETROLEUM CORP
TINNIN THOMAS P	TOINTON BRYAN E
TINSLEY MEREDITH K	TOINTON ROBERT G
TIPOR RESOURCES OG	TOINTON WILLIAM I
TIPPERARY O&G CORP	TOJAC MINERALS
TIPPERARY OG CORP	TOKLAN O&G CORP
TIPPIT JOHN H	TOKLAN OG CORP
TIPTON DWIGHT A	TOKLAN OIL & GAS CORP
TIPTON OIL & GAS ACQUISITIONS	TOLEDO MINING CO

Current BLM Oil and Gas Lessees:

TOLES CYNTHIA	TR ENERGY INC
TOLES ED H III	T-R OG INC
TOLES JOHN H	TR OPERATING LLC
TOLES NOVALENE B	TRACER ENE INC
TOLES PENROD J	TRACHYTE OIL CO
TOLES SALLY S	TRACY DRILLING CO
TOLTEK DRILLING CO	TRACY FRANCIS G III
TOM BOYD DRILLING CO	TRADE EXPLORATION CORP
TOM BROWN INC	TRAIL ENERGY LLC
TOM O MONCRIEF 1967 TRST	TRAIL MOUNTAIN INC
TOM O MONCRIEF 1967 TRUST	TRAINE INC
TOM P STEPHENS TRUST	TRAINER C W
TOM R CONE TRUSTEE	TRAINER JACKIE
TOM R NORRIS TRUST	TRAINER MICHAEL SHEA
TOMAHAWK OIL CO INC	TRAINER PARTNERS LP
TOMPKINS THOMAS J	TRAINER PARTNERS LTD
TOMSCO ENERGY	TRAINER RANDLL MARK
TONI ROSEN TRUST	TRAINER TERRI JAN
TONKA OIL & GAS PROD INC	TRAMMELL ESTATE
TOOKE WALTER P	TRAMMELL MILDRED M
TOOLE WALKER EXPL	TRANS ATLANTIC PETRO
TOP BRASS OIL PROPERTIES INC	TRANS ENERGY INC
TOPAT OIL CORP	TRANS REPUBLIC ENE
TOPAZ MINERALOGICAL	TRANSCONTINENTAL OIL
TOPCAT ENERGY LLC	TRANSFUEL RES CO
TOPPER RESOURCES LC	TRANSFUEL RESOURCES CO
TORA OIL & GAS	TRANSGLOBE OIL & GAS CORP
TORCH O&G CO	TRANSREPUBLIC RESOURCES LTD
TORCH OIL & GAS CO	TRAVCO RESOURCES LLC
TORCH OPERATING CO	TRAVIS CAROLE A
TOREADOR ACQUISITION CORP	TRAVIS DEPREST L J
TOREADOR EXPL & PROD	TRAVIS LAWRENCE
TOREADOR EXPL & PROD INC	TRAVIS OIL CO
TOREADOR RLTY CORP	TRAVIS STEVEN S
TORGERSON M JEAN	TRAVIS WILLIAM J
TORGERSON RONALD K	TRAYLOR WILHELMINA B
TORKELSON FRANCES	TRB PETROLEUM
TOTAL E&P USA INC	TREALMIN & CO
TOTENBERG NINA	TREASURE RESOURCES INC
TOURMALINE EXPL CO	TRENCHARD JOHN HUGHES
TOURTELLOTTE CARLA L	TREND EXPL I LLC
TOWER OPERATING CO	TREND EXPL LLC #1
TOWNE WILLIAM S	TREND OIL CO
TOWNSEND CHARLES C	TRENDWELL WEST INC
TOWNSEND DONALD	TREVIZO PAUL
TOWNSEND LUCIA W	TREW CHRIS

Current BLM Oil and Gas Lessees:

TRI POWER RES INC	TRIPOWER RESOURCES INC
TRI STAR ENE CORP	TRIPOWER RESOURCES LLC
TRI STAR INC	TRI-POWER RESRCS INC
TRIANA ENERGY LEASES INC	TRISEARCH
TRIANGLE PETROLEUM CORPORATION	TRI-SERVICE DRILLING
TRIBO PROD CO LTD	TRITEX ENERGY A LP
TRICONTINENTAL RES	TRITEX ENERGY LLC
TRICOR ENERGY LLC	TRITEX PROD CO
T'RIDE LLC	TRITON ENERGY CORP
TRIDENT OIL & GAS LLC	TRITON O&G CORP
TRIDENT OIL CORP	TRNCO PETRO CORP
TRIDENT USA CORP	TROBAUGH MELBA Y
TRIDIMENSION ENERGY LP	TROBAUGH PROPERTIES
TRI-EX DEV CO	TROLLINGER SHARON
TRIGG BILLIE M	TROLLINGER-MARSH RESRCS
TRIGG CONROW LLC	TROMPETER EMANUEL
TRIGG DRLG CO INC	TROMPETER SYLVIA
TRIGG JOHN H	TRONCO ENERGY CORP
TRIGG OG LTD PTNRSHP	TROOP MARCIA A
TRIGG OIL & GAS LP	TROOPER OIL & GAS LLC
TRIGG OIL LLC	TROPPMANN MARGARET S
TRIGG RALPH S JR	TROUSDALE DALE M
TRIGG VENTURE NOM	TROUSDALE MARGUERITE
TRILOGY OPERATING INC	TROUSDALE PAUL W
TRILON OIL CO INC	TROUSIL & ASSOC INC
TRIMBLE JAMES C	TROUT KYE JR
TRIMBLE PROPERTIES	TROYER PAMELA L
TRINACA INVST CORP	TRUBE HEIDI
TRINITY ENERGY ASSOC INC	TRUE NORTH ENERGY CORP
TRINITY INDUSTRIES	TRUE OIL CO
TRINITY LTD PTNRSHP	TRUE OIL LLC
TRINITY LTD PTRSHP	TRUE RICHARD L
TRINITY RESOURCES INC	TRUEBLOOD HARRY A JR
TRINITY RESOURCES LLC	TRUEBLOOD RES INC
TRIO OIL CO	TRUETTNER JAMES III
TRIO PETROLEUM INC	TRUETTNER JAMES W
TRIO PRODUCTION CO LLC	TRUJILLO ANN M
TRIPCO INC	TRUJILLO IRENE
TRIPLE B LTD PRTNRSHP 1998B	TRUJILLO LAND SERVICES
TRIPLE C EXPL LLC	TRUJILLO ROSITA S
TRIPLE J OIL & GAS LLC	TRUST A
TRIPLE T RESOURCES LP	TRUST B
TRIPLE W EXPLORATION INC	TRUST C
TRIPPLETT LARRY W	TRUST FOR GARLAND L AVERA
TRIPOR RES OG FUND	TRUST Q
	TRUST Q PEGGY A YATES DEC

Current BLM Oil and Gas Lessees:

TRYTHALL JAMES H	TURTLE MTN G&O INC
TRYTHALL JEANETTE M	TUSKET WEDGE TRADING
TRZ ENE LLC	TUTHILL & BARBEE
TSAR ENERGY LLC	TUTHILL KEITH S
TSAR ENERGY WV LLC	TVEDT C R
TSC OIL & GAS INC	TVEDT PATRICIA
TUARUS EXPL USA INC	TW OG EXPL LLC
TUCK BYRON J	TWENTY O FIVE CORP
TUCKER ALAN	TWENTY-O-FIVE CORP
TUCKER FAMILY INVESTMENTS LLLP	TWENTY-TWENTY OIL & GAS INC
TUCKER FRED E JR	TWIFORD FOREST
TUCKER INVESTMENT	TWILIGHT RESOURCES LLC
TUCKER R LEE	TWIN ARROW
TUCKER VICKI	TWIN ARROW INC
TUFTS O&G II LP	TWIN BRIDGES RESOURCES LLC
TULIPAN LLC	TWIN CITY TECHNICAL LLC
TULL DOUG	TWIN EAGLE PETRO CO
TUMBLEWEED EXPL LLC	TWIN EAGLE PETROLEUM
TUMBLEWEED OIL & GAS LLC	TWIN M INC
TUMBLING JASPER G	TWIN MONTANA INC
TUNDRA RESOURCES LLC	TWODUBYAH LLC
TURBO EXPL INC	TX & NM EXPL LLC
TURLOCK IRRIGATION DISTRICT	TX & NM INC
TURNBOW DUANE	TX AMERICAN OIL CORP
TURNCO INC	TX COMMERCE BANK
TURNER CHARLES R	TX ENERGY SUPPLY INC
TURNER CLINT W	TX INDEP EXPL INC
TURNER DAVID	TX INDEPENDENT EXPL
TURNER FRED	TX INTL PETRO
TURNER FRED E	TX PACIFIC CORP
TURNER GLENN JR	TX PACIFIC OIL CO
TURNER J GLENN JR	TX VANGUARD OIL CO
TURNER JOHN L	TX-CON OIL & GAS CO
TURNER JOHN LEE	TXO PRODUCTION CORP
TURNER MARY FRANCES JR	TX-OK ENERGY LTD
TURNER PETRO LAND	TXP OPERATING CO
TURNER PETROLEUM LAND SVCS INC	TYL OIL
TURNER RESOURCES INC	TYL OIL AND GAS
TURNER WANDA W	TYLER CHARLES D
TURNKEY PIPELINE CO	TYLER M S
TURNLEY EARL R	TYLER N A
TURNPIKE OIL CO	TYLER NEIL A JR
TURPIN JACK A	TYLER OIL COMPANY
TURRENTINE DAVID	TYLER ROCKIES EXPLORATION LTD
TURRENTINE OIL & GAS	TYREX OIL CO
	U A HUNTER TRUST

Current BLM Oil and Gas Lessees:

U D DONALDSON TRUST	UNITED OIL CORP
U S ENERCORP LTD	UNITED OIL CORPORATION
UDESEN ROBERT JR	UNITED PIPE & SUPPLY
UFFORD DONALD BRUCE	UNITED RES 86-A DEV
UFFORD RON	UNITED RESOURCES LP
UFFORD RONALD DALE	UNITED SHORES INC
UGGS ENERGY LLC	UNITED TRANS-WTN INC
UHC NEW MEXICO CORP	UNITED UTILITIES CORP
UHREN WILFRED P	UNITED WESTERN EXPL LLC
UINTA OIL & GAS INC	UNIV RESOURCES HLDGS
UINTAH MGMT CORP	UNIVERSAL DRLG FLUID
ULM GENEVA KEITH	UNIVERSAL EXPL
ULTERRA TECHNOLOGIES	UNIVERSAL EXPL OPTNG CO INC
ULTIMATE EXPL & DEV	UNIVERSAL FUELS CO
ULTRA RESOURCES INC	UNIVERSAL RES CORP
UMPTY UMP COMPANY	UNIVERSITY OF TX
UNDERWOOD CARL D	UNIVERSITY OF WY-GEOLGY DEPT
UNDERWOOD D W	UNKNOWN
UNDERWOOD E D	UNRUH D DEAN
UNDERWOOD ELIZABETH	UNRUH DEAN
UNICON PRODUCING CO	UOS ENERGY LLC
UNICON PRODUCTION CO	UPC HOLDING CORP
UNICORN DRILLING INC	UPDIKE BROTHERS INC
UNIFIED ASSESTS LTD	UPHAM FREDERICK M SR
UNIFIED ASSETS LTD	UPLAND EXPLORATION INC
UNION BANK	UPLAND PRODUCTION CO
UNION DRILLING INC	UPLAND RESOURCES INC
UNION OIL CO	UPSIDE LLC
UNION OIL CO OF CA	UPSON TODD M
UNION PACIFIC OG CO	UPTON RES USA INC
UNION PACIFIC RES CO	UPTON RESOURCES USA INC
UNION PACIFIC RES GROUP INC	URBAN ANN MARIE
UNION SEABOARD CORP	URBAN PAUL
UNION TEXAS PETRO CORP	URSA RES GP LLC
UNION TX PETRO CORP	US BANK OF GRAND JUNCTION
UNIONVILLE ROYALTY CO LLC	US BORAX & CHEM CORP
UNIT DRLG & EXPL CO	US CANADA LP
UNIT FOUR PTNRSHP	US CANADA LTD PTNR
UNIT PETRO CO	US CAPITAL ENERGY
UNIT PETROLEUM CO	US GASCO INC
UNITED BANK OF GRAND JCT TRUST	US MARSHALL
UNITED DRILLING CO	US MIN & ROYALTY
UNITED DRILLING INC	US NATURAL GAS CO
UNITED ENERGY CORPORATION	US OIL & GAS INC
UNITED GAS SEARCH	US OPERATING INC
UNITED NATIONAL BANK	US ORE CORPORATION

Current BLM Oil and Gas Lessees:

US RES INC	VAN RYAN LAWRENCE O
US RESOURCES INC	VAN SWOL NOEL
US SMELTING REFINING	VANCE KENNETH M
US STEEL CORP	VANDEN BROECK CLAUDE
USA EXPLOR & PRODUCTION LLC	VANDENBROECK MAY C
USZYNSKI BRUCE J	VANDERHOEF RONALD D
UTAH NORTHERN WASATCH LP	VANDERSLICE JEAN F
UTAH OIL & GAS RESOURCES LLC	VANDERSLICE PETRO
UTE PROD CO	VANDERVOORT INVST CORP
UTI ENERGY CORP	VANDERVORT DOROTHY
UTON DIVIDE LLC	VANDERVORT GAYLE A
UTTER DELBERT RAY	VANDERVORT GLADYS M
UTTER JAMES ROSS	VANDERVORT LONNA G
UTTER MYRTLE	VANDERVORT W C EST
UV INDUSTRIES INC	VANDEVEER JAMES W
V A ISAACS JR LLC	VANDIVER JAMES
V A JOHNSTON TRUST	VANDIVER SCOTT
V E FAULCONER INC	VANGUARD O&G INC
V F NEUHAUS PROP INC	VANGUARD RES INC
V F PETRO INC	VANITALLIE H F
VA GAS CO	VANLANDINGHAM MARY ANN
VA RESOURCES LLC	VANSCOY EDWARD
VAGG ETHEL A	VANSON PRODUCTION CORP
VAGG FRANCES A	VANTAGE ENERGY PICEANCE LLC
VAGG JO ANN	VANTAGE ENERGY UNTA LLC
VAILE PILAR	VANTAGE TUBULARS
VALE & CO	VANTERRA ENERGY INC
VALENCE OPER CO	VAQUERO ENERGY INC
VALENTIS OK ENERGY LLC	VAQUERO PARTNERS I LP
VALHALLA NAT RES LLC	VAREL DANIEL W
VALIANT EXPLORATION LLC	VARHUS DANIEL V
VALIOSO PETRO CO INC	VARN ROBERT M
VALKO LLC	VARNA OIL CORP
VALLECITO GAS LLC	VARNER JAMES B
VALLEY OIL & GAS CO	VARNER THOMAS A
VALLEY VIEW ENERGY	VARNER WILLIAM V
VALUE PETROLEUM INC	VASKOV LINDA
VAN ARSDALE B E	VASKOV MILAN
VAN DUYNE ROSALIE	VASSILOPOULOS SPRIOS G
VAN FOSSEN GARY R	VASTAR RESOURCES INC
VAN FOSSEN GORDON W	VAUGHAN DANIEL EST
VAN HEEMST ANNA	VAUGHAN E M
VAN ITALLIE H F	VAUGHEY & VAUGHEY
VAN METER BAYLOR JR	VAUGHEY W M JR
VAN METER GEOSCIENCES INC	VAUGHEY W M JR EST
VAN RYAN BARBARA A	VAUGHEY, VAUGHEY & BLACKBURN

Current BLM Oil and Gas Lessees:

VAUGHN PETRO INC	VERNON R DRWENSKI EST OF
VAUGHN PETRO ROYALTY PRTS LTD	VERNON ROBERT P
VAUGHT GEORGE G JR	VERNON ROBERT P 1994
VAVREK JERRY	VERONDA GEORGE R
VAWDREY DWAYNE	VERRETT WAYNE
VAYDIK FRANK W	VERRY MARK
VECO DRILLING INC	VERRY ROBERT
VECTA OG LTD	VESENMEIR LEO JR
VECTA OIL & GAS LTD	VESS OIL CORP
VECTA OIL AND GAS LTD	VESSELS COAL GAS INC
VECTOR ENERGY CO	VESSELS O&G CO
VECTOR MINERALS CORP	VESSELS OIL & GAS CO
VECTOR RES LLC	VESSELS TOM
VEDDER FAM PTNRSHP	VESTMAN JOHN M
VEDDER WINIFRED M	VESTMAN KEITH E
VEGAS PROD CO	VESTMAN VICTOR T
VEGAS PRODUCTION CO	VETERAN EXPL INC
VEIRS DANIEL L	V-F EXPL CO II
VENADA NATIONAL	VF NEUHAUS PROP INC
VENESKY GEORGE J	VF NEUHAUS PROPERTIES INC
VENGHIATTIS CHRIS	V-F PETROLEUM INC
VENOCO INC	VIA CORONAE PARTNERS LTD
VENOCO LLC	VICON INC
VENTANA ENERGY LLC	VICTEX INC
VENTANA EXPL INC	VICTORIA EXPL INC
VENTANA MINERALS LLC	VICTORIA TRADING CO LLC
VENTEX OIL AND GAS PROPERTIES	VICTORY OIL CO
VENTORA CORP	VIDLER WATER CO INC
VENTURE DRILLING CO	VIERSEN & COCHRAN
VENTURE RES 1986 GP	VIERSEN OG CO
VENTURE ROYALTIES	VIERSEN OIL & GAS CO
VEON FRANCES G	VIERSON OIL & GAS CO
VEON HELEN J	VIKING EXPLORATION LLC
VEON JOHN E	VIKING INT VIRCO INC
VEON PHILLIP R	VIKING INTERNATIONAL RESOURCES
VEON STEVEN T	VIKING OG CO
VEON THOMAS M	VIKING OG EXPL CO
VEON WILLIAM R	VIKING PETROLEUM
VERDAD O&G CORP	VIKING RES CORP
VERDAD OIL & GAS CORP	VIKING RESOURCE CORP
VERDE VISTA ENE CO	VIKING RESOURCES CORP
VERITAS 321 ENERGY PARTNERS LP	VILLETTÉ MARGARET R
VERN JONES OIL & GAS CORP	VINCE ALLEN MU 80 PROG LTD
VERNAL WEST DRILLING	VINCELETTE RICHARD R
VERNON E FAULCONER INC	VINCENT DUNCAN TRST
VERNON FAULCONER INC	VINCENT J DUNCAN TRUST

Current BLM Oil and Gas Lessees:

VINCENT JOSEPH DUNCAN TR	VROOM REVOCABLE TRUST
VINCERO RESOURCES LTD	VROOMAN DONNA J
VINEY RALPH H	VROOMAN ENERGY LLC
VINING FRANCIS	VROOMAN OTTO
VINSEL LINDSAY M	VSW2 EXPL & PROD LLC
VINSON OIL CO	VTOC ENERGY INC
VINSON OIL CO TRUST	VUJOVICH GREG
VINTAGE DRILLING CO LLC	VUKSIC JAMES S
VINTAGE LEASE SERVICES LLC	VUKSICH JENNIE WARD
VINTAGE PETRO INC	W & A WHEELER TRST
VINTAGE PETROLEUM	W & W OIL INC
VINTAGE PETROLEUM LLC	W A KRAMER TRUST
VINTAGE PRODUCTION CALIFORNIA	W A MONCRIEF EST
VIOLA PROD INC	W A MONCRIEF III TR
VIRG TODD TRUST	W A MONCRIEF JR TRST
VIRGINIA A DESMOND TRUST	W A MONCRIEF TRST
VIRGINIA M. GOODEN	W A POUNDS ESTATE
VIRO & CO	W B OSBORN JR TRST
VISION ENERGY INC	W B OSBORN O&G OPER
VISION RESOURCES LLC	W B OSBORN OG OPER
VISTA ENERGY LLC	W C MCCAMMON TRUSTEE
VISTA EXPLORATION LLC	W C NEAL TRUSTEE
VISTA RESOURCES PARNTERS LP	W C ROBERTSON TRUST
VISTA VERDE ENERGY CO	W C SEMPLE INVSTMNT
VISTICA BONNIE G	W CLIFTON ARBUCKLE TRST
VITAL ENE INC	W CLIFTON ARBUCKLE TRUST
VITAL ENERGY INC	W D ANDERSON & SONS
VITRUVIAN EXPL LLC	W D OIL & GAS NM LLC
VITRUVIAN EXPLORATION LLC	W D PARTNERS LP
VLS O&G LTD PTRNSHP	W E ROBERTSON EST
VML RESOURCES INC	W G PARKER TRUSTEE
VOGLER ED	W H HUNT TRUST ESTATE
VOIGT MARY DOUGHERTY	W H TAYLOR HEIRS
VOLA VALE HORST FAMILY TRUST	W J SWEATT
VOLANT MINERALS INC	W K ARBUCKLE TRUST
VOLKER JAMES J	W K LAND CO
VOLKMANN ROBERT G	W L GRAY & CO
VON DREHLE WILLIAM F	W L MORRIS REVOCABLE TRUST
VOORHEES CAROLYN JO	W O PRODUCTION INC
VOORHIES S S TRUSTEE	W O WILSON TRST
VORTEX PETROLEUM INC	W P KENDALL TRST
VOTAW KATHERYN	W P PROPERTIES CORP
VOYAGER EXPLORATION INC	W PALMER DIXON EST
VOYAGER OIL & GAS	W R BRENT EST
VOYLES MARIE M	W T BOYLE & CO
VRAME GEORGE	W T CHUMNEY TRUST

Current BLM Oil and Gas Lessees:

W TIMBERS PTNRSHP	WALKER J MORT JR
W WHEELER TRST	WALKER JACK V
W&T OFFSHORE INC	WALKER JAMES L
W2 LTD	WALKER JOEL
WAB INC	WALKER JOYCE
WACKER OIL INC	WALKER MELBA
WACO LLC	WALKER O&G CORP
WADE ENERGY CORP	WALKER OG CORP
WADE JAMES E	WALKER PAUL
WADE KENNETH R	WALKER REX ROSS
WADE LORRAINE G	WALKER ROBERT R
WADE MARIE	WALKER VALORIE F
WADE PETROLEUM CORP	WALKER VALORIE TRST
WADE REV TRUST	WALKER-BUCKLER TRUST
WADE THOMAS MALCOLM	WALKING X INC
WADI PETRO INC	WALL ST FINANCIAL
WADI PETROLEUM INC	WALL ST FINANCIAL CORP
WAGER MINERAL TRUST	WALLA OMER E ESTATE
WAGGONER EXPL INC	WALLACE JAMES B
WAGGONER JOE	WALLACE JAMES C
WAGNER & BROWN LTD	WALLACE JOHN
WAGNER & COCHRAN INC	WALLACE WILLIAM
WAGNER BRYAN C	WALLER BROTHERS INC
WAGNER CARYL JEAN	WALLER THOMAS J
WAGNER DUER III	WALLER WILLIAM L SR
WAGNER DUER III	WALLFAM LTD
WAGNER DUER JR	WALLIS HAL B
WAGNER OIL CO	WALLIS JAMES
WAGNER STEPHANIE ANN	WALLIS WILLIAM B
WAGSTAFF MARJORIE M LVNG TRST	WALLS A G
WAINOCO O&G CO	WALSH F HOWARD JR
WAINOCO OIL & GAS CO	WALSH MARY D
WAITE PATRICIA E	WALSH MICHAEL H
WAKEFIELD LYMAN E JR REV TRST	WALSH SUZANNE
WALBERT CHARLES R	WALSH TRUST
WALDFOGEL MORTON S	WALTER ARBUCKLE TR
WALE HERBERT E III	WALTER ARBUCKLE TRUST
WALFORD PANSY LONG	WALTER BLACK WARRIOR BASIN
WALISZEK NANCY J TRUSTEE	WALTER DUNCAN ESTATE
WALKER C DANIEL	WALTER DUNCAN OIL
WALKER CAROL N	WALTER DUNCAN OIL LP
WALKER DANIEL C	WALTER DUNCAN OIL LTD
WALKER EDNA	WALTER FAWCETT EST
WALKER HUNTINGTON	WALTER K ARBUCKLE TRST
WALKER HUNTINGTON T	WALTER K ARBUCKLE TRUST
WALKER J D	WALTER M BENSON TRST

Current BLM Oil and Gas Lessees:

WALTER OIL & GAS CORP	WARREN DAVID M
WALTER S FEES INTERVIVOS TR #1	WARREN ENTERPRISES
WALTER S FEES JR & SON O&G LLC	WARREN EXPL & PROD INC
WALTER S FEES JR & SON OG LLC	WARREN INC
WALTER S FEES JR TRUST #1	WARREN JACK
WALTON JAMES A	WARREN JAY TRUST
WALTON OIL CO LLC	WARREN KENDALL TRST
WALTON PAUL T	WARREN P KENDALL TR
WAMCO I LTD	WARREN PAUL O
WAMSUTTER GAS PARTNERS LLC	WARREN PETROLEUM CO
WANDA WALSH TRST	WARREN RESOURCES INC
WANGER ETTA L	WARREN T CLARK TRUST
WANGER HENRY F	WARREN VENTURES LTD
WAPITI OIL & GAS LLC	WARRINGTON MARY J
WARD BARBARA L	WASATCH GAS DEVELOPMENT
WARD ELMER A	WASATCH OIL & GAS LLC
WARD L O	WASHAKIE ENERGIES CO
WARD LAKE ENERGY INC	WASHAKIE OIL CO
WARD MYRA B	WASHBURN LEE
WARD PETRO CORP	WASHINGTON LUCY D
WARD PETROLEUM CORP	WASHINGTON LUCY INC
WARD STEPHEN S	WASHUTA STEVEN N
WARD WILLISTON CO	WASP CO
WARD X LLC	WASSON EDWARD B
WARD/X LTD PTNESHP	WASZAK CHRISTIE E
WARE HERBERT E III	WATERFORD ENERGY INC
WARE HERBERT E JR EST OF	WATERHOUSE BRUCE
WARE HERBERT E JR ESTATE OF	WATERS D H
WARE HOUSE INDUSTRIES INC	WATERS ROBERT B
WARE OIL & GAS INC	WATKINS H VAUGHAN JR
WAR-GAL LLC	WATSON JOSEPH J
WARING ROBERT W	WATSON KATHARINE
WARNE BONNIE B	WATSON OG PROPERTIES LLC
WARNE JOHN R	WATSON ROBERT H
WARNICK ALYSON	WATSON ST LP
WARNICK MARY K	WATSON VERNON R
WARNICK PHILLIP	WATSON W R MD EST
WARNICK SHANNON L	WATSON WILLIAM H
WARNICK-HUBBARK TRUST	WATTERS CHALMER ETAL
WARREN ALVAH D	WATTS BILL
WARREN ALVAH J	WATTS LEE
WARREN AMERICAN OIL	WATTS RANDY V
WARREN AMERICAN OIL CO	WAVERLY EXPL LTD PTR
WARREN ASSOCIATES	WAYNE OIL & GAS 1988
WARREN CLARK ESTATE	WAYTE ROSEMARY FLINT
WARREN CLARK TRUST	WBA COLORADO CO

Current BLM Oil and Gas Lessees:

WBH OIL ASSOCIATES  
WBI PRODUCTION INC  
WCB INVESTMENTS LLC  
WD O&G NM LLC  
WD OG NM LLC  
WDE OIL PROPERTIES  
WEANT JERRY A  
WEATHERLY A D  
WEAVER BEVERLY PARKER  
WEBB ALICE JANE  
WEBB CHARLES R  
WEBB DEL ESTATE  
WEBB MAX D  
WEBB RESOURCES INC  
WEBB RODNEY D  
WEBB WILLIAM  
WEBB WILLIAM G  
WEBER F PALMER  
WEBER LAWRENCE  
WEBRE J F  
WEBSTER F F  
WECHES EXPLORATION INC  
WECKBACHER GERALD G  
WEDLOCK ROBERT  
WEDLOCK RUTHIE  
WEED OG  
WEED OIL & GAS  
WEED OIL & GAS CO  
WEED OIL & GAS COMPANY LC  
WEEKEND CYCLIST LLC  
WEHRLE H B JR  
WEHRLY PATSY  
WEIDERHOFFER INV INC  
WEIDLER J J  
WEIDLER MARK E  
WEIDLER TRUST  
WEIG FAMILY TRUST  
WEIG FAMILY TRUST 90  
WEIGEL RAYMOND J  
WEILERT MICHAEL  
WEIMER INC  
WEINBERG RICHARD E  
WEINER CHARLES  
WEINER DILLARD DIANE  
WEINER MARY DON  
WEINER OIL PROP TST

WEINER PATRICIA ANN  
WEINER TED  
WEINGARTEN REUBEN  
WEINKAUF PETRO INC  
WEINMANN JOHN G  
WEINSZ OIL AND GAS INC  
WEISE CARLTON P  
WEISER-BROWN OIL CO  
WEISER-BROWN OPER CO  
WEISS ROBERT J JR  
WEISS TRUST  
WEK DRILLING CO INC  
WELCH DANA L  
WELCH DAVID J  
WELCH MARIAN C  
WELDON ASTON  
WELLBORN CHARLES I  
WELLCO ENERGY INC  
WELLER & SONS PARTNERS LP  
WELLING DALE R  
WELLINGTON OPERATING  
WELLMAN ARTHUR  
WELLMAN ARTHUR O  
WELLS BIRA M  
WELLS DONNELL O  
WELLS FARGO BANK SD & CA  
WELLS FARGO BANK, TRUSTEE  
WELLS FRANK G  
WELLS PETR CORP  
WELLS PETRO INC  
WELLS PETROLEUM INC  
WELLS RES INC  
WELLS S STICKLE TRST  
WELLSTAR CORP  
WELSCH STEVEN P  
WELSH OIL CO INC  
WELTER L 83 TRUST  
WENDELL W IVERSON TRUSTEE  
WENDMAR OIL CO  
WENDY KAEUPER LLC 1  
WENDY KAEUPER LLC 2  
WENK JOHN A  
WENTLAND ROSE MARIE  
WENTWORTH OPERATING CO  
WENTWORTH STEVEN D  
WENTZ OIL CO LLC

Current BLM Oil and Gas Lessees:

WENTZ PROD LLC	WESTALL MYRTLE TRUST
WENZEL LAWRENCE W	WESTALL OIL & GAS CO LLC
WEPCO ENE 1985 DRILLING PROG	WESTALL OIL & GAS LLC
WEPCO ENERGY 1984	WESTALL RAY
WERINGER RAYMOND SCOTT	WESTAR ENERGY & RES
WERME DOUGLAS R	WESTAR OIL & MINERAL
WERNER OIL INC	WESTBROOK OIL CORP
WERNTZ BILLIE S	WESTBROOK RONNIE H
WES STATE LANDS	WESTBROOK V H
WES STATE LANDS INC	WESTCO FAMILY LTD PRTNRSHP
WES TEX DRILLING CO LP	WESTCO INVESTMENTS
WESCO OPERATING INC	WESTECH ENERGY CORP
WESGRA CORP	WESTERBERG RICHARD E
WESLEY HILL WISENBAKER TRUST	WESTERLY EXPL INC
WESPAC ENERGY LLC	WESTERLY EXPL INC
WESSCO INC	WESTERLY EXPLORATION INC
WESSELY ENERGY CO	WESTERN AMER EXPL CO
WESSON 1990 WI ACQ	WESTERN AMER RES LLC
WESSON 1990-WI ACQ	WESTERN AMER RESOURCES LLC
WESSON 1992-WI ACQ	WESTERN AMERICAN RESOURCES LLC
WESSON ENERGY CORP	WESTERN ENERGY RESOURCES INC
WEST AMERICAN ENERGY CORP	WESTERN ENERGY RESRC
WEST BAY EXPLORATION CO	WESTERN EXPL LTD
WEST BAY INVST INC	WESTERN FARMERS ELEC
WEST BAY O&G CORP	WESTERN GAS RES INC
WEST COAST LAND SERVICE	WESTERN GAS RESOURCES INC
WEST ENERGY LLC	WESTERN GATE LP
WEST GAP LLC	WESTERN GENERAL INC
WEST GORDON T	WESTERN GOLD'N GAS
WEST J F	WESTERN HYDROCARBONS LLC
WEST J F ESTATE	WESTERN INDEPENDENT
WEST J H	WESTERN INDEPENDENT OIL
WEST LARGO CORP	WESTERN INTERIOR ENE
WEST PLAINS ENE CO	WESTERN INTERIOR O&G CORP
WEST REBEKAH S	WESTERN INTERIOR RES
WEST ROUNDUP RESOURCES INC	WESTERN NAT GAS
WEST SABINE LLC	WESTERN NAT GAS CPTAL
WEST SOL III	WESTERN NATURAL GAS
WEST STAR O&G INC	WESTERN OG DEV CORP
WEST SUSSEX ROYALTIES LLC	WESTERN OIL & MIN
WEST TEXAS GAS INC	WESTERN OIL CO
WEST TREND RES CORP	WESTERN OIL PROD INC
WEST W E JR	WESTERN OIL PRODUCER
WESTALL FAMILY OIL PROP LLC	WESTERN OPER CO
WESTALL FAMILY TRUST	WESTERN PRODUCTION CO
WESTALL MYRTLE M	

Current BLM Oil and Gas Lessees:

WESTERN RES INC  
WESTERN RES OIL CO  
WESTERN RESERVES OIL  
WESTERN ROALTIES  
WESTERN ROALTY CORP  
WESTERN STATES INTERNATIONAL  
WESTERN WELLSITE SVCS LLC  
WES-TEX DRILLING CO LP  
WES-TEX DRLG CO  
WESTLAND CHARTER LLC  
WESTLAND OIL DEV  
WESTLAND OIL DEV CO  
WESTLAND PROD CO INC  
WESTMAN HARRIET G  
WESTMORELAND TODD E  
WESTPHAL OIL&GAS INC  
WESTPORT O&G CO LP  
WESTPORT OIL & GAS CO INC  
WESTPORT OIL & GAS CO LP  
WESTPORT OIL AND GAS CO LP  
WESTSTAR OG INC  
WESTWATER JOINT VENTURE  
WESTWATER TRUSTEES  
WESTWAY PETRO  
WESTWAY PETRO FOUR  
WESTWAY PETRO FOUR A  
WESTWAY PETRO THREE  
WESTWAY PETROLEUM  
WESTWOOD ENERGY INC  
WESTWOOD LAKE VILLAGE INC  
WETTENKAMP ANDREA L  
WETZLER EVELYN DOROTHY  
WEXPRO CO  
WEXPRO COMPANY  
WEYMAN WILLIAM R  
WF WYNN & SB WYNN CO-TRUSTEES  
WFD OIL CORP  
WHARTON OIL CO  
WHC EXPL LLC  
WHEATLAND OIL INC  
WHEELER C MARK  
WHEELER EDITH C  
WHEELER FREDDIE J  
WHEELER MARION N  
WHEELER PATRICIA  
WHEELER W RIDLEY EST

WHELESS TDL EXPLORAT  
WHITACRE ENTERPRISES INC  
WHITAKER PAUL W  
WHITAKER TERRENCE M  
WHITCOMB HARRY S  
WHITE EAGLE EXP INC  
WHITE EAGLE EXPLORATION  
WHITE EDGAR W  
WHITE EDNA M  
WHITE ELIZABETH TRST  
WHITE ERIC A  
WHITE FRED C  
WHITE GEORGE R  
WHITE HORSEBRUSH LLC  
WHITE INVEST INC  
WHITE J P  
WHITE J PHELPS III  
WHITE JOHN K  
WHITE JUDITH A  
WHITE LARRY J  
WHITE MELISSA  
WHITE PERRY  
WHITE PHELPS J III  
WHITE PHILIP L  
WHITE PHILLIP L  
WHITE PHLEPS J  
WHITE T ALAN  
WHITE TED M  
WHITE TIGER LTD PTNRSHP  
WHITE VINCENT L  
WHITE WALLACE M SR  
WHITEAKER DOROTHY  
WHITEHEAD MERRILL III  
WHITEHEAD WILL F  
WHITETAIL SERVICES  
WHITFORD CYNTHIA C  
WHITING 1988 PROD  
WHITING OG CORP  
WHITING OIL & GAS CORP  
WHITING OIL AND GAS CORP  
WHITING PETRO CORP  
WHITING-GOLDEN GAS PROD CO  
WHITING-PARK PROD  
WHITLEY & CO  
WHITLEY CAROL C  
WHITLOW D W EST

Current BLM Oil and Gas Lessees:

WHITMAN LUCIA PIEK	WILBUR D WILSON REVOCABLE TRST
WHITMAN OIL&GAS CORP	WILBUR E MCMURTRY LLC
WHITMAR EXPL CO	WILBUR WILLIAM F
WHITMAR EXPLORATION	WILCARD FAMILY LTD
WHITMAR EXPLORATION CO	WILCO PROPERTIES INC
WHITMAR EXPLORATION COMPANY	WILCOX ENERGY CO
WHITMORE BETTY R	WILCOX NATURAL FUELS LLC
WHITMORE JOHN D EST	WILCOX SWANSON LLC
WHITNEY BARBARA L	WILD BRUSH ENERGY INC
WHITNEY H MARVIN REVOCABLE TR	WILDCARD FAMILY LP
WHITT JUDY E	WILDCARD FAMILY LTD
WHITTEMORE PATRICIA	WILDCARD LTD
WHITTEN TRUST	WILDCARD O&G CO
WHITTIER ENERGY CO	WILDCARD OIL & GAS CO
WHITTINGTON ADA D	WILDCAT ENERGY DEVELOPMENT
WHITTINGTON JOHN D	LLC
WHITWORTH ENE RES	WILDCAT ENERGY LLC
WICHITA PROD PTNRS	WILDFIRE PARTNERS
WICHITA RIVER OIL	WILDFIRE PARTNERS INC
WICKHAM ELDON	WILDHORSE EXPL
WIDE OPEN SPACES	WILDHORSE RESOURCES LLC
WIDENMANN HANS A	WILDROSE RESOURCES
WIDNER KEVIN L	WILEY GARY N
WIELAND CAROLYN R	WILEY W S
WIEPKING FULLERTON ENERGY LLC	WILFRED WHEELER TRST
WIEPKING-FULLERTON	WILHITE I J
WIESE G	WILKE LTD CO
WIESE GENE	WILKEN HUBERT T
WIESE SALLE W	WILKERSON ALLEN W
WIESENFELD FAMILY LP	WILKERSON ENE CORP
WIGGINS CHARLES R	WILKERSON RALPH R
WIGGINS MAX	WILKES JEAN E EST
WIGGO LLP	WILKINS C HOWARD
WIGHT JOHN	WILKINSON C H JR
WIGLEY JOEL M	WILKINSON CHARLES
WIGZELL H B	WILKINSON DORIS JEAN
WIKERT ALINA H	WILKINSON JOEL
WILBANKS ACQUISITIONS I LLC	WILKINSON RESOURCES INC
WILBANKS ACQUISITIONS II LLC	WILKS RANCH MONTANA LTD
WILBANKS BRUCE A	WILL DRILL RES INC
WILBANKS FAMILY LTD	WILLAM A HUDSON II
WILBANKS FMLY PTNRS	WILLARD BILLY M
WILBANKS G L	WILLARD DAVID
WILBANKS RES CORP	WILLARD JEFFREY S
WILBANKS RESERVE CORP	WILLARD ROBERT W
WILBANKSI BRUCE A	WILLE JACQUELINE B

Current BLM Oil and Gas Lessees:

WILLETT H L	WILLIAMS PROD RYAN GULCH LLC
WILLIAM A MONCRIEF III TRUST	WILLIAMS PRODUCTION CO LLC
WILLIAM BRAUN RES	WILLIAMS PRODUCTION RMT CO
WILLIAM CURRY TRUST	WILLIAMS PROP INC
WILLIAM EVERET ANDRAU TRST NO 1	WILLIAMS R KEN
WILLIAM EVERET ANDRAU TRST NO 2	WILLIAMS TED H
WILLIAM FULLER TRUST	WILLIAMS THOMAS V
WILLIAM G HELIS CO	WILLIAMSON CHARLOTTE
WILLIAM G HUSBAND ESTATE	WILLIAMSON ENTPR
WILLIAM H DOHENY INC	WILLIAMSON GARY
WILLIAM H HUNT TRUST	WILLIAMSON H N
WILLIAM H LONG TRUST	WILLIAMSON J C
WILLIAM H MARTIN ENERGY LTD	WILLIAMSON J C FAMILY TRUST
WILLIAM HJORTH TRUST	WILLIAMSON JC
WILLIAM J STRICKLER LLC	WILLIAMSON LOIS G
WILLIAM JACOBS EST	WILLIAMSON RALPH E
WILLIAM P DOOLEY EST	WILLIE RAYMOND JR
WILLIAM R THURSTON TRUST	WILLIFORD ENERGY CO
WILLIAM SPIRES INC	WILLIFORD RICHARD A
WILLIAM T SPELLER LLC	WILLIS ENTERPRISES
WILLIAM TODD TRUST	WILLIS ENTERPRISES CORP
WILLIAM V MONTIN INC	WILLISCHILD O&G CORP
WILLIAM V PALMER LLC	WILLISCHILD OIL & GAS CORP
WILLIAM W ALLEN REVOCABLE TRST	WILLISTON BASIN PPLN
WILLIAM W SHAW TRUST	WILLISTON BSN JNT VT
WILLIAMS ALVIS R	WILLISTON IND SUPPLY CO INC
WILLIAMS ANNETTE L	WILLISTON IND SUPPLY CORP
WILLIAMS ARTIE P	WILLOW DIST INC
WILLIAMS C W JR	WILLOWBROOK RES INC
WILLIAMS CLAYTON W	WILLSON DOUGLAS H
WILLIAMS CRYSTAL J	WILLSON F L D TRST
WILLIAMS DAN W	WILLSOURCE ENTERPRISE LLC
WILLIAMS ELIZABETH J	WILLSTAR ENERGY LP
WILLIAMS EXPL CO	WIL-MC OIL CORP
WILLIAMS HERBERT M	WILMINGTON TRUST CO
WILLIAMS JIM	WILMINGTON TRUST CO TRUSTEE
WILLIAMS LANGDON G	WILSHIRE ENTERPRISES INC
WILLIAMS LOIS G	WILSON A TRUST
WILLIAMS PROD CO LLC	WILSON BOBBY JOE
WILLIAMS PROD GULF COAST CO LP	WILSON CELIA R
WILLIAMS PROD MGT CO	WILSON CHARLES
WILLIAMS PROD MID CONTINENT CO	WILSON EARL R
WILLIAMS PROD RMT CO	WILSON ENERGY LLC
WILLIAMS PROD RMT CO LLC	WILSON GLADYS G
WILLIAMS PROD ROCKY MTN CO	WILSON H AFTON REV TRUST
	WILSON H R

Current BLM Oil and Gas Lessees:

WILSON J W	WINDSOR WYOMING LLC
WILSON JAMES	WINES KAREN
WILSON JEFF	WINGED FOOT OIL CO
WILSON JOHN H	WINGED FOOT OIL INC
WILSON JOHN L	WINGO DAVID
WILSON JUANITA R	WINGROVE WAYNE
WILSON MARK A	WINIFRED GAS PTNRSHP
WILSON MARK D	WINKLER C R JR
WILSON MICHELE	WINKLER FRANCES A
WILSON MORRIS L	WINKLER L W JR
WILSON OIL CO LTD	WINN EUSTACE D
WILSON SCOTT	WINN EXP CO INC
WILSON SCOTT E	WINN EXPL CO INC
WILSON SUSAN M	WINN EXPLORATION CO INC
WILSON TODD M	WINN EXPLORATION COMPANY INC
WILSON V D ESTATE	WINN INVESTMENT CO
WILSON VIVIENNE H	WINN INVESTMENT INC
WILSON W O	WINN INVESTMENTS INC
WILSON W TRUST	WINN O&G EXPL
WILSON WHITNEY KARIS	WINN O&G EXPL INC
WILSON WILBUR A	WINN OG EXPL INC
WILSON WILBUR D	WINNIE OG INC
WILSON WILBUR TRUST	WINONA OIL CO
WILSON WM B	WINSTON LAND-CATTLE
WILSON-HUNTER PROP	WINSTON OIL CO INC
WILSPENMUN LLC	WINSTON TRUST
WINCHESTER PROD CO	WINTER RIDGE ENERGY LLC
WINCHESTER PRODUCTION CO	WINTERGREEN ENE CORP
WINCO PETROLEUM CORP	WINTERS FREDERICK
WIND RIVER HYDROCARBONS INC	WINTERSHALL CORP
WIND RIVER II CORP	WINTHROP ROBERT
WIND RIVER PETROLEUM LLC	WISE BRION G
WIND RIVER RES INC	WISE OG NO 4 LTD
WINDER TJ&DJ	WISE OIL & GAS NO 2 LTD
WINDFOHR ANNE B	WISE OIL & GAS NO 6 LTD
WINDFOHR R F TRUST	WISE OIL & GAS NO 8 LTD
WINDLANDS CORP	WISE OIL CO LTD
WINDMILL ENERGY SERVICES LLC	WISE SUE
WINDMILL OIL & GAS CO LLC	WISE SUPPLY CO INC
WINDRUSH OPERATING CO LLC	WISE WILLIAM D JR
WINDSOR BEAVER CREEK LLC	WISENBAKER MICHAEL BUSH JR
WINDSOR CASTLE SPRINGS LLC	WISER OIL CO
WINDSOR DAKOTA LLC	WITCO CORP
WINDSOR ENERGY GROUP LLC	WITHCER MARVIN D
WINDSOR GAS DRAW LLC	WITHERS JACQUELINE M
WINDSOR PRODUCTION COMPANY	WITHROW PHILLIP B

Current BLM Oil and Gas Lessees:

WITMAC O&G PROP INC	WOLVERINE GAS&OIL CO
WITTE DONALD H	WOMACK KIM
WITTINGTON OPER CO	WOMBLE LOELLA M
WITTKOPP LELAND	WOMMACK H H III
WITTKOPP VIRGINIA	WOOD MARLENA LENORE
WJ STRICKLER LP	WOOD MCSHANE & THAMS
WJP EXPL INC	WOOD OIL CO
WK LAND CO	WOOD OIL CORP
WKG INVESTMENTS	WOOD RALPH J JR
W-L RADENTZ LTD	WOOD RUN LTD
WM R THURSTON TRUST	WOOD WALTER
WM WY ENERGY RESOURCES II LLC	WOODARD JAMES B
WM WY ENERGY RESOURCES LLC	WOODARD JIM
WMRT MID-CONTINENT LLC	WOODARD&DILLARD PART
WOHLFORD BILL	WOODBINE FINANCIAL
WOHLFORD BURNET B	WOODBINE PETRO INC
WOHLFORD BURNET F	WOODROW PAUL
WOHLFORD DANA M	WOODRUFF HOWARD L
WOHLFORD ELIZABETH B	WOODRUFF JUDITH M
WOHLFORD MARY M ESTATE	WOODRUFF LEONARD J
WOLCOTT JOHN	WOODS DANIEL A
WOLCOTT LLC	WOODS JOHN D JR
WOLD JOHN S	WOODS JOHN JR
WOLD OIL PROP INC	WOODS RESEARCH & DEV
WOLD OIL PROPERTIES INC	WOODS WALTER E
WOLF ELAINE	WOODSIDE DRILLING A PTNERSHP
WOLF ENERGY LLC	WOODSON EXPLORATION LLC
WOLF ERVIN	WOODSON O&G LP
WOLF ERVING	WOODSTONE RES LLC
WOLF ESTELLE R	WOODSTONE RESOURCES LLC
WOLF EXPLORATION INC	WOODUL PAUL J
WOLF HAVEN CORP THE	WOODWARD DEVELOPMENT INC
WOLF HELENE B	WOODWARD DEVELOPMENT LLC
WOLF JERRY D	WOODWARD DON E
WOLF MARVIN E	WOODWARD ENTERPRISES LLC
WOLF STEVEN T	WOODWARD OIL CO
WOLFE ETHEL M H	WOODWARD W T TRUST
WOLFE ROBERT	WOODY L HUNT
WOLFSNARE RLTY & MIN	WOOLDRIDGE PRODUCTION CO
WOLFSNARE ROYTY&MINS	WOOLF & MAGEE INC
WOLL GLEN OLIVE	WOOLFOLK JOHN
WOLLARD FAMILY TRUST	WOOLSEY PETRO CORP
WOLTER ROY L	WOOLVERTON JANET H
WOLVERINE EXPL CO	WORD B WILSON INV LP
WOLVERINE GAS & OIL	WORLAND ASSOCIATES
WOLVERINE GAS & OIL CORP	WORLD PRODUCERS INC

Current BLM Oil and Gas Lessees:

WORLDWIDE COMPANIES	WTN DRILLING CO
WORLDWIDE EXPLORATION CORP	WTN INTERIOR INC
WORLEY DONALD S	WTN OIL CO INC
WORLEY EARL & MARY	WTN OIL CO INC 88-1
WORLTON JAMES T JR	WTN OIL CO INC 88-2
WORRAL INVST CORP	WTR REVOCABLE TRUST
WORRALL INVESTMENT CORP	WULF OIL CORP
WORRALL JOHN III	WUNSCH ANNE L
WORRALL KENNETH E	WW OIL INC
WORRALL LORI SCOTT	WWF OIL CORP
WORRELL CHARLES L	WWI 1990 TRUST
WORTH ENERGY LLC	WWR ENTERPRISES INC
WORTH ROBERT C	WY ASSOCIATED OIL
WORTHEY JIMMY D	WY CASING SVC
WORTHEY LEAQUITA J	WY COAL CORP
WORTHINGTON GEORGIA	WY LA BARGE OIL CO
WORTHINGTON RALPH E	WY NATIONAL BANK
WORTHINGTON RALPH IV	WY PACIFIC COAL
WORTLEY RICHARD C	WY PACIFIC OIL
WORTZ CARL III	WY RESERVE OIL CO
WP PROPERTIES CORP	WY RESOURCES OIL CO
WRATHER DAVID	WY TERRE RESOURCES LLC
WRATHER J D JR	WYATT JOSEPH M
WRATHER JOHN	WYCHGRAM DANIEL C
WRBD II LP	WYE OIL CO INC
WRIGHT ALBERTA EST	WYMAN LOUIS M
WRIGHT DALE O	WYMAN PAULA J
WRIGHT FAMILY TRUST	WYMOND TYLER R
WRIGHT J G	WYNN CLAUDE FORREST
WRIGHT JOE R	WYNN CROSBY ROYALTY
WRIGHT LARRY	WYNN EDNA L
WRIGHT MINERALS LLC	WYNN SHIRLEY B
WRIGHT R DEAN	WYNN SHIRLEY BARNES ESTATE
WRIGHT R L	WYNN W F
WRIGHT ROBERT L	WYNN W T
WRIGHT SCOTT W	WYNN-CROSBY PARTNERS I LTD
WRIGHT W W	WYNNE JAMES R
WRIGHT WINFIELD	WYNNE M BROWN CHILDRENS TRST
WRS INTERESTS INC	WYNN-TEXAS COMM TRST
WRT COMPANY A COLORADO CORP	WYNR LLC
WS & DM INC	WYOIL CORP
WSC #15 OIL & GAS IN	WYOMING OIL & MINERALS INC
WTG EXPL INC	WYOMING OIL AND LAND LLC
WTG EXPLORATION INC	WYOMING RES CORP
WTI 1993 LTD	WYOMING RESOURCES CORP
WTN DISCOVERY USA INC	WYOMING SOUTHERN RES

Current BLM Oil and Gas Lessees:

WYOTEX OIL CO	YATES GEORGE M
WYTEX VENTURES LLC	YATES HARVEY E
XAE CORP	YATES INDUSTRIES LLC
XANADU RESOURCES INC	YATES JAMES H INC
XERIC O&G CORP	YATES JO ANN
XERIC OG CORP	YATES JOHN A
XERIC OIL & GAS CORP	YATES JOHN A JR
XH LLC	YATES JOHN JR&NANCY
XION INVESTMENT	YATES JUDY H
XO EXPLORATION INC	YATES LILLIE M
XOG OPER LLC	YATES LILLIE M EST
XOG OPERATING LLC	YATES MCMINN LTD
XPLORATION, INC	YATES NANCY E
XS ENERGY INC	YATES PEGGY A
XTO ENE INC	YATES PEGGY A EST
XTO ENERGY INC	YATES PETRO CORP
XTO ENERGY PARTNERS OPER LLC	YATES PETROLEUM CORP
XTO OFFSHORE INC	YATES PEYTON
XTO RESOURCES I LP	YATES RICHARD
XTRACT LTD	YATES S P
XYZ CORP	YATES STEVEN M
XYZ INC	YATES THOMAS H
Y SONENSHINE TRUST	YATES THOMAS H JR
YABROVE EDWARD	YATES US INC
YAGER JOE	YATES-DAVIS MARY
YAGER L W	YECKEL J C
YAGER MARY	YEDNAK PAUL R
YALE OIL ASSN INC	YEGEN E C
YALE OIL ASSOC INC	YELBOM OIL INC
YALE OIL ASSOCIATION INC	YELLOW QUEEN URANIUM CO
YARBOROUGH P390	YELLOWSTONE INVSTMNTS
YARBOROUGH OIL & GAS	YELLOWSTONE PETRO
YARBOROUGH OIL CO	YLITALO ROD W
YARBOROUGH W B	YOAKAM C A
YATER ALEXANDER YOG	YOCKIM DENNIS W
YATES BROTHERS	YOELIN SHERWIN D
YATES CAROLYN BULOVAS	YORK J LOUIS
YATES D M	YORK MRS J LOUIS
YATES DRILLING CO	YOSEMITE CREEK OG LLLP
YATES DRILLING CO	YOSEMITE CREEK OIL & GAS LLC
YATES DRILLING CORP	YOUNG BETTY R
YATES EMPL 83 LTD	YOUNG CHARLES A
YATES EMPLOYEES'87, LTD	YOUNG DENZIL R
YATES ENERGY CORP	YOUNG DWAYNE R
YATES FRED G	YOUNG JOHN H
YATES FRED G INC	YOUNG LEIGHTON F JR

Current BLM Oil and Gas Lessees:

YOUNG ROBERT H	ZENITH OIL&GAS INC
YOUNGBLOOD J LEE	ZENITH PETROLEUM CORPORATION
YUCCA ENERGY INC	ZENNER KENNETH L
YUCCA PETROLEUM CORP	ZENO CO LLC
YUMA RESOURCES INC	ZENO COLORADO LLC
YUNG DENNIS	ZENO WYOMING LLC
YUNG FLORENCE	ZERBST LEONARD A
YUNG KEVIN H	ZERBST ROBERT K
Z K BRINKERHOFF TRST	ZIA ENTERPRISES
ZAB INC	ZIA INVESTMENTS
ZACHARY J M	ZIA ROYALTY LLC
ZACHARY J M TRUSTEE	ZICK MARY S
ZACHARY OIL OPER CO	ZIER NANCY C
ZALMAN RES INC	ZIMMERMAN ROBERT E JR
ZALMAN RESOURCES INC	ZINKE & TRUMBO INC
ZANKEL ARTHUR	ZINKE ROBERT
ZANKEL ARTHUR S	ZINSZER KENDALL B
ZARET I A	ZINSZER RICHARD H
ZARLENGO ANTHONY F	ZINSZER ROBERT H
ZAVANNA LLC	ZIONS 1ST NATL BANK
ZECCHI PAUL J	ZKB PROPERTIES
ZELIGSON JOEL L	ZOLLER ENTERPRISES LLC
ZELLER THERESA M	ZOLLER H E JR
ZEMORE PHYLLIS M	ZONE EXPLORATION INC
ZENEKO INC	ZORRO PARTNERS LTD
ZENERGY INC	ZOW ENTERPRISES LLC
ZENERGY ONSHORE PROPERTIES LLC	ZSCHACH INC
ZENITH FUND IX	ZULLO LORETTA
ZENITH FUND V	ZUNDEL SALLY D
ZENITH FUND VI	ZURCHER SUZETTE M
ZENITH FUND VIII	ZYLENE LMTD PTNRSHP

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: BU			ID: BU17183
Unique INC #: CR11-02-DI	Well Name: KEELINE UNIT		ID Date: 10/18/10
	Well #: 17-21		Effective Date: 10/28/10
Operator: WELLSTAR CORPORATION			Abatement Date: 10/30/10
Case #: WYW178681X	FAC ID:		Corrected Date: 11/30/10
Form: I	FAC NAME:		Followup Date: 11/30/10
Assessment: \$0	Inspector: ROSS		Extend Date:
Gravity: 3			
Authority Ref: 43 CFR 3161.2 and Onshore Order No. 1 IV.			

Remarks Date: 10/18/10

A copy of the Application for Permit to Drill is not available at the drill site. To correct this violation comply with Onshore Order No. 1 IV, which states that "A copy of the approved APD and any Conditions of Approval must be available for review at the drill site."

Office: CA			ID: CA3611
Unique INC #: 11CH0025I	Well Name: SPILLMAN DRAW UNIT 35-73		ID Date: 12/15/10
	Well #: 15-1H		Effective Date: 12/15/10
Operator: CHESAPEAKE OPERATING INC			Abatement Date: 12/29/10
Case #: WYW177621X	FAC ID:		Corrected Date: 12/23/10
Form: I	FAC NAME:		Followup Date: 12/15/10
Assessment: \$0	Inspector: HERNANDEZ		Extend Date:
Gravity: 1			
Authority Ref: 43 CFR 3163.1(a)			

Remarks Date: 12/15/10

Number 1 of the Wildlife Conditions of Approval within the approved APD for the above well states..."Avoid surface-disturbing and disruptive activities between November 15 through March 14 to protect Sage Grouse Winter habitat." Chesapeake is currently in violation of this Condition of Approval. Chesapeake is required to conduct a field survey for Sage-grouse by a third party qualified Wildlife Biologist. This survey must be done within a half mile radius of the activity area, including the road and well pad. The field survey is required to be completed by December 22, 2010, with a follow up report due by December 29, 2010. After report review, the BLM will determine if further mitigation measures are required. The BLM anticipates drilling to be finished by January 28, 2010. When Chesapeake is finished drilling and moving the rig off this location, all operations shall cease until after March 14, 2011. Completion activities will not be allowed until after this date.

Office: CA			ID: CA3568
Unique INC #: 11CH0005I	Well Name: FEDERAL		ID Date: 10/07/10
	Well #: 14-8		Effective Date: 10/07/10
Operator: BLACK BEAR OIL CORPORATION			Abatement Date: 10/07/10
Case #: WYW33783	FAC ID:		Corrected Date: 10/07/10
Form: I	FAC NAME:		Followup Date: 10/07/10
Assessment: \$0	Inspector: HERNANDEZ		Extend Date:
Gravity: 3			
Authority Ref: 43 CFR 3163.1(a) & Onshore Order 1 IV.			

Remarks Date: 10/07/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

The approved Application for Permit to Drill (APD) is not on location as required both by Onshore Order 1 and the Conditions of Approval (COA's). The absence of the APD caused much confusion on the approved cement for the surface casing job. A copy of the APD and COA's must be available for review at the drill site. For compliance, supply a copy of the APD to be available on location.

Office: CA ID: CA3566  
Unique INC #: 11CH0003I Well Name: FEDERAL  
Well #: 14-8 ID Date: 10/05/10  
Operator: BLACK BEAR OIL CORPORATION Effective Date: 10/05/10  
Case #: WYW33783 FAC ID: Abatement Date: 10/06/10  
Form: I FAC NAME: Corrected Date: 10/05/10  
Assessment: \$0 Inspector: HERNANDEZ Followup Date: 10/13/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-1(b) & Onshore Order 1 IV.  
Remarks Date: 10/05/10

A preliminary drilling inspection at the Federal 14-8 on September 7, 2010 noted unauthorized surface disturbance. Many vehicles and some drilling equipment were observed off the north edge of location. Per 43 CFR, the operator shall exercise due care and diligence to assure that leasehold operations do not result in undue damage to surface resources. Per Onshore Order 1, drilling operations must be conducted to minimize adverse effects to surface resources and prevent unnecessary surface disturbance. Doug Robinson was informed of this violation at the time of inspection, and the vehicles and equipment were subsequently moved back onto the location within one hour. For compliance, prevent any future unauthorized surface disturbance. See the enclosed photographs and location survey.

Office: CA ID: CA3620  
Unique INC #: 11CH0029I Well Name: SPILLMAN DRAW UNIT 35-73  
Well #: 15-1H ID Date: 12/22/10  
Operator: CHESAPEAKE OPERATING INC Effective Date: 12/23/10  
Case #: WYW177621X FAC ID: Abatement Date: 12/23/10  
Form: I FAC NAME: Corrected Date: 12/23/10  
Assessment: \$0 Inspector: HERNANDEZ/COLEMAN Followup Date: 12/23/10  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 2 III.A.2.g.  
Remarks Date: 12/22/10

An inspection at the above location noted that three of the six hand wheels were not installed on the BOP as required. Manual locking devices (hand wheels) or automatic locking devices shall be installed. For compliance, maintain the hand wheels on the BOP. See the enclosed photographs.

Office: CA ID: CA3618  
Unique INC #: 11CH0028I Well Name: SPILLMAN DRAW UNIT 35-73  
Well #: 15-1H ID Date: 12/22/10  
Operator: CHESAPEAKE OPERATING INC Effective Date: 12/23/10  
Case #: WYW177621X FAC ID: Abatement Date: 12/23/10  
Form: I FAC NAME: Corrected Date: 12/23/10  
Assessment: \$0 Inspector: HERNANDEZ/COLEMAN Followup Date: 12/23/10  
Gravity: 1 Extend Date:  
Authority Ref: Onshore Order 2 III.C.7.  
Remarks Date: 12/22/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

An inspection at the above location noted that one of the two flare lines was not anchored as required. All flare lines shall be anchored. For compliance, anchor the flare line. See the enclosed photographs.

Office: CB		ID: CB22006
Unique INC #: 11-DHW-003	Well Name: SHOWSTOPPER 19 FEDERAL	
	Well #: 6	ID Date: 11/08/10
Operator: MARBOB ENERGY CORPORATION		Effective Date: 11/15/10
Case #: NMNM55929	FAC ID:	Abatement Date: 12/15/10
Form: I	FAC NAME:	Corrected Date: 12/27/10
Assessment: \$0	Inspector: BLAKLEY	Followup Date: 01/04/11
Gravity: 3		Extend Date:
Authority Ref: 43CFR.3162.1(a); APD COA.VII.B		

Remarks Date: 11/08/10

APD COA.VII.B - Changes to the approved APD casing and cement program require submitting an sundry and receiving approval prior to work. Failure to obtain approval prior to work will result in an Incident of Non-Compliance being issued. Cement program on the well was changed without prior approval by the BLM. BLM recieved the sundry after the work was finished with the wrong name on the sundry. Corrective action: Tell the BLM how you, the operator, should have handled the situation to avoid the INC, sign and date the INC, and do not allow this to happen on future operations. for questions and comments, please contact the BLM-Carlsbad Field Office representative: Dusty Winkler (575) 234-5914 620 E. Greene St. Carlsbad, NM 88220

Office: CB		ID: CB22256
Unique INC #: 11LB003I	Well Name: ROSS DRAW UNIT	
	Well #: 31	ID Date: 02/25/11
Operator: WILLIAMSON J C		Effective Date: 02/27/11
Case #: NMNM0480904A	FAC ID:	Abatement Date: 02/28/11
Form: I	FAC NAME:	Corrected Date: 02/28/11
Assessment: \$0	Inspector: BRUMLEY	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: CFR 3162.1(a)	Conditions of Approval VII.E.	

Remarks Date: 02/25/11

Conditions of Approval for the above mentioned well Section VII.E. states "All waste (i.e. sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Fluids from the septic systems are being drained in the surrounding area. Immediately begin safely containing waste fluids and disposing of them properly, at a waste disposal facility. Secure the contaminated areas to prevent any disturbance and await further instructions from the BLM.

Office: CB		ID: CB22258
Unique INC #: 11LB004I	Well Name: PLU ROSS RANCH 20 FEDERAL	
	Well #: 1H	ID Date: 02/28/11
Operator: CHESAPEAKE OPERATING INC		Effective Date: 02/28/11
Case #: NMNM71016X	FAC ID:	Abatement Date: 03/01/11
Form: I	FAC NAME:	Corrected Date: 03/01/11
Assessment: \$0	Inspector: BRUMLEY	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1(a)	Conditions of Approval Drilling Section VI.E.	

Remarks Date: 02/28/11

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Conditions of Approval for the above mentioned well Section VI.E. states "All waste (i.e. sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Fluids from the septic systems are being drained in the surrounding area. Immediately begin safely containing waste fluids and disposing of them properly, at a waste disposal facility. Secure the contaminated areas to prevent any disturbance and await further instructions from the BLM.

Office: CB		ID: CB21986
Unique INC #: 11LB001I	Well Name: POWER 31 FEDERAL SWD	
	Well #: 3	ID Date: 10/27/10
Operator: BURNETT OIL COMPANY INC		Effective Date: 10/29/10
Case #: NMNM98824	FAC ID:	Abatement Date: 10/29/10
Form: I	FAC NAME:	Corrected Date: 10/28/10
Assessment: \$0	Inspector: BRUMLEY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 10/27/10

Conditions of Approval for the above referenced well stated that a casing integrity test is to be performed on the 5 1/2" casing per Onshore Oil and Gas Order 2.III.B.1.h after drilling out all plugs to PBTD of 11405' with a test pressure of 1710 psi. The Conditions of Approval also stated that a Notice of Intent sundry with the procedure to complete the above referenced well shall be submitted and approved prior to commencing completion work. Neither of these conditions was met. To gain compliance the following conditions shall be met. Prior to commencing any further completion work on the well, a casing integrity test shall be conducted on the 5 1/2" production casing, with the test pressure to be 1710 psi. Should the test fail, a sundry shall be submitted describing the remedial work that will be performed so that the casing will hold the 1710 psi test pressure. Work will not start without approval. Injection shall not commence until a passing CIT has been completed. A Subsequent Report sundry shall be submitted upon completion of the CIT describing how the test was conducted, what equipment was in the hole and at what depth the equipment is set.

Office: CB		ID: CB21994
Unique INC #: 11-KC-04	Well Name:	
	Well #:	ID Date: 11/03/10
Operator: STEPHENS & JOHNSON OPER CO		Effective Date: 11/12/10
Case #: NMLC064670	FAC ID: A	Abatement Date: 12/12/10
Form: I	FAC NAME: FEATHERSTONE	Corrected Date: 12/09/10
Assessment: \$0	Inspector: CAFFALL	Followup Date: 12/29/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a) O.O.III.D.2.e		

Remarks Date: 11/03/10

During a recent inspection the following violation was found: Wind Direction Indicator O. O. 6.III.D.2.e e. At least 1 permanent wind direction indicator shall be installed so that wind direction can be easily determined at or approaching the storage tank(s). Corrective Action: Install wind direction indicator as per Onshore Order #6. Inquiries/correspondence pertaining to this Order can be directed to:  
of Land Management Bureau  
Attention: Lead PET Roy 'Kent'

Caffall

88220

620 E Greene St  
Phone # (575) 234-5906

Carlsbad, NM

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: CB ID: CB22231  
Unique INC #: 11RE12 Well Name: BARNSDALL FEDERAL  
Well #: 18 ID Date: 02/23/11  
Operator: APACHE CORPORATION Effective Date: 02/23/11  
Case #: NMLC028775B FAC ID:  
Form: I FAC NAME:  
Assessment: \$1,000 Inspector: ESPINOZA  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.b.ii.  
Remarks Date: 02/23/11  
Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The observed choke manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. PANIC LINE FROM CHOKE MANIFOLD TO FLARE PIT OR TYANK NOT HOOKED UP. VOLUNTARILY STABLIZE HOLE AND CEASE DRILLING OPERATIONS UNTIL LINE IS INSTALLED. TWO DAYS WERE DRILLED WITHOUT PANIC LINE

Office: CB ID: CB22232  
Unique INC #: 11RE13 Well Name: BARNSDALL FEDERAL  
Well #: 18 ID Date: 02/23/11  
Operator: APACHE CORPORATION Effective Date: 02/23/11  
Case #: NMLC028775B FAC ID:  
Form: I FAC NAME:  
Assessment: \$1,000 Inspector: ESPINOZA  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.b.iv.  
Remarks Date: 02/23/11  
Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Pressure gauges in the well control system shall be of a type designed for drill fluid service. Replace pressure gauge with a type designed for drill fluid service. ASSESSMENT FOR TWO DAYS

Office: CB ID: CB22208  
Unique INC #: 11RE10 Well Name: DALE H PARKE C  
Well #: 23 ID Date: 02/18/11  
Operator: PREMIER OIL & GAS INCORPORATED Effective Date: 02/18/11  
Case #: NMLC029020C FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ESPINOZA  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.d.  
Remarks Date: 02/18/11  
Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The accumulator precharge pressure test shall be conducted prior to connecting the closing unit to the BOP stack and at least once every 6 months. Perform test

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: CB ID: CB22204  
Unique INC #: 11RE07 Well Name: DALE H PARKE C ID Date: 11/18/11  
Well #: 23 Effective Date: 11/18/11  
Operator: PREMIER OIL & GAS INCORPORATED Abatement Date: 11/18/11  
Case #: NMLC029020C FAC ID: Corrected Date: 02/18/11  
Form: I FAC NAME: Followup Date: 02/20/11  
Assessment: \$500 Inspector: ESPINOZA Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.b.ii.  
  
Remarks Date: 11/18/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The observed choke manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. PANIC LINE IS NOT HOOKED TO FLARE PIT STABILIZE WELL AND HOOK UP PANIC LINE TO APPROVED STANDARDS.

Office: CB ID: CB22205  
Unique INC #: 11R8008 Well Name: DALE H PARKE C ID Date: 02/18/11  
Well #: 23 Effective Date: 02/18/11  
Operator: PREMIER OIL & GAS INCORPORATED Abatement Date: 02/18/11  
Case #: NMLC029020C FAC ID: Corrected Date: 02/18/11  
Form: I FAC NAME: Followup Date: 02/20/11  
Assessment: \$500 Inspector: ESPINOZA Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.b.ii.  
  
Remarks Date: 02/18/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The observed choke manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. THERE IS NO VALVE OFF OF BOP STACK TO CHOKE MANIFOLD STABALIZE WELL AND REPLACE VALVE

Office: CB ID: CB22240  
Unique INC #: 11RE15 Well Name: BLUE THUNDER 5 FEDERAL ID Date: 02/24/11  
Well #: 4H Effective Date: 02/24/11  
Operator: COG OPERATING LLC Abatement Date: 02/24/11  
Case #: NMLC069033 FAC ID: Corrected Date: 02/24/11  
Form: I FAC NAME: Followup Date: 02/25/11  
Assessment: \$1,500 Inspector: ESPINOZA Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.b.iv.  
  
Remarks Date: 02/24/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Pressure gauges in the well control system shall be of a type designed for drill fluid service. Replace pressure gauge with a type designed for drill fluid service.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: CB ID: CB22239  
 Unique INC #: 11RE14 Well Name: BLUE THUNDER 5 FEDERAL ID Date: 02/24/11  
 Well #: 4H Effective Date: 02/24/11  
 Operator: COG OPERATING LLC Abatement Date: 02/24/11  
 Case #: NMLC069033 FAC ID: Corrected Date: 02/24/11  
 Form: I FAC NAME: Followup Date: 02/25/11  
 Assessment: \$1,500 Inspector: ESPINOZA Extend Date:  
 Gravity: 1  
 Authority Ref: Onshore Order No. 2, III.A.2.b.ii.

Remarks Date: 02/24/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The observed choke manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. PANIC LINE FRON BUFFER TUBE TO FLARE/PIT NOT HOOKED UP/ CHOKE LINES FROM BUFFER TUBE TO MUD PIT NOT INSTALLED AS REQUIRED. INSTALL LINES AS REQUIRED BY APPROVED APD

Office: CB ID: CB22227  
 Unique INC #: 11RE11 Well Name: FOLK FEDERAL ID Date: 02/23/11  
 Well #: 26 Effective Date: 02/23/11  
 Operator: COG OPERATING LLC Abatement Date: 02/24/11  
 Case #: NMNM0397623 FAC ID: Corrected Date: 02/23/11  
 Form: I FAC NAME: Followup Date: 02/23/11  
 Assessment: \$0 Inspector: ESPINOZA Extend Date:  
 Gravity: 3  
 Authority Ref: Onshore Order No. 2, III.A.2.b.iv.

Remarks Date: 02/23/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Pressure gauges in the well control system shall be of a type designed for drill fluid service. Replace pressure gauge with a type designed for drill fluid service.

Office: CB ID: CB22226  
 Unique INC #: 11RE09 Well Name: FOLK FEDERAL ID Date: 02/23/11  
 Well #: 26 Effective Date: 02/23/11  
 Operator: COG OPERATING LLC Abatement Date: 02/23/11  
 Case #: NMNM0397623 FAC ID: Corrected Date: 02/23/11  
 Form: I FAC NAME: Followup Date: 02/23/11  
 Assessment: \$500 Inspector: ESPINOZA Extend Date:  
 Gravity: 1  
 Authority Ref: Onshore Order No. 2, III.A.2.g.

Remarks Date: 02/23/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. A manual locking device (i.e. hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. Install locking devices. Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. A manual locking device (i.e. hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. Install locking devices.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: CB ID: CB22198  
Unique INC #: 11RE06 Well Name: LOST TANK 4 FEDERAL  
Well #: 17 ID Date: 02/17/11  
Operator: OXY USA INC Effective Date: 02/17/11  
Case #: NMNM0417696 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ESPINOZA  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.b.ii.  
  
Remarks Date: 02/17/11  
  
Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The observed choke manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. SAFETY HOBLES ON FLEX HOSE FROM BOP TO CHOKE MANIFOLD NOT TO APPROVED STANDARDS // REPAIR OR REPLACE WITH CORRECT SAFETY HOBLES.

Office: CB ID: CB22195  
Unique INC #: 11RE05 Well Name: LOST TANK 4 FEDERAL  
Well #: 17 ID Date: 02/17/11  
Operator: OXY USA INC Effective Date: 02/17/11  
Case #: NMNM0417696 FAC ID:  
Form: I FAC NAME:  
Assessment: \$500 Inspector: ESPINOZA  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.g.  
  
Remarks Date: 02/17/11  
  
Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. A manual locking device (i.e. hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. Install locking devices.

Office: CB ID: CB22176  
Unique INC #: 11RE01 Well Name: STEVENS A  
Well #: 17H ID Date: 02/14/11  
Operator: BURNETT OIL COMPANY INC Effective Date: 02/15/11  
Case #: NMNM2747 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ESPINOZA  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.b.iv.  
  
Remarks Date: 02/14/11  
  
Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Pressure gauges in the well control system shall be of a type designed for drill fluid service. Replace pressure gauge with a type designed for drill fluid service THE MUD GAUGE IN CHOKE MANIFOLD DOES NOT MEET REQUIRED STANDARDS

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: CB ID: CB22177  
Unique INC #: 11RE02 Well Name: STEVENS A ID Date: 02/14/11  
Well #: 17H Effective Date: 02/15/11  
Operator: BURNETT OIL COMPANY INC Abatement Date: 02/16/11  
Case #: NMNM2747 FAC ID: Corrected Date: 02/15/11  
Form: I FAC NAME: Followup Date: 02/15/11  
Assessment: \$1,000 Inspector: ESPINOZA Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.b.ii.

Remarks Date: 02/14/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The observed choke manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. CHOKE LINES ARE NOT HOOKED UP AND PANIC LINE SHOULD BE RUN WITH STRAIGHT LINE TO FLARE PIT  
CONTACTED BELTON MATTHEWS @ 11:15 ON 2/15/11 OPERATOR IS VOLUNTARILY STABLING WELLBORE AND CEASING DRILLING OPERATIONS AND CORRECTING ALL VIOLATIONS PRIOR TO RESUMING OF DRILLING OPERATIONS, CURRENTLY @ 3600 FEET WITH WATER FLOW OF 125 BBLS/HR

Office: CB ID: CB22178  
Unique INC #: 11RE003 Well Name: STEVENS A ID Date: 02/14/11  
Well #: 17H Effective Date: 02/15/11  
Operator: BURNETT OIL COMPANY INC Abatement Date: 02/16/11  
Case #: NMNM2747 FAC ID: Corrected Date: 02/15/11  
Form: I FAC NAME: Followup Date: 02/15/11  
Assessment: \$0 Inspector: ESPINOZA Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.d.

Remarks Date: 02/14/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The accumulator precharge pressure test shall be conducted prior to connecting the closing unit to the BOP stack and at least once every 6 months. Perform test.

Office: CB ID: CB22213  
Unique INC #: 11RE04 Well Name: LOST TANK 10 FEDERAL ID Date: 02/16/11  
Well #: 1 Effective Date: 02/16/11  
Operator: OXY USA INC Abatement Date: 02/17/11  
Case #: NMNM0417506 FAC ID: Corrected Date: 02/17/11  
Form: I FAC NAME: Followup Date: 02/18/11  
Assessment: \$0 Inspector: ESPINOZA/HOSKINSON Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.d.

Remarks Date: 02/16/11

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The accumulator precharge pressure test shall be conducted prior to connecting the closing unit to the BOP stack and at least once every 6 months. Perform test

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: CB		ID: CB22012
Unique INC #: 11RH03	Well Name: SERRANO 29 FEDERAL	
	Well #: 1	ID Date: 11/18/10
Operator: DEVON ENERGY PRODUCTION CO L P		Effective Date: 11/18/10
Case #: NMNM112269	FAC ID:	Abatement Date: 11/19/10
Form: I	FAC NAME:	Corrected Date: 11/18/10
Assessment: \$0	Inspector: HOSKINSON	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.5-1(a) COA's		

Remarks Date: 10/18/10

OPERATOR DISCHARGING WASTE WATER FROM BUNKHOUSE (H&P 372) SHOWERS & WASHING MACHINE OFF WELLPAD. (SEE ATTACHED PICTURES) CORRECTIVE ACTION: CEASE & DESIST DISCHARGING ALL WASTE WATER OFF WELLPAD & PUT IN TANK TO BE HAULED OFF. REMOVE ALL CONTAMINATED SOILS & REPLACE WITH CLEAN LIKE SOILS. COMPANY REPRESENTATIVE WAS PRESENT AND STOPPED ALL WASTE WATER DISCHARGE & PUT IN WASTE TANKS, AND WILL HAVE REMEDIATION DONE ASAP. If you have any questions please contact:

Sr.  
Technician  
Management  
Carlsbad, NM 88220  
361-0106 Fax: (575) 234-5927

Robert E. Hoskinson  
Petroleum Engineering  
Bureau of Land  
620 East Greene Street,  
Office: (575) 234-5966 Cell (575)  
E-mail: Robert\_Hoskinson@nm.blm.gov

Office: CB		ID: CB21364
Unique INC #: 10-TT-002	Well Name: SKELLY UNIT	
	Well #: 626	ID Date: 11/13/09
Operator: COG OPERATING LLC		Effective Date: 11/14/09
Case #: NMLC029419A	FAC ID:	Abatement Date: 11/14/09
Form: I	FAC NAME:	Corrected Date: 12/30/10
Assessment: \$0	Inspector: TUCKER	Followup Date: 01/15/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)/APD COA'S		

Remarks Date: 11/13/09

FAILURE TO COMPLY W/APD CONDITIONS OF APPROVAL, FAILURE TO NOTIFY AUTHORIZED OFFICER OF SURFACE CSG JOB.. THE BLM IS TO NOTIFIED A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS SUFACE CASING JOB. PARAGRAPH 9,(a) IN THE MASTER DRILLING PROGRAM WILL BE EXTENDED TO THE SURFACE TO VERIFY SURFACE CASING WAS SET IN THE RUSTILER.

Office: CB		ID: CB22091
Unique INC #: 13TW10	Well Name: RDX FED 21	
	Well #: 13	ID Date: 12/19/10
Operator: RKI EXPLORTION AND PRODUCTION		Effective Date: 12/19/10
Case #: NMNM102917	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 12/19/10
Assessment: \$500	Inspector: WILSON	Followup Date: 12/21/10
Gravity: 1		Extend Date:
Authority Ref: 43 cfr 3162.1(a) Onshore Oil and Gas Order #2.III.A.1.e 43CFR3163.1(b)(1)		

Remarks Date: 12/19/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

During Inspection of Silver Oak #9 Drilling Rig on 12/19/2010 found the air valve to the Pressure Accumulator System to be in the closed position,no air supply to the pressure accumulator system. Per O.O.#2 III.A.1. e. Minimum standards and enforcement provisions for power availability. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. 43 CFR 3163.1(b)(1).For failure to install blowout preventer or other equivalent well control equipment, as required by the approved drilling plan, \$500 per day for each day that the violation existed, including days the violation existed prior to discovery, not to exceed \$5,000; Violation: Major. Corrective Action: Install the equipment as specified & submit assesment of \$500.00. Normal Abatement Period: Prompt correction required. Equipment Installed as specified on 12/19/10. Submitt assesment of \$500.00

Office: CB		ID: CB22089
Unique INC #: 12TW10	Well Name: RDX FED 21	
	Well #: 13	ID Date: 12/19/10
Operator: RKI EXPLORTION AND PRODUCTION		Effective Date: 12/19/10
Case #: NMNM102917	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 12/19/10
Assessment: \$500	Inspector: WILSON	Followup Date: 12/21/10
Gravity: 3		Extend Date:
Authority Ref: Onshore Oil and Gas Order #2 III.A.2.b.iv. 43CFR3163.1(b)(1)		

Remarks Date: 12/19/10

During inspection of Silver Oak Drilling Rig #9 on 12/19/10 found drilling fluid (mud guage) to be missing from the choke manifold system. Per O.O.#2 III.A.2.b.iv.Pressure gauges in the well control system shall be a type designed for drilling fluid service 43 CFR 3163.1(b)(1).For failure to install blowout preventer or other equivalent well control equipment, as required by the approved drilling plan, \$500 per day for each day that the violation existed, including days the violation existed prior to discovery, not to exceed \$5,000; Corrective Action; Install the equipment as specified & submit assesment of \$500.00. Normal Abatement Period; Prompt correction required. Equipment Installed as specified on 12/19/10.Submitt assesment of \$500.00

Office: CC		ID: CC1828
Unique INC #: RG11LP046	Well Name: BELLA FEDERAL, FREUND FEDERAL	
	Well #: 23-7, 25-7	ID Date: 10/06/10
Operator: KERR-MCGEE ROCKY MOUNTAIN CORP		Effective Date: 12/07/10
Case #: COC52545	FAC ID:	Abatement Date: 01/13/11
Form: I	FAC NAME:	Corrected Date: 01/11/11
Assessment: \$20,000	Inspector: LPETERSON	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1(b)(2)		

Remarks Date: 12/05/10

The Freund Federal #25-7 (API#0512330767) and the Bella Federal #23-7 (API#0512330782) were directionally drilled under the railroad Special Act ROW Lease COC52545, into federal minerals. Violation is for building a location and drilling two federal wells without an approved Application for Permit to Drill (APD). The violation is in excess of 10 days. CORRECTIVE ACTION REQUIRED: Complete APDs (with \$6500 APD fee per well) shall be submitted within 30 days of receipt of this Incident of Non-compliance which includes the required information needed to complete the APD review. See Instruction Memorandum No. 2009-078 for procedures for processing Federal APDs for directional drilling into Federal mineral estate from multiple well pads on non-Federal locations. Bill #2011011563 is attached to the INC. (Assessment is \$5000 per well drilled without approval.) Payment is due 1/5/11. Questions should be directed to Leslie Peterson at 719-269-8566.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: DK ID: DK6499  
Unique INC #: IDH110010 Well Name: SUBMARINER FEDERAL  
Well #: 1-23-24H ID Date: 12/14/10  
Operator: SLAWSON EXPLORATION CO INC Effective Date: 12/14/10  
Case #: NDM99280 FAC ID: Abatement Date: 12/15/10  
Form: I FAC NAME: Corrected Date: 12/15/10  
Assessment: \$0 Inspector: DENNIS HANNUM Followup Date: 12/16/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 O.S.O. #6, III, C,3,b,i  
Remarks Date: 12/14/10  
No safety equipment on location. Must install safety equipment. Talked to Sonny, on drilling site about this matter on 12/14/10.

Office: FE ID: FE15605  
Unique INC #: 10WW167 Well Name: FLORANCE  
Well #: 11C ID Date: 11/13/10  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 11/13/10  
Case #: NMSF079511A FAC ID: Abatement Date: 11/15/10  
Form: I FAC NAME: Corrected Date: 11/15/10  
Assessment: \$0 Inspector: WEATHERFORD Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 1.III.D.3.c.  
Remarks Date: 11/13/10  
Failure to notify the AO of changes to the appoved APD; configuration change to the BOP. Annular preventer tested to 1500psi with the ASP at 1755psi.

Office: GJ ID: GJ6866  
Unique INC #: EF11007 Well Name:  
Well #: ID Date: 10/13/10  
Operator: PETRO MEX LLC Effective Date: 10/15/10  
Case #: COC0124705A FAC ID: 15-9 Abatement Date: 11/15/10  
Form: I FAC NAME: Corrected Date: 11/02/10  
Assessment: \$0 Inspector: FANCHER Followup Date: 12/08/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
Remarks Date: 10/13/10  
Your well head is leaking and requires repairs.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: GJ ID: GJ6680  
Unique INC #: EF010003 Well Name:  
Well #: ID Date: 10/06/09  
Operator: PETRO MEX LLC Effective Date: 10/30/09  
Case #: COC0124705A Abatement Date: 11/19/09  
Form: I Corrected Date: 10/27/10  
Assessment: \$0 FAC NAME: Followup Date: 10/13/10  
Gravity: 3 Inspector: FANCHER Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 10/06/09  
Your well head is leaking and requires repairs.

Office: GJ ID: GJ6677  
Unique INC #: EF010001 Well Name: ESMERELDA FEDERAL  
Well #: 1-2-8-101 ID Date: 10/06/09  
Operator: PETRO MEX LLC Effective Date: 10/30/09  
Case #: COC60770 Abatement Date: 11/19/09  
Form: I Corrected Date: 12/08/10  
Assessment: \$0 FAC NAME: Followup Date: 12/08/10  
Gravity: 3 Inspector: FANCHER Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 10/06/09  
Your rat hole is open and creates an immediate health and safety issue to the public and wildlife. You are required to fill in the rat hole or cover it and fence it off so no one will be able to fall into it.

Office: GJ ID: GJ6679  
Unique INC #: EF010002 Well Name: ESMERELDA FEDERAL  
Well #: 1-2-8-101 ID Date: 10/06/09  
Operator: PETRO MEX LLC Effective Date: 10/30/09  
Case #: COC60770 Abatement Date: 11/19/09  
Form: I Corrected Date: 12/08/10  
Assessment: \$0 FAC NAME: Followup Date: 12/08/10  
Gravity: 1 Inspector: FANCHER Extend Date:  
Authority Ref: Onshore Order No. 2, III.A.2.a.i.

Remarks Date: 10/06/09  
A well control device shall be installed at the surface that is capable of complete closure of the well bore. This device shall be closed whenever the well is unattended. You are required to install the required equipment.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: GS		ID: GS7013
Unique INC #: 110015	Well Name: FEDERAL	
	Well #: SR 22-9	ID Date: 01/27/11
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 01/27/11
Case #: COC073320	FAC ID:	Abatement Date: 01/28/11
Form: I	FAC NAME:	Corrected Date: 02/14/11
Assessment: \$0	Inspector: GIBOO	Followup Date: 02/07/11
Gravity: 3		Extend Date:
Authority Ref: O.O.2.III.B.1.h.		

Remarks Date: 01/27/11

Surface casing string pressure test did not meet the minimum required time standard according to O.O.2.III.B.1.h. Corrective action: Ensure all future casing string pressure tests are conducted in accordance with O.O.2.B.III.1.h.

Office: GS		ID: GS6997
Unique INC #: 110002	Well Name: GGU FEDERAL	
	Well #: 42B-29-691	ID Date: 11/04/10
Operator: BILL BARRETT CORPORATION		Effective Date: 11/09/10
Case #: COC52447A	FAC ID:	Abatement Date: 12/09/10
Form: I	FAC NAME:	Corrected Date: 11/18/10
Assessment: \$0	Inspector: GIBOO	Followup Date: 11/18/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1(a)		

Remarks Date: 11/04/10

Flare pit was not in preapproved location. Rig orientation was not in preapproved location. No sundry for changing location was submitted. According to 43 CFR 3162.5-1(a); "The operator shall conduct operations in a manner which protects the mineral resources, other natural resources, and environmental quality. In that respect, the operator shall comply with the pertinent orders of the authorized officer and other standards and procedures as set forth in the applicable laws, regulations, lease terms and conditions, and the approved drilling plan or subsequent operations plan." Corrective actions: Submit a sundry reflecting actual orientation of rig and flare pit along with updated plats showing rig layout and flare pit location.

Office: GS		ID: GS6996
Unique INC #: 110001	Well Name: KEINATH FEDERAL	
	Well #: 10-10H (C16OU)	ID Date: 11/04/10
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 11/08/10
Case #: COC66496X	FAC ID:	Abatement Date: 11/09/10
Form: I	FAC NAME:	Corrected Date: 11/09/10
Assessment: \$0	Inspector: GIBOO	Followup Date: 11/09/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 11/04/10

Proper site identification was not present or not in a conspicuous location. Per 43 CFR 3162.6(b), "For wells located on Federal and Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well, other than those permanently abandoned. The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds)." Corrective action: Place a sign containing all required information in a conspicuous location.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: GS ID: GS7037  
Unique INC #: 110039 Well Name: DIXON FEDERAL ID Date: 02/23/11  
Well #: B10 Effective Date: 02/24/11  
Operator: ANTERO RESOURCES PICEANCE CORP Abatement Date: 02/24/11  
Case #: COC73832 FAC ID: Corrected Date: 02/24/11  
Form: I FAC NAME: Followup Date: 02/24/11  
Assessment: \$0 Inspector: GIBOO Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2.III.A.2.i.xi.

Remarks Date: 02/23/11

No record was made in the IADC stating the RAM's (pipe & blind) had been activated while tripping. Corrective action: Ensure all described tests and/or drills be recorded in the drilling log.

Office: GS ID: GS7033  
Unique INC #: 110035 Well Name: DIXON FEDERAL ID Date: 02/23/11  
Well #: B10 Effective Date: 02/23/11  
Operator: ANTERO RESOURCES PICEANCE CORP Abatement Date: 02/24/11  
Case #: COC73832 FAC ID: Corrected Date: 02/24/11  
Form: I FAC NAME: Followup Date: 02/24/11  
Assessment: \$0 Inspector: GIBOO Extend Date:  
Gravity: 3  
Authority Ref: O.O.#1.IV.

Remarks Date: 02/23/11

An incomplete copy of the approved APD was on location. No sundry notices were on location. Corrective action: Prior to drilling, ensure a complete copy of the approved APD and all sundries are on location for all future wells.

Office: GS ID: GS7038  
Unique INC #: 110040 Well Name: DIXON FEDERAL ID Date: 02/23/11  
Well #: B10 Effective Date: 02/23/11  
Operator: ANTERO RESOURCES PICEANCE CORP Abatement Date: 02/24/11  
Case #: COC73832 FAC ID: Corrected Date: 02/24/11  
Form: I FAC NAME: Followup Date: 02/24/11  
Assessment: \$0 Inspector: GIBOO Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2.III.B.1.f.

Remarks Date: 02/23/11

No record was made in the IADC stating the use or number of centralizers during casing run. Corrective action: Ensure use and number of centralizers used are annotated in the driller's log for all future wells.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: GS ID: GS7034  
Unique INC #: 110036 Well Name: DIXON FEDERAL ID Date: 02/23/11  
Well #: B10 Effective Date: 02/23/11  
Operator: ANTERO RESOURCES PICEANCE CORP Abatement Date: 02/24/11  
Case #: COC73832 FAC ID: Corrected Date: 02/24/11  
Form: I FAC NAME: Followup Date: 02/24/11  
Assessment: \$0 Inspector: GIBOO Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)

Remarks Date: 02/23/11

No well identification sign on location. Corrective action: Ensure an approved well identification sign is present on location for all future wells.

Office: GS ID: GS7035  
Unique INC #: 110037 Well Name: DIXON FEDERAL ID Date: 02/23/11  
Well #: B10 Effective Date: 02/23/11  
Operator: ANTERO RESOURCES PICEANCE CORP Abatement Date: 02/24/11  
Case #: COC73832 FAC ID: Corrected Date: 02/25/11  
Form: I FAC NAME: Followup Date: 02/25/11  
Assessment: \$0 Inspector: GIBOO Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2.III.A.2.b.iv.

Remarks Date: 02/23/11

Improper pressure gauge was found on choke manifold. Corrective action: Ensure pressure gauge designed for drilling fluid service is installed prior to drilling out on all future wells.

Office: GS ID: GS7039  
Unique INC #: 110041 Well Name: DIXON FEDERAL ID Date: 02/23/11  
Well #: B10 Effective Date: 02/23/11  
Operator: ANTERO RESOURCES PICEANCE CORP Abatement Date: 02/24/11  
Case #: COC73832 FAC ID: Corrected Date: 02/24/11  
Form: I FAC NAME: Followup Date: 02/24/11  
Assessment: \$0 Inspector: GIBOO Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2.III.B.1.c.

Remarks Date: 02/23/11

No record was made in the IADC stating cement returning to surface. Corrective action: Ensure cement returning to surface is annotated in the driller's log for all future wells.

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Office: GS		ID: GS6994
Unique INC #: WTH-11-006	Well Name: DAYBREAK FEDERAL	
	Well #: 30-12BB (PL30)	ID Date: 10/18/10
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 10/18/10
Case #: COC0128381	FAC ID:	Abatement Date: 12/08/10
Form: I	FAC NAME:	Corrected Date: 10/18/10
Assessment: \$0	Inspector: HOWELL	Followup Date: 11/01/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.5		

Remarks Date: 11/01/10

CERTIFIED MAIL No: 7010 1060 0002 3108 7059 Return Receipt Requested EnCana Oil & Gas, Inc. Attn: Ms. RuthAnn Morss 370 17th Street, Ste 1700 Denver, CO 80202 October 15, 2010 NOTICE OF INCIDENT OF NONCOMPLIANCE (INC) Dear Ms. Morss: The surface casing setting depth for the following Daybreak Federal wells: 25-9, 30-11BB, 30-12, 30-12BB, and 30-13BB; was not set per the approved APD's or COA's. The Conditions of Approval concerning Daybreak Federal 30-12BB (PL30) in Step 10 require a triple combo log to be run on the subject well pad. This operation was to be accomplished before running surface casing; an open hole log must be run before running casing. This operation violates 43 CFR 3162.5 concerning the approved drilling plan. INCIDENTS OF NONCOMPLIANCE The following violations were identified during drilling operations on the following Daybreak Federal wells: 25-9, 30-11BB, 30-12, 30-12BB, and 30-13BB. Specifically: INC number WTH-11-001, 002, 003, 004, and 005: The surface casing setting depth of +/-1025 feet is not per the approved APD or COA's. Corrective Action: Submit a Sundry Notice for the Surface Casing setting depth for the PL30 pad subject wells. INC number WTH-11-006: The required triple combo log was not run as required on the Daybreak Federal 30-12BB. Corrective Action: Pull surface casing, run triple combo log, send log to Will Howell, CRVFO, for evaluation. In accordance with 43 CFR 3163.1 (a), please comply with the corrective action(s) for the identified environmental/drilling problems. Corrective actions for these violations were completed 10/14/2010.

WARNING Orders of the Authorized Officer or Incidents of Non Compliance and reporting time frames begin upon receipt of the Notice or 7 business days after the date it is mailed, whichever is earlier. Each problem or violation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management office at the address shown above. For Incidents of Non Compliance, please note that you already may have been assessed for noncompliance (see amount under "Assessed for Noncompliance"). If you do not comply as noted above "Corrective Action To Be Completed By," you may incur additional assessment under (43 CFR 3163.1) and may also incur Civil Penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time for correction. Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20

Office: GS		ID: GS6995
Unique INC #: WTH-11-001	Well Name: DAYBREAK FEDERAL	
	Well #: 25-9BB(PL30)	ID Date: 10/18/10
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 10/18/10
Case #: COC33152	FAC ID:	Abatement Date: 10/18/10
Form: I	FAC NAME:	Corrected Date: 10/18/10
Assessment: \$0	Inspector: HOWELL	Followup Date: 11/01/10
Gravity: 3		Extend Date:
Authority Ref:		

Remarks Date: 10/18/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

CERTIFIED MAIL No: 7010 1060 0002 3108 7059 Return Receipt Requested EnCana Oil & Gas, Inc. Attn: Ms. RuthAnn Morss 370 17th Street, Ste 1700 Denver, CO 80202 October 15, 2010 NOTICE OF INCIDENT OF NONCOMPLIANCE (INC) Dear Ms. Morss: The surface casing setting depth for the following Daybreak Federal wells: 25-9, 30-11BB, 30-12, 30-12BB, and 30-13BB; was not set per the approved APD's or COA's. The Conditions of Approval concerning Daybreak Federal 30-12BB (PL30) in Step 10 require a triple combo log to be run on the subject well pad. This operation was to be accomplished before running surface casing; an open hole log must be run before running casing. This operation violates 43 CFR 3162.5 concerning the approved drilling plan. INCIDENTS OF NONCOMPLIANCE The following violations were identified during drilling operations on the following Daybreak Federal wells: 25-9, 30-11BB, 30-12, 30-12BB, and 30-13BB. Specifically: INC number WTH-11-001, 002, 003, 004, and 005: The surface casing setting depth of +/-1025 feet is not per the approved APD or COA's. Corrective Action: Submit a Sundry Notice for the Surface Casing setting depth for the PL30 pad subject wells. INC number WTH-11-006: The required triple combo log was not run as required on the Daybreak Federal 30-12BB. Corrective Action: Pull surface casing, run triple combo log, send log to Will Howell, CRVFO, for evaluation. In accordance with 43 CFR 3163.1 (a), please comply with the corrective action(s) for the identified environmental/drilling problems. Corrective actions for these violations were completed 10/14/2010.

WARNING Orders of the Authorized Officer or Incidents of Non Compliance and reporting time frames begin upon receipt of the Notice or 7 business days after the date it is mailed, whichever is earlier. Each problem or violation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management office at the address shown above. For Incidents of Non Compliance, please note that you already may have been assessed for noncompliance (see amount under "Assessed for Noncompliance"). If you do not comply as noted above "Corrective Action To Be Completed By," you may incur additional assessment under (43 CFR 3163.1) and may also incur Civil Penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time for correction. Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20

Office: HO		ID: HO13372
Unique INC #: 1003PS12I	Well Name: TEAS YATES UNIT TR 1	ID Date: 05/18/10
	Well #: 2	Effective Date:
Operator: MOMENTUM OPERATING CO INC		Abatement Date: 06/18/10
Case #: NMNM71049A	FAC ID:	Corrected Date: 11/03/10
Form: I	FAC NAME:	Followup Date: 07/21/10
Assessment: \$0	Inspector: SWARTZ	Extend Date: 11/15/10
Gravity: 3		
Authority Ref: 43 CFR 3161.2, 43 CFR 3162.1(a), 43 CFR 3162.4-2,(b), 43 CFR 3162.6		
Remarks Date: 05/18/10		
INC - "1003PS12I" for failure to comply with written order 1003PS12W as to the Mechanical Integrity Test : "Conduct a Mechanical Integrity Test of 500psig for 30 minutes on the injection tbg/csg annulus of the well. Document the test on no more than a 1,000psig calibrated recorder chart. Notify Paul R. Swartz at 575.234.5985 and/or 575.200.7902 at least 24 hours before the test. If there is no response, notify the BLM on call drilling phone, 575.361.2822. Submit a copy of the chart recorded and a Sundry Form 3160-005 relating the MIT activity to this BLM office. Reference this Written Order number 1003PS12W in the MIT Sundry text." Referenced Authority Regulation(s): 43 CFR 3161.2, 43 CFR 3162.1(a), 43 CFR 3162.4-2,(b), 43 CFR 3162.6 For regulation lookup quotes, or to secure necessary BLM forms go to: <a href="http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html">http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html</a> Sign and return this notice, providing a brief summary of your compliance in the space provided. Mail on or before June 18, 2010, to the address below: U.S. Department of Interior - Bureau of Land Management Carlsbad Field Office , Attn: Paul R. Swartz 620 East Greene Street Carlsbad, New Mexico 88220 Contact information: paul_swartz@nm.blm.gov 575-234-5985 office 575-234-5927 fax 575-200-7902 cell		

Office: HO		ID: HO13727
Unique INC #: 110THOB1	Well Name: NORTH LEA FEDERAL	ID Date: 02/17/11
	Well #: 12	Effective Date: 02/17/11
Operator: READ & STEVENS INCORPORATED		Abatement Date: 02/18/11
Case #: NMNM56264	FAC ID:	Corrected Date: 02/18/11
Form: I	FAC NAME:	Followup Date: 02/18/11
Assessment: \$0	Inspector: TORRES	Extend Date:
Gravity: 3		
Authority Ref: Onshore Order No. 2, III.A.2.b.iv.		
Remarks Date: 02/17/11		

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Pressure gauges in the well control system shall be of a type designed for drill fluid service. Replace pressure gauge with a type designed for drill fluid service.

Office: KM ID: KM1412  
Unique INC #: 11APP025V Well Name: CRAWFORD FEDERAL  
Well #: 1 ID Date: 02/23/11  
Operator: MATADOR RESOURCES COMPANY Effective Date: 02/23/11  
Case #: WYW174338 FAC ID: Abatement Date: 02/24/11  
Form: I FAC NAME: Corrected Date: 02/23/11  
Assessment: \$0 Inspector: PAT PRINGLE Followup Date: 02/23/11  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 2.III.A.2.g.

Remarks Date: 02/23/11

While conducting a detailed rig inspection it was found that the valve on the annular preventer that is used as a locking device was in the closed position. This valve needs to be maintained in the open position at all times and shall be closed only when the power source for the accumulator system is inoperative.

Office: KM ID: KM1411  
Unique INC #: 11APP024V Well Name: CRAWFORD FEDERAL  
Well #: 1 ID Date: 02/23/11  
Operator: MATADOR RESOURCES COMPANY Effective Date: 02/23/11  
Case #: WYW174338 FAC ID: Abatement Date: 02/24/11  
Form: I FAC NAME: Corrected Date: 02/23/11  
Assessment: \$0 Inspector: PAT PRINGLE Followup Date: 02/23/11  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 2.III.A.2.b.

Remarks Date: 02/23/11

While conducting a detailed inspection of the drilling rig it was found that the choke line was not anchored down to prevent whip and reduce vibration.

Office: RE ID: RE83  
Unique INC #: 10DCI004 Well Name: FLT  
Well #: 1 ID Date: 02/10/11  
Operator: EMERGENT VALUE GROUP LLC Effective Date: 02/10/11  
Case #: NVN080092 FAC ID: Abatement Date: 02/11/11  
Form: I FAC NAME: Corrected Date: 02/10/11  
Assessment: \$0 Inspector: CARTER Followup Date: 02/10/11  
Gravity: 1 Extend Date:  
Authority Ref: OO#2.III.A.2.e

Remarks Date: 02/10/11

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

POWER TO THE CLOSING UNIT PUMPS SHALL BE AVAILABLE AT ALL TIMES SO THAT THE PUMPS SHALL AUTOMATICALLY START WHEN THE CLOSING VALVE MANIFOLD PRESSURE HAS DROPPED TO THE PRE-SET LEVEL. AIR SUPPLY AND ELECTRICAL POWER WAS FOUND TURNED OFF AT TIME OF INSPECTION. VIOLATION WAS CORRECTED BY COMPANY MAN/TOOL PUSHER. NORMALLY, THIS VIOLATION WOULD BE AN IMMEDIATE ASSESSMENT (\$500/DAY, NOT TO EXCEED \$5000 (43 CFR 3163.1(b)(1).

Office: RE		ID: RE84
Unique INC #: 10DCI005	Well Name: FLT	
	Well #: 1	ID Date: 02/10/11
Operator: EMERGENT VALUE GROUP LLC		Effective Date: 02/10/11
Case #: NVN080092	FAC ID:	Abatement Date: 02/11/11
Form: I	FAC NAME:	Corrected Date: 02/10/11
Assessment: \$0	Inspector: CARTER	Followup Date: 02/10/11
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.A.2..b.i		

Remarks Date: 02/10/11

ALL CHOKE LINES SHALL BE STRAIGHT LINES UNLESS TURNS USE TEE BLOCKS OR ARE TARGETED WITH RUNNING TEES, AND SHALL BE ANCHORED TO PREVENT WHIP AND REDUCE VIBRATION. PANIC LINE WAS NOT HOOKED UP AS REQUIRED. TEE AT MUD GAUGE HAD NIPPLE OPEN ENDED AND DIRECTED BACK TOWARD RIG. REMOVE NIPPLE AND BULL PLUG OPENING. SEE ATTACHED PHOTO.

Office: RO		ID: RO8517
Unique INC #: 04-09-11I	Well Name: EVEREST FEDERAL	
	Well #: 2	ID Date: 10/05/10
Operator: MACK ENERGY CORPORATION		Effective Date: 10/27/10
Case #: NMNM121943	FAC ID:	Abatement Date: 11/17/10
Form: I	FAC NAME:	Corrected Date: 11/03/10
Assessment: \$0	Inspector: GARNAND	Followup Date: 11/08/11
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 10/05/10

Operator is being issued an incident of noncompliance for failure to comply with conditions of approval for the Application Permit to Drill. Operator has failed to build a barrier fence prior to construction of pad to protect archaeological site. Operator has also failed to build containment structures to protect the Duncan Tank and Playa located to the west of the pad. You must comply with both items before drilling rig is moved in, or before November 17, 2010. . Sign INC and return to the Roswell field office when you have complied.

Office: RW		ID: RW5189
Unique INC #: ML11001	Well Name: LISTER FEDERAL	
	Well #: 24-24D	ID Date: 10/25/10
Operator: ANADARKO E & P COMPANY LP		Effective Date: 10/22/10
Case #: WYW133702	FAC ID:	Abatement Date: 11/09/10
Form: I	FAC NAME:	Corrected Date: 10/29/10
Assessment: \$0	Inspector: LYON	Followup Date: 10/29/10
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 10/25/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Violation: Failed to Notify and request permission from Petroleum Engineer regarding Changes to the cement procedure for production casing.  
Abatement: Within 10 business days submit all reports of perforating and cementing of production casing to PE J. Dickinson. For all future activities changes to the APD and COAs must be approved by the Authorized Officer. Be advised that any future violations of this type will be subject to Civil Penalties under 43 CFR 3163.2

Office: RW ID: RW5244  
Unique INC #: ML110141 Well Name: EIGHTMILE  
Well #: 26-31 ID Date: 12/20/10  
Operator: WHITING OIL & GAS CORPORATION Effective Date: 12/20/10  
Case #: WYW172469 FAC ID: Abatement Date: 12/20/10  
Form: I FAC NAME: Corrected Date: 12/20/10  
Assessment: \$0 Inspector: LYON Followup Date: 12/20/10  
Gravity: 3 Extend Date:  
Authority Ref: OO #2 III. A. 2. g.

Remarks Date: 12/20/10

Violation: Valve not installed on the closing line of Annular preventer to act as a locking device. Corrective Action: Install valve on closing line of annular preventer as close to annular preventer as possible. Archie Fuller was notified of this violation and violation was corrected immediately. No further action is required at this time.

Office: RW ID: RW5241  
Unique INC #: ML110121 Well Name: EIGHTMILE  
Well #: 26-31 ID Date: 12/09/10  
Operator: WHITING OIL & GAS CORPORATION Effective Date: 12/09/10  
Case #: WYW172469 FAC ID: Abatement Date: 12/09/10  
Form: I FAC NAME: Corrected Date: 12/09/10  
Assessment: \$0 Inspector: LYON Followup Date: 12/09/10  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 12/09/10

Violation: Operator failed to submit Notification of Spud with in 24hrs as required in COA's. Corrective action: Submit spud notification form as required by COA's with in 24hrs. Spoke with Archie Fuller with Whiting about this issue. The issue has been corrected. No further action is required at this time.

Office: RW ID: RW5242  
Unique INC #: ML110131 Well Name: EIGHTMILE  
Well #: 26-31 ID Date: 12/09/10  
Operator: WHITING OIL & GAS CORPORATION Effective Date: 12/09/10  
Case #: WYW172469 FAC ID: Abatement Date: 12/09/10  
Form: I FAC NAME: Corrected Date: 12/09/10  
Assessment: \$0 Inspector: LYON Followup Date: 12/09/10  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 12/09/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Violation: Operator failed to notify BLM 24hrs in advance of running and cementing surface casing as required by COA's. Corrective action: Submit electronic notification form as required by COA's within 24hrs. Spoke to Archie Fuller with Whiting regarding this issue. Issue has been corrected. No further action is required at this time.

Office: RW		ID: RW5264
Unique INC #: PM1111	Well Name: WAMSUTTER	
	Well #: 7-14-20-94	
Operator: DEVON ENERGY PRODUCTION CO LP		
Case #: WYW139891	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MORGAN	
Gravity: 3		
Authority Ref: OO#2 III. A. 2. e.		

Remarks Date: 02/10/11

Violation: 2 out of the 3 air pumps on the accumulator were shut off while drilling below the surface casing shoe. Remedy: Turn on air supply to air pumps. NOTE: Violation was remedied on 2/10/2011 before inspector left drill site.

Office: RW		ID: RW5245
Unique INC #: PM1105	Well Name: FIVE MILE DITCH	
	Well #: 9-32-21-93	
Operator: DEVON ENERGY PRODUCTION CO LP		
Case #: WYW145716	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MORGAN	
Gravity: 3		
Authority Ref: OO#2 III.A.2.c.iii.		

Remarks Date: 12/27/10

Violation: Two independent sources of power not available for powering the closing unit pumps: Backup air powered pumps (air jammers) are installed, but air supply valves are closed. Remedy: Return air pumps to full operation. Note: Violation remedied immediately. Remedy witnessed by P. Morgan on 12/27/2010

Office: RW		ID: RW5243
Unique INC #: 11WS0002I	Well Name: CRESTON NOSE	
	Well #: 8-2-18-92	
Operator: DEVON ENERGY PRODUCTION CO LP		
Case #: WYW130678	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: SAUERESSIG	
Gravity: 3		
Authority Ref: OO2.III.A.2.i.viii. &OO2.III.A.2.i.xi.		

Remarks Date: 12/13/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Pipe and blind rams shall be activated each trip, however, this function need not be performed more than once a day. All of the above described tests and/or drills shall be recorded in the drilling log. Activate rams each trip and record in the drillers log.

Office: TU ID: TU25628  
Unique INC #: SRK2010 01 Well Name: HENCKEN UNIT A FED  
Well #: 6H ID Date: 11/04/10  
Operator: DEVON ENERGY PRODUCTION CO LP Effective Date: 11/04/10  
Case #: TXNM98256 FAC ID: Abatement Date: 11/06/10  
Form: I FAC NAME: Corrected Date: 11/06/10  
Assessment: \$250 Inspector: KIDD Followup Date: 11/06/10  
Gravity: 3 Extend Date:  
Authority Ref:

Remarks Date: 11/05/10

INC for not complying with a written order of the Authorized Officer (inc #1) did not notify adjudication staff 24 hrs prior to spud on Hencken Unit A 6H  
You are hereby assessed a fine of \$250.00 for not complying with the Conditions of Approval for Drilling th Hencken Unit A 6H

Office: TU ID: TU25630  
Unique INC #: SRK2010 03 Well Name: HENCKEN UNIT A FED  
Well #: 6H ID Date: 11/04/10  
Operator: DEVON ENERGY PRODUCTION CO LP Effective Date: 11/04/10  
Case #: TXNM98256 FAC ID: Abatement Date: 11/09/10  
Form: I FAC NAME: Corrected Date: 11/06/10  
Assessment: \$0 Inspector: KIDD Followup Date: 11/06/10  
Gravity: 3 Extend Date:  
Authority Ref:

Remarks Date: 11/04/10

Operator failed to comply with a written order of the Authorized Officer. Did not notify the Inspection & Enforcement Staff 48 hours prior to running casing, cementing casing, or testing the Blow Out Preventor Equipment.

Office: TU ID: TU25540  
Unique INC #: ZL2010-1 Well Name: HENCKEN UNIT A FED  
Well #: 3H ID Date: 08/13/10  
Operator: DEVON ENERGY PRODUCTION CO LP Effective Date: 08/13/10  
Case #: TXNM98256 FAC ID: Abatement Date: 08/20/10  
Form: I FAC NAME: Corrected Date: 10/06/10  
Assessment: \$0 Inspector: LAWRENCE Followup Date: 10/06/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 08/13/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Install well sign in a conspicuous place. The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or metes and bounds).

Office: VE ID: VE12918  
Unique INC #: CT10015 Well Name: ASHLEY FEDERAL  
Well #: 2 ID Date: 08/26/10  
Operator: VANTAGE ENERGY UNTA LLC Effective Date: 09/13/10  
Case #: UTU86335X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CADE TAYLOR  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1,(a)

Remarks Date: 08/26/10

THE ABOVE WELL WAS COMPLETED ON 11/15/2008, IT IS INDICATED IN THE APD THAT THE RESERVE PIT WOULD BE RECLAIMED WITHIN 120 DAYS OF THE COMPLETION OF THE WELL. PLEASE RECLAIM THE PIT.

Office: VE ID: VE12949  
Unique INC #: RA10052 Well Name: FEDERAL  
Well #: 7-11D-65 ID Date: 09/22/10  
Operator: BERRY PETROLEUM COMPANY Effective Date: 10/01/10  
Case #: UTU77330 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: R ARNOLD  
Gravity: 3  
Authority Ref: 43CFR3162.5-1(a)

Remarks Date: 09/22/10

The conditions of approval for the Application for Permit to Drill, and Berry Petroleums approved Standard Operating Practices, require this office 24 hours prior to the spud of a well.

Office: VE ID: VE12950  
Unique INC #: RA10053 Well Name: FEDERAL  
Well #: 7-11D-65 ID Date: 09/22/10  
Operator: BERRY PETROLEUM COMPANY Effective Date: 10/01/10  
Case #: UTU77330 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: R ARNOLD  
Gravity: 3  
Authority Ref: 43CFR3162.5-1(a)

Remarks Date: 09/22/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

The conditions of approval for the Application for Permit to Drill, and Berry Petroleum's approved Standard Operating Practices, require this office 24 hours prior to the running and cementing of any casing string.

Office: VE ID: VE12948  
Unique INC #: RA10051 Well Name: FEDERAL  
Well #: 7-11D-65 ID Date: 09/22/10  
Operator: BERRY PETROLEUM COMPANY Effective Date: 10/01/10  
Case #: UTU77330 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: R ARNOLD Abatement Date: 10/10/10  
Gravity: 3 Corrected Date: 10/08/10  
Authority Ref: 43CFR3162.6(a) Followup Date: 10/19/10  
Extend Date:

Remarks Date: 09/22/10

No well sign on location.

Office: VE ID: VE13002  
Unique INC #: SA11004 Well Name: GREATER MONUMENT BUTTE  
Well #: S-26-8-16 ID Date: 01/10/11  
Operator: NEWFIELD EXPLORATION COMPANY Effective Date: 01/11/11  
Case #: UTU87538X FAC ID:  
Form: I FAC NAME:  
Assessment: \$500 Inspector: STONEY ANDERTON Abatement Date: 01/11/11  
Gravity: 3 Corrected Date: 01/10/11  
Authority Ref: 43CFR3162.3-1(a) Followup Date: 02/07/11  
43CFR3163.1(b)(2) Extend Date:

Remarks Date: 01/10/11

The S-26-8-16 well was approved to be drilled on the 16-26-8-16 well pad (SE\SE Sec.26 T8S R16E). However the S-26-8-16 was mistakenly spud on the 9-26-8-16 well pad,(NE\SE Sec. 26 T8S R16E). This resulted in a new unnamed or numbered well being spud without prior approval. Therefore for drilling without prior approval, you are hereby assessed \$500.00. Billing is attached

Office: WO ID: WO2590  
Unique INC #: 11-OL-01 Well Name: SOUTH SPRING CREEK  
Well #: 87 ID Date: 10/29/10  
Operator: MARATHON OIL COMPANY Effective Date: 10/29/10  
Case #: WYW109710A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR Abatement Date: 10/30/10  
Gravity: 3 Corrected Date: 10/29/10  
Authority Ref: 43 CFR3162.5-1 Followup Date: 10/29/10  
Extend Date:

Remarks Date: 10/29/10

Safety and Drilling Related Violations (INCs) Issued During FY 2011 (10/1/10 to 3/3/11)  
As of March 3, 2011

Elec. Items in dog house not Explosion Proof, Coffee pot, water cooler, air cooler. Note at time of Insp. 60' from TD, and in H2S Zone.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: BA		ID: BA2907
Unique INC #: 03-012-10I	Well Name: Well #: 347A-10Z	ID Date: 07/30/10
Operator: OCCIDENTAL ELK HILLS INC	FAC ID:	Effective Date:
Case #: CACA38042	FAC NAME:	Abatement Date: 09/09/10
Form: I	Inspector: 3 GABE GARCIA	Corrected Date: 09/01/10
Assessment: \$0		Followup Date: 09/01/10
Gravity: 3		Extend Date:
Authority Ref:		

Remarks Date: 07/30/10

United States Department of the Interior Bureau of Land Management Bakersfield Field Office 3801 Pegasus Drive Bakersfield, California 93308-6837                   www.ca.blm.gov/bakersfield CERTIFIED MAIL RETURN RECEIPT REQUESTED 3100(P) CACA38042 LLCA-C06000.90 03-012-10I Occidental of Elk Hills, Inc. 10800 Stockdale Highway Bakersfield, CA 93311 Attn: Shawn Kerns Dear Mr. Kerns, This Notice of Incident of Noncompliance (INC) by the Authorized Officer is to inform you that your company did not comply with conditions of approval (see attached) set forth in your application for permit to drill on well 347A-10Z. The following is a list of violations that occurred July 21, 2010 on rig H&P 262. Proper notification was not given for the required BOP test. In our approval it clearly states that you shall give advance notice of 24 hours for all BOP tests for 3M and larger systems. In this instance notification was given 4 hours prior to the test and was given on the incorrect phone line. BOP testing was attempted without a BLM inspector and the test was being held for 5 minutes when it should have been held for 10 minutes. (in accordance with Onshore Order # 2 see attached) In talking with company reps, it is quite apparent that they are not aware of our regulations set forth in onshore order # 2, and that they had not read their permit for specific guidance on BOP testing. Some were even unaware that they were working on a BLM well. Unfortunately, this has become somewhat of a recurring theme with regards to Oxy federal wells where BOP testing is required. This is the third such instance in the past couple of years where Oxy has not notified BLM properly for required BOP tests. In previous instances we tried to take care of the problem at the field level by talking with and training company drilling representatives in the proper way to conduct drilling operations on federal leases. These informal talks and training sessions have apparently not worked, and I feel we need to take a look at how we can address these issues to ensure overall public safety. In order to fulfill the requirements of this INC we would like a letter back from you detailing the steps taken by your company to resolve these issues. This letter must be received by our office within 30 days of your receipt of this INC and no later than September 9, 2010. Your letter should have documentation of any meetings or training sessions you have with staff in regards to BLM drilling requirements. Failure to comply with the specifications of this Incident of Non-Compliance in the future may result in an assessment for continued non-compliance pursuant to 43 CFR 3163.1(a)(1) or 43 CFR 3163.1(a)(2). If you should need additional time to comply with this order, please contact our office for authorization to avoid further compliance actions. You have the right to request a State Director Review of the provisions of this letter, pursuant to 43 CFR 3165.3(b), and if

Office: BU		ID: BU16081
Unique INC #: MB-3-10	Well Name: FEDERAL	ID Date: 01/19/10
	Well #: 13-32	Effective Date: 01/20/10
Operator: TREND EXPLORATION I, LLC	FAC ID:	Abatement Date: 02/17/10
Case #: WYW129512	FAC NAME:	Corrected Date: 01/27/10
Form: I	Inspector: BLAKESLEY	Followup Date: 03/24/10
Assessment: \$0		Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 01/19/10

The well sign is incorrect. The Township reads 55N. It should read Township 56N.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: BU		ID: BU13566
Unique INC #: MB-09-13	Well Name: W GAS DRAW BETA SORENSEN RANCH	
	Well #: 21-19	ID Date: 11/25/08
Operator: LANCE OIL + GAS CO INC	FAC ID:	Effective Date: 11/15/08
Case #: WYW137635	FAC NAME:	Abatement Date: 12/01/08
Form: I		Corrected Date: 12/03/09
Assessment: \$0	Inspector: BLAKESLEY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: COA's		

Remarks Date: 11/25/08

The divertor line is only 20' long. You must have a 30' divertor line, made of non-flammable material, and it must be staked down in two places.

Office: BU		ID: BU16234
Unique INC #: AB-10-10	Well Name: CABIN CREEK IV CB	
	Well #: R/11CC-27	ID Date: 03/04/10
Operator: PINNACLE GAS RESOURCES, INC	FAC ID:	Effective Date: 01/29/10
Case #: WYW149629	FAC NAME:	Abatement Date: 03/10/10
Form: I		Corrected Date: 03/10/10
Assessment: \$0	Inspector: BREWER	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: C.O. A. in APD		

Remarks Date: 03/04/10

Failure to notify this office of spud as required in C.O.A within APD

Office: BU		ID: BU16091
Unique INC #: DC10-004	Well Name: DRY WILLOW 3	
	Well #: 13-12	ID Date: 01/20/10
Operator: ANADARKO PETROLEUM CORP	FAC ID:	Effective Date: 01/21/10
Case #: WYW163057X	FAC NAME:	Abatement Date: 01/22/10
Form: I		Corrected Date: 01/22/10
Assessment: \$0	Inspector: CORK	Followup Date: 01/25/10
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval For Coal Bed Natural Gas Drilling and Production Operations, 1.3		

Remarks Date: 01/20/10

A field inspection of drilling operations by the MJ#1 rig at the Dry Willow 3 #13-12 showed the flowline exiting the diverter at 90 degrees. This situation was discussed off location with Anadarko's Tim Gimbel at 12:40 on 1/20/10 at which time the flowline was being evaluated. On 1/21/10, 14:45, Tim was notified via phone that the flowline was an Incident of Noncompliance. Corrective Action: Eliminate any angle on the flowline to provide a straight run of the flowline used by the MJ#1 rig. This will be done prior to drilling out the surface casing shoe on the next Federal well drilled by the MJ#1 rig, Dry Willow 3 #12-23

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: BU		ID: BU16036
Unique INC #: JNE-012-10	Well Name: SIMPSON RANCH FEDERAL	
	Well #: 23-10	ID Date: 12/17/09
Operator: LOWRY EXPLORATION INC	FAC ID:	Effective Date: 12/17/09
Case #: WYW128539	FAC NAME:	Abatement Date: 12/17/09
Form: I	Inspector: EVANS	Corrected Date: 12/17/09
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 III. D		

Remarks Date: 12/17/09

On 12/16/2009 a drill stem test was opened after daylight hours. No corrective action is required since the test is over. All future tests shall follow the Drill Stem Testing Requirements.

Office: BU		ID: BU15810
Unique INC #: JNE-10-10	Well Name: LAMBDA RHO ANADARKO	
	Well #: 6-34R	ID Date: 10/06/09
Operator: ANADARKO PETROLEUM CORP	FAC ID:	Effective Date: 10/13/09
Case #: WYW162879	FAC NAME:	Abatement Date: 11/30/09
Form: I	Inspector: EVANS	Corrected Date: 12/15/09
Assessment: \$5,000		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43CFR3163.1(b)(2)		

Remarks Date: 10/06/09

11/2/2006 Anadarko moved the drilling location of the Lambda RHO Anadarko to a new location and drilled the well without approval. A new APD cover sheet for this must be submitted along with a survey plot showing the corrected drilling location. A correct API number and well name will be reported for this well.

Office: BU		ID: BU16793
Unique INC #: MH1044IP	Well Name: WDU DELTA WILLIAMS DU	
	Well #: 43-34	ID Date: 07/13/10
Operator: LANCE OIL + GAS CO INC	FAC ID:	Effective Date: 07/13/10
Case #: WYW146611X	FAC NAME:	Abatement Date: 08/06/10
Form: I	Inspector: HAINES	Corrected Date: 07/14/10
Assessment: \$0		Followup Date: 07/27/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a) (b)		

Remarks Date: 07/13/10

Violation: The drill site was not properly identified ( No well sign ). Correction: You shall install the proper well sign with all the required information on it by 8/6/2010. If there are any questions contact Mark Haines at 307-684-1065 or Jerry Walker at 307-684-1167.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: BU ID: BU15975  
Unique INC #: RN-10-47A Well Name: BORIS FEDERAL COM ID Date: 12/03/09  
Well #: 5 Effective Date: 12/03/09  
Operator: YATES PETROLEUM CORP Abatement Date: 12/03/09  
Case #: WYW133594 FAC ID: Corrected Date: 12/03/09  
Form: I FAC NAME: Followup Date: 12/03/09  
Assessment: \$1,500 Inspector: NAVARRETTE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1(b)

Remarks Date: 12/04/09

The hand wheels on the BOP were not installed. All equipment (BOPE) must be installed, used, maintain, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Drill out date 12/1/09. Hand wheels were install 12/3/09

Office: BU ID: BU15974  
Unique INC #: RN-10-45A Well Name: BORIS FEDERAL COM ID Date: 12/03/09  
Well #: 5 Effective Date: 12/03/09  
Operator: YATES PETROLEUM CORP Abatement Date: 12/03/09  
Case #: WYW133594 FAC ID: Corrected Date: 12/03/09  
Form: I FAC NAME: Followup Date: 12/03/09  
Assessment: \$1,500 Inspector: NAVARRETTE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR3163.1(b) (1)

Remarks Date: 12/04/09

The kill line was not installed. All equipment (BOPE) must be installed, used, maintain, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Drill out date 12/1/09. Kill line was installed 12/3/09.

Office: BU ID: BU16877  
Unique INC #: RN-10-200 Well Name: DIAMOND RUN IBERLIN ID Date: 07/15/10  
Well #: 23-6 Effective Date: 07/15/10  
Operator: WOLD OIL PROPERTIES, INC Abatement Date: 07/19/10  
Case #: WYW34743 FAC ID: Corrected Date: 07/21/10  
Form: I FAC NAME: Followup Date: 07/21/10  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.5-2(a)

Remarks Date: 07/15/10

This well not have a valve on the 7" casing and its blowing gas. You must install valve on the well. Wold was called at 307-265-7252 Mr. Otteman said he would get a valve on the well today..

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: BU		ID: BU16945
Unique INC #: RN-10-203	Well Name: DIAMOND RUN IBERLIN	
	Well #: 12-5*	ID Date: 08/30/10
Operator: WOLD OIL PROPERTIES, INC		Effective Date: 08/30/10
Case #: WYW34743	FAC ID:	Abatement Date: 08/30/10
Form: I	FAC NAME:	Corrected Date: 08/30/10
Assessment: \$500	Inspector: NAVARRETTE	Followup Date: 08/30/10
Gravity: 3		Extend Date:
Authority Ref: COA and the APD		

Remarks Date: 08/31/10

They were drilling without the rubber in the diverter. You must have the rubber in the diverter at all times when drilling. They installed the rubber when inspector was on location. The operator representative Joe Corbitt was on location and was told about the assessment for failure to have a working diverter when drilling.

Office: BU		ID: BU16878
Unique INC #: RN-10-201	Well Name: DIAMOND RUN IBERLIN	
	Well #: 23-6	ID Date: 07/15/10
Operator: WOLD OIL PROPERTIES, INC		Effective Date: 07/15/10
Case #: WYW34743	FAC ID:	Abatement Date: 07/19/10
Form: I	FAC NAME:	Corrected Date: 07/21/10
Assessment: \$0	Inspector: NAVARRETTE	Followup Date: 07/21/10
Gravity: 1		Extend Date:
Authority Ref: COA / APD		

Remarks Date: 07/15/10

The well does not cement to surface. You must log the well for cement top and do the remedial cementing. You must call Rafael Navarrette at (307) 684-1165 or 217-0740 prior to logging or cementing. Wold was called at 307-265-7252 Mr. Otteman was told about violations.

Office: BU		ID: BU16879
Unique INC #: RN-10-202	Well Name: DIAMOND RUN IBERLIN	
	Well #: 23-6	ID Date: 07/15/10
Operator: WOLD OIL PROPERTIES, INC		Effective Date: 07/15/10
Case #: WYW34743	FAC ID:	Abatement Date: 07/19/10
Form: I	FAC NAME:	Corrected Date: 07/21/10
Assessment: \$0	Inspector: NAVARRETTE	Followup Date: 07/21/10
Gravity: 3		Extend Date:
Authority Ref: COA / APD		

Remarks Date: 07/15/10

The drilling pits are not fenced . You must fence the drilling pits and keep them fence until pit are closed. Wold was called at 307-265-7252 Mr. Otteman was told about violations.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: BU ID: BU15818  
Unique INC #: CR10-01DI Well Name: FEDERAL ID Date: 10/20/09  
Well #: 14-35 Effective Date: 10/28/09  
Operator: C & H WELL SERVICING INC Abatement Date: 11/30/09  
Case #: WYW101101 FAC ID: Corrected Date: 11/30/09  
Form: I FAC NAME: Followup Date: 11/30/09  
Assessment: \$0 Inspector: ROSS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (b)

Remarks Date: 10/20/09

The well sign does not have the correct well location. The Qtr Qtr on the sign says NENE and the footage survey in the APD indicates that the well is in the SWNE quarter section. To correct this violation comply with the regulations in 43 CFR 3162.6 (b).

Office: BU ID: BU15856  
Unique INC #: CR10-02-DI Well Name: GLEASON FEDERAL ID Date: 11/02/09  
Well #: 41-15 Effective Date: 11/10/09  
Operator: TRUE OIL LLC Abatement Date: 11/10/09  
Case #: WYW138116 FAC ID: Corrected Date: 11/03/09  
Form: I FAC NAME: Followup Date: 11/03/09  
Assessment: \$0 Inspector: ROSS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3161.2 and Onshore Order No. 2 III C. 7.

Remarks Date: 11/02/09

The flare line from the choke manifold does not extend 100 feet from the well head. To correct this violation comply with Onshore Order No. 2, III C. 7.

Office: BU ID: BU15857  
Unique INC #: CR10-03-DI Well Name: GLEASON FEDERAL ID Date: 11/02/09  
Well #: 41-15 Effective Date: 11/10/09  
Operator: TRUE OIL LLC Abatement Date: 11/10/09  
Case #: WYW138116 FAC ID: Corrected Date: 11/03/09  
Form: I FAC NAME: Followup Date: 11/03/09  
Assessment: \$500 Inspector: ROSS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3161.2 and Onshore Order No. 2 III A. 2. iii.

Remarks Date: 11/02/09

The kill line is not installed. To correct this violation comply with Onshore Order No. 2, III A. 2. iii.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: BU ID: BU15817  
Unique INC #: 10MRW002 Well Name: CARR DRAW V / IIA CARU ID Date: 10/19/09  
Well #: 12-17GW Effective Date: 10/27/09  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 11/27/09  
Case #: WYW150647X FAC ID: Corrected Date: 11/26/09  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WARREN, MATTHEW Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.0-9(c)(1)

Remarks Date: 10/19/09

Operator has not submitted a Well Completion Report for this well. Operator has 30 days to submit this report.

Office: BU ID: BU15816  
Unique INC #: 10MRW001 Well Name: CARR DRAW V / IIA CARU ID Date: 10/19/09  
Well #: 12-17GW Effective Date: 10/19/09  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 10/19/09  
Case #: WYW150647X FAC ID: Corrected Date: 10/19/09  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WARREN, MATTHEW Extend Date:  
Gravity: 3  
Authority Ref: General COA #5

Remarks Date: 10/19/09

Operator failed to notify the Buffalo Field Office 24 hours prior to spudding this well. No corrective action is required.

Office: CA ID: CA3066  
Unique INC #: JM-REC-09 Well Name: EAST BIG MUDDY ID Date: 05/07/09  
Well #: W-1 Effective Date: 05/07/09  
Operator: RANCHER ENERGY CORPORATION Abatement Date: 06/19/09  
Case #: WYW109493A FAC ID: Corrected Date: 05/05/10  
Form: I FAC NAME: Followup Date: 06/19/09  
Assessment: \$0 Inspector: MESROBIAN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 05/07/09

Failed to respond from an Order of the Authorized Officer dated 3/23/09. The Order explained to Rancher Energy Corporation to perform a Mechanical Integrity Test (MIT) to prove good wellbore integrity for Temporarily Abandoned approval, or submit a plug and abandoned procedure. You now have until 6/19/09 to initiate either procedure. However, failure to respond with this Incident of Noncompliance will result with a monetary assessment, a bond increase, and a plug and abandonment of this well.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: CA		ID: CA3335
Unique INC #: 10JM0001I	Well Name: BR FEDERAL	
	Well #: 44-4H	ID Date: 12/23/09
Operator: SOUTHWESTERN PRODUCTION CORP		Effective Date: 12/23/09
Case #: WYW178860	FAC ID:	Abatement Date: 12/29/09
Form: I	FAC NAME:	Corrected Date: 12/29/09
Assessment: \$0	Inspector: MESROBIAN	Followup Date: 12/29/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3160 OO#2 III.B.i.		

Remarks Date: 12/23/09

Operator failed to do a pressure integrity test. Any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Formation at the shoe shall be tested to a minimum of the mud weight equivalent anticipated to control the formation pressure to the next casing depth or at total depth of the well. The test shall be performed before drilling more than 20 feet of new hole. If this procedure is not implemented on the next drilled hole then drilling will not commence until its done according to Federal regulations.

Office: CB		ID: CB21666
Unique INC #: 10LB008I	Well Name: POSEIDON 3 FEDERAL	
	Well #: 18	ID Date: 05/19/10
Operator: CIMAREX ENERGY CO OF COLORADO		Effective Date: 06/01/10
Case #: NMNM074937	FAC ID:	Abatement Date: 06/04/10
Form: I	FAC NAME:	Corrected Date: 07/14/10
Assessment: \$0	Inspector: BRUMLEY	Followup Date: 07/15/10
Gravity: 3		Extend Date: 07/30/10
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 05/19/10

Failure to comply with the Application for Permit to Drill (APD) conditions of approval part VII.B.. "Changes to the approved APD casing and cement program require submitting a sundry and receiving approval prior to work. Failure to obtain approval prior to work will result in an Incident of Non-Compliance being issued." APD approved the spudding of a 14 3/4" hole. Well was spudded with a 16" hole on 5/18/2010, casing cemented on 5/19/2010 and sundry submitted requesting change to hole size and cement program on May 21, 2010. Corrective action will be deemed complete upon return of signed I&E copy of Incident of Noncompliance. Any questions may be addressed to: Legion Brumley 575-234-5957 legion\_brumley@nm.blm.gov

Office: CB		ID: CB21871
Unique INC #: 10LB015I	Well Name: LIMOUSINE 15CD FED	
	Well #: 1H	ID Date: 08/11/10
Operator: MEWBOURNE OIL COMPANY		Effective Date: 08/18/10
Case #: NMNM104640	FAC ID:	Abatement Date: 09/10/10
Form: I	FAC NAME:	Corrected Date: 08/19/10
Assessment: \$0	Inspector: BRUMLEY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 08/11/10

Conditions of Approval section VII.A.2. of the Approved Application to Drill (3160-3) for the above referenced well stated that "Unless the production casing has been run and cemented...the drilling rig shall not be removed from over the hole without prior approval." According to the subsequent report the rig was released on 6/10/10, and the production casing was cemented on 6/18/2010. Remedial Action: Submit amended Well Completion Report form 3160-4 following the instructions for properly filling out boxes 30 and 31. Ensure that boxes 30 and 31 are filled out on form 3160-4, also submit details of each stage of the frac treatment.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: CB		ID: CB21870
Unique INC #: 10LB014I	Well Name: LAKEWOOD 34 FEDERAL IP	
	Well #: 1H	ID Date: 08/11/10
Operator: MEWBOURNE OIL COMPANY		Effective Date: 08/18/10
Case #: NMNM31200	FAC ID:	Abatement Date: 09/10/10
Form: I	FAC NAME:	Corrected Date: 08/19/10
Assessment: \$0	Inspector: BRUMLEY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 08/11/10

Conditions of Approval section VII.A.2. of the Approved Application to Drill (3160-3), for the above referenced well, stated that "Unless the production casing has been run and cemented...the drilling rig shall not be removed from over the hole without prior approval." According to the subsequent report the rig was released on 5/26/10, and the production casing was cemented on 6/2/2010. Remedial Action: Submit amended Well Completion Report form 3160-4 following the instructions for properly filling out boxes 30 and 31. Ensure that boxes 30 and 31 are filled out on form 3160-4, also submit details of each stage of the frac treatment.

Office: CB		ID: CB21514
Unique INC #: 10LB003I	Well Name: DICKENS 29 FEDERAL	
	Well #: 3H	ID Date: 02/04/10
Operator: DEVON ENERGY PRODUCTION CO L P		Effective Date: 02/04/10
Case #: NMNM54856	FAC ID:	Abatement Date: 02/04/10
Form: I	FAC NAME:	Corrected Date: 02/17/10
Assessment: \$0	Inspector: BRUMLEY	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1(a) OO#1 IV.		

Remarks Date: 02/04/10

Under section 5 of the Drilling Program in the APD, testing with the rig pumps to 1000psi was declined and the Conditions of Approval were referenced. Conditions of Approval section VII.C.4. were not followed. The BOPE was tested with the rig pumps to 1000psi and the test was not recorded on a calibrated test chart. There is no remedial action for this violation. Sign and return the INC to the above address, to the attention: Legion Brumley

Office: CB		ID: CB21788
Unique INC #: 10-KC-53	Well Name:	
	Well #:	ID Date: 06/29/10
Operator: NORDSTRAND ENGINEERING INC		Effective Date: 07/13/10
Case #: NMLC050797	FAC ID: B	Abatement Date: 08/13/10
Form: I	FAC NAME: 14 FED 3 BATTERY	Corrected Date: 08/31/10
Assessment: \$0	Inspector: CAFFALL	Followup Date: 08/05/10
Gravity: 3		Extend Date: 09/07/10
Authority Ref: 43 CFR 3162.1(a) O. O. 6.III.D.2.e		

Remarks Date: 06/29/10

Wind Direction Indicator O. O. 6.III.D.2.e e. At least 1 permanent wind direction indicator shall be installed so that wind direction can be easily determined at or approaching the storage tank(s). Corrective Action: Install wind direction indicator as per Onshore Order #6. Inquiries/correspondence pertaining to this Order can be directed to:

Management

Caffall

88220

Bureau of Land  
Attention: Lead PET Roy 'Kent'  
620 E Greene St  
Phone # (575) 234-5906  
Carlsbad, NM

Safety and Drilling Related Violations (INC's) Issued During FY 2010  
As of March 3, 2011

Office: CB		ID: CB21787
Unique INC #: 10-KC-52	Well Name:	
	Well #:	
Operator: NORDSTRAND ENGINEERING INC		
Case #: NMLC050797	FAC ID: A	ID Date: 06/29/10
Form: I	FAC NAME: 13 FED 16 BATTERY	Effective Date: 07/13/10
Assessment: \$0	Inspector: CAFFALL	Abatement Date: 08/13/10
Gravity: 3		Corrected Date: 08/31/10
Authority Ref: 43 CFR 3162.1(a)	O. O. 6.III.D.2.e	Followup Date: 08/05/10
		Extend Date: 09/07/10

Remarks Date: 06/29/10

Wind Direction Indicator O. O. 6.III.D.2.e e. At least 1 permanent wind direction indicator shall be installed so that wind direction can be easily determined at or approaching the storage tank(s). Corrective Action: Install wind direction indicator as per Onshore Order #6. Inquiries/correspondence pertaining to this Order can be directed to:

Management Attention: Lead PET Roy 'Kent'  
Caffall 620 E Greene St Carlsbad, NM  
88220 Phone # (575) 234-5906

Office: CB		ID: CB21847
Unique INC #: 10-KC-55	Well Name:	
	Well #:	
Operator: DORAL ENERGY CORP		
Case #: NMLC062407	FAC ID: B	ID Date: 07/07/10
Form: I	FAC NAME: ATSEL FED #1 BATTERY	Effective Date: 08/01/10
Assessment: \$0	Inspector: CAFFALL	Abatement Date: 08/30/10
Gravity: 3		Corrected Date: 08/26/10
Authority Ref: 43 CFR 3162.1(a)	O. O. 6.III.D.2.e	Followup Date: 09/07/10
		Extend Date:

Remarks Date: 07/07/10

No Wind Direction Indicator on subject facility. O. O. 6.III.D.2.e e. At least 1 permanent wind direction indicator shall be installed so that wind direction can be easily determined at or approaching the storage tank(s). Corrective Action: Install wind direction indicator as per Onshore Order #6. Inquiries/correspondence pertaining to this Order can be directed to:

Management Attention: Lead PET Roy 'Kent'  
Caffall 620 E Greene St Carlsbad, NM  
88220 Phone # (575) 234-5906

Office: CB		ID: CB21633
Unique INC #: 10-DHW-002	Well Name: FEDERAL COM 13	
	Well #: 2	
Operator: CIMAREX ENERGY CO OF COLORADO		
Case #: NMNM72243	FAC ID:	ID Date: 05/04/10
Form: I	FAC NAME:	Effective Date: 05/14/10
Assessment: \$0	Inspector: CAFFALL	Abatement Date: 06/11/10
Gravity: 3		Corrected Date: 06/11/10
Authority Ref: 43 CFR 3162.1(a)		Followup Date: 06/21/10
		Extend Date:

Remarks Date: 05/04/10

3162.1 General requirements. (a) The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. Per Subsequent Report on the referenced well Conditions of Approval on Notice of Intent approved on 3/15/2010 stated to notify BLM 24 hours prior to setting CIBP's above the Atoka & Morrow, setting a 210' plug across the top of the Morrow from 11140' to 10930'. Corrective Action: Plug back Morrow zone as approved. Contact BLM @ 575-361-2822 a minimum of 24 hours prior to plug back operations for a BLM representative to witness plug placement. Contact: Dusty Winkler 620 E Greene St Carlsbad, NM 88220 575-234-5914 Dustin\_Winkler@nm.blm.gov

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: CB ID: CB21677  
Unique INC #: 10-RC-I31 Well Name: NORTH PURE GOLD 8 FEDERAL ID Date: 05/27/10  
Well #: 13 Effective Date: 05/27/10  
Operator: DEVON ENERGY PRODUCTION CO L P Abatement Date: 05/27/10  
Case #: NMNM77046 FAC ID: Corrected Date: 05/28/10  
Form: I FAC NAME: Followup Date: 05/28/10  
Assessment: \$0 Inspector: CARRASCO Extend Date:  
Gravity: 1  
Authority Ref: OO#2.III.A.2.a.v  
  
Remarks Date: 05/27/10  
ALL BOPE CONNECTIONS SUBJECT TO WELL PRESSURE SHALL BE WELDED, CLAMPED, OR FLANGED.....REPLACE ALL CONNECTIONS THAT DO NOT MEET FEDERAL REGULATIONS STANDARDS.

Office: CB ID: CB21674  
Unique INC #: 10-RC-I28 Well Name: NORTH PURE GOLD 8 FEDERAL ID Date: 05/27/10  
Well #: 13 Effective Date: 05/27/10  
Operator: DEVON ENERGY PRODUCTION CO L P Abatement Date: 05/28/10  
Case #: NMNM77046 FAC ID: Corrected Date: 05/27/10  
Form: I FAC NAME: Followup Date: 05/27/10  
Assessment: \$0 Inspector: CARRASCO Extend Date:  
Gravity: 3  
Authority Ref: OO #2.III.A.2.v  
  
Remarks Date: 05/27/10  
CHOKE MANIFOLD HAS 2 CHOKES INSTALLED.....10M BOPE SYSTEM REQUIRES AT A MINIMUM 3 CHOKES BE INSTALLED ON MANIFOLD....INSTALL 3RD CHOKE IMMEDIATELY.

Office: CB ID: CB21676  
Unique INC #: 10-RC-I30 Well Name: NORTH PURE GOLD 8 FEDERAL ID Date: 05/27/10  
Well #: 13 Effective Date: 05/27/10  
Operator: DEVON ENERGY PRODUCTION CO L P Abatement Date: 05/28/10  
Case #: NMNM77046 FAC ID: Corrected Date: 05/28/10  
Form: I FAC NAME: Followup Date: 05/28/10  
Assessment: \$0 Inspector: CARRASCO/BRUMLEY Extend Date:  
Gravity: 3  
Authority Ref: OO#2.III.A.2.b.i.  
  
Remarks Date: 05/27/10  
ALL CHOKELINES SHALL BE STRAIGHT LINES UNLESS TURNS USE TEE BLOCKS OR ARE TARGETED WITH RUNNING TEES, AND SHALL BE ANCHORED TO PREVENT WHIP AND REDUCE VIBRATION REPLACE ALL BLIND TEES WITH RUNNING TEES OR USE TEE BLOCKS.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: CB		ID: CB21282
Unique INC #: 10DC002	Well Name: RUSSELL USA	
	Well #: 3	ID Date: 11/16/09
Operator: APOLLO ENERGY L P		Effective Date: 11/18/09
Case #: NMLC050797	FAC ID:	Abatement Date: 12/27/09
Form: I	FAC NAME:	Corrected Date: 11/23/09
Assessment: \$0	Inspector: CARTER	Followup Date: 11/30/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a); 43 CFR 3162.3-2(a)		

Remarks Date: 11/16/09

43 CFR 3162.3-2(a) THE WORK WAS DONE TO THE WELL BEFORE THE NOTICE OF INTENT (NOI) WAS SUBMITTED THE BLM FOR APPROVAL AND TO RECEIVE THE CONDITIONS OF APPROVAL FOR THE WORK TO BE DONE. RECTIFY BY SUBMITTING THE SPECIFICATIONS OF THE CASING, THE CEMENT PROGRAM, THE CEMENTER'S REPORT, THE CIT TEST CHART (IF CIT RUN), A COMPLETION REPORT, AND INFORMATION ON WHAT IS BEING INJECTED AND WHETHER IS FROM ON OR OFF LEASE. IF A CIT WAS NOT RUN AT THE TIME THE CASING WAS SET, A MIT IS TO BE COMPLETED AFTER A NOI (NOTICE OF INTENT) IS SUBMITTED AND APPROVED, WITH A BLM PET TO WITNESS. BASED ON THE RESPONSE TO THESE REQUIREMENTS, FURTHER REQUIREMENTS MAY BE ADDED. ANY QUESTIONS, CONTACT DUSTIN WINKLER, ENGINEER AT 575-234-5914 OR DARRELL CARTER, PET, AT 234-5950

Office: CB		ID: CB21691
Unique INC #: 10DC008	Well Name: DICKENS 29 FEDERAL	
	Well #: 3H	ID Date: 06/08/10
Operator: DEVON ENERGY PRODUCTION CO L P		Effective Date: 06/08/10
Case #: NMNM54856	FAC ID:	Abatement Date: 07/14/10
Form: I	FAC NAME:	Corrected Date: 07/01/10
Assessment: \$0	Inspector: CARTER	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 06/08/10

FAILURE TO CEMENT PRODUCTION CASING PRIOR TO MOVING DRILLING RIG PER COA. CORRECTIVE ACTION REQUIRED: RUN A CBL AND PRESENT A PROCEDURE FOR FUTURE OPERATIONS INVOLVING THE CEMENTING OF THE PRODUCTION CASING USING A WELL SERVICING UNIT. IF YOU HAVE ANY QUESTIONS, CONTACT WESLEY INGRAM AT 575-234-5982

Office: CB		ID: CB21518
Unique INC #: 10-TC-011	Well Name: JAMES RANCH UNIT	
	Well #: 108H	ID Date: 02/09/10
Operator: BOPCO LP		Effective Date: 02/18/10
Case #: NMNM02884A	FAC ID:	Abatement Date: 03/18/10
Form: I	FAC NAME:	Corrected Date: 03/04/10
Assessment: \$0	Inspector: CARTWRIGHT	Followup Date: 03/16/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a) / O.O.#2.III.B.1.h.		

Remarks Date: 02/09/10

9 5/8" CASING WASN'T TESTED TO THE REQUIRED .22 PSI/FT WITH A MINIMUM OF 1500 PSI. RECTIFY BY SUBMITTING THE SPECIFICATIONS OF THE CASING USED - FOUND DISCREPANCY BECAUSE THERE IS NO 40# 9 5/8" HCP-110 IN THE REDBOOK. NEED DETAILS.

Safety and Drilling Related Violations (INC's) Issued During FY 2010  
As of March 3, 2011

Office: CB ID: CB21519  
Unique INC #: 10-TC-012 Well Name: JAMES RANCH UNIT  
Well #: 108H ID Date: 02/09/10  
Operator: BOPCO LP Effective Date: 02/18/10  
Case #: NMNM02884A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CARTWRIGHT Abatement Date: 04/05/10  
Gravity: 3 Corrected Date: 03/04/10  
Authority Ref: 43CFR3162.1(a) / 43CFR3162.3-2(a) Followup Date: 03/16/10  
Extend Date:

Remarks Date: 02/09/10

A NOI TO CHANGE CASING ON THE FIRST AND SECOND INTERMEDIATE WAS NOT RECEIVED. THE CASING PUT IN THE WELL, AND CEMENTED IN PLACE WAS NOT WHAT WAS APPROVED IN THE APD. RECTIFY BY SUBMITTING A RADIAL CBL TO VERIFY THAT THERE IS ADEQUATE PROTECTION.

Office: CB ID: CB21852  
Unique INC #: 10CD80 Well Name: POKER LAKE UNIT  
Well #: 302H ID Date: 07/30/10  
Operator: BOPCO LP Effective Date: 08/07/10  
Case #: NMNM0506A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: DE MONTIGNY Abatement Date: 08/15/10  
Gravity: 3 Corrected Date: 08/13/10  
Authority Ref: 43 CFR 3162.1(a), COA I.C4. Followup Date: 09/21/10  
Extend Date:

Remarks Date: 07/30/10

FAILURE TO GIVE 4 HOUR NOTIFICATION PRIOR TO TESTING BOP EQUIPMENT, PER CONDITIONS OF APPROVAL I.C.4. "THE APPROPRIATE BLM OFFICE SHALL BE NOTIFIED A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS THE TESTS." CORRECTIVE ACTION: OPERATOR IS REQUIRED TO FOLLOW CONDITIONS OF APPROVAL AS STATED IN THE APPROVED APPLICATION FOR PERMIT TO DRILL 3160-3. THIS VIOLATION WILL BE REDEEMED WHEN BLM RECEIVES SIGNED COPY OF THIS NOTICE OF INCIDENTS OF NONCOMPLIANCE.

Office: CB ID: CB21293  
Unique INC #: 10RH12 Well Name: DELIAH  
Well #: 1 ID Date: 11/24/09  
Operator: PROBITY OPERATING LLC Effective Date: 11/24/09  
Case #: NMNM103591 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HOSKINSON Abatement Date: 11/24/09  
Gravity: 3 Corrected Date: 11/24/09  
Authority Ref: 43CFR3162.1(a) AAPD & COA'S Followup Date: 11/25/09  
Extend Date:

Remarks Date: 11/24/09

ALTERING OR CHANGING CASING DESIGN WITHOUT PRIOR APPROVAL. OPERATOR MAY RESUME OPERATIONS AFTER RECEIVING APPROVED SUNDAY FOR CASING ALTERATIONS OR DESIGN.

Safety and Drilling Related Violations (INC's) Issued During FY 2010  
As of March 3, 2011

Office: CB		ID: CB21585
Unique INC #: 10-DW-01	Well Name: FEDERAL 23	
	Well #: 4	ID Date: 03/12/10
Operator: OXY USA INCORPORATED		Effective Date: 04/21/10
Case #: NMNM62589	FAC ID:	Abatement Date: 05/21/10
Form: I	FAC NAME:	Corrected Date: 05/07/10
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 05/10/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3162.1(a), O.O.#2.III.A.2.i.ii, COA.VII.C.2		

Remarks Date: 03/12/10

O.O.#2.III.A.2.i.ii. Ram type preventers and associated equipment shall be tested to approved (see item I.D.1. of this order) stack working pressure if isolated by test plug or to 70 percent of internal yield pressure of casing if BOP stack is not isolated from casing. Per Sundry Notice 3160-5 submitted on 03/03/10 & pressure chart received 3/29/10 pipe rams & associated equipment were tested to 1500 p.s.i.. Test should have been performed @ 3000 p.s.i.. Blind rams were not shown to be tested. Corrective Action: Sign Incident of Noncompliance Form3160-9, return to above address, and conduct future Blow Out Preventer Equipment tests per Onshore Orders, Conditions of Approval, & other Orders of the Authorized Officer. Any questions contact: Dusty Winkler 620 E Greene St Carlsbad, NM 88220 575-234-5914

Office: CB		ID: CB21434
Unique INC #: 10RH14	Well Name: NASH UNIT	
	Well #: 29	ID Date: 01/11/10
Operator: XTO ENERGY INC		Effective Date: 01/14/09
Case #: NMNM70992C	FAC ID:	Abatement Date: 01/29/10
Form: I	FAC NAME:	Corrected Date: 01/29/10
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 02/19/10
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.1(a) & COA'S		

Remarks Date: 01/11/10

VIOLATION : FAILURE TO PLUGBACK WELL PER CONDITIONS OF APPROVAL. CORRECTIVE ACTION : DRILL OUT PLUGS & SET ALL PLUGS PER CONDITIONS OF APPROVAL.(SEE ATTACHMENT) ANY QUESTIONS CONTACT : WESLEY INGRAM, PETROLEUM ENGINEER, 620 E. GREENE STREET, CARLSBAD NM, 88220, 575-234-5982

Office: CB		ID: CB21215
Unique INC #: 10RH01	Well Name: LONGVIEW FEDERAL 1	
	Well #: 14	ID Date: 10/23/09
Operator: RKI EXPLORTION AND PRODUCTION		Effective Date: 10/23/09
Case #: NMNM91078	FAC ID:	Abatement Date: 11/27/09
Form: I	FAC NAME:	Corrected Date: 10/23/09
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 12/14/09
Gravity: 3		Extend Date:
Authority Ref: APD & COA'S		

Remarks Date: 10/23/09

Changes to the approved APD casing & cement program require submitting a Sundry and receiving approval prior to commencing work. Failure to obtain Approval prior to work will result in an Incident of Non-Compliance being Issued. SUBMIT SUNDRY 3160-5 PRIOR TO CHANGIING OR ALTERING APPROVED CASING DESIGN.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: CB		ID: CB21878
Unique INC #: 10PS0823I	Well Name: MOBIL FEDERAL	
	Well #: 2, 9	ID Date: 08/23/10
Operator: OXY USA INCORPORATED		Effective Date:
Case #: NMNM0281482A	FAC ID:	Abatement Date: 09/23/10
Form: I	FAC NAME:	Corrected Date: 09/28/10
Assessment: \$0	Inspector: SWARTZ	Followup Date: 09/29/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 08/23/10

The requirement for at least one correct legible well sign to be installed and maintained in a conspicuous place from the spud date until final abandonment is being violated at the listed wells: Install the required signs and remove any incorrect signs. The following is an example of satisfactory well sign information: BLANK OIL COMPANY Blank FEDERAL WELL NO. 2 ????F?L & ???F?L, SEC ??, T??S, R??E API 30 015 ????? Lease: NM???????? Reason: 1 - Authority Reference: 43 CFR 3162.6(b) For regulation lookup quotes, or to secure necessary BLM forms go to: [http://www.blm.gov/nm/st/en/prog/energy/oil\\_and\\_gas.html](http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html)

Office: CB		ID: CB21173
Unique INC #: 0910PRS01	Well Name: PINTAIL 23 FEDERAL COM	
	Well #: 5Y	ID Date: 10/01/09
Operator: CIMAREX ENERGY CO OF COLORADO		Effective Date:
Case #: NMNM19423	FAC ID:	Abatement Date: 10/26/09
Form: I	FAC NAME:	Corrected Date: 10/22/09
Assessment: \$0	Inspector: SWARTZ	Followup Date: 11/02/09
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 2.III.B1.h		

Remarks Date: 10/01/09

In your subsequent report of 09.28.09, the entry for 06.04.09 is "Pressure-tested surface casing to 1000 psi for 30 minutes." The minimum pressure test for this casing at this depth calculates to be 1500 psi for 30 minutes. The 8 5/8" surface casing and 5 1/2" intermediate annulus has been cemented and this test cannot be duplicated at the required pressure. It is necessary that these tests be conducted as per Onshore Order 2.III.B.1.h. Submit your plan to accomplish that objective.

Office: CB		ID: CB21879
Unique INC #: 10PS0824I	Well Name: FEDERAL 23	
	Well #: 9	ID Date: 08/23/10
Operator: OXY USA INCORPORATED		Effective Date:
Case #: NMNM62589	FAC ID:	Abatement Date: 09/23/10
Form: I	FAC NAME:	Corrected Date: 09/28/10
Assessment: \$0	Inspector: SWARTZ	Followup Date: 09/29/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 08/23/10

The requirement for at least one correct legible well sign to be installed and maintained legible in a conspicuous place from the spud date until final abandonment is being violated at the listed well. Install the required signs and remove any incorrect signs. The following is an example of satisfactory well sign information: BLANK OIL COMPANY Blank FEDERAL WELL NO. 2 ????F?L & ???F?L, SEC ??, T??S, R??E API 30 015 ????? Lease: NM???????? For regulation lookup quotes, or to secure necessary BLM forms go to: [http://www.blm.gov/nm/st/en/prog/energy/oil\\_and\\_gas.html](http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html)

Safety and Drilling Related Violations (INC's) Issued During FY 2010  
As of March 3, 2011

Office: CB		ID: CB21880
Unique INC #: 10PS0825I	Well Name: FEDERAL 23	
	Well #: 6	ID Date: 08/23/10
Operator: OXY USA INCORPORATED		Effective Date:
Case #: NMNM62589	FAC ID:	Abatement Date: 09/23/10
Form: I	FAC NAME:	Corrected Date: 09/28/10
Assessment: \$0	Inspector: SWARTZ	Followup Date: 09/29/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 08/23/10

The requirement for at least one correct legible well sign to be installed and maintained legible in a conspicuous place from the spud date until final abandonment is being violated at the listed well. Install the required sign and remove any incorrect sign. The following is an example of satisfactory well sign information: BLANK OIL COMPANY Blank FEDERAL WELL NO. 2 ???F?L & ???F?L, SEC ??, T??S, R??E API 30 015 ????

Lease: NM????????

Office: CB		ID: CB21368
Unique INC #: 10-TT-006	Well Name: SKELLY UNIT	
	Well #: 626	ID Date: 11/13/09
Operator: COG OPERATING LLC		Effective Date: 11/14/09
Case #: NMLC029419A	FAC ID:	Abatement Date: 11/14/09
Form: I	FAC NAME:	Corrected Date: 12/30/09
Assessment: \$0	Inspector: TUCKER	Followup Date: 01/14/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)/APD COA'S		

Remarks Date: 11/13/09

FAILURE TO COMPLY W/APD CONDITIONS OF APPROVAL, FAILURE TO NOTIFY AUTHORIZED OFFICER OF BOP/BOPE TEST AFTER SUFFICIENT WOC ON INTERMEDIATE CASING JOB. THE BLM IS TO NOTIFIED A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS BOP/BOPE TEST. RETESTING OF ALL BOPE EQUIPMENT WILL BE REQUIRED.

Office: CB		ID: CB21363
Unique INC #: 10-TT-001	Well Name: SKELLY UNIT	
	Well #: 626	ID Date: 11/13/09
Operator: COG OPERATING LLC		Effective Date: 11/14/09
Case #: NMLC029419A	FAC ID:	Abatement Date: 11/14/09
Form: I	FAC NAME:	Corrected Date: 12/30/09
Assessment: \$0	Inspector: TUCKER	Followup Date: 01/14/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)/APD COA'S		

Remarks Date: 11/13/09

FAILURE TO COMPLY W/APD CONDITIONS OF APPROVAL, FAILURE TO NOTIFY AUTHORIZED OFFICER OF WELL SPUD. THE BLM IS TO NOTIFIED A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS SPUDDING WELL.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: CB ID: CB21367  
Unique INC #: 10-TT-005 Well Name: SKELLY UNIT ID Date: 11/13/09  
Well #: 626 Effective Date: 11/14/09  
Operator: COG OPERATING LLC Abatement Date: 11/14/09  
Case #: NMLC029419A FAC ID: Corrected Date: 12/30/09  
Form: I FAC NAME: Followup Date: 01/14/09  
Assessment: \$0 Inspector: TUCKER Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1(a)/APD COA'S  
  
Remarks Date: 11/13/09

FAILURE TO COMPLY W/APD CONDITIONS OF APPROVAL, FAILURE TO NOTIFY AUTHORIZED OFFICER OF BOPE TEST AFTER SUFFICIENT WOC ON SURFACE CASING JOB. THE BLM IS TO NOTIFIED A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS INTERMEDIATE CASING JOB.

Office: CB ID: CB21365  
Unique INC #: 10-TT-003 Well Name: SKELLY UNIT ID Date: 11/13/09  
Well #: 626 Effective Date: 11/14/09  
Operator: COG OPERATING LLC Abatement Date: 11/14/09  
Case #: NMLC029419A FAC ID: Corrected Date: 12/30/09  
Form: I FAC NAME: Followup Date: 01/14/10  
Assessment: \$0 Inspector: TUCKER Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1(a)/APD COA'S  
  
Remarks Date: 11/13/09

FAILURE TO COMPLY W/APD CONDITIONS OF APPROVAL, INSUFFICIENT WOC PRIOR TO DRILLING OUT SURFACE CASING SHOE. ALL WOC TIMES SHALL BE 18HRS OR TIME TO REACH 500PSI COMPRESSIVE STRENGTH WHICH EVER IS GREATER.

Office: CB ID: CB21366  
Unique INC #: 10-TT-004 Well Name: SKELLY UNIT ID Date: 11/13/09  
Well #: 626 Effective Date: 11/14/09  
Operator: COG OPERATING LLC Abatement Date: 11/14/09  
Case #: NMLC029419A FAC ID: Corrected Date: 12/30/09  
Form: I FAC NAME: Followup Date: 01/14/10  
Assessment: \$0 Inspector: TUCKER Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1(a)/APD COA'S  
  
Remarks Date: 11/13/09

FAILURE TO COMPLY W/APD CONDITIONS OF APPROVAL, FAILURE TO NOTIFY AUTHORIZED OFFICER OF INTERMEDIATE CASING JOB. THE BLM IS TO NOTIFIED A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS INTERMEDIATE CASING JOB.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: CB		ID: CB21305
Unique INC #: 10-TT-01	Well Name: DELIAH	
	Well #: 1	ID Date: 11/27/09
Operator: PROBITY OPERATING LLC		Effective Date: 12/04/09
Case #: NMNM103591	FAC ID:	Abatement Date: 12/22/09
Form: I	FAC NAME:	Corrected Date: 12/07/09
Assessment: \$0	Inspector: TUCKER	Followup Date: 12/30/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR3162.1(a) OO#2.III.B		

Remarks Date: 11/27/09

43 CFR 3162.1 General requirements.(a) The operating rights owner or operator,as appropriate, shall comply with applicable laws and regulations;with the lease terms, Onshore Oil and Gas Orders, NTL s; and with other orders and instructions of the authorized officer. Onshore Order #2.III.B The proposed casing and cementing programs shall be conducted as approved to protect and/or isolate all usable water zones, potentially productive zones, lost circulation zones, abnormally pressured zones, and any prospectively valuable deposits of minerals. Any isolating medium other than cement shall receive approval prior to use. Pea gravel was approved only for obtaining 10 feet of fill. Corrective action; Submit a narrative of all remedial cementing operations conducted on the 13 3/8 surface casing of this well.

Office: CB		ID: CB21658
Unique INC #: 10TW04	Well Name: PLU BIG SINKS 11 FEDERAL	
	Well #: 1H	ID Date: 05/18/10
Operator: CHESAPEAKE OPERATING INC		Effective Date: 05/18/10
Case #: NMLC068905	FAC ID:	Abatement Date: 05/18/10
Form: I	FAC NAME:	Corrected Date: 05/19/10
Assessment: \$0	Inspector: WILSON	Followup Date: 09/27/10
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.1(a) AAPD COA's		

Remarks Date: 05/18/10

Drilling with out approval for a Flex Hose. With out approved variance.All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, and shall be anchored to prevent whip and reduce vibration. Corrective Action; Submitt Sundry 3165-5 for flex hose Issued Written Order Number 10TW03 on 5/2/2010. Failed to comply.

Office: CC		ID: CC1585
Unique INC #: RG10LP061	Well Name: MATRIX	
	Well #: 13-29, 14-29	ID Date: 04/06/10
Operator: MATRIX ENERGY LLC		Effective Date:
Case #: COC74095	FAC ID:	Abatement Date: 05/21/10
Form: I	FAC NAME:	Corrected Date: 05/11/10
Assessment: \$20,000	Inspector: LPETERSON	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.3-1(c)(d)		

Remarks Date: 04/06/10

The Matrix #13-29 (API#0512326095) and #14-29 (API#0512326094) wells were directionally drilled under the railroad Special Act ROW Lease COC73129, into federal minerals. Violation is for building a location and drilling two federal wells without an approved Application for Permit to Drill (APD). The violation is in excess of 10 days. CORRECTIVE ACTION REQUIRED: Complete APDs (with \$6500 APD fee per well) shall be submitted within 30 days of receipt of this Incident of Non-compliance which includes the required information needed to complete the APD review. The Cultural inventory: By 06/25/2010 submit a complete Cultural Report with field site inventory of all access roads, drill pads, and any other areas of surface disturbance that has occurred. Report must be completed by an Archaeologist which has been certified to conduct such surveys for the BLM. It is the operator's responsibility to assure that the Archaeologist has legal permission to access the site to conduct the survey. - Submit a signed Communitization Agreement application, with spacing order. These two wells have been assigned a CA number of COC74095. - Bill #2010034336 is attached to the INC. Payment is due 05/21/2010. Questions should be directed to Leslie Peterson at 719-269-8566.

Safety and Drilling Related Violations (INC's) Issued During FY 2010  
As of March 3, 2011

Office: CR		ID: CR1316
Unique INC #: RW10-13	Well Name: BUTTER LAKE FEDERAL	
	Well #: 32-10	ID Date: 08/01/10
Operator: ENTEK GRB LLC	FAC ID:	Effective Date: 08/08/10
Case #: COC63212X	FAC NAME:	Abatement Date:
Form: I	Inspector: WALLIS	Corrected Date: 08/08/10
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3262.1		

Remarks Date: 08/01/10

Ken Bull of Entek advised me on 07/30/2010 that cementing of surface pipe on this well would begin late on 07/31/2010. Prior to leaving to witness that work, I received a message from Jubil Terry about changing the depth of the surface casing. I obtained that approval and called him. In the course of that conversation, I asked him about the well status in regards to the surface pipe cementing. He said that they were circulating waiting on BLM approval for depth change. He further volunteered to have Ken call me two hours before cementing was to begin. I did not require further notification but welcomed it, thinking that perhaps there had been a delay. I did not receive the promised call. As result, the BLM did not in effect receive notification of the cementing as required and did not witness it. By all accounts the cementing was problem free, hence there is no abatement and/or practical remedy. This INC is to emphasize that such miscommunication not happen again.

Office: DK		ID: DK6427
Unique INC #: IDB09004	Well Name: USA	
	Well #: 24-4	ID Date: 09/02/09
Operator: JP OIL COMPANY INCORPORATED	FAC ID: A	Effective Date: 09/10/09
Case #: NDM88441	FAC NAME: USA 24-4	Abatement Date: 10/10/09
Form: I	Inspector: DEBBIE BOHLMAN	Corrected Date: 10/05/09
Assessment: \$0		Followup Date: 10/14/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3164.1	Onshore Order #6 III.D.3.e	

Remarks Date: 09/02/09

Wind direction indicator is not able to blow freely in the wind (see attached photo). Wind direction indicator on tanks is wrapped around the walkway and there is no wind direction indicator on pole at entrance to location. Either fix the wind direction indicator on tanks or install wind direction indicator on pole at entrance to location. The green copy of this Notice of Incidents of Noncompliance is the operator copy.

Office: FE		ID: FE15454
Unique INC #: 10AVJ006	Well Name: ROSA UNIT SWD	
	Well #: 2	ID Date: 08/29/10
Operator: WILLIAMS PRODUCTION CO LLC	FAC ID:	Effective Date: 08/29/10
Case #: NMSF078768	FAC NAME:	Abatement Date: 08/30/10
Form: I	Inspector: JAMISON	Corrected Date: 09/11/10
Assessment: \$0		Followup Date: 09/14/10
Gravity: 1		Extend Date:
Authority Ref: OO#2 III A.(1)		

Remarks Date: 08/29/10

BOPE MANAFOLD CHOKES VALVES LEAKING REPLACE AND TEST BEFOR DRILLING OUT INTERMEDIATE CSG. MUST HAVE CHART BY THIRD PARTY. MUST NOTIFY BLM 24hr's PRIOR TO TESTING NEW VALVES FAILER TO REPLACE VALVES WILL RESULT IN IMMEDIATE ASSESSMENT UNDER 43CFR 3163.1(b)(1) assessment begins 8/29/10

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: FE		ID: FE15167
Unique INC #: 10JIR008	Well Name: STORY B LS	
	Well #: 4	ID Date: 12/09/09
Operator: BP AMERICA PRODUCTION CO.		Effective Date: 12/30/09
Case #: NMNM73415	FAC ID: 4	Abatement Date: 01/20/10
Form: I	FAC NAME: STORY B LS	Corrected Date: 01/13/10
Assessment: \$0	Inspector: RUYBALID	Followup Date: 01/13/10
Gravity: 3		Extend Date:
Authority Ref: 3162.5-3 Onshore Order 6		

Remarks Date: 12/16/09

Onshore Oil and Gas Order No. 6, Hydrogen Sulfide Operation III. Requirements The authorized officer may, after consideration of all appropriate factors, vary from those specified actions of this Order that he/she determines to be necessary to protect public health and safety, the environment, or to maintain control of a well to prevent waste of Federal mineral resources. A. Applications, Approvals, and Reports A.2 Production "The operator shall initially test the H<sub>2</sub>S concentration of the gas stream for each well or production facility and shall make the results available to the authorized officer upon request." In the course of production of the well, if H<sub>2</sub>S is detected in the gas stream by the pipeline company, the Farmington Field Office is requesting notification of the test results, including the concentration of H<sub>2</sub>S at the wellhead for each well located on a federal lease. 3162.5-3 Safety precautions The operator shall perform operations and maintain equipment in a safe and workmanlike manner. The operator shall take all precautions necessary to provide adequate protection for the health and safety of life and the protection of property. Compliance with health and safety requirements prescribed by the authorized officer shall not relieve the operator of the responsibility for compliance with other pertinent health and safety requirements under applicable laws or regulations.

Office: GJ		ID: GJ6793
Unique INC #: EF10074	Well Name: CALF CANYON	
	Well #: 25-3	ID Date: 08/05/10
Operator: MARALEX RESOURCES INCORPORATED		Effective Date: 08/24/10
Case #: COC10373	FAC ID: 25-3	Abatement Date: 09/14/10
Form: I	FAC NAME:	Corrected Date: 09/01/10
Assessment: \$0	Inspector: FANCHER	Followup Date: 10/05/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5		

Remarks Date: 08/05/10

We noticed a leak on the wellhead during our last inspection. Have it repaired by the date indicated.

Office: GJ		ID: GJ6704
Unique INC #: EF10002	Well Name: FEDERAL	
	Well #: 1-15	ID Date: 12/28/09
Operator: HRM RESOURCES LLC		Effective Date: 01/11/10
Case #: COC28029	FAC ID: 1-15	Abatement Date: 01/21/10
Form: I	FAC NAME:	Corrected Date: 01/15/10
Assessment: \$0	Inspector: FANCHER	Followup Date: 01/20/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6.2		

Remarks Date: 12/28/09

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

The operator shall perform operations and maintain equipment in a safe and workmanlike manner. You are required to repair the gas leak on the simplex.

Office: GJ ID: GJ6738  
Unique INC #: EF10040 Well Name:  
Well #:  
Operator: MARALEX RESOURCES INCORPORATED  
Case #: COC47655A FAC ID: 20-1  
Form: I FAC NAME: FEDERAL  
Assessment: \$0 Inspector: FANCHER  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3

ID Date: 04/20/10  
Effective Date: 05/10/10  
Abatement Date: 05/30/10  
Corrected Date: 06/17/10  
Followup Date:  
Extend Date:

Remarks Date: 04/20/10

The operator shall perform operations in a safe and workmanlike manner. The operator shall take all precautions necessary to provide adequate protection for the health and safety of life and the protection of property. Your pit fence and berm requires repairs. Use Onshore Order 7 for a guide in maintaining your pits.

Office: GR ID: GR1669  
Unique INC #: 10TFC01 Well Name: HORSESHOE BASIN UNIT  
Well #: 1-4H  
Operator: DEVON ENERGY PRODUCTION CO  
Case #: WYW163027X FAC ID:  
Form: I FAC NAME:  
Assessment: \$4,500 Inspector: CARTMELL  
Gravity: 1  
Authority Ref: 3160.1(b)(1)

ID Date: 08/06/10  
Effective Date: 08/06/10  
Abatement Date: 08/09/10  
Corrected Date: 08/09/10  
Followup Date: 08/09/10  
Extend Date:

Remarks Date: 08/06/10

Failure to install 10M annular INC letter written

Office: GR ID: GR1568  
Unique INC #: HN1001 Well Name: MONELL UNIT  
Well #: 43-10  
Operator: ANADARKO E&P COMPANY LP  
Case #: 891008645A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NEWSHAM  
Gravity: 3  
Authority Ref: 43CFR3163.1(a)

ID Date: 04/04/10  
Effective Date: 04/04/10  
Abatement Date: 04/04/10  
Corrected Date: 04/04/10  
Followup Date:  
Extend Date:

Remarks Date: 04/04/10

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Failure to comply with Approved APD for surface cement quality and quantity. APD pg2, Drilling Program, lead and tail cement.

Office: GR ID: GR1604  
Unique INC #: 10HN0002 Well Name: CANYON CREEK UNIT  
Well #: 13B-4D ID Date: 06/10/10  
Operator: WEXPRO Effective Date: 06/10/10  
Case #: WYW094531X Abatement Date: 06/10/10  
Form: I FAC ID: Corrected Date: 06/10/10  
Assessment: \$0 FAC NAME: Followup Date: 06/11/10  
Gravity: 3 Inspector: NEWSHAM Extend Date:  
Authority Ref: Onshore Order #2.III.A.g  
  
Remarks Date: 06/10/10  
Valve not installed in the closing side of the annular preventer

Office: GR ID: GR1552  
Unique INC #: 2010-6-MRT Well Name:  
Well #: ID Date: 01/27/10  
Operator: GRYNBERG JACK J Effective Date: 01/27/10  
Case #: WYW147046 FAC ID: 1-34 Abatement Date: 01/27/10  
Form: I FAC NAME: 1-34 Corrected Date: 09/02/10  
Assessment: \$5,000 Inspector: TYLER Followup Date: 07/21/10  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3163.1(b)(2)  
  
Remarks Date: 01/27/10  
43 CFR3163.1(b)(2) For drilling without approval or causing surface disturbance on Federal or Indian surface preliminary to drilling without approval, \$500 per day for each day that the violation existed, including the days the violation existed prior to discovery, not to exceed \$5000.

Office: GS ID: GS6789  
Unique INC #: 100032 Well Name: JOLLY FED  
Well #: 12D-20-691(#12) ID Date: 02/16/10  
Operator: BILL BARRETT CORPORATION Effective Date: 02/16/10  
Case #: COC70803 FAC ID: Abatement Date: 02/16/10  
Form: I FAC NAME: Corrected Date: 02/16/10  
Assessment: \$0 Inspector: FICKLIN Followup Date: 02/16/10  
Gravity: 1 Extend Date:  
Authority Ref: O.O. #2 III. A. 2. e.  
  
Remarks Date: 02/16/10

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Minimum standards and enforcement provision for power availability. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. The air line valve to the accumulator air pump was found in the closed position. Corrective Action: turn the air valve to the open position and maintain it in the open position in order that the air pump(s) will automatically start when closing valve manifold pressure decreases to the pre-set level.

Office: GS		ID: GS6773
Unique INC #: 100015	Well Name: FEDERAL RWF	
	Well #: 431-30(171-19)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC70819	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. B. f.		

Remarks Date: 11/25/09

Surface casing shall have centralizers on the bottom 3 joints of the casing (a minimum of 1 centralizer per joint, starting with the shoe joint). The centralizers were not recorded in the Driller Daily Log (IADC). Corrective Action: Provide proof that centralizers were used as required and record their use in the IADC. Provide copies of the IADC to this office showing the centralizers used. Proof was provided and the IADC was updated on 11/25/2009 and copies were faxed to this office on 11/25/2009.

Office: GS		ID: GS6771
Unique INC #: 100013	Well Name: FEDERAL RWF	
	Well #: 431-30(171-19)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC70819	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. B. 1. h.		

Remarks Date: 11/25/09

All casing below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10 percent in 30 minutes, corrective action shall be taken. The testing of the casing was not recorded in the Drillers Daily Log (IADC Book). Corrective Action: Perform casing test as required and record results in the Drillers Daily Log (IADC Book). Provide this office with copies of the IADC verifying that the test has been conducted and properly recorded. The verification of the Casing Test was provided and the results were recorded in the IADC Book on 11/25/2009. Copies of the IADC book were faxed to this office on 11/25/2009.

Office: GS		ID: GS6848
Unique INC #: DEG-10-04	Well Name: FEDERAL RWF	
	Well #: 312-19 (12-19)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC42344	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: GEYER	
Gravity: 1		
Authority Ref: 43CFR3162.5		

Remarks Date: 06/24/10

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

June 24, 2010 CERTIFIED MAIL No. 7009 3410 0000 4678 0472 Return Receipt Requested Williams Production RMT CO Attn: Julie Tannehill Howard Harris Greg Davis Jay Foreman 1515 Arapahoe Street Tower 3, suite 1000 Denver, CO 80202 NOTICE OF INCIDENTS OF NONCOMPLIANCE (INC) Dear Ms. Tannehill: For the RWF 312-19 (NWSW Sec. 19, T6S, R94W), it was found that operations were not being conducted in a manner designed to protect the mineral resources, other natural resources, and environmental quality (43 CFR 3162.5), due to hydraulic fracturing occurring too close to the cement top, which was in violation of the authorized officer's conditions of approval. INCIDENTS OF NONCOMPLIANCE The following violation was identified during a review of the RWF 312-19: INC number DEG-10-04: Williams failed to follow the conditions of approval, required by the authorized officer, by hydraulically fracturing above 7450'. No corrective action is required. On 12/4/2010, Williams requested a verbal approval, via email, from Dane Geyer (CRVFO) to proceed with remedial work to bring cement above the Mesaverde - prior to the MVIII stage (top perforation at 7211'). The top of quality cement was at 7030' with a few stringers above. On 12/17/2010, Dane Geyer granted verbal approval, via email, to proceed with the outlined plan, with a condition of approval prohibiting hydraulically fracturing above 7450' due to a low cement top. On 6/22/2010, Williams notified Dane Geyer of the cement squeeze results (as required in the previously mentioned conditions of approval), provided a log identifying the new cement top, and requested to hydraulically fracture the MV4-MV6 stages. Upon this request, Dane Geyer requested Williams to provide evidence of receiving a variance to hydraulically fracture above 7450' since it was apparent that the MVIII stage had been already hydraulically fractured. On 6/23/2010 (the same day of the request for information by Dane Geyer) Williams notified Dane Geyer, via email and telephone, and stated no request was granted and Williams had mistakenly hydraulically fractured above the specified depth. Title 43 CFR 3162.5-1(a) states, "The operator shall conduct operations in a manner which protects the mineral resources, other natural resources, and environmental quality. In that respect, the operator shall comply with the pertinent orders of the authorized officer and other standards and procedures as set forth in the applicable laws, regulations, lease terms and conditions, and the approved drilling plan or subsequent operations plan". WARNING Orders of the Authorized Officer or Incidents of Noncompliance and reporting time frames begin upon receipt of the Notice or 7 business days after the date it is mailed, whichever is earlier. Each problem or violation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management office at the address shown above. For Incidents of Noncompliance,

Office: GS		ID: GS6803
Unique INC #: 100046	Well Name: WARREN FEDERAL	
	Well #: 15-16BB (PI15)	
Operator: ENCANA OIL & GAS (USA) INC		
Case #: COC01524	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: GIBOO	
Gravity: 3		
Authority Ref: O.O.#2 III.B.1.d.		

Remarks Date: 03/02/10

The surface casing shall be cemented back to surface either during the primary cement job or by remedial cementing. d. All of the above described tests shall be recorded in the drilling log. While setting surface casing, the cement to surface was not recorded in the IADC (drillers log). Corrective action: Perform the necessary test or provide documentation and record in the IADC.

Office: GS		ID: GS6775
Unique INC #: 100017	Well Name: GMU	
	Well #: 27-8C2 (H27NW)	
Operator: ENCANA OIL & GAS (USA) INC		
Case #: COC56608A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: GIBOO	
Gravity: 3		
Authority Ref: O.O. #2 III. A. 2. xi.		

Remarks Date: 12/11/09

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Pipe and blind rams shall be activated each trip, however, this function need not be performed more than once a day. All of the above described tests and/or drills shall be recorded in the drilling log (IADC). There was no record of activation of the pipe rams during trips recorded in the drilling log.  
Corrective Action: Activated the pipe rams and record the action in the drilling log (IADC).

Office: GS ID: GS6776  
Unique INC #: 100018 Well Name: GMU  
Well #: 27-8C2 (H27NW)  
Operator: ENCANA OIL & GAS (USA) INC ID Date: 12/11/09  
Case #: COC56608A Effective Date: 12/12/09  
Form: I FAC ID:  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: GIBOO  
Authority Ref: O.O. #2 III. A. 2. xi.  
Followup Date: 12/15/09  
Abatement Date: 12/13/09  
Corrected Date: 12/12/09  
Extend Date: 12/15/09

Remarks Date: 12/11/09

Pipe and blind rams shall be activated each trip, however, this function need not be performed more than once a day. All of the above described tests and/or drills shall be recorded in the drilling log (IADC). There was no record of activation of the blind rams during trips recorded in the drilling log.  
Corrective Action: Activated the blind rams and record the action in the drilling log (IADC).

Office: GS ID: GS6774  
Unique INC #: 100016 Well Name: GMU  
Well #: 27-8C2 (H27NW)  
Operator: ENCANA OIL & GAS (USA) INC ID Date: 12/11/09  
Case #: COC56608A Effective Date: 12/11/09  
Form: I FAC ID:  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: GIBOO  
Authority Ref: O.O. #2 III. A. 2. xi.  
Followup Date: 12/15/09  
Abatement Date: 12/12/09  
Corrected Date: 12/12/09  
Extend Date: 12/15/09

Remarks Date: 12/11/09

Annular preventer shall be functionally operated at least weekly. All of the above described tests and/or drills shall be recorded in the drilling log (IADC). There was no record of functioning the annular recorded in the drilling log. Corrective Action: Functionally operate the annular and record the action in the drilling log (IADC).

Office: GS ID: GS6966  
Unique INC #: 100206 Well Name: GGU FEDERAL  
Well #: 23C-28-691 (#9)  
Operator: BILL BARRETT CORPORATION ID Date: 07/28/10  
Case #: COC52447A Effective Date: 07/28/10  
Form: I FAC ID:  
Assessment: \$0 FAC NAME:  
Gravity: 1 Inspector: MOTEN  
Authority Ref: O.O. #2. III. A. 2. b. i.  
Followup Date: 08/02/10  
Abatement Date: 07/31/10  
Corrected Date: 07/31/10  
Extend Date: 08/02/10

Remarks Date: 07/28/10

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, and shall be anchored to prevent whip and reduce vibration. Several bolts not fully threaded on choke line flange. Corrective Action: Install bolts as required.

Office: GS		ID: GS6967
Unique INC #: 100207	Well Name: GGU FEDERAL	
	Well #: 23C-28-691 (#9)	
Operator: BILL BARRETT CORPORATION		
Case #: COC52447A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MOTEN	
Gravity: 3		
Authority Ref: O.O. #2. III. A. 2. i. viii		

Remarks Date: 07/28/10

Pipe and blind rams shall be activated each trip, however, this function need not be performed more than once a day. Pipe rams not activated during trip as required. Corrective action: Perform the necessary test or provide documentation.

Office: GS		ID: GS6808
Unique INC #: 100051	Well Name: JOLLY FED	
	Well #: 11B-20-691(#12)	
Operator: BILL BARRETT CORPORATION		
Case #: COC70803	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MOTEN	
Gravity: 3		
Authority Ref: O.O. #2. III. A. 2. i. viii		

Remarks Date: 03/11/10

Pipe and blind rams shall be activated each trip, however, this function need not be performed more than once a day. Blind rams not activated during trip as required. Corrective action: Perform the necessary test or provide documentation.

Office: GS		ID: GS6807
Unique INC #: 100050	Well Name: JOLLY FED	
	Well #: 11B-20-691(#12)	
Operator: BILL BARRETT CORPORATION		
Case #: COC70803	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MOTEN	
Gravity: 3		
Authority Ref: O.O. #2. III. A. 2. i. viii		

Remarks Date: 03/11/10

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Pipe and blind rams shall be activated each trip, however, this function need not be performed more than once a day. Pipe rams not activated during trip as required. Corrective action: Perform the necessary test or provide documentation.

Office: GS ID: GS6806  
Unique INC #: 100049 Well Name: JOLLY FED  
Well #: 11B-20-691(#12) ID Date: 03/11/10  
Effective Date: 03/11/10  
Operator: BILL BARRETT CORPORATION Abatement Date: 03/12/10  
Case #: COC70803 FAC ID: Corrected Date: 03/12/10  
Form: I FAC NAME: Followup Date: 03/12/10  
Assessment: \$0 Inspector: MOTEN Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2. III. A. 2. i. xi.

Remarks Date: 03/11/10

A BOPE pit level drill shall be conducted weekly for each drilling crew. All of the above described tests and/or drills shall be recorded in the drilling log.  
Corrective action: Perform the necessary test or provide documentation.

Office: GS ID: GS6809  
Unique INC #: 100052 Well Name: JOLLY FED  
Well #: 11B-20-691(#12) ID Date: 03/11/10  
Effective Date: 03/11/10  
Operator: BILL BARRETT CORPORATION Abatement Date: 03/12/10  
Case #: COC70803 FAC ID: Corrected Date: 03/12/10  
Form: I FAC NAME: Followup Date: 03/12/10  
Assessment: \$0 Inspector: MOTEN Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2. III. C. 1

Remarks Date: 03/11/10

Record slow pump speed on daily drilling report after mudding up. The slow pump rates were not recorded every tour. Corrective Action: Record required information.

Office: GS ID: GS6770  
Unique INC #: 100011 Well Name: FEDERAL RWF  
Well #: 531-30(171-19) ID Date: 11/13/09  
Effective Date: 11/13/09  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 11/14/09  
Case #: COC70819 FAC ID: Corrected Date: 11/15/09  
Form: I FAC NAME: Followup Date: 12/07/09  
Assessment: \$0 Inspector: SIEBER Extend Date:  
Gravity: 3  
Authority Ref: O.O #2. III. A.2.i.xi.

Remarks Date: 11/13/09

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

BOPE test results were not recorded in the IADC log book. Corrective action: All BOPE tests shall be recorded in the IADC log book. Copy shall be sent to the Glenwood Springs Field Office in Silt (attn: Todd Sieber).

Office: GS		ID: GS6769
Unique INC #: 100012	Well Name: FEDERAL RWF	
	Well #: 531-30(171-19)	ID Date: 11/13/09
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 11/13/09
Case #: COC70819	FAC ID:	Abatement Date: 11/14/09
Form: I	FAC NAME:	Corrected Date: 11/15/09
Assessment: \$0	Inspector: SIEBER	Followup Date: 12/07/09
Gravity: 3		Extend Date:
Authority Ref: O.O #2. III. B.1.h.		

Remarks Date: 11/13/09

All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10 percent in 30 minutes, corrective action shall be taken. Casing test shall be recorded in the IADC log book. Corrective action: All casing pressure tests shall be recorded .in the IADC log book. Copy shall be sent to the Glenwood Springs Field Office in Silt (attn: Todd Sieber).

Office: HO		ID: HO13380
Unique INC #: 004PS03I	Well Name: WALLEN BASS	
	Well #: 02	ID Date: 05/24/10
Operator: RHCJ ENTERPRISES LLC		Effective Date:
Case #: NMLC070315	FAC ID:	Abatement Date: 06/24/10
Form: I	FAC NAME:	Corrected Date: 08/24/10
Assessment: \$0	Inspector: SWARTZ	Followup Date: 06/29/10
Gravity: 3		Extend Date:
Authority Ref: written order 004PS03W		

Remarks Date: 05/24/10

INC: 004PS03I for non compliance of written order 004PS03W in regard to the Mechanical Integrity Test. "Conduct a Mechanical Integrity Test of 500psig for 30 minutes on the injection tbg/csg annulus of the well. Prepare the wellhead for a bradenhead test, such that surface and intermediate casing annulus (if applicable) may be opened to the atmosphere. Document the MIT test on no more than a 1,000psig calibrated recorder chart. Notify Paul R. Swartz at 575.234.5985 and/or 575.200.7902 at least 24 hours before the test. If there is no response, notify the BLM on call drilling phone, 575.361.2822." Submit three copies of the recorded MIT chart and a subsequent Sundry Form 3160-005 relating the MIT activity to this BLM office. Reference this Written Order number 004PS03W in the MIT Sundry text. Sign and return this notice, providing a brief summary of your compliance in the space provided. Mail on or before June 24, 2010, to the address below: Bureau of Land Management Carlsbad Field Office , Attn: Paul R. Swartz 620 East Greene Street Carlsbad, New Mexico 88220 Contact information: paul\_swartz@nm.blm.gov 575-234-5985 office 575-234-5927 fax 575-200-7902 cell

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: HO ID: HO13493  
Unique INC #: 1006PS30I Well Name: BROOKS 7 ID Date: 07/21/10  
Well #: 03 Effective Date:  
Operator: MCADAMS J F Abatement Date: 08/21/10  
Case #: NMNM0149957 FAC ID: Corrected Date: 08/20/10  
Form: I FAC NAME: Followup Date: 09/13/10  
Assessment: \$0 Inspector: SWARTZ Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3161.2, 43 CFR 3162.1(a), 43 CFR 3162.4-2, 43 CFR 3162.5-1, 2, & 3, 43 CFR 3162  
Remarks Date: 07/21/10  
Failure to comply with Written Order 1006PS30W.

Office: JA ID: JA2346  
Unique INC #: CB-10-103L Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 10 Effective Date:  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/18/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3

Remarks Date: 01/27/10  
The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA ID: JA2341  
Unique INC #: CB-10-103G Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 5 Effective Date:  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/18/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3

Remarks Date: 01/27/10  
The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2344  
Unique INC #: CB-10-103J Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 8 Effective Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/18/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3  
  
Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA ID: JA2347  
Unique INC #: CB-10-103M Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 11 Effective Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/18/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3

Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA ID: JA2342  
Unique INC #: CB-10-103H Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 6 Effective Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/18/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3

Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2343  
Unique INC #: CB-10-103I Well Name: USA-FB CARDEN  
Well #: 7 ID Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Effective Date: 01/27/10  
Case #: LABLM16209 FAC ID: Abatement Date: 03/04/10  
Form: I FAC NAME: Corrected Date: 02/10/10  
Assessment: \$0 Inspector: CHARLES R BOYD Followup Date: 02/18/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3160.5-3  
  
Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA ID: JA2337  
Unique INC #: CB-10-103C Well Name: USA-FB CARDEN  
Well #: 1 ID Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Effective Date: 01/27/10  
Case #: LABLM16209 FAC ID: Abatement Date: 03/04/10  
Form: I FAC NAME: Corrected Date: 02/10/10  
Assessment: \$0 Inspector: CHARLES R BOYD Followup Date: 02/18/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3160.5-3  
  
Remarks Date: 01/28/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA ID: JA2338  
Unique INC #: CB-10-103D Well Name: USA-FB CARDEN  
Well #: 2 ID Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Effective Date: 01/27/10  
Case #: LABLM16209 FAC ID: Abatement Date: 03/04/10  
Form: I FAC NAME: Corrected Date: 02/10/10  
Assessment: \$0 Inspector: CHARLES R BOYD Followup Date: 02/18/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3160.5-3  
  
Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2348  
Unique INC #: CB-10-103N Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 12 Effective Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/18/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3  
  
Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA ID: JA2345  
Unique INC #: CB-10-103K Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 9 Effective Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/10/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3  
  
Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA ID: JA2340  
Unique INC #: CB-10-103F Well Name: USA-FB CARDEN ID Date: 01/27/10  
Well #: 4 Effective Date: 01/27/10  
Operator: SOUTHERN STATES OIL PROD LLC Abatement Date: 03/04/10  
Case #: LABLM16209 FAC ID: Corrected Date: 02/10/10  
Form: I FAC NAME: Followup Date: 02/18/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3160.5-3  
  
Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: JA		ID: JA2339
Unique INC #: CB-10-103E	Well Name: USA-FB CARDEN	
	Well #: 3	ID Date: 01/27/10
Operator: SOUTHERN STATES OIL PROD LLC		Effective Date: 01/27/10
Case #: LABLM16209	FAC ID:	Abatement Date: 03/04/10
Form: I	FAC NAME:	Corrected Date: 02/10/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 02/18/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3160.5-3		

Remarks Date: 01/27/10

The pumping unit at the above well is not equipped with a belt guard to cover the moving belts and pulleys. This results in an unsafe working environment which could cause personal injury if personnel were to come in contact with these moving parts. Operator is ordered to place a belt guard over these moving parts to provide protection to employees or other persons.

Office: JA		ID: JA2352
Unique INC #: CB-10-106A	Well Name:	
	Well #:	ID Date: 02/03/10
Operator: FERRY LAKE OIL CO LLC		Effective Date: 02/03/10
Case #: LABLM33649	FAC ID: A	Abatement Date: 02/09/10
Form: I	FAC NAME: US GOVT. TB	Corrected Date: 02/05/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 02/09/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 02/03/10

THE BELT GUARD ON THE PUMPING UNIT ON THE #2 WELL IS NOT INSTALLED ON THE UNIT. BELT GUARD IS LYING ON THE GROUND ADJACENT TO UNIT. OPERATOR IS ORDERED TO INSTALL THE BELT GUARD ON THE UNIT AND IN THE FUTURE TO NOT OPERATE THE UNIT UNLESS THE BELT GUARD IS IN PLACE. OPERATOR HAS UNTIL 2-9-2010 TO CORRECT THIS VIOLATION.

Office: JA		ID: JA2449
Unique INC #: CB-10-110C	Well Name: USA (MM), USA (MM) SWD	
	Well #: 60, 63-ALT, 70-ALT, 93, 100-ALT, 101-ALT, 120-ALT, 140-ALT	ID Date: 06/23/10 Effective Date: 06/23/10
Operator: CHESAPEAKE OPERATING INC		Abatement Date: 07/26/10
Case #: LABLMA24527	FAC ID: A, B	Corrected Date: 07/23/10
Form: I	FAC NAME: USA M&M NORTH, USA M&M CTB #2	Followup Date: 07/23/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, THERE ARE NUMEROUS VALVES LOCATED ON THE WELL HEADS, METER RUNS, SEPARATORS AND OTHER PRODUCTION RELATED EQUIPMENT THAT ARE NOT PROPERLY PLUGGED TO PREVENT THE UNAUTHORIZED OPENING OF THE VALVES. OPERATOR IS ORDERED TO PLACE A STEEL PLUG IN ALL OF THESE VALVES. THIS PLUG MUST BE OF EQUAL OR GREATER WORKING PRESSURE THAN THE VALVE IN WHICH IT IS INSTALLED. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-26-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA		ID: JA2450
Unique INC #: CB-10-110D	Well Name: USA (MM), USA (MM) SWD	ID Date: 06/23/10
	Well #: 28L, 89-ALT, 93, 106-ALT, 108-ALT, 110-ALT, 112-ALT, 115-ALT, 116-ALT	Effective Date: 06/23/10
Operator: CHESAPEAKE OPERATING INC		Abatement Date: 07/26/10
Case #: LABLMA24527	FAC ID: A, B	Corrected Date: 07/23/10
Form: I	FAC NAME: USA M&M NORTH, USA M&M CTB #2	Followup Date: 07/23/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

ALL FUEL, OIL OR CHEMICAL TANKS USED IN CONJUNCTION WITH LEASE OPERATIONS ARE TO BE PLACED WITHIN A CONTAINMENT VESSEL. THIS CONTAINMENT VESSEL MUST BE OF SUFFICIENT SIZE TO CONTAIN THE CONTENTS OF ALL THE TANKS LOCATED WITHIN IT. ALSO, THE DRAIN ON THE CONTAINMENT VESSEL MUST BE CLOSED AT ALL TIMES. THE DISCHARGE OF ANY FLUIDS FROM THE CONTAINMENT VESSEL SHALL BE CONSIDERED AS AN INTENTIONAL DISCHARGE OF E&P WASTE WHICH COULD LEAD TO IMMEDIATE ASSESSMENTS OR FINES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-26-2010..

Office: JA		ID: JA2448
Unique INC #: CB-10-110B	Well Name:	ID Date: 06/23/10
	Well #:	Effective Date: 06/23/10
Operator: CHESAPEAKE OPERATING INC		Abatement Date: 07/26/10
Case #: LABLMA24527	FAC ID: B	Corrected Date: 07/23/10
Form: I	FAC NAME: USA M&M CTB #2 SOUTH	Followup Date: 07/23/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, ALL PRESSURE RELIEF VALVES ARE TO BE EQUIPPED WITH EITHER A STEEL RAIN CAP OR A RUBBER COVER TO PREVENT THE ENTRY OF RAIN WATER ONTO THE SEAT OF THE VALVE WHICH COULD RENDER IT INOPERABLE. ADDITIONALLY, THIS COVER WILL PREVENT BIRDS OR ANY OTHER WILDLIFE FROM NESTING IN THESE PIPES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-26-2010.

Office: JA		ID: JA2451
Unique INC #: CB-10-110E	Well Name:	ID Date: 08/25/10
	Well #:	Effective Date: 08/25/10
Operator: CHESAPEAKE OPERATING INC		Abatement Date: 09/27/10
Case #: LABLMA24527	FAC ID: A, B	Corrected Date: 09/02/10
Form: I	FAC NAME: USA M&M NORTH, USA M&M CTB #2	Followup Date: 09/08/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

ALL COMPRESSORS MUST BE EQUIPPED WITH A REMOTE SHUT DOWN SYSTEM. THIS REMOTE SHUTDOWN SHOULD BE A SUFFICIENT DISTANCE FROM THE AFFECTED EQUIPMENT TO PREVENT A PERSON FROM HAVING TO RISK EXPOSURE TO A FIRE OR UNSAFE CONDITION IN ORDER TO SHUT DOWN THAT EQUIPMENT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 9-27-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA		ID: JA2452
Unique INC #: CB-10-110F	Well Name:	
	Well #:	ID Date: 06/23/10
Operator: CHESAPEAKE OPERATING INC		Effective Date: 06/23/10
Case #: LABLMA24527	FAC ID: B	Abatement Date: 07/26/10
Form: I	FAC NAME: USA M&M CTB #2 SOUTH	Corrected Date: 07/23/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 07/23/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

ALL DRUMS, EITHER EMPTY OR CONTAINING WASTE MATERIALS ASSOCIATED WITH ANY SPILL OR STANDARD HOUSEKEEPING OPERATIONS ARE TO BE REMOVED AND DISPOSED OF PROPERLY OFF OF THE LEASE. THIS APPLIES TO THE FACILITIES NOTED IN THIS ORDER. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-26-2010.

Office: JA		ID: JA2407
Unique INC #: CB-10-111D	Well Name: USA, USA 4425	
	Well #: 1, 1-CV, 1AT, 2CV, 6-T, 12, 14, 15, 16, 17, 18, 19, 20, 21, 22	ID Date: 05/26/10 Effective Date: 06/23/10
Operator: SAMSON CONTOUR ENERGY		Abatement Date: 07/12/10
Case #: LABLMA34425	FAC ID: A, B	Corrected Date: 07/09/10
Form: I	FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI	Followup Date: 07/26/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 05/26/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, THE EXHAUST MUFFLER ON THE INJECTION COMPRESSOR HAS A HOLE OR CRACK IN THE BOTTOM OF IT. OPERATOR IS ORDERED TO REPAIR OR REPLACE THIS MUFFLER. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-12-2010.

Office: JA		ID: JA2404
Unique INC #: CB-10-111A	Well Name: USA, USA 4425	
	Well #: 1, 1-CV, 1AT, 2CV, 6-T, 12, 14, 15, 16, 17, 18, 19, 20, 21, 22	ID Date: 05/26/10 Effective Date: 06/23/10
Operator: SAMSON CONTOUR ENERGY		Abatement Date: 07/12/10
Case #: LABLMA34425	FAC ID: A, B	Corrected Date: 07/16/10
Form: I	FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI	Followup Date: 07/26/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date: 07/22/10
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 05/26/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, SOME OF THE PIPING AND EQUIPMENT AT THE WELLS AND FACILITIES IS NOT PROTECTED WITH PROPER COATINGS AND/OR PAINT TO PREVENT CORROSION AND EQUIPMENT FAILURE DUE TO EXPOSURE THE ELEMENTS AND CORROSIVE PRODUCED FLUIDS. OPERATOR IS ORDERED TO PAINT OR COAT ALL OF THE EXPOSED EQUIPMENT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-12-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2409  
 Unique INC #: CB-10-111F Well Name: USA, USA 4425 ID Date: 05/26/10  
 Well #: 1, 1-CV, 1AT, 2CV, 6-T, 12, 14, 15, 16, 17, 18, 19, 20, 21, 22 Effective Date: 06/23/10  
 Operator: SAMSON CONTOUR ENERGY Abatement Date: 07/12/10  
 Case #: LABLMA34425 FAC ID: A, B Corrected Date: 07/09/10  
 Form: I FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI Followup Date: 07/26/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/26/10

ALL FUEL, OIL OR CHEMICAL TANKS USED IN CONJUNCTION WITH LEASE OPERATIONS ARE TO BE PLACED WITHIN A CONTAINMENT VESSEL. THIS CONTAINMENT VESSEL MUST BE OF SUFFICIENT SIZE TO CONTAIN THE CONTENTS OF ALL THE TANKS LOCATED WITHIN IT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-12-2010.

Office: JA ID: JA2408  
 Unique INC #: CB-10-111E Well Name: USA, USA 4425 ID Date: 05/26/10  
 Well #: 1, 1-CV, 1AT, 2CV, 6-T, 12, 14, 15, 16, 17, 18, 19, 20, 21, 22 Effective Date: 06/23/10  
 Operator: SAMSON CONTOUR ENERGY Abatement Date: 07/12/10  
 Case #: LABLMA34425 FAC ID: A, B Corrected Date: 07/08/10  
 Form: I FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI Followup Date: 07/26/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/26/10

ALL DRUMS AND ANY WASTE MATERIALS ASSOCIATED WITH ANY SPILL OR STANDARD HOUSEKEEPING OPERATIONS LOCATED AT ANY WELL OR FACILITY ARE TO REMOVED AND DISPOSED OF PROPERLY OFF OF THE LEASE. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-12-2010.

Office: JA ID: JA2405  
 Unique INC #: CB-10-111B Well Name: USA, USA 4425 ID Date: 05/26/10  
 Well #: 1, 1-CV, 1AT, 2CV, 6-T, 12, 14, 15, 16, 17, 18, 19, 20, 21, 22 Effective Date: 06/23/10  
 Operator: SAMSON CONTOUR ENERGY Abatement Date: 07/12/10  
 Case #: LABLMA34425 FAC ID: A, B Corrected Date: 07/08/10  
 Form: I FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI Followup Date: 07/26/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/26/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, THERE ARE NUMEROUS VALVES LOCATED ON THE WELL HEADS, METER RUNS, SEPARATORS AND OTHER PRODUCTION RELATED EQUIPMENT THAT ARE NOT PROPERLY PLUGGED TO PREVENT THE UNAUTHORIZED OPENING OF THE VALVES. OPERATOR IS ORDERED TO PLACE A STEEL PLUG IN ALL OF THESE VALVES. THIS PLUG MUST BE OF EQUAL OR GREATER WORKING PRESSURE THAN THE VALVE IN WHICH IT IS INSTALLED. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-12-2010.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: JA		ID: JA2411
Unique INC #: CB-10-111H	Well Name:	
	Well #:	ID Date: 05/26/10
Operator: SAMSON CONTOUR ENERGY		Effective Date: 06/23/10
Case #: LABLMA34425	FAC ID: A, B	Abatement Date: 07/12/10
Form: I	FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI	Corrected Date: 07/09/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 07/26/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 05/26/10

ALL FLUID LEVEL CONTROL SYSTEMS ON ALL SEPARATORS SHALL BE IN COMPLETE WORKING ORDER. MORE, SPECIFICALLY, EACH DEVICE SHALL BE COMPLETELY OPERATIONAL IF IN USE. ALSO, THE DEVICE SHALL BE FREE OF LEAKS, EITHER OIL OR GAS. ALL GAUGES SHALL BE IN GOOD WORKING ORDER. THE CONTROL BOX ON THESE DEVICES SHALL BE CLOSED AT ALL TIMES UNLESS IT IS BEING ADJUSTED.

Office: JA		ID: JA2406
Unique INC #: CB-10-111C	Well Name: USA, USA 4425	
	Well #: 1, 1-CV, 1AT, 2CV, 6-T, 12, 14, 15, 16, 17, 18, 19, 20, 21, 22	ID Date: 05/26/10 Effective Date: 06/23/10
Operator: SAMSON CONTOUR ENERGY		Abatement Date: 07/12/10
Case #: LABLMA34425	FAC ID: A, B	Corrected Date: 07/08/10
Form: I	FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI	Followup Date: 07/26/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 05/26/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, ALL PRESSURE RELIEF VALVES ARE TO BE EQUIPPED WITH EITHER A STEEL RAIN CAP OR A RUBBER COVER TO PREVENT THE ENTRY OF RAIN WATER ONTO THE SEAT OF THE VALVE WHICH COULD RENDER IT INOPERABLE. ADDITIONALLY, THIS COVER WILL PREVENT BIRDS OR ANY OTHER WILDLIFE FROM NESTING IN THESE PIPES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-12-2010.

Office: JA		ID: JA2410
Unique INC #: CB-10-111G	Well Name:	
	Well #:	ID Date: 05/26/10
Operator: SAMSON CONTOUR ENERGY		Effective Date: 06/23/10
Case #: LABLMA34425	FAC ID: A, B	Abatement Date: 07/12/10
Form: I	FAC NAME: SLIGO USA CTB, SLIGO USA SATELLI	Corrected Date: 07/09/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 07/26/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 05/26/10

ALL COMPRESSORS MUST BE EQUIPPED WITH A REMOTE SHUT DOWN SYSTEM. THIS REMOTE SHUTDOWN SHOULD BE A SUFFICIENT DISTANCE FROM THE AFFECTED EQUIPMENT TO PREVENT A PERSON FROM HAVING TO RISK EXPOSURE TO A FIRE OR UNSAFE CONDITION IN ORDER TO SHUT DOWN THAT EQUIPMENT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-12-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA		ID: JA2423
Unique INC #: CB-10-112E	Well Name: USA B	
	Well #: 2, 6-ALT, 7-ALT, 8, 9-ALT, 10-ALT, 11-ALT, 12-ALT, 13-ALT, 14	ID Date: 06/23/10 Effective Date: 07/02/10
Operator: XTO ENERGY INCORPORATED		Abatement Date: 07/19/10
Case #: LABLMA54489	FAC ID: C	Corrected Date: 07/16/10
Form: I	FAC NAME: B LEASE COMPRESSOR	Followup Date: 07/24/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

ALL DRUMS, EITHER EMPTY OR CONTAINING WASTE MATERIALS ASSOCIATED WITH ANY SPILL OR STANDARD HOUSEKEEPING OPERATIONS ARE TO BE REMOVED AND DISPOSED OF PROPERLY OFF OF THE LEASE. THIS APPLIES TO ALL WELLS AND FACILITIES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA		ID: JA2424
Unique INC #: CB-10-112F	Well Name: USA B	
	Well #: 2, 6-ALT, 7-ALT, 8, 9-ALT, 10-ALT, 11-ALT, 12-ALT, 13-ALT, 14	ID Date: 06/23/10 Effective Date: 07/02/10
Operator: XTO ENERGY INCORPORATED		Abatement Date: 07/19/10
Case #: LABLMA54489	FAC ID: C	Corrected Date: 07/22/10
Form: I	FAC NAME: B LEASE COMPRESSOR	Followup Date: 07/23/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date: 07/29/10
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

ALL COMPRESSORS MUST BE EQUIPPED WITH A REMOTE SHUT DOWN SYSTEM. THIS REMOTE SHUTDOWN SHOULD BE A SUFFICIENT DISTANCE FROM THE AFFECTED EQUIPMENT TO PREVENT A PERSON FROM HAVING TO RISK EXPOSURE TO A FIRE OR UNSAFE CONDITION IN ORDER TO SHUT DOWN THAT EQUIPMENT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA		ID: JA2420
Unique INC #: CB-10-112B	Well Name: USA B	
	Well #: 2, 6-ALT, 7-ALT, 8, 9-ALT, 10-ALT, 11-ALT, 12-ALT, 13-ALT, 14	ID Date: 06/23/10 Effective Date: 07/02/10
Operator: XTO ENERGY INCORPORATED		Abatement Date: 07/19/10
Case #: LABLMA54489	FAC ID: C	Corrected Date: 08/30/10
Form: I	FAC NAME: B LEASE COMPRESSOR	Followup Date: 09/02/10
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date: 08/30/10
Gravity: 3		
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/23/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, SOME OF THE PIPING AND EQUIPMENT AT THE WELLS AND FACILITIES IS NOT PROTECTED WITH PROPER COATINGS AND/OR PAINT TO PREVENT CORROSION AND EQUIPMENT FAILURE DUE TO EXPOSURE THE ELEMENTS AND CORROSIVE PRODUCED FLUIDS. OPERATOR IS ORDERED TO PAINT OR COAT ALL OF THE EXPOSED EQUIPMENT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2421  
 Unique INC #: CB-10-112C Well Name: USA B ID Date: 06/23/10  
 Well #: 2, 6-ALT, 7-ALT, 8, 9-ALT, 10-ALT, 11-ALT, 12-ALT, 13-ALT, 14 Effective Date: 07/02/10  
 Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54489 FAC ID: C Corrected Date: 07/16/10  
 Form: I FAC NAME: B LEASE COMPRESSOR Followup Date: 07/23/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3  
 Remarks Date: 06/23/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, THERE ARE NUMEROUS VALVES LOCATED ON THE WELL HEADS, METER RUNS, SEPARATORS AND OTHER PRODUCTION RELATED EQUIPMENT THAT ARE NOT PROPERLY PLUGGED TO PREVENT THE UNAUTHORIZED OPENING OF THE VALVES. OPERATOR IS ORDERED TO PLACE A STEEL PLUG IN ALL OF THESE VALVES. THIS PLUG MUST BE OF EQUAL OR GREATER WORKING PRESSURE THAN THE VALVE IN WHICH IT IS INSTALLED. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2422  
 Unique INC #: CB-10-112D Well Name: USA B ID Date: 06/23/10  
 Well #: 2, 6-ALT, 7-ALT, 8, 9-ALT, 10-ALT, 11-ALT, 12-ALT, 13-ALT, 14 Effective Date: 07/02/10  
 Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54489 FAC ID: C Corrected Date: 07/16/10  
 Form: I FAC NAME: B LEASE COMPRESSOR Followup Date: 07/23/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/23/10

ALL FUEL, OIL OR CHEMICAL TANKS USED IN CONJUNCTION WITH LEASE OPERATIONS ARE TO BE PLACED WITHIN A CONTAINMENT VESSEL. THIS CONTAINMENT VESSEL MUST BE OF SUFFICIENT SIZE TO CONTAIN THE CONTENTS OF ALL THE TANKS LOCATED WITHIN IT. ALSO, THE DRAIN ON THE CONTAINMENT VESSEL MUST BE CLOSED AT ALL TIMES. THE DISCHARGE OF ANY FLUIDS FROM THE CONTAINMENT VESSEL SHALL BE CONSIDERED AS AN INTENTIONAL DISCHARGE OF E&P WASTE WHICH COULD LEAD TO IMMEDIATE ASSESSMENTS OR FINES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2425  
 Unique INC #: CB-10-112G Well Name: USA B ID Date: 06/23/10  
 Well #: 2, 6-ALT, 7-ALT, 8, 9-ALT, 10-ALT, 11-ALT, 12-ALT, 13-ALT, 14 Effective Date: 07/02/10  
 Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54489 FAC ID: C Corrected Date: 07/16/10  
 Form: I FAC NAME: B LEASE COMPRESSOR Followup Date: 07/24/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/23/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, ALL PRESSURE RELIEF VALVES ARE TO BE EQUIPPED WITH EITHER A STEEL RAIN CAP OR A RUBBER COVER TO PREVENT THE ENTRY OF RAIN WATER ONTO THE SEAT OF THE VALVE WHICH COULD RENDER IT INOPERABLE. ADDITIONALLY, THIS COVER WILL PREVENT BIRDS OR ANY OTHER WILDLIFE FROM NESTING IN THESE PIPES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2413  
Unique INC #: CB-10-113B Well Name: USA, USA SWD ID Date: 06/21/10  
Well #: 1, 2, 3, 8-ALT, 17, 20, 21, 24, 25, 27-D, 28-ALT, 30-ALT, 32-ALT Effective Date: 07/02/10  
Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
Case #: LABLMA54490 FAC ID: A1, B Corrected Date: 08/30/10  
Form: I FAC NAME: SLIGO PLANT, USA #32-ALT Followup Date: 09/02/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date: 08/30/10  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 06/21/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, SOME OF THE PIPING AND EQUIPMENT AT THE WELLS AND FACILITIES IS NOT PROTECTED WITH PROPER COATINGS AND/OR PAINT TO PREVENT CORROSION AND EQUIPMENT FAILURE DUE TO EXPOSURE THE ELEMENTS AND CORROSIVE PRODUCED FLUIDS. OPERATOR IS ORDERED TO PAINT OR COAT ALL OF THE EXPOSED EQUIPMENT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2418  
Unique INC #: CB-10-113G Well Name: USA, USA SWD ID Date: 06/21/10  
Well #: 1, 2, 3, 8-ALT, 17, 20, 21, 24, 25, 27-D, 28-ALT, 30-ALT, 32-ALT Effective Date: 07/02/10  
Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
Case #: LABLMA54490 FAC ID: A1, B Corrected Date: 07/16/10  
Form: I FAC NAME: SLIGO PLANT, USA #32-ALT Followup Date: 07/24/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/21/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, ALL PRESSURE RELIEF VALVES ARE TO BE EQUIPPED WITH EITHER A STEEL RAIN CAP OR A RUBBER COVER TO PREVENT THE ENTRY OF RAIN WATER ONTO THE SEAT OF THE VALVE WHICH COULD RENDER IT INOPERABLE. ADDITIONALLY, THIS COVER WILL PREVENT BIRDS OR ANY OTHER WILDLIFE FROM NESTING IN THESE PIPES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2417  
Unique INC #: CB-10-113F Well Name: USA, USA SWD ID Date: 06/21/10  
Well #: 1, 2, 3, 8-ALT, 17, 20, 21, 24, 25, 27-D, 28-ALT, 30-ALT, 32-ALT Effective Date: 07/02/10  
Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
Case #: LABLMA54490 FAC ID: A1 Corrected Date: 07/14/10  
Form: I FAC NAME: SLIGO PLANT Followup Date: 07/23/10  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/21/10

THE VALVE WHICH SERVES AS THE REMOTE SHUTDOWN FOR THE MAIN FACILITY IS NOT CLEARLY IDENTIFIED. OPERATOR IS ORDERED TO PLACE A SIGN AT OR NEAR THIS VALVE WHICH IDENTIFIES AND STATES THE PURPOSE OF THE VALVE.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2414  
 Unique INC #: CB-10-113C Well Name: USA, USA SWD ID Date: 06/21/10  
 Well #: 1, 2, 3, 8-ALT, 17, 20, 21, 24, 25, 27-D, 28-ALT, 30-ALT, 32-ALT Effective Date: 07/02/10  
 Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54490 FAC ID: A1, B Corrected Date: 07/07/10  
 Form: I FAC NAME: SLIGO PLANT, USA #32-ALT Followup Date:  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3  
 Remarks Date: 06/21/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, THERE ARE NUMEROUS VALVES LOCATED ON THE WELL HEADS, METER RUNS, SEPARATORS AND OTHER PRODUCTION RELATED EQUIPMENT THAT ARE NOT PROPERLY PLUGGED TO PREVENT THE UNAUTHORIZED OPENING OF THE VALVES. OPERATOR IS ORDERED TO PLACE A STEEL PLUG IN ALL OF THESE VALVES. THIS PLUG MUST BE OF EQUAL OR GREATER WORKING PRESSURE THAN THE VALVE IN WHICH IT IS INSTALLED. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2416  
 Unique INC #: CB-10-113E Well Name: USA, USA SWD ID Date: 06/21/10  
 Well #: 1, 2, 3, 8-ALT, 17, 20, 21, 24, 25, 27-D, 28-ALT, 30-ALT, 32-ALT Effective Date: 07/02/10  
 Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54490 FAC ID: A1, B Corrected Date: 07/16/10  
 Form: I FAC NAME: SLIGO PLANT, USA #32-ALT Followup Date: 07/23/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/21/10

ALL DRUMS, EITHER EMPTY OR CONTAINING WASTE MATERIALS ASSOCIATED WITH ANY SPILL OR STANDARD HOUSEKEEPING OPERATIONS ARE TO BE REMOVED AND DISPOSED OF PROPERLY OFF OF THE LEASE. THIS APPLIES TO ALL WELLS AND FACILITIES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2415  
 Unique INC #: CB-10-113D Well Name: USA, USA SWD ID Date: 06/21/10  
 Well #: 1, 2, 3, 8-ALT, 17, 20, 21, 24, 25, 27-D, 28-ALT, 30-ALT, 32-ALT Effective Date: 07/02/10  
 Operator: XTO ENERGY INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54490 FAC ID: A1, B Corrected Date: 07/16/10  
 Form: I FAC NAME: SLIGO PLANT, USA #32-ALT Followup Date: 07/23/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/21/10

ALL FUEL, OIL OR CHEMICAL TANKS USED IN CONJUNCTION WITH LEASE OPERATIONS ARE TO BE PLACED WITHIN A CONTAINMENT VESSEL. THIS CONTAINMENT VESSEL MUST BE OF SUFFICIENT SIZE TO CONTAIN THE CONTENTS OF ALL THE TANKS LOCATED WITHIN IT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2440  
 Unique INC #: CB-10-114C Well Name: USA (PARCEL 3) ID Date: 06/22/10  
 Well #: 1, 5, 6, 7, 8, 9, 33, 34, 36-ALT, 37-ALT, 38-ALT, 39-ALT, 40-A Effective Date: 06/22/10  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54491 FAC ID: F, K, L Corrected Date: 07/19/10  
 Form: I FAC NAME: USA #79 SATELLITE FACILITY, USA #6 Followup Date: 07/24/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/22/10

ALL FUEL, OIL OR CHEMICAL TANKS USED IN CONJUNCTION WITH LEASE OPERATIONS ARE TO BE PLACED WITHIN A CONTAINMENT VESSEL. THIS CONTAINMENT VESSEL MUST BE OF SUFFICIENT SIZE TO CONTAIN THE CONTENTS OF ALL THE TANKS LOCATED WITHIN IT. ALSO, THE DRAIN ON THE CONTAINMENT VESSEL MUST BE CLOSED AT ALL TIMES. THE DISCHARGE OF ANY FLUIDS FROM THE CONTAINMENT VESSEL SHALL BE CONSIDERED AS AN INTENTIONAL DISCHARGE OF E&P WASTE WHICH COULD LEAD TO IMMEDIATE ASSESSMENTS OR FINES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2439  
 Unique INC #: CB-10-114B Well Name: USA (PARCEL 3) ID Date: 06/22/10  
 Well #: 1, 5, 6, 7, 8, 9, 33, 34, 36-ALT, 37-ALT, 38-ALT, 39-ALT, 40-A Effective Date: 06/22/10  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54491 FAC ID: F, K, L Corrected Date: 07/19/10  
 Form: I FAC NAME: USA #79 SATELLITE FACILITY, USA #6 Followup Date: 07/24/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/22/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, THERE ARE NUMEROUS VALVES LOCATED ON THE WELL HEADS, METER RUNS, SEPARATORS AND OTHER PRODUCTION RELATED EQUIPMENT THAT ARE NOT PROPERLY PLUGGED TO PREVENT THE UNAUTHORIZED OPENING OF THE VALVES. OPERATOR IS ORDERED TO PLACE A STEEL PLUG IN ALL OF THESE VALVES. THIS PLUG MUST BE OF EQUAL OR GREATER WORKING PRESSURE THAN THE VALVE IN WHICH IT IS INSTALLED. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA ID: JA2442  
 Unique INC #: CB-10-114E Well Name: USA (PARCEL 3) ID Date: 06/22/10  
 Well #: 1, 5, 6, 7, 8, 9, 33, 34, 36-ALT, 37-ALT, 38-ALT, 39-ALT, 40-A Effective Date: 06/22/10  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54491 FAC ID: F, K, L Corrected Date: 07/19/10  
 Form: I FAC NAME: USA #79 SATELLITE FACILITY, USA #6 Followup Date: 07/24/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/22/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, ALL PRESSURE RELIEF VALVES ARE TO BE EQUIPPED WITH EITHER A STEEL RAIN CAP OR A RUBBER COVER TO PREVENT THE ENTRY OF RAIN WATER ONTO THE SEAT OF THE VALVE WHICH COULD RENDER IT INOPERABLE. ADDITIONALLY, THIS COVER WILL PREVENT BIRDS OR ANY OTHER WILDLIFE FROM NESTING IN THESE PIPES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: JA ID: JA2443  
 Unique INC #: CB-10-114F Well Name: USA (PARCEL 3) ID Date: 06/22/10  
 Well #: 1, 5, 6, 7, 8, 9, 33, 34, 36-ALT, 37-ALT, 38-ALT, 39-ALT, 40-A Effective Date: 06/22/10  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54491 FAC ID: F Corrected Date: 07/19/10  
 Form: I FAC NAME: USA PARCEL 3 CTB #4 Followup Date: 07/24/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3  
 Remarks Date: 06/22/10

THE STAIRWAY RAILS AT THE TOP OF THE LANDING AT THE TANK BATTERY ARE NOT PROPERLY SECURED. THIS CONDITION COULD RESULT IN THE LOSS OF BALANCE BY PERSONNEL DESCENDING THE STAIRWAY. ALSO THERE IS THE POSSIBILITY OF CLOTHING BECOMING SNAGGED WHICH COULD CAUSE INJURY OR A FALL WHICH COULD RESULT IN INJURY OR DEATH. OPERATOR IS ORDERED TO SECURE THESE HANDRAILS TO PREVENT ANY TYPE OF ACCIDENT FROM OCCURRING.

Office: JA ID: JA2444  
 Unique INC #: CB-10-114G Well Name: USA (PARCEL 3) ID Date: 06/22/10  
 Well #: 1, 5, 6, 7, 8, 9, 33, 34, 36-ALT, 37-ALT, 38-ALT, 39-ALT, 40-A Effective Date: 06/22/10  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54491 FAC ID: F Corrected Date: 07/19/10  
 Form: I FAC NAME: USA PARCEL 3 CTB #4 Followup Date: 07/23/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3  
 Remarks Date: 06/22/10

THE ELECTRICAL LINES LEADING TO THE LEVEL CONTROL SWITCHES FOR THE SALTWATER TANBKS NEED TO BE ELEVATED AND SECURED SO THAT THEY DO NOT BECOME SUBMERGED IN THE EVENT THAT WATER FILLS UP THE FIREWALL. OPERATOR IS ORDERED TO CORRECT THIS SITUATION BY 7-19-2010.

Office: JA ID: JA2441  
 Unique INC #: CB-10-114D Well Name: USA (PARCEL 3) ID Date: 06/22/10  
 Well #: 1, 5, 6, 7, 8, 9, 33, 34, 36-ALT, 37-ALT, 38-ALT, 39-ALT, 40-A Effective Date: 06/22/10  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 07/19/10  
 Case #: LABLMA54491 FAC ID: F, K, L Corrected Date: 07/19/10  
 Form: I FAC NAME: USA #79 SATELLITE FACILITY, USA #8 Followup Date: 07/24/10  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.5-3  
 Remarks Date: 06/22/10

ALL DRUMS, EITHER EMPTY OR CONTAINING WASTE MATERIALS ASSOCIATED WITH ANY SPILL OR STANDARD HOUSEKEEPING OPERATIONS ARE TO BE REMOVED AND DISPOSED OF PROPERLY OFF OF THE LEASE. THIS APPLIES TO ALL WELLS AND FACILITIES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA		ID: JA2431
Unique INC #: CB-10-115F	Well Name: USA	
	Well #: 29-ALT, 48-ALT, 60-ALT, 84-ALT	ID Date: 06/28/10
Operator: CHESAPEAKE OPERATING INC		Effective Date: 07/01/10
Case #: LABLMA54492	FAC ID: A, B	Abatement Date: 07/19/10
Form: I	FAC NAME: SLIGO NORTH USA #3, SLIGO NORTH	Corrected Date: 07/16/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 07/16/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/28/10

ALL FUEL, OIL OR CHEMICAL TANKS USED IN CONJUNCTION WITH LEASE OPERATIONS ARE TO BE PLACED WITHIN A CONTAINMENT VESSEL. THIS CONTAINMENT VESSEL MUST BE OF SUFFICIENT SIZE TO CONTAIN THE CONTENTS OF ALL THE TANKS LOCATED WITHIN IT. ALSO, THE DRAIN ON THE CONTAINMENT VESSEL MUST BE CLOSED AT ALL TIMES. THE DISCHARGE OF ANY FLUIDS FROM THE CONTAINMENT VESSEL SHALL BE CONSIDERED AS AN INTENTIONAL DISCHARGE OF E&P WASTE WHICH COULD LEAD TO IMMEDIATE ASSESSMENTS OR FINES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA		ID: JA2428
Unique INC #: CB-10-115C	Well Name: USA	
	Well #: 9-D, 24-ALT, 28-ALT, 31-ALT, 35-ALT	ID Date: 06/28/10
Operator: CHESAPEAKE OPERATING INC		Effective Date: 07/01/10
Case #: LABLMA54492	FAC ID: A, B	Abatement Date: 07/19/10
Form: I	FAC NAME: SLIGO NORTH USA #3, SLIGO NORTH	Corrected Date: 07/16/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 07/16/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/28/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, THERE ARE NUMEROUS VALVES LOCATED ON THE WELL HEADS, METER RUNS, SEPARATORS AND OTHER PRODUCTION RELATED EQUIPMENT THAT ARE NOT PROPERLY PLUGGED TO PREVENT THE UNAUTHORIZED OPENING OF THE VALVES. OPERATOR IS ORDERED TO PLACE A STEEL PLUG IN ALL OF THESE VALVES. THIS PLUG MUST BE OF EQUAL OR GREATER WORKING PRESSURE THAN THE VALVE IN WHICH IT IS INSTALLED. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA		ID: JA2429
Unique INC #: CB-10-115D	Well Name:	
	Well #:	ID Date: 06/28/10
Operator: CHESAPEAKE OPERATING INC		Effective Date: 07/01/10
Case #: LABLMA54492	FAC ID: A, B	Abatement Date: 07/19/10
Form: I	FAC NAME: SLIGO NORTH USA #3, SLIGO NORTH	Corrected Date: 07/16/10
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 07/16/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/28/10

EQUIPMENT FOUND AT THE WELL SITES AND THE FACILITIES ASSOCIATED WITH THIS LEASE IS NOT BEING MAINTAINED IN A SAFE AND WORKMANLIKE MANNER AS REQUIRED BY THE REGULATION. SPECIFICALLY, ALL PRESSURE RELIEF VALVES ARE TO BE EQUIPPED WITH EITHER A STEEL RAIN CAP OR A RUBBER COVER TO PREVENT THE ENTRY OF RAIN WATER ONTO THE SEAT OF THE VALVE WHICH COULD RENDER IT INOPERABLE. ADDITIONALLY, THIS COVER WILL PREVENT BIRDS OR ANY OTHER WILDLIFE FROM NESTING IN THESE PIPES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: JA		ID: JA2432
Unique INC #: CB-10-115G	Well Name:	
	Well #:	
Operator: CHESAPEAKE OPERATING INC		
Case #: LABLMA54492	FAC ID: A, B	ID Date: 08/25/10
Form: I	FAC NAME: SLIGO NORTH USA #3, SLIGO NORTH	Effective Date: 08/25/10
Assessment: \$0	Inspector: CHARLES R BOYD	Abatement Date: 09/27/10
Gravity: 3		Corrected Date: 09/02/10
Authority Ref: 43 CFR 3162.5-3		Followup Date: 09/08/10
		Extend Date:

Remarks Date: 06/28/10

ALL COMPRESSORS MUST BE EQUIPPED WITH A REMOTE SHUT DOWN SYSTEM. THIS REMOTE SHUTDOWN SHOULD BE A SUFFICIENT DISTANCE FROM THE AFFECTED EQUIPMENT TO PREVENT A PERSON FROM HAVING TO RISK EXPOSURE TO A FIRE OR UNSAFE CONDITION IN ORDER TO SHUT DOWN THAT EQUIPMENT. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: JA		ID: JA2430
Unique INC #: CB-10-115E	Well Name:	
	Well #:	
Operator: CHESAPEAKE OPERATING INC		
Case #: LABLMA54492	FAC ID: A	ID Date: 06/28/10
Form: I	FAC NAME: SLIGO NORTH DEHY PLANT	Effective Date: 07/01/10
Assessment: \$0	Inspector: CHARLES R BOYD	Abatement Date: 07/19/10
Gravity: 3		Corrected Date: 07/16/10
Authority Ref: 43 CFR 3162.5-3		Followup Date: 07/16/10
		Extend Date:

Remarks Date: 06/28/10

ALL DRUMS, EITHER EMPTY OR CONTAINING WASTE MATERIALS ASSOCIATED WITH ANY SPILL OR STANDARD HOUSEKEEPING OPERATIONS ARE TO BE REMOVED AND DISPOSED OF PROPERLY OFF OF THE LEASE. THIS APPLIES TO ALL WELLS AND FACILITIES. THE DUE DATE FOR THIS WORK TO BE COMPLETED IS 7-19-2010.

Office: KM		ID: KM1348
Unique INC #: 10DWB057I	Well Name: CHURCH BUTTES UNIT	
	Well #: 181	
Operator: WEXPRO COMPANY		
Case #: WYE021367	FAC ID:	ID Date: 08/10/10
Form: I	FAC NAME:	Effective Date: 08/11/10
Assessment: \$0	Inspector: D W BREWER	Abatement Date:
Gravity: 3		Corrected Date: 08/25/10
Authority Ref: APD COA #4		Followup Date: 08/25/10
		Extend Date:

Remarks Date: 08/10/10

APD Condition of Approval #4 requires at least 24 "verbal" notice so BLM Inspectors may plan and witness casing/cementing & BOP tests. Wexpro Drilling Rep. phoned in only 4 hrs prior to running of surface casing, and failed to contact BLM prior to BOP test. Advanced email "spud notices" do not suffice; Operators must call 307-828-4559 to determine which PET to call.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: MI ID: MI1845  
Unique INC #: JTW 10 034 Well Name: USA ID Date: 07/14/10  
Well #: 1 Effective Date: 07/19/10  
Operator: DERRICK PETROLEUM Abatement Date: 08/15/10  
Case #: OHBLMA044568 FAC ID: A Corrected Date: 07/20/10  
Form: I FAC NAME: Followup Date: 08/25/10  
Assessment: \$0 Inspector: WOOD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162..1  
  
Remarks Date: 07/14/10

Currently your pumpjack is not equipped with a belt guard. Install either a belt guard, or fence off the entire pumpjack. Failure to comply will result in a monetary assessment.

Office: MI ID: MI1849  
Unique INC #: JTW 10 037 Well Name: MONTGOMERY ID Date: 07/14/10  
Well #: 5 Effective Date: 07/19/10  
Operator: EDWARD H EVERETT CO Abatement Date: 08/19/10  
Case #: OHES36908 FAC ID: A Corrected Date: 08/10/10  
Form: I FAC NAME: Followup Date: 08/25/10  
Assessment: \$0 Inspector: WOOD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1  
  
Remarks Date: 07/14/10

The pumpjack on the Montgomery #5 well needs to have a belt guard installed, or a fence installed around the entire pumpjack. Failure to comply will result in a monetary assessment.

Office: MI ID: MI1761  
Unique INC #: JTW-10-016 Well Name: MEEKS/USA ID Date: 05/06/10  
Well #: 1 Effective Date: 05/10/10  
Operator: VIKING RESOURCES CORP Abatement Date: 05/24/10  
Case #: OHES37916 FAC ID: A Corrected Date: 05/14/10  
Form: I FAC NAME: MEEKS USA 1 Followup Date: 05/19/10  
Assessment: \$0 Inspector: WOOD Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162(a)(b)  
  
Remarks Date: 05/06/10

Tank # 6035 is currently leaking a small volume of oil. The fluid level is below the holes in the tank, but when the meter run was blown down the tank leaked. This tank shall be repalced and the area around the tank bottom where oil has hit the ground shall be cleaned up and contaminated soil shall be disposed of in accordance with local, state and federal regulations. Failure to comply with in the abatement period will result in a monetary assessment. See attached photos.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: MI		ID: MI1760
Unique INC #: JTW-10-015	Well Name: SIMCO-BERLIN RESERVOIR	
	Well #: 1	ID Date: 05/05/10
Operator: OHIO VALLEY ENERGY SYS CORP		Effective Date: 05/10/10
Case #: OHES45412	FAC ID: A	Abatement Date: 05/24/10
Form: I	FAC NAME:	Corrected Date: 05/12/10
Assessment: \$0	Inspector: WOOD	Followup Date: 05/19/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5(a)		

Remarks Date: 05/05/10

The blowdown valve on the drip pot inside your tank facility is cracked and has been leaking and blowing small amounts of oil and water outside the diked area and is also dripping on the ground around this 1" pipe. This valve shall be replaced and the area both inside the dike and outside the dike shall be cleaned up. Failure to comply timely will result in a monetary assessment.

Office: MI		ID: MI1720
Unique INC #: JTW-10-007	Well Name: MARTHA SHEETS	
	Well #: 1, 3, 4	ID Date: 11/06/09
Operator: G R CONTRACTORS		Effective Date: 11/12/09
Case #: OHES50558	FAC ID: A	Abatement Date: 12/12/09
Form: I	FAC NAME: SHEETS	Corrected Date: 12/10/09
Assessment: \$0	Inspector: WOOD	Followup Date: 12/16/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 11/06/09

43 CFR 3162.5-3 requires operations to be conducted in a safe and workman like manner. Currently your 3 pumpjacks are not equipped with belt guards which poses a hazard to company personnel, as well as the general public. Install belt guards or fence off the entire pumpjack. Failure to comply will result in a monetary assessment.

Office: MR		ID: iMR1744
Unique INC #: SJ10RB11	Well Name: UMT D	
	Well #: 10	ID Date: 04/06/10
Operator: XTO ENERGY		Effective Date: 04/20/10
Case #: 142060479	FAC ID:	Abatement Date: 05/03/10
Form: I	FAC NAME:	Corrected Date: 05/03/10
Assessment: \$0	Inspector: BRASHEAR	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR. 3162.1(a).		

Remarks Date: 04/06/10

XTO Energy commenced well operations on the Ute Mountain Tribal D #10 on 3/25/2010. XTO Energy failed to notify the BLM 72 hours prior to commencing well operations as set forth in the conditions of approval that were required by the Authorized Officer. XTO Energy shall notify Petroleum Engineer Dan Rabinowitz at the BLM, Durango Colorado Field Office, upon receipt of this notice. Dan Rabinowitz can be contacted at: 970-385-1363.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: MR ID: iMR1709  
Unique INC #: SJ10LW01 Well Name: QUINTANA 32-5  
Well #: 7-3 ID Date: 01/05/10  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 01/06/10  
Case #: 750022001 FAC ID: Abatement Date: 02/05/10  
Form: I FAC NAME: Corrected Date: 01/18/10  
Assessment: \$0 Inspector: WICKSTROM Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3162.1(a)

Remarks Date: 01/05/10

Failure to notify the BLM 24 hours prior to spudding well, running and cementing all casing strings, and BOP test, as stated in the drilling plan conditions of approvals. Please submit cement reports, and BOP test charts.

Office: NE ID: NE4258  
Unique INC #: 09MH098FC Well Name:  
Well #: 4 ID Date: 09/30/09  
Operator: FRANK EBLEN SYNDICATE INC Effective Date: 10/09/09  
Case #: WYB043623 FAC ID: 4 Abatement Date: 06/01/10  
Form: I FAC NAME: Corrected Date: 09/23/10  
Assessment: \$0 Inspector: HUNTLEY Followup Date: 09/23/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3163.1(a)

Remarks Date: 09/30/09

This Notice of Incidents of Noncompliance is being issued for failure to comply with all of the provisions of the Notice of Written Order number 09MH065HS (see attached). Comply with all of the requirements of the Notice of Written Order number 09MH065HS. This includes the removal of the pipe that runs across the entrance road to the oil tank battery from the plugged and abandoned Frank Eblen Syndicate well to the west. The unused oil tank # 440 must be removed from the location and the remaining oil tank must be properly bermed and fenced.

Office: NE ID: NE4598  
Unique INC #: 10JH0136I Well Name: FEDERAL  
Well #: 23-35 ID Date: 07/29/10  
Operator: TIMBERLINE PRODUCTION COMPANY Effective Date: 07/30/10  
Case #: WYW177066X FAC ID: Abatement Date: 08/02/10  
Form: I FAC NAME: Corrected Date: 07/30/10  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 08/06/10  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3162.1

Remarks Date: 07/29/10

The approved APD specified class G cement to be used when cementing the surface casing. A review of the drilling log indicated that 200 sx of light cement and 100 sx of class G were pumped. Please contact Jack Hanson, BLM-Petroleum Engineer, at 307 746-6600 to discuss remedial cementing options.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: PD		ID: PD1998
Unique INC #: 06RC02	Well Name: CABRITO	
	Well #: 67-25	ID Date: 02/03/06
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 02/06/06
Case #: WYW138889L	FAC ID:	Abatement Date: 04/01/06
Form: I	FAC NAME:	Corrected Date: 03/31/10
Assessment: \$0	Inspector: CANTERBURY	Followup Date: 03/31/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)		

Remarks Date: 02/03/06

Operator constructed the flare pit in an unapproved location..

Office: PD		ID: PD1996
Unique INC #: WY-100-RC-	Well Name: CABRITO	
	Well #: 16-25	ID Date: 02/03/06
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 02/06/06
Case #: WYW138889L	FAC ID:	Abatement Date: 04/01/06
Form: I	FAC NAME:	Corrected Date: 03/31/10
Assessment: \$0	Inspector: CANTERBURY	Followup Date: 03/31/10
Gravity: 3		Extend Date:
Authority Ref: Surface Use Plan Conditions of Approval		

Remarks Date: 02/03/06

The Completions Pit was constructed outside the area authorized for surface disturbance.

Office: PD		ID: PD1137
Unique INC #: RC-04-01	Well Name: YELLOW POINT	
	Well #: 1-12	ID Date: 11/19/03
Operator: MCMURRY OIL COMPANY		Effective Date: 12/09/03
Case #: WYW141883	FAC ID:	Abatement Date: 01/30/04
Form: I	FAC NAME:	Corrected Date: 03/31/10
Assessment: \$0	Inspector: CANTERBURY	Followup Date: 02/03/04
Gravity: 3		Extend Date:
Authority Ref: 3162.1(a)		

Remarks Date: 12/04/03

The Operator agreed during completion operations for the 5 additional wells on this location, a road would be constructed on the west side of the location through the reserve pit stockpile to access the north side of the location with pickup trucks and light vehicles. Although the Operator's representative originally proposed it, It was agreed a two track trail would not be created in the area east of the location. However during an inspection on 11/19/03, it was discovered the area east of the location was used for access and a two track trail was created and an area approximately 100 feet by 100 feet was disturbed. The Operator should submit a plan for reclaiming this area of unauthorized surface disturbance by January 30, 2004, The plan will include completing the reclamtion work by May 31, 2003

Safety and Drilling Related Violations (INC's) Issued During FY 2010  
As of March 3, 2011

Office: PD		ID: PD3302
Unique INC #: 11DE0022I	Well Name: MESA	
	Well #: 14C1-15	ID Date: 09/20/10
Operator: QEP ENERGY COMPANY		Effective Date: 09/22/10
Case #: WYW015317	FAC ID:	Abatement Date: 09/24/10
Form: I	FAC NAME:	Corrected Date: 09/24/10
Assessment: \$0	Inspector: ECKLUND	Followup Date: 09/24/10
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.A.i.viii.		

Remarks Date: 09/20/10

Found: While witnessing BOPE test and Drilling Inspection reviewed IADC log and found that the required annular functionality and activation of Pipe and Blind rams had not been documented and actually unknown if they were actually performed. Resolution: Function annular at least weekly. Activate Pipe and Blind rams each trip, need not be performed more than once a day. Record this information in the IADC Drillers log.

Office: PD		ID: PD2982
Unique INC #: 09DE2010	Well Name: MESA	
	Well #: 6B1-22	ID Date: 03/15/10
Operator: QUESTAR EXPL & PROD CO PNDL		Effective Date: 03/15/10
Case #: WYW015317	FAC ID:	Abatement Date: 03/16/10
Form: I	FAC NAME:	Corrected Date: 03/15/10
Assessment: \$0	Inspector: ECKLUND	Followup Date: 09/18/10
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.A.1.		

Remarks Date: 03/15/10

Found: Upon reviewing BOPE test charts various components were tested to 9000#. Resolution: Perform BOPE tests to comply with OO#2.III.A.1., COA's and APD Master Drill Plans. Rig is in Production stage of drilling at this time.

Office: PD		ID: PD3196
Unique INC #: 06DE0016I	Well Name: RIVERSIDE	
	Well #: 9C1-3D	ID Date: 07/03/10
Operator: ULTRA RESOURCES INC		Effective Date: 07/03/10
Case #: WYW06270	FAC ID:	Abatement Date: 07/07/10
Form: I	FAC NAME:	Corrected Date: 07/07/10
Assessment: \$0	Inspector: ECKLUND	Followup Date: 07/07/10
Gravity: 3		Extend Date:
Authority Ref: Master Drill Plan p. 4 of 8		

Remarks Date: 07/03/10

Found: Ultra's Master drill plan submitted was approved for cementing surface casing with density of 15.8 ppg on tail cement. Tail cement used was a 13.5 ppg. Resolution: Run cement as per approved APD Master drill plan.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: PD ID: PD1381  
Unique INC #: WW-04-004 Well Name: MESA  
Well #: 6-18 ID Date: 09/14/04  
Operator: ANSCHUTZ PINEDALE CORP Effective Date: 09/21/04  
Case #: WYW135123 FAC ID: Abatement Date: 09/22/04  
Form: I FAC NAME: Corrected Date: 04/02/10  
Assessment: \$0 Inspector: WILLIS Followup Date: 04/02/10  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 2. III.A.2.i.xi  
  
Remarks Date: 09/14/04

BOP drills, function testing of annular preventor, activation of pipe and blind rams, slow pump speed not recorded in driller's log. Regulations require all the above described tests and/or drills shall be recorded in the drilling log. Corrective action: Provide the proper documentation. (Document in driller's log)

Office: PD ID: PD1380  
Unique INC #: WW-04-003 Well Name: MESA  
Well #: 6-18 ID Date: 09/14/04  
Operator: ANSCHUTZ PINEDALE CORP Effective Date: 09/21/04  
Case #: WYW135123 FAC ID: Abatement Date: 09/28/04  
Form: I FAC NAME: Corrected Date: 04/02/10  
Assessment: \$0 Inspector: WILLIS Followup Date: 04/02/10  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3162.6(b)  
  
Remarks Date: 09/14/04

Well site not identified. Corrective action: Install a well identification sign.

Office: RE ID: RE81  
Unique INC #: 10DCI002 Well Name: LAKE VALLEY  
Well #: 10-29 ID Date: 09/23/10  
Operator: CABOT OIL & GAS CORPORATION Effective Date: 09/23/10  
Case #: NVN86819 FAC ID: Abatement Date: 09/24/10  
Form: I FAC NAME: Corrected Date: 09/23/10  
Assessment: \$0 Inspector: CARTER Followup Date: 09/23/10  
Gravity: 3 Extend Date:  
Authority Ref: OO#2..III.A.2.g  
  
Remarks Date: 09/23/10

A manual locking device--handwheels--or automatic locking devices shall be installed on all systems of 2M or greater. This inspection found no handwheels in place as required. This violation was corrected immediately upon bringing it to the attention of the Tool Pusher and Company Man.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: RE		ID: RE82
Unique INC #: 10DCI003	Well Name: LAKE VALLEY	
	Well #: 10-29	ID Date: 09/23/10
Operator: CABOT OIL & GAS CORPORATION		Effective Date: 09/23/10
Case #: NVN86819	FAC ID:	Abatement Date: 09/30/10
Form: I	FAC NAME:	Corrected Date: 09/27/10
Assessment: \$0	Inspector: CARTER	Followup Date: 10/12/10
Gravity: 1		Extend Date:
Authority Ref: OO#2.III.A.2.iv		

Remarks Date: 09/23/10

All BOPE connections subjected to well pressure shall be flanged, welded, or clamped. The inspection found that the panic line was threaded-with a threaded valve and threaded hammer union. These items needed to replaced as per regulations. Company Man stated that it would take a week to get the necessary parts to complete.

Office: RE		ID: RE80
Unique INC #: 10DCI001	Well Name: LAKE VALLEY	
	Well #: 10-29	ID Date: 09/23/10
Operator: CABOT OIL & GAS CORPORATION		Effective Date: 09/23/10
Case #: NVN86819	FAC ID:	Abatement Date: 09/24/10
Form: I	FAC NAME:	Corrected Date: 09/23/10
Assessment: \$0	Inspector: CARTER	Followup Date: 09/23/10
Gravity: 1		Extend Date:
Authority Ref: OO#2.III.A.2.e		

Remarks Date: 09/23/10

Power to the closing unit pumps shall be available at all times so that the pumps shall automatically start when the closing valve manifold pressure has dropped to the pre-set level. Air supply to the air pumps was found turned off at time of inspection. Violation was corrected by Tool Pusher/Co. Man. Normally, this violation would be an immediate assessment (\$500/day, not to exceed \$5000 (43 CFR 3163.1(b)(1).

Office: RO		ID: RO8463
Unique INC #: 26-200-10I	Well Name: GRID IRON BLI FEDERAL	
	Well #: 2	ID Date: 08/23/10
Operator: YATES PETROLEUM CORPORATION		Effective Date: 08/23/10
Case #: NMNM101580	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 08/30/10
Assessment: \$0	Inspector: FITZPATRICK	Followup Date: 08/30/10
Gravity: 3		Extend Date:
Authority Ref:		

Remarks Date: 08/23/10

Failure to notify authorized officer in time to witness casing being run

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: RO		ID: RO8464
Unique INC #: 27-200-10I	Well Name: GRID IRON BLI FEDERAL	
	Well #: 2	ID Date: 08/23/10
Operator: YATES PETROLEUM CORPORATION		Effective Date: 08/23/10
Case #: NMNM101580	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 08/30/10
Assessment: \$0	Inspector: FITZPATRICK	Followup Date: 08/30/10
Gravity: 3		Extend Date: 08/30/10
Authority Ref:		

Remarks Date: 08/23/10

Centerlizers were not run appropriate, the bottom three joints must each have one

Office: RO		ID: RO8457
Unique INC #: 25-002-10I	Well Name: SPEAR OA FEDERAL COM	
	Well #: 10	ID Date: 07/16/10
Operator: YATES PETROLEUM CORPORATION		Effective Date: 07/16/10
Case #: NMNM28171	FAC ID:	Abatement Date: 07/17/10
Form: I	FAC NAME:	Corrected Date: 07/21/10
Assessment: \$0	Inspector: TUCKER	Followup Date: 07/21/10
Gravity: 3		Extend Date:
Authority Ref: OO#2 III A 2. (b) iv.		

Remarks Date: 07/16/10

During a non detailed rig inspection performed 7/16/10, it was discovered the BOPE requirements enumerated in OO #2 III. A 2. (b) iv were not being met. The choke manifold had no gauge installed. Install a pressure gauge in the well control system designed for drilling fluid service.

Office: RW		ID: RW5178
Unique INC #: ML10038I	Well Name: CRESTON III UNIT	
	Well #: 12-26D	ID Date: 09/04/10
Operator: ANADARKO E & P COMPANY LP		Effective Date: 09/04/10
Case #: WYW109475X	FAC ID:	Abatement Date: 09/04/10
Form: I	FAC NAME:	Corrected Date: 09/04/10
Assessment: \$0	Inspector: LYON	Followup Date: 09/04/10
Gravity: 3		Extend Date:
Authority Ref: APD COA's		

Remarks Date: 09/04/10

Violation: Cement quantities required in APD were not followed. 265 sacks called for in APD, only 235 sacks were pumped. Corrective Action: Have required quantities of cement called for in the APD on location prior to starting Cementing activities. For all future cement jobs requirements for Cement called for in the APD will be followed, Unless Prior Authorization is received from BLM Petroleum Engineers.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: RW		ID: RW5114
Unique INC #: ML10026I	Well Name: LATHAM	
	Well #: 12-18-20-93	ID Date: 06/10/10
Operator: DEVON ENERGY PRODUCTION CO LP		Effective Date: 06/10/10
Case #: WYW162134	FAC ID:	Abatement Date: 06/11/10
Form: I	FAC NAME:	Corrected Date: 06/10/10
Assessment: \$0	Inspector: LYON	Followup Date: 06/10/10
Gravity: 1		Extend Date:
Authority Ref: COA's		

Remarks Date: 06/10/10

Violation: Drilling mud was not at appropriate weight for depth as required by APD. Abatement: Bring mud up to prescribed weight before continuing to drill ahead. Informed Ralph Montoya and Derek Ridgway of violation. Derek Ridgway called for mud to be weighted up immediately. Abatement period began immediately.

Office: RW		ID: RW4935
Unique INC #: AW2010-01	Well Name: EAST ECHO SPRINGS	
	Well #: 14-34-19-92	ID Date: 10/20/09
Operator: DEVON ENERGY PRODUCTION CO LP		Effective Date: 10/20/09
Case #: WYW131287	FAC ID:	Abatement Date: 11/26/09
Form: I	FAC NAME:	Corrected Date: 10/28/09
Assessment: \$0	Inspector: WHITE	Followup Date: 10/30/09
Gravity: 3		Extend Date:
Authority Ref: COA		

Remarks Date: 10/20/09

Trash

Office: TU		ID: iTU24911
Unique INC #: 10-JRF-189	Well Name: BOATSMAN	
	Well #: 2-1H	ID Date: 09/01/10
Operator: PENN VIRGINIA MC ENERGY LLC		Effective Date: 09/02/10
Case #: 142020513257	FAC ID:	Abatement Date: 09/17/10
Form: I	FAC NAME:	Corrected Date: 09/16/10
Assessment: \$0	Inspector: FRANKS	Followup Date: 09/22/10
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 09/01/10

You failed to notify this office 48 hrs before the surface casing was run and cemented as was you were required to do in the Conditions of Approval page 1 line 7.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: TU ID: iTU24900  
Unique INC #: 10-JRF-166 Well Name: BOATSMAN ID Date: 09/01/10  
Well #: 2-1H Effective Date: 09/02/10  
Operator: PENN VIRGINIA MC ENERGY LLC Abatement Date: 09/03/10  
Case #: 142020513257 FAC ID: Corrected Date: 09/03/10  
Form: I FAC NAME: Followup Date: 09/12/10  
Assessment: \$0 Inspector: FRANKS Extend Date:  
Gravity: 3  
Authority Ref: CRF 3162.6(b)

Remarks Date: 09/01/10

For wells located on Federal and Indian lands, The operator shall properly identify, by a sign in a conspicuous place , the well. The well sign shall include the well name, number, the operator, the lease serial number, the surveyed location( the sec., twp, and rng) .

Office: TU ID: iTU24901  
Unique INC #: 10-JRF-167 Well Name: BOATSMAN ID Date: 09/01/10  
Well #: 2-1H Effective Date: 09/02/10  
Operator: PENN VIRGINIA MC ENERGY LLC Abatement Date: 09/03/10  
Case #: 142020513257 FAC ID: Corrected Date: 09/03/10  
Form: I FAC NAME: Followup Date: 09/12/01  
Assessment: \$0 Inspector: FRANKS Extend Date:  
Gravity: 3  
Authority Ref: OSO #2 III.A.iii

Remarks Date: 09/01/10

All BOP connections subjected to well pressure shall be flanged, welded, or clamped. You are to replace the hammer unions on your panic line to conform with these regulations.

Office: TU ID: iTU24902  
Unique INC #: 10-JRF-168 Well Name: BOATSMAN ID Date: 09/01/10  
Well #: 2-1H Effective Date: 09/02/10  
Operator: PENN VIRGINIA MC ENERGY LLC Abatement Date: 09/03/10  
Case #: 142020513257 FAC ID: Corrected Date: 09/03/10  
Form: I FAC NAME: Followup Date: 09/12/10  
Assessment: \$0 Inspector: FRANKS Extend Date:  
Gravity: 3  
Authority Ref: OSO #2 III.A2.g

Remarks Date: 09/01/10

A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: TU		ID: iTU24879
Unique INC #: 10-JRF-163	Well Name: LIZZIE STARR	
	Well #: 2-18	ID Date: 07/28/10
Operator: CHIZUM OIL LLC		Effective Date: 07/28/10
Case #: 46660	FAC ID:	Abatement Date: 07/28/10
Form: I	FAC NAME:	Corrected Date: 08/02/10
Assessment: \$0	Inspector: FRANKS	Followup Date: 08/02/10
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3164.1(b)	Onshore Order #2,III.B.	

Remarks Date: 07/28/10

The casing and cementing programs shall be conducted as approved. The submitted pipe manifest requested showed that the casing in the well bore was not in accordance with the approved plan. You are to obtain approval from the operations staff before proceeding with operations. All verbal approvals are to be followed by a sundry notice detailing the change and demonstrating that the change meets or exceeds the standards of the original casing standards, or justification for the lesser grade.

Office: TU		ID: iTU24880
Unique INC #: 10-JRF-164	Well Name: LIZZIE STARR	
	Well #: 2-18	ID Date: 07/28/10
Operator: CHIZUM OIL LLC		Effective Date: 07/28/10
Case #: 46660	FAC ID:	Abatement Date: 07/28/10
Form: I	FAC NAME:	Corrected Date: 08/04/10
Assessment: \$0	Inspector: FRANKS	Followup Date: 08/05/10
Gravity: 1		Extend Date: 08/04/10
Authority Ref: 43 CFR 3164.1(b)	Onshore Order #2,III.A.2.a.i	

Remarks Date: 07/28/10

The blowout preventer (BOPE) and related equipment shall be installed, and tested in a manner necessary to assure well control. The BOPE on location does not meet minimum standards and must be brought up to these standards before drilling out the surface casing shoe. You are to install a system which meets the minimum standards for a 2M system. You must have an accumulator, choke manifold, and an annular preventor and or a two ram preventer rated at least for 2M. The accumulator must be of sufficient rating to operate the BOPE. and the choke manifold must meet the minimum requirements as stated in Onshore Operations #2.

Office: TU		ID: iTU24928
Unique INC #: 10-DJM-176	Well Name: BEHNKE	
	Well #: 2-1H	ID Date: 09/15/10
Operator: PENN VIRGINIA MC ENERGY LLC		Effective Date: 09/17/10
Case #: OKNM79776	FAC ID:	Abatement Date: 09/17/10
Form: I	FAC NAME:	Corrected Date: 09/16/10
Assessment: \$0	Inspector: MCMILLAN	Followup Date: 09/16/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)		

Remarks Date: 09/15/10

Verbal notification shall be given to the Authorized Officer at least 48 hours before formation tests, BOP tests, running and cementing casing, and drilling over lease expiration dates. You were required to notify the Authorized Officer 48 hours in advance per conditions of approval page 1 line 7.

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: VE		ID: VE12875
Unique INC #: AW10005	Well Name: LONE TREE FEDERAL	
	Well #: H-22-9-17	ID Date: 05/18/10
Operator: NEWFIELD EXPLORATION COMPANY		Effective Date: 05/28/10
Case #: UTU87538X	FAC ID:	Abatement Date: 06/15/10
Form: I	FAC NAME:	Corrected Date: 06/02/10
Assessment: \$0	Inspector: ALAN WALKER	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.6(a)(b)		

Remarks Date: 05/18/10

Every well within a Federal or Indian lease or supervised agreement shall have a well identification sign. All signs shall be maintained in a legible condition. There is no well sign, install well sign as per above stated regulations.

Office: VE		ID: VE12929
Unique INC #: WO10016	Well Name: SOUTH MONUMENT BUTTE	
	Well #: W-2-9-16	ID Date: 06/01/10
Operator: NEWFIELD EXPLORATION COMPANY		Effective Date: 09/15/10
Case #: UTU87538X	FAC ID:	Abatement Date: 09/30/10
Form: I	FAC NAME:	Corrected Date: 09/23/10
Assessment: \$0	Inspector: BILL OWENS	Followup Date: 09/23/10
Gravity: 1		Extend Date:
Authority Ref: 43 cfr 3162.3-1(c)		

Remarks Date: 09/10/10

The above referenced well was spud on 3/29/2010 and reached a total depth on 4/13/2010 in a federal lease without an approved application for permit to drill (APD).

Office: VE		ID: VE12934
Unique INC #: WO10021	Well Name: MONUMENT BUTTE EAST	
	Well #: B-36-8-16	ID Date: 06/01/10
Operator: NEWFIELD EXPLORATION COMPANY		Effective Date: 09/15/10
Case #: UTU87538X	FAC ID:	Abatement Date: 09/30/10
Form: I	FAC NAME:	Corrected Date: 09/23/10
Assessment: \$0	Inspector: BILL OWENS	Followup Date: 09/23/10
Gravity: 1		Extend Date:
Authority Ref: 43 cfr 3161.3-1(c)		

Remarks Date: 09/10/10

The above referenced well was spud on 6/12/2010 and reached total depth on 6/25/2010 in a federal lease without a approved application for permit to drill (APD).

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: VE ID: VE12935  
Unique INC #: WO10022 Well Name: GREATER MONUMENT BUTTE  
Well #: T-36-8-16 ID Date: 06/01/10  
Operator: NEWFIELD EXPLORATION COMPANY Effective Date: 09/15/10  
Case #: UTU87538X FAC ID: Abatement Date: 09/30/10  
Form: I FAC NAME: Corrected Date: 09/23/10  
Assessment: \$0 Inspector: BILL OWENS Followup Date: 09/23/10  
Gravity: 1 Extend Date:  
Authority Ref: 43 cfr 3162.3-1(c)

Remarks Date: 09/10/10

The above referenced well was spud on 6/17/2010 and reached a total depth on 6/30/2010 in a federal lease without an approved application for permit to drill (APD).

Office: VE ID: VE12907  
Unique INC #: WO10013 Well Name: SOUTH MONUMENT BUTTE  
Well #: X-2-9-16 ID Date: 05/19/10  
Operator: NEWFIELD EXPLORATION COMPANY Effective Date: 06/01/10  
Case #: UTU87538X FAC ID: Abatement Date: 07/26/10  
Form: I FAC NAME: Corrected Date: 08/13/10  
Assessment: \$5,000 Inspector: BILL OWENS Followup Date: 08/13/10  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3163.1(b)(2)

Remarks Date: 05/19/10

The above referenced well was spud on 3/8/2010 and reached total depth on 3/17/2010 in a federal lease without an approved application for permit to drill (APD). Therefore an assessment of \$500.00 per day for each day the violation existed, including days the violation existed prior to the discovery (05/19/2010), not to exceed \$5000.00 is required. The assessment is \$5000.00 (\$500.00 times ten (10) days).

Office: VE ID: VE12931  
Unique INC #: WO10018 Well Name: MONUMENT BUTTE EAST  
Well #: J-36-8-16 ID Date: 06/01/10  
Operator: NEWFIELD EXPLORATION COMPANY Effective Date: 09/15/10  
Case #: UTU87538X FAC ID: Abatement Date: 09/30/10  
Form: I FAC NAME: Corrected Date: 09/23/10  
Assessment: \$0 Inspector: BILL OWENS Followup Date: 09/23/10  
Gravity: 1 Extend Date:  
Authority Ref: 43 cfr 3162.3-1(c)

Remarks Date: 09/10/10

The above referenced well was spud on 6/5/2010 and reached a total depth on 6/11/2010 in a federal lease without an approved application for permit to drill (APD).

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: VE ID: VE12933  
Unique INC #: WO10020 Well Name: MONUMENT BUTTE EAST ID Date: 06/01/10  
Well #: C-36-8-16 Effective Date: 09/15/10  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date: 09/30/10  
Case #: UTU87538X FAC ID: Corrected Date: 09/23/10  
Form: I FAC NAME: Followup Date: 09/23/20  
Assessment: \$0 Inspector: BILL OWENS Extend Date:  
Gravity: 1  
Authority Ref: 43 cfr 3162.3-1(c)

Remarks Date: 06/01/10

The above referenced well was spud on 6/11/2010 and reached total depth on 6/22/2010 in a federal lease without a approved application for permit to drill (APD).

Office: VE ID: VE12928  
Unique INC #: WO10015 Well Name: SOUTH MONUMENT BUTTE ID Date: 06/01/10  
Well #: P-2-9-16 Effective Date: 09/15/10  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date: 09/30/10  
Case #: UTU87538X FAC ID: Corrected Date: 09/23/10  
Form: I FAC NAME: Followup Date: 09/23/10  
Assessment: \$0 Inspector: BILL OWENS Extend Date:  
Gravity: 1  
Authority Ref: 43 cfr 3162.3-1(c)

Remarks Date: 06/01/10

The above referenced well was spud on 3/9/2010 and reached total depth on 3/21/2010 in a federal lease without an approved application for permit to drill (APD).

Office: VE ID: VE12908  
Unique INC #: WO10014 Well Name: SOUTH MONUMENT BUTTE ID Date: 06/01/10  
Well #: V-2-9-16 Effective Date: 06/01/10  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date: 07/26/10  
Case #: UTU87538X FAC ID: Corrected Date: 08/13/10  
Form: I FAC NAME: Followup Date: 08/13/10  
Assessment: \$5,000 Inspector: BILL OWENS Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3163.1(b)(2)

Remarks Date: 08/06/10

The above referenced well was spus on 4/1/2010 and reached total depth on 4/10/2010 in a federal lease without an approved application for permit to drill (APD). Therefore an assessment of \$500.00 per day for each day the violation existed, including days the violation existed prior to the discovery (6/1/2010), not to exceed \$5000.00 is required. The assesment is \$5000.00 (\$500.00 times ten (10) days.

Safety and Drilling Related Violations (INC)s Issued During FY 2010  
As of March 3, 2011

Office: VE ID: VE12936  
Unique INC #: WO10023 Well Name: GREATER MONUMENT BUTTE ID Date: 06/01/10  
Well #: B-1-9-16 Effective Date: 09/15/10  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date: 09/30/10  
Case #: UTU87538X FAC ID: Corrected Date: 09/23/10  
Form: I FAC NAME: Followup Date: 09/23/05  
Assessment: \$0 Inspector: BILL OWENS Extend Date:  
Gravity: 1  
Authority Ref: 43 cfr 3162.3-1(c)

Remarks Date: 09/10/10

The above referenced well was spud on 4/23/2010 and reached total depth on 5/8/2010 in a federal lease without a approved application for permit to drill (APD).

Office: VE ID: VE12938  
Unique INC #: WO10025 Well Name: GREATER MONUMENT BUTTE ID Date: 06/01/10  
Well #: F-1-9-16 Effective Date: 09/15/10  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date: 09/30/10  
Case #: UTU87538X FAC ID: Corrected Date: 09/23/10  
Form: I FAC NAME: Followup Date: 09/23/10  
Assessment: \$0 Inspector: BILL OWENS Extend Date:  
Gravity: 1  
Authority Ref: 43 cfr 3162.3-1(c)

Remarks Date: 09/10/10

The above referenced well was spud on 6/30/2010 and reached total depth on 7/9/2010 in a federal lease without a aproved application for permit to drill (APD).

Office: VE ID: VE12930  
Unique INC #: WO10017 Well Name: MONUMENT BUTTE EAST ID Date: 06/01/10  
Well #: K-36-8-16 Effective Date: 09/15/10  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date: 09/30/10  
Case #: UTU87538X FAC ID: Corrected Date: 09/23/10  
Form: I FAC NAME: Followup Date: 09/23/10  
Assessment: \$0 Inspector: BILL OWENS Extend Date:  
Gravity: 1  
Authority Ref: 43 cfr 3162.3-1(c)

Remarks Date: 09/10/10

The above referenced well was spud on 5/18/2010 and reached a total depth on 5/25/2010 in a federal lease without an approved application for permit to drill (APD).

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: VE		ID: VE12932
Unique INC #: WO10019	Well Name: MONUMENT BUTTE EAST	
	Well #: A-36-8-16	ID Date: 06/01/10
Operator: NEWFIELD EXPLORATION COMPANY		Effective Date: 09/15/10
Case #: UTU87538X	FAC ID:	Abatement Date: 09/30/10
Form: I	FAC NAME:	Corrected Date: 09/23/10
Assessment: \$0	Inspector: BILL OWENS	Followup Date: 09/23/10
Gravity: 1		Extend Date:
Authority Ref: 43 cfr 3162.3-1(c)		

Remarks Date: 09/10/10

The above referenced well was spud on 6/6/2010 and reached total depth on 6/16/2010 in a federal lease without an approved application for permit to drill (APD).

Office: VE		ID: VE12877
Unique INC #: CT10005	Well Name: FEDERAL	
	Well #: 13-6D-64	ID Date: 05/28/10
Operator: BERRY PETROLEUM COMPANY		Effective Date: 06/10/10
Case #: UTU77322	FAC ID:	Abatement Date: 06/16/10
Form: I	FAC NAME:	Corrected Date: 06/16/10
Assessment: \$500	Inspector: CADE TAYLOR	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.3-1(c);Onshore Order No. 1, III., B. 2.		

Remarks Date: 05/28/10

THE ABOVE REFERENCED WELL WAS DRILLED ON 5/26/2010 WITHOUT AN APPROVED APD, WHICH RESULTS IN AN IMMEDIATE ASSESSMENT OF \$ 500.00. ASSESSMENT IS FOR DRILLING WITHOUT APPROVAL , \$ 500.00 PER DAY FOR EACH DAY THAT THE VIOLATION EXISTED.

Office: VE		ID: iVE11803
Unique INC #: RA10032	Well Name: UTE TRIBAL	
	Well #: 20-15	ID Date: 03/20/10
Operator: PETROGLYPH OPERATING CO INC		Effective Date: 03/20/10
Case #: 1420H624650	FAC ID:	Abatement Date: 03/20/10
Form: I	FAC NAME:	Corrected Date: 03/20/10
Assessment: \$0	Inspector: R ARNOLD	Followup Date: 03/20/10
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)		

Remarks Date: 03/20/10

Surface casing cement not as approved. \* Hand delivered to Les Farnsworth

Safety and Drilling Related Violations (INCs) Issued During FY 2010  
As of March 3, 2011

Office: VE ID: VE12951  
Unique INC #: CRB10025 Well Name: FEDERAL  
Well #: 16-35-8-15 ID Date: 09/20/10  
Operator: NEWFIELD EXPLORATION COMPANY Effective Date: 09/20/10  
Case #: UTU87538X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: RANDY BYWATER Abatement Date: 09/24/10  
Gravity: 3 Corrected Date: 09/22/10  
Authority Ref: 43cfr3162.6{b} Followup Date:  
Remarks Date: 09/20/10 Extend Date:

No well sign. Install required sign with required information.

Office: WO ID: WO2583  
Unique INC #: 10-OL-15 Well Name: HALF MOON FEDERAL  
Well #: 008-22 ID Date: 05/21/10  
Operator: PHOENIX PRODUCTION COMPANY Effective Date: 05/21/10  
Case #: WYW150042 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR Abatement Date: 05/21/10  
Gravity: 3 Corrected Date: 05/21/10  
Authority Ref: OO#2 III. A. Followup Date:  
Remarks Date: 05/21/10 Extend Date:

No hand wheel on kill line valve. In place befor insp. left loc.

Office: WO ID: WO2585  
Unique INC #: 010-10-013 Well Name: UTAH SOUTHERN  
Well #: 75 ID Date: 05/25/10  
Operator: MARATHON OIL COMPANY Effective Date: 05/26/10  
Case #: WYW109519A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SWICK Abatement Date: 05/26/10  
Gravity: 3 Corrected Date: 05/26/10  
Authority Ref: 43CFR 3164.1 O.O. #2 III. A. g. Followup Date:  
Remarks Date: 05/25/10 Extend Date:

During my Drilling Inspection found blind and pipe rams with no hand wheels. These hand wheels are a locking device for the rams and are required to be installed during drilling operations. Talked to the company hand and driller about this.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: BU ID: BU13468  
Unique INC #: MB-09-2 Well Name: HIGHLINE ADDITION I SPELLMAN ID Date: 10/27/08  
Well #: A3-22\* Effective Date: 10/29/08  
Operator: COMET ENERGY SERVICES LLC Abatement Date: 10/30/08  
Case #: WYW132260 FAC ID: Corrected Date: 10/30/08  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: BLAKESLEY Extend Date:  
Gravity: 3  
Authority Ref: COA's

Remarks Date: 10/27/08

You have failed to maintain 2' of free board in the pits. You must maintain a minimum 2' of free board in the pits at all times.

Office: BU ID: BU13424  
Unique INC #: MB-08-15 Well Name: DIAMOND RUN IBERLIN ID Date: 09/29/08  
Well #: 12-6 Effective Date: 09/29/08  
Operator: BLACK DIAMOND ENERGY INC Abatement Date: 10/01/08  
Case #: WYW34743 FAC ID: Corrected Date: 11/02/08  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: BLAKESLEY Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (b)

Remarks Date: 09/29/08

There is no well sign on this drill site. You must install a well sign that contains the following: Well name and number, lease number, operator name, legal land description including the 1/4 1/4, section, township, and range.

Office: BU ID: BU13449  
Unique INC #: KRB090011 Well Name: HOMESTEAD DR III S ODEGARD ID Date: 09/23/08  
Well #: 3CKWP-30 Effective Date: 10/08/08  
Operator: JM HUBER CORP Abatement Date: 10/15/08  
Case #: WYW0108382 FAC ID: Corrected Date: 10/22/08  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: BRUS Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.5-1(a)

Remarks Date: 09/23/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

This well was relocated to the existing road disturbance at the onsite to reduce disturbance to sagebrush habitat. On Sept 23, Operator reported that contractor (surface owner) had mistakenly brush hogged through thick sagebrush habitat to the original location proposed for this well, brushhogged the location and installed the pipelines. The operator halted construction and notified the BFO. They subsequently removed the pipeline, reseeded the disturbance and blocked it off to prevent travel. This will be an inc, but no assessment. Corrective Action: 1) The operator will monitor the revegetation success and reseed next spring if warranted. 2) Access to mowed area will remain blocked for the life of the project.

Office: BU		ID: BU13390
Unique INC #: JNE-09-10	Well Name:	
	Well #: 176	
Operator: ANADARKO E&P COMPANY LP		
Case #: WYB044668	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: EVANS	
Gravity: 3		
Authority Ref: COA		

Remarks Date: 09/18/08

MIT was ordered by 8/31/08 as COA for TA status.

Office: BU		ID: BU13389
Unique INC #: JNE-09-02	Well Name: LK A	
	Well #: 5	
Operator: ANADARKO E&P COMPANY LP		
Case #: WYB044668	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: EVANS	
Gravity: 3		
Authority Ref: COA		

Remarks Date: 09/18/08

MIT ordered by 8/31/08 as COA for TA status.

Office: BU		ID: BU13388
Unique INC #: JNE-09-01	Well Name: MC	
	Well #: 44	
Operator: ANADARKO E&P COMPANY LP		
Case #: WYB044668	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: EVANS	
Gravity: 3		
Authority Ref: COA		

Remarks Date: 09/18/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

MIT was ordered by 8/31/08 as COA for TA status

Office: BU ID: BU14332  
Unique INC #: JNE-09-40 Well Name: FEDERAL  
Well #: 2-27  
Operator: KENNEDY OIL ID Date: 05/05/09  
Case #: WYW0148158 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: TA Sundry COA #3  
Abatement Date: 06/30/09  
Corrected Date: 08/01/09  
Followup Date: 06/16/09  
Extend Date: 08/15/09

Remarks Date: 05/05/09

Kennedy Oil as a Condition of Approval to TA this well was to MIT the well by 4/30/2009. The MIT on this well shall be run by 6/30/2009.

Office: BU ID: BU14335  
Unique INC #: JNE-09-43 Well Name:  
Well #: 8-22  
Operator: KENNEDY OIL ID Date: 05/05/09  
Case #: WYW0148158 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: TA Sundry COA #3  
Effective Date: 05/11/09  
Abatement Date: 06/30/09  
Corrected Date: 08/01/09  
Followup Date: 06/16/09  
Extend Date: 08/15/09

Remarks Date: 05/05/09

Kennedy Oil as a Condition of Approval to TA this well was to MIT the well by 4/30/2009. The MIT on this well shall be run by 6/30/2009.

Office: BU ID: BU14334  
Unique INC #: JNE-09-42 Well Name: FEDERAL  
Well #: 5-22  
Operator: KENNEDY OIL ID Date: 05/05/09  
Case #: WYW0148158 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: TA Sundry COA #3  
Effective Date: 05/11/09  
Abatement Date: 06/30/09  
Corrected Date: 08/01/09  
Followup Date: 06/16/09  
Extend Date: 08/15/09

Remarks Date: 05/05/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Kennedy Oil as a Condition of Approval to TA this well was to MIT the well by 4/30/2009. The MIT on this well shall be run by 6/30/2009.

Office: BU		ID: BU14333
Unique INC #: JNE-09-41	Well Name: FEDERAL	
	Well #: 3-22	
Operator: KENNEDY OIL		ID Date: 05/05/09
Case #: WYW0148158	FAC ID:	Effective Date: 05/11/09
Form: I	FAC NAME:	Abatement Date: 06/30/09
Assessment: \$0	Inspector: EVANS	Corrected Date: 08/01/09
Gravity: 3		Followup Date: 06/16/09
Authority Ref: TA Sundry COA #3		Extend Date: 08/15/09

Remarks Date: 05/05/09

Kennedy Oil as a Condition of Approval to TA this well was to MIT the well by 4/30/2009. The MIT on this well shall be run by 6/30/2009.

Office: BU		ID: BU13392
Unique INC #: JNE-09-04	Well Name: TN A	
	Well #: 175	
Operator: ANADARKO E&P COMPANY LP		ID Date: 08/31/08
Case #: WYW109596B	FAC ID:	Effective Date: 09/25/08
Form: I	FAC NAME:	Abatement Date: 10/31/08
Assessment: \$0	Inspector: EVANS	Corrected Date: 11/30/08
Gravity: 3		Followup Date: 10/23/08
Authority Ref: COA		Extend Date: 12/31/08

Remarks Date: 09/18/08

MIT as ordered by 8/31/08 as COA for TA status

Office: BU		ID: BU13399
Unique INC #: JNE-09-12	Well Name: TN A	
	Well #: 179	
Operator: ANADARKO E&P COMPANY LP		ID Date: 08/31/08
Case #: WYW109596B	FAC ID:	Effective Date: 09/25/08
Form: I	FAC NAME:	Abatement Date: 10/31/08
Assessment: \$0	Inspector: EVANS	Corrected Date: 11/30/08
Gravity: 3		Followup Date: 10/23/08
Authority Ref: COA		Extend Date: 12/31/08

Remarks Date: 09/18/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13393  
Unique INC #: JNE-09-05 Well Name: TN A  
Well #: 193 ID Date: 08/31/08  
Effective Date: 09/25/08  
Operator: ANADARKO E&P COMPANY LP Abatement Date: 10/31/08  
Case #: WYW109596B FAC ID: Corrected Date: 11/30/08  
Form: I FAC NAME: Followup Date: 10/23/08  
Assessment: \$0 Inspector: EVANS Extend Date: 12/31/08  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13391  
Unique INC #: JNE-09-03 Well Name: TN A  
Well #: 173 ID Date: 08/31/08  
Effective Date: 09/25/08  
Operator: ANADARKO E&P COMPANY LP Abatement Date: 10/31/08  
Case #: WYW109596B FAC ID: Corrected Date: 11/30/08  
Form: I FAC NAME: Followup Date: 10/23/08  
Assessment: \$0 Inspector: EVANS Extend Date: 12/31/05  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

MIT was orderde by 8/31/08 as COA for TA status.

Office: BU ID: BU13397  
Unique INC #: JNE-09-11 Well Name: 1TN A  
Well #: 178 ID Date: 08/31/08  
Effective Date: 09/25/08  
Operator: ANADARKO E&P COMPANY LP Abatement Date: 10/31/08  
Case #: WYW109596B FAC ID: Corrected Date: 11/30/08  
Form: I FAC NAME: Followup Date: 10/23/08  
Assessment: \$0 Inspector: EVANS Extend Date: 12/31/08  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13396  
Unique INC #: JNE-09-09 Well Name: 1TN A  
Well #: 172  
Operator: ANADARKO E&P COMPANY LP  
Case #: WYW109596B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13394  
Unique INC #: JNE-09-07 Well Name: TN A  
Well #: 95  
Operator: ANADARKO E&P COMPANY LP  
Case #: WYW109596B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13395  
Unique INC #: JNE-09-08 Well Name: TN A  
Well #: 127  
Operator: ANADARKO E&P COMPANY LP  
Case #: WYW109596B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13398  
Unique INC #: JNE-09-13 Well Name: TN  
Well #: 204 ID Date: 08/31/08  
Effective Date: 09/25/08  
Operator: ANADARKO E&P COMPANY LP Abatement Date: 10/31/08  
Case #: WYW109596B FAC ID: Corrected Date: 11/30/08  
Form: I FAC NAME: Followup Date: 10/23/08  
Assessment: \$0 Inspector: EVANS Extend Date: 12/31/08  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13400  
Unique INC #: JNE-09-14 Well Name: MC  
Well #: 205 ID Date: 08/31/08  
Effective Date: 09/25/08  
Operator: ANADARKO E&P COMPANY LP Abatement Date: 10/31/08  
Case #: WYW109596B FAC ID: Corrected Date: 11/30/08  
Form: I FAC NAME: Followup Date: 10/23/08  
Assessment: \$0 Inspector: EVANS Extend Date: 12/31/08  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU13401  
Unique INC #: JNE-09-06 Well Name: SHANNON AB  
Well #: 48 ID Date: 08/31/08  
Effective Date: 09/25/08  
Operator: ANADARKO E&P COMPANY LP Abatement Date: 10/31/08  
Case #: WYW109596D FAC ID: Corrected Date: 11/30/08  
Form: I FAC NAME: Followup Date: 10/23/08  
Assessment: \$0 Inspector: EVANS Extend Date: 12/31/08  
Gravity: 3  
Authority Ref: COA

Remarks Date: 09/18/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

MIT as ordered by 8/31/08 as COA for TA status

Office: BU ID: BU14726  
Unique INC #: JNE-09-53 Well Name: ANTELOPE FLAT SIOUX RANCH  
Well #: 14-22 ID Date: 06/15/09  
Operator: COLEMAN OIL & GAS INCORPORATED Effective Date: 06/22/09  
Case #: WYW143520 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: TA Sundry COA #1  
Abatement Date: 07/30/09  
Corrected Date: 06/24/09  
Followup Date: 07/08/09  
Extend Date:

Remarks Date: 06/15/09

As a Condition of Approval for TA of Antelope 14-22 Coleman was to either MIT the well or submitt Sundry to Plug and Abandon by 4/30/2009. Coleman shall either MIT or submitt Sundry to Plug and Abandon the Antelope 14-22 well by 7/30/2009.

Office: BU ID: BU14732  
Unique INC #: JNE-09-54 Well Name: ANTELOPE FLAT SIOUX RANCH  
Well #: 21-27 ID Date: 06/15/09  
Operator: COLEMAN OIL & GAS INCORPORATED Effective Date: 06/22/09  
Case #: WYW143521 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: EVANS  
Gravity: 3  
Authority Ref: TA Sundry COA #1  
Abatement Date: 07/30/09  
Corrected Date: 06/24/09  
Followup Date: 07/08/09  
Extend Date:

Remarks Date: 06/15/09

As a Condition of Approval for TA of Antelope 21-27 Coleman was to either MIT the well or submitt Sundry to Plug and Abandon by 4/30/2009. Coleman shall either MIT or submitt Sundry to Plug and Abandon the Antelope 21-27 well by 7/30/2009.

Office: BU ID: BU13491  
Unique INC #: JJ-09-002 Well Name: DIAMOND RUN MOORE  
Well #: 41-12 ID Date: 10/30/08  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 10/30/08  
Case #: WYW39577 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JETTE, JEFF  
Gravity: 3  
Authority Ref: Onshore Order #2.III.B.1.a.  
Abatement Date: 10/30/08  
Corrected Date: 11/06/08  
Followup Date: 11/06/08  
Extend Date:

Remarks Date: 10/30/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

7" x 17# Limited Service casing does not meet Master Drilling Plan casing design. Corrective action remove casing and run approved casing.

Office: BU		ID: BU13492
Unique INC #: JJ-09-003	Well Name: DIAMOND RUN MOORE	
	Well #: 41-12	ID Date: 10/30/08
Operator: BLACK DIAMOND ENERGY INC		Effective Date: 10/30/08
Case #: WYW39577	FAC ID:	Abatement Date: 10/30/08
Form: I	FAC NAME:	Corrected Date: 11/06/08
Assessment: \$0	Inspector: JETTE, JEFF	Followup Date: 11/06/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval Diamond Run POD		

Remarks Date: 10/30/08

When casing was pulled from hole no centralizers were on the bottom three joints. Corrective action put centralizers on bottom three joints as specified in the conditions of approval.

Office: BU		ID: BU14281
Unique INC #: MM09029I	Well Name: PETERSEN 29 EXT CHASE FARMS	
	Well #: 13-23MZCR	ID Date: 04/16/09
Operator: PENNACO ENERGY, INC.		Effective Date: 05/11/09
Case #: WYW145650	FAC ID:	Abatement Date: 06/08/09
Form: I	FAC NAME:	Corrected Date: 06/23/09
Assessment: \$0	Inspector: MADDUX	Followup Date: 04/24/09
Gravity: 3		Extend Date: 07/10/09
Authority Ref: COA; Cultural #1; page 5		

Remarks Date: 04/16/09

Violation: The operator failed to comply with Site Specific Condition of Approval (Cultural)(1) on page 5 of the Surface Use Conditions of Approval for the Petersen 29 Ext. POD. Corrective Action: 1. Per the Site Specific COA (Cultural) (1), archaeological monitoring was required for the construction of well pad #13-23-58-82 and associated infrastructure. Because the reserve pits were not monitored, a trench with a minimum length of 12 feet and to the depth of the original pit must be opened and analyzed by a cultural resource use permittee (CRUP). The trench should be placed adjacent to or in close proximity to the original reserve pits. The trench wall must be examined and profiled by a CRUP. Any questions related to this corrective action should be directed to Ardy Hahn, BFO archeologist at (307) 684 1043. 2. If any cultural values [sites, artifacts, human remains (Appendix L PRB FEIS)] are observed, they will be left intact and the Buffalo Field Manager notified. Further discovery procedures are explained in the Standard COA (General)(A)(1). 3. A report documenting this corrective action will be presented to the BLM-BFO within 30 days of completion of the work.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: BU ID: BU13337  
Unique INC #: RN-08-92 Well Name: WEST KITTY THRONE ID Date: 09/02/08  
Well #: 41-10AN Effective Date: 09/02/08  
Operator: KENNEDY OIL Abatement Date: 09/22/08  
Case #: WYW0203041 FAC ID: Corrected Date: 10/03/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 09/02/08

You have failed to comply per INC #RN-08-8; the return receipt was signed 8-14-08. You are to log this well from the top of cement call Rafael Navarrette at (307) 684-1165 or (307)217-0740 prior to logging. DO NOT do any cementing prior to logging.

Office: BU ID: BU13338  
Unique INC #: RN-08-93 Well Name: WEST KITTY BARLOW, WEST KITTY THRONE ID Date: 09/02/08  
Well #: 34-10AN, 41-10AN Effective Date: 09/02/08  
Operator: KENNEDY OIL Abatement Date: 09/22/08  
Case #: WYW0203041 FAC ID: Corrected Date: 10/03/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 09/02/08

You have failed to comply per INC #RN-08-81; the return receipt was signed 8-14-08. You are to log this well from the top of cement call Rafael Navarrette at (307) 684-1165 or (307)217-0740 prior to logging. DO NOT do any cementing prior to logging.

Office: BU ID: BU13260  
Unique INC #: RN-08-78 Well Name: ID Date: 08/12/08  
Well #: Effective Date: 08/12/08  
Operator: KENNEDY OIL Abatement Date: 08/29/08  
Case #: WYW0203041 FAC ID: 41-10A Corrected Date: 10/03/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III.B.b and COA

Remarks Date: 08/12/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: BU ID: BU13375  
Unique INC #: RN-08-97 Well Name: WEST KITTY GUSTAFSON ID Date: 09/08/08  
Well #: 23-14AN Effective Date: 09/08/08  
Operator: KENNEDY OIL Abatement Date: 09/29/08  
Case #: WYW0203042 FAC ID: Corrected Date: 10/03/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III.B.c. and COA  
  
Remarks Date: 09/08/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Office: BU ID: BU13373  
Unique INC #: RN-08-95 Well Name: WEST KITTY GUSTAFSON ID Date: 09/08/08  
Well #: 14-14AN Effective Date: 09/08/08  
Operator: KENNEDY OIL Abatement Date: 09/29/08  
Case #: WYW0203042 FAC ID: Corrected Date: 10/03/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III.B.c. and COA  
  
Remarks Date: 09/08/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Office: BU ID: BU13372  
Unique INC #: RN-08-94 Well Name: WEST KITTY GUSTAFSON ID Date: 09/08/08  
Well #: 34-14AN Effective Date: 09/08/08  
Operator: KENNEDY OIL Abatement Date: 09/29/08  
Case #: WYW0203042 FAC ID: Corrected Date: 10/03/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III.B.c. and COA  
  
Remarks Date: 09/08/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: BU		ID: BU13481
Unique INC #: RN-08-103	Well Name: TEX DRAW T CHAIR	
	Well #: 43-27	ID Date: 11/03/08
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 11/05/08
Case #: WYW142081	FAC ID:	Abatement Date: 11/24/08
Form: I	FAC NAME:	Corrected Date: 11/07/08
Assessment: \$0	Inspector: NAVARRETTE	Followup Date: 11/07/08
Gravity: 3		Extend Date:
Authority Ref: COA and Onshore Order #2		

Remarks Date: 11/05/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307) 684-1165 or (307) 217-0740 prior to logging and doing any remedial cementing.

Office: BU		ID: BU14585
Unique INC #: RN-09-13	Well Name:	
	Well #:	ID Date: 06/04/09
Operator: MERIT ENERGY CO		Effective Date: 06/08/09
Case #: WYW174634	FAC ID: 43-33	Abatement Date: 06/18/09
Form: I	FAC NAME: TUIT DRAW FED.	Corrected Date: 06/22/09
Assessment: \$0	Inspector: NAVARRETTE	Followup Date: 06/22/09
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2 III.B.c. & COA		

Remarks Date: 06/08/09

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Office: BU		ID: BU13730
Unique INC #: GR0830	Well Name: HD CBM 3 HARTZOG	
	Well #: 12-24BG	ID Date: 12/23/08
Operator: XTO ENERGY INC		Effective Date: 12/23/08
Case #: WYW42622	FAC ID:	Abatement Date: 01/09/09
Form: I	FAC NAME:	Corrected Date: 01/05/09
Assessment: \$0	Inspector: ROTH	Followup Date: 01/13/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 12/23/08

Failure to maintain well identification. Specifically; No well identification sign located. Corrective action; Install and maintain well identification to meet standards required in 43 CFR 3162.6

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: BU		ID: BU13673
Unique INC #: GR0828	Well Name: HD CBM 3 HARTZOG	
	Well #: 41-24BG	ID Date: 12/16/08
Operator: XTO ENERGY INC		Effective Date: 12/16/08
Case #: WYW46867	FAC ID:	Abatement Date: 01/09/09
Form: I	FAC NAME:	Corrected Date: 12/23/08
Assessment: \$0	Inspector: ROTH	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 12/16/08

Failure to maintain well identification. Specifically, No sign was found on location. Corrective action, install and maintain a well identification sign that meets 43 CFR 3162.6 for this well.

Office: BU		ID: BU13761
Unique INC #: KMS09-028I	Well Name: HOMESTEAD DR III N BRUG	
	Well #: 1CKWP-23	ID Date: 12/16/08
Operator: JM HUBER CORP		Effective Date: 01/05/09
Case #: WYW0323689A	FAC ID:	Abatement Date: 01/26/09
Form: I	FAC NAME:	Corrected Date: 01/12/09
Assessment: \$0	Inspector: ST CLAIR, KIM	Followup Date: 01/13/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 12/16/08

Failure to properly identify well. Well sign has lease # WYW0323589A, Corrective Action: Correct well sign with lease number of WYW0323689A. Gave verbal warning to Baker company man, on 12/16/2008 - Was informed on 12/22/08 this had been taken care of. On followup inspection on 01/05/09 - sign still not corrected.

Office: BU		ID: BU13760
Unique INC #: KMS09-026I	Well Name: HOMESTEAD DR III N BRUG	
	Well #: 5CKWP-23	ID Date: 12/01/08
Operator: JM HUBER CORP		Effective Date: 01/05/09
Case #: WYW0323689A	FAC ID:	Abatement Date: 01/26/09
Form: I	FAC NAME:	Corrected Date: 01/12/09
Assessment: \$0	Inspector: ST CLAIR, KIM	Followup Date: 01/13/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 12/01/08

Failure to properly identify well - No well sign. Corrective Action: Install legible well sign with correct Lease No WYW0323689A. Verbal warning give to Baker hand on 12/4/08 to correct well sign. On 12/22/08 I was told sign had been corrected. Upon followup inspection on 1/5/09 - No sign on location.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: BU		ID: BU13553
Unique INC #: KMS09-025	Well Name: BRINKERHOFF	
	Well #: 13-20MZCR	ID Date: 11/24/08
Operator: PENNACO ENERGY, INC.		Effective Date: 11/24/08
Case #: WYW168813	FAC ID:	Abatement Date: 12/16/08
Form: I	FAC NAME:	Corrected Date: 12/05/08
Assessment: \$0	Inspector: ST CLAIR, KIM	Followup Date: 12/11/08
Gravity: 3		Extend Date:
Authority Ref: Brinkerhoff POD Drilling C.O.A.s Cement of Casing		

Remarks Date: 11/24/08

Failure to comply with drilling COA's dated July 21, 2004. - Inadequate primary cementing of the produciton casing string. Corrective Action: Submit to this office by the specified date December 16, 2008, a full evaluation consisting of cement bond long, cement evaluation tool log or combination thereof. Also a detailed plan for remedial correction.

Office: BU		ID: BU14934
Unique INC #: 09MRW032	Well Name: BIG BEND II	
	Well #: E/9-34	ID Date: 07/10/09
Operator: NORTH FINN, LLC		Effective Date: 07/17/09
Case #: WYW134927	FAC ID:	Abatement Date: 08/07/09
Form: I	FAC NAME:	Corrected Date: 07/10/09
Assessment: \$5,000	Inspector: WARREN, MATTHEW	Followup Date: 08/10/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1(b)(2)		

Remarks Date: 07/10/09

This well was drilled without approval. It has been at least 10 days since this well was spudded therefore the assessment is \$5000. The corrective action is to sumbit a Notice of Intent to Abandon this well to this office by August 7, 2009. Failure to comply will result in the issuance of another Incidence of Non-Compliance and any assessments associated with that Incidence of Non-Compliance.

Office: CA		ID: CA3216
Unique INC #: CH09-122	Well Name: TEAPOT WEST	
	Well #: 1	ID Date: 09/23/09
Operator: CONTINENTAL INDUSTRIES LC		Effective Date: 09/24/09
Case #: WYW153083	FAC ID:	Abatement Date: 09/25/09
Form: I	FAC NAME:	Corrected Date: 09/25/09
Assessment: \$0	Inspector: HERNANDEZ	Followup Date: 09/25/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 09/23/09

The location of the above well is not fenced. The Multi-Point Surface Use and Operations Plan (9F) of the approved APD for the above well states..."Prior to the commencement of drilling operations, the location will be fenced sheep tight on four sides ..." Per notification of Scott Chipperfield on September 24, 2009 at 1500, this location is required to be completely fenced within 24 hours.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CA		ID: CA2815
Unique INC #: CH09-035	Well Name: FOSSIL (182)	
	Well #: 31-NE-13H	
Operator: FOSSIL ENERGY GROUP LLC		
Case #: WYW86091	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: HERNANDEZ	
Gravity: 3		
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 11/19/08

The Multi-point Surface Use Plan and Operations Plan of the approved APD, section 5A, under location and type of water supply, states "Fresh water for use in drilling operations will be obtained from the municipal water supply for (of) the community of Midwest, Wyoming". A recent surface inspection by Surface Compliance Technician Art Terry, noted that water for the above drilling well was being taken from a private stock pond on a different lease, located at NE NW Section 32 T 40N R 79W. Water for use in drilling operations must be acquired from the approved location in the APD. Please see the enclosed photographs. Art Terry notified Monte George by telephone on November 21, 2008 at 11:15 a.m. of this violation, due to the short abatement date.

Office: CA		ID: CA3025
Unique INC #: JM-MX1-09	Well Name: AMPET	
	Well #: 7, 8	
Operator: MATRIX PRODUCTION COMPANY		
Case #: WYW6477	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MESROBIAN	
Gravity: 3		
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/21/09

Failed to comply with conditions of approval from sundries to workover wells by 12/2008, and submit a notice to plug and abandon by 1/ 2009 if wells were nonproductive. You will submit notices to plug and abandon both wells, Ampet #7, and Ampet #8 by 4/27/09. Failure to provide this information will result with an incident of non-compliance with an assessment. Also your bond will increase to cover the costs to plug and reclaim both wells.

Office: CA		ID: CA2921
Unique INC #: JM-FE7-09	Well Name: FOSSIL (182)	
	Well #: 31-NE-13H	
Operator: FOSSIL ENERGY GROUP LLC		
Case #: WYW86091	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$250	Inspector: MESROBIAN	
Gravity: 3		
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 12/11/08

Failure to comply with incident of noncompliance JM-FE6-09. You were required to submit a sundry to provide a reclamation plan from unauthorized surface disturbances around well site 31NE13H. You failed to follow the approved APD. Fossil is assessed \$250 for not responding within the abatement time given. Failure to follow the Multi-Point Surface Use Plan and Operations Plan of the approved APD. The APD specifically outlined how the construction of the wellsite was approved. You have exceeded the authorized surface disturbance. All the outside surface disturbed areas, entering and exiting the drilling pad, need an evaluation concerning the amount of surface disturbance created by off road driving. Also, Fossil will submit on a sundry how they will reclaim these disturbed areas with-in a time frame in the Spring of 2009 with consent from the private landowner. You will comply with in the abatement time given.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CA		ID: CA2922
Unique INC #: JM-FE8-09	Well Name: FOSSIL (182)	ID Date: 01/13/09
	Well #: 31-NE-13H	Effective Date: 01/13/09
Operator: FOSSIL ENERGY GROUP LLC		Abatement Date: 02/13/09
Case #: WYW86091	FAC ID:	Corrected Date: 03/31/09
Form: I	FAC NAME:	Followup Date: 11/21/08
Assessment: \$0	Inspector: MESROBIAN	Extend Date: 03/31/09
Gravity: 3		
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 01/13/09

Failure to correctly fence the reserve pit . The reserve pit should be appropriately fenced to prevent access by persons, wildlife or livestock. During the drilling in active livestock areas, the reserve pit must be fenced with an enclosure fence on three sides and then fenced on the fourth side once drilling has been completed. The approved drilling permit stated the pit will be constructed with sheep tight fencing materials on three sides during the drilling phase and the fourth side closed once the drilling rig leaves. Fossil Energy Group LLC failed to construct the proper fencing materials at this well site. After cessation of drilling and completion operations, any visible product or hydrocarbons present in the reserve pit must be removed and taken to an authorized disposal site or if hydrocarbons are not removed the pit will be netted to prevent wildlife entrapment. After completion of this well, the horizontal test tanks will be removed from this well site location. The sales tank will not be located on the fill side of the well location. This preventative measure considers that the tank will not move due to soil erosion over a period of time. Fossil Energy Group LLC will also submit a sundry required from the APD on a proposed detailed diagram showing where your production facilities and piping configuration will be at this well site. You will comply with abatement time given for this incident of noncompliance.

Office: CA		ID: CA2874
Unique INC #: JM-FE6-09	Well Name: FOSSIL (182)	ID Date: 12/11/08
	Well #: 31-NE-13H	Effective Date: 12/14/08
Operator: FOSSIL ENERGY GROUP LLC		Abatement Date: 01/12/09
Case #: WYW86091	FAC ID:	Corrected Date: 03/31/09
Form: I	FAC NAME:	Followup Date: 11/21/08
Assessment: \$0	Inspector: MESROBIAN	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 12/11/08

Failure to follow the Multi-Point Surface Use Plan and Operations Plan of the approved APD. The APD specifically outlined how the construction of the wellsite was approved. You have exceeded the authorized surface disturbance. All the outside surface disturbed areas, entering and exiting the drilling pad, need an evaluation concerning the amount of surface disturbance created by off road driving. Also, Fossil will submit on a sundry how they will reclaim these disturbed areas within a time frame in the Spring of 2009 with consent from the private landowner. You will comply with the abatement time given.

Office: CA		ID: CA2816
Unique INC #: JM-FE4-10	Well Name: FOSSIL (182)	ID Date: 11/14/08
	Well #: 31-NE-13H	Effective Date: 11/14/08
Operator: FOSSIL ENERGY GROUP LLC		Abatement Date: 12/22/08
Case #: WYW86091	FAC ID:	Corrected Date: 03/31/09
Form: I	FAC NAME:	Followup Date: 03/31/09
Assessment: \$0	Inspector: MESROBIAN	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 11/14/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Failure to follow the Multi-Point Surface Use Plan and Operations Plan of the approved APD. The APD specifically outlined how the construction of the wellsite was approved. You have exceeded the authorized surface disturbance around the pad, since the pad appears to be small for current drilling operations. You have created two unauthorized roads from the wellsite. The roads will be barricaded to prevent vehicle use. You have set trailers and equipment by the road away from the well pad where traffic circumvented and created more unauthorized surface disturbance. You will not use the area of native vegetation between the unconstructed pad and trailer locations for vehicle parking or staging area. You will submit a sundry on the amount of unauthorized surface disturbance and a reclamation proposal for the whole disturbed area. Please reply with in the abatement time given.

Office: CA		ID: CA2923
Unique INC #: JM-FE9-09	Well Name: FOSSIL (182)	
	Well #: 31-NE-13H	
Operator: FOSSIL ENERGY GROUP LLC		
Case #: WYW86091	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MESROBIAN	
Gravity: 3		
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 01/13/09

For wells located on Federal land, the operator shall properly identify each well. Fossil Energy Group LLC has the wrong well number on this sign. The well sign shall include the well number, the name of the operator, the lease number and the surveyed location which includes quarter quarter, section, township, and range and county. Please comply with in the abatement time given.

Office: CA		ID: CA2873
Unique INC #: JM-FE5-09	Well Name: FOSSIL (182)	
	Well #: 31-NE-13H	
Operator: FOSSIL ENERGY GROUP LLC		
Case #: WYW86091	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$250	Inspector: MESROBIAN	
Gravity: 3		
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 12/11/08

Failure to follow the Multi-Point Surface Use Plan and Operations Plan of the approved APD. The APD specifically outlined how the construction of the wellsite was approved. You have exceeded the authorized surface disturbance around the pad, since the pad appears to be small for current drilling operations. You have contacted BLM for an extension to submit the requested sundry concerning the unauthorized additional surface disturbance beyond the well pad. However, Fossil failed from the abatement time given to barricade two unauthorized roads from the wellsite stated from Incident of NonCompliance (JM-FE4-10). The roads will be barricaded to prevent vehicle use. The third unauthorized road discussed with the company man on location was directed to move the drilling and workover rig off location. No other traffic allowed on this road. You will comply with a submitted sundry on the amount of surface disturbance done beyond the drilling pad. Fossil will present a reclamation plan and time frame with consent from the private landowner to do the project. Fossil is assessed \$250 for not barricading the two unauthorized roads beyond the drill site. Please reply with in the abatement time given.

Safety and Drilling Related Violations (INC)s Issued During FY 2009  
As of March 3, 2011

Office: CB		ID: CB20800
Unique INC #: 09-JA-060	Well Name: HACKBERRY HILLS 1 FEDERAL	ID Date: 06/06/09
	Well #: 1	Effective Date:
Operator: MEWBOURNE OIL COMPANY	FAC ID:	Abatement Date: 06/26/09
Case #: NMNM047423	FAC NAME:	Corrected Date: 07/22/09
Form: I		Followup Date: 07/22/09
Assessment: \$0	Inspector: AMOS	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3061.1.a, APD COA's		

Remarks Date: 06/06/09

Failure to comply with APD Conditions of Approval. "The minimum required fill of cement behind the 4-1/2" production casing is: Cement to surface. If cement does not circulate, contact the appropriate BLM office. Cement must come to surface due to high cave/karst requirement that two casing strings with cement cover the cave zone." Sundry Notice dated 5/19/09, indicates the TOC to be at 1150' by CBL. Submit plans to bring th cement to surface to remediate the Conditions of Approval. If any questions, contact Jim Amos or Wesley Ingram.

Office: CB		ID: CB20504
Unique INC #: 09LB002I	Well Name: ROADRUNNER FEDERAL	ID Date: 12/30/08
	Well #: 1	Effective Date: 12/30/08
Operator: MARBOB ENERGY CORPORATION	FAC ID:	Abatement Date: 01/20/09
Case #: NMLC029435B	FAC NAME:	Corrected Date: 01/02/09
Form: I		Followup Date: 01/13/09
Assessment: \$0	Inspector: BRUMLEY	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.3-2	Conditions of Approval	

Remarks Date: 12/30/08

Failure to comply with the Application for Permit to Drill (APD) conditions of approval part VII. Drilling, subsection B. Casing. "Changes to the approved APD casing and cement program require submitting a sundry and receiving approval prior to work. Failure to obtain approval prior to work will result in an Incident of Non-Compliance being issued." A DV tool was run with the intermediate 9 5/8" string without submitting a sundry for approval. As a result, cement is required to circulate to surface for the 5 1/2" production string. Should modifications be made to the approved APD casing and cement program, submit a sundry.

Office: CB		ID: CB20752
Unique INC #: 09LB005I	Well Name: JAMES RANCH UNIT	ID Date: 05/21/09
	Well #: 113H	Effective Date: 06/03/09
Operator: EOG RESOURCES, INC.	FAC ID:	Abatement Date: 06/23/09
Case #: NMNM02953C	FAC NAME:	Corrected Date: 06/15/09
Form: I		Followup Date: 06/15/09
Assessment: \$0	Inspector: BRUMLEY	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.1(a)	Conditions of Approval	

Remarks Date: 05/21/09

Failure to comply with the Application for Permit to Drill (APD) Conditions of Approval part VII. Drilling, subsection B. Casing. "Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in a potash area, or 500 pounds compressive strength, whichever is greater for all casing strings." 24 hours is the minimum wait time for cement on this job due to Potash. According to the subsequent report the operator waited 21.5 hours for cement. Operator is to attach a narrative to the returned INC describing several scenarios to indicate their understanding of the wait on cement Condition of Approval. This information will be used in future workshops regarding drilling operations.

Safety and Drilling Related Violations (INC)s Issued During FY 2009  
As of March 3, 2011

Office: CB		ID: CB20916
Unique INC #: 09LB006I	Well Name: ELECTRA FEDERAL	
	Well #: 36	ID Date: 07/16/09
Operator: COG OPERATING LLC		Effective Date: 07/28/09
Case #: NMNM0467931	FAC ID:	Abatement Date: 08/25/09
Form: I	FAC NAME:	Corrected Date: 07/23/09
Assessment: \$0	Inspector: BRUMLEY	Followup Date: 07/28/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)	Conditions of Approval	

Remarks Date: 07/16/09

Failure to comply with the Application for Permit to Drill (APD) Conditions of Approval part VII. Drilling, subsection B. Casing. "Wait on cement (WOC) time for a primary cement job will be minimum 18 hours for water basin, 24 hours in a potash area, or 500 pounds compressive strength, whichever is greater for all casing strings." 18 hours is the minimum wait time for cement on this job due to Controlled Water Basin. According to the subsequent report the operator waited 12 hours for cement. Operator is to attach a narrative to the returned INC describing several scenarios to indicate their understanding of the wait on cement Condition of Approval. This information will be used in future workshops regarding drilling operations.

Office: CB		ID: CB20922
Unique INC #: 09LB007I	Well Name: ELECTRA FEDERAL	
	Well #: 36	ID Date: 07/16/09
Operator: COG OPERATING LLC		Effective Date: 07/28/09
Case #: NMNM0467931	FAC ID:	Abatement Date: 08/25/09
Form: I	FAC NAME:	Corrected Date: 07/23/09
Assessment: \$0	Inspector: BRUMLEY	Followup Date: 07/28/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a) OO#2.III.B.1.h		

Remarks Date: 07/16/09

A subsequent report was submitted stating that the production casing was tested to 600# for 20min. As per Onshore Order #2.III.B.1.h all casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. Submit the report that shows the test pressure placed on the production string of casing.

Office: CB		ID: CB20927
Unique INC #: 09LB009I	Well Name: SKELLY UNIT	
	Well #: 606	ID Date: 07/16/09
Operator: COG OPERATING LLC		Effective Date: 07/28/09
Case #: NMNM98122	FAC ID:	Abatement Date: 08/25/09
Form: I	FAC NAME:	Corrected Date: 07/23/09
Assessment: \$0	Inspector: BRUMLEY	Followup Date: 07/28/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)	Conditions of Approval	

Remarks Date: 07/16/09

Failure to comply with the Application for Permit to Drill (APD) Conditions of Approval part VII. Drilling, subsection B. Casing. "Wait on cement (WOC) time for a primary cement job will be minimum 18 hours for water basin, 24 hours in a potash area, or 500 pounds compressive strength, whichever is greater for all casing strings." 18 hours is the minimum wait time for cement on this job due to Controlled Water Basin. According to the subsequent report the operator waited 12 hours for cement. Operator is to attach a narrative to the returned INC describing several scenarios to indicate their understanding of the wait on cement Condition of Approval. This information will be used in future workshops regarding drilling operations.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB			ID: CB20925
Unique INC #: 09LB008I	Well Name: SKELLY UNIT		
	Well #: 606	ID Date:	07/16/09
Operator: COG OPERATING LLC		Effective Date:	07/28/09
Case #: NMNM98122	FAC ID:	Abatement Date:	08/25/09
Form: I	FAC NAME:	Corrected Date:	07/31/09
Assessment: \$0	Inspector: BRUMLEY	Followup Date:	08/04/09
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.1(a) OO#2.III.B.1.h			

Remarks Date: 07/16/09

A subsequent report was submitted stating that the production casing was tested to 600# for 20min. As per Onshore Order #2.III.B.1.h all casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. Submit the report that shows the test pressure placed on the production string casing.

Office: CB			ID: CB21053
Unique INC #: 09-RC-I04	Well Name: FOLK FEDERAL		
	Well #: 7	ID Date:	08/13/09
Operator: COG OPERATING LLC		Effective Date:	08/24/09
Case #: NMNM0397623	FAC ID:	Abatement Date:	09/14/09
Form: I	FAC NAME:	Corrected Date:	08/24/09
Assessment: \$0	Inspector: CARRASCO	Followup Date:	10/01/09
Gravity: 3		Extend Date:	
Authority Ref: OO#2.III.B.1.h			

Remarks Date: 08/13/09

A subsequent report was submitted stating that the production casing was tested to 600# for 20min. As per Onshore Order #2.III.B.1.h all casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. Submit the report that shows the test pressure placed on the production string of casing.

Office: CB			ID: CB21055
Unique INC #: 09-RC-I06	Well Name: REDSKINS FEDERAL COM		
	Well #: 1	ID Date:	08/13/09
Operator: MACK ENERGY CORPORATION		Effective Date:	08/24/09
Case #: NMNM109644	FAC ID:	Abatement Date:	09/14/09
Form: I	FAC NAME:	Corrected Date:	08/26/09
Assessment: \$0	Inspector: CARRASCO	Followup Date:	
Gravity: 3		Extend Date:	
Authority Ref: OO#2.III.B.1.h			

Remarks Date: 08/13/09

A subsequent report was submitted stating that the production casing was tested to 600# for 20min. As per Onshore Order #2.III.B.1.h all casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10% in 30 minutes, corrective action shall be taken. Submit the report that shows the test pressure placed on the production string of casing.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB		ID: CB21054
Unique INC #: 09-RC-I05	Well Name: BALSAM BNL FED COM	
	Well #: 1H	ID Date: 08/13/09
Operator: YATES PETROLEUM CORPORATION		Effective Date: 08/24/09
Case #: NMNM117120	FAC ID:	Abatement Date: 09/14/09
Form: I	FAC NAME:	Corrected Date: 09/09/09
Assessment: \$0	Inspector: CARRASCO	Followup Date: 10/01/09
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.B.1.h		

Remarks Date: 08/13/09

A subsequent report was submitted stating that the surface casing was tested to 1220 psi.. Actual test should have been to 1386 psi. As per Onshore Order #2.III.B.1.h all casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. Submit the report that shows the test pressure placed on the production string of casing.

Office: CB		ID: CB21048
Unique INC #: 09DCINC20	Well Name: LUCKY WOLF 30 FED COM	
	Well #: 1H	ID Date: 07/11/09
Operator: RSC RESOURCES LIMITED		Effective Date: 08/12/09
Case #: NMNM54856	FAC ID:	Abatement Date: 09/28/09
Form: I	FAC NAME:	Corrected Date: 09/21/09
Assessment: \$0	Inspector: CARTER	Followup Date: 09/21/09
Gravity: 3		Extend Date: 09/28/09
Authority Ref: 43 CFR 3162.1(a) ; OO#2.III.B.1.h		

Remarks Date: 07/11/09

All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, BUT not to exceed 70 % of the minimum internal yield. Casing run 13.375" 48# H-40 Minimum internal yield 1730# 70 % of 1730 = 1211# Casing was only tested to 1000# per subsequent report. Submit testing report showing actual pressure--i.e. drilling log, 3rd party testing, etc.

Office: CB		ID: CB20408
Unique INC #: 09-TC-003	Well Name: SAND TANK 18 FED COM	
	Well #: 2H	ID Date: 10/01/08
Operator: EOG RESOURCES, INC.		Effective Date: 10/01/08
Case #: NMLC063621A	FAC ID:	Abatement Date: 10/01/08
Form: I	FAC NAME:	Corrected Date: 10/01/08
Assessment: \$0	Inspector: CARTWRIGHT	Followup Date: 11/05/08
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3162.1(a) / APD COA'S		

Remarks Date: 10/01/08

BOP/BOPE TESTED AT 3000 PSI. TEST BOP/BOPE TO 5000 PSI AS PER APD, COA'S AND FEDERAL REQUIREMENTS.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB ID: CB20406  
Unique INC #: 09-TC-001 Well Name: SAND TANK 18 FED COM  
Well #: 2H ID Date: 10/01/08  
Operator: EOG RESOURCES, INC. Effective Date: 10/01/08  
Case #: NMLC063621A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CARTWRIGHT Abatement Date: 10/01/08  
Gravity: 3 Corrected Date: 10/01/08  
Authority Ref: O.O.#2.III.A.2.h. / 43CFR 3162.1(a) / APD COA'S Followup Date: 11/05/08  
Remarks Date: 10/01/08 Extend Date:

REMOTE CONTROL NOT PROPERLY HOOKED UP. AIR LINE NOT HOOKED UP. PROPERLY HOOK UP REMOTE CONTROL. COMPANY MAN WAS NOTIFIED TO STOP DRILLING UNTIL REMOTE WAS HOOKED UP AND TESTED PER FEDERAL REQUIREMENTS.

Office: CB ID: CB20407  
Unique INC #: 09-TC-002 Well Name: SAND TANK 18 FED COM  
Well #: 2H ID Date: 10/01/08  
Operator: EOG RESOURCES, INC. Effective Date: 10/01/08  
Case #: NMLC063621A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CARTWRIGHT Abatement Date: 10/01/08  
Gravity: 3 Corrected Date: 10/01/08  
Authority Ref: O.O.#2.III.A.2.g. / 43CFR 3162.1(a) / APD COA'S Followup Date: 11/05/08  
Remarks Date: 10/01/08 Extend Date:

MANUAL LOCKING DEVICE ( i.e., hand wheels ) NOT INSTALLED ON RAMS. INSTALL MANUAL LOCKING DEVICE ( i.e., hand wheels ) ON RAMS.

Office: CB ID: CB20409  
Unique INC #: 09-TC-004 Well Name: SAND TANK 18 FED COM  
Well #: 2H ID Date: 10/01/08  
Operator: EOG RESOURCES, INC. Effective Date: 10/01/08  
Case #: NMLC063621A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CARTWRIGHT Abatement Date: 10/01/08  
Gravity: 3 Corrected Date: 10/01/08  
Authority Ref: 43CFR 3162.1(a) / O.O.#2.III.A.2.a.iv. Followup Date: 11/05/08  
Remarks Date: 10/01/08 Extend Date:

TWO HYDRAULICALLY CONTROLLED CHOKE VALVES ON CHOKE MANIFOLD. REMOVE ONE HYDRAULICALLY CONTROLLED CHOKE VALVE AND INSTALL MANUAL CONTROLLED CHOKE VALVE AS PER REQUIRED EQUIPMENT IN O.O.# 2.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB		ID: CB20410
Unique INC #: 09-TC-005	Well Name: SAND TANK 18 FED COM	
	Well #: 2H	ID Date: 10/01/08
Operator: EOG RESOURCES, INC.		Effective Date: 10/01/08
Case #: NMLC063621A	FAC ID:	Abatement Date: 10/01/08
Form: I	FAC NAME:	Corrected Date: 10/24/08
Assessment: \$1,500	Inspector: CARTWRIGHT	Followup Date: 11/05/08
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3162.1(a) / 43CFR 3163.1(b)(1)		

Remarks Date: 10/01/08

BLOW OUT PREVENTER (BOP) AND RELATED EQUIPMENT (BOPE) SHALL BE INSTALLED, USED, MAINTAINED, AND TESTED IN A MANNER NECESSARY TO ASSURE WELL CONTROL AND SHALL BE IN PLACE AND OPERATIONAL PRIOR TO DRILLING THE CASING SHOE UNLESS OTHERWISE APPROVED BY THE APD. AS PER INC #'s 09-TC-001, 09-TC-002, 09-TC-003 & 09-TC-004, BOP & BOPE WAS NOT USED, MAINTAINED, & TESTED AS PER ONSHORE ORDER # 2. CORRECT ABOVE REFERENCED VIOLATIONS AND PAY ASSESSMENT.

Office: CB		ID: CB21142
Unique INC #: 09-TC-036	Well Name: RDX 15	
	Well #: 6	ID Date: 09/11/09
Operator: RKI EXPLORTION AND PRODUCTION		Effective Date: 09/11/09
Case #: NMNM102036	FAC ID:	Abatement Date: 09/12/09
Form: I	FAC NAME:	Corrected Date: 09/11/09
Assessment: \$0	Inspector: CARTWRIGHT	Followup Date: 09/15/09
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.1(a) / 43CFR3162.5-1(c)		

Remarks Date: 09/11/09

AS PER APPROVED APD SURFACE USE PLAN ALL SEWAGE WASTE WILL BE REMOVED FROM LOCATION AND DISPOSED OF IN AN APPROVED SANITARY LAND FILL.

Office: CB		ID: CB20439
Unique INC #: 09CD1	Well Name: HYDRUS 10 FEDERAL	
	Well #: 5	ID Date: 10/28/08
Operator: CIMAREX ENERGY CO OF COLORADO		Effective Date: 10/28/08
Case #: NMNM074937	FAC ID:	Abatement Date: 10/29/08
Form: I	FAC NAME:	Corrected Date: 10/28/08
Assessment: \$0	Inspector: DE MONTIGNY	Followup Date: 10/29/08
Gravity: 3		Extend Date:
Authority Ref: oo#2.III.A.2.d		

Remarks Date: 10/28/08

Nitrogen precharge pressure test has not been check in 60 days on the nitrogen bottles. Have individual nitrogen bottles pressure tested.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB ID: CB20441  
Unique INC #: 09CD3 Well Name: HYDRUS 10 FEDERAL  
Well #: 5 ID Date: 10/28/08  
Operator: CIMAREX ENERGY CO OF COLORADO Effective Date: 10/28/08  
Case #: NMNM074937 FAC ID: Abatement Date: 10/29/08  
Form: I FAC NAME: Corrected Date: 10/28/08  
Assessment: \$0 Inspector: DE MONTIGNY Followup Date: 10/29/08  
Gravity: 3 Extend Date:  
Authority Ref: OO#@.III.A.2.g.

Remarks Date: 10/28/08

Closing valve not installed on closing line of annualr preventor. Install closing valve.

Office: CB ID: CB20440  
Unique INC #: 09CD2 Well Name: HYDRUS 10 FEDERAL  
Well #: 5 ID Date: 10/28/08  
Operator: CIMAREX ENERGY CO OF COLORADO Effective Date: 10/28/08  
Case #: NMNM074937 FAC ID: Abatement Date: 10/29/08  
Form: I FAC NAME: Corrected Date: 10/29/08  
Assessment: \$0 Inspector: DE MONTIGNY Followup Date: 10/29/08  
Gravity: 3 Extend Date:  
Authority Ref: OO#2.III.A.2.g.

Remarks Date: 10/28/08

Hand wheels not installed on BOPE. Install handwheels on BOP.

Office: CB ID: CB20883  
Unique INC #: 09RH30 Well Name: POLARIS B FEDERAL  
Well #: 26 ID Date: 06/27/09  
Operator: COG OPERATING LLC Effective Date: 07/13/09  
Case #: NMLC029342B FAC ID: Abatement Date: 07/31/09  
Form: I FAC NAME: Corrected Date: 07/28/09  
Assessment: \$0 Inspector: HOSKINSON Followup Date: 07/28/09  
Gravity: 3 Extend Date:  
Authority Ref: OO2.III.B.1.h

Remarks Date: 06/27/09

TESTED 5 1/2" PRODUCTION CASING TO 600 PSI. SHOULD HAVE TESTED TO 1500 PSI ( 600' = 1321.5 PSI) PER ONSHORE ORDER 2.III.B.1h:  
All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10 percent in 30 minutes, corrective action shall be taken. SEND DOCUMENTATION TO SHOW WHAT CASING WAS TESTED TO, IE: COPY OF DRILLER LOG TO WESLEY INGRAM P.E.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB		ID: CB20905
Unique INC #: 09RH50	Well Name: SKELLY UNIT	
	Well #: 611	ID Date: 06/28/09
Operator: COG OPERATING LLC		Effective Date: 07/17/09
Case #: NMLC029419A	FAC ID:	Abatement Date: 07/31/09
Form: I	FAC NAME:	Corrected Date: 07/28/09
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 07/28/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.3-1(e)		

Remarks Date: 06/28/09

Using a DV tool without Prior Approval, the Conditions of Approval (COA VII.B.) states no changes to APD can be made without a Sundry or approval prior to work. Resolution: Submit the following: Depth of DV tool, Yield of cement, and notify if the first stage of cement circulated through the DV tool

Office: CB		ID: CB20882
Unique INC #: 09RH29	Well Name: SKELLY UNIT	
	Well #: 611	ID Date: 06/19/09
Operator: COG OPERATING LLC		Effective Date: 07/13/09
Case #: NMLC029419A	FAC ID:	Abatement Date: 07/31/09
Form: I	FAC NAME:	Corrected Date: 08/05/09
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 08/05/09
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a) APD/COA VII.B.2		

Remarks Date: 06/19/09

SET 8.625" J55 32# INTERMEDIATE CASING @ 1786' SHOULD HAVE BEEN SET @ 1600' PER COA'S 43CFR3162.1 GENERAL REQUIREMENTS STATES (a) The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with thye lease terms, Onshore Orders, NTL's ; and other orders and instructions of the Authorized Officer. RESOLUTION: SUBMIT WELL LOG SEGMENT SHOWING 8 5/8" WAS SET IN THE TANSIL FORMATION.

Office: CB		ID: CB20906
Unique INC #: 09RH51	Well Name: SKELLY UNIT	
	Well #: 611	ID Date: 06/28/09
Operator: COG OPERATING LLC		Effective Date: 07/17/09
Case #: NMLC029419A	FAC ID:	Abatement Date: 07/31/09
Form: I	FAC NAME:	Corrected Date: 07/28/09
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 07/28/09
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 2.III.B.1.h		

Remarks Date: 06/28/09

Tested 5 1/2" Production Csg to 600 PSI, Should have tested to  $6890 \times .22 = 1515.8$  PSI All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10 percent in 30 minutes, corrective action shall be taken. Corrective Action: Submit testing report showing actual pressure, IE Copy of Drillers log, ETC

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB ID: CB20536  
Unique INC #: 09RH05 Well Name: EMPIRE 7 P FEDERAL  
Well #: 3 ID Date: 01/14/09  
Operator: MEWBOURNE OIL COMPANY Effective Date: 01/15/09  
Case #: NMNM101967 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HOSKINSON Abatement Date: 01/15/09  
Gravity: 3 Corrected Date: 01/14/09  
Authority Ref: 43CFR3162.1(a) Conditions of Approvaol Followup Date: 01/30/09  
Remarks Date: 01/14/09 Extend Date:  
  
OPERATOR CHANGED CASING DESIGN WITHOUT PRIOR APPROVAL. AAPD WAS APPROVED FOR 5 1/2" CASING AND OPERATOR RAN 4 1/2 " 11.6 # LT/C J-55 CASING. SEND IN SUNDRY FOR DESIGN CHANGES PRIOR TO RUNNING CASING. INC WILL BE CONSIDERED SATISFIED UPON RECEIPT.

Office: CB ID: CB20420  
Unique INC #: 09-RH-03 Well Name: LINK BKT FEDERAL COM  
Well #: 3H ID Date: 10/06/08  
Operator: YATES PETROLEUM CORPORATION Effective Date: 10/10/08  
Case #: NMNM10266 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HOSKINSON Abatement Date: 10/17/08  
Gravity: 3 Corrected Date: 10/07/08  
Authority Ref: 43CFR3162.1(A) CONDITIONS OF APPROVAL Followup Date: 10/28/08  
Remarks Date: 10/06/08 Extend Date:  
  
OPERATOR SET 8.625" 24# & 32# J55 CASING WITHOUT PRIOR APPROVAL. PER CONDITIONS OF APPROVAL ONLY 8.625" 24# J55 WAS APPROVED.

Office: CB ID: CB20419  
Unique INC #: 09-RH-02 Well Name: LINK BKT FEDERAL COM  
Well #: 3H ID Date: 10/06/08  
Operator: YATES PETROLEUM CORPORATION Effective Date: 10/10/08  
Case #: NMNM10266 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HOSKINSON Abatement Date: 10/17/08  
Gravity: 3 Corrected Date: 10/07/08  
Authority Ref: OO2.III.B.1.h Followup Date: 10/28/08  
Remarks Date: 10/06/08 Extend Date:  
  
Operator tested 8.625" 24# & 32# Intermediate Casing to 600 PSI, should have tested to 2065 PSI. All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10 percent in 30 minutes, corrective action shall be taken.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB			ID: CB20418
Unique INC #: 09-RH-01	Well Name: LINK BKT FEDERAL COM		
	Well #: 3H	ID Date:	10/06/08
Operator: YATES PETROLEUM CORPORATION		Effective Date:	10/10/08
Case #: NMNM10266	FAC ID:	Abatement Date:	10/17/08
Form: I	FAC NAME:	Corrected Date:	10/07/08
Assessment: \$0	Inspector: HOSKINSON	Followup Date:	10/28/08
Gravity: 3		Extend Date:	
Authority Ref: OO2.III.B.1.h			

Remarks Date: 10/06/08

Operator tested 13.375" 48# H-40 Surface Casing to 600 PSI, should have tested to 1000PSI. Per Onshore Order 2 ;All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10 percent in 30 minutes, corrective action shall be taken.

Office: CB			ID: CB20703
Unique INC #: 09RH26	Well Name: BASASHI FEDERAL		
	Well #: 1	ID Date:	04/22/09
Operator: MARBOB ENERGY CORPORATION		Effective Date:	05/01/09
Case #: NMNM103597	FAC ID:	Abatement Date:	05/29/09
Form: I	FAC NAME:	Corrected Date:	04/28/09
Assessment: \$0	Inspector: HOSKINSON	Followup Date:	05/08/09
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.1(a) & OO2.III.B			

Remarks Date: 04/22/09

COA stated that: Changes to the approved APD casing and cement program require submitting a sundry and receiving approval prior to work. Failure to obtain approval prior to work will result in an Incident of Non-Compliance being issued. The operator has submitted a sundry date 4/17/2009 requesting a modification to the cementing program on the production casing from a two stage to a three stage job. Operator subsequently submitted a sundry dated 4/21/2009 that states that the production casing was run and cemented on 4/13/2009 prior to the other sundry. The operator failed to comply with the Conditions of Approval with the APD. The operator did not circulate cement on the third stage as required (TOC 1600 by temperature survey). Corrective action: Operator to submit plan to bring cement to surface as it is required in this High Cave/Karst area. Operator required to run CBL to confirm bond behind entire length of production casing. ANY QUESTIONS CONTACT: WESLEY INGRAM, PETROLEUM ENGINEER 575-234-5982

Office: CB			ID: CB20704
Unique INC #: 09RH27	Well Name: BASASHI FEDERAL		
	Well #: 1	ID Date:	04/22/09
Operator: MARBOB ENERGY CORPORATION		Effective Date:	05/01/09
Case #: NMNM103597	FAC ID:	Abatement Date:	05/29/09
Form: I	FAC NAME:	Corrected Date:	04/28/09
Assessment: \$0	Inspector: HOSKINSON	Followup Date:	05/08/09
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.1(a) & OO2.III.B			

Remarks Date: 04/22/09

Operator drilled to new TD prior to submitting sundry requesting approval for the additional depth. SUBMIT SUNDRY PRIOR TO ALTERING DEPTH STATED IN APPROVED APD. ANY QUESTIONS CONTACT: WESLEY INGRAM, PETROLEUM ENGINEER 575-234-5982

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB		ID: CB20961
Unique INC #: 0907PS02I	Well Name: REDSKINS FEDERAL COM	
	Well #: 2	ID Date: 07/23/09
Operator: MACK ENERGY CORPORATION		Effective Date: 07/28/09
Case #: NMLC046119A	FAC ID:	Abatement Date: 08/28/09
Form: I	FAC NAME:	Corrected Date: 08/05/09
Assessment: \$0	Inspector: SWARTZ	Followup Date: 08/18/09
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2.III.B.1.h		

Remarks Date: 07/23/09

The Federal Form 3160-5 Subsequent Report dated by your office on 7/17/2009, comments for the date of 7/8/2009 state: "WOC 12 hours tested casing to 600# for 20 minutes, held ok." This quote raises an issue of non compliance. To meet Onshore Order #2.III.B.1.h requirements, the 5 1/2" casing needed to be tested to the cemented ported collar with 1500psig for 30 minutes with less than a 150psig decline in pressure. Submit a plan or explanation for approval to demonstrate that your operation has met or exceeded these requirements. If planned field work is necessary, notify the Carlsbad Field Office (575) 361-2822 a minimum of 4 hours in advance for a representative to witness. Reference this Incidence of Non Compliance: 0907PS02I with a brief summary of your compliance method in correspondence mailed on or before August 28, 2009.

Office: CB		ID: CB20960
Unique INC #: 0907PS01I	Well Name: REDSKINS FEDERAL COM	
	Well #: 2	ID Date: 07/23/09
Operator: MACK ENERGY CORPORATION		Effective Date: 07/27/09
Case #: NMLC046119A	FAC ID:	Abatement Date: 08/28/09
Form: I	FAC NAME:	Corrected Date: 08/04/09
Assessment: \$0	Inspector: SWARTZ	Followup Date: 08/18/09
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 07/23/09

The Federal Form 3160-5 Subsequent Report dated by your office on 7/17/2009, comments for the date of 7/8/2009 state: "WOC 12 hours tested casing to 600# for 20 minutes, held ok." This quote raises an issue of non compliance. The Conditions of Approval (page 2 of 4) in response to the sundry dated 06/22/09 from your office requesting approval for your intent to change plans has a requirement (in part) under I. DRILLING B. CASING "Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours for a water basin, . . ." Submit a plan or explanation for approval to demonstrate that your operation has met or exceeded these requirements. If planned field work is necessary, notify the Carlsbad Field Office (575) 361-2822 a minimum of 4 hours in advance for a representative to witness. Reference this Incidence of Non Compliance: 0907PS01I with a brief summary of your compliance method in correspondence mailed on or before August 28, 2009.

Office: CB		ID: CB20958
Unique INC #: 0907PS03I	Well Name: FOLK FEDERAL	
	Well #: 10	ID Date: 07/23/09
Operator: COG OPERATING LLC		Effective Date: 08/24/09
Case #: NMNM0397623	FAC ID:	Abatement Date: 08/28/09
Form: I	FAC NAME:	Corrected Date: 08/03/09
Assessment: \$0	Inspector: SWARTZ	Followup Date: 08/18/09
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 07/23/09

The Federal Form 3160-5 Subsequent Report dated by your office on 7/15/2009, comments for the date of 7/6/2009 state: "WOC 12hrs." and for the date of 07/13/09: "WOC 12 hrs. Tested csg to 600# for 20min,ok." This quote raises an issue of non compliance. The Conditions of Approval (page 8 of 17) for your Application for Permit to Drill dated 10/23/2008 from your office has a requirement (in part) under VI. DRILLING B. CASING "Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours for a water basin, . . ." Submit a plan for approval or an explanation to demonstrate that your operation has met/will meet or exceed these requirements. If field work is necessary, notify the Carlsbad Field Office (575) 361-2822 a minimum of 4 hours in advance for a representative to witness the compliance. Reference this Incidence of Non Compliance: 0907PS03I with a brief summary of your compliance method in correspondence mailed on or before August 28, 2009.

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Office: CB		ID: CB20959
Unique INC #: 0907PS04I	Well Name: FOLK FEDERAL	
	Well #: 10	ID Date: 07/23/09
Operator: COG OPERATING LLC		Effective Date: 07/28/09
Case #: NMNM0397623	FAC ID:	Abatement Date: 08/28/09
Form: I	FAC NAME:	Corrected Date: 08/03/09
Assessment: \$0	Inspector: SWARTZ	Followup Date: 08/18/09
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2.III.B.1.h		

Remarks Date: 07/23/09

The Federal Form 3160-5 Subsequent Report dated by your office on 7/15/2009, comments for the date of 7/6/2009 state: "WOC 12hrs." and for the date of 07/13/09: "WOC 12 hrs. Tested csg to 600# for 20min,ok." This quote raises an issue of non compliance. To meet Onshore Order #2.III.B.1.h requirements, the 5 ½" casing needed to be tested with 1500psig for 30 minutes with less than a 150psig decline in pressure. Submit a plan for approval or an explanation to demonstrate that your operation has met/will meet or exceed these requirements. If field work is necessary, notify the Carlsbad Field Office (575) 361-2822 a minimum of 4 hours in advance for a representative to witness the compliance. Reference this Incidence of Non Compliance: 0907PS04I with a brief summary of your compliance method in correspondence mailed on or before August 28, 2009.

Office: CB		ID: CB20702
Unique INC #: 09-DW-008A	Well Name: PLU PIERCE CANYON 28 FEDERAL	
	Well #: 1H	ID Date: 04/21/09
Operator: CHESAPEAKE OPERATING INC		Effective Date: 04/21/09
Case #: NMNM71016X	FAC ID:	Abatement Date: 04/22/09
Form: I	FAC NAME:	Corrected Date: 04/22/09
Assessment: \$5,000	Inspector: WHITLOCK	Followup Date: 04/22/09
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.1(a)/43CFR3163.1(b)(2)		

Remarks Date: 04/21/09

FAILURE TO OBTAIN PRIOR APPROVAL TO EXPAND THE DRILLING PAD CAUSING SURFACE DISTURBANCE BEYOND THE ALLOWED SURFACE DISTURBANCE AUTHORIZED IN THE APD. CHESAPEAKE WAS GIVEN NOTICE ON 4/21/09 THAT THEY HAD NOT BUILT THE LOCATION FOR THE PLU PIERCE CANYON 28 FEDERAL 1H AS APPROVED IN THE APD. THE CONDITIONS OF APPROVAL IN THE APD REQUIRED CHESAPEAKE TO ORIENT THE V-DOOR SOUTHEAST, RESTRICTED THE PAD 80' NORTH AND TO AVOID BUILDING OVER A DRAINAGE. THESE REQUIREMENTS WERE NOT COMPLIED WITH CHESAPEAKE IS BEING ASSESSED AT \$500.00 PER DAY FOR EACH DAY THAT THE VIOLATION EXISTED INCLUDING DAYS THE VIOLATION EXISTED PRIOR TO DISCOVERY, NOT TO EXCEED \$5000.00 . THE ASSESSMENT IS CAPPED AT \$5000.00 DUE TO THE FACT THAT THE UNAUTHORIZED SURFACE DISTURBANCE BEING DONE OVER 10 DAY PRIOR TO DISCOVERY. WITHIN 6 MONTH OF WELL COMPLETION THE LOCATION WILL UNDERGO INTERIM RECLAMATION (SEE ATTACHED). THIS WILL INVOLVE RECLAMATION OF ALL AREAS NOT NEEDED FOR PRODUCTION. SUBMIT A PLAN FOR INTERIM RECLAMATION. THIS PLAN SHOULD INCLUDE CLUSTERING FACILITIES TO ALLOW FOR THE MAXIMUM INTERIM RECLAMATION. AS FOR THE DRAINAGE, YOU MUST INSTALL A CULVERT IN THE ORIGINAL DRAINAGE THAT WILL ALLOW MAXIMUM FLOWS. CONSTRUCTION SHOULD PROVIDE ADEQUATE EROSION CONTROL AND THE REVEGETATION OF ALL AREAS UNDER INTERIM RECLAMATION. SEED MIXTURE #2 SHOULD BE USED FOR SEEDING. NOTE: INTERIM RECLAMATION IS TO BE DESIGNED BASED ON THE APPROVED PAD DEMINISONS.

Office: CC		ID: CC1273
Unique INC #: RG09LP011	Well Name: KELLER FEDERAL	
	Well #: 13-11 2S46W, 24-11 2S46W, 34-10 2S46W	ID Date: 11/06/08
Operator: BERRY PETROLEUM COMPANY		Effective Date: 12/12/08
Case #: COC4420	FAC ID:	Abatement Date: 12/26/08
Form: I	FAC NAME:	Corrected Date: 12/15/08
Assessment: \$0	Inspector: LPETERSON	Followup Date: 12/16/08
Gravity: 3		Extend Date:
Authority Ref: OO#2, III(B)h		

Remarks Date: 11/06/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The production casing strings for the 3 wells were not tested in accordance with Onshore Oil and Gas Order No. 2, III(B)(h), which requires a test for a minimum of 30 minutes. The casing strings were tested for 15 minutes. In the future, operator shall test the casing in accordance with the regulations. Please sign and return INC within 14 business days.

Office: DK		ID: DK6399
Unique INC #: IDH09001	Well Name:	
	Well #:	
Operator: PRIDE ENERGY COMPANY		
Case #: NDM32785	FAC ID: A	ID Date: 11/04/08
Form: I	FAC NAME: USA 32-23-21	Effective Date: 11/10/08
Assessment: \$0	Inspector: DENNIS HANNUM	Abatement Date: 12/15/08
Gravity: 3		Corrected Date: 05/29/09
Authority Ref: 43 CFR 3162.1 (a), &	43 CFR 3162.5-1	Followup Date: 06/02/09
		Extend Date:

Remarks Date: 11/04/08

Failed to comply with a written order (WODH08015) dated 9/24/2008. Must repair or replace flare ignitor and put in good working order, and maintain in good working order. The green copy is the operators copy.

Office: DK		ID: DK6401
Unique INC #: IDH09002	Well Name: BURKE	
	Well #: 19-28H	
Operator: EOG RESOURCES INC		
Case #: NDM94456	FAC ID:	ID Date: 03/16/09
Form: I	FAC NAME:	Effective Date: 03/16/09
Assessment: \$0	Inspector: DENNIS HANNUM	Abatement Date: 03/16/09
Gravity: 3		Corrected Date: 03/16/09
Authority Ref: 43 CFR 3162.3-1 (c),	APD	Followup Date: 03/16/09
		Extend Date:

Remarks Date: 03/16/09

Non-Compliance with APD Conditions of Approval, not notifying BLM NDOF 24 hours prior to Spudding well, and B.O.P.E. test, well number Burke 19-28H. Must stop drilling, trip out of the hole and notify BLM NDOF of B.O.P.E. test, and test B.O.P.E. with BLM witness. Talked to Mr. Jim Binegar about this matter 3/16/09. The green copy is the operators copy.

Office: FE		ID: FE14830
Unique INC #: 09AVJ002	Well Name: NE HOGBACK UNIT	
	Well #: 2, 21, 22, 28, 29, 31, 33, 34, 35, 36, 37, 38, 39, 40, 41, 5, 50, 51, 52, 53, 54	ID Date: 06/04/09 Effective Date: 06/04/09
Operator: PARAWON OPERATING LLC		Abatement Date: 06/10/09
Case #: MNM78403A	FAC ID: 55, 60, A	Corrected Date: 06/18/09
Form: I	FAC NAME: NE HOGBACK UNIT	Followup Date: 06/18/09
Assessment: \$0	Inspector: JAMISON	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR .5-3		

Remarks Date: 06/04/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The operator shall perform operations and maintain equipment in a safe and workmanlike manner. All precautions necessary to provide adequate protection of life and property shall be taken, when draining lines.

Office: GJ ID: GJ6579  
Unique INC #: EF09104 Well Name:  
Well #:  
Operator: PETRO MEX LLC ID Date: 01/31/09  
Case #: COC0124705A Effective Date: 07/31/09  
Form: I Abatement Date: 08/05/09  
Assessment: \$0 FAC NAME: Corrected Date: 08/14/09  
Gravity: 1 Inspector: FANCHER Followup Date: 08/14/09  
Authority Ref: 43 CFR 3162.5-3 Extend Date:  
  
Remarks Date: 01/31/09

The operator shall perform operations and maintain equipment in a safe and workmanlike manner.YOUR WELL HEAD IS LEAKING. IT REQUIRES IMMEDIATE ATTENTION TO MAKE THE AREA SAFE.

Office: GJ ID: GJ6593  
Unique INC #: EF09108 Well Name:  
Well #:  
Operator: MARALEX RESOURCES INCORPORATED ID Date: 08/11/09  
Case #: COC47655A Effective Date: 09/02/09  
Form: I FAC ID: 15-1 Abatement Date: 09/22/09  
Assessment: \$0 FAC NAME: ALBERTSON Corrected Date: 11/15/08  
Gravity: 3 Inspector: FANCHER Followup Date: 04/20/10  
Authority Ref: Onshore Order No. 7, III.E.1.c. Extend Date: 11/15/09  
  
Remarks Date: 08/11/09

The pit shall be fenced or enclosed to prevent access by livestock, wildlife, and unauthorized personnel. If necessary, the pit shall be equipped to deter entry by birds. Fences shall not be constructed on the levees. Please correct the fence and levees by the date indicated.

Office: GJ ID: GJ6541  
Unique INC #: EF09077 Well Name:  
Well #:  
Operator: ASPEN OPERATING LLC ID Date: 05/08/09  
Case #: COC61718 FAC ID: 12-2 Effective Date: 05/28/09  
Form: I FAC NAME: EVERTSON FED Abatement Date: 06/17/09  
Assessment: \$0 Inspector: FANCHER Corrected Date: 07/30/09  
Gravity: 3 Followup Date: 08/03/09  
Authority Ref: 43 CFR 3162.5 Extend Date: 08/15/09  
  
Remarks Date: 05/08/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

We noticed there are surface stains and an open barrel of oil on the 12-2 pad. You are required to remove the stained soil and the barrel of oil to an approved dump site, by the date indicated.

Office: GJ ID: GJ6563  
Unique INC #: EF09098 Well Name: SOLDIER CANYON  
Well #: 12-4 ID Date: 06/17/09  
Operator: MARALEX RESOURCES INCORPORATED Effective Date: 07/13/09  
Case #: COC9434 FAC ID: Abatement Date: 07/30/09  
Form: I FAC NAME: Corrected Date: 07/08/09  
Assessment: \$0 Inspector: FANCHER Followup Date: 07/28/09  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/17/09

The operator shall perform operations and maintain equipment in a safe and workmanlike manner. The operator shall take all precautions necessary to provide adequate protection for the health and safety of life and the protection of property. The rat and mouse holes are still open and should be closed or fenced off to protect wild life.

Office: GJ ID: GJ6434  
Unique INC #: EF08048 Well Name: FEDERAL  
Well #: 2-A ID Date: 09/10/08  
Operator: MONT ROUGE INCORPORATED Effective Date: 10/02/08  
Case #: COD057242 FAC ID: Abatement Date: 10/31/08  
Form: I FAC NAME: Corrected Date: 10/14/08  
Assessment: \$0 Inspector: FANCHER Followup Date: 10/15/08  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3161.3 & 43 CFR 3162.5 3

Remarks Date: 09/10/08

The road to the "2A" well is no longer passable and the pipe line is exposed. You are required to perform operations in a safe and workmanlike manner and repair your road by the date indicated.

Office: GR ID: GR1428  
Unique INC #: HN0911 Well Name: BIG SANDY FEDERAL  
Well #: 1-34 ID Date: 01/16/09  
Operator: GRYNBERG JACK J Effective Date: 01/16/09  
Case #: WYW147046 FAC ID: Abatement Date: 02/06/09  
Form: I FAC NAME: Corrected Date: 01/23/09  
Assessment: \$250 Inspector: NEWSHAM Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3163.1(a)(2)

Remarks Date: 01/16/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Failure to comply with INC # HN0908. 43CFR3163.1(a)(2). Identify a well with a sign as per 43CFR3162.6(a)(b) Had a phone conversation with Mr. Ken McKinney on 01/16/2009 @ 0900hrs and informed him the the INC's and assessments would be issued.

Office: GR ID: GR1419  
Unique INC #: HN0905 Well Name: BIG SANDY FEDERAL  
Well #: 1-3  
Operator: GRYNBERG JACK J  
Case #: WYW176743X  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.b.ii.  
FAC ID:  
FAC NAME:  
Inspector: NEWSHAM  
ID Date: 11/10/08  
Effective Date: 11/10/08  
Abatement Date: 11/15/08  
Corrected Date: 11/15/08  
Followup Date: 11/17/08  
Extend Date:

Remarks Date: 11/10/08

The manual choke valve on the choke manifold has a bent stem and is not operational.

Office: GR ID: GR1417  
Unique INC #: HN0903 Well Name: BIG SANDY FEDERAL  
Well #: 1-3  
Operator: GRYNBERG JACK J  
Case #: WYW176743X  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.g.  
FAC ID:  
FAC NAME:  
Inspector: NEWSHAM  
ID Date: 11/10/08  
Effective Date: 11/10/08  
Abatement Date: 11/15/08  
Corrected Date: 11/15/08  
Followup Date: 11/17/08  
Extend Date:

Remarks Date: 11/10/08

no valve installed in the closing line of the annular preventer.

Office: GR ID: GR1415  
Unique INC #: HN0901 Well Name: BIG SANDY FEDERAL  
Well #: 1-3  
Operator: GRYNBERG JACK J  
Case #: WYW176743X  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: AAPD operating standards #9  
FAC ID:  
FAC NAME:  
Inspector: NEWSHAM  
ID Date: 11/03/08  
Effective Date: 11/03/08  
Abatement Date: 11/03/08  
Corrected Date: 11/03/08  
Followup Date: 11/04/08  
Extend Date:

Remarks Date: 11/03/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Failure to call Authorized Officer prior to setting surface casing as per APD, COA's.

Office: GR ID: GR1418  
Unique INC #: HN0904 Well Name: BIG SANDY FEDERAL  
Well #: 1-3  
Operator: GRYNBERG JACK J  
Case #: WYW176743X  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.g.  
FAC ID:  
FAC NAME:  
Inspector: NEWSHAM  
ID Date: 11/10/08  
Effective Date: 11/10/08  
Abatement Date: 11/15/08  
Corrected Date: 11/15/08  
Followup Date: 11/17/08  
Extend Date:

Remarks Date: 11/10/08  
No manual locking device (hand wheels) installed on the BOP Rams.

Office: GR ID: GR1420  
Unique INC #: HN0906 Well Name: BIG SANDY FEDERAL  
Well #: 1-3  
Operator: GRYNBERG JACK J  
Case #: WYW176743X  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: Onshore Order #2.III.C.7.  
FAC ID:  
FAC NAME:  
Inspector: NEWSHAM  
ID Date: 11/10/08  
Effective Date: 11/10/08  
Abatement Date: 11/15/08  
Corrected Date: 11/15/08  
Followup Date: 11/17/08  
Extend Date:

Remarks Date: 11/10/08  
Flare system not installed.

Office: GS ID: GS6605  
Unique INC #: 090025 Well Name: GGU JOLLEY FEDERAL  
Well #: 21A-28-691(#3)  
Operator: BILL BARRETT CORPORATION  
Case #: COC52447A  
Form: I  
Assessment: \$0  
Gravity: 1  
Authority Ref: 43 CFR 3162.1 (a)  
FAC ID:  
FAC NAME:  
Inspector: FICKLIN  
ID Date: 12/02/08  
Effective Date: 12/02/08  
Abatement Date: 12/03/08  
Corrected Date: 12/02/08  
Followup Date:  
Extend Date:

Remarks Date: 12/02/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. The Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Running casing - at least twenty-four (24) hours prior to running casing strings Corrective Action: Submit to the Glenwood Springs Energy Office the casing tally and cement logs for well number 21A-28-691 (COC52447A) Required documentation submitted to Glenwood Springs Energy Office on 12/02/08

Office: GS		ID: GS6607
Unique INC #: 090027	Well Name: GGU JOLLEY FEDERAL	
	Well #: 21A-28-691(#3)	
Operator: BILL BARRETT CORPORATION		
Case #: COC52447A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 1		
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 12/02/08

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. The lessee failed to notify the Glenwood Springs Energy Office after spudding Well # 21A-28-691 (COC52447A) The Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Spud Notice - at least twenty-four (24) hours after spudding the well. Corrective Action: Submit to the Glenwood Springs Energy Office the exact time and date of completion of spudding the well. Required documentaion submitted to the Glenwood Springs Energy Office on 12/02/08.

Office: GS		ID: GS6606
Unique INC #: 090026	Well Name: GGU JOLLEY FEDERAL	
	Well #: 21A-28-691(#3)	
Operator: BILL BARRETT CORPORATION		
Case #: COC52447A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 1		
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 12/02/08

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. The Lessee failed to notify BLM Glenwood Springs Energy Office at least 24 hours prior to conducting BOPE tests. The Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Conducting BOPE tests - at least twenty-four (24) hours prior to conducting BOPE tests Corrective Action: Submit to the Glenwood Springs Energy Office the BOPE test results and corresponding charts. (21A-28-691) Required documentation submitted to Glenwood Springs Energy Office on 12/02/08

Office: GS		ID: GS6724
Unique INC #: 090118	Well Name: FEDERAL RWF	
	Well #: 34-4 (SO-4)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC58078	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 06/09/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Minimum standards and enforcement provisions for well control equipment. 3M system: -3 inch diameter choke line A flange on the choke line was missing one bolt. Corrective Action: Install bolt in flange and tighten.

Office: GS		ID: GS6734
Unique INC #: 090127	Well Name: PARACHUTE RANCH FEDERAL	
	Well #: 35-41A (35B)	ID Date: 07/28/09
Operator: NOBLE ENERGY INC		Effective Date: 07/28/09
Case #: COC64739	FAC ID:	Abatement Date: 07/29/09
Form: I	FAC NAME:	Corrected Date: 07/28/09
Assessment: \$0	Inspector: FICKLIN	Followup Date: 07/30/09
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 07/28/09

Minimum standards and enforcement provisions for well control equipment. -Fill-up line above the uppermost preventer. The fill line was not hooked up. It was lying loose by the stack. Corrective action: Install the fill line as required. Fill line was hooked up as required while I was on location.

Office: GS		ID: GS6578
Unique INC #: 080213	Well Name: FEDERAL GM	
	Well #: 441-4	ID Date: 09/29/08
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 09/29/08
Case #: COC50760	FAC ID:	Abatement Date: 10/08/08
Form: I	FAC NAME:	Corrected Date: 10/11/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O. O. #2. III. A. 2. b.		

Remarks Date: 09/29/08

Minimum standards and enforcement provisions for choke manifold equipment. All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees. The 2 " line running from the choke manifold to the gas buster was not equipped with a running tee as required. Corrective Action: Install equipment as specified. Install equipment as required prior to commencement of next well.

Office: GS		ID: GS6616
Unique INC #: 090036	Well Name: GGU JOLLEY FEDERAL	
	Well #: 21C-28-691(#3)	ID Date: 12/29/08
Operator: BILL BARRETT CORPORATION		Effective Date: 12/29/08
Case #: COC52447A	FAC ID:	Abatement Date: 12/29/08
Form: I	FAC NAME:	Corrected Date: 12/29/08
Assessment: \$0	Inspector: KING	Followup Date: 01/06/09
Gravity: 3		Extend Date:
Authority Ref: O.O. #2. III. A. 2. c. ii.		

Remarks Date: 12/29/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The 3M system shall have 2 independent power sources to close the preventers. The power to the air jammer pumps was found off during the inspection. Corrective Action: Ensure 2 independent power sources are maintained as required. The discrepancy was corrected during the inspection. (12/29/08)

Office: GS		ID: GS6608
Unique INC #: 090028	Well Name: GGU JOLLEY FEDERAL	
	Well #: 21A-28-691(#3)	
Operator: BILL BARRETT CORPORATION		
Case #: COC52447A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 1		
Authority Ref: O.O.#2. III. C.7.		

Remarks Date: 12/02/08

All flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the wellhead. The flare system was not located 100 feet from the wellhead as required. Corrective Action: Ensure the flare system is at least 100 feet from the wellhead. Discrepancy corrected on 12/2/08

Office: GS		ID: GS6614
Unique INC #: 090034	Well Name: WILLIAMS	
	Well #: GM 42-32	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC56546	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O.O.#2. III.A.2.b.		

Remarks Date: 12/29/08

All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, and shall be anchored to prevent whip and reduce vibration. The 2 choke lines (3" and 4") installed on the choke manifold was not targeted as required. Corrective Action: Install target tees in the turn on lines as required by the regulations. Received confirmation on 12/30/08 from Ray Meeks (company man) the discrepancy was corrected.

Office: GS		ID: GS6577
Unique INC #: 080212	Well Name: FEDERAL RWF	
	Well #: 333-8 (RM2-8)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC62160	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O . O. # 2. III. A. 2. b.		

Remarks Date: 09/30/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Minimum standards and enforcement provisions for choke manifold equipment. All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees. The running tee for the choke line was improperly installed. Corrective Action: Install equipment as specified. The running tee shall be installed as specified prior to commencement of the next well.

Office: GS		ID: GS6638
Unique INC #: 090058	Well Name: JOHNSON FED	
	Well #: 5-04B (5-05)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67149	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 02/03/09

3162.1 General requirements (a) The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. APD, Downhole Conditions of Approval, Item #7, requires a trip tank to be utilized beyond the surface casing shoe. At the time of the inspection, a trip tank was not being utilized as required in the COA. Corrective Action: Ensure all aspects of the regulations, APD and COA's are adhered to.

Office: GS		ID: GS6639
Unique INC #: 090059	Well Name: JOHNSON FED	
	Well #: 5-04B (5-05)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67149	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O.O. # 2. III. A. 2. a. iv.		

Remarks Date: 02/03/09

Minimum standards and enforcement provisions for well control equipment. -Kill line (2inch minimum) The kill line was not installed as required. Corrective Action: Install kill line as per Onshore Order # 2. The kill line was installed on 02/03/09 as per Cory Clausen. (Company Representative)

Office: GS		ID: GS6643
Unique INC #: 090063	Well Name: JOHNSON FED	
	Well #: 5-04B (5-05)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67149	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O. O. # 2. III. A. 2. i. vii.		

Remarks Date: 02/03/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Minimum standards and enforcement provisions for well control equipment testing. Annular preventers shall be functionally operated at least weekly. There was no indication the annular preventer was activated weekly. Corrective Action: Activate annular preventer within 24 hours or provide documentation. The annular preventer was activated on 02/03/09 as per Cory Clausen.

Office: GS		ID: GS6644
Unique INC #: 090064	Well Name: JOHNSON FED	
	Well #: 5-04B (5-05)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67149	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O. O. # 2. III. B. 1. i.		

Remarks Date: 02/03/09

Minimum standards and enforcement provisions for well control equipment testing. On all exploratory wells, and on that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Formation at the shoe shall be tested to a minimum of the mud weight equivalent anticipated to control the formation pressure to the next casing depth or at total depth of the well. This test shall be performed before drilling more than 20 feet of new hole. According to documentation in the daily driller's log and while on a 5M BOPE system, 50 feet of new hole was drilled before conducting the pressure integrity tests on the surface casing. Corrective Action: Ensure the test is performed as per the regulation.

Office: GS		ID: GS6641
Unique INC #: 090061	Well Name: JOHNSON FED	
	Well #: 5-04B (5-05)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67149	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O. O. # 2. III. A. 2. i. ix.		

Remarks Date: 02/03/09

A BOPE pit level drill shall be conducted weekly for each drilling crew. According to the daily driller's log, (IADC) the last documented BOPE pit level drill was performed on 1-24-09 and was conducted by the night drilling crew only. As of 02/03/09, there were no other drills documented. Corrective Action: Conduct a BOPE pit level drill for each drilling crew within 24 hours or next trip, as appropriate. On 02/03/09, the BOPE drills were conducted as per Cory Clausen, (Company man)

Office: GS		ID: GS6640
Unique INC #: 090060	Well Name: JOHNSON FED	
	Well #: 5-04B (5-05)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67149	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O. O. # 2. III. A. 2. b. iv.		

Remarks Date: 02/03/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Minimum standards and enforcement provisions for well control equipment. 5M system - Pressure gauge on choke manifold At the time of the inspection, there was no pressure gauge installed on the choke manifold. Corrective Action: Install the appropriate pressure gauge as required. The discrepancy was corrected on 02/03/09 as per Cory Clausen, Company man.

Office: GS		ID: GS6642
Unique INC #: 090062	Well Name: JOHNSON FED	
	Well #: 5-04B (5-05)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67149	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O. O. # 2. III. A. 2. i. xi.		

Remarks Date: 02/03/09

Minimum standards and enforcement provisions for well control equipment testing. All of the described tests and/or drills shall be recorded in the drilling log. The BOPE test conducted on 1-22-09 was not recorded in the daily driller's log. (IADC) Corrective Action: Record BOPE tests and test pressures in the drilling log. Discrepancy corrected on 02/03/09, as per Cory Clausen, (company man)

Office: GS		ID: GS6609
Unique INC #: 090029	Well Name: JOHNSON FED	
	Well #: 05-10C (5-07)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67150	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 1		
Authority Ref: O.O. #2. III. C. 7.		

Remarks Date: 12/01/08

All flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees. A targeted running tee was not installed on the 6" flare line as required. Corrective Action: Install a target in the turn of the 6" flare line as required. A target tee was constructed and installed on 12/1/08 as per Michael Blakely.

Office: GS		ID: GS6610
Unique INC #: 090030	Well Name: JOHNSON FED	
	Well #: 05-10C (5-07)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC67150	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O.O. #7. III. E. 1.b.		

Remarks Date: 12/01/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The pit shall have adequate storage capacity for safe containment. The design shall provide for a minimum of 2 feet of free-board. The cuttings pit was full to the point of over topping the embankment. Corrective Action: Ensure there is adequate storage capacity for safe containment, with a minimum of 2 feet of free-board. The cuttings pit was pumped down to comply with the required regulations as per Michael Blakely on 12/1/08.

Office: GS		ID: GS6780
Unique INC #: 100022	Well Name: JOLLY FED	ID Date: 01/04/10
	Well #: 22B-20-691(#12)	Effective Date: 01/04/10
Operator: BILL BARRETT CORPORATION		Abatement Date: 01/06/10
Case #: COC70803	FAC ID:	Corrected Date: 01/05/09
Form: I	FAC NAME:	Followup Date: 01/05/09
Assessment: \$0	Inspector: SIEBER	Extend Date:
Gravity: 3		
Authority Ref: O.O.#2.III.E.1.		

Remarks Date: 01/04/10

The blooie line discharge was not 100 feet from well bore. Corrective action: Blooie line discharge shall be reconfigured to meet minimum standards of O.O.#2.III.E.1.

Office: HO		ID: HO13034
Unique INC #: ASC-024-09	Well Name: GC FEDERAL	ID Date: 07/14/09
	Well #: 14	Effective Date:
Operator: COG OPERATING LLC		Abatement Date: 08/14/09
Case #: NMLC029405B	FAC ID:	Corrected Date: 07/23/09
Form: I	FAC NAME:	Followup Date: 08/07/09
Assessment: \$0	Inspector: CORTEZ	Extend Date:
Gravity: 3		
Authority Ref: OO&GO #2. III.B.1.h.		

Remarks Date: 07/14/09

Documents show the production csg. was tested to only 600 psi - submit proof that the production csg. was tested to at least 1545.5 psi. Failure to comply may result in monetary assessments.

Office: HO		ID: HO13033
Unique INC #: ASC-023-09	Well Name: GC FEDERAL	ID Date: 07/14/09
	Well #: 14	Effective Date:
Operator: COG OPERATING LLC		Abatement Date: 08/14/09
Case #: NMLC029405B	FAC ID:	Corrected Date: 07/23/09
Form: I	FAC NAME:	Followup Date: 08/07/09
Assessment: \$0	Inspector: CORTEZ	Extend Date:
Gravity: 3		
Authority Ref: Drilling COA.1.B.2		

Remarks Date: 07/14/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Intermediate csg. was drilled to 2122' instead of the approved 1900' - Submit copy of log segments that show casing was set in the Tansill formation instead of the Yates formation. Failure to comply may result in monetary assessments.

Office: HO ID: HO13032  
Unique INC #: ASC-022-09 Well Name: GC FEDERAL  
Well #: 14 ID Date: 07/14/09  
Effective Date:  
Operator: COG OPERATING LLC Abatement Date: 08/14/09  
Case #: NMLC029405B FAC ID: Corrected Date: 07/23/09  
Form: I FAC NAME: Followup Date: 08/07/09  
Assessment: \$0 Inspector: CORTEZ Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.3-1(e)

Remarks Date: 07/14/09

DV tool was used in the intermediate csg. without prior approval - Submit the cement program that was actually used to include the depth of the DV tool, the yield of cmt. & whwter or not cmt. circulated on the 1st stage. Failure to comply may result in monetary assessments.

Office: HO ID: HO13035  
Unique INC #: ASC-025-09 Well Name: JC FEDERAL  
Well #: 22 ID Date: 07/14/09  
Effective Date:  
Operator: COG OPERATING LLC Abatement Date: 08/14/09  
Case #: NMLC029509B FAC ID: Corrected Date: 07/23/09  
Form: I FAC NAME: Followup Date: 08/07/09  
Assessment: \$0 Inspector: CORTEZ Extend Date:  
Gravity: 3  
Authority Ref: OO&GO #2. III.B.1.h

Remarks Date: 07/14/09

Failure to test production csg. to 0.22 psi/ft or 1500 psi, which ever is greater. - submit proof that the production csg. was tested to at least 1545.5 psi. Failure to comply may result in monetary assessments.

Office: HO ID: HO12713  
Unique INC #: KAH-049-08 Well Name: CP FALBY FEDERAL A  
Well #: 07 ID Date: 08/15/08  
Effective Date:  
Operator: CHEVRON USA INCORPORATED Abatement Date: 09/22/08  
Case #: NMLC033706A FAC ID: Corrected Date: 10/08/08  
Form: I FAC NAME: Followup Date: 10/08/08  
Assessment: \$0 Inspector: HASTON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)(b)(c)

Remarks Date: 08/15/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

WELL IDENTIFICATION SIGN DOES NOT CONTAIN ALL REQUIRED INFORMATION. -- ADD FEDERAL LEASE SERIAL NUMBER "LC033706A" TO WELL IDENTIFICATION SIGN.

Office: HO ID: HO12854  
Unique INC #: KAH-017-09 Well Name: MCA UNIT  
Well #: 414 ID Date: 01/05/09  
Operator: CONOCOPHILLIPS COMPANY Effective Date: 01/12/09  
Case #: NMNM70987A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HASTON Abatement Date: 02/12/09  
Gravity: 3 Corrected Date: 01/29/09  
Authority Ref: 43 CFR 3162.6(a)(b)(c) Followup Date: 01/29/09  
Remarks Date: 01/05/09 Extend Date:

WELL IDENTIFICATION SIGN HAS WRONG FEDERAL LEASE NUMBER "LC058396". -- CORRECT LEASE NUMBER ON WELL SIGN TO REFLECT CORRECT FEDERAL LEASE NUMBER "LC057210".

Office: JA ID: JA2180  
Unique INC #: BRB-09-024 Well Name: USA 35-9  
Well #: 2 ID Date: 05/11/09  
Operator: VENTURE OIL & GAS INC Effective Date: 05/11/09  
Case #: MSBLMA11554B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BOTELER Abatement Date: 06/01/09  
Gravity: 1 Corrected Date: 05/20/09  
Authority Ref: 43 cfr 3162.3-2 (a) Followup Date: 05/20/09  
Remarks Date: 05/11/09 Extend Date:

Submit approval to set C.I.B.P. at 9690'.

Office: JA ID: JA2182  
Unique INC #: BRB-09-026 Well Name: USA 35-9  
Well #: 2 ID Date: 05/11/09  
Operator: VENTURE OIL & GAS INC Effective Date: 05/11/09  
Case #: MSBLMA11554B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BOTELER Abatement Date: 06/01/09  
Gravity: 1 Corrected Date: 05/20/09  
Authority Ref: 43 cfr 3162.3 -2 (a) Followup Date: 05/20/09  
Remarks Date: 05/11/09 Extend Date:

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Was interval 9110' -9122' perforated? if so, when? Submit required information.

Office: JA	Well Name: USA 35-9	ID: JA2185
Unique INC #: BRB-09-029	Well #: 2	ID Date: 06/02/09
Operator: VENTURE OIL & GAS INC	FAC ID:	Effective Date: 06/02/09
Case #: MSBLMA11554B	FAC NAME:	Abatement Date: 07/01/09
Form: I	Inspector: BOTELER	Corrected Date: 07/01/09
Assessment: \$5,000		Followup Date: 07/01/09
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1 (b) (1)		

Remarks Date: 06/02/09

WELL DRILLED WITHOUT NOTIFICATION AND APPROVAL OF SPUD. Based on your failure to install blowout preventer or other equivalent well control equipment, as required by the approved drilling plan, and Onshore Order #2 a \$500. per day assessment will be levied not to exceed \$5,000. This instance of noncompliance is a violation of such a serious nature as to warrant the imposition of immediate assessments upon discovery. BASED ON THE ABOVE, AN ASSESSMENT IN THE AMOUNT OF \$5,000 HAS BEEN LEVIED FOR THIS VIOLATION.

Office: JA	Well Name: USA 35-9	ID: JA2186
Unique INC #: BRB-09-030	Well #: 2	ID Date: 06/02/09
Operator: VENTURE OIL & GAS INC	FAC ID:	Effective Date: 06/02/09
Case #: MSBLMA11554B	FAC NAME:	Abatement Date: 07/01/09
Form: I	Inspector: BOTELER	Corrected Date: 07/01/09
Assessment: \$5,000		Followup Date: 07/01/09
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1 (b) (2)		

Remarks Date: 06/02/09

WELL DRILLED WITHOUT NOTIFICATION AND APPROVAL OF SPUD. Based on the "Conditions of Approval" for Permit to Drill the USA 35-9#2 and 43 CFR 3162.3 -4 and to the specifications of Onshore Order No. 2 (G) you were required to notify BLM 48 hours prior to initiation of dirt work and well spud. No notification was received prior to commencement of this work. For failure to notify a \$500. per day assessment will be levied for this this violation. This instance of noncompliance is a violation of such a serious nature as to warrant the imposition of immediate assessments upon discovery. BASED ON THE ABOVE, AN ASSESSMENT IN THE AMOUNT OF \$5,000 HAS BEEN LEVIED FOR THIS VIOLATION.

Office: JA	Well Name: USA 35-9	ID: JA2172
Unique INC #: BRB-09-016	Well #: 2	ID Date: 05/11/09
Operator: VENTURE OIL & GAS INC	FAC ID:	Effective Date: 05/11/09
Case #: MSBLMA11554B	FAC NAME:	Abatement Date: 06/01/09
Form: I	Inspector: BOTELER	Corrected Date: 05/20/09
Assessment: \$0		Followup Date: 05/20/09
Gravity: 1		Extend Date:
Authority Ref: ORDER #2 2 (H) (iii)		

Remarks Date: 05/11/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

USA 35-9 #2 B.O.P.E. was not tested to approved pressure of 1000 P.S.I., it was tested only to 850 P.S.I.. Explain you reason for this unapproved change.

Office: JA		ID: JA2176
Unique INC #: BRB-09-020	Well Name: USA 35-9	
	Well #: 2	
Operator: VENTURE OIL & GAS INC		
Case #: MSBLMA11554B	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BOTELER	
Gravity: 1		
Authority Ref: ORDER #2 A(g) (ix)		

Remarks Date: 05/11/09

Records and reports indicate that no B.O.P.E pit level drills were conducted on a weekly basis for each drilling crew. Explan why these drills were not conducted.

Office: JA		ID: JA2181
Unique INC #: BRB-09-025	Well Name: USA 35-9	
	Well #: 2	
Operator: VENTURE OIL & GAS INC		
Case #: MSBLMA11554B	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BOTELER	
Gravity: 1		
Authority Ref: 43 cfr 3162.1 & 3162.3-2(a)		

Remarks Date: 05/11/09

Perforation interval of 9722-9730 was not approved on your Application for Permit to Drill, your approved production interval was at 8200' to 8220'. Please submit corrected Sundry Notice.

Office: JA		ID: JA2177
Unique INC #: BRB-09-021	Well Name: USA 35-9	
	Well #: 2	
Operator: VENTURE OIL & GAS INC		
Case #: MSBLMA11554B	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BOTELER	
Gravity: 1		
Authority Ref: 43 CFR 3162.5-2(d)		

Remarks Date: 05/11/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Records and reports indicate that the USDW was not protected on this well. Surface casing was set at 1084', USDW was identified and picked at 1800'. Submit your plans to correct this deficiency.

Office: JA	Well Name: USA 35-9	ID: JA2178
Unique INC #: BRB-09-022	Well #: 2	ID Date: 05/11/09
Operator: VENTURE OIL & GAS INC	FAC ID:	Effective Date: 05/11/09
Case #: MSBLMA11554B	FAC NAME:	Abatement Date: 06/01/09
Form: I	Inspector: BOTELER	Corrected Date: 05/20/09
Assessment: \$0		Followup Date: 05/20/09
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.3-4(c)		

Remarks Date: 05/11/09

Records and reports indicate that drilling was complete on 2/20/2009, completion on the well commenced on 3/25/2009. You are required to submit a request for temporary abandonment for this time period.

Office: JA	Well Name: USA 35-9	ID: JA2175
Unique INC #: BRB-09-019	Well #: 2	ID Date: 05/11/09
Operator: VENTURE OIL & GAS INC	FAC ID:	Effective Date: 05/11/09
Case #: MSBLMA11554B	FAC NAME:	Abatement Date: 06/01/09
Form: I	Inspector: BOTELER	Corrected Date: 05/21/09
Assessment: \$0		Followup Date: 05/21/09
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.3-1(E),3162.3-2(A)		

Remarks Date: 05/11/09

Approved Permit To Drill USA 35-9 #2 indicated that well bore was to be a straight hole , your reports and records indicate the well bore was converted to a directional hole. Submit for approval your request to convert this well to a directional hole.

Office: JA	Well Name: USA 35-9	ID: JA2179
Unique INC #: BRB-09-023	Well #: 2	ID Date: 05/11/09
Operator: VENTURE OIL & GAS INC	FAC ID:	Effective Date: 05/11/09
Case #: MSBLMA11554B	FAC NAME:	Abatement Date: 06/01/09
Form: I	Inspector: BOTELER	Corrected Date: 05/21/09
Assessment: \$0		Followup Date: 05/21/09
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1		

Remarks Date: 05/11/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Failure to protect personnel and the environment occurred by your failure to conduct B.O.P.E. test at well completion stage. Explain why this occurred.

Office: JA		ID: JA2174
Unique INC #: BRB-09-018	Well Name: USA 35-9	
	Well #: 2	
Operator: VENTURE OIL & GAS INC		
Case #: MSBLMA11554B	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BOTELER	
Gravity: 1		
Authority Ref: ORDER #2 A (g) (viii), 43cfr 3165.54		

Remarks Date: 05/11/09

B.O.P.E. function test not performed as required in Onshore Order #2. Pipe and blind rams should be activated on all pipe trips. The annular preventer should be activated weekly. Explain why function test were not performed.

Office: JA		ID: JA2187
Unique INC #: BRB-09-031	Well Name: USA 35-9	
	Well #: 2	
Operator: VENTURE OIL & GAS INC		
Case #: MSBLMA11554B	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$5,000	Inspector: BOTELER	
Gravity: 1		
Authority Ref: 43 CFR 3163.1(b) (3)		

Remarks Date: 06/02/09

WELL DRILLED WITHOUT NOTIFICATION AND APPROVAL OF SPUD. Based on the "Conditions of Approval" for Permit to Drill the USA 35-9#2 you were required to submit a "Subsequent Report of Abandonment" (Form 3160-5) if well was found to be dry. The original approved Total Depth was reached at 8210' on 2/12/2009. The lower Wash/Fed was tested and deemed non-commercial. No approval to plug and abandon this section of the hole was submitted to BLM. therefore, a \$500.00 per day assessment will be levied not to exceed \$5000.00. This instance of noncompliance is a violation of such a serious nature as to warrant the imposition of immediate assessments upon discovery. BASED ON THE ABOVE, AN ASSESSMENT IN THE AMOUNT OF \$5,000 HAS BEEN LEVIED FOR THIS VIOLATION.

Office: JA		ID: JA2173
Unique INC #: BRB-09-017	Well Name: USA 35-9	
	Well #: 2	
Operator: VENTURE OIL & GAS INC		
Case #: MSBLMA11554B	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BOTELER	
Gravity: 1		
Authority Ref: ORDER #2 B(f), #2 B (e)		

Remarks Date: 05/11/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Centralizers were not used on bottom three joints of surface casing. Explain why they were not used.

Office: JA	Well Name: US GOVERNMENT	ID: JA2193
Unique INC #: CB-09-106D	Well #: 2	ID Date: 07/07/09
Operator: FERRY LAKE OIL CO LLC	FAC ID:	Effective Date: 07/08/09
Case #: LABLM33649	FAC NAME:	Abatement Date: 07/10/09
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 07/10/09
Assessment: \$0		Followup Date: 07/16/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 07/07/09

THE FENCING AROUND THE PUMPING UNIT IS OPEN IN THE REAR AND WOULD ALLOW ACCESS TO THE MOVING PARTS OF THE UNIT BY UNAUTHORIZED PERSONNEL SUCH AS CHILDREN THAT LIVE IN THE ADJACENT HOUSES. OPERATOR IS ORDERED TO SECURE THIS FENCING TO PREVENT ANY UNAUTHORIZED ENTRY TO THE AREA AROUND THE UNIT.

Office: JA	Well Name:	ID: JA2195
Unique INC #: CB-09-106F	Well #:	ID Date: 07/07/09
Operator: FERRY LAKE OIL CO LLC	FAC ID: A	Effective Date: 07/08/09
Case #: LABLM33649	FAC NAME: US GOVT. TB	Abatement Date: 08/07/09
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 07/15/09
Assessment: \$0		Followup Date: 07/16/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 07/07/09

TANK #11729 SHOWS SIGNS OF LEAKAGE AROUND THE BOTTOM OF THE VESSEL. THIS LEAKAGE COULD RESULT IN THE LOSS OF PRODUCT AND ROYALTY REVENUE ALONG WITH POSSIBLE DAMAGE TO THE ENVIRONMENT IF THE TANK WERE TO RUPTURE. THEREFORE, OPERATOR IS ORDERED TO REPLACE THIS VESSEL WITHIN 30 DAYS OF THIS ORDER.

Office: JA	Well Name: US GOVERNMENT	ID: JA2192
Unique INC #: CB-09-106C	Well #: 2	ID Date: 07/07/09
Operator: FERRY LAKE OIL CO LLC	FAC ID:	Effective Date: 07/08/09
Case #: LABLM33649	FAC NAME:	Abatement Date: 07/10/09
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 07/10/09
Assessment: \$0		Followup Date: 07/16/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 07/07/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

THE BELT GUARD ON THE PUMPING UNIT ON THE #2 WELL IS NOT INSTALLED ON THE UNIT. BELT GUARD IS LYING ON THE GROUND ADJACENT TO UNIT. OPERATOR IS ORDERED TO INSTALL THE BELT GUARD ON THE UNIT AND IN THE FUTURE TO NOT OPERATE THE UNIT UNLESS THE GUARD IS IN PLACE. OPERATOR HAS UNTIL 7-10-2009 TO CORRECT THIS VIOLATION.

Office: JA ID: JA2194  
Unique INC #: CB-09-106E Well Name: US GOVERNMENT  
Well #: 2 ID Date: 07/07/09  
Operator: FERRY LAKE OIL CO LLC Effective Date: 07/08/09  
Case #: LABLM33649 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CHARLES R BOYD  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 07/10/09  
Corrected Date: 07/10/09  
Followup Date: 07/16/09  
Extend Date:

Remarks Date: 07/07/09

OPERATOR IS ORDERED TO REPLACE THE ELECTRICAL COVER ON THE ELECTRIC MOTOR TO SECURE THE WIRING FROM THE WEATHER AND PREVENT POSSIBLE HUMAN CONTACT.

Office: JA ID: JA2199  
Unique INC #: CB-09-107D Well Name: USA  
Well #: 4 ID Date: 07/07/09  
Operator: PETROL INDUSTRIES INCORPORATED Effective Date: 07/10/09  
Case #: LABLM40630 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CHARLES R BOYD  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 07/17/09  
Corrected Date: 07/17/09  
Followup Date: 07/17/09  
Extend Date:

Remarks Date: 07/07/09

THERE IS NO FENCE AROUND THE PUMPING UNIT TO PREVENT ACCESS TO THE MOVING PARTS OF THE UNIT BY UNAUTHORIZED PERSONNEL SUCH AS CHILDREN THAT LIVE IN THE AREA. OPERATOR IS ORDERED TO CONSTRUCT AND INSTALL THIS FENCING TO PREVENT ANY UNAUTHORIZED ENTRY TO THE AREA AROUND THE UNIT.

Office: JA ID: JA2202  
Unique INC #: CB-09-107G Well Name: USA  
Well #: 4 ID Date: 07/07/09  
Operator: PETROL INDUSTRIES INCORPORATED Effective Date: 07/10/09  
Case #: LABLM40630 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CHARLES R BOYD  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 07/17/09  
Corrected Date: 07/17/09  
Followup Date: 07/17/09  
Extend Date:

Remarks Date: 07/07/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

OPERATOR IS ORDERED TO PLACE AN ELECTRICAL COVER ON THE ELECTRIC MOTOR TO SECURE THE WIRING FROM THE WEATHER AND PREVENT POSSIBLE HUMAN CONTACT.

Office: JA	Well Name: USA	ID: JA2198
Unique INC #: CB-09-107C	Well #: 4	ID Date: 07/07/09
Operator: PETROL INDUSTRIES INCORPORATED	FAC ID: A	Effective Date: 07/10/09
Case #: LABLM40630	FAC NAME: USA CTB	Abatement Date: 07/17/09
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 07/14/09
Assessment: \$0		Followup Date: 07/14/09
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 07/07/09

OPERATOR IS ORDERED TO INSTALL A BELT GUARD ON THE UNIT AND IN THE FUTURE TO NOT OPERATE THE UNIT UNLESS THIS GUARD IS IN PLACE. OPERATOR HAS UNTIL 7-17-2009 TO CORRECT THIS VIOLATION.

Office: JA	Well Name: USA	ID: JA2149
Unique INC #: CB-09-D05A	Well #: 59	ID Date: 02/12/09
Operator: XTO ENERGY INCORPORATED	FAC ID:	Effective Date: 02/12/09
Case #: LABLMA54490	FAC NAME:	Abatement Date: 02/13/09
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 02/12/09
Assessment: \$0		Followup Date: 02/12/09
Gravity: 1		Extend Date:
Authority Ref: Onshore O&G Order #2 Part III.A.2.a		

Remarks Date: 02/12/09

IBOP VALVE WAS FOUND IN THE CLOSED POSITION ON THE RIG FLOOR. THE DART IN THIS VALVE MUST ALWAYS BE LOCKED IN THE OPEN POSITION DURING DRILLING OPERATIONS. OPERATOR IS ORDERED TO CORRECT THIS DESCREPANCY IMMEDIATELY UPON RECEIPT OF THIS INCIDENCE OF NONCOMPLIANCE OR NO LATER THAN 24 HOURS.

Office: JA	Well Name: USA	ID: JA2151
Unique INC #: CB-09-D05C	Well #: 59	ID Date: 02/16/09
Operator: XTO ENERGY INCORPORATED	FAC ID:	Effective Date: 02/16/09
Case #: LABLMA54490	FAC NAME:	Abatement Date: 02/17/09
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 02/17/09
Assessment: \$0		Followup Date: 02/17/09
Gravity: 1		Extend Date:
Authority Ref: Onshore O&G Order #2 Part III.A.2.a.vi		

Remarks Date: 02/16/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

DURING TESTING PROCEDURES, THE ANNULAR PREVENTER FAILED TO TEST TO THE REQUIRED PRESSURES. IT APPEARS THAT THE RUBBER ELEMENT IS NOT SEALING ON THE DRILL PIPE AS REQUIRED. OPERATOR IS ORDERED TO MAKE REPAIRS TO THIS EQUIPMENT AND RE-TEST SAME PROMPTLY. THIS WORK MUST BE PERFORMED PRIOR TO THE DRILLING OUT OF THE CASING SHOE.

Office: JA ID: JA2150  
Unique INC #: CB-09-D05B Well Name: USA  
Well #: 59 ID Date: 02/12/09  
Effective Date: 02/12/09  
Operator: XTO ENERGY INCORPORATED Abatement Date: 02/13/09  
Case #: LABLMA54490 FAC ID: Corrected Date: 02/13/09  
Form: I FAC NAME: Followup Date: 02/13/09  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 1  
Authority Ref: Onshore O&G Order #2 Part III.A.1  
Remarks Date: 02/12/09

TWO GAUGES (ACCUMULATOR PRESSURE AND ANNULAR PRESSURE ON THE REMOTE CONTROL ON THE RIG FLOOR ARE NOT FUNCTIONING. AS PER ONSHORE ORDER #2, ALL BOPE SHALL BE FULLY FUNCTIONAL AND IN GOOD CONDITION TO PROVIDE FULL WELL CONTROL. OPERATOR IS ORDERED TO REPAIR THIS DESCREPANCY WITHIN 24 HOURS OF THE RECEIPT OF THIS NOTICE.

Office: JA ID: JA2228  
Unique INC #: CB-09-D01B Well Name: BLM 013045  
Well #: 1 ID Date: 10/14/08  
Effective Date: 10/14/08  
Operator: BRIGHAM OIL & GAS LP Abatement Date: 10/15/08  
Case #: LABLMFW13045 FAC ID: Corrected Date: 10/15/08  
Form: I FAC NAME: Followup Date: 10/15/08  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore O&G Order #2 Part III.A.2.i.viii  
Remarks Date: 10/14/08

Functioning the pipe and blind rams after the bit trip on 10-10-2008 was not documented and recorded in the IADC Book as required by the Order. Operator is ordered to document and record future function test, if there are any.

Office: JA ID: JA2226  
Unique INC #: CB-09-D01A Well Name: BLM 013045  
Well #: 1 ID Date: 10/14/08  
Effective Date: 10/14/08  
Operator: BRIGHAM OIL & GAS LP Abatement Date: 10/15/08  
Case #: LABLMFW13045 FAC ID: Corrected Date: 10/15/08  
Form: I FAC NAME: Followup Date: 10/15/08  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore O&G Order #2 Part III.A.2.i.vii  
Remarks Date: 10/14/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Annular preventer was not functioned during the week of 10-3-2008 thru 10-10-2008 as required. Operator is ordered to function the annular preventer ASAP and document same in the IADC Book.

Office: KM	Well Name: CLIFTON FEDERAL	ID: KM1055
Unique INC #: 09INC002	Well #: 34-5	ID Date: 11/19/08
Operator: WEXPRO COMPANY	FAC ID:	Effective Date: 11/19/08
Case #: WYW48198	FAC NAME:	Abatement Date: 11/19/08
Form: I	Inspector: RICHARD A FLEMING	Corrected Date: 11/19/08
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O.2.B.		

Remarks Date: 11/19/08

See attached letter dated 1/23/2008 to Dee Findlay, Wexpro Company, specifically requiring surface casing to be set at a depth of least 2480.

Office: LA	Well Name: FED	ID: LA532
Unique INC #: 258	Well #: 11-1	ID Date: 09/16/08
Operator: RYDER OIL & GAS LLC	FAC ID: A	Effective Date: 10/03/08
Case #: WYW173082	FAC NAME: #11-1	Abatement Date: 10/19/08
Form: I	Inspector: MCLEOD	Corrected Date: 10/30/08
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 09/16/08

10/03/2008 - YOU MUST REPLACE THE BELT GUARDS ON YOUR PUMPING UNIT. HEALTH & SAFETY PRECAUTIONS.

Office: LA	Well Name: FED	ID: LA535
Unique INC #: 261	Well #: 11-1	ID Date: 10/30/08
Operator: RYDER OIL & GAS LLC	FAC ID: A	Effective Date: 11/03/08
Case #: WYW173082	FAC NAME: #11-1	Abatement Date: 11/24/08
Form: I	Inspector: MCLEOD	Corrected Date: 12/09/08
Assessment: \$250		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 10/30/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Health & Safety Precautions.Belt Guards Must Be Installed

Office: ME ID: ME2650  
Unique INC #: 09EM02MEFO Well Name: PICEANCE CREEK UNIT  
Well #: 296-17A8  
Operator: EXXON MOBIL CORP  
Case #: COC47666A  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: Onshore Order #2 III.A.2.g.  
FAC ID:  
FAC NAME:  
Inspector: MILLER  
ID Date: 11/06/08  
Effective Date: 11/06/08  
Abatement Date: 11/12/08  
Corrected Date: 11/12/08  
Followup Date: 11/18/08  
Extend Date:

Remarks Date: 11/06/08

Inspection of well # 296-17A8 on 11/6/08 found that hand wheels were not installed on the BOP as required by regulation. Install hand wheels according to O.O.#2 III.A.2.g. by 11/12/08.

Office: ME ID: ME2714  
Unique INC #: 09EM30MEFO Well Name: FEDERAL RGU  
Well #: 14-14-298  
Operator: WILLIAMS PRODUCTION RMT CO.  
Case #: COC66586  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.2.a.iv.  
FAC ID:  
FAC NAME:  
Inspector: MILLER  
ID Date: 01/02/09  
Effective Date: 01/02/09  
Abatement Date: 01/02/09  
Corrected Date: 01/02/09  
Followup Date: 01/02/09  
Extend Date:

Remarks Date: 01/02/09

Inspection on 1/2/09 found the kill line not attached to the BOP stack. All BOP associated equipment must be installed and functional. Install kill line in accordance with Onshore Order #2.III.A.2.a.iv. immediately. Mike Alcorn was notified at the time of inspection.

Office: ML ID: iML3414  
Unique INC #: CD09-I-001 Well Name: DUNMORE  
Well #: 1-9-1S-34E  
Operator: URSA MAJOR (CROW OG) LLC  
Case #: 142002525145  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1(a)  
FAC ID:  
FAC NAME:  
Inspector: DEVAULT  
ID Date: 11/12/08  
Effective Date: 11/13/08  
Abatement Date: 12/15/08  
Corrected Date: 04/21/09  
Followup Date: 04/21/09  
Extend Date: 04/30/09

Remarks Date: 11/12/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The APD for this well stated to set 190 feet of surface casing. Ursa Major only set about 120 feet of casing. 43 CFR 3162.5-1(a) states in part: The operator shall comply with the pertinent orders of the authorized officer and other standards and procedures set forth in the applicable laws, regulations, lease terms and conditions, and the approved drilling plan or subsequent operations plan. Corrective Action: Ursa Major, LLC shall cement the production casing to the surface.

Office: MR		ID: MR1441
Unique INC #: EF09093	Well Name: FEDERAL	
	Well #: 24-2 WDW	
Operator: S G INTERESTS I LTD		
Case #: COC67120X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FANCHER	
Gravity: 3		
Authority Ref: 43 CFR 3164.1 & Onshore Order No. 1		

Remarks Date: 06/13/09

A copy of the APD was not located during our inspection.

Office: MR		ID: MR1442
Unique INC #: EF09094	Well Name: FEDERAL	
	Well #: 24-2 WDW	
Operator: S G INTERESTS I LTD		
Case #: COC67120X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FANCHER	
Gravity: 1		
Authority Ref: Onshore Order No. 2, III.B.		

Remarks Date: 06/13/09

The proposed casing and cementing programs shall be conducted as approved. Operator did not follow the approved plan for cement as noted in APD. Your are required to: submit Sundry Notice explaining your change of cementing and forward a copy of the bond log to this office by the date indicated.

Office: NE		ID: NE4087
Unique INC #: AA09028	Well Name: FEDERAL	
	Well #: 31-8	
Operator: ASHER ASSOCIATES INCORPORATED		
Case #: WYW34660A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: AMBROSE	
Gravity: 3		
Authority Ref: OO#6.III.D.2.d.		

Remarks Date: 02/04/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The danger sign on the side of the entrance road to the well is faded. The old sign needs to be replaced with a new one.

Office: NE ID: NE4065  
Unique INC #: 09MH001HS Well Name:  
Well #:  
Operator: OILFIELD SALVAGE ID Date: 12/11/08  
Case #: 8910086690 Effective Date: 12/12/08  
Form: I FAC ID: OLDS Abatement Date: 12/15/08  
Assessment: \$0 FAC NAME: OLDS EXTENSION Corrected Date: 12/13/08  
Gravity: 1 Inspector: HUNTLEY Followup Date: 12/15/08  
Authority Ref: 43 CFR 3162.5-3 Extend Date:  
  
Remarks Date: 12/11/08

The operator shall perform operations and maintain equipment in a safe and workmanlike manner. The operator shall take all precautions necessary to provide adequate protection for the health and safety of life and the protection of property. Currently there is insulation material and sheets of metal from the heater treater strewn across the facility location and even across the highway. This is a health and safety hazard to the public driving on the highway and to cattle in the vicinity of the facility that could possibly ingest the insulation. Remove and properly dispose of all insulation and metal from wherever it has travelled to away from the heater treater. Remove or secure the insulating materials that remain on the heater treater to prevent it from coming off in the future.

Office: NE ID: NE3873  
Unique INC #: JDH08003DI Well Name: MILLER  
Well #: 6-7 ID Date: 11/20/07  
Operator: BEARTOOTH OIL & GAS COMPANY Effective Date: 11/20/07  
Case #: WYW173481 FAC ID: Abatement Date: 12/20/07  
Form: I FAC NAME: Corrected Date: 12/20/08  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 01/28/08  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6  
  
Remarks Date: 11/20/07

43 CFR 3162.6 (b) Lease number must be added to the well sign. The correct lease number is WYW173481

Office: NE ID: NE4115  
Unique INC #: JDH09028PI Well Name:  
Well #: ID Date: 03/10/09  
Operator: WILDFIRE PARTNERS, INC. Effective Date: 03/12/09  
Case #: WYW66387 FAC ID: WILD Abatement Date: 04/15/09  
Form: I FAC NAME: WILDFIRE Corrected Date: 05/11/09  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 05/22/09  
Gravity: 3 Extend Date: 05/15/09  
Authority Ref: Onshore Order No. 6 III.D.2.b.  
  
Remarks Date: 03/10/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

All stairs/ladders leading to the top of storage tanks shall be chained and/or marked to restrict entry. Corrective Action: Chain or mark stair(s)/ladder(s) or post sign, as necessary.

Office: NE ID: NE4116  
Unique INC #: JDH09029PI Well Name:  
Well #: ID Date: 03/10/09  
Operator: WILDFIRE PARTNERS, INC. Effective Date: 03/12/09  
Case #: WYW66387 FAC ID: WILD Abatement Date: 04/15/09  
Form: I FAC NAME: WILDFIRE Corrected Date: 05/11/09  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 05/22/09  
Gravity: 3 Extend Date: 05/15/09  
Authority Ref: Onshore Order No. 6 III.D.2.c.&d.

Remarks Date: 03/10/09

A danger sign shall be posted on or within 50 feet of the storage tank(s) to alert the public of the potential H2S danger. Corrective Action: Post or move sign(s), as necessary. The sign(s) shall be painted in high visibility red, black, and white. The sign(s) shall read: DANGER POISON GAS HYDROGEN SULFIDE

Office: NE ID: NE4117  
Unique INC #: JDH09030PI Well Name:  
Well #: ID Date: 03/10/09  
Operator: WILDFIRE PARTNERS, INC. Effective Date: 03/12/09  
Case #: WYW66387 FAC ID: WILD Abatement Date: 04/15/09  
Form: I FAC NAME: WILDFIRE Corrected Date: 05/11/09  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 05/22/09  
Gravity: 3 Extend Date: 05/15/09  
Authority Ref: Onshore Order No. 6 III.D.2.e.

Remarks Date: 03/10/09

At least 1 permanent wind direction indicator shall be installed so that wind direction can be easily determined at or approaching the storage tank(s). Corrective Action: Install, repair, or replace wind direction indicator, as necessary.

Office: PD ID: PD2597  
Unique INC #: 8DF012109 Well Name: MESA  
Well #: 14B2-20 ID Date: 01/21/09  
Operator: QUESTAR EXPL & PROD CO PNDL Effective Date: 01/21/09  
Case #: WYW015315 FAC ID: Abatement Date: 01/22/09  
Form: I FAC NAME: Corrected Date: 01/22/09  
Assessment: \$0 Inspector: FALLON Followup Date: 01/23/09  
Gravity: 3 Extend Date:  
Authority Ref: O.O. #2 III.A.2.i.xi.

Remarks Date: 01/21/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Found: During a detailed drilling inspection of Unit Rig # 323, it was discovered no BOP pit level drills were recorded within the last week. Corrective Action: A BOP pit level drill shall be conducted weekly for each drilling crew and recorded in the driller's log. Company man informed the BLM the requested corrective actions were implemented 01/22/09.

Office: PD		ID: PD2595
Unique INC #: 6DF012109	Well Name: MESA	
	Well #: 14B2-20	
Operator: QUESTAR EXPL & PROD CO PNLD		
Case #: WYW015315	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FALLON	
Gravity: 3		
Authority Ref: O.O. #2 III.A.2.h.i.vii.		

Remarks Date: 01/21/09

Found: During a detailed rig inspection of Unit rig # 323, it was found the annular preventer was not activated during the last week. Corrective action: Annular preventers shall be functionally operated at least weekly. Note: Company man activated annular preventer as requested on 01/22/09. Violation abated.

Office: PD		ID: PD2892
Unique INC #: 36DF081209	Well Name: RIVERSIDE	
	Well #: 16B2-3D	
Operator: ULTRA RESOURCES INC		
Case #: WYW06270	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FALLON	
Gravity: 3		
Authority Ref: O.O. #2 III.A.2.i.xi.		

Remarks Date: 08/12/09

Found: During a detailed drilling inspection of Precision Rig # 110, it was discovered the driller's log did not indicate the required BOP tests and associated pressures. Corrective Action: All of the BOP tests shall be recorded in the driller's log and include equipment tested, duration of test, and low and high pressures of the test.

Office: PD		ID: PD2893
Unique INC #: 37DF081209	Well Name: RIVERSIDE	
	Well #: 16B2-3D	
Operator: ULTRA RESOURCES INC		
Case #: WYW06270	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FALLON	
Gravity: 3		
Authority Ref: O.O. #2 III.A.2.i.xi		

Remarks Date: 08/12/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Found: During a detailed rig inspection of Precision Rig # 110 , it was found the pipe rams were not documented in the driller's log book as being activated during the last trip. Corrective action: Pipe rams shall be activated each trip, however, this function need not be preformed more than once a day. All the above tests and/or drills shall be recorded in the driller's log book.

Office: RO		ID: RO8131
Unique INC #: 01-002-09I	Well Name: EPPERS B FEDERAL	
	Well #: 2	ID Date: 11/14/08
Operator: MCKAY OIL CORPORATION		Effective Date: 11/14/08
Case #: NMNM36190	FAC ID:	Abatement Date: 12/03/08
Form: I	FAC NAME:	Corrected Date: 12/02/08
Assessment: \$0	Inspector: GARNAND	Followup Date: 12/02/08
Gravity: 3		Extend Date:
Authority Ref: 3162.6(b)		

Remarks Date: 11/14/08

Operator has been issued a noncompliance for well sign identification. Operator shows the location as Eppers B Federal #2, but the actual location is Mckay Federal #4. Operator must correct the well sign to properly identify location according the 43 CFR 3162.6 (b). Sign INC and return to Roswell Field Office when you have complied.

Office: RW		ID: RW4456
Unique INC #: ML09001I	Well Name: BLUE GAP	
	Well #: 8-5	ID Date: 10/08/08
Operator: QUESTAR EXPL AND PRODUCTION CO		Effective Date: 10/08/08
Case #: WYW161382	FAC ID:	Abatement Date: 10/19/08
Form: I	FAC NAME:	Corrected Date: 10/13/08
Assessment: \$0	Inspector: LYON	Followup Date: 10/14/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 10/08/08

Violation: Reserve pit not fenced Resolution: Install fence in accordance with COA's and Onshore Order #7. Attachment # 1-1

Office: RW		ID: RW4537
Unique INC #: ML09009I	Well Name: RED DESERT	
	Well #: 9-8-20-95	ID Date: 02/23/09
Operator: DEVON ENERGY PRODUCTION CO LP		Effective Date: 02/23/09
Case #: WYW17125	FAC ID:	Abatement Date: 02/23/09
Form: I	FAC NAME:	Corrected Date: 02/23/09
Assessment: \$0	Inspector: LYON	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: OO #2. III. A. 2.b		

Remarks Date: 02/23/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Violation: Kill line was not connected outside of sub. Abatement: Spoke to Company Representative Jackie Williams. Violation was corrected promptly before inspector left location. 02/23/09 1130hrs.

Office: RW ID: RW4469  
Unique INC #: JRM08005 Well Name: ESPY UNIT  
Well #: 12 ID Date: 11/05/08  
Operator: NADEL & GUSSMAN ROCKIES LLC Effective Date: 11/05/08  
Case #: WYW109504X FAC ID: Abatement Date: 12/03/08  
Form: I FAC NAME: Corrected Date: 12/03/08  
Assessment: \$0 Inspector: MENDOZA Followup Date: 12/03/08  
Gravity: 3 Extend Date:  
Authority Ref: OO#2 III.A.i.xi.

Remarks Date: 11/05/08

No I.A.D.C. record of B.O.P.E. drills

Office: RW ID: RW4470  
Unique INC #: JRM08006 Well Name: ESPY UNIT  
Well #: 12 ID Date: 11/05/08  
Operator: NADEL & GUSSMAN ROCKIES LLC Effective Date: 11/05/08  
Case #: WYW109504X FAC ID: Abatement Date: 12/03/08  
Form: I FAC NAME: Corrected Date: 12/03/08  
Assessment: \$0 Inspector: MENDOZA Followup Date: 12/03/08  
Gravity: 3 Extend Date:  
Authority Ref: OO #6 III.A.1.c.iv.

Remarks Date: 11/05/08

H2S caution / danger sign(s) and flag(s) not posted/visible.

Office: RW ID: RW4472  
Unique INC #: JRM08003 Well Name: ESPY UNIT  
Well #: 12 ID Date: 11/05/08  
Operator: NADEL & GUSSMAN ROCKIES LLC Effective Date: 11/12/08  
Case #: WYW109504X FAC ID: Abatement Date: 12/03/08  
Form: I FAC NAME: Corrected Date: 12/03/08  
Assessment: \$0 Inspector: MENDOZA Followup Date: 12/03/08  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-1

Remarks Date: 11/05/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Equipement off of pad location.

Office: RW ID: RW4471  
Unique INC #: JRM08004 Well Name: ESPY UNIT  
Well #: 12 ID Date: 11/05/08  
Operator: NADEL & GUSSMAN ROCKIES LLC Effective Date: 11/05/08  
Case #: WYW109504X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MENDOZA  
Gravity: 3  
Authority Ref: OO# 2 III.C.1.  
Abatement Date: 12/03/08  
Corrected Date: 12/03/08  
Followup Date: 12/03/08  
Extend Date:

Remarks Date: 11/05/08

No I.A.D.C. record of slow pump speed.

Office: RW ID: RW4455  
Unique INC #: JRM08002 Well Name: CELSIUS FEDERAL  
Well #: 34-14D ID Date: 10/07/08  
Operator: ANADARKO E & P COMPANY LP Effective Date: 10/07/08  
Case #: WYW125460 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MENDOZA  
Gravity: 3  
Authority Ref: OO #1 IV  
Abatement Date: 10/09/08  
Corrected Date: 10/09/08  
Followup Date: 10/09/08  
Extend Date:

Remarks Date: 10/07/08

Violation: At time of inspection a copy of approved A.P.D. was not on location for review. Remedy: Acquire approved A.P.D. and make available on site.

Office: RW ID: RW4445  
Unique INC #: JRM08001 Well Name: WAMSUTTER FEDERAL  
Well #: 42-26 ID Date: 09/12/08  
Operator: ENCANA OIL & GAS (USA) INC Effective Date: 09/12/08  
Case #: WYW125919 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MENDOZA  
Gravity: 3  
Authority Ref: OO #7 III.E.1.c.  
Abatement Date: 09/19/08  
Corrected Date: 09/22/09  
Followup Date: 09/22/09  
Extend Date:

Remarks Date: 09/12/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Pit fence does not meet design requirements of OO#7 III.E.1.c. Remedial action: Bring fence into compliance with OO#7.

Office: RW ID: RW4561  
Unique INC #: MJR09012 Well Name: RED DESERT FEDERAL  
Well #: 43-20D  
Operator: ANADARKO E & P COMPANY LP ID Date: 03/16/09  
Case #: WYW134358 FAC ID: Effective Date: 03/17/09  
Form: I FAC NAME: Abatement Date: 04/03/09  
Assessment: \$0 Inspector: MENDOZA Corrected Date: 03/27/09  
Gravity: 3 Followup Date: 03/27/09  
Authority Ref: 43 CFR 3162.5-1 (a) (b) (c) Extend Date:  
  
Remarks Date: 03/16/09  
Violation: Trash from location needs picked up. Remedy: Pick up wind blown and other trash.

Office: RW ID: RW4462  
Unique INC #: AW08-30 Well Name: CELSIUS FEDERAL  
Well #: 13-14D  
Operator: ANADARKO E & P COMPANY LP ID Date: 10/17/08  
Case #: WYW125460 FAC ID: Effective Date: 10/17/08  
Form: I FAC NAME: Abatement Date: 10/31/08  
Assessment: \$0 Inspector: WHITE Corrected Date: 10/17/08  
Gravity: 3 Followup Date: 10/22/08  
Authority Ref: COA Extend Date:  
  
Remarks Date: 10/17/08  
Flare pit not fenced.

Office: RW ID: RW4461  
Unique INC #: AW08-29 Well Name: CELSIUS FEDERAL  
Well #: 13-14D  
Operator: ANADARKO E & P COMPANY LP ID Date: 10/17/08  
Case #: WYW125460 FAC ID: Effective Date: 10/17/08  
Form: I FAC NAME: Abatement Date: 10/31/08  
Assessment: \$0 Inspector: WHITE Corrected Date: 10/17/08  
Gravity: 3 Followup Date: 10/22/08  
Authority Ref: 43CFR3162.5-1(a)(b)(c) Extend Date:  
  
Remarks Date: 10/17/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Trash on and around location.

Office: RW ID: RW4718  
Unique INC #: AW09-11 Well Name: FLAT TOP  
Well #: 2-8  
Operator: DEVON ENERGY PRODUCTION CO LP  
Case #: WYW134709 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE  
Gravity: 3  
Authority Ref: COA  
Remarks Date: 07/27/09  
Culvert ends not marked.

Office: RW ID: RW4509  
Unique INC #: AW09-02 Well Name: WAMSUTTER  
Well #: 10-12-20-94  
Operator: DEVON ENERGY PRODUCTION CO LP  
Case #: WYW143006 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE  
Gravity: 3  
Authority Ref: C.O.A.  
Remarks Date: 01/22/09  
Trash

Office: RW ID: RW4464  
Unique INC #: AW08-32 Well Name: BROWN COW AR FEDERAL 1491  
Well #: 3-14  
Operator: ANADARKO E & P COMPANY LP  
Case #: WYW156218X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE  
Gravity: 1  
Authority Ref: OO#2 III. C. 7.  
Remarks Date: 10/24/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Flare line discharge less than 100' from well head. Flare line discharge positioned into prevailing wind. Flare system has no method of ignition.

Office: TU ID: iTU24524  
Unique INC #: 09TC008 Well Name: WHITE  
Well #: 1-24H  
Operator: QUESTAR EXPL + PROD COMPANY  
Case #: 142020514037 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: COLON  
Gravity: 1  
Authority Ref: O.O. 2.III.A.2.e.

Remarks Date: 09/22/09

Air to accumulator air pumps shut off. Power for the accumulator closing unit air pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Pumps were activated and operational before I left location.

Office: TU ID: iTU24525  
Unique INC #: 09TC009 Well Name: WHITE  
Well #: 1-24H  
Operator: QUESTAR EXPL + PROD COMPANY  
Case #: 142020514037 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: COLON  
Gravity: 3  
Authority Ref: O.O.2.III.C.1.

Remarks Date: 09/22/09

Mud pump slow speed not being logged. Record slow pump speed on daily drilling report after mudding up.

Office: TU ID: iTU24523  
Unique INC #: 09TC007 Well Name: WHITE  
Well #: 1-24H  
Operator: QUESTAR EXPL + PROD COMPANY  
Case #: 142020514037 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: COLON  
Gravity: 3  
Authority Ref: O.O. 2.III.A.2.h.

Remarks Date: 09/22/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Accumulator remote not readily accessible to Driller. Relocation of remote scheduled with welder.

Office: TU ID: iTU24526  
Unique INC #: 09TC010 Well Name: WHITE  
Well #: 1-24H  
Operator: QUESTAR EXPL + PROD COMPANY  
Case #: 142020514037 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: COLON  
Gravity: 3  
Authority Ref: O.O.2.III.A.1  
Remarks Date: 09/22/09  
Flare line not capable of containing fluids. A closed loop choke manifold system must be capable of containing fluids. A mud box will be installed with the flare line.

Office: TU ID: iTU24522  
Unique INC #: 09TC006 Well Name: WHITE  
Well #: 1-24H  
Operator: QUESTAR EXPL + PROD COMPANY  
Case #: 142020514037 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: COLON  
Gravity: 3  
Authority Ref: O.O. 2.III.A.2.g.  
Remarks Date: 09/22/09  
No valve installed in the closing line of the annular preventer. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. Valve ordered 9-22-09

Office: TU ID: iTU24376  
Unique INC #: 09-JRF-062 Well Name: MARTIN UNIT C  
Well #: 12  
Operator: BP AMERICA PRODUCTION COMPANY  
Case #: 67163 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FRANKS  
Gravity: 3  
Authority Ref: OSO #2 III.A.2.a  
Remarks Date: 04/24/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

All well control devices shall be installed at the surface which are capable of the complete closure of the wellbore. You are to have an inside BOP installed in the top drive of the rig assembly which meets or exceeds approved BOP pressure ratings found in the drilling permit. Please install the certified tested inside bop before drilling out the casing shoe.

Office: TU		ID: iTU24375
Unique INC #: 09-JRF-061	Well Name: MARTIN UNIT C	
	Well #: 12	ID Date: 04/24/09
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 04/24/09
Case #: 67163	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 04/25/09
Assessment: \$0	Inspector: FRANKS	Followup Date: 04/25/09
Gravity: 3		Extend Date:
Authority Ref: OSO #2 III.A.2.a		

Remarks Date: 04/24/09

All well control devices shall be installed at the surface which are capable of the complete closure of the wellbore. You are to have available a back up drill string safety valve which is certified tested to approved pressure on the rig floor at all times.

Office: TU		ID: iTU24420
Unique INC #: LB2009-07	Well Name:	
	Well #:	ID Date: 05/28/09
Operator: H C M		Effective Date: 06/10/09
Case #: OKNM78965	FAC ID: A	Abatement Date: 06/30/09
Form: I	FAC NAME: CURTIS PLUMMER 1	Corrected Date: 07/01/09
Assessment: \$0	Inspector: LBARTEL	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 06/09/09

In the middle of the enclosed tank battery there is a hole the size of an oil drum with several inches of water and weeds growing around it. You cannot see this hole until directly over it, I almost fell into it and could possibly cause harm or death to small wildlife. Fill hole with appropriate material and cut weeds. Refer to attached CFR and pictures. 7.1.0 Received a letter from Dorena Temple of Jon F. Cobb Oil and Gas Exp. informing the BLM that HCM is no longer in business and the new owner/operator is Chaco Energy Co.

Office: TU		ID: iTU24530
Unique INC #: 09-DJM-114	Well Name: WHITE	
	Well #: 1-24H	ID Date: 09/23/09
Operator: QUESTAR EXPL + PROD COMPANY		Effective Date: 09/24/09
Case #: 142020514037	FAC ID:	Abatement Date: 09/25/09
Form: I	FAC NAME:	Corrected Date: 09/25/09
Assessment: \$0	Inspector: MCMILLAN	Followup Date: 09/25/09
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2.III.2.a.iv		

Remarks Date: 09/23/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Blowout preventer and related equipment shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be inplace and operational prior to drilling the surface casing shoe. You are ordered to install a pressure gauge on the choke manifold.

Office: TU ID: iTU24243  
Unique INC #: 09BDS04 Well Name: LIZZIE GOAT  
Well #: 6  
Operator: COOK OIL COMPANY  
Case #: 66472 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SELF  
Gravity: 3  
Authority Ref: OO 2 III.A.2.g.

Remarks Date: 12/30/08

There was no valve on the closing side of annular.

Office: TU ID: TU25036  
Unique INC #: 09BDS03 Well Name: CAT CREEK, D L SANDERS, ELOISE  
Well #: 1, 1-19, 1-24  
Operator: CHESAPEAKE OPERATING INC  
Case #: OKNM74631 FAC ID: A  
Form: I FAC NAME: CAT CREEK, ELOISE 1-24, SANDERS  
Assessment: \$0 Inspector: SELF  
Gravity: 3  
Authority Ref: Onshore Order 6 III.D.2.e.

Remarks Date: 11/18/08

Gary Carter pumper with Chesapeake said all wind socks have been replaced. 1-9-09

Office: VE ID: iVE11747  
Unique INC #: AW09033 Well Name: DWR  
Well #: 3-28C6  
Operator: EL PASO E&P COMPANY LP  
Case #: 14204621323 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ALAN WALKER  
Gravity: 1  
Authority Ref: 43cfr3162.1.(a) apd drilling program #3

Remarks Date: 09/15/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Failure to install 1500 PSI annular and choke manifold from 600' to 3001'.

Office: VE ID: iVE11748  
Unique INC #: AW09034 Well Name: DWR  
Well #: 3-28C6 ID Date: 09/15/09  
Operator: EL PASO E&P COMPANY LP Effective Date: 09/15/09  
Case #: 14204621323 FAC ID: Abatement Date: 09/16/09  
Form: I FAC NAME: Corrected Date: 09/15/09  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: 43cfr3162.1.(a) Onshore Order #2 part III.3.B.1.f.  
Remarks Date: 09/15/09  
Surface casing shall have centralizers on the bottom 3 jts. of casing with 1 centralizer per joint, starting with the shoe joint.

Office: VE ID: iVE11745  
Unique INC #: AW09031 Well Name: DWR  
Well #: 3-28C6 ID Date: 09/15/09  
Operator: EL PASO E&P COMPANY LP Effective Date: 09/15/09  
Case #: 14204621323 FAC ID: Abatement Date: 09/16/09  
Form: I FAC NAME: Corrected Date: 09/15/09  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43cfr3162.1.(a) apd drilling program #3  
Remarks Date: 09/15/09  
Failure to obtain approval to change setting depth of surface casing from 3001' to 2050'. Obtain approval from the Authorized Officer.

Office: VE ID: iVE11744  
Unique INC #: AW09030 Well Name: DWR  
Well #: 3-28C6 ID Date: 09/15/09  
Operator: EL PASO E&P COMPANY LP Effective Date: 09/15/09  
Case #: 14204621323 FAC ID: Abatement Date: 09/17/09  
Form: I FAC NAME: Corrected Date: 09/15/09  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43cfr3162.1(a) APD drilling program #3  
Remarks Date: 09/15/09

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

Failure to obtain approval to change setting depth of conductor pipe from 600' to 40'. Obtain approval from the Authorized Officer.

Office: VE ID: iVE11746  
Unique INC #: AW09032 Well Name: DWR  
Well #: 3-28C6 ID Date: 09/15/09  
Operator: EL PASO E&P COMPANY LP Effective Date: 09/15/09  
Case #: 14204621323 FAC ID: Abatement Date: 09/16/09  
Form: I FAC NAME: Corrected Date: 09/15/09  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43cfr3162.1.(a) apd drilling program #3  
Remarks Date: 09/15/09  
Failure to give 24 hr. notice of running and cementing of surface casing. Give 24 hr. notice in the furture.

Office: VE ID: VE11603  
Unique INC #: GR07007 Well Name: FEDERAL  
Well #: 16-8-9-16 ID Date: 02/06/07  
Operator: NEWFIELD EXPLORATION COMPANY Effective Date: 02/15/07  
Case #: UTU64379 FAC ID: Abatement Date: 03/15/07  
Form: I FAC NAME: Corrected Date: 12/01/08  
Assessment: \$0 Inspector: GLADE RICH Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(a)(b)  
Remarks Date: 02/06/07  
Wells located on Federal and Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well, other than those permanently abandoned. The well sign has the wrong lease number. Please put the right lease number on the well sign.

Office: VE ID: VE11602  
Unique INC #: SBA07001 Well Name: BONANZA  
Well #: 1023-7H ID Date: 02/07/07  
Operator: WESTPORT OIL & GAS COMPANY LP Effective Date: 02/15/07  
Case #: UTU38420 FAC ID: Abatement Date: 03/15/07  
Form: I FAC NAME: Corrected Date: 11/17/08  
Assessment: \$0 Inspector: STONEY ANDERTON Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 cfr 3162.6(a)  
Remarks Date: 02/07/07

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

The 1023-7H is missing its well sign. Every well within a Federal or Indian lease or supervised agreement shall have a well identification sign.

Office: WO ID: WO2438  
Unique INC #: 010-08-019 Well Name: SILVERTIP ID Date: 09/18/08  
Well #: 26-28F Effective Date: 09/22/08  
Operator: FIDELITY EXPL & PROD CO Abatement Date: 10/14/08  
Case #: WYW109689A FAC ID: Corrected Date: 10/14/08  
Form: I FAC NAME: Followup Date: 10/15/08  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O. #2 III. A. 2. c. ii

Remarks Date: 09/18/08

During my drilling inspection I found the air to be turned off on the accumulator air pump. See (photo). The air has to be turned on at all times during drilling operation. Fidelity will require the drilling contractor to keep the air supply turned on during drilling operations. We will inspect this during our next drilling inspection.

Office: WO ID: WO2438  
Unique INC #: 010-08-017 Well Name: SILVERTIP ID Date: 09/18/08  
Well #: 26-28F Effective Date: 09/22/08  
Operator: FIDELITY EXPL & PROD CO Abatement Date: 10/14/08  
Case #: WYW109689A FAC ID: Corrected Date: 10/14/08  
Form: I FAC NAME: Followup Date: 10/14/08  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O. #2 III. A. 2. g.

Remarks Date: 09/18/08

There were no hand wheels on the hydraulic rams for the BOP stack during my drilling inspection. See (photo). Fidelity will require drilling contractor to have hand wheels on stack during next Drilling Inspection. No set date.

Office: WO ID: WO2437  
Unique INC #: 010-08-018 Well Name: SILVERTIP ID Date: 09/18/08  
Well #: 26-28F Effective Date: 09/22/08  
Operator: FIDELITY EXPL & PROD CO Abatement Date: 10/14/08  
Case #: WYW109689A FAC ID: Corrected Date: 10/14/08  
Form: I FAC NAME: Followup Date: 10/14/08  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O. #2 III.A. 2. g.

Remarks Date: 09/18/08

Safety and Drilling Related Violations (INCs) Issued During FY 2009  
As of March 3, 2011

I found no valve in the closing line of the annular preventer during my drilling inspection. See (photo). Fidelity will require drilling contractor to have a valve in the closing line from date received of this notice. We will check this during next inspection.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU ID: BU12877  
Unique INC #: MB-08-4 Well Name: KINGSBURY IV FEDERAL  
Well #: 34-15 ID Date: 02/26/08  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 02/26/08  
Case #: WYW0266642 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: COA's  
Abatement Date: 02/27/08  
Corrected Date: 02/27/08  
Followup Date: 03/03/08  
Extend Date:

Remarks Date: 02/26/08

The divertor rubber on the drilling rig is leaking excessively. You must install and maintain a rubber in the divertor head that does not leak and is capable of diverting fluid from the well bore.

Office: BU ID: BU12897  
Unique INC #: MB-08-6 Well Name: KINGSBURY IV FEDERAL  
Well #: 23-23 ID Date: 03/04/08  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 03/04/08  
Case #: WYW0266642 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: Wildlife COA' #2a  
Abatement Date: 03/05/08  
Corrected Date: 03/04/08  
Followup Date: 09/23/08  
Extend Date:

Remarks Date: 03/04/08

You have failed to comply with Wildlife COA' #2a. You can finish setting the liner, but you must cease activity at that point. Any additional work in the future must be authorized by BLM.

Office: BU ID: BU13342  
Unique INC #: MB-08-14 Well Name: DIAMOND RUN FEDERAL (MOORE)  
Well #: 32-13 ID Date: 09/03/08  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 09/03/08  
Case #: WYW100384 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: COA's  
Abatement Date: 09/04/08  
Corrected Date: 09/04/08  
Followup Date:  
Extend Date:

Remarks Date: 09/03/08

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Well head diverter is leaking excessively. You must install equipment that is capable of controlling the well.

Office: BU		ID: BU12600
Unique INC #: MB-08-3	Well Name: PETROX BIG GEORGE BG	
	Well #: 5-6SR	ID Date: 10/22/07
Operator: PETROX RESOURCES INC		Effective Date: 10/22/07
Case #: WYW145623	FAC ID:	Abatement Date: 10/23/07
Form: I	FAC NAME:	Corrected Date: 10/30/07
Assessment: \$0	Inspector: BLAKESLEY	Followup Date: 10/30/07
Gravity: 3		Extend Date:
Authority Ref: COA's		

Remarks Date: 10/22/07

Divertor line is only 19'. You must have a 30' diverter line made of non-flammable material, and it must be staked down in at least two places.

Office: BU		ID: BU12598
Unique INC #: MB-08-1	Well Name: PETROX BIG GEORGE BG	
	Well #: 5-6SR	ID Date: 10/22/07
Operator: PETROX RESOURCES INC		Effective Date: 10/22/07
Case #: WYW145623	FAC ID:	Abatement Date: 10/24/07
Form: I	FAC NAME:	Corrected Date: 10/30/07
Assessment: \$0	Inspector: BLAKESLEY	Followup Date: 10/30/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 10/22/07

There is no well sign on location. You must have a well sign which includes: well name, legal description, lease number, operator name, county and state.

Office: BU		ID: BU12599
Unique INC #: MB-08-2	Well Name: PETROX BIG GEORGE BG	
	Well #: 5-6SR	ID Date: 10/22/07
Operator: PETROX RESOURCES INC		Effective Date: 10/22/07
Case #: WYW145623	FAC ID:	Abatement Date: 10/23/07
Form: I	FAC NAME:	Corrected Date: 10/30/07
Assessment: \$0	Inspector: BLAKESLEY	Followup Date: 10/30/07
Gravity: 3		Extend Date:
Authority Ref: COA's		

Remarks Date: 10/22/07

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Mud pits are only 17' from the well bore. You must have 30' from the well bore to the nearest edge of the pits.

Office: BU		ID: BU12896
Unique INC #: MB-08-5	Well Name: KINGSBURY IV KU	
	Well #: 23-21	ID Date: 03/04/08
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 03/04/08
Case #: WYW150648X	FAC ID:	Abatement Date: 03/05/08
Form: I	FAC NAME:	Corrected Date: 03/04/08
Assessment: \$0	Inspector: BLAKESLEY	Followup Date: 09/23/08
Gravity: 3		Extend Date:
Authority Ref: Wildlife COA's #2 a		

Remarks Date: 03/04/08

You have failed to comply with Wildlife COA' #2 a. You must cease activity on this location. Any additional work in the future must be authorized by BLM.

Office: BU		ID: BU13189
Unique INC #: MB-08-13	Well Name: DIAMOND RUN MOORE	
	Well #: 23-13	ID Date: 06/23/08
Operator: BLACK DIAMOND ENERGY INC		Effective Date: 06/24/08
Case #: WYW62643	FAC ID:	Abatement Date: 06/25/08
Form: I	FAC NAME:	Corrected Date: 06/26/08
Assessment: \$0	Inspector: BLAKESLEY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 06/23/08

There is no well sign on this location. You must install a well sign with the following: Well name, operator name, lease number, and well location including 1/4 1/4's.

Office: BU		ID: BU12574
Unique INC #: AB-08-01	Well Name: JEPSON DRAW II STREETER BG	
	Well #: 43-05	ID Date: 10/15/07
Operator: WINDSOR ENERGY GROUP LLC		Effective Date: 09/07/07
Case #: WYW0312471A	FAC ID:	Abatement Date: 10/22/07
Form: I	FAC NAME:	Corrected Date: 10/22/07
Assessment: \$5,000	Inspector: BREWER	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43CFR3163.1(b)(2)		

Remarks Date: 10/15/07

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Well was drilled outside of approved parameters without prior approval of BLM authority, specifically, well location was moved 20' & drilled without contact of any BLM personnel by Windsor's representatives. Sundry was submitted, then received in Buffalo Wy. BLM office on 9-26-07. By regulation, Windsor Energy Group LLC is assessed \$500 per day from spud date of 8-31-07 to 9-26-07 (date of sundry) with a maximum of 10 days totaling \$5000. 3163.1(b) (2) For drilling without approval or for causing surface disturbance on Federal or Indian surface preliminary to drilling without approval, \$500 per day for each day that the violation existed, including days the violation existed prior to discovery, not to exceed \$5,000;

Office: BU		ID: BU12695
Unique INC #: KRB08004A	Well Name: HD CBM 2 HARTZOG	ID Date: 01/07/08
	Well #: 43-5BG	Effective Date: 01/07/08
Operator: XTO ENERGY INC	FAC ID:	Abatement Date: 01/22/08
Case #: WYW50394	FAC NAME:	Corrected Date: 01/22/08
Form: I	Inspector: BRUS	Followup Date:
Assessment: \$5,000		Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.3-1(a)		

Remarks Date: 01/07/08

Well location was moved at the pre-approval onsite to the disturbed pad, approximately 75 feet to the SW of the proposed location. Well was approved at the new location. Operator drilled well at the originally staked location, not at the approved location. Well spud reported 12-17-07. Spud date 12-19-07. Drilling completed 01-05-08. By regulation, XTO is assessed \$500 per day from spud date for a maximum of 10 days totaling \$5000. 43 CFR 3163.1(b) states "Certain instances of noncompliance are violations of such a serious nature as to warrant the imposition of immediate assessment upon discovery. (2) For drilling without approval or for causing surface disturbance... prior to approval, \$500 per day for each day that the violation existed, includng days the violation existed prior to discovery, not to exceed \$5000." The operator will be required to submit a Sundry Notice with a new APD cover sheet for the actual well location.

Office: BU		ID: BU12757
Unique INC #: KB/08/05	Well Name: FISH UNIT FEDERAL	ID Date: 01/30/08
	Well #: 6	Effective Date: 02/07/08
Operator: SLAWSON EXPLORATION CO INC	FAC ID:	Abatement Date: 02/27/08
Case #: WYW126496X	FAC NAME:	Corrected Date: 02/04/08
Form: I	Inspector: BRYCE	Followup Date:
Assessment: \$0		Extend Date:
Gravity: 3		
Authority Ref: APD site specific conditions of approval.		

Remarks Date: 01/31/08

There was no well sign on location. CFR 3162.6(b) states: For wells located on Federal and Indian lands, the operator shall properly identify by a sign in a conspicuous place. The sign shall include the well number, the name of the operator, the lease serial number, the surveyed location. The quarter / quarter, section, township and range. Your attention to this matter is appreciated.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU ID: BU12756  
Unique INC #: KB/08/04 Well Name: FISH UNIT FEDERAL  
Well #: 6 ID Date: 01/30/08  
Operator: SLAWSON EXPLORATION CO INC Effective Date: 02/07/08  
Case #: WYW126496X FAC ID: Abatement Date: 02/27/08  
Form: I FAC NAME: Corrected Date: 02/04/08  
Assessment: \$0 Inspector: BRYCE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: APD Site specific conditions of approval  
Remarks Date: 01/31/08

The reserve pit was not fenced. Site specific conditions of approval C.11. states: Reserve pit will be adequately fenced during and after drilling operations until reclaimed. Your attention to this matter is appreciated.

Office: BU ID: BU12935  
Unique INC #: DC08-008 Well Name: EDISTO ALERT CS FEDERAL  
Well #: 24 ID Date: 03/10/08  
Operator: YATES PETROLEUM CORP Effective Date: 03/21/08  
Case #: WYW131237 FAC ID: Abatement Date: 03/28/08  
Form: I FAC NAME: Corrected Date: 03/24/08  
Assessment: \$0 Inspector: CORK Followup Date: 03/26/08  
Gravity: 3 Extend Date:  
Authority Ref: Surface Use Conditions of Approval  
Remarks Date: 03/10/08

This well has been drilled. The fence around the pit at this location is down on one side and allows access to the pit underneath the fence on two sides.  
Corrective Action: Adequately fence the pit to deny access to the open pit.

Office: BU ID: BU12508  
Unique INC #: DC07-049 Well Name: CRAZY WOMAN S SCHUMAN  
Well #: 23-19 ID Date: 09/18/07  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 09/28/07  
Case #: WYW141149 FAC ID: Abatement Date: 10/18/07  
Form: I FAC NAME: Corrected Date: 10/01/07  
Assessment: \$0 Inspector: CORK Followup Date: 10/16/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR, Subpart 3162.6, (b)  
Remarks Date: 09/18/07

The well sign at this location has an incorrect Federal Lease Number, WYW148318. Corrective Action: Correct the well sign to show the correct lease number, WYW141149.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU		ID: BU13191
Unique INC #: MH0841	Well Name: ACACIA GILDA CS	
	Well #: 15	ID Date: 06/23/08
Operator: YATES PETROLEUM CORP		Effective Date: 06/25/07
Case #: WYW128607	FAC ID:	Abatement Date: 07/22/08
Form: I	FAC NAME:	Corrected Date: 07/02/08
Assessment: \$0	Inspector: HAINES	Followup Date: 07/02/08
Gravity: 3		Extend Date:
Authority Ref: Coditions of Approval		

Remarks Date: 06/23/08

Violation: Yates failed to comply with the Variance of Onshore Order#2, that was approved by the Buffalo Field Office to have mud and additives on location to control the well. Correction : You shall mud and additives on location drilling the drilling of all wells in the future. If you have any question contact Mark Haines at 307-684-1065.

Office: BU		ID: BU13192
Unique INC #: MH0442	Well Name: ACACIA GILDA CS	
	Well #: 15	ID Date: 06/23/08
Operator: YATES PETROLEUM CORP		Effective Date: 06/25/08
Case #: WYW128607	FAC ID:	Abatement Date: 07/22/08
Form: I	FAC NAME:	Corrected Date: 07/02/08
Assessment: \$0	Inspector: HAINES	Followup Date: 07/02/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 06/23/08

Violation: Yates has failed to comply with the vataince from Onshore Order #2, approved by the Buffalo Field Office, by not having handheld gas detection equipment on location. Correction : You shall have a handheld gas detection equipment on location durinf all drilling operations. If ther are any questions contact Mark Haines at 307-684-1065.

Office: BU		ID: BU12647
Unique INC #: MH0803	Well Name: ACACIA FARIS CS FEDERAL COM	
	Well #: 2 INC	ID Date: 11/27/07
Operator: YATES PETROLEUM CORP		Effective Date: 11/28/07
Case #: WYW130612	FAC ID:	Abatement Date: 12/24/07
Form: I	FAC NAME:	Corrected Date: 11/27/07
Assessment: \$500	Inspector: HAINES	Followup Date: 12/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1(b)(2)		

Remarks Date: 11/27/07

On November 27, 2007, Yates Petroleum informed the Buffalo Field Office that they had spud the Acacia Faris CS Federal Com #2 well at an unapproved site in Campbell County, WY. You shall submit a Notice of Intent to Abandon and a Sundry Notice with the new well location, accompanied by a new well plat, to the Buffalo Field Office by 12/24/2007. If you have any questions please contact Mark Haines, PET at 307-684-1065 or Mike Worden, Engineer at 307-684-1197.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU		ID: BU12679
Unique INC #: MH0804	Well Name: MOONEY DRAW MOONEY FED	
	Well #: 13-31MZ	ID Date: 12/14/07
Operator: PETRO-CANADA RES (USA) INC		Effective Date: 12/14/07
Case #: WYW132255	FAC ID:	Abatement Date: 12/15/07
Form: I	FAC NAME:	Corrected Date: 12/15/07
Assessment: \$0	Inspector: HAINES	Followup Date: 12/17/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1(a)(1)		

Remarks Date: 12/14/07

Violation: You have spud the Mooney Draw Mooney Federal 13-31WA during Bald Eagle Roosting Stipulations. Corrections: You shall finishing drilling, cementing the surface casing to surface, secure the well bore and remove all drilling equipment by 12/15/2007. Contact Mark Haines at 307-684-1065.

Office: BU		ID: BU13318
Unique INC #: MH0844	Well Name: MITCHELL DRAW 2 MDU	
	Well #: 21-44WA	ID Date: 08/25/08
Operator: PETRO-CANADA RES (USA) INC		Effective Date: 08/26/08
Case #: WYW163060X	FAC ID:	Abatement Date: 10/03/08
Form: I	FAC NAME:	Corrected Date: 09/10/08
Assessment: \$0	Inspector: HAINES	Followup Date: 09/10/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6.(a).(b)		

Remarks Date: 08/25/08

Violation ; The wellsite was not properly identified ( No well sign ). Correction: You shall install a well sign. If there are any questions contact Mark Haines at 307-684-1065.

Office: BU		ID: BU13319
Unique INC #: MH0845	Well Name: MITCHELL DRAW 2 MDU	
	Well #: 28-11WA	ID Date: 08/25/08
Operator: PETRO-CANADA RES (USA) INC		Effective Date: 08/26/08
Case #: WYW163060X	FAC ID:	Abatement Date: 10/03/08
Form: I	FAC NAME:	Corrected Date: 09/10/08
Assessment: \$0	Inspector: HAINES	Followup Date: 09/10/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (a).(b)		

Remarks Date: 08/25/08

Violation: Well site not properly identified ( No well sign ). Correction: You shall install the proper well sign. If there are any question please contact Mark Haines at 307-684-1065.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU		ID: BU12685
Unique INC #: SL-08-001I	Well Name: DRY WILLOW 1	
	Well #: 29-32	ID Date: 12/21/07
Operator: ANADARKO PETROLEUM CORP		Effective Date: 12/28/07
Case #: WYW163057X	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 12/28/07
Assessment: \$0	Inspector: LAMBERT	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1(a)		

Remarks Date: 12/21/07

The operator failed to comply with wildlife site specific Condition of Approval #4 "No surface disturbing activity shall occur within one mile of bald eagle habitat (The Pumpkin Buttes) annually from November 1 through April 1, prior to a winter roost survey or from February 1 through August 15 prior to a nesting survey." An exception from bald eagle roosting stipulations has been requested for this POD, however it has not yet been approved. Any other wells in lease WYW145174 subject to wildlife timing stipulations that are drilled prior to an approved exception will result in an automatic assessment.

Office: BU		ID: BU13336
Unique INC #: RN-08-91	Well Name: WEST KITTY BARLOW	
	Well #: 43-10AN	ID Date: 09/02/08
Operator: KENNEDY OIL		Effective Date: 09/02/08
Case #: WYW0203041	FAC ID:	Abatement Date: 09/22/08
Form: I	FAC NAME:	Corrected Date: 09/05/08
Assessment: \$500	Inspector: NAVARRETTE	Followup Date: 09/05/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1(a)(1)		

Remarks Date: 09/02/08

You have failed to comply per INC #RN-08-79 the return receipt was signed 8-14-08. You are hereby assessed \$500 per day. You are to log this well from the top of cement call Rafael Navarrette at (307) 684-1165 or (307)217-0740 prior to logging. DO NOT do any cementing prior to logging.

Office: BU		ID: BU13335
Unique INC #: RN-08-90	Well Name: WEST KITTY BARLOW	
	Well #: 12-11AN	ID Date: 09/02/08
Operator: KENNEDY OIL		Effective Date: 09/02/08
Case #: WYW0203041	FAC ID:	Abatement Date: 09/22/08
Form: I	FAC NAME:	Corrected Date: 09/05/08
Assessment: \$500	Inspector: NAVARRETTE	Followup Date: 09/05/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1(a)(1)		

Remarks Date: 09/03/08

You have failed to comply per INC #RN-08-81; the return receipt was signed 8-14-08. You are hereby assessed \$500 per day. You are to log this well from the top of cement call Rafael Navarrette at (307) 684-1165 or (307)217-0740 prior to logging. DO NOT do any cementing prior to logging.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU ID: BU13374  
Unique INC #: RN-08-96 Well Name: WEST KITTY BARLOW ID Date: 09/08/08  
Well #: 12-14AN Effective Date: 09/08/08  
Operator: KENNEDY OIL Abatement Date: 09/29/08  
Case #: WYW0203042 FAC ID: Corrected Date: 09/30/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshsore Order #2 III.B.c. and COA  
Remarks Date: 09/08/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Office: BU ID: BU13376  
Unique INC #: RN-08-98 Well Name: WEST KITTY BARLOW ID Date: 09/08/08  
Well #: 41-14AN Effective Date: 09/08/08  
Operator: KENNEDY OIL Abatement Date: 09/29/08  
Case #: WYW0203042 FAC ID: Corrected Date: 09/29/08  
Form: I FAC NAME: Followup Date: 09/29/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshsore Order #2 III.B.c. and COA  
Remarks Date: 09/08/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Office: BU ID: BU12678  
Unique INC #: RN-08-18 Well Name: ACACIA FARIS CS FEDERAL COM ID Date: 12/12/07  
Well #: 2 Effective Date: 12/12/07  
Operator: YATES PETROLEUM CORP Abatement Date: 01/07/08  
Case #: WYW130612 FAC ID: Corrected Date: 01/04/08  
Form: I FAC NAME: Followup Date: 01/04/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date: 01/10/08  
Gravity: 3  
Authority Ref: COA & Approved Drilling Plan  
Remarks Date: 12/13/07

The cement on this well is not to surface. You will log this well to find the top of cement, submit the log to this office and call Rafael Navarrette at (307)-684-1165 or (307)-217-0740 prior to doing any remedial cementing.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU ID: BU12677  
Unique INC #: RN-08-17 Well Name: TWENTY MILE CREEK EATON ID Date: 12/12/07  
Well #: 13-33WA Effective Date: 12/12/07  
Operator: PETRO-CANADA RES (USA) INC Abatement Date: 12/17/07  
Case #: WYW139677 FAC ID: Corrected Date: 12/13/07  
Form: I FAC NAME: Followup Date: 12/13/07  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 12/12/07

You have failed to comply with COA and your drilling plan. The fence around the drilling pit was not put up. You must install a fence all the way around the drilling pit until the pit is closed. 12/13/07 at 0750 hrs. Called Janny Gregson at 307-686-1240 and ask them to get fence up around the pit.

Office: BU ID: BU12530  
Unique INC #: RN-08-2 Well Name: CRAZY WOMAN S STATE ID Date: 10/02/07  
Well #: 14-21 Effective Date: 10/02/07  
Operator: BLACK DIAMOND ENERGY INC Abatement Date: 10/03/07  
Case #: WYW140488 FAC ID: Corrected Date: 10/03/07  
Form: I FAC NAME: Followup Date: 10/03/07  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil & Gas Order # 2.III.A.1

Remarks Date: 10/02/07

The diverter is not diverting all the drilling fluid to the drilling pit as required by the condition of approval. You must install a diverter that seals and diverts all cutting and circulating medium to the drilling pit. (Please see attached copy of the condition of approval) NOTICE WAS BY PHONE TO RED LUFKIN WITH BLACK DIAMOND AT 1145 HRS on 10/2/07.

Office: BU ID: BU13382  
Unique INC #: RN-08-102 Well Name: CARR DRAW III E CARU ID Date: 09/10/08  
Well #: 32-25W Effective Date: 09/11/08  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date:  
Case #: WYW150647X FAC ID: Corrected Date: 09/23/08  
Form: I FAC NAME: Followup Date: 09/23/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 3  
Authority Ref: COA

Remarks Date: 08/28/08

Surface use not in accordance with the approved plan. Someone drove off the approved location. You must keep all the equipment on the approved location and right of ways.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU ID: BU13379  
Unique INC #: RN-08-101 Well Name: CARR DRAW III E CARU ID Date: 08/28/08  
Well #: 21-30W Effective Date: 09/10/08  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 09/28/08  
Case #: WYW150647X FAC ID: Corrected Date: 09/23/08  
Form: I FAC NAME: Followup Date: 09/23/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 3  
Authority Ref: COA  
  
Remarks Date: 09/10/08

Surface use not in accordance with the approved plan. Some one drove off the approved location. You must keep all the equipment on the approved location and right of ways.

Office: BU ID: BU12943  
Unique INC #: RN-08-63 Well Name: CENTRAL KITTY TWENTY MILE ID Date: 03/13/08  
Well #: 13-29CA Effective Date: 03/17/08  
Operator: KENNEDY OIL Abatement Date: 04/07/08  
Case #: WYW155581 FAC ID: Corrected Date: 05/14/08  
Form: I FAC NAME: Followup Date: 05/22/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III.B.b and the COA  
  
Remarks Date: 03/17/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Office: BU ID: BU13378  
Unique INC #: RN-08-100 Well Name: WEST KITTY BARLOW ID Date: 09/08/08  
Well #: 31-15AN Effective Date: 09/08/08  
Operator: KENNEDY OIL Abatement Date: 09/29/08  
Case #: WYW159929 FAC ID: Corrected Date: 09/30/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III. B.b.c. and COA  
  
Remarks Date: 09/08/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU ID: BU13324  
 Unique INC #: CR08-56-I Well Name: KINGSBURY IV KU ID Date: 08/27/08  
 Well #: 43-21 Effective Date: 09/05/08  
 Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 09/17/08  
 Case #: WYW150648X FAC ID: Corrected Date: 09/18/08  
 Form: I FAC NAME: Followup Date: 09/24/08  
 Assessment: \$0 Inspector: ROSS Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3161.2 and Conditions of Approval in APD.

Remarks Date: 08/27/08

The drilling reserve pit at well 43-21 4677 has not been reclaimed within 90 days after drilling. To correct this violation comply with the Conditions of Approval in the APD.

Office: BU ID: BU12803  
 Unique INC #: GR0801A Well Name: FISH UNIT FEDERAL ID Date: 02/05/08  
 Well #: 6 Effective Date: 01/31/08  
 Operator: SLAWSON EXPLORATION CO INC Abatement Date: 02/06/08  
 Case #: WYW126496X FAC ID: Corrected Date: 02/05/08  
 Form: I FAC NAME: Followup Date: 02/05/08  
 Assessment: \$3,000 Inspector: ROTH Extend Date:  
 Gravity: 1  
 Authority Ref: OO #2. III. A. 1.

Remarks Date: 02/05/08

Failure to maintain BOPE system to assure well control. Specifically; Master 3-way valves on accumulator were locked into position preventing the remote control from operating the BOPE. Also BOP stack and choke valves were covered with ice making choke valves inoperable. As per 43 CFR 3163.1 (b) (1) this violation is subject to an immediate assessment of \$500 per day effective 1/31/08 for a total of \$3000. Corrective Action: Remove locking device from master 3-way valves on accumulator allowing the floor remote to function the BOPE and maintain BOPE so it is operational in sub-zero weather. Immediate action required. Violations were corrected same day of inspection.

Office: BU ID: BU12805  
 Unique INC #: GR0805 Well Name: FISH UNIT FEDERAL ID Date: 02/05/08  
 Well #: 6 Effective Date: 02/05/08  
 Operator: SLAWSON EXPLORATION CO INC Abatement Date: 02/06/08  
 Case #: WYW126496X FAC ID: Corrected Date: 02/05/08  
 Form: I FAC NAME: Followup Date: 02/05/08  
 Assessment: \$0 Inspector: ROTH Extend Date:  
 Gravity: 1  
 Authority Ref: Onshore Order # 2.III.C.7.

Remarks Date: 02/05/08

Failure to follow approved Mud Program. Specifically; Flare line and flow line (Bloovie Line) were only 60' in length. Approved APD and Onshore Order #2 states these lines will not be less than 100'. Corrective action; Extend lines to meet approved APD or request a variance for the 60'. The violation was corrected by the company man who called and received a variance from BLM engineer.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU ID: BU12874  
Unique INC #: GR0810 Well Name: CABIN CREEK II CB ID Date: 02/26/08  
Well #: 13CCWP-12 Effective Date: 02/26/08  
Operator: PINNACLE GAS RESOURCES, INC Abatement Date: 03/17/08  
Case #: WYW144218 FAC ID: Corrected Date: 03/12/08  
Form: I FAC NAME: Followup Date: 03/12/08  
Assessment: \$0 Inspector: ROTH Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 02/26/08

Failure to properly identify well. Specifically; No lease number on sign. Correction; Add lease number to sign or replace sign with all the correct required information. Notified Nate Meyers by phone 2-26-08 about sign.

Office: BU ID: BU12873  
Unique INC #: GR0809 Well Name: CABIN CREEK II CB ID Date: 02/26/08  
Well #: 09CCWP-13 Effective Date: 02/26/08  
Operator: PINNACLE GAS RESOURCES, INC Abatement Date: 03/17/08  
Case #: WYW144218 FAC ID: Corrected Date: 03/12/08  
Form: I FAC NAME: Followup Date: 03/12/08  
Assessment: \$0 Inspector: ROTH Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 02/26/08

Failure to properly identify well. Specifically; No lease number on sign. Correction; Add lease number to sign or replace sign with all the correct required information. Notified Nate Meyers by phone 2-26-08 about sign.

Office: BU ID: BU12872  
Unique INC #: GR0808 Well Name: CABIN CREEK II CB ID Date: 02/26/08  
Well #: 01CCWP-14 Effective Date: 02/26/08  
Operator: PINNACLE GAS RESOURCES, INC Abatement Date: 03/17/08  
Case #: WYW144219 FAC ID: Corrected Date: 03/12/08  
Form: I FAC NAME: Followup Date: 03/12/08  
Assessment: \$0 Inspector: ROTH Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 02/26/08

Failure to properly identify well. Specifically; No lease number on sign. Correction; Add lease number to sign or replace sign with all the correct required information. Notified Nate Meyers by phone 2-26-08 about sign.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU		ID: BU9296
Unique INC #: GR05119	Well Name: DEUEL	
	Well #: 14-30	ID Date: 08/01/05
Operator: TRUE OIL LLC		Effective Date: 08/01/05
Case #: WYW48277	FAC ID:	Abatement Date: 08/01/05
Form: I	FAC NAME:	Corrected Date: 08/01/08
Assessment: \$0	Inspector: ROTH	Followup Date: 08/01/05
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2 III.A.2.a.iii		

Remarks Date: 08/01/05

: Failure to install kill line on BOPE system. Specifically: Kill line was being used for other means on the rig. Corrective action: Kill line must stay connected and ready for use from the time surface shoe is drilled out until BOPE is removed. Shoe was drilled out 7-30-2005, kill line installed 8-1-2005. Corrected When corrected, sign and return original copy to the above address.

Office: BU		ID: BU9295
Unique INC #: GR05118	Well Name: DEUEL	
	Well #: 14-30	ID Date: 08/01/05
Operator: TRUE OIL LLC		Effective Date: 08/01/05
Case #: WYW48277	FAC ID:	Abatement Date: 08/01/05
Form: I	FAC NAME:	Corrected Date: 08/01/08
Assessment: \$1,500	Inspector: ROTH	Followup Date: 08/01/05
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2 III.A.1.		

Remarks Date: 08/01/05

Failure to install and maintain BOPE system. Specifically:2 Majors and 2 Minor violations related to BOPE system. Refer to following Non-Compliances GR05119, GR05121, GR05122, and GR05123 NOTE: Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). Shoe was drilled out 7-30-2005, inspected 8-1-2005.

Office: BU		ID: BU9299
Unique INC #: GR05122	Well Name: DEUEL	
	Well #: 14-30	ID Date: 08/01/05
Operator: TRUE OIL LLC		Effective Date: 08/01/05
Case #: WYW48277	FAC ID:	Abatement Date: 08/01/05
Form: I	FAC NAME:	Corrected Date: 08/01/08
Assessment: \$0	Inspector: ROTH	Followup Date: 08/01/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 III.2.h.		

Remarks Date: 08/01/05

Failure maintain remote control in working condition. Specifically: Remote control was not connected to system and incapable of operating closing unit. Corrective action: Connect remote controls so it shall be capable of closing all preventers. Shoe was drilled out 7-30-2005, remote control connected 8-1-2005 Corrected When corrected, sign and return original copy to the above address.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU		ID: BU9298
Unique INC #: GR05121	Well Name: DEUEL	
	Well #: 14-30	ID Date: 08/01/05
Operator: TRUE OIL LLC		Effective Date: 08/01/05
Case #: WYW48277	FAC ID:	Abatement Date: 08/01/05
Form: I	FAC NAME:	Corrected Date: 08/01/08
Assessment: \$1,500	Inspector: ROTH	Followup Date: 08/01/05
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2 III.2.e.		

Remarks Date: 08/01/05

Failure to maintain power to close unit pumps. Specifically: Air supply was closed to air jammer pump. Corrective action: Power (air supply) for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Shoe was drilled out 7-30-2005, Air valve was opened 8-1-2005 Corrected When corrected, sign and return original copy to the above address.

Office: BU		ID: BU9300
Unique INC #: GR05123	Well Name: DEUEL	
	Well #: 14-30	ID Date: 08/01/05
Operator: TRUE OIL LLC		Effective Date: 08/01/05
Case #: WYW48277	FAC ID:	Abatement Date: 08/01/05
Form: I	FAC NAME:	Corrected Date: 08/01/08
Assessment: \$0	Inspector: ROTH	Followup Date: 08/01/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 III.2.g.		

Remarks Date: 08/01/05

Failure maintain Hand Wheels / Locking devices for BOPE. Specifically: Hand wheels / locking devices were not installed on preventer. Corrective action: Install Hand Wheels / locking devices on preventer. Shoe was drilled out 7-30-2005, hand wheels installed 8-1-2005 Corrected When corrected, sign and return original copy to the above address.

Office: BU		ID: BU9297
Unique INC #: GR05120	Well Name: DEUEL	
	Well #: 14-30	ID Date: 08/01/05
Operator: TRUE OIL LLC		Effective Date: 08/01/05
Case #: WYW48277	FAC ID:	Abatement Date: 08/01/05
Form: I	FAC NAME:	Corrected Date: 08/01/08
Assessment: \$0	Inspector: ROTH	Followup Date: 08/01/05
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2 III.C.7		

Remarks Date: 08/01/05

Failure to install Flare line on BOPE system. Specifically: Flare line was not installed on choke manifold and ran out to a flare pit. Corrective action: Dig a flare pit and install flare line to run out not less than 100' and anchor in place. Shoe was drilled out 7-30-2005, pit dug and flare line installed 8-1-2005. Corrected When corrected, sign and return original copy to the above address.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU		ID: BU12694
Unique INC #: GDT08-15	Well Name: SKYWARD CS FEDERAL	
	Well #: 10	ID Date: 01/07/08
Operator: YATES PETROLEUM CORP		Effective Date: 01/08/08
Case #: WYW0312434	FAC ID:	Abatement Date: 01/08/08
Form: I	FAC NAME:	Corrected Date: 01/08/08
Assessment: \$0	Inspector: TRUJILLO	Followup Date: 01/08/08
Gravity: 3		Extend Date:
Authority Ref: OSO #2 III A. 2. (b) i		

Remarks Date: 01/07/08

III. Requirements b. Minimum standards and enforcement provisions for choke manifold equipment. i. All lines shall be anchored to prevent whip and reduce vibration. The Mud return line needs to be staked down. On 01/07/2008 at 1300, I inspected the Skyward CS Federal #10. The mud line was not staked down. I informed Steve Frazee, the drilling consultant , that the line was not staked down.

Office: BU		ID: BU12743
Unique INC #: JW08-003-I	Well Name: SLPU FED	
	Well #: 12-3H	ID Date: 01/24/08
Operator: EL PASO E&P CO LP		Effective Date: 01/24/08
Case #: WYW144500	FAC ID:	Abatement Date: 01/28/08
Form: I	FAC NAME:	Corrected Date: 01/28/08
Assessment: \$0	Inspector: WALKER	Followup Date: 01/28/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 01/24/08

Drilling inspection of Federal Geer 12-3H well shows there is not a flare pit. Conditions of Approval for this well requires a flare pit to be located on the well pad. Corrective action: Please install flare pit for this well. Thank you

Office: BU		ID: BU12745
Unique INC #: JW08-004-V	Well Name: SLPU FED	
	Well #: 12-3H	ID Date: 01/24/08
Operator: EL PASO E&P CO LP		Effective Date: 01/24/08
Case #: WYW144500	FAC ID:	Abatement Date: 01/24/08
Form: I	FAC NAME:	Corrected Date: 01/24/08
Assessment: \$0	Inspector: WALKER	Followup Date: 01/24/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 01/24/08

Drilling inspection of Federal Geer 12-3H well shows that there is not a well sign on location. Corrective Action: Please install sign identifying this well. Thank you

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: BU		ID: BU12744
Unique INC #: JW08-005-I	Well Name: SLPU FED	
	Well #: 12-3H	ID Date: 01/24/08
Operator: EL PASO E&P CO LP		Effective Date: 01/24/08
Case #: WYW144500	FAC ID:	Abatement Date: 01/28/08
Form: I	FAC NAME:	Corrected Date: 01/28/08
Assessment: \$0	Inspector: WALKER	Followup Date: 01/28/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 01/24/08

Drilling inspection of Federal Geer 12-3H well shows that the flare lines are not long enough and they are not securely anchored. Corrective Action: Extend flare lines to flare pit and securely anchor them. Thank you

Office: BU		ID: BU13095
Unique INC #: UWK08009I	Well Name: BOOS	
	Well #: 22-25	ID Date: 04/30/08
Operator: NATIONAL PRIDE OPER CO INC		Effective Date: 05/07/08
Case #: WYW110276	FAC ID:	Abatement Date: 06/30/08
Form: I	FAC NAME:	Corrected Date: 06/30/08
Assessment: \$0	Inspector: WILKERSON-KEELE	Followup Date: 07/02/08
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3162.5		

Remarks Date: 04/30/08

On 04-30-08 a follow up inspection to a reported SURFACE USE COMPLIANCE issue at this site was conducted by surface comp. techs. Found on site were hydrocarbon contaminated soils and water. Impermeable liner material and flagging covering pit in unsatisfactory condition. Leaking tank catch basin. Banking soil of retention pond is contaminated on north side of BERMED area. Misc. piping, oil soaked rag and 5 gal bucket found on site- (TO BE REMOVED).. Signage is incorrect and not reflective of current owner. Fence surrounding retention pond is in need of repair.

Office: CB		ID: CB20254
Unique INC #: 08-JA-038	Well Name: PINON FEDERAL COM	
	Well #: 1	ID Date: 05/27/08
Operator: CHI OPERATING INCORPORATED		Effective Date:
Case #: NMLC028785B	FAC ID:	Abatement Date: 08/31/08
Form: I	FAC NAME:	Corrected Date: 08/25/08
Assessment: \$0	Inspector: AMOS	Followup Date: 08/25/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1.a, COA		

Remarks Date: 05/27/08

Failure to comply with Conditions of Approval, which required you to notify the BLM Carlsbad Field Office at least 3 days prior to construction start. The COA also identified archaeological sites to the NE, NW, and South. The archaeological stipulations were to be given to a monitor at least 5 days prior to start. Temporary site protection barrier was to be in place during the drilling operations. There were to be no ground disturbing activities within 100' of the sites. The access road was to come in from the south and east side of the location. You built the access road on the NE side of the location, coming through the NE archaeological site. The archaeological site assessment as outlined in the attached letter will be complied with. In addition, upon completion of the well the location will be downsized as per APD COA. This will include downsizing the access road to the north. Contact Jim Amos at 505-234-5909 prior to start. All interim reclamation areas will be contoured back to the original landform, ripped and seeded with seed mixture #2.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB		ID: CB19892
Unique INC #: 08-JA-021	Well Name: OXY WILD BURRO FEDERAL	
	Well #: 1	ID Date: 12/31/07
Operator: CHI OPERATING INCORPORATED		Effective Date:
Case #: NMLC061783A	FAC ID:	Abatement Date: 01/15/08
Form: I	FAC NAME:	Corrected Date: 01/11/08
Assessment: \$0	Inspector: AMOS	Followup Date: 01/11/08
Gravity: 3		Extend Date:
Authority Ref: APD COA		

Remarks Date: 12/31/07

APD Conditions of Approval required cement on the long string to at least tie back into the intermediate casing by 200 feet. Sundry identified the calculated TOC to be at 6400 feet. Submit plans for approval to correct deficiency.

Office: CB		ID: CB20030
Unique INC #: 08-JA-0261	Well Name: CROZIER 28 FEDERAL	
	Well #: 1	ID Date: 02/23/08
Operator: CHI OPERATING INCORPORATED		Effective Date:
Case #: NMNM0265356A	FAC ID:	Abatement Date: 04/15/08
Form: I	FAC NAME:	Corrected Date: 04/11/08
Assessment: \$0	Inspector: AMOS	Followup Date: 04/11/08
Gravity: 3		Extend Date:
Authority Ref: APD COA		

Remarks Date: 02/23/08

This office was sent out 2/23/08, and was returned as not yours. Unclaimed. We have no change of operator for anyone else. Top of cement behind the 5-1/2" production casing is at 6940' per Well Completion Report (Form 3160-4). The Application for Permit to Drill, Conditions of Approval required at the minimum, top of cement behind the 5-1/2" production casing to extend 200 feet into the intermediate casing (1942'). Records submitted do not show how TOC was determined (TS, CBL, or calculated TOC). Submit a plan for approval, on how you plan to comply with the Conditions of Approval. If you have any questions contact Wesley Ingram (PE) at 505-234-5982.

Office: CB		ID: CB20050
Unique INC #: 08JA0281	Well Name: RDX 15	
	Well #: 1	ID Date: 03/02/08
Operator: RKI EXPLORTION AND PRODUCTION		Effective Date:
Case #: NMNM100558	FAC ID:	Abatement Date: 03/16/08
Form: I	FAC NAME:	Corrected Date: 03/07/08
Assessment: \$0	Inspector: AMOS	Followup Date: 03/07/08
Gravity: 3		Extend Date:
Authority Ref: APD, COA, 43 CFR 3162.1.a		

Remarks Date: 03/02/08

Per CBL, TOC located at 3,250'. APD Conditions of Approval required the TOC to be 500' into the previous casing string. Should be at 3,005' or higher. Submit plans for remedial cementing. If you have any questions contact Jim Amos at 505-234-5909.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB		ID: CB20057
Unique INC #: 08-JA-029	Well Name: IMC 21 FEDERAL COM	
	Well #: 2H	ID Date: 03/08/08
Operator: CHESAPEAKE OPERATING INC		Effective Date:
Case #: NMNM119272	FAC ID:	Abatement Date: 03/22/08
Form: I	FAC NAME:	Corrected Date: 03/17/08
Assessment: \$0	Inspector: AMOS	Followup Date: 03/17/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1.a, APD, COA		

Remarks Date: 03/08/08

Change to casing program without authorization. 3/5/08, ran 9 5/8" 36# K55 casing instead of the approved 8 5/8". We realize this casing exceeds the permitted casing, but it still requires prior authorization to make these changes. The well was permitted for a 11" wellbore. What was the hole size drilled? Future changes are to be authorized prior to making the changes.

Office: CB		ID: CB19984
Unique INC #: 08JA025I	Well Name: MOSAIC 34 FEDERAL	
	Well #: 2H	ID Date: 02/03/08
Operator: CHESAPEAKE OPERATING INC		Effective Date:
Case #: NMNM17222	FAC ID:	Abatement Date: 02/13/08
Form: I	FAC NAME:	Corrected Date: 02/09/08
Assessment: \$0	Inspector: AMOS	Followup Date: 02/09/08
Gravity: 3		Extend Date:
Authority Ref: APD COA		

Remarks Date: 02/03/08

APD Conditions of Approval required the production casing to circulate to surface. Sundry Notice dated 1/3/08 show top of cement at 2100'. Submit plan for remedial cementing to bring cement to surface

Office: CB		ID: CB19727
Unique INC #: 08JB001I	Well Name: INDIAN HILL 6 FEDERAL	
	Well #: 1	ID Date: 10/04/07
Operator: DEVON ENERGY PRODUCTION CO L P		Effective Date: 10/04/07
Case #: NMNM96212	FAC ID:	Abatement Date: 10/04/07
Form: I	FAC NAME:	Corrected Date: 10/04/07
Assessment: \$0	Inspector: BLAKLEY	Followup Date: 02/19/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval APD		

Remarks Date: 10/04/07

See next page for INC Text. Failure to comply with The conditions of approval of APD. APD states: "I. DRILLING OPERATIONS REQUIREMENTS: A. The Bureau of Land Management (BLM) is to be notified a minimum of 4 hours in advance for a representative to witness: 1. Spudding well 2. Setting and/or Cementing of all casing strings 3. BOPE tests Eddy County call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 361-2822 ." Prior Notice was not given for well Spud. Corrective Action: Not correctable. Give prior notices on next casing ,cement and BOP test.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB		ID: CB19728
Unique INC #: 08JB002I	Well Name: INDIAN HILL 6 FEDERAL	
	Well #: 1	ID Date: 10/04/07
Operator: DEVON ENERGY PRODUCTION CO L P		Effective Date: 10/04/07
Case #: NMNM96212	FAC ID:	Abatement Date: 10/04/07
Form: I	FAC NAME:	Corrected Date: 10/04/07
Assessment: \$0	Inspector: BLAKLEY	Followup Date: 02/19/08
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval APD		

Remarks Date: 10/04/07

See next page for INC Text. Failure to comply with The conditions of approval of APD. APD states: "I. DRILLING OPERATIONS REQUIREMENTS: A. The Bureau of Land Management (BLM) is to be notified a minimum of 4 hours in advance for a representative to witness: 1. Spudding well 2. Setting and/or Cementing of all casing strings 3. BOPE tests Eddy County call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (505) 361-2822 ." Proper Prior Notice was not given for well cementing of surface casing string. Corrective Action: Not correctable. Give prior notices on next casing ,cement and BOP test.

Office: CB		ID: CB20227
Unique INC #: 08-KC-053	Well Name: MESA FEDERAL	
	Well #: 2	ID Date: 05/07/08
Operator: THOMPSON CLEO J		Effective Date: 05/07/08
Case #: NMLC064490	FAC ID:	Abatement Date: 05/08/08
Form: I	FAC NAME:	Corrected Date: 05/08/08
Assessment: \$0	Inspector: CAFFALL	Followup Date: 05/08/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1(a) O.O.2.III.A.2.a.iv		

Remarks Date: 05/07/08

NO REMOTELY CONTROLLED CHOKE ON MANIFOLD. 5M SYSTEM REQUIRED TO HAVE 2 CHOKES WITH 1 REMOTELY CONTROLLED FROM RIG FLOOR. INSTALL 1 REMOTELY CONTROLLED (FROM RIG FLOOR) CHOKE.

Office: CB		ID: CB20225
Unique INC #: 08-KC-51	Well Name: MESA FEDERAL	
	Well #: 2	ID Date: 05/07/08
Operator: THOMPSON CLEO J		Effective Date: 05/07/08
Case #: NMLC064490	FAC ID:	Abatement Date: 05/08/08
Form: I	FAC NAME:	Corrected Date: 05/08/08
Assessment: \$0	Inspector: CAFFALL	Followup Date: 05/08/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1(a) O.O.2.III.a.2.g		

Remarks Date: 05/07/08

A MANUAL LOCKING DEVICE (I.E., HAND WHEELS) SHALL BE INSTALLED ON ALL SYSTEMS OF 2M OR GREATER. HAND WHEELS WERE NOT ATTACHED TO BLIND RAMS ON STACK. ATTACH HAND WHEELS TO BLIND RAMS ON STACK.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB ID: CB20226  
Unique INC #: 08-KC-052 Well Name: MESA FEDERAL ID Date: 05/07/08  
Well #: 2 Effective Date: 05/07/08  
Operator: THOMPSON CLEO J Abatement Date: 05/08/08  
Case #: NMLC064490 FAC ID: Corrected Date: 05/08/08  
Form: I FAC NAME: Followup Date: 05/08/08  
Assessment: \$0 Inspector: CAFFALL Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a) O.O.2.III.A.2.iv  
  
Remarks Date: 05/07/08  
5M BOPE SYSTEM SHALL HAVE 1 REMOTE KILL LINE (WHICH SHALL RUN TO THE OUTER EDGE OF THE SUBSTRUCTURE AND BE UNOBSTRUCTED. INSTALL 1 REMOTE KILL LINE AS PER ONSHORE ORDER #2.

Office: CB ID: CB20228  
Unique INC #: 08-KC-55 Well Name: MESA FEDERAL ID Date: 05/07/08  
Well #: 2 Effective Date: 05/07/08  
Operator: THOMPSON CLEO J Abatement Date: 05/08/08  
Case #: NMLC064490 FAC ID: Corrected Date: 05/27/08  
Form: I FAC NAME: Followup Date: 05/29/08  
Assessment: \$5,000 Inspector: CAFFALL Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a) O.O.2.III.A.1. 43 CFR 3163.1(b)(1)  
  
Remarks Date: 05/07/08

BLOW OUT PREVENTER (BOP) AND RELATED EQUIPMENT (BOPE) SHALL BE INSTALLED, USED, MAINTAINED, AND TESTED IN A MANNER NECESSARY TO ASSURE WELL CONTROL AND SHALL BE IN PLACE AND OPERATIONAL PRIOR TO DRILLING THE SURFACE CASING SHOE UNLESS OTHERWISE APPROVED BY THE APD. AS PER INC #'S 08-KC-481, 08-KC-050, 08-KC-051, 08-KC-052, 08-KC-053 BOP & BOPE WAS NOT USED, MAINTAINED, & TESTED AS PER ONSHORE ORDER #2 AFTER SETTING THE INTERMEDIATE CASING. CORRECT ABOVE REFERENCED VIOLATIONS.

Office: CB ID: CB20222  
Unique INC #: 08-KC-481 Well Name: MESA FEDERAL ID Date: 05/07/08  
Well #: 2 Effective Date: 05/07/08  
Operator: THOMPSON CLEO J Abatement Date: 05/08/08  
Case #: NMLC064490 FAC ID: Corrected Date: 05/08/08  
Form: I FAC NAME: Followup Date: 05/08/08  
Assessment: \$0 Inspector: CAFFALL Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a) O.O.II.A.1.c.iii.  
  
Remarks Date: 05/07/08

5M & HIGHER SYSTEMS THE ACCUMULATOR SHALL HAVE 2 INDEPENDENT SOURCES OF POWER AVAILABLE FOR POWERING THE CLOSING UNIT PUMPS. SUFFICIENT NITROGEN BOTTLES ARE SUITABLE AS A BACKUP POWER SOURCE ONLY. AIR SUPPLY WAS NOT TURNED ON @ THE ACCUMULATOR. MAINTAIN 2 INDEPENDENT SOURCES OF POWER FOR POWERING THE CLOSING UNIT PUMPS.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB		ID: CB20224
Unique INC #: 08-KC-50	Well Name: MESA FEDERAL	
	Well #: 2	ID Date: 05/07/08
Operator: THOMPSON CLEO J		Effective Date: 05/07/08
Case #: NMLC064490	FAC ID:	Abatement Date: 05/08/08
Form: I	FAC NAME:	Corrected Date: 05/08/08
Assessment: \$0	Inspector: CAFFALL	Followup Date: 05/08/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1(a) O.O.2.III.A.2.h		

Remarks Date: 05/07/08

REMOTE CONTROLS FOR 5M OR GREATER SYSTEMS SHALL BE CAPABLE OF BOTH OPENING AND CLOSING ALL PREVENTERS. AIR SUPPLY IS NOT ATTACHED TO REMOTE CONTROL. ATTACH AIR SUPPLY TO REMOTE CONTROL SO SYSTEMS SHALL BE CAPABLE OF BOTH OPENING AND CLOSING ALL PREVENTERS.

Office: CB		ID: CB20355
Unique INC #: 08-KC-60	Well Name: KYLE 34 FEDERAL	
	Well #: 1	ID Date: 08/13/08
Operator: NADEL & GUSSMAN		Effective Date: 08/22/08
Case #: NMNM105352	FAC ID:	Abatement Date: 09/19/08
Form: I	FAC NAME:	Corrected Date: 09/19/08
Assessment: \$0	Inspector: CAFFALL	Followup Date: 10/06/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 08/13/08

Failure to comply with an order of the Authorized Officer. Conditions of Approval on Sundry Notice 3160-5 submitted & approved on 08/12/2008 state 1. BLM to be notified at 575-361-2822 a minimum of 24 hours prior to beginning work. See Attached copy of Sundry Notice 3160-5 with Conditions of Approval Questions may be directed to Wesley Ingram Supervisor Petroleum Engineer Carlsbad Field Office (575) 234-5982 or Roy 'Kent' Caffall Lead Petroleum Engineering Technician Carlsbad Field Office (575) 234-5906

Office: CB		ID: CB19993
Unique INC #: 08-RC-I06	Well Name: SAND TANK 10 FEDERAL	
	Well #: 1	ID Date: 02/07/08
Operator: EOG RESOURCES, INC.		Effective Date: 02/07/08
Case #: NMNM01159	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 02/12/08
Assessment: \$0	Inspector: CARRASCO	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: OO #2.III.B.1.f.		

Remarks Date: 02/07/08

While running surface casing, Centralizers were not put on the first three joints ran in the hole. As per BLM engineer, Production string must now be cemented to surface.....Notify BLM before setting Production Casing. Failure to notify will result in assessments. Any Questions or Concerns call Richard Carrasco (575) 361-3565

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB ID: CB20383  
Unique INC #: 08-RC-I31 Well Name: QUEEN LAKE 20 FEDERAL ID Date: 09/02/08  
Well #: 2H Effective Date: 09/11/08  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 09/11/08  
Case #: NMNM17224 FAC ID: Corrected Date: 09/08/08  
Form: I FAC NAME: Followup Date: 09/16/08  
Assessment: \$0 Inspector: CARRASCO Extend Date:  
Gravity: 3  
Authority Ref: COA's....43 CFR 3162.1(a)

Remarks Date: 09/02/08

Commenced drilling operations after surface cement was pumped without allowing adequate set up of lead slurry to achieve 500psi compressive strength per approved COAs

Office: CB ID: CB20382  
Unique INC #: 08-RC-I30 Well Name: QUEEN LAKE 20 FEDERAL ID Date: 09/02/08  
Well #: 2H Effective Date: 09/11/08  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 10/01/08  
Case #: NMNM17224 FAC ID: Corrected Date: 09/08/08  
Form: I FAC NAME: Followup Date: 09/16/08  
Assessment: \$0 Inspector: CARRASCO Extend Date:  
Gravity: 3  
Authority Ref: COA's...43 CFR 3162.1(a)

Remarks Date: 09/02/08

Operator failed to provide inspector with proper paperwork indicating Wait on Cement times for lead and tail slurries to achieve 500psi Compressive strength as stated in approved APD COAs....Provide inspector with proper paperwork for this well.

Office: CB ID: CB20109  
Unique INC #: 08DCINC01 Well Name: BGSAU ID Date: 03/27/08  
Well #: 12-5 Effective Date: 03/27/08  
Operator: TANDEM ENERGY CORPORATION Abatement Date: 04/16/08  
Case #: NMNM68291X FAC ID: Corrected Date: 04/08/08  
Form: I FAC NAME: Followup Date: 04/14/08  
Assessment: \$0 Inspector: CARTER Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a); 43 CFR 3162.3-2(a)

Remarks Date: 03/27/08

The proposed casing programs shall be conducted as approved. The observed surface casing in the well bore was not in accordance with the approved APD. Failure to obtain prior approval to change the casing as called for in the approved APD. Please submit the invoice or bill of lading reflecting the casing that was used on the BGSAU 12-5. Also, submit the subsequent report showing the actual casing that was run for all casing strings. Further non-compliance of the conditions set forth in the APD regarding the casing program will result in an immediate assessment.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB ID: CB20005  
Unique INC #: 08-TC-006 Well Name: ROSS DRAW ID Date: 02/08/08  
Well #: 30 Effective Date: 02/08/08  
Operator: WILLIAMSON J C Abatement Date: 02/08/08  
Case #: NMNM11042 FAC ID: Corrected Date: 02/08/08  
Form: I FAC NAME: Followup Date: 02/08/08  
Assessment: \$0 Inspector: CARTWRIGHT Extend Date:  
Gravity: 1  
Authority Ref: O.O.#2.III.B.1.f.

Remarks Date: 02/08/08

Failure to install Centralizers as per O.O.#2.III.B.1.f. Surface casing shall have centralizers on the bottom 3 joints of the casing ( a minimum of 1 centralizer per joint, starting with the shoe joint). Install Centralizers as per O.O.#2.III.B.1.f.

Office: CB ID: CB20167  
Unique INC #: 08-TC-008 Well Name: BGSAU TRACT #1 ID Date: 04/08/08  
Well #: 5 Effective Date: 04/08/08  
Operator: TANDEM ENERGY CORPORATION Abatement Date: 04/11/08  
Case #: NMNM68291X FAC ID: Corrected Date: 04/21/08  
Form: I FAC NAME: Followup Date: 06/25/08  
Assessment: \$0 Inspector: CARTWRIGHT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1(a) & 3162.3-1(e) / OO#2.III.B.&B.1.a

Remarks Date: 04/08/08

Ran surface and intermediate casing that were not approved in APD As per conversation with Toben Scott on 4/7/2008 he indicated to Wesley Ingram that he would submit a sundry notice via fax on 4/7/2008 to cover the casing change.

Office: CB ID: CB20166  
Unique INC #: 08-TC-007 Well Name: BGSAU TRACT #1 ID Date: 04/08/08  
Well #: 5 Effective Date: 04/08/08  
Operator: TANDEM ENERGY CORPORATION Abatement Date: 04/28/08  
Case #: NMNM68291X FAC ID: Corrected Date: 04/21/08  
Form: I FAC NAME: Followup Date: 06/25/08  
Assessment: \$0 Inspector: CARTWRIGHT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1(a) 43CFR3162.6(b)

Remarks Date: 04/08/08

Well was not properly identify had wrong well sign. Sign was for well number BGSAU 6-4 Install correct well sign.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB		ID: CB20404
Unique INC #: 08CD58I	Well Name: COTTON DRAW UNIT	
	Well #: 112	ID Date: 09/23/08
Operator: DEVON ENERGY PRODUCTION CO L P		Effective Date: 09/30/08
Case #: NMNM012121	FAC ID:	Abatement Date: 09/30/08
Form: I	FAC NAME:	Corrected Date: 09/30/08
Assessment: \$0	Inspector: DE MONTIGNY	Followup Date: 09/30/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a), OO#2.III.A.i.ii., COA's VII.C.2.e		

Remarks Date: 09/23/08

FAILURE TO COMPLY WITH FEDERAL REGULATORY REQUIREMENTS, OO#2.III.A.i.ii AND COA's.VII.C.2.e, OF THE "APD" (APPLICATION PERMIT TO DRILL). TESTING BOP/BOPE EQUIPMENT (PIPE RAMS AND ANNULAR FOR 15 MINUTES TO 1200 PSI) USING A RIG PUMP ON THE 13 3/8" SURFACE CASING WAS NOT APPROVED PER COA's.VII.C.2.e. HAND DELIVERED NO FOLLOW-UP IS NEEDED.

Office: CB		ID: CB19792
Unique INC #: 08-WWI-01	Well Name: SALAMANDER 10 FEDERAL COM	
	Well #: 1	ID Date: 11/02/07
Operator: MEWBOURNE OIL COMPANY		Effective Date: 11/02/07
Case #: NMLC068722	FAC ID:	Abatement Date: 11/05/07
Form: I	FAC NAME:	Corrected Date: 11/02/07
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 11/02/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.3-2 (a)		

Remarks Date: 11/02/07

October 31, 2007 Received call from Mewbourne Oil Company (Wesley) and they are proposing to kick-off at approximately 9000' and penetrate the Morrow at an approximate 10 degree angle from the existing well bore. Operator was instructed to send in a Sundry with the proposed operations for review. November 2, 2007 Received call from Mewbourne Oil Company (Wesley) that two plugs had been set as of 0809 hours and that a thousand foot plug would be set from 9300-8300'. No Sundry received for operations. 0830 hours - issued verbal shutdown order. This will occur after setting of third plug, currently being pumped. Operator is to stabilize hole and conduct no further drilling operations until an approved Sundry for this procedure is in the hands of the company man onsite.

Office: CB		ID: CB20285
Unique INC #: 08RH23	Well Name: KNOLL AOK FEDERAL	
	Well #: 2H	ID Date: 06/19/08
Operator: YATES PETROLEUM CORPORATION		Effective Date: 06/24/08
Case #: NMNM85891	FAC ID:	Abatement Date: 06/30/08
Form: I	FAC NAME:	Corrected Date: 06/26/08
Assessment: \$0	Inspector: HOSKINSON	Followup Date: 06/30/08
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 2.III.B		

Remarks Date: 06/19/08

The proposed casing and cementing programs shall be conducted as approved. The Production casing in the well bore was not in accordance with the approved plan. Failure to obtain prior approval to change the approved APD. Submit a sundry notice detailing the change and demonstrating that the change meets or exceeds the standards of the original casing standards, or justification for the lesser standard. Submit the Production Casing Cementation report with sundry notice.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CB ID: CB20400  
Unique INC #: 08TW8INC Well Name: NIAGARA 3 FEE COM  
Well #: 2H ID Date: 09/22/08  
Operator: EOG RESOURCES, INC. Effective Date: 09/22/08  
Case #: NMNM100530 FAC ID: Abatement Date: 09/22/08  
Form: I FAC NAME: Corrected Date: 09/22/08  
Assessment: \$0 Inspector: WILSON Followup Date: 09/24/08  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3162.1(a)

Remarks Date: 09/22/08

Failed to call in spud notice.

Office: CB ID: CB20401  
Unique INC #: 08TW9INC Well Name: NIAGARA 3 FEE COM  
Well #: 2H ID Date: 09/22/08  
Operator: EOG RESOURCES, INC. Effective Date: 09/22/08  
Case #: NMNM100530 FAC ID: Abatement Date: 09/22/08  
Form: I FAC NAME: Corrected Date: 09/22/08  
Assessment: \$0 Inspector: WILSON Followup Date: 09/24/08  
Gravity: 3 Extend Date:  
Authority Ref: APD CONDITIONS OF APPROVAL

Remarks Date: 09/22/08

FAILED TO NOTIFY THE BLM A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS SPUDDING WELL AS REQUIRED BY THE PECOS DISTRICT CONDITIONS OF APPROVAL, VII. DRILLING , A.a. MET WITH LYNN CLAYTON , EOG RESOURCES REP. AND DISCUSSED AND RESOLVED VIOLATION.

Office: CB ID: CB20402  
Unique INC #: 08TW10INC Well Name: NIAGARA 3 FEE COM  
Well #: 2H ID Date: 09/22/08  
Operator: EOG RESOURCES, INC. Effective Date: 09/22/08  
Case #: NMNM100530 FAC ID: Abatement Date: 09/22/08  
Form: I FAC NAME: Corrected Date: 09/22/08  
Assessment: \$0 Inspector: WILSON Followup Date: 09/24/08  
Gravity: 3 Extend Date:  
Authority Ref: APD CONDITIONS OF APPROVAL

Remarks Date: 09/22/08

FAILED TO NOTIFY THE BLM A MINIMUM OF 4 HOURS IN ADVANCE FOR A REPRESENTATIVE TO WITNESS SETTING AND/OR CEMENTING OF CASING AS REQUIRED BY THE PECOS DISTRICT CONDITIONS OF APPROVAL , VII. DRILLING , A. b.. MET WITH LYNN CLAYTON , EOG RESOURCES REP. AND DISCUSSED AND RESOLVED VIOLATION.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: CC		ID: CC1124
Unique INC #: RG08GH048	Well Name:	
	Well #:	
Operator: WESTERN OPERATING COMPANY		
Case #: COC02136	FAC ID: BUT-1X	ID Date: 05/21/08
Form: I	FAC NAME: USA BUTLER 1X	Effective Date: 05/22/08
Assessment: \$0	Inspector: HUNT	Abatement Date: 06/12/08
Gravity: 3		Corrected Date: 07/19/08
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.a.		Followup Date: 04/13/10
		Extend Date:

Remarks Date: 05/21/08

Signs at the facility indicate the existence of H<sub>2</sub>S gas in the battery. Within 20 days of notice, submit results of latest tests for H<sub>2</sub>S in the facility (produced liquids) tankage. In the event that tanks contain more than 500 ppm H<sub>2</sub>S, operators of federal leases and agreements are required to also calculate and submit radii of exposure for the tanks for the 100 ppm and 500 ppm levels of H<sub>2</sub>S. Based on the amount of H<sub>2</sub>S in the tanks, and the radii of exposure calculations, additional requirements for operating in an H<sub>2</sub>S environment may be required. Questions concerning this Incident of Noncompliance may be addressed to Gene Hunt, at (719) 269-8533.

Office: CC		ID: CC1056
Unique INC #: RG07GH166	Well Name: ALEXANDER H, BB DRAW H	
	Well #: 4-1J, 4-2JI, 4-4J, 4-7-JI	
Operator: NOBLE ENERGY INC		
Case #: COC37699	FAC ID: A, B, C	ID Date: 06/12/07
Form: I	FAC NAME: 4-2JI, 4-7JI BATTERY, BB DRAW H 4-1,	Effective Date: 07/05/07
Assessment: \$0	Inspector: HUNT	Abatement Date: 08/05/07
Gravity: 3		Corrected Date: 10/01/07
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b		Followup Date: 09/25/07
		Extend Date: 10/01/07

Remarks Date: 06/12/07

Indications of Hydrogen Sulfide gas on the locations. Submit levels of H<sub>2</sub>S for this location and 100 and 500 ppm radii of exposure information within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Office: DK		ID: DK6367
Unique INC #: IMK08001	Well Name: MARTIN FEDERAL	
	Well #: 31X-33H	
Operator: ENCORE OPERATING LP		
Case #: NDM80953	FAC ID:	ID Date: 04/28/08
Form: I	FAC NAME:	Effective Date: 05/05/08
Assessment: \$0	Inspector: MIKE KOLLING	Abatement Date: 05/10/08
Gravity: 1		Corrected Date: 05/06/08
Authority Ref: Notice to Lessees MSO-91-1		Followup Date: 05/06/08
		Extend Date:

Remarks Date: 04/28/08

Failure to report blowout in a timely manner. Within 5 days of receipt of this notice you are required to submit information regarding the blowout and your plan for future operations.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: FE ID: FE14507  
Unique INC #: 08MG068 Well Name: SAN JUAN 27-4 UNIT ID Date: 08/20/08  
Well #: 141M Effective Date: 08/20/08  
Operator: BURLINGTON RESOURCES O&G CO LP Abatement Date: 08/23/08  
Case #: NMNM78408A FAC ID: Corrected Date: 08/20/08  
Form: I FAC NAME: Followup Date: 08/25/08  
Assessment: \$0 Inspector: GILBREATH Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order 2. III.A.2.g.

Remarks Date: 08/20/08

Hand wheels not installed on BOP system and the annular closing line valve handle not installed. Verbally informed Conoco company man David Sandoval of the violation on 8/20/08. Install and secure hand wheels and install handle on annular closing line valve.

Office: FE ID: FE14278  
Unique INC #: 08MOW005 Well Name: CENTRAL BASIN SWD ID Date: 02/02/08  
Well #: 1 Effective Date: 02/02/08  
Operator: ENERGEN RESOURCES CORPORATION Abatement Date: 02/11/08  
Case #: 0NMSF077968 OLD FAC ID: Corrected Date: 02/12/08  
Form: I FAC NAME: Followup Date: 02/19/08  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2,III. B.

Remarks Date: 02/02/08

The proposed casing and cementing programs shall be conducted as approved. The observed intermediate casing grade in the well bore was not in accordance with the approved plan. Failure to obtain prior approval to change the approved APD. Submit a sundry notice detailing the change and demonstrating that the change meets or exceeds the standards of the original casing standards, or justification for the lesser standard.

Office: FE ID: FE14277  
Unique INC #: 08MOW004 Well Name: CENTRAL BASIN SWD ID Date: 02/02/08  
Well #: 1 Effective Date: 02/02/08  
Operator: ENERGEN RESOURCES CORPORATION Abatement Date: 02/11/08  
Case #: 0NMSF077968 OLD FAC ID: Corrected Date: 02/12/08  
Form: I FAC NAME: Followup Date: 02/19/08  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2,III. B.

Remarks Date: 02/02/08

The proposed casing and cementing programs shall be conducted as approved. The observed surface casing grade in the well bore was not in accordance with the approved plan. Failure to obtain prior approval to change the approved APD. Submit a sundry notice detailing the change and demonstrating that the change meets or exceeds the standards of the original casing standards, or justification for the lesser standard.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: FE ID: FE14286  
Unique INC #: 08MOW006 Well Name: CENTRAL BASIN SWD ID Date: 02/22/08  
Well #: 1 Effective Date: 02/22/08  
Operator: ENERGEN RESOURCES CORPORATION Abatement Date: 02/22/08  
Case #: 0NMSF077968 OLD FAC ID: Corrected Date: 02/22/08  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order No. 2,III. B.

Remarks Date: 02/22/08

The proposed casing and cementing programs shall be conducted as approved. The observed quantity of cement used for production liner casing was not in accordance with the approved plan. Failure to obtain prior approval to change the approved APD. No Corrective action required.

Office: FE ID: FE14288  
Unique INC #: 08WW095 Well Name: CENTRAL BASIN SWD ID Date: 02/15/08  
Well #: 1 Effective Date: 02/15/08  
Operator: ENERGEN RESOURCES CORPORATION Abatement Date: 02/15/08  
Case #: NMSF077968 FAC ID: Corrected Date: 02/15/08  
Form: I FAC NAME: Followup Date: 02/15/08  
Assessment: \$0 Inspector: WEATHERFORD Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.e.

Remarks Date: 02/15/08

Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. The valve to the air supply was closed and was resolved; no further action necessary.

Office: GF ID: GF2531  
Unique INC #: AP-9-07 Well Name: ID Date: 07/24/07  
Well #: 3506-2 Effective Date: 09/21/07  
Operator: NOBLE ENERGY INC Abatement Date: 10/15/07  
Case #: MTM8557 FAC ID: Corrected Date: 10/09/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: PARROTT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1(a)

Remarks Date: 07/24/07

Location not reclaimed or seeded in accordance with '98 Master APD or Conditions of Approval attached to APD, dated September 29, 2006. Fence is not painted correct color. Trash is adjacent to location. Operator will correct this INC by October 15, 2007.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GJ		ID: GJ6355
Unique INC #: EF08011	Well Name: VEGA FEDERAL	
	Well #: 34-224	ID Date: 01/22/08
Operator: DELTA PETROLEUM CORPORATION		Effective Date: 02/04/08
Case #: COC47696B	FAC ID:	Abatement Date: 02/26/08
Form: I	FAC NAME:	Corrected Date: 02/26/08
Assessment: \$0	Inspector: FANCHER	Followup Date: 02/25/08
Gravity: 3		Extend Date: 03/03/08
Authority Ref: Onshore Order No. 2, III.B.		

Remarks Date: 01/22/08

"cementing program shall be conducted as approved" on the APD. 85/18/8, 12.5 ppg, 2.14 ft<sup>3</sup>/sx yld, is what was approved on the APD and 35/65 Type III, 12.5 ppg, 1.98 ft<sup>3</sup>/sx yld is shown on the "BJ" Cement Job Report, as used. You are required to submit Sundry Notice for the change in cement. Further a bond log is required to be submitted to this office by the date indicated.

Office: GJ		ID: GJ6345
Unique INC #: EF08005	Well Name: FEDERAL	
	Well #: 13-11-M	ID Date: 11/05/07
Operator: ASPEN OPERATING LLC		Effective Date: 11/05/07
Case #: COC61718	FAC ID:	Abatement Date: 11/23/07
Form: I	FAC NAME:	Corrected Date: 06/12/08
Assessment: \$0	Inspector: FANCHER	Followup Date: 02/22/08
Gravity: 3		Extend Date:
Authority Ref: Onshore Order No. 2, III.B.1.		

Remarks Date: 11/05/07

The proposed casing and cementing programs shall be conducted as approved. Operator did not follow the approved plan for cement as noted in APD. Your are required to submit Sundry Notice explaining your change of cementing by the indicated. Reduced to a minor violation.

Office: GJ		ID: GJ6346
Unique INC #: EF08006	Well Name: FEDERAL	
	Well #: 13-11-M	ID Date: 11/05/07
Operator: ASPEN OPERATING LLC		Effective Date: 11/05/07
Case #: COC61718	FAC ID:	Abatement Date: 11/23/07
Form: I	FAC NAME:	Corrected Date: 11/15/07
Assessment: \$0	Inspector: FANCHER	Followup Date: 02/22/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1 (a)(3)		

Remarks Date: 11/05/07

When necessary for compliance, or "where operations have been commenced without approval, ... the authorized officer may shut down operations. Immediate shut-in action may be taken where operations are initiated and conducted without prior approval, ... Operator failed to shut down operation and await approval for cement change, as instructed by PET. Please instruct your personnel accordingly. Reduced to a minor violation.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GJ		ID: GJ6347
Unique INC #: EF08007A	Well Name: FEDERAL	
	Well #: 13-11-M	ID Date: 11/10/07
Operator: ASPEN OPERATING LLC		Effective Date: 11/10/07
Case #: COC61718	FAC ID:	Abatement Date: 11/11/07
Form: I	FAC NAME:	Corrected Date: 01/16/08
Assessment: \$2,000	Inspector: FANCHER	Followup Date: 02/22/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1 (a)(6)(b)(1) & Onshore Order No.2, III.1.		

Remarks Date: 11/10/07

'Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). You are assessed \$2000. Your assessment is calculated from the day you drilled out the surface casing shoe, without having your BOPE connected, operative and tested, to the day of testing. The assessment rate is set at \$500.00 per day. Your pusher, Don, stated on 11/10/07 that he drilled out on Wednesday, 11/07/07. The co-man, Dan Benedict, was notified 11/10/07 that the blind rams were not connected to the accumulator and the kelly valve was not installed. On 11/10/07, Don was not able to pressure up the acccumulator to start the test and also had KLC added to the water in the casing.. On 11/11/07 Dan was notified that the kelly valve needed to be installed and a plug would be needed to test the BOPE.

Office: GJ		ID: GJ6418
Unique INC #: EF08044	Well Name:	
	Well #:	ID Date: 07/22/08
Operator: PLAINS EXPL & PROD COMPANY		Effective Date: 08/01/08
Case #: COC64790	FAC ID: 2A	Abatement Date: 08/22/08
Form: I	FAC NAME:	Corrected Date: 08/30/08
Assessment: \$0	Inspector: FANCHER	Followup Date: 08/30/08
Gravity: 1		Extend Date: 08/30/08
Authority Ref: 43 CFR 3162-5-3		

Remarks Date: 07/22/08

The operator shall perform operations and maintain equipment in a safe and workmanlike manner. Please remove pollutants stains off your tanks and remove build up of pollutants from the gravel.

Office: GJ		ID: GJ6344
Unique INC #: CS08005V	Well Name: VEGA FEDERAL	
	Well #: 35-33	ID Date: 10/29/07
Operator: DELTA PETROLEUM CORPORATION		Effective Date: 10/31/07
Case #: COC47696B	FAC ID:	Abatement Date: 10/31/07
Form: I	FAC NAME:	Corrected Date: 11/08/07
Assessment: \$0	Inspector: SNYDER	Followup Date: 11/08/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1(a)		

Remarks Date: 10/29/07

THE OPERATOR SHALL CONDUCT OPERATIONS IN A MANNER WHICH PROTECTS THE MINERAL RESOURCES, OTHER NATURAL RESOURCES, AND ENVIRONMENTAL QUALITY....RESERVE PIT WAS VERY FULL AND DID NOT MEET THE MINIMUM 2 FOOT FREEBOARD REQUIREMENT.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GR ID: GR1331  
Unique INC #: 063045 Well Name: TRAIL UNIT  
Well #: 23W ID Date: 05/23/06  
Operator: WEXPRO Effective Date: 05/23/06  
Case #: WYW094528A Abatement Date: 05/24/06  
Form: I FAC ID: Corrected Date: 09/08/08  
Assessment: \$0 FAC NAME: Followup Date: 09/08/08  
Gravity: 3 Inspector: MOFFETT Extend Date:  
Authority Ref: OO#2 III.A.1.

Remarks Date: 05/23/06

Violation: Kill line not installed in accordance with Onshore Order #2. Corrective Action: Install kill line as required per Onshore Order #2.

Office: GR ID: GR1330  
Unique INC #: 063044 Well Name: TRAIL UNIT  
Well #: 23W ID Date: 05/23/06  
Operator: WEXPRO Effective Date: 05/23/06  
Case #: WYW094528A Abatement Date: 05/24/06  
Form: I FAC ID: Corrected Date: 09/08/08  
Assessment: \$0 FAC NAME: Followup Date: 09/08/08  
Gravity: 3 Inspector: MOFFETT Extend Date:  
Authority Ref: OO#2 III.A.2.i.xi.

Remarks Date: 05/23/06

Violation: Functioning of the annular, pipe rams, and blind rams were not recorded in the IADC as required by Onshore Order #2. Corrective Action: Record the above stated actions on the IADC as required per Onshore Order #2.

Office: GR ID: GR1329  
Unique INC #: 063043 Well Name: TRAIL UNIT  
Well #: 23W ID Date: 05/23/06  
Operator: WEXPRO Effective Date: 05/23/06  
Case #: WYW094528A Abatement Date: 05/24/06  
Form: I FAC ID: Corrected Date: 09/08/08  
Assessment: \$0 FAC NAME: Followup Date: 09/08/08  
Gravity: 3 Inspector: MOFFETT Extend Date:  
Authority Ref: OO#2 III.A.2.g.

Remarks Date: 05/23/06

Violation: The hand-wheels were not installed in accordance with Ohshore Order #2. Corrective Action: Install all hand-wheels as required per Onshore Order #2.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GR ID: GR1339  
Unique INC #: 073003 Well Name: CANYON CREEK UNIT  
Well #: 10C-35J ID Date: 11/01/06  
Operator: WEXPRO Effective Date: 11/01/06  
Case #: WYW094531X Abatement Date: 11/08/06  
Form: I FAC ID: Corrected Date: 09/08/08  
Assessment: \$0 FAC NAME: Followup Date: 09/08/08  
Gravity: 3 Inspector: MOFFETT Extend Date:  
Authority Ref: O. O. #2.III.A.i.xi.

Remarks Date: 11/01/06

Violation: Functioning of the blind rams were not recorded as required per OO#2. Corrective Action: Function blind rams on the next trip and record as required per OO#2.

Office: GR ID: GR1320  
Unique INC #: 063034 Well Name: FULLERTON FEDERAL  
Well #: 33-12 ID Date: 02/22/06  
Operator: TRUE OIL COMPANY Effective Date: 02/22/06  
Case #: WYW132374 FAC ID: Abatement Date: 09/08/08  
Form: I FAC NAME: Corrected Date: 09/08/08  
Assessment: \$0 Inspector: MOFFETT Followup Date: 09/08/08  
Gravity: 3 Extend Date:  
Authority Ref: OO#2 III.B.1.h

Remarks Date: 02/22/06

The surface casing was tested to the incorrect pressure. Could not perform any type of corrective action as the well was already at TD.

Office: GR ID: GR1340  
Unique INC #: 073004 Well Name: GHOST ISLAND FEDERAL  
Well #: 2 ID Date: 12/05/06  
Operator: DAVIS PETROLEUM CORPORATION Effective Date: 12/08/06  
Case #: WYW152258 FAC ID: Abatement Date: 12/08/06  
Form: I FAC NAME: Corrected Date: 09/08/08  
Assessment: \$0 Inspector: MOFFETT Followup Date: 09/08/08  
Gravity: 3 Extend Date:  
Authority Ref: OO #2 III.A.1.

Remarks Date: 12/05/06

Violation: Valve handles not installed on inside and outside kill valves. Corrective Action: Install valve handles as required per Onshore Order #2.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GR ID: GR1359  
Unique INC #: HN0802W Well Name: JADE FEDERAL  
Well #: 7-10 ID Date: 11/16/07  
Operator: MAK-J ENERGY WYOMING LLC Effective Date: 11/16/07  
Case #: WYW88489 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NEWSHAM  
Gravity: 3  
Authority Ref: Approved APD p#4  
  
Remarks Date: 11/16/07  
Surface casing was not set according to the approved APD. Issued a written INC.

Office: GR ID: GR1360  
Unique INC #: HN0803W Well Name: JADE FEDERAL  
Well #: 7-10 ID Date: 11/18/07  
Operator: MAK-J ENERGY WYOMING LLC Effective Date: 11/18/07  
Case #: WYW88489 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NEWSHAM  
Gravity: 3  
Authority Ref: OO # 2 III.B1.i  
  
Remarks Date: 11/18/07  
Drilled more than 20' past the casing shoe for the formation integrity test. Issued a written INC.

Office: GR ID: GR1353  
Unique INC #: 073016 Well Name: NORTH ANDERSON CANYON  
Well #: 31-21 ID Date: 08/21/07  
Operator: WHITING OIL AND GAS CORPORATIO Effective Date: 08/22/07  
Case #: WYW102102 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NOVAK  
Gravity: 3  
Authority Ref: OO#2 III B. 1. h.  
  
Remarks Date: 08/22/07

On August 21 this office performed a Drilling Inspection on North Anderson Canyon 31-21. And violation was noted referencing the casing pressure test. It was not performed An Incident of Noncompliance (INC) has been issued for noncompliance with Onshore Oil and Gas Orders 43 CFR 3160 (OO#3160) No.2 III B. 1.h. Corrective Action Not Available

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GR ID: GR1357  
Unique INC #: 08INCMW01 Well Name: BIG SANDY FEDERAL  
Well #: 1-34 ID Date: 11/09/07  
Operator: GRYNBERG JACK J Effective Date: 11/09/07  
Case #: WYW147046 Abatement Date: 11/11/07  
Form: I FAC ID: Corrected Date: 11/09/07  
Assessment: \$0 FAC NAME: Followup Date: 12/17/07  
Gravity: 3 Inspector: NOVAK Extend Date: 11/11/07  
Authority Ref: OO 2 III.A.2.i.iv.D.

Remarks Date: 11/09/07

BOPE was last tested on 9-27-07. The next 30 day test should have been on 10-27-07. On 11-9-07 it was discovered that no BOPE test had occurred since 9-27-07. Operator has been verbally told to stabilize hole and trip out for a BOPE test.

Office: GR ID: GR1365  
Unique INC #: 0806 Well Name: WHISKEY CANYON UNIT  
Well #: 3 ID Date: 01/05/08  
Operator: QUESTAR EXPLORATION Effective Date: 01/05/08  
Case #: WYW164218X Abatement Date: 01/25/08  
Form: I FAC ID: Corrected Date: 01/14/08  
Assessment: \$0 FAC NAME: Followup Date: 01/14/08  
Gravity: 3 Inspector: NOVAK Extend Date:  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 01/05/08

Operator has failed to comply with INC #0803.

Office: GR ID: GR1367  
Unique INC #: 0808 Well Name: WHISKEY CANYON UNIT  
Well #: 3 ID Date: 01/05/08  
Operator: QUESTAR EXPLORATION Effective Date: 01/05/08  
Case #: WYW164218X Abatement Date: 01/25/08  
Form: I FAC ID: Corrected Date: 03/06/08  
Assessment: \$250 FAC NAME: Followup Date: 03/06/08  
Gravity: 3 Inspector: NOVAK Extend Date:  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 01/05/08

Operator has failed to comply with INC #0805.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GR ID: GR1363  
Unique INC #: 0804 Well Name: WHISKEY CANYON UNIT  
Well #: 3 ID Date: 01/01/08  
Operator: QUESTAR EXPLORATION Effective Date: 01/04/08  
Case #: WYW164218X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NOVAK  
Gravity: 3  
Authority Ref: OO#2 III.A.2.a.v.

Remarks Date: 01/01/08

There are hammer unions downstream of the valves on the panic line and before targeted tees. This does not meet the requirements of Onshore Order 2 for flanged, welded or clamped connections that are subjected to well-bore pressure.

Office: GR ID: GR1366  
Unique INC #: 0807 Well Name: WHISKEY CANYON UNIT  
Well #: 3 ID Date: 01/05/08  
Operator: QUESTAR EXPLORATION Effective Date: 01/05/08  
Case #: WYW164218X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NOVAK  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 01/05/08

Operator has failed to comply with INC #0804.

Office: GR ID: GR1364  
Unique INC #: 0805 Well Name: WHISKEY CANYON UNIT  
Well #: 3 ID Date: 01/01/08  
Operator: QUESTAR EXPLORATION Effective Date: 01/04/08  
Case #: WYW164218X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NOVAK  
Gravity: 3  
Authority Ref: OO#2 III.A.2.b.i.

Remarks Date: 01/01/08

Hose coming from BOPE stack to choke manifold is not straight and makes a 90 degree turn.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GR ID: GR1362  
Unique INC #: 0803 Well Name: WHISKEY CANYON UNIT  
Well #: 3 ID Date: 01/01/08  
Operator: QUESTAR EXPLORATION Effective Date: 01/04/08  
Case #: WYW164218X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NOVAK  
Gravity: 3 Extend Date:  
Authority Ref: OO#2 III.A.2.a.v.

Remarks Date: 01/01/08

There are hammer unions downstream of the chokes and before targeted tees. This does not meet the requirements of Onshore Order 2 for flanged, welded or clamped connections that are subjected to well-bore pressure.

Office: GR ID: GR1382  
Unique INC #: 0811 Well Name: FOUR MILE GULCH  
Well #: 88-6 ID Date: 06/16/08  
Operator: CABOT OIL & GAS CORPORATION Effective Date: 06/20/08  
Case #: WYW64897 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NOVAK  
Gravity: 3 Extend Date:  
Authority Ref: APD Drilling COA #5

Remarks Date: 06/16/08

The company man didn't call for BOP test

Office: GS ID: GS6337  
Unique INC #: 080003 Well Name: FEDERAL  
Well #: 7-42B (7G) ID Date: 10/11/07  
Operator: NOBLE ENERGY INC Effective Date: 10/12/07  
Case #: COC23443 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CAVANAUGH  
Gravity: 3 Extend Date:  
Authority Ref: O.O # 2. III.C. 1.

Remarks Date: 10/11/07

The characteristics, use and testing of drilling mud and the implementation of related drilling procedures shall be designed to prevent the loss of well control. Sufficient quantities of mud materials shall be maintained or readily accessible for the purpose of assuring well control. Minimum Standards and Enforcement Provisions for mud Program and equipment. 1. Record slow pump speed on daily drilling report after mudding up. Corrective Action: Start writing down slow pump speed in drilling log

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS			ID: GS6336
Unique INC #: 080002	Well Name: FEDERAL		
	Well #: 7-42B (7G)	ID Date:	10/11/07
Operator: NOBLE ENERGY INC		Effective Date:	10/11/07
Case #: COC23443	FAC ID:	Abatement Date:	10/12/07
Form: I	FAC NAME:	Corrected Date:	10/11/07
Assessment: \$0	Inspector: CAVANAUGH	Followup Date:	10/16/07
Gravity: 3		Extend Date:	
Authority Ref: O.O. # 2III. A. 2. G			

Remarks Date: 10/11/07

Minimum standards and enforcement provisions for locking devices. A manual locking device ( ie, hand wheels) or automatic locking devices shall be installed on all systems of 2 M or greater. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative. Corrective action: Install valve in closing line as close as possible to annular.

Office: GS			ID: GS6439
Unique INC #: 0801027007	Well Name: FEDERAL		
	Well #: 19-16 (PI19)	ID Date:	06/16/08
Operator: ENCANA OIL & GAS (USA) INC		Effective Date:	06/16/08
Case #: COC01523	FAC ID:	Abatement Date:	06/18/08
Form: I	FAC NAME:	Corrected Date:	06/18/08
Assessment: \$0	Inspector: FICKLIN	Followup Date:	06/25/08
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 06/16/08

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. EnCana failed to comply with the Downhole Conditions of Approval attached to the Approved Application for Permit to Drill or Reenter (APD). Condition of Approval require the Operating rights owner or operator, as appropriate to call at least 24 hours prior to running and cementing surface casing. Corrective Action: Submit to this office copies of the surface casing tally and cement report. Submit to this office copies of the BOP Test 's charts and log. Comply with all the Conditions of Approval within the APD.

Office: GS			ID: GS6438
Unique INC #: 080101	Well Name: FEDERAL		
	Well #: 19-16 (PI19)	ID Date:	06/16/08
Operator: ENCANA OIL & GAS (USA) INC		Effective Date:	06/16/08
Case #: COC01523	FAC ID:	Abatement Date:	06/18/08
Form: I	FAC NAME:	Corrected Date:	06/18/08
Assessment: \$0	Inspector: FICKLIN	Followup Date:	06/25/08
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 06/16/08

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. EnCana failed to comply with the Downhole Conditions of Approval attached to the Approved Application for Permit to Drill or Reenter (APD). Condition of Approval require the Operating rights owner or operator, as appropriate to call at least 24 hours prior to spud. Corrective Action: Submit to this office copies of the surface casing tally and cement report. Submit to this office copies of the BOP Test 's charts and log. Comply with all the Conditions of Approval within the APD.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS			ID: GS6440
Unique INC #: 080103	Well Name: FEDERAL		
	Well #: 19-16 (PI19)		ID Date: 06/16/08
Operator: ENCANA OIL & GAS (USA) INC			Effective Date: 06/16/08
Case #: COC01523	FAC ID:		Abatement Date: 06/18/08
Form: I	FAC NAME:		Corrected Date: 06/18/08
Assessment: \$0	Inspector: FICKLIN		Followup Date: 06/25/08
Gravity: 3			Extend Date:
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 06/16/08

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. EnCana failed to comply with the Downhole Conditions of Approval attached to the Approved Application for Permit to Drill or Reenter (APD). Condition of Approval require the Operating rights owner or operator, as appropriate to call at least 24 hours prior Testing BOP. Corrective Action: Submit to this office copies of the surface casing tally and cement report. Submit to this office copies of the BOP Test's charts and log. Comply with all the Conditions of Approval within the APD.

Office: GS			ID: GS6437
Unique INC #: 080100	Well Name: FEDERAL		
	Well #: 15-4BB (PH16)		ID Date: 06/16/08
Operator: ENCANA OIL & GAS (USA) INC			Effective Date: 06/16/08
Case #: COC01524	FAC ID:		Abatement Date: 06/18/08
Form: I	FAC NAME:		Corrected Date: 06/18/08
Assessment: \$0	Inspector: FICKLIN		Followup Date: 06/25/08
Gravity: 3			Extend Date:
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 06/16/08

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. EnCana failed to comply with the Downhole Conditions of Approval attached to the Approved Application for Permit to Drill or Reenter (APD). Condition of Approval require the Operating rights owner or operator, as appropriate to call at least 24 hours after spud. Corrective Action: Call the number listed in the APD with the exact time and date of the Spud. Comply with all the Conditions of Approval within the APD. Run Cement Bond Log on Surface Pipe and submit log to this office for review prior to drilling out the shoe.

Office: GS			ID: GS6436
Unique INC #: 080099	Well Name: FEDERAL		
	Well #: 15-4BB (PH16)		ID Date: 06/16/08
Operator: ENCANA OIL & GAS (USA) INC			Effective Date: 06/16/08
Case #: COC01524	FAC ID:		Abatement Date: 06/18/08
Form: I	FAC NAME:		Corrected Date: 06/18/08
Assessment: \$0	Inspector: FICKLIN		Followup Date: 06/25/08
Gravity: 3			Extend Date:
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 06/16/08

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. EnCana failed to comply with the Downhole Conditions of Approval attached to the Approved Application for Permit to Drill or Reenter (APD). Condition of Approval require the Operating rights owner or operator, as appropriate to call at least 24 hours prior to spud. Corrective Action: Call the number listed in the APD with the exact time and date of the Spud. Comply with all the Conditions of Approval within the APD. Run Cement Bond Log on Surface Pipe and submit log to this office for review prior to drilling out the shoe.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6364
Unique INC #: 080030	Well Name: FEDERAL RWF	
	Well #: 512-9 (12-9)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC62160	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. A. 2. i. xi.		

Remarks Date: 11/19/07

Pipe rams shall be activated each trip, however, this function need not be performed more than once a day. All of the above described tests and/or drills shall be recorded in the drilling log. The functioning of the pipe rams was not recorded in the drilling log. Corrective Action: Perform the functioning of the pipe rams as required and then record the fuinctioning in the drilling log on the next trip. After the functioning has been recorded in the drilling log, call Steve Ficklin @ 970-319-2509 and report the functioning.

Office: GS		ID: GS6365
Unique INC #: 080031	Well Name: FEDERAL RWF	
	Well #: 512-9 (12-9)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC62160	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. A. 2. i. xi.		

Remarks Date: 11/19/07

Blind rams shall be activated each trip, however, this function need not be performed more than once a day. All of the above described tests and /or drills shall be recorded in the drilling log. The functioning of the blind rams was not recorded in the drilling log. Corrective Action: Perform the functioning of the blind rams as required and then record the functioning in the drilling log on the next trip. After the functioning has been recorded in the drilling log, call Steve Ficklin @970-319-2509 and report the functioining.

Office: GS		ID: GS6348
Unique INC #: 080014	Well Name: OVERACKER FEDERAL	
	Well #: 29-05B (29-04)	
Operator: LARAMIE ENERGY II, LLC		
Case #: COC64181	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. A. 2. g.		

Remarks Date: 10/23/07

Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. Manual locking devices (i.e., hand wheels) were not installed on the pipe and blind rams. Corrective action: Install hand wheels on the the rams.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6502
Unique INC #: 080153	Well Name: HELLS GULCH FEDERAL	
	Well #: 23-13A(23-13)	ID Date: 07/24/08
Operator: PLAINS EXPL & PROD COMPANY		Effective Date: 07/24/08
Case #: COC66918	FAC ID:	Abatement Date: 07/25/08
Form: I	FAC NAME:	Corrected Date: 07/24/08
Assessment: \$0	Inspector: FICKLIN	Followup Date: 07/28/08
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 07/24/08

Minimum standards and enforcement provisions for well control equipment. - 3 inch diameter choke line A flange on the choke line between the HCR valve and the choke line manual valve was missing a bolt. Corrective Action: Install the bolt as required.

Office: GS		ID: GS6421
Unique INC #: 080084	Well Name: FEDERAL	
	Well #: 19-10 (PI19)	ID Date: 05/12/08
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 05/12/08
Case #: COC019572	FAC ID:	Abatement Date: 05/13/08
Form: I	FAC NAME:	Corrected Date: 05/12/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O. O. # 2 III. A. 2. c. ii		

Remarks Date: 05/12/08

Two independent sources of power shall be available for powering the closing unit pumps. At the time of the inspection, the second power source (supply air pressure) for the closing unit pumps, was found in the off position. Corrective Action: Ensure Accumulator system has two independent sources of power available for powering the closing unit pumps at all times. Corrective action was performed on 05/12/2008.

Office: GS		ID: GS6400
Unique INC #: 080064	Well Name: FEDERAL	
	Well #: 19-11 (PM19)	ID Date: 04/01/08
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 04/01/08
Case #: COC019572	FAC ID:	Abatement Date: 04/01/08
Form: I	FAC NAME:	Corrected Date: 04/01/08
Assessment: \$0	Inspector: KING	Followup Date: 04/07/08
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III A. 2. e.		

Remarks Date: 04/01/08

Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Air supply to accumulator was not turned on. Corrective Action: Turn on power for the closing pump, so that the pumps shall automatically start.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6487
Unique INC #: 080138	Well Name: FEDERAL	
	Well #: 6-24C (7D)	ID Date: 07/21/08
Operator: NOBLE ENERGY INC		Effective Date: 07/21/08
Case #: COC23443	FAC ID:	Abatement Date: 07/23/08
Form: I	FAC NAME:	Corrected Date: 07/22/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O. #2. III. A. 2. i. ix.		

Remarks Date: 07/21/08

Minimum standards and enforcement provisions for well control equipment testing A BOPE pit level drill shall be conducted weekly for each drilling crew. All of the above described testsand/or drills shall be recorded in the drilling log. There is no documentation in the driller's log (IADC) to indicate BOPE pit level drills were conducted as required. Corrective action: Conduct drills as required, record the drills in the driller's log (IADC) within 24 hours and provide documentation to this office.

Office: GS		ID: GS6492
Unique INC #: 080143	Well Name: FEDERAL	
	Well #: 6-24C (7D)	ID Date: 07/21/08
Operator: NOBLE ENERGY INC		Effective Date: 07/21/08
Case #: COC23443	FAC ID:	Abatement Date: 07/21/08
Form: I	FAC NAME:	Corrected Date: 07/22/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: O.O. #2. III B. 1. f.		

Remarks Date: 07/21/08

Surface casing shall have centralizers on the bottom 3 joints of the casing (a minimum of 1 centralizer per joint, starting with the shoe joint). The use and number of centralizers was not recorded in the IADC. No documentation of centralizers was provided during the inspection. Corrective Action: Perform cement logging to determine quality of the cementing job. Provide this office the log for review. Begin logging within 24 hours or as prudent to the situation.

Office: GS		ID: GS6493
Unique INC #: 080144	Well Name: FEDERAL	
	Well #: 6-24C (7D)	ID Date: 07/21/08
Operator: NOBLE ENERGY INC		Effective Date: 07/21/08
Case #: COC23443	FAC ID:	Abatement Date: 07/23/08
Form: I	FAC NAME:	Corrected Date: 07/22/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O. #2. III. B. 1. h.		

Remarks Date: 07/21/08

All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. The casing test was not recorded in the drilling log (IADC). Corrective Action: Perform test as required and record test in the IADC within 24 hours. Provide this office with proof of the test being recorded in the IADC.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6484
Unique INC #: 080135	Well Name: FEDERAL	
	Well #: 6-24C (7D)	
Operator: NOBLE ENERGY INC		
Case #: COC23443	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O.O.#2. III. A. 2. g.		

Remarks Date: 07/21/08

Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. The manual locking device (hand wheel) was missing from the pipe ram on the BOP stack. Corrective Action: Install manual locking device. Discrepancy corrected during the inspection. (07/21/08)

Office: GS		ID: GS6485
Unique INC #: 080136	Well Name: FEDERAL	
	Well #: 6-24C (7D)	
Operator: NOBLE ENERGY INC		
Case #: COC23443	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 1		
Authority Ref: O.O.#2. III. A. 2. a. iii.		

Remarks Date: 07/21/08

Minimum standards and enforcement provisions for well control equipment. 3M system: A minimum of 2 choke line valves (3 inch minimum) The choke line valve did not have a handle installed as required. Corrective Action: install handle as required. discrepancy corrected during the inspection. (07/21/08)

Office: GS		ID: GS6491
Unique INC #: 080142	Well Name: FEDERAL	
	Well #: 6-24C (7D)	
Operator: NOBLE ENERGY INC		
Case #: COC23443	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O.O. #2. III.B. 1. D.		

Remarks Date: 07/21/08

The surface casing shall be cemented back to surface either during the primary cement job or by remedial cementing. All of the above described tests shall recorded in the drilling log. Cementing of the surface casing and cement returns to the surface was not recorded in the driller's log (IADC) Corrective Action: Record the cement volume returned to surface in the IADC within 24 hours, and provide this office proof of recording.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6483
Unique INC #: 080134	Well Name: FEDERAL	
	Well #: 6-24C (7D)	ID Date: 07/21/08
Operator: NOBLE ENERGY INC		Effective Date: 07/21/08
Case #: COC23443	FAC ID:	Abatement Date: 07/22/08
Form: I	FAC NAME:	Corrected Date: 07/21/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O.#2. III. A. 2. a. iii.		

Remarks Date: 07/21/08

Minimum standards and enforcement provisions for well control equipment. 3M system: - Kill line (2 inch minimum) The kill line was not installed as required. Corrective Action: Install kill line. The discrepancy was corrected on 07/21/08.

Office: GS		ID: GS6488
Unique INC #: 080139	Well Name: FEDERAL	
	Well #: 6-24C (7D)	ID Date: 07/21/08
Operator: NOBLE ENERGY INC		Effective Date: 07/21/08
Case #: COC23443	FAC ID:	Abatement Date: 07/23/08
Form: I	FAC NAME:	Corrected Date: 07/22/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O. # 2. III. A. 2. i. viii.		

Remarks Date: 07/21/08

Minimum standards and enforcement provisions for well control equipment testing Pipe rams shall be activated each trip. There is no documentation to indicate the pipe rams were activated each trip as required. Corrective Action: Activate pipe rams, record activation in the driller's log (IADC) within 24 hours, and provide proof to this office.

Office: GS		ID: GS6490
Unique INC #: 080141	Well Name: FEDERAL	
	Well #: 6-24C (7D)	ID Date: 07/21/08
Operator: NOBLE ENERGY INC		Effective Date: 07/21/08
Case #: COC23443	FAC ID:	Abatement Date: 07/23/08
Form: I	FAC NAME:	Corrected Date: 07/22/08
Assessment: \$0	Inspector: KING	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 07/21/08

The operating rights owner or operator, as appropriate shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. Surface casing was set deeper than the approved Application for Permit to Drill (APD). Surface casing set at 2,518 feet, APD approved to 1,500 feet. Corrective Action: Submit Sundry notice within 24 hours for BLM engineers approval regarding the change of depth of surface casing. Approval by the engineer is required prior to proceeding.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6486
Unique INC #: 080137	Well Name: FEDERAL	
	Well #: 6-24C (7D)	
Operator: NOBLE ENERGY INC		
Case #: COC23443	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O.O. #2. A. i. xi.		

Remarks Date: 07/21/08

Minimum standards and enforcement provisions for well control equipment testing. Pressure tests shall apply to all related wellcontrol equipment. All of the tests and/or drills shall be recorded in the drilling log. There is no documentation in the driller's log (IADC) of pressures and components tested on the BOPE. Corrective Action: Record tests in the drilling log (IADC) within 24 hours and provide this office with proof of being recorded.

Office: GS		ID: GS6489
Unique INC #: 080140	Well Name: FEDERAL	
	Well #: 6-24C (7D)	
Operator: NOBLE ENERGY INC		
Case #: COC23443	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 3		
Authority Ref: O.O. #2.III. A. 2. i. viii.		

Remarks Date: 07/21/08

Minimum standards and enforcement provisions for well control equipment testing Blind rams should be activated each trip. There is no documentation to indicate the blind rams were activated each trip as required. Corrective Action: Activate blind rams, record activation in the driller's log (IADC) within 24 hours, and provide proof to this office.

Office: GS		ID: GS6567
Unique INC #: 080203	Well Name: FEDERAL PA	
	Well #: 442-31(PA42-31)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC62737	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KING	
Gravity: 1		
Authority Ref: O.O.#2. III. A. 2.e.		

Remarks Date: 09/03/08

Two independent sources of power shall be available for powering the closing unit pumps. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. The power for the closing unit pump was found off. Corrective Action: Ensure power to closing unit pumps remains available for both sources of power. The power was restored to closing unit pump at the time of the inspection.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS ID: GS6474  
Unique INC #: 080126 Well Name: DIXON FEDERAL ID Date: 07/11/08  
Well #: B8 Effective Date: 07/11/08  
Operator: ANTERO RESOURCES PICEANCE CORP Abatement Date: 07/12/08  
Case #: COC65762 FAC ID: Corrected Date: 07/11/08  
Form: I FAC NAME: Followup Date: 07/11/08  
Assessment: \$0 Inspector: KING Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2. III. A. 2. a. v.

Remarks Date: 07/11/08

Minimum standards and enforcement provisions for well control equipment. kill line (2 inch minimum) Kill line was not installed as required.  
Corrective Action: Install kill line (2 inch minimum) as required. Discrepancy corrected on 07/11/08

Office: GS ID: GS6451  
Unique INC #: 080110 Well Name: HELL'S GULCH FEDERAL ID Date: 06/17/08  
Well #: 23-11C(23-13) Effective Date: 06/17/08  
Operator: PLAINS EXPL & PROD COMPANY Abatement Date: 06/18/08  
Case #: COC66918 FAC ID: Corrected Date: 06/17/08  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KING Extend Date:  
Gravity: 3  
Authority Ref: O. O. #2. III. A. 2. a. iii.

Remarks Date: 06/17/08

Minimum standards and enforcement provisions for well control equipment. Safety valve and all subs to fit all drill string connections in use. The safety valves, (Floor valve and Inside BOP valve) were found in the closed position. Corrective Action: All safety valves on the rig floor shall be kept in the "Open" position. Corrected during the inspection. 06/17/08

Office: GS ID: GS6448  
Unique INC #: 080108 Well Name: HELL'S GULCH FEDERAL ID Date: 06/17/08  
Well #: 23-11C(23-13) Effective Date: 06/17/08  
Operator: PLAINS EXPL & PROD COMPANY Abatement Date: 06/18/08  
Case #: COC66918 FAC ID: Corrected Date: 06/17/08  
Form: I FAC NAME: Followup Date: 06/18/08  
Assessment: \$0 Inspector: KING Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. A. 2. iii

Remarks Date: 06/17/08

Minimum Standards and enforcement provisions for well control equipment. 3M BOPE system: Kill line (2 inch minimum) The kill line was not connected to the BOP stack. Corrective Action: Install kill line as required. Discrepancy was corrected on 06/17/08.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6453
Unique INC #: 080112	Well Name: HELLS GULCH FEDERAL	
	Well #: 23-11C(23-13)	ID Date: 06/17/08
Operator: PLAINS EXPL & PROD COMPANY		Effective Date: 06/17/08
Case #: COC66918	FAC ID:	Abatement Date: 06/20/08
Form: I	FAC NAME:	Corrected Date: 06/20/08
Assessment: \$0	Inspector: KING	Followup Date: 06/20/08
Gravity: 3		Extend Date:
Authority Ref: O.O. #2. III. A. 2. g.		

Remarks Date: 06/17/08

Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. There is no manual or automatic locking device installed on the BOP as required. Corrective Action: Install a manual or automatic locking device.

Office: GS		ID: GS6449
Unique INC #: 080107	Well Name: HELLS GULCH FEDERAL	
	Well #: 23-11C(23-13)	ID Date: 06/17/08
Operator: PLAINS EXPL & PROD COMPANY		Effective Date: 06/17/08
Case #: COC66918	FAC ID:	Abatement Date: 06/18/08
Form: I	FAC NAME:	Corrected Date: 06/18/08
Assessment: \$0	Inspector: KING	Followup Date: 06/18/08
Gravity: 3		Extend Date:
Authority Ref: O. O. # 2. III. A. 2. iii.		

Remarks Date: 06/17/08

Minimum standards and enforcement provisions for well control equipment. 3M system: 2 chokes (refer to diagram in Attachment 1) 3 M Choke Manifold Equipment, (2) two inch (minimum) adjustable chokes. Choke manifold only had 1 adjustable choke installed. Corrective Action: Install a second adjustable choke in the choke manifold as required for a 3M system. Discrepancy corrected on 06/18/08.

Office: GS		ID: GS6562
Unique INC #: 080197	Well Name: FEDERAL	
	Well #: 7-32D (7G)	ID Date: 08/29/08
Operator: NOBLE ENERGY INC		Effective Date: 08/29/08
Case #: COC23443	FAC ID:	Abatement Date: 08/30/08
Form: I	FAC NAME:	Corrected Date: 08/30/08
Assessment: \$0	Inspector: SIEBER	Followup Date: 08/30/08
Gravity: 1		Extend Date:
Authority Ref: 43CFR 3162.5-1 (b)		

Remarks Date: 08/29/08

The operator shall exercise due care and diligence to assure that leasehold operations do not result in undue damage to surface or subsurface resources or surface improvements. Violation: The operator, by being aware of and insufficiently addressing leaking containers, failed to uphold their environmental obligations. Corrective action: The operator shall move all leaking containers to a containment area, and properly clean and dispose of liquid waste. This corrective action shall be completed no later than 1300 hrs on August 30, 2008 (24 hours from the time the INC was issued).

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6561
Unique INC #: 080196	Well Name: FEDERAL	
	Well #: 7-32D (7G)	ID Date: 08/29/08
Operator: NOBLE ENERGY INC		Effective Date: 08/29/08
Case #: COC23443	FAC ID:	Abatement Date: 08/30/08
Form: I	FAC NAME:	Corrected Date: 08/30/08
Assessment: \$0	Inspector: SIEBER	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: O.O.#2, III, C, 7.		

Remarks Date: 08/29/08

All flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. The flare system shall have an effective method for ignition. Where noncombustible gas is likely or expected to be vented, the system shall be provided supplemental fuel for ignition and to maintain a continuous flare. Violation: The 3" bleed line was installed to discharge less than 100' from the well bore, and was insufficiently anchored. Corrective action: The bleed line shall be reconfigured, extended, anchored and contained in accordance with the requirements of O.O.#2. This corrective action shall be completed no later than 1300 hrs on August 30, 2008 (24 hours from the time the INC was issued).

Office: GS		ID: GS6389
Unique INC #: 080052	Well Name: NAUGLE RWF	
	Well #: 21-30 (PA41-25)	ID Date: 03/20/08
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 03/20/08
Case #: COC27871	FAC ID:	Abatement Date: 03/21/08
Form: I	FAC NAME:	Corrected Date: 03/21/08
Assessment: \$0	Inspector: SIEBER	Followup Date: 06/02/08
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. B. 1. h.		

Remarks Date: 03/20/08

All casing strings below the conductor shall be pressure tested to 0.22 psi per foot of casing string length or 1500 psi, whichever is greater, but not to exceed 70 percent of the minimum internal yield. If pressure declines more than 10 percent in 30 minutes, corrective action shall be taken. Corrective Action: Perform the required test and record the results in the drilling log (IADC) within 24 hours.

Office: GS		ID: GS6387
Unique INC #: 080051	Well Name: NAUGLE RWF	
	Well #: 21-30 (PA41-25)	ID Date: 03/20/08
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 03/20/08
Case #: COC27871	FAC ID:	Abatement Date: 03/21/08
Form: I	FAC NAME:	Corrected Date: 03/21/08
Assessment: \$0	Inspector: SIEBER	Followup Date: 06/02/08
Gravity: 3		Extend Date:
Authority Ref: CFR 3162.6 (b)		

Remarks Date: 03/20/08

For wells located of Federal and Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well, other than those permanently abandoned. The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quartersection, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds). Corrective Action: Install well identification sign with the required information as described above within 24 hours..

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS ID: GS6386  
Unique INC #: 080050 Well Name: NAUGLE RWF ID Date: 03/20/08  
Well #: 21-30 (PA41-25) Effective Date: 03/20/08  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 03/21/08  
Case #: COC27871 FAC ID: Corrected Date: 03/21/08  
Form: I FAC NAME: Followup Date: 06/02/08  
Assessment: \$0 Inspector: SIEBER Extend Date:  
Gravity: 3  
Authority Ref: O.O.#1 III. G. 3. f.  
Remarks Date: 03/20/08

A copy of the approved Form 3160-3 and the pertinent drilling plan, along with any conditions of approval, shall be available at the drill site to authorized or delegated representatives of the United States whenever active construction, drilling, or completion operations are under way. Corrective Action: A copy of the approved Form 3160-3 (APD) shall be acquired and maintained on site within 24 hrs.

Office: GS ID: GS6388  
Unique INC #: 080053 Well Name: NAUGLE RWF ID Date: 03/20/08  
Well #: 21-30 (PA41-25) Effective Date: 03/20/08  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 03/21/08  
Case #: COC27871 FAC ID: Corrected Date: 03/21/08  
Form: I FAC NAME: Followup Date: 06/02/08  
Assessment: \$0 Inspector: SIEBER Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. A. 2. i. xi.  
Remarks Date: 03/20/08

Minimum standards and enforcement provisions for well control equipment testing. (Pressures and times of the specific equipment tested) All of the above described tests and/or drills shall be recorded in the drilling log. Corrective Action: Record the BOP equipment test in the drilling log (IADC) as described above within 24 hours.

Office: GS ID: GS6390  
Unique INC #: 080054 Well Name: NAUGLE RWF ID Date: 03/20/08  
Well #: 21-30 (PA41-25) Effective Date: 03/20/08  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 03/21/08  
Case #: COC27871 FAC ID: Corrected Date: 03/21/08  
Form: I FAC NAME: Followup Date: 06/02/08  
Assessment: \$0 Inspector: SIEBER Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. B. 1. d.  
Remarks Date: 03/20/08

The surface casing shall be cemented back to surface either during the primary cement job or by remedial cementing. All of the above described tests shall be recorded in the drilling log. Corrective Action: Record the results of the surface casing including the amount of cement to surface in the drilling log (IADC) within 24 hours.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: GS		ID: GS6417
Unique INC #: 080080	Well Name: FEDERAL PA	
	Well #: 24-31 (1-M-31)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC62162	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: SIEBER	
Gravity: 1		
Authority Ref: O.O. #2, III, C, 7.		

Remarks Date: 05/07/08

The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. The flare line discharge was found to be less than 100 feet from the well head. Corrective action: The flare line discharge shall be extended to not less than 100 feet from the well head. Lines must be extended as required prior to drilling out the surface casing shoe. The lines should terminate at the flare pit as shown on plat #2 and plat #4 as per the approved APD.

Office: GS		ID: GS6463
Unique INC #: 080118	Well Name: HELL'S GULCH FEDERAL	
	Well #: 23-14B(23-13)	
Operator: PLAINS EXPL & PROD COMPANY		
Case #: COC66918	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: SIEBER	
Gravity: 3		
Authority Ref: O.O. #2, III, A, 2, a, iii		

Remarks Date: 07/02/08

Minimum standards and enforcement provisions for well control equipment. 3M system - 3 inch diameter choke line. Violation: Studs and nuts on the choke line between the BOP stack and the choke manifold were not fully threaded and tightened. Resolution: In order to assure and maintain well control standards; all studs and nuts on the choke line, choke manifold, and related equipment shall be fully threaded and tightened.

Office: GS		ID: GS6383
Unique INC #: 080048	Well Name: ENCANA RPW	
	Well #: 24-23-596	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC44963	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: TRUEAX	
Gravity: 3		
Authority Ref: O.O.#2. III A. 2. i. xi.		

Remarks Date: 02/14/08

Pipe and blind rams shall be activated each trip, however, this function need not be performed more than once a day. All of the above described tests and/or drills shall be recorded in the drilling log. Pipe ram drills were not conducted and/or recorded in drilling log. Corrective Action: provide a copy of drilling log showing the function tests were conducted and recorded as an individual item for each trip.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: HO		ID: HO12592
Unique INC #: 08-JA-033	Well Name: JCT FEDERAL 13	
	Well #: 01	ID Date: 04/26/08
Operator: THOMPSON J CLEO		Effective Date:
Case #: NMNM066884A	FAC ID:	Abatement Date: 05/15/08
Form: I	FAC NAME:	Corrected Date: 05/15/08
Assessment: \$0	Inspector: AMOS	Followup Date: 05/15/08
Gravity: 3		Extend Date:
Authority Ref: APD COA, 43 CFR 3162.1.a		

Remarks Date: 04/26/08

Sundry Notice dated 4/17/08, identified TOC @ 7751'. APD COA's, state cement should tie-back at least 200 feet into previous casing string. Operator shall provide method of verification. Operator is estimating TOC at 4000'. First stage to circulate; if cement does not, contact the appropriate BLM Office. No indications of DV, two stage job. Previous casing string, 8-5/8" set at 5225. 200' into 8-5/8" would be 5025'. Supply method of verification for the TOC. Submit plan for approval on how you plan on bringing cement top to comply with COA's. If you have questions, contact J. Amos at 505-234-5909, or Wesley Ingram @ 505-234-5982.

Office: HO		ID: HO12477
Unique INC #: 08JA027I	Well Name: GAINER 27	
	Well #: 01	ID Date: 02/29/08
Operator: THOMPSON J CLEO		Effective Date:
Case #: NMNM112945	FAC ID:	Abatement Date: 03/14/08
Form: I	FAC NAME:	Corrected Date: 04/20/08
Assessment: \$0	Inspector: AMOS	Followup Date: 04/20/08
Gravity: 3		Extend Date:
Authority Ref: APD COA, 43 CFR 3162.1.a		

Remarks Date: 02/29/08

Conditions of Approval required the production casing to tie back into the previous casing by 200'. The top of cement as determined by a temperature survey shows to be 5432' plus/minus. The 9.625" casing is at 5125, should be no lower than 4925'. By due date, submit a plan to bring well into compliance with conditions of approval. Suggest running a CBL to determine actual TOC, may not be as bad as indicated. This office is to be notified, for witnessing purposes, 48 hours prior to any action. If any questions contact Jim Amos at 505-234-5909, or Wesley Ingram at 505-234-5982.

Office: HO		ID: HO12608
Unique INC #: KAH-037-08	Well Name:	
	Well #:	ID Date: 05/02/08
Operator: CONOCOPHILLIPS COMPANY		Effective Date: 05/07/08
Case #: NMLC031621B	FAC ID: D	Abatement Date: 06/02/08
Form: I	FAC NAME: BRITT B	Corrected Date: 06/25/08
Assessment: \$0	Inspector: HASTON	Followup Date: 06/25/08
Gravity: 3		Extend Date: 06/27/08
Authority Ref: OOGO #6.III.D.2.e		

Remarks Date: 05/02/08

NO WIND DIRECTION INDICATOR INSTALLED AT BATTERY. - INSTALL A WIND DIRECTION INDICATOR AT THIS BATTERY.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: HO ID: HO12493  
Unique INC #: KAH-022-08 Well Name: BURGER B-17 ID Date: 03/09/08  
Well #: 01 Effective Date: 03/17/08  
Operator: APACHE CORPORATION Abatement Date: 04/17/08  
Case #: NMLC031670B FAC ID: Corrected Date: 03/20/08  
Form: I FAC NAME: Followup Date: 03/20/08  
Assessment: \$0 Inspector: HASTON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)(b)(c)

Remarks Date: 03/09/08

WELL IDENTIFICATION SIGN DOES NOT CONTAIN ALL REQUIRED INFORMATION. -- ADD FEDERAL LEASE SERIAL NUMBER "LC031670b" TO WELL IDENTIFICATION SIGN.

Office: JA ID: JA2034  
Unique INC #: CB-08-D14C Well Name: USA (MM) ID Date: 12/17/07  
Well #: 109 -ALT Effective Date: 12/17/07  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 12/17/07  
Case #: LABLMA24527 FAC ID: Corrected Date: 12/17/07  
Form: I FAC NAME: Followup Date: 12/17/07  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.e

Remarks Date: 12/17/07

Upon inspection, the dart valve of the IBOP was found to be in the closed position. This effectively prevents the valve being installed in a loss of well control event. I made the toolpusher, Sappo Thompson, aware of the violation and witnessed the dart being put in the open position and locked. I advised both the toolpusher and the rig supervisor, Fred Colvin, that this valve is always to be locked down in the open position while the rig is in the drilling mode.

Office: JA ID: JA2033  
Unique INC #: CB-08-D14B Well Name: USA (MM) ID Date: 12/17/07  
Well #: 109 -ALT Effective Date: 12/17/07  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 12/17/07  
Case #: LABLMA24527 FAC ID: Corrected Date: 12/17/07  
Form: I FAC NAME: Followup Date: 12/17/07  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.e

Remarks Date: 12/17/07

Upon inspection, the air supply line to the accumulator unit was found to be in the closed position. This, in effect, disabled the unit from being able to start automatically when the manifold pressure decreased below the preset level. I made the toolpusher, Sappo Thompson, aware of the violation and witnessed him placing the valve in the open position. I advised both the toolpusher and the rig supervisor, Fred Colvin, that under no circumstances was this valve to be closed while the rig was in the drilling mode.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: JA ID: JA2039  
Unique INC #: CB-08-D22A Well Name: USA (MM) ID Date: 02/19/08  
Well #: 119-ALT Effective Date: 02/19/08  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 02/19/08  
Case #: LABLMA24527 FAC ID: Corrected Date: 02/19/08  
Form: I FAC NAME: Followup Date: 02/19/08  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.e  
  
Remarks Date: 02/19/08  
THE AIR SUPPLY VALVE FOR THE CLOSING UNIT AIR PUMPS WAS FOUND TO BE IN THE CLOSED POSITION.. POWER, BOTH AIR AND ELECTRIC, FOR THE CLOSING UNIT MUST BE ON AT ALL TIMES.

Office: JA ID: JA2032  
Unique INC #: CB-08-D14A Well Name: USA (MM) ID Date: 12/17/07  
Well #: 109 -ALT Effective Date: 12/17/07  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 12/18/07  
Case #: LABLMA24527 FAC ID: Corrected Date: 12/17/07  
Form: I FAC NAME: Followup Date: 12/22/07  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.B.1.h  
  
Remarks Date: 12/17/07  
Operator failed to test the surface casing to the proper test pressure of 1500# as required by the Order. Since the operator had already began to run the intermediate casing string when this error was found, it was not possible to perform the test as required. Therefore, the operator is ordered to provide to this office a letter detailing the circumstances of this violation and the corrective actions that will be taken to prevent this type of violation from occurring in the future.

Office: JA ID: JA2040  
Unique INC #: CB-08-D22B Well Name: USA (MM) ID Date: 02/17/08  
Well #: 119-ALT Effective Date: 02/19/08  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 02/20/08  
Case #: LABLMA24527 FAC ID: Corrected Date: 02/17/08  
Form: I FAC NAME: Followup Date: 02/19/08  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii  
  
Remarks Date: 02/17/08  
PIPE AND BLIND RAMS WERE NOT FUNCTIONED AFTER BIT TRIP AS REQUIRED. OPERATOR IS TO PERFORM THE NECESSARY TEST AND/OR PROVIDE DOCUMENTATION CONCERNING THIS INCIDENT.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: KM		ID: KM960
Unique INC #: 08INC023	Well Name: FERDINAND FEDERAL	
	Well #: 80-18	ID Date: 03/12/08
Operator: CABOT OIL & GAS CORPORATION		Effective Date: 03/12/08
Case #: WYW128032	FAC ID:	Abatement Date: 03/12/08
Form: I	FAC NAME:	Corrected Date: 03/12/08
Assessment: \$250	Inspector: D W BREWER	Followup Date: 05/13/08
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.A.2.h.v. & vi.		

Remarks Date: 03/12/08

BOPE tester, Eager Beaver: Neil, failed to hold kill line check valve open, or remove ball (or loosen/remove cap, or plug) as required by "Violation" referenced above. After being called on the violation, all kill valves were re-tested & witnessed by BLM rep. All kill line components, as well as blind rams passed "second" tests as required. No further action required.

Office: KM		ID: KM981
Unique INC #: 08INC035	Well Name: BRUFF FEDERAL	
	Well #: 5-14	ID Date: 06/03/08
Operator: KERR-MCGEE OIL & GAS ONSHORE L		Effective Date: 06/03/08
Case #: WYW31555	FAC ID:	Abatement Date: 07/03/08
Form: I	FAC NAME:	Corrected Date: 06/03/08
Assessment: \$5,000	Inspector: MATTHEW WARREN	Followup Date: 06/12/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1(b)(2)		

Remarks Date: 06/03/08

On May 28, 2008 an email from Kerr-McGee was sent to the Kemmerer Field Office. This email details the new location of the Bruff Federal 5-14 well. The new location is 74' south and 55' west of the approved location. Since this change has not been approved this well has been drilled without approval. There is an immediate assessment of \$500 per day for each day that the violation existed prior to discovery, not to exceed \$5000. This well was spud on March 22, 2008. This is 80 days from the effective date of the INC. The maximum assessment of \$5000 is applied. The corrective action for this INC is to submit a sundry notice with the corrected well plat and location.

Office: KM		ID: KM979
Unique INC #: 08INC033	Well Name: WHISKEY BUTTES UNIT	
	Well #: 330-10E	ID Date: 05/21/08
Operator: EOG RESOURCES, INC.		Effective Date: 05/22/08
Case #: WYW0310645	FAC ID:	Abatement Date: 05/22/08
Form: I	FAC NAME:	Corrected Date: 05/22/08
Assessment: \$250	Inspector: PAT PRINGLE	Followup Date: 05/27/08
Gravity: 3		Extend Date:
Authority Ref: APD COA # 3		

Remarks Date: 05/21/08

Failed to notify the Authorized Officer's representative at least 48 hours prior to spudding, unless otherwise required in site specific conditions of approval.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: KM		ID: KM980
Unique INC #: 08INC034	Well Name: WHISKEY BUTTES UNIT	
	Well #: 330-10E	ID Date: 05/21/08
Operator: EOG RESOURCES, INC.		Effective Date: 05/22/08
Case #: WYW0310645	FAC ID:	Abatement Date: 05/22/08
Form: I	FAC NAME:	Corrected Date: 05/22/08
Assessment: \$250	Inspector: PAT PRINGLE	Followup Date: 05/27/08
Gravity: 3		Extend Date:
Authority Ref: APD COA #4		

Remarks Date: 05/21/08

Failed to notify the Authorized Officer's representative at least 24 hours in advance of Formation Test, Blowout Prevention Equipment Test, Running & Cementing Casing ( other than conductor casing ), according to the APD COA #4.

Office: ME		ID: ME2386
Unique INC #: 08MH01MEOF	Well Name: PICEANCE CREEK UNIT	
	Well #: T87X-3G2	ID Date: 10/04/07
Operator: EXXON MOBIL CORP		Effective Date: 10/12/07
Case #: COC47666A	FAC ID:	Abatement Date: 11/01/07
Form: I	FAC NAME:	Corrected Date: 11/01/07
Assessment: \$0	Inspector: HENDRICKS	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1-a		

Remarks Date: 10/04/07

Failure to comply with the Onshore Order #2 and the approved Application to Drill. Operator was permitted to drill a directional well, but drilled a horizontal well without getting prior BLM approval.

Office: ML		ID: ML3651
Unique INC #: BN-08-020	Well Name:	
	Well #:	ID Date: 04/16/08
Operator: CITATION OIL & GAS CORPORATION		Effective Date: 04/14/08
Case #: CANRM1675	FAC ID: A	Abatement Date: 05/28/08
Form: I	FAC NAME: ANDERSON 1-32R	Corrected Date: 04/29/08
Assessment: \$0	Inspector: BRIAN NANSEL	Followup Date: 05/19/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3164.1	Onshore Order #6 III.D.2.e.	

Remarks Date: 04/16/08

There is no permanent wind direction indicator installed. Install permanent wind direction indicator.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: ML		ID: ML3703
Unique INC #: CEL-IL-01	Well Name: BUXBAUM	
	Well #: 1-18H	ID Date: 06/10/08
Operator: NEWFIELD PRODUCTION COMPANY		Effective Date: 06/19/08
Case #: MTM25842	FAC ID:	Abatement Date: 07/30/08
Form: I	FAC NAME:	Corrected Date: 06/18/08
Assessment: \$0	Inspector: CHUCK LAAKSO	Followup Date: 06/18/08
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.3-1(c)		

Remarks Date: 06/10/08

Well was drilled in trespass. Operator is required to submit an APD; was fined \$5,000. Bill of Collection was attached to INC Letter. APD was received 6/18/08. Assessment and APD filing fees have been paid.

Office: NE		ID: NE3872
Unique INC #: JDH08002DI	Well Name: MILLER	
	Well #: 6-7	ID Date: 11/20/07
Operator: BEARTOOTH OIL & GAS COMPANY		Effective Date: 11/20/07
Case #: WYW173481	FAC ID:	Abatement Date: 11/27/07
Form: I	FAC NAME:	Corrected Date: 11/27/07
Assessment: \$0	Inspector: HUTCHINSON	Followup Date: 12/09/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1		

Remarks Date: 11/20/07

Surface Use Conditions of Approval C.11. requires the reserve pit to be adequately fenced during and after drilling operations until reclaimed so as to effectively keep out wildlife and livestock. This requires that it be fenced on the three non-working sides prior to drilling and on the remaining side immediately following rig release. Fencing will be constructed in accordance with BLM specifications. (Plastic snow fence is not acceptable fencing material for conventional wells.) Please fence reserve pit.

Office: NE		ID: NE4010
Unique INC #: JDH08048DW	Well Name: LONE CROW UNIT	
	Well #: 4-1	ID Date: 08/26/08
Operator: M & K OIL COMPANY INCORPORATED		Effective Date: 09/03/08
Case #: WYW176027X	FAC ID:	Abatement Date: 09/15/08
Form: I	FAC NAME:	Corrected Date: 09/11/08
Assessment: \$0	Inspector: HUTCHINSON	Followup Date: 09/11/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1		

Remarks Date: 08/26/08

Upon inspection of the reserve pit it was found that the pit was constructed with a containment volume of approximately 50% of the volume specified in the APD. Mitigation measures discussed with Jack Hanson and M&K personnel on 27 Aug 08 and the discussion between Jim Hutchinson and Kenny Hunter onsite on 02 Sep 08 included the following: " Monitor reserve pit and maintain a 2' free board at all times. " If the 2' freeboard is exceeded then move cuttings to a lined pit constructed on the well pad. Upon release of the drill rig, please submit a sundry notice to this office with a report of total volume of cuttings transferred to the secondary lined pit. Please sign and return this original notice of noncompliance along with the above described sundry notice.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: NE		ID: NE3878
Unique INC #: AA08INC01	Well Name: NLO FEDERAL	
	Well #: 20-1	ID Date: 01/13/08
Operator: NORTHERN LIGHTS OIL CO LC		Effective Date: 01/20/08
Case #: WYW147254	FAC ID:	Abatement Date: 02/05/08
Form: I	FAC NAME:	Corrected Date: 01/29/08
Assessment: \$0	Inspector: HUTCHINSON/AMBROSE	Followup Date: 01/29/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162. 1 (a)		

Remarks Date: 01/13/08

Failure to comply with the application to drill (APD). The APD states that surface casing will be set to 1000 feet but was only set to 713 feet. This was done without a sundry or approved change in procedures. The remedy for this action will be: 1) Run a SP log and a gama ray log. 2) A determination will be made on the log interpretation to determine the need for a cement stage tool to isolate a critical formation. 3) This will be done either prior to plugging of the well or prior to production of the well.

Office: PD		ID: PD2290
Unique INC #: 08DF112007	Well Name: WARBONNET	
	Well #: 6C1-9D	ID Date: 11/20/07
Operator: ULTRA RESOURCES INC		Effective Date: 11/21/07
Case #: WYW015316	FAC ID:	Abatement Date: 11/21/07
Form: I	FAC NAME:	Corrected Date: 11/20/07
Assessment: \$0	Inspector: FALLON	Followup Date: 12/03/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A.2.c.iii.		

Remarks Date: 11/20/07

Found: It was found that upon submission of the accumulator function test of the BOPE on H&P rig #286, that the useable fluid stored in the accumulator was too low. The remaining pressure was to be 1250, with the precharge determined at 1120. Corrective Action: The minimum standards and enforcement provisions for the accumulator mandates that the remaining pressure after system activation, as per Onshore Order #2 III. A.2.c.iii, retains a minimum of 200 psi above precharge on the closing manifold.

Office: PD		ID: PD2284
Unique INC #: 03DF111907	Well Name: WARBONNET	
	Well #: 5D1-4D	ID Date: 11/19/07
Operator: ULTRA RESOURCES INC		Effective Date: 11/20/07
Case #: WYW015316	FAC ID:	Abatement Date: 11/20/07
Form: I	FAC NAME:	Corrected Date: 11/20/07
Assessment: \$0	Inspector: FALLON	Followup Date: 11/21/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III.A.2.v.		

Remarks Date: 11/19/07

Found: During a detailed inspection of rig # Patterson 476, it was discovered the remote kill line did not extend to the outer edge of the substructure. Corrective Action: On 10K-15K rates systems, the kill line shall run to the outer edge of the substructure and be unobstructed.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PD		ID: PD2289
Unique INC #: 07DF112007	Well Name: WARBONNET	
	Well #: 6C1-9D	ID Date: 11/20/07
Operator: ULTRA RESOURCES INC		Effective Date: 11/20/07
Case #: WYW015316	FAC ID:	Abatement Date: 11/21/07
Form: I	FAC NAME:	Corrected Date: 11/20/07
Assessment: \$0	Inspector: FALLO	Followup Date: 11/26/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III.A.2.d.		

Remarks Date: 11/20/07

Found: It was found that upon submission of the accumulator function test of the BOPE on H&P rig #286, that the precharge pressure test was out of acceptable range. The actual precharge pressure was determined to be 1120 psi. Corrective Action: The precharge pressure test for a 3000psi accumulator shall be between 900psi (minimal acceptable precharge) and 1100 psi (maximum acceptable precharge).

Office: PD		ID: PD2272
Unique INC #: 02DF110707	Well Name: BOULDER	
	Well #: 1B-32DST	ID Date: 11/07/07
Operator: SWEPI LP		Effective Date: 11/07/07
Case #: WYW015316	FAC ID:	Abatement Date: 11/07/07
Form: I	FAC NAME:	Corrected Date: 11/07/07
Assessment: \$0	Inspector: FALLO	Followup Date: 11/13/07
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III.C.7		

Remarks Date: 11/07/07

Found: During a detailed rig inspection it was discovered the flare line(s) of Nabors Rig # 169 had no ignition source and was drilling at a depth, @8000", where gas was anticipated. Corrective Action: The Flare system shall have an effective method for ignition. Where noncombustible gas is likely or expected to be vented, the system shall be provided supplemental fuel for ignition and to maintain a continuous flare. This violation was corrected immediately upon notification.

Office: PD		ID: PD2271
Unique INC #: 01DF102907	Well Name: MESA	
	Well #: 7C-27DX	ID Date: 10/29/07
Operator: SWEPI LP		Effective Date: 10/30/07
Case #: WYW116265	FAC ID:	Abatement Date: 10/31/07
Form: I	FAC NAME:	Corrected Date: 10/31/07
Assessment: \$0	Inspector: FALLO	Followup Date: 11/01/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III.A.2.a.v.		

Remarks Date: 10/29/07

Found: During a detailed inspection of rig # Nabors 789, it was discovered the remote kill line did not extend to the outer edge of the substructure. Corrective Action: On 10K-15K rates systems, the kill line shall run to the outer edge of the substructure and be unobstructed.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PD		ID: PD2464
Unique INC #: 47DF042108	Well Name: CORONA	
	Well #: 51-30	ID Date: 04/21/08
Operator: ENCANA OIL & GAS USA INC		Effective Date: 04/21/08
Case #: WYW138876E	FAC ID:	Abatement Date: 04/21/08
Form: I	FAC NAME:	Corrected Date: 04/21/08
Assessment: \$0	Inspector: FALLON/GOODIN	Followup Date: 04/23/08
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III.C.7.		

Remarks Date: 04/21/08

Found: During a detailed rig inspection it was discovered the flare line(s) of Ensign Rig # 134 had no effect ignition source turned on. Corrective action: The Flare system shall have an effective method for ignition. Where noncombustible gas is likely or expected to be vented, the system shall be provided supplemental fuel for ignition and to maintain a continuous flare.

Office: PD		ID: PD2403
Unique INC #: 03ML2008	Well Name: STUD HORSE BUTTE	
	Well #: 28-22	ID Date: 03/06/08
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 03/06/08
Case #: WYW127749	FAC ID:	Abatement Date: 03/06/08
Form: I	FAC NAME:	Corrected Date: 03/06/08
Assessment: \$0	Inspector: LANE	Followup Date: 03/06/08
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.2.a.iv.		

Remarks Date: 03/06/08

O.O.#2.III.A.2.a.iv. Found: While witnessing a BOPE test it was found that the components for the check valve where missing. After investigation it was found that the components had been removed during the last formation integrity test (FIT) and had not been reinstalled prior to commencement of drilling operations. Corrective Action: Install and maintain well control equipment prior to drilling operations, as stated in Onshore Orders #2

Office: PD		ID: PD2399
Unique INC #: 02ML2008	Well Name: STUD HORSE BUTTE	
	Well #: 28-22	ID Date: 03/06/08
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 03/06/08
Case #: WYW127749	FAC ID:	Abatement Date: 03/06/08
Form: I	FAC NAME:	Corrected Date: 03/06/08
Assessment: \$0	Inspector: LANE	Followup Date: 03/06/08
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.2.i.iv.B.		

Remarks Date: 03/06/08

O.O.#2.III.A.2.III.i.iv.B. Found: While witnessing a BOPE test it was found that the check valve seal, located on the kill line, had been broken and not retested before drilling operations commenced. Corrective Action: Test shall be preformed whenever any seal subject to test pressure is broken.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PD		ID: PD2369
Unique INC #: MG2008-06	Well Name: WARBONNET	
	Well #: 3A1-14D	ID Date: 02/05/08
Operator: ULTRA RESOURCES INC		Effective Date: 02/05/08
Case #: WYW016161	FAC ID:	Abatement Date: 02/08/08
Form: I	FAC NAME:	Corrected Date: 03/28/08
Assessment: \$0	Inspector: PITTILO	Followup Date: 03/29/08
Gravity: 3		Extend Date:
Authority Ref: 43cfr3162.5-3		

Remarks Date: 02/05/08

Operator has failed to secure spud conductor against accidental entry upon release of the spud rig. Per 43CFR3162.5-3 : The opeator shall perform operations and maintain equipment in a safe and workmanlike manner. the operator shall take all precautions necessary to rprovide adequate protection for the heal th and safety or life and the protection of property.". Therefore Ultra shall immediately initiate actions to secure all spud conductors on this location to secure them against accidental entry. Compliance with this INC is required no later than February 8, 2008.

Office: PD		ID: PD2368
Unique INC #: MG2008-05	Well Name: WARBONNET	
	Well #: 2B1-14D	ID Date: 02/05/08
Operator: ULTRA RESOURCES INC		Effective Date: 02/05/08
Case #: WYW016161	FAC ID:	Abatement Date: 02/08/08
Form: I	FAC NAME:	Corrected Date: 03/28/08
Assessment: \$0	Inspector: PITTILO	Followup Date: 03/29/08
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.5		

Remarks Date: 02/05/08

Operator has failed to secure spud conductor against accidental entry upon release of the spud rig. Per 43CFR3162.5-3 : The opeator shall perform operations and maintain equipment in a safe and workmanlike manner. the operator shall take all precautions necessary to rprovide adequate protection for the heal th and safety or life and the protection of property.". Therefore Ultra shall immediately initiate actions to secure all spud conductors on this location to secure them against accidental entry. Compliance with this INC is required no later than February 8, 2008.

Office: PD		ID: PD2275
Unique INC #: LAW07044	Well Name: WARBONNET	
	Well #: 6A1-15D	ID Date: 11/14/07
Operator: ULTRA RESOURCES INC		Effective Date: 11/15/07
Case #: WYW015314	FAC ID:	Abatement Date: 11/16/07
Form: I	FAC NAME:	Corrected Date: 11/15/07
Assessment: \$0	Inspector: WALDO	Followup Date: 11/15/07
Gravity: 3		Extend Date:
Authority Ref: OO2.III.A.2.g.		

Remarks Date: 11/14/07

Problem: No hand wheels on BOP. Corrective action: Install hand wheels as per On Shore Orders on all valves and rams on the BOP. A manual locking device (i.e. hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PD ID: PD2462  
Unique INC #: LAW08029 Well Name: WARBONNET  
Well #: 2B1-11D ID Date: 04/15/08  
Operator: ULTRA RESOURCES INC Effective Date: 04/15/08  
Case #: WYW016162 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date:  
Gravity: 3 Corrected Date: 04/16/08  
Authority Ref: OO2 III.A.2.g. Followup Date: 04/16/08  
Extend Date:

Remarks Date: 04/15/08

Problem: The closing line of the annular does not have a manual locking device. Corrective action : Install closing line valve as close to the annular as possible.

Office: PR ID: PR3648  
Unique INC #: 08-006 EJ Well Name: KENILWORTH RAILROAD  
Well #: 15-3 ID Date: 11/29/07  
Operator: MARION ENERGY INCORPORATED Effective Date: 12/07/07  
Case #: UTU81161 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: E JONES Abatement Date: 12/21/07  
Gravity: 3 Corrected Date: 12/18/07  
Authority Ref: 43CFR 3162.1(a) and 3162.4-1(a) and (b) Followup Date:  
Extend Date:

Remarks Date: 11/29/07

Operator failed to submit a Well Completion or Recompletion Report and Log within 30 days after completing the well. Within 10 days of receipt of this notice, submit a Well Completion or Recompletion Report and Log along with associated information such as the directional survey and well logs.

Office: PR ID: PR3643  
Unique INC #: 08-001 EJ Well Name: KENILWORTH RAILROAD  
Well #: 15-3 ID Date: 11/29/07  
Operator: MARION ENERGY INCORPORATED Effective Date: 11/29/07  
Case #: UTU81161 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: E JONES Abatement Date: 11/29/07  
Gravity: 3 Corrected Date: 11/29/07  
Authority Ref: 43CFR 3162.1(a) Followup Date:  
Extend Date:

Remarks Date: 11/29/07

BLM was not notified prior to pad construction. The approved APD required that the BLM be notified 48 hours prior to commencing construction of the location.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PR ID: PR3646  
Unique INC #: 80-004 EJ Well Name: KENILWORTH RAILROAD ID Date: 11/29/07  
Well #: 15-3 Effective Date: 12/07/07  
Operator: MARION ENERGY INCORPORATED Abatement Date: 12/21/07  
Case #: UTU81161 FAC ID: Corrected Date: 12/18/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: E JONES Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3162.1(a)

Remarks Date: 11/29/07

A first production conference was not scheduled with the BLM as soon as the productivity of the well was apparent. Contact the BLM Price Field Office to schedule this conference.

Office: PR ID: PR3644  
Unique INC #: 08-002 EJ Well Name: KENILWORTH RAILROAD ID Date: 11/29/07  
Well #: 15-3 Effective Date: 12/07/07  
Operator: MARION ENERGY INCORPORATED Abatement Date: 12/21/07  
Case #: UTU81161 FAC ID: Corrected Date: 12/18/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: E JONES Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 11/29/07

BLM was not notified 24 hours prior to spud and written notification was not submitted. Daily drilling reports were not submitted. Daily drilling reports which provide detail as to drilling operations and conditions, from spud date through completion shall be submitted to the BLM Moab Field Office within 10 days of receipt of notice.

Office: PR ID: PR3650  
Unique INC #: 08-008 EJ Well Name: KENILWORTH RAILROAD ID Date: 11/29/07  
Well #: 15-3 Effective Date: 12/07/07  
Operator: MARION ENERGY INCORPORATED Abatement Date: 12/21/07  
Case #: UTU81161 FAC ID: Corrected Date: 01/07/08  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: E JONES Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3162.1(a)

Remarks Date: 11/29/07

Operator failed to notify BLM 3 hours prior to testing the blow out prevention (BOP) equipment. Within 10 days of receipt of this notice submit all data, charts, log book entries and other information that might serve to document BOPE testing that occurred during the drilling of the well.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PR ID: PR3649  
Unique INC #: 08-007 EJ Well Name: KENILWORTH RAILROAD ID Date: 11/29/07  
Well #: 15-3 Effective Date: 12/07/07  
Operator: MARION ENERGY INCORPORATED Abatement Date: 12/21/07  
Case #: UTU81161 FAC ID: Corrected Date: 01/07/08  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: E JONES Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3162.1(a)

Remarks Date: 11/29/07

Operator did not notify BLM when drilling reached 50 feet prior to the surface casing setting depth. Within 10 days of receipt of this notice, submit a job description form the cement contractor for the surface casing cement job.

Office: PR ID: PR3647  
Unique INC #: 08-005 EJ Well Name: KENILWORTH RAILROAD ID Date: 11/29/07  
Well #: 15-3 Effective Date: 12/07/07  
Operator: MARION ENERGY INCORPORATED Abatement Date: 12/17/07  
Case #: UTU81161 FAC ID: Corrected Date: 12/18/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: E JONES Extend Date:  
Gravity: 3  
Authority Ref: 3162.4-1(c)

Remarks Date: 11/29/07

BLM was not notified when the well was placed into production. Within 5 days of receipt of this notice, submit a written notification of the date production commenced.

Office: PR ID: PR3645  
Unique INC #: 80-003 EJ Well Name: KENILWORTH RAILROAD ID Date: 11/29/07  
Well #: 15-3 Effective Date: 12/07/07  
Operator: MARION ENERGY INCORPORATED Abatement Date: 12/21/07  
Case #: UTU81161 FAC ID: Corrected Date: 12/18/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: E JONES Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3162.1(a)

Remarks Date: 11/29/07

Daily drilling reports were not submitted. Daily drilling reports which provide detail as to drilling operations and conditions, from spud date through completion date shall be submitted to the BLM Moab Field Office within 10 days.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PR		ID: PR3609
Unique INC #: 13RK2007	Well Name: PETERS POINT UNIT FEDERAL	
	Well #: 2-7D-13-17 DEEP	ID Date: 10/15/07
Operator: BILL BARRETT CORPORATION		Effective Date: 10/18/07
Case #: UTU63014X	FAC ID:	Abatement Date: 10/22/07
Form: I	FAC NAME:	Corrected Date: 11/15/07
Assessment: \$0	Inspector: R KNIGHT	Followup Date: 11/16/07
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 2.111.A.2.c.iii.		

Remarks Date: 10/15/07

Violation - Onshore Order 2.111.A.2.c.iii. Two independent sources of power shall be available for powering the closing unit pumps. During a routine witnessing of a BOP tests and the accumulator test I discovered that the air pump was shut off on the accumulator. The rig Co. Man and the tool pusher both were informed a week prior to repair the pump and it still wasn't done. Corrective Action - Repair or replace the air pump on the accumulator.

Office: PR		ID: PR3666
Unique INC #: 32-WW-2008	Well Name: FEDERAL	
	Well #: 12-13	ID Date: 01/09/08
Operator: INTEGRATED ENERGY LLC		Effective Date: 01/16/08
Case #: UTU43778	FAC ID:	Abatement Date: 01/16/08
Form: I	FAC NAME:	Corrected Date: 01/09/08
Assessment: \$0	Inspector: W WILLIS	Followup Date: 01/09/08
Gravity: 1		Extend Date:
Authority Ref: Onshore Order 2 A.2.c.ii		

Remarks Date: 01/09/08

Air turned off Air Pump on Accumulator leaving a single source to close BOP rather than the two Power Sources required. Corrective Action: Turn Air on Air Pump on Accumulator and leave it on.

Office: PR		ID: PR3665
Unique INC #: 31-WW-2008	Well Name: FEDERAL	
	Well #: 12-13	ID Date: 01/07/08
Operator: INTEGRATED ENERGY LLC		Effective Date: 01/08/08
Case #: UTU43778	FAC ID:	Abatement Date: 01/12/08
Form: I	FAC NAME:	Corrected Date: 01/09/08
Assessment: \$0	Inspector: W WILLIS	Followup Date: 01/09/08
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3163.1 (a)		

Remarks Date: 01/07/08

No fence around reserve pit. Corrective action: Erect fence around reserve pit.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PR ID: PR3621  
Unique INC #: 21WW2008 Well Name: PETERS POINT UNIT FEDERAL  
Well #: 2-7D-13-17 DEEP  
Operator: BILL BARRETT CORPORATION  
Case #: UTU63014X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: W WILLIS  
Gravity: 3  
Authority Ref: Onshore Order #2 III.A2.i.xi; and i.vii  
Remarks Date: 11/01/07  
Blind Rams not closed on trips. Corrective Action: Close Blind Rams when out of hole on trips.

Office: PR ID: PR3617  
Unique INC #: 17WW2008 Well Name: PETERS POINT UNIT FEDERAL  
Well #: 2-7D-13-17 DEEP  
Operator: BILL BARRETT CORPORATION  
Case #: UTU63014X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: W WILLIS  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.2.i.ii  
Remarks Date: 11/01/07  
BOP not tested to stack working pressure. Corrective Action: Perform the necessary test.

Office: PR ID: PR3618  
Unique INC #: 18WW2008 Well Name: PETERS POINT UNIT FEDERAL  
Well #: 2-7D-13-17 DEEP  
Operator: BILL BARRETT CORPORATION  
Case #: UTU63014X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: W WILLIS  
Gravity: 3  
Authority Ref: Onshore Order #2 III.A2.i.xi; and i.vii  
Remarks Date: 11/01/07  
Weekly Annular Preventor fuction test not performed. Corrective Action: Perform the necessary test and record in IADC.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PR ID: PR3616  
Unique INC #: 16WW2008 Well Name: PETERS POINT UNIT FEDERAL ID Date: 11/01/07  
Well #: 2-7D-13-17 DEEP Effective Date: 11/08/07  
Operator: BILL BARRETT CORPORATION Abatement Date: 11/09/07  
Case #: UTU63014X FAC ID: Corrected Date: 11/09/07  
Form: I FAC NAME: Followup Date: 11/09/07  
Assessment: \$0 Inspector: W WILLIS Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.2.e.

Remarks Date: 11/01/07

Air turned off on BOP Accumulator Air Pump and Air Pump inoperative. Corrective Action: Repair Air Pump and keep air turned on pump at all times.

Office: PR ID: PR3619  
Unique INC #: 19WW2008 Well Name: PETERS POINT UNIT FEDERAL ID Date: 11/01/07  
Well #: 2-7D-13-17 DEEP Effective Date: 11/08/07  
Operator: BILL BARRETT CORPORATION Abatement Date: 11/09/07  
Case #: UTU63014X FAC ID: Corrected Date: 11/09/07  
Form: I FAC NAME: Followup Date: 11/09/07  
Assessment: \$0 Inspector: W WILLIS Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2 III.A2.i.xi; and i.vii

Remarks Date: 11/01/07

Pipe Rams not activated on trips. Corrective Action: Perform the necessary tests and record in IADC.

Office: PR ID: PR3620  
Unique INC #: 20WW2008 Well Name: PETERS POINT UNIT FEDERAL ID Date: 11/01/07  
Well #: 2-7D-13-17 DEEP Effective Date: 11/08/07  
Operator: BILL BARRETT CORPORATION Abatement Date: 11/09/07  
Case #: UTU63014X FAC ID: Corrected Date: 11/09/07  
Form: I FAC NAME: Followup Date: 11/09/07  
Assessment: \$0 Inspector: W WILLIS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1.(a)

Remarks Date: 11/01/07

Casing Shoe pressure integrity test not performed. Corrective Action: Perform a pressure integrity test.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PR ID: PR3637  
Unique INC #: 33WW2008 Well Name: PRICKLY PEAR UNIT FEDERAL ID Date: 11/26/07  
Well #: 1-17D-12-15 Effective Date: 12/03/07  
Operator: BILL BARRETT CORPORATION Abatement Date: 12/03/07  
Case #: UTU79487X FAC ID: Corrected Date: 12/03/07  
Form: I FAC NAME: Followup Date: 12/03/07  
Assessment: \$0 Inspector: W WILLIS Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2 III.A.2.b.

Remarks Date: 11/26/07

Choke Manifold discharge lines do no have Targeted Tee's. Install equipment as specified in the Onshore Order #2, All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees,.....

Office: PR ID: PR3636  
Unique INC #: 31WW2008 Well Name: PRICKLY PEAR UNIT FEDERAL ID Date: 11/26/07  
Well #: 1-17D-12-15 Effective Date: 12/03/07  
Operator: BILL BARRETT CORPORATION Abatement Date: 12/03/07  
Case #: UTU79487X FAC ID: Corrected Date: 12/03/07  
Form: I FAC NAME: Followup Date: 12/03/07  
Assessment: \$0 Inspector: W WILLIS Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2 III.A.1.

Remarks Date: 11/26/07

Drilling inspection revealed Dart Valve Inoperative. Corrective Action: Repair Dart Valve.

Office: PR ID: PR3675  
Unique INC #: 47-WW-2008 Well Name: PRICKLY PEAR UNIT FEDERAL ID Date: 01/28/08  
Well #: 7-18D-12-15 Effective Date: 01/28/08  
Operator: BILL BARRETT CORPORATION Abatement Date: 01/28/08  
Case #: UTU79487X FAC ID: Corrected Date: 01/28/08  
Form: I FAC NAME: Followup Date: 01/28/08  
Assessment: \$0 Inspector: W WILLIS Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 II.A.2.h.iv.

Remarks Date: 01/28/08

Operator failed to pressure test BOP after its removal and replacement. No corrective action required.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: PR		ID: PR3631
Unique INC #: 27WW2008	Well Name: PRICKLY PEAR UNIT FEDERAL	
	Well #: 1-17D-12-15	ID Date: 11/26/07
Operator: BILL BARRETT CORPORATION		Effective Date: 11/27/07
Case #: UTU79487X	FAC ID:	Abatement Date: 11/27/07
Form: I	FAC NAME:	Corrected Date: 11/27/07
Assessment: \$0	Inspector: W WILLIS	Followup Date: 11/27/07
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2 III.A.2.e.		

Remarks Date: 11/27/07

Air turned off Accumulator as well as both Air Pumps. Corrective Action: Turn air on and leave it on.

Office: PR		ID: PR3661
Unique INC #: 39-WW-2008	Well Name: PRICKLY PEAR UNIT FEDERAL	
	Well #: 10-17D-12-15	ID Date: 12/10/07
Operator: BILL BARRETT CORPORATION		Effective Date: 12/11/07
Case #: UTU79487X	FAC ID:	Abatement Date: 12/11/07
Form: I	FAC NAME:	Corrected Date: 12/11/07
Assessment: \$0	Inspector: W WILLIS	Followup Date: 12/11/07
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 III.A.2.C.iii		

Remarks Date: 12/10/07

During drilling inspection I found the Air turned off the Air Pumps on the BOP Accumulator. Regulation requires two power sources to be available at all times on the BOP Accumulator. Corrective Action: Repair whatever the reason is that Air turned off the Accumulator and then leave air on at all times while drilling.

Office: RO		ID: RO8123
Unique INC #: 01-005-01I	Well Name: SNAKEWEED B FEDERAL	
	Well #: 1	ID Date: 08/12/08
Operator: MCKAY OIL CORPORATION		Effective Date: 08/12/08
Case #: NMNM32323	FAC ID:	Abatement Date: 08/13/08
Form: I	FAC NAME:	Corrected Date: 08/18/08
Assessment: \$0	Inspector: GARNAND	Followup Date: 08/19/08
Gravity: 1		Extend Date: 08/19/08
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 08/12/08

Operator has been issued an Incident of noncompliance for removing drilling rig without prior approval. Conditions of Application for permit to drill, states that operator shall not remove the drilling rig without the production casing ran and cemented or the well being properly plugged. Operator must rig up on the hole and remediate and/or plug well. Contact was made with Caroll Shanks on 8-12-08 about the said INC being issued. Sign INC and return to Roswell field office.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: RO ID: RO8124  
Unique INC #: 01-006-08I Well Name: EPPERS B FEDERAL  
Well #: 2 ID Date: 08/14/08  
Operator: MCKAY OIL CORPORATION Effective Date: 08/14/08  
Case #: NMNM36190 FAC ID: Abatement Date: 08/15/08  
Form: I FAC NAME: Corrected Date: 08/15/08  
Assessment: \$0 Inspector: GARNAND Followup Date: 08/21/08  
Gravity: 1 Extend Date:  
Authority Ref: Onshore Order #2  
  
Remarks Date: 08/14/08

Operator has been issued an incident of noncompliance on wanting to run used casing without approval. All casing, except the conductor casing, shall be new or reconditioned and tested casing. Sign INC and return to Roswell field office.

Office: RW ID: RW4265  
Unique INC #: JLC06-2007 Well Name: CATALINA UNIT POD B  
Well #: 24-32 ID Date: 11/01/07  
Operator: DOUBLE EAGLE PETROLEUM Effective Date: 11/01/07  
Case #: WYW163121X FAC ID: Abatement Date: 11/03/07  
Form: I FAC NAME: Corrected Date: 11/08/07  
Assessment: \$0 Inspector: CINNAMON Followup Date: 11/08/07  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 2 III.C.1.  
  
Remarks Date: 11/01/07

Slow Pump speed was not recorded in drillers log. It is required each tour so a 48 hour abatement period was given to record current tour slow pump speed.

Office: RW ID: RW4264  
Unique INC #: JLC05-2007 Well Name: BLUE GAP  
Well #: 12-9 ID Date: 10/31/07  
Operator: QUESTAR EXPL AND PRODUCTION CO Effective Date: 10/31/07  
Case #: WYW164992 FAC ID: Abatement Date: 11/01/07  
Form: I FAC NAME: Corrected Date: 11/01/07  
Assessment: \$0 Inspector: CINNAMON Followup Date: 11/01/07  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order III A.c.  
  
Remarks Date: 10/31/07

Test and charge accumulator bottles and function test failure.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: RW		ID: RW4254
Unique INC #: ETF07-01	Well Name: HORSESHOE RIDGE FEDERAL	
	Well #: 8-1	ID Date: 10/10/07
Operator: RICHARDSON OPERATING COMPANY		Effective Date: 10/10/07
Case #: WYW142851	FAC ID:	Abatement Date: 10/11/07
Form: I	FAC NAME:	Corrected Date: 10/11/07
Assessment: \$0	Inspector: FAZEDIN	Followup Date: 10/11/07
Gravity: 3		Extend Date:
Authority Ref: OO#2 III.A.2.g.		

Remarks Date: 10/10/07

Hand wheels on BOP not installed as per Onshore Order #2 III.A.2.g. Install handwheels as directed.

Office: RW		ID: RW4428
Unique INC #: ETF08-15	Well Name: ESPY UNIT	
	Well #: 13	ID Date: 08/18/08
Operator: NADEL & GUSSMAN ROCKIES LLC		Effective Date: 08/19/08
Case #: WYW109504X	FAC ID:	Abatement Date: 08/20/08
Form: I	FAC NAME:	Corrected Date: 09/05/08
Assessment: \$0	Inspector: FAZENDIN	Followup Date: 09/14/08
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.A.2.b.i		

Remarks Date: 08/18/08

It was found on 8/18/08 that Nabors rig 444 was drilling the Espy Unit #13 well with a co-flex choke line without prior approval. As stated in the APD, prior approval for the co-flex line is required.

Office: RW		ID: RW4346
Unique INC #: ETF08-01	Well Name: SUN DOG C AR 1691	
	Well #: 6-29	ID Date: 01/17/08
Operator: ANADARKO E & P COMPANY LP		Effective Date: 01/17/08
Case #: WYW152954X	FAC ID:	Abatement Date: 02/19/08
Form: I	FAC NAME:	Corrected Date: 01/31/08
Assessment: \$0	Inspector: FAZENDIN	Followup Date: 01/31/08
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 01/17/08

On 1/16/08 during a drilling inspection I noticed that there was no location identification sign. I spoke with John Merkle about the issue and he stated that he would have a temporary sign up that day. During a follow up inspection on 1/17/08 I noted that there was still not a sign on location.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: RW ID: RW4359  
Unique INC #: ETF08-02 Well Name: SUN DOG UNIT POD D ID Date: 01/31/08  
Well #: 6-3 Effective Date: 01/31/08  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 02/15/08  
Case #: WYW152954X FAC ID: Corrected Date: 01/31/08  
Form: I FAC NAME: Followup Date: 02/13/08  
Assessment: \$0 Inspector: FAZENDIN Extend Date:  
Gravity: 3  
Authority Ref: Conditions of Approval  
  
Remarks Date: 01/31/08

Page 17, #6 under PITS states: ...all pits and open cellars shall be fenced on all sides, with corner bracing, immediately upon construction. Reserve, flare, completion, and production pits will be adequately fenced during and after drilling operations until pits are reclaimed so as to effectively keep out wildlife and livestock.

Office: RW ID: RW4327  
Unique INC #: ETF07-05 Well Name: AMERICAN BEAUTY ID Date: 11/29/07  
Well #: 4 Effective Date: 11/29/07  
Operator: QUESTAR EXPL AND PRODUCTION CO Abatement Date: 11/30/07  
Case #: WYW159695 FAC ID: Corrected Date: 07/23/08  
Form: I FAC NAME: Followup Date: 07/23/08  
Assessment: \$0 Inspector: FAZENDIN Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III.A.2.b.i  
  
Remarks Date: 11/29/07

Operator needs to have an approved Sundry notice on hand for the use of Co-Flex choke line hoses.

Office: RW ID: RW4339  
Unique INC #: ETF07-06 Well Name: ZIRCON FEDERAL ID Date: 12/12/07  
Well #: 22-6 Effective Date: 12/12/07  
Operator: TRUE OIL LLC Abatement Date: 12/13/07  
Case #: WYW164935 FAC ID: Corrected Date: 12/19/07  
Form: I FAC NAME: Followup Date: 12/21/07  
Assessment: \$0 Inspector: FAZENDIN Extend Date:  
Gravity: 3  
Authority Ref: OO2.III.A.2.b.i  
  
Remarks Date: 12/12/07

Operator needs to have an approved Sundry notice on hand for the use of Co-Flex choke line hoses.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: RW ID: RW4425  
Unique INC #: ML08006I Well Name: HORSESHOE RIDGE FEDERAL  
Well #: 12-1 ID Date: 07/15/08  
Operator: RICHARDSON OPERATING COMPANY Effective Date: 07/17/08  
Case #: WYW173550 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LYON Abatement Date: 08/15/08  
Gravity: 3 Corrected Date: 07/15/08  
Authority Ref: COA'S Followup Date: 07/16/08  
Extend Date:

Remarks Date: 07/15/08

No fence around the reserve pit.

Office: RW ID: RW3927  
Unique INC #: AW-108-06 Well Name: BROWN COW II AR FED 1491  
Well #: 15-11 ID Date: 10/24/06  
Operator: ANADARKO E & P COMPANY LP Effective Date: 10/24/06  
Case #: WYW156218X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE Abatement Date: 10/25/06  
Gravity: 1 Corrected Date: 10/26/07  
Authority Ref: OO#2 III C. 7. Followup Date: 05/25/07  
Extend Date:

Remarks Date: 10/24/06

The flare line is much less than 100 feet from the well head. The flare line is not positioned down wind of the prevailing wind direction. And is not anchored. Please correct.

Office: RW ID: RW4333  
Unique INC #: AW30-07 Well Name: FERRIS  
Well #: 1-1H ID Date: 12/06/07  
Operator: CONTINENTAL PRODUCTION COMPANY Effective Date: 12/06/07  
Case #: WYW172750 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE Abatement Date: 12/07/07  
Gravity: 3 Corrected Date: 12/08/07  
Authority Ref: OO#2.III.A.2.g. Followup Date: 12/27/07  
Extend Date:

Remarks Date: 12/06/07

No valve on closing side of annular preventer.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: RW ID: RW4331  
Unique INC #: AW28-07 Well Name: FERRIS ID Date: 12/06/07  
Well #: 1-1H Effective Date: 12/06/07  
Operator: CONTINENTAL PRODUCTION COMPANY Abatement Date: 12/07/07  
Case #: WYW172750 FAC ID: Corrected Date: 12/09/07  
Form: I FAC NAME: Followup Date: 12/27/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 1  
Authority Ref: OO#2.III.C.7.

Remarks Date: 12/06/07

Flare lines not installed.

Office: RW ID: RW4332  
Unique INC #: AW29-07 Well Name: FERRIS ID Date: 12/06/07  
Well #: 1-1H Effective Date: 12/06/07  
Operator: CONTINENTAL PRODUCTION COMPANY Abatement Date: 12/07/07  
Case #: WYW172750 FAC ID: Corrected Date: 12/08/07  
Form: I FAC NAME: Followup Date: 12/08/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: OO#2.III.A.2.a.iii.

Remarks Date: 12/06/07

No pressure guage on choke manifold.

Office: RW ID: RW4330  
Unique INC #: AW27-07 Well Name: FERRIS ID Date: 12/06/07  
Well #: 1-1H Effective Date: 12/06/07  
Operator: CONTINENTAL PRODUCTION COMPANY Abatement Date: 12/30/07  
Case #: WYW172750 FAC ID: Corrected Date: 12/08/07  
Form: I FAC NAME: Followup Date: 12/27/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: COA

Remarks Date: 12/06/07

Flare pit not fenced.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: RW		ID: RW4300
Unique INC #: AW26-07	Well Name: COAL GULCH	
	Well #: 12-20	ID Date: 11/26/07
Operator: DEVON ENERGY PRODUCTION CO LP		Effective Date: 11/26/07
Case #: WYW7174	FAC ID:	Abatement Date: 12/31/07
Form: I	FAC NAME:	Corrected Date: 12/04/07
Assessment: \$0	Inspector: WHITE	Followup Date: 12/05/07
Gravity: 3		Extend Date:
Authority Ref: COA		

Remarks Date: 11/26/07

Trash on and around location.

Office: SL		ID: SL40
Unique INC #: 01RK2008	Well Name: FEDERAL	
	Well #: 23-44	ID Date: 01/02/08
Operator: DELTA PETROLEUM CORPORATION		Effective Date: 01/07/08
Case #: UTU82512	FAC ID:	Abatement Date: 01/19/08
Form: I	FAC NAME:	Corrected Date: 02/07/08
Assessment: \$0	Inspector: RANDY KNIGHT	Followup Date: 09/01/08
Gravity: 3		Extend Date:
Authority Ref: O.O.2.III.F		

Remarks Date: 01/02/08

Violation: According to Conditions of Approval Federal # 23-44 Surface Use Plan of Operations, Location of Existing and/or Proposed Facilities if Well is Productive; "all drilling activity, including removal of the drill rig, will be completed prior to January 1st deadline to protect the nesting habitat". Any well operations, other than those specifically identified in the surface use plan will not be carried out between January 1st and august 31st, unless approved by the Authorized officer. On a routine drilling inspection on January 2nd, I found that the drilling rig was still on location and drilling activities were being conducted. The requirements of the Conditions of Approval were not met and there was no extensions approved by an Authorized Officer. Corrective Action: Define a plan and time table to have all drilling activities ceased and drilling rig equipment removed from location. Also, inform an Authorized Officer of the Cedar City Field Office of this plan and any deviations that may arise. Abatement date may change in accordance to the Authorized Office of the Cedar City Field Office.

Office: SL		ID: SL43
Unique INC #: 54-WW-2008	Well Name: WOLVERINE FEDERAL	
	Well #: 17-13	ID Date: 07/15/08
Operator: WOLVERINE GAS & OIL CO OF UT		Effective Date: 07/22/08
Case #: UTU80800A	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 07/23/08
Assessment: \$0	Inspector: WALTON WILLIS	Followup Date: 07/23/08
Gravity: 3		Extend Date:
Authority Ref: OnShore Order #2.II.A.2.b.i.		

Remarks Date: 07/15/08

Choke Lines not fitted with Tee Blocks or running targeted tee's. Corrective Action: Install Targeted Tee's on Choke Lines,

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: SL ID: SL42  
Unique INC #: 55-WW-2008 Well Name: WOLVERINE FEDERAL  
Well #: 17-13 ID Date: 07/15/08  
Operator: WOLVERINE GAS & OIL CO OF UT Effective Date: 07/22/08  
Case #: UTU80800A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALTON WILLIS  
Gravity: 3  
Authority Ref: 43CFR 3162.6(b)

Remarks Date: 07/15/08

Violation: No Well Sign Corrective Action: Install Well Identification Sign.

Office: TU ID: iTU23919  
Unique INC #: 08WA136 Well Name:  
Well #: ID Date: 06/27/08  
Operator: PETCO PETROLEUM CORPORATION Effective Date: 06/28/08  
Case #: 21924 FAC ID: A, B, C Abatement Date: 07/26/08  
Form: I FAC NAME: MOSEART-US-SEE, MOSEARTUSEE, I Corrected Date: 07/26/08  
Assessment: \$0 Inspector: ALEX Followup Date: 09/24/08  
Gravity: 3 Extend Date: 10/10/08  
Authority Ref: NO AFMSS

Remarks Date: 06/27/08

NO AFMSS AT TIME

Office: VE ID: VE11974  
Unique INC #: AW08002 Well Name: NBU  
Well #: 920-25N ID Date: 10/31/07  
Operator: KERR MCGEE OIL & GAS ONSHORE L Effective Date: 11/01/07  
Case #: UTU63047A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ALAN WALKER Abatement Date: 11/07/07  
Gravity: 3  
Authority Ref: 43CFR3162.1.(a) Corrected Date: 11/07/07  
Followup Date: Extend Date:

Remarks Date: 11/01/07

APD natural Buttes Unit SOP surface use plan #7 requires the pit to be fenced. Fence the pit on the above named location by 11/7/07. Verbale notification was given to Lou Weldon on 11/1/2007.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: VE		ID: VE11973
Unique INC #: AW08001	Well Name: NBU	ID Date: 10/31/07
	Well #: 920-25N	Effective Date: 11/01/07
Operator: KERR MCGEE OIL & GAS ONSHORE L		Abatement Date: 11/07/07
Case #: UTU63047A	FAC ID:	Corrected Date: 11/07/07
Form: I	FAC NAME:	Followup Date:
Assessment: \$0	Inspector: ALAN WALKER	Extend Date:
Gravity: 3		
Authority Ref: 43CFR3162.6(a)		

Remarks Date: 11/01/07

Every well shall have a well identification sign. All signs shall be maintained in a legible condition. Install well sign by 11/7/07 Lou Weldon contacted by phone on 11/1/2007.

Office: VE		ID: VE12126
Unique INC #: CT08015	Well Name: FEDERAL	ID Date: 04/09/08
	Well #: 3-3-9-18	Effective Date: 06/10/08
Operator: NEWFIELD EXPLORATION COMPANY		Abatement Date: 06/10/08
Case #: UTU84229	FAC ID:	Corrected Date: 06/16/08
Form: I	FAC NAME:	Followup Date:
Assessment: \$500	Inspector: CADE TAYLOR	Extend Date:
Gravity: 1		
Authority Ref: 43 CFR 3163.1(b) (2); 43 CFR 3162.3-1(c) (d)		

Remarks Date: 04/09/08

THE APPROVED APD FOR THE ABOVE REFERENCED WELL EXPIRED ON 3/8/2008. THE CONSTRUCTION OF THE LOCATION BEGAN ON 4/8/2008 WITHOUT A PROPER EXTENSION BEING SUBMITTED. NEWFIELD MADE A CALL ON 4/9/2008 TO MICHEAL LEE (BLM PETROLEUM ENGINEER) MAKING HIM AWARE OF THE FACT. THE VIOLATION SHALL RESULT IN AN IMMEDIATE ASSESSMENT IN THE FOLLOWING SPECIFIED AMOUNT: FOR DRILLING WITHOUT A PROPER EXTENSION OF THE EXPIRED APD, \$500 PER DAY X 1 DAY = \$500.00. PLEASE SUBMIT ALL THE PROPER PAPERWORK FOR A APD EXTENSION

Office: VE		ID: VE11985
Unique INC #: JS08007	Well Name: FEDERAL	ID Date: 11/20/07
	Well #: 34-30-9-19	Effective Date: 11/20/07
Operator: GASCO PRODUCTION COMPANY		Abatement Date: 11/20/07
Case #: UTU37246	FAC ID:	Corrected Date: 11/22/07
Form: I	FAC NAME:	Followup Date:
Assessment: \$0	Inspector: JAMIE SPARGER	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.1 (a); APD COAs and Surface Use Plan		

Remarks Date: 11/20/07

Spud date is to be reported to this office 24 hours prior to spudding of the well. The well was spud 11/02/2007 in the am (?). Notice of spud was called in 11/20/2007 at 1135 hours - 17 days after spud. In the future, please notify this office of initial well spud as required, 24 hours prior to spud. Thank you.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: VE ID: VE11984  
Unique INC #: JS08006 Well Name: NORTH CHAPITA ID Date: 11/20/07  
Well #: 336-34 Effective Date: 11/20/07  
Operator: EOG RESOURCES INC Abatement Date: 11/20/07  
Case #: UTU43916 FAC ID: Corrected Date: 10/22/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); APD Surface Use Plan  
  
Remarks Date: 11/20/07

Operator called this office with information that the long string casing job began at 0630, 11/20/2007. Time of call was 1130, 11/20/2007- 5 hours after job start. This operation was rated high for subsurface resource protection and was supposed to have been witnessed by a BLM representative. As a reminder, you are required to notify this office 24 hour in ADVANCE of casing jobs. Thank you.

Office: VE ID: VE11967  
Unique INC #: JS08003 Well Name: FEDERAL ID Date: 10/27/07  
Well #: 8-19-9-16 Effective Date: 10/27/07  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date: 10/27/07  
Case #: UTU64379 FAC ID: Corrected Date: 10/29/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date: 10/29/07  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); APD COAs;  
  
Remarks Date: 10/27/07

Operator notified this office of surface casing job at 11:17 am, 10/27/07. Said job was scheduled to begin at 13:30 pm; 10/27/07. The operator is required to provide notification 24 hours prior to job start. Operator only provided notification less than 3 hours before job start.

Office: VE ID: VE11963  
Unique INC #: JS08001 Well Name: EAST CHAPITA ID Date: 10/18/07  
Well #: 14-23Z Effective Date: 10/18/07  
Operator: EOG RESOURCES INC Abatement Date: 10/18/07  
Case #: UTU67868 FAC ID: Corrected Date: 10/20/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 6162.1 (a); APD Surface Use Plan and COAs  
  
Remarks Date: 10/18/07

Operator failed to notify this office 24 hours in advance of running surface casing. Operator representative notified this office at the beginning of job. Well was rated High requiring BLM witness the casing job. Being notified late, we were not able to witness job. Please notify this office at least 24 hours in advance of all casing jobs as required.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: VE ID: VE11968  
Unique INC #: JS08004 Well Name: FEDERAL ID Date: 10/29/07  
Well #: 15-19-9-16 Effective Date: 10/29/07  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date:  
Case #: UTU74391 FAC ID: Corrected Date: 10/31/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); APD COAs  
  
Remarks Date: 10/29/07

Operator notified this office of surface casing job at 1059 hours, 10/29/2007. Said job was scheduled to begin at 1530 hours, 10/29/2007. The operator is required to provide notification 24 hours prior to job start. Operator provided notification less than 5 hours before job start.

Office: VE ID: VE11964  
Unique INC #: JS08002 Well Name: LONE TREE FEDERAL ID Date: 10/18/07  
Well #: 13-22-9-17 Effective Date: 10/18/07  
Operator: NEWFIELD EXPLORATION COMPANY Abatement Date:  
Case #: UTU77236X FAC ID: Corrected Date: 10/20/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); APD COAs; Monument Butte SOP  
  
Remarks Date: 10/18/07

Operator notified this office of the start of the surface casing job at 0928 hours on 10.18.2007. Job was reported to start at 1300 hours on 10.18.2007. Operator is required to notify this office at least 24 hours in advance of all casing jobs. Being notified less than 4 hours before job start does not equal 24 hours. In the future, please notify this office at least 24 hours in advance of all casing jobs (the start of casing going in the hole.) as required. Thank you.

Office: VE ID: VE11995  
Unique INC #: JS08008 Well Name: TU ID Date: 12/31/07  
Well #: 3-35-7-21 Effective Date: 12/31/07  
Operator: QUESTAR EXPL & PROD COMPANY Abatement Date: 12/31/07  
Case #: UTU85843X FAC ID: Corrected Date: 12/31/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Order #1, IV.; APD and Sundry Notice Drilling Plans & COAs  
  
Remarks Date: 12/31/07

Well is not being drilled in compliance with the Drilling Plan of the Sundry Notice approved 12/07/2007 and the APD approved 05/18/2007. The intermediate portion of the well is being drilled using air drilling operations without approval. The approved Drilling Plan requires the intermediate section of the well to be drilled with a water based drilling fluid. The operator shall stop all air drilling operations and comply with the water based drilling fluid requirements of the Drilling Plan. [During inspection of 12/31/2007, operator had discontinued the air drilling operation and was preparing to drill the remaining portion of the intermediate hole with a water based drilling fluid, as required, thereby correcting this Notice of Incidents of Noncompliance.]

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: VE		ID: VE11991
Unique INC #: JPB08005	Well Name: FEDERAL	
	Well #: 1022-33B	ID Date: 12/10/07
Operator: KERR MCGEE OIL & GAS ONSHORE L		Effective Date: 12/14/07
Case #: UTU037166	FAC ID:	Abatement Date: 12/14/07
Form: I	FAC NAME:	Corrected Date: 12/12/07
Assessment: \$0	Inspector: JOHNNY BOWEN	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a); APD, COA'S, SOP		

Remarks Date: 12/10/07

Operator failed to notify Vernal feild office of a surface casing job. Operator is required to provide notification 24 hours prior to job start. This surface casing job was rated high and was supposed to have been witnessed by a BLM representative. Please provide 24 hour notification.

Office: VE		ID: VE12104
Unique INC #: CRB08046	Well Name: FEDERAL	
	Well #: 32-19-9-19	ID Date: 05/21/08
Operator: GASCO PRODUCTION COMPANY		Effective Date: 05/23/08
Case #: UTU76033	FAC ID:	Abatement Date: 06/13/08
Form: I	FAC NAME:	Corrected Date: 06/10/08
Assessment: \$5,000	Inspector: RANDY BYWATER	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1 (b) (2) 43 CFR 3162.3-1(c) (d)		

Remarks Date: 05/21/08

Upon discovery, the following violation shall result in immediate assessments, which is retroactive, in the following specified amount: For drilling without approval, \$500 per day X 10 days = \$5000.00. Please submit an APD.

Office: WO		ID: WO2440
Unique INC #: 08-OL-13	Well Name: GOOSEBERRY B	
	Well #: 32-22	ID Date: 09/29/08
Operator: ENCORE OPERATING LP		Effective Date: 09/29/08
Case #: WYW109527B	FAC ID:	Abatement Date: 09/30/08
Form: I	FAC NAME:	Corrected Date: 09/30/08
Assessment: \$0	Inspector: LEAR	Followup Date: 10/06/08
Gravity: 3		Extend Date:
Authority Ref: OO III.A. 1.		

Remarks Date: 09/29/08

No hand wheel on Kill line valve. In stall with in 24hrs.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: WO ID: WO2441  
Unique INC #: 08-OL-14 Well Name: GOOSEBERRY B ID Date: 09/29/08  
Well #: 32-22 Effective Date: 09/29/08  
Operator: ENCORE OPERATING LP Abatement Date: 09/30/08  
Case #: WYW109527B FAC ID: Corrected Date: 09/30/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OO III.A.2.e.  
  
Remarks Date: 09/29/08  
Power to Closing unit is off.

Office: WO ID: WO2439  
Unique INC #: 08-OL-12 Well Name: GOOSEBERRY B ID Date: 09/29/08  
Well #: 32-22 Effective Date: 09/29/08  
Operator: ENCORE OPERATING LP Abatement Date: 09/30/08  
Case #: WYW109527B FAC ID: Corrected Date: 09/30/08  
Form: I FAC NAME: Followup Date: 10/06/08  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OOIII.A.2.g.  
  
Remarks Date: 09/29/08  
No locking hand wheel on BOP (pipe rams) 24hrs to in stall.

Office: WO ID: WO2406  
Unique INC #: 08-OL-06 Well Name: MEETEETSE CA FRMD ID Date: 02/26/08  
Well #: 5-13-4999 Effective Date: 02/26/08  
Operator: SAGA PETROLEUM Abatement Date: 02/27/08  
Case #: WYW176060 FAC ID: Corrected Date: 02/28/08  
Form: I FAC NAME: Followup Date: 02/28/08  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III.C. 7.

Remarks Date: 02/26/08  
Flair lines not anchored. Anchore within 24hrs.

Safety and Drilling Related Violations (INCs) Issued During FY 2008  
As of March 3, 2011

Office: WO ID: WO2405  
Unique INC #: 08-OL-05 Well Name: MEETEETSE CA FRMD ID Date: 02/26/08  
Well #: 5-13-4999 Effective Date: 02/26/08  
Operator: SAGA PETROLEUM Abatement Date: 02/27/08  
Case #: WYW176060 FAC ID: Corrected Date: 02/28/08  
Form: I FAC NAME: Followup Date: 04/18/08  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III.A.1.

Remarks Date: 02/26/08

No handles on Kill line Valve and Choke line Valve. 24hrs. to install.

Office: WO ID: WO2404  
Unique INC #: 08-OL-04 Well Name: MEETEETSE CA FRMD ID Date: 02/26/08  
Well #: 5-13-4999 Effective Date: 02/26/08  
Operator: SAGA PETROLEUM Abatement Date: 02/27/08  
Case #: WYW176060 FAC ID: Corrected Date: 02/28/08  
Form: I FAC NAME: Followup Date: 02/28/08  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III. A. 2. g.

Remarks Date: 02/26/08

No locking wheels on BOP, 24hrs to in stall.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: BA ID: BA2416  
Unique INC #: 05-008-07I Well Name: USL ID Date: 12/12/06  
Well #: 66 Effective Date: 12/12/06  
Operator: CHEVRON U S A INCORPORATED Abatement Date: 12/13/06  
Case #: CAS037494 FAC ID: Corrected Date: 12/13/06  
Form: I FAC NAME: Followup Date: 12/14/06  
Assessment: \$0 Inspector: 5 GARNAND G Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 12/12/06

Incident of noncompliance has been issued for not having a remote control on rig floor. Operator must install remote control on rig floor on or before 12-13-06. Sign INC and return to Bakersfield field office.

Office: BU ID: BU10702  
Unique INC #: MB-07-2 Well Name: HOMESTEAD DRAW I MANIGAULT ID Date: 10/17/06  
Well #: 5CKW-19 Effective Date: 10/19/06  
Operator: THE TERMO COMPANY Abatement Date: 10/29/06  
Case #: WYW043718 FAC ID: Corrected Date: 10/26/06  
Form: I FAC NAME: Followup Date: 10/31/06  
Assessment: \$0 Inspector: BLAKESLEY Extend Date:  
Gravity: 3  
Authority Ref: COA's

Remarks Date: 10/17/06

Failure to follow item 4. B. d, of Drilling Prognosis in the Homestead Draw POD. You cemented your production string in an unapproved manner. Specifically: You failed to leave a 40' cement shoe in the production casing after the cement was displaced.

Office: BU ID: BU10704  
Unique INC #: MB-07-4 Well Name: HOMESTEAD DRAW I MANIGAULT ID Date: 10/17/06  
Well #: 5CKW-19 Effective Date: 10/19/06  
Operator: THE TERMO COMPANY Abatement Date: 10/29/06  
Case #: WYW043718 FAC ID: Corrected Date: 10/26/06  
Form: I FAC NAME: Followup Date: 10/31/06  
Assessment: \$0 Inspector: BLAKESLEY Extend Date:  
Gravity: 3  
Authority Ref: COA's

Remarks Date: 10/17/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Failure to follow the Drilling Prognosis of Homestead Draw POD. Specifically: You mixed an unapproved source of water with the cement and could not supply a water analysis at the time of cementing. Correction: You are required to use an approved water source or supply this office with a request for change of plan for the new water source including a water quality analysis.

Office: BU		ID: BU10703
Unique INC #: MB-07-3	Well Name: HOMESTEAD DRAW I MANIGAULT	
	Well #: 5CKW-19	
Operator: THE TERMO COMPANY		
Case #: WYW043718	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: COA's		

Remarks Date: 10/17/06

Failure to follow Drilling Prognosis item 4. B, proposed casing and cementing in the Homestead Draw POD. Specifically: You have run a burst sub in the casing string without approval. Correction: Submit a request (change plan) for correct equipment in production string for the Homestead Draw 1 POD.

Office: BU		ID: BU10740
Unique INC #: MB-07-10	Well Name: STRIPE LX BAR CS	
	Well #: 19	
Operator: YATES PETROLEUM CORP		
Case #: WYW108596	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: COA's		

Remarks Date: 10/26/06

Failure to follow Conditions of Approval (COA) of the Surface Use Plan of Strip Plan of Development (POD) page 8, item #9 well site layout. Specifically, the drilling pit is 18 feet from the well bore. Corrective Action: On all future wells you are required to have at least 30 feet from the well bore to the nearest edge of the pit.

Office: BU		ID: BU10706
Unique INC #: MB-07-6	Well Name: DUGOUT DRAW	
	Well #: 32LC-2843	
Operator: THOMAS OPERATING COMPANY, INC		
Case #: WYW135601	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: COS's		

Remarks Date: 10/19/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Your pits are 21' 10" from the well bore. The closest edge of any pit must be at least 30" from the well bore.

Office: BU		ID: BU10705
Unique INC #: MB-07-5	Well Name: DUGOUT DRAW	
	Well #: 32LC-2843	
Operator: THOMAS OPERATING COMPANY, INC		
Case #: WYW135601	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 01/19/06

Your well sign is incorrect. You must install a well sign that includes the following: Operators name, well name, legal description, and the lease number. All signs must be maintained in a legible condition and shall be apparent to any person approaching the well site.

Office: BU		ID: BU10761
Unique INC #: MB-07-11	Well Name: SCRIBNER	
	Well #: 24-3	
Operator: BALLARD PETROLEUM HOLDINGS LLC		
Case #: WYW140197	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 1		
Authority Ref: OSO#2,III.A.2.e.		

Remarks Date: 11/08/06

Failure to comply with OSO#2,III.A.2.e. Specifically: the power to the air jammers was shut off. Corrective Action: maintain power to the power system for the unit at all times so the pumps will automatically start when the closing valve manifold pressure has decreased to the pre-set level.

Office: BU		ID: BU10701
Unique INC #: MB-07-1	Well Name: PLATEAU CS	
	Well #: 6	
Operator: YATES PETROLEUM CORP		
Case #: WYW145611	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: COA's		

Remarks Date: 10/18/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Failure to follow item 4, under the Drilling Plan of the Plateau POD. Specifically: You have failed to submit a water quality analysis for a non-municipal, cementing water source. Correction: Submit a copy of the water quality analysis for the intended non-municipal water source.

Office: BU		ID: BU12369
Unique INC #: MB-07-37	Well Name: BCU EPSILON KNUDSON	
	Well #: 21-11	
Operator: LANCE OIL + GAS CO INC		ID Date: 08/06/07
Case #: WYW149551X	FAC ID:	Effective Date: 08/07/07
Form: I	FAC NAME:	Abatement Date: 08/14/07
Assessment: \$0	Inspector: BLAKESLEY	Corrected Date: 08/14/07
Gravity: 3		Followup Date: 09/04/07
Authority Ref: BFO COA'S		Extend Date:

Remarks Date: 08/06/07

The diverter line is not 30' in length. The diverter line must be 30' in length.

Office: BU		ID: BU12370
Unique INC #: MB-07-38	Well Name: BCU EPSILON KNUDSON	
	Well #: 21-11	
Operator: LANCE OIL + GAS CO INC		ID Date: 08/06/07
Case #: WYW149551X	FAC ID:	Effective Date: 08/07/07
Form: I	FAC NAME:	Abatement Date: 08/09/07
Assessment: \$0	Inspector: BLAKESLEY	Corrected Date: 08/09/07
Gravity: 3		Followup Date: 09/04/07
Authority Ref: 43 CFR 3162.6(a)		Extend Date:

Remarks Date: 08/06/07

There is no well sign on location. The operator shall properly identify each well, by a sign in a conspicuous place. The sign shall include the well number, operator name, lease number, the 1/4 1/4 section, township, and range, the county and state.

Office: BU		ID: BU10881
Unique INC #: MB-07-15	Well Name: HORSE CREEK C FEDERAL	
	Well #: W34-13-43	
Operator: WINDSOR ENERGY GROUP LLC		ID Date: 12/22/06
Case #: WYW4758	FAC ID:	Effective Date: 12/28/06
Form: I	FAC NAME:	Abatement Date: 12/29/06
Assessment: \$0	Inspector: BLAKESLEY	Corrected Date: 12/29/06
Gravity: 3		Followup Date:
Authority Ref: COA's		Extend Date:

Remarks Date: 12/22/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Your mud pits are not 30' from the well bore. Your nearest pit must be at least 30' from the well bore.

Office: BU		ID: BU10529
Unique INC #: KB/06/37	Well Name: BOX ELDER REMU FED	
	Well #: 24-09CK	
Operator: NANCE PETROLEUM CORP		
Case #: WYW160315A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$1,000	Inspector: BRYCE	
Gravity: 1		
Authority Ref: 43 CFR 3162.3-1 (c)		

Remarks Date: 08/31/06

The 24-09 CK well was drilled on a location that was not permitted. Corrective action: You have already submitted a sundry to move the location.

Office: BU		ID: BU10837
Unique INC #: DC07-008	Well Name: SLPU FED	
	Well #: 41-25H	
Operator: EL PASO E&P CO LP		
Case #: WYW133611	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 1		
Authority Ref: On Shore Oil and Gas Order No. 2, III., C., 7.		

Remarks Date: 12/12/06

A rig inspection of 12/12/06 showed that the flare line did not have an effective method for ignition. Corrective Action: Provide an effective method for ignition at the flare line. This was corrected within an hour of notice of this violation.

Office: BU		ID: BU10836
Unique INC #: DC07-007	Well Name: SLPU FED	
	Well #: 41-25H	
Operator: EL PASO E&P CO LP		
Case #: WYW133611	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 1		
Authority Ref: On Shore Oil and Gas Order No. 2, III., C., 7.		

Remarks Date: 12/12/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

A rig inspection of 12/12/06 showed that the flare line was not complete. The end length of the flare line was not connected to the rest of the line. The flare line discharge shall be located not less than 100 feet from the well head. Corrective Action: Connect the last length of flare line. This was corrected within an hour of notice of this violation.

Office: BU		ID: BU10835
Unique INC #: DC07-006	Well Name: SLPU FED	
	Well #: 41-25H	
Operator: EL PASO E&P CO LP		
Case #: WYW133611	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 1		
Authority Ref: On Shore Oil and Gas Order No. 2, III., A., 1.		

Remarks Date: 12/12/06

A rig inspection of 12/12/06 showed that the inside kill line valve did not have a valve handle. Blowout preventer equipment shall be maintained in a manner necessary to assure well control and shall be in place and operational prior to drill out of the casing shoe. Corrective Action: Install valve handle on inside kill line valve. The Inspector witnessed the immediate installation of the valve handle.

Office: BU		ID: BU10893
Unique INC #: DC07-010	Well Name: WEST BEAR DRAW TEAR DROP	
	Well #: 32-21	
Operator: LANCE OIL + GAS CO INC		
Case #: WYW137303	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Surface Use Conditions of Approval		

Remarks Date: 01/09/07

Fencing at the north end of the pit at this location is laying down. Fencing on the east side of the pit goes over a cut in the pit, allowing access to the pit under the fence. Pits will be adequately fenced during and after drilling operations until pit is reclaimed so as to effectively keep out wildlife and livestock. Corrective action: Adequately fence the pit.

Office: BU		ID: BU12509
Unique INC #: DC07-050	Well Name: CRAZY WOMAN S FEDERAL CHRISTIA	
	Well #: 23-28	
Operator: BLACK DIAMOND ENERGY INC		
Case #: WYW140488	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Surface Use Conditions of Approval		

Remarks Date: 09/18/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Fencing on the side of the pit nearest the well bore goes over a cut in the pit, allowing access to the pit under the fence. Pits will be adequately fenced during and after drilling operations until pit is reclaimed so as to effectively keep out wildlife and livestock. Corrective action: Adequately fence the pit. Red Lufkin was informed of this on 9/18/07 at 1530.

Office: BU		ID: BU12510
Unique INC #: DC07-051	Well Name: CRAZY WOMAN S CHRISTIAN	
	Well #: 12-28	
Operator: BLACK DIAMOND ENERGY INC		
Case #: WYW140488	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 1		
Authority Ref: Onshore Oil and Gas Order No.2, III., A., 1.		

Remarks Date: 09/18/07

The rig on this location was drilling at 1300' and the diverter was not sealing, allowing spillage of fluids. The diverter shall be installed, used and maintained in a manner necessary to assure well control. Corrective action: Provide a diverter that seals before drilling to TD. Red Lufkin was informed of this via phone at 1530 on 9/18/07.

Office: BU		ID: BU10679
Unique INC #: DC07-002	Well Name: BIG BEND I FEDERAL	
	Well #: 15-26	
Operator: NORTH FINN, LLC		
Case #: WYW146860	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: 43 CFR, Subpart 3162.6, (b)		

Remarks Date: 10/02/06

The well identification sign at this well has an incorrect Federal Lease Number. Corrective Action: Change the Federal Lease Number on the well identification sign to read 'WYW146860'.

Office: BU		ID: BU10678
Unique INC #: DC07-001	Well Name: BIG BEND I FEDERAL	
	Well #: 15-26	
Operator: NORTH FINN, LLC		
Case #: WYW146860	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Conditions of Approval		

Remarks Date: 10/02/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

This Office did not receive notice of spudding this well. Conditions of Approval require notification 24 hours prior to spudding. Corrective Action: This was discussed via phone on 10/5/06 with Neal Neumiller who called the spud into the Buffalo Field Office within 10 minutes.

Office: BU ID: BU10879  
Unique INC #: DC07-009 Well Name: WHISKEY DRAW UNIT 1 WDU  
Well #: 32-18BG ID Date: 12/21/06  
Operator: LANCE OIL + GAS CO INC Effective Date: 01/08/07  
Case #: WYW148368X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CORK Abatement Date: 01/16/07  
Gravity: 3 Followup Date: 01/03/07  
Authority Ref: Surface Use Conditions of Approval Extend Date: 01/18/07

Remarks Date: 12/21/06

20' of fencing at the front of the pit at this location is down, allowing access to the pit. (See attached photograph) Pits will be adequately fenced during and after drilling operations until pit is reclaimed so as to effectively keep out wildlife and livestock. Corrective action: Adequately fence the pit or reclaim it.

Office: BU ID: BU12357  
Unique INC #: CF-07-025 Well Name: DRY WILLOW 2 T-CHAIR  
Well #: 11-32 ID Date: 07/30/07  
Operator: ANADARKO PETROLEUM CORP Effective Date: 07/31/07  
Case #: WYW144531 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FREISE Abatement Date: 07/31/07  
Gravity: 3 Followup Date: Extend Date:  
Authority Ref: 43 CFR 3162.5-1(a)

Remarks Date: 08/02/07

THE OPERATOR FAILED TO COMPLY WITH WILDLIFE SITE SPECIFIC CONDITION OF APPROVAL #2 "NO SURFACE DISTURBING ACTIVITY SHALL OCCUR WITHIN 1/2 MILE OF ALL IDENTIFIED RAPTOR NESTS FROM FEBRUARY 1 THROUGH JULY 31, ANNUALLY, PRIOR TO A RAPTOR NEST OCCUPANCY SURVEY FOR THE CURRENT BREEDING SEASON". THE RELEASE FOR INACTIVE NESTS WAS REQUESTED FOR THIS POD; THIS WELL WAS NOT RELEASED FROM THE STIPULATION DUE TO ACTIVE NESTS. ANY OTHER WELLS DRILLED ON LEASE WYW144531 WITHIN A WILDLIFE TIMING STIPULATION WILL RESULT IN AN AUTOMATIC ASSESSMENT.

Office: BU ID: BU10833  
Unique INC #: DEG-62-06 Well Name: TWENTY MILE CREEK EATON  
Well #: 13-23CA ID Date: 12/12/06  
Operator: PETRO-CANADA RES (USA) INC Effective Date: 12/19/06  
Case #: WYW139677 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: GEYER Abatement Date: 01/12/07  
Gravity: 3 Followup Date: Extend Date:  
Authority Ref: 43CFR3162.3-2(a)

Remarks Date: 12/12/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

CERTIFIED MAIL No. 70041160000519655725 Return Receipt Requested Petro-Canada Resources (USA) INC Attn: Janny Gregson 3801 N. HWY 14-16 Gillette, WY 82716 RE: Eaton Fed 13-23CO, WYW139677, SWNW Sec.13 T52N R75W Fed 24-21CO, WYW31786, NENW Sec.24 T51N R75W Love Fed 12-31CO, WYW146810, NESW Sec.12 T50N R75W FED11-11CO, WYW138612, NENE Sec.11 T52N R75W Gentlemen: 43CFR3162.3-2(a) states that a proposal for further well operations shall be submitted by the operator on Form 3160-5 for approval by the authorized officer prior to commencing operations to plug-back. On 4/3/2006 the Buffalo Field Office (BFO) received a separate subsequent report of plugging back each of the referenced wells; however, a Notice of Intent (NOI) was not submitted to the BFO and an oral approval was never granted for the plug-back done from the Wall to the Cook coal seam. Therefore, this is an issuance of an Incident of Noncompliance (INC). In order to comply with this INC, Petro-Canada shall submit a NOI, for each of the referenced wells, giving detail of the plug-back (e.g. cement volume, class, density and plug-back depth) by 1/12/2007. The subsequent reports that were submitted for these wells on 4/3/2006 are denied due to insufficient information. These subsequent reports will need to identify detail of the plug-back (e.g. cement volume, class, density and plug-back depth) and the top and bottom depths of the Wall and Cook coal seams as well as the perforations. Additionally, an updated well completion report will need to be submitted. If you fail to submit the required information in the time specified, you will be liable for an assessment of \$250.00 under 43 CFR 3163.1(a)(2), and additional enforcement actions may be required. Warning Each violation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management Office at the address shown above. Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 day Review and Appeal Rights. A person contesting a decision shall request a State Director review of the Incidents of Noncompliance. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 4015 Wilson Blvd., Arlington, VA 22203 (see 43 CFR 3165.4). If you have any questions concerning this matter, please contact Dane Geyer at 307-684-1157. Sincerely, Chris Hanson Field Mana

Office: BU		ID: BU10608
Unique INC #: MH0659	Well Name: SAVAGETON 4 PUMPKIN BUTTES RCH	
	Well #: 21-19BG	ID Date: 09/27/06
Operator: LANCE OIL + GAS CO INC		Effective Date: 09/27/06
Case #: WYW145136	FAC ID:	Abatement Date: 10/26/06
Form: I	FAC NAME:	Corrected Date: 10/04/06
Assessment: \$0	Inspector: HAINES	Followup Date: 10/16/06
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 09/27/06

You have failed to comply with the Conditions of Approval in The Plan Of Development ( POD ) for failure to give the Buffalo Field Office 24 hour notice prior to spudding this well. You shall give the Buffalo Field Office 24 hours notice before spudding any wells in the future. If there are any questios, contact Mark Haines at 307-684-1065 or Darrel Cork at 307 - 684 -1054.

Office: BU		ID: BU12507
Unique INC #: MH0730	Well Name: CEDAR DRAW UNIT 2 CDU	
	Well #: 42-20WG	ID Date: 09/18/07
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 09/18/07
Case #: WYW148838X	FAC ID:	Abatement Date: 09/19/07
Form: I	FAC NAME:	Corrected Date: 09/20/07
Assessment: \$0	Inspector: HAINES	Followup Date: 09/20/07
Gravity: 1		Extend Date:
Authority Ref: Coditions of Approval		

Remarks Date: 09/18/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Violation : Diverter did not have lid or rubbers in place, so the Diverter was not in working order to control the well. I contacted Pete Peterson , Williams 's Drilling consultant and told him they had 24 hours to correct this problem. Correction: Put Diverter in good working order.

Office: BU ID: BU10731  
Unique INC #: MH0706 Well Name: BETA 2 ADD BGU  
Well #: 21-23 ID Date: 10/25/06  
Operator: ANADARKO PETROLEUM CORP Effective Date: 10/25/06  
Case #: WYW149537A FAC ID: Abatement Date: 11/22/06  
Form: I FAC NAME: Corrected Date: 11/29/06  
Assessment: \$0 Inspector: HAINES Followup Date: 11/29/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 10/25/06

During a review of our records, it was found that a 24-hour notice of spudding was not called into the Buffalo Field Office. You shall call the BFO 24 hours in advance before commencing any drilling operations. If you fail to comply with the Conditions of Approval, you could be subject to penalties under 46 CFR 3162.1(a). If there are any questions, contact Mark haines at 307-684-1065.

Office: BU ID: BU10725  
Unique INC #: MH0701 Well Name: KFC S BAR  
Well #: 14-18FAW ID Date: 10/24/06  
Operator: EMERALD OPERATING COMPANY Effective Date: 10/25/06  
Case #: WYW49874 FAC ID: Abatement Date: 11/22/06  
Form: I FAC NAME: Corrected Date: 11/28/06  
Assessment: \$0 Inspector: HAINES Followup Date: 11/28/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6 (a) (b)

Remarks Date: 10/24/06

During a field inspection it was found that there not a well sign installed . You shall install a porper well sign, as stated in 43 CFR 3162.6(b). If there are any questions contact Mark Haines at 307-684-1065.

Office: BU ID: BU10727  
Unique INC #: MH0703 Well Name: KFC S BAR  
Well #: 32-19FAW ID Date: 10/24/06  
Operator: EMERALD OPERATING COMPANY Effective Date: 10/25/06  
Case #: WYW49874 FAC ID: Abatement Date: 11/22/06  
Form: I FAC NAME: Corrected Date: 10/26/06  
Assessment: \$0 Inspector: HAINES Followup Date: 10/26/06  
Gravity: 1 Extend Date: 10/26/06  
Authority Ref: Conditions of Approval

Remarks Date: 10/24/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

During the field inspection, it was found that there was not 2 feet of free-board in the reserve pit as approved in the Conditions of Approval in the POD. I contacted Ralph Chaney regarding this INC. You shall maintain 2 feet of free-board in all reserve pits at all times during the drilling operation. If there are any questions, please contact Mark Haines at 307-684-1065.

Office: BU ID: BU10729  
Unique INC #: MH0704 Well Name: KFC S BAR  
Well #: 21-19FAW ID Date: 10/24/06  
Operator: EMERALD OPERATING COMPANY Effective Date: 10/25/06  
Case #: WYW49874 FAC ID: Abatement Date: 10/26/06  
Form: I FAC NAME: Corrected Date: 10/26/06  
Assessment: \$0 Inspector: HAINES Followup Date: 10/26/06  
Gravity: 1 Extend Date:  
Authority Ref: conditions of Approval

Remarks Date: 10/24/06

During the field inspection, it was found that the reserve pit did not have 2 feet of free-board. You shall maintain 2 feet of free-board in the reserve pit at all times during the drilling operations. I contacted Ralph Chaney, and I notified him of this Incidents of Noncompliance. If there are any questions, please contact Mark Haines at 307-684-1065.

Office: BU ID: BU10726  
Unique INC #: MH0702 Well Name: KFC S BAR  
Well #: 32-19FAW ID Date: 10/24/03  
Operator: EMERALD OPERATING COMPANY Effective Date: 10/25/06  
Case #: WYW49874 FAC ID: Abatement Date: 11/22/06  
Form: I FAC NAME: Corrected Date: 11/28/06  
Assessment: \$0 Inspector: HAINES Followup Date: 11/28/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR3162.6(a) (b)

Remarks Date: 10/24/03

During the field inspection, it was found that the drilling site was not properly identified. You shall install a well sign according to 43 CFR 3162.6(b). If there are any questions, please contact Mark Haines at 307-684-1065.

Office: BU ID: BU10730  
Unique INC #: MH0705 Well Name: KFC S BAR  
Well #: 21-19FAW ID Date: 10/24/06  
Operator: EMERALD OPERATING COMPANY Effective Date: 10/25/06  
Case #: WYW49874 FAC ID: Abatement Date: 10/26/06  
Form: I FAC NAME: Corrected Date: 11/28/06  
Assessment: \$0 Inspector: HAINES Followup Date: 11/28/06  
Gravity: 1 Extend Date:  
Authority Ref: Conditions of approval

Remarks Date: 10/24/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

During the field inspection, it was found that the reserve pit was not fenced as approved in the Conditions of Approval for the POD. You shall fence the pit. I contacted Ralph Chaney regarding this IINC. You shall fence all future reserve pits, after they are dug, as approved in the POD Conditions of Approval. If there are any questions, please contact Mark Haines at 307-684-1065.

Office: BU		ID: BU10945
Unique INC #: KAK07001	Well Name: TREND	
	Well #: 13-18	
Operator: TREND EXPLORATION I, LLC		
Case #: WYW145538	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KASPRZYK	
Gravity: 3		
Authority Ref: OO2.III.A.1		

Remarks Date: 01/31/07

Failure to maintain BOP equipment in a manner necessary to assure well control. BOPE shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. SPECIFICALLY - Master controls are locked in the neutral position, making the remote control inoperable. CORRECTIVE ACTION: Remove locks from master controls.

Office: BU		ID: BU10947
Unique INC #: KAK07002	Well Name: TREND	
	Well #: 13-18	
Operator: TREND EXPLORATION I, LLC		
Case #: WYW145538	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KASPRZYK	
Gravity: 3		
Authority Ref: OO2.III.B.1.i		

Remarks Date: 01/31/07

Failure to perform the casing shoe pressure integrity test. CORRECTIVE ACTION: On future holes, perform the specified test when required.

Office: BU		ID: BU10951
Unique INC #: KAK07003	Well Name: TREND	
	Well #: 13-18	
Operator: TREND EXPLORATION I, LLC		
Case #: WYW145538	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KASPRZYK	
Gravity: 3		
Authority Ref: OO2.III.A.1.		

Remarks Date: 01/31/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Failure to install BOP related equipment. SPECIFICALLY: Kill line was not hooked up. CORRECTIVE ACTION: Hook up kill line

Office: BU ID: BU10961  
Unique INC #: KAK07004 Well Name: SCHOONOVER RD 5 SRU  
Well #: 34-11 ID Date: 02/06/07  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 02/06/07  
Case #: WYW148333X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KASPRZYK  
Gravity: 3  
Authority Ref: 43CFR3162-1(a)  
Abatement Date: 02/09/07  
Corrected Date: 02/09/07  
Followup Date: 02/09/07  
Extend Date:

Remarks Date: 02/06/07

Failure to comply with Conditions of Approval. Specifically - Wildlife, paragraph #2 Corrective Action: leave the hole and location in a secure and environmentally sound condition; vacate location.

Office: BU ID: BU10963  
Unique INC #: KAK07006 Well Name: SCHOONOVER RD 5 SRU  
Well #: 43-13 ID Date: 02/06/07  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 02/06/07  
Case #: WYW148333X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KASPRZYK  
Gravity: 3  
Authority Ref: 43CFR3162.1(a)  
Abatement Date: 02/09/07  
Corrected Date: 02/07/07  
Followup Date: 02/07/07  
Extend Date:

Remarks Date: 02/06/07

Failure to comply with Conditions of Approval. Specifically - Wildlife, paragraph #2 Corrective Action: leave the hole and location in a secure and environmentally sound condition; vacate location.

Office: BU ID: BU10975  
Unique INC #: KAK07008 Well Name: SCHOONOVER RD 5 SRU  
Well #: 43-13 ID Date: 02/07/07  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 02/07/07  
Case #: WYW148333X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KASPRZYK  
Gravity: 3  
Authority Ref: 43CFR3162.5-1(a)  
Abatement Date: 02/08/07  
Corrected Date: 02/09/07  
Followup Date: 02/09/07  
Extend Date:

Remarks Date: 02/07/07

**Safety and Drilling Related Violations (INCs) Issued During FY 2007**  
**As of March 3, 2011**

Failure to comply with Conditions of Approval Specifically: COA III.B.11 (pg 16) Corrective Action: effectively fence pit to keep out wildlife and livestock. Called John Short @ 0820 on 2/8/07. He said he would get someone over there right away to get it fixed

Office: BU ID: BU10962  
Unique INC #: KAK07005 Well Name: SCHOONOVER RD 5 SRU ID Date: 02/06/07  
Well #: 34-12 Effective Date: 02/06/07  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 02/09/07  
Case #: WYW148333X FAC ID: Corrected Date: 02/09/07  
Form: I FAC NAME: Followup Date: 02/09/07  
Assessment: \$0 Inspector: KASPRZYK Extend Date:  
Gravity: 3 Authority Ref: 43CFR3162.1(a)

Remarks Date: 02/06/07

Failure to comply with Conditions of Approval. Specifically - Wildlife, paragraph #2 Corrective Action: leave the hole and location in a secure and environmentally sound condition; vacate location.

Office: BU ID: BU11038  
Unique INC #: KAK07009 Well Name: SCHOONOVER RD 5 SRU ID Date: 02/20/07  
Well #: 43-12 Effective Date: 02/20/07  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 02/21/07  
Case #: WYW148333X FAC ID: Corrected Date: 02/22/07  
Form: I FAC NAME: Followup Date: 02/22/07  
Assessment: \$0 Inspector: KASPRZYK Extend Date:  
Gravity: 3 Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 02/20/07

2/20/07 - Failure to comply with COA. Specifically - Wildlife, paragraph #2 Corrective Action - Secure well and move off location. No Activity is allowed until wildlife stipos have expired.

Office: BU ID: BU10964  
Unique INC #: KAK07007 Well Name: SCHOONOVER RD 5 SRU ID Date: 02/06/07  
Well #: 21-5 Effective Date: 02/06/07  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 02/09/07  
Case #: WYW148333X FAC ID: Corrected Date: 02/09/07  
Form: I FAC NAME: Followup Date: 02/09/07  
Assessment: \$0 Inspector: KASPRZYK Extend Date:  
Gravity: 3 Authority Ref: 43CFR3162-1(a)

Remarks Date: 02/06/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Failure to comply with Conditions of Approval. Specifically - Wildlife, paragraph #2 Corrective Action: leave the hole and location in a secure and environmentally sound condition; vacate location.

Office: BU ID: BU13377  
Unique INC #: RN-08-99 Well Name: WEST KITTY BARLOW  
Well #: 21-14AN ID Date: 09/08/08  
Operator: KENNEDY OIL Effective Date: 09/08/08  
Case #: WYW0203042 Abatement Date: 09/29/08  
Form: I FAC ID: Corrected Date: 10/03/06  
Assessment: \$0 FAC NAME: Followup Date: 10/06/08  
Gravity: 1 Inspector: NAVARRETTE Extend Date:  
Authority Ref: Onshore Order #2 III.B.c. and COA

Remarks Date: 09/08/08

This well does not have cement to surface. You must run a cement bond log on this well to find the top of cement, submit the log to this office for evaluation and approval of remedial cementing. You must call Rafael Navarrette at (307)-684-1165 or (307)217-0740 prior to logging and doing any remedial cementing.

Office: BU ID: BU12438  
Unique INC #: RN-7-133 Well Name: CRAZY WOMAN S STATE  
Well #: 23-21 ID Date: 08/21/07  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 08/21/07  
Case #: WYW140488 FAC ID: Abatement Date: 08/22/07  
Form: I FAC NAME: Corrected Date: 08/22/07  
Assessment: \$0 Inspector: NAVARRETTE Followup Date: 08/22/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 08/23/07

The flow line is only 25 feet. You must install 5 feet of flow line for a total of 30 feet.

Office: BU ID: BU12437  
Unique INC #: RN-07-132 Well Name: CRAZY WOMAN S STATE  
Well #: 12-21 ID Date: 08/21/07  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 08/21/07  
Case #: WYW140488 FAC ID: Abatement Date: 08/22/07  
Form: I FAC NAME: Corrected Date: 08/22/07  
Assessment: \$0 Inspector: NAVARRETTE Followup Date: 08/22/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 08/23/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

The flow line is only 21 feet. You must install 9 more feet of flow line (30 feet of flow line).

Office: BU	Well Name: E SQUAW CREEK FED SS	ID: BU10816
Unique INC #: RN-07-9	Well #: 11CC-27	ID Date: 12/05/06
Operator: PINNACLE GAS RESOURCES, INC	FAC ID:	Effective Date: 12/05/06
Case #: WYW146790	FAC NAME:	Abatement Date: 01/05/07
Form: I	Inspector: NAVARRETTE	Corrected Date: 12/06/06
Assessment: \$0		Followup Date: 12/06/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.(b)		

Remarks Date: 12/06/06

The well does not have the well sign on location. You must properly identify this well with a well sign.

Office: BU	Well Name: E SQUAW CREEK FED SS	ID: BU10858
Unique INC #: RN-07-14	Well #: 5WP-27	ID Date: 12/19/06
Operator: PINNACLE GAS RESOURCES, INC	FAC ID:	Effective Date: 12/19/06
Case #: WYW146790	FAC NAME:	Abatement Date: 01/05/07
Form: I	Inspector: NAVARRETTE	Corrected Date: 01/16/07
Assessment: \$0		Followup Date: 01/16/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a) & Condition fo approval		

Remarks Date: 12/19/06

You have failed to report the spud date to the Authorized Officer 24 hours before spudding this well. You must report the spud date to this office as required by the Condition of Approval.

Office: BU	Well Name: E SQUAW CREEK FED SS	ID: BU10818
Unique INC #: RN-07-10	Well #: 5WP-27	ID Date: 12/06/06
Operator: PINNACLE GAS RESOURCES, INC	FAC ID:	Effective Date: 12/06/06
Case #: WYW146790	FAC NAME:	Abatement Date: 12/14/06
Form: I	Inspector: NAVARRETTE	Corrected Date: 12/15/06
Assessment: \$0		Followup Date: 12/15/06
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1(a) & condition of approval		

Remarks Date: 12/06/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

You have failed to comply with the Condition of Approval for cementing of casing. You must log this well and do the remedial cement . You are required to call Rafael Navarrette at 307-684-1165 or 307-217-0740 three hour before running any logs or cement.

Office: BU ID: BU10814  
Unique INC #: RN-07-7 Well Name: E SQUAW CREEK FED SS  
Well #: 7WP-27 ID Date: 12/05/06  
Operator: PINNACLE GAS RESOURCES, INC Effective Date: 12/05/06  
Case #: WYW146790 FAC ID: Abatement Date: 01/05/07  
Form: I FAC NAME: Corrected Date: 12/06/06  
Assessment: \$0 Inspector: NAVARRETTE Followup Date: 12/06/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.(b)

Remarks Date: 12/06/06

The well does not have the well sign on location. You must properly identify this well with a well sign.

Office: BU ID: BU10889  
Unique INC #: RN-07-15 Well Name: GPE FEDERAL  
Well #: 15-4 ID Date: 01/08/07  
Operator: GPE ENERGY INC Effective Date: 01/08/07  
Case #: WYW152138 FAC ID: Abatement Date: 01/16/07  
Form: I FAC NAME: Corrected Date: 01/16/07  
Assessment: \$0 Inspector: NAVARRETTE Followup Date: 01/16/07  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order #2 III.g.

Remarks Date: 01/09/07

The manual locking devices are not installed on the BOP. Corrective Action: Install the manual locking devices on the BOP. See attached photo.

Office: BU ID: BU10672  
Unique INC #: CR07-02-DI Well Name: CRAZY WOMAN S CHRISTIAN  
Well #: 14-28 ID Date: 10/03/06  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 10/11/06  
Case #: WYW140488 FAC ID: Abatement Date: 10/17/06  
Form: I FAC NAME: Corrected Date: 10/05/06  
Assessment: \$0 Inspector: ROSS Followup Date: 10/05/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3161.2 and Conditions of Approval in Application for Permit to Drill

Remarks Date: 10/03/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

The reserve pit at Crazy Woman S Christian # 14-28 was not fenced during drilling operations. To correct this violation, comply with the reserve pit fencing requirement in the Conditions of Approval in the Application for Permit to Drill.

Office: BU ID: BU10681  
Unique INC #: CR07-08-DI Well Name: CRAZY WOMAN S STATE  
Well #: 23-21 ID Date: 10/05/06  
Effective Date: 10/12/06  
Operator: BLACK DIAMOND ENERGY INC Abatement Date: 10/19/06  
Case #: WYW140488 FAC ID: Corrected Date: 10/19/06  
Form: I FAC NAME: Followup Date: 10/26/06  
Assessment: \$0 Inspector: ROSS Extend Date:  
Gravity: 3

Authority Ref: 43 CFR 3161.2 and the Conditions of Approval in the Application for Permit to Drill

Remarks Date: 10/05/06

The reserve pit at Crazy Woman S State #23-21 is not fenced during drilling operations. To correct this violation comply with reserve pit fencing requirements in the Conditions of Approval in the Application for Permit to Drill.

Office: BU ID: BU12465  
Unique INC #: CR07-74-I Well Name: TREND  
Well #: 23-18 ID Date: 09/03/07  
Effective Date: 09/04/07  
Operator: TREND EXPLORATION I, LLC Abatement Date: 09/04/07  
Case #: WYW145538 FAC ID: Corrected Date: 09/05/07  
Form: I FAC NAME: Followup Date: 09/05/07  
Assessment: \$0 Inspector: ROSS Extend Date:  
Gravity: 3

Authority Ref: 43 CFR 3161.2 and Onshore Order No. 2, III A.2.c.ii.

Remarks Date: 09/03/07

The air jammers are not working. The Accumulator system does not have two independent power sources to close the preventers. To correct this violation comply with Onshore Order No. 2. III.A.2.c.ii. The suggested correction given in Onshore Order No. 2 is to "Install the equipment as specified."

Office: BU ID: BU12469  
Unique INC #: CRO7-76-DI Well Name: TREND  
Well #: 23-18 ID Date: 09/04/07  
Effective Date: 09/10/07  
Operator: TREND EXPLORATION I, LLC Abatement Date: 09/15/07  
Case #: WYW145538 FAC ID: Corrected Date: 09/06/07  
Form: I FAC NAME: Followup Date: 09/06/07  
Assessment: \$0 Inspector: ROSS Extend Date:  
Gravity: 3

Authority Ref: 43 CFR 3161.2 and Conditions of Approval in APD

Remarks Date: 09/04/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

On well Trend #23-18 Trend failed to perform a Formation Integrity Test (F.I.T.) when drilling out the surface casing shoe as required in the conditions of approval in the APD. To correct this action, since it is now too late to perform the F.I.T. on this well, comply with the conditions of approval for any federal wells to be drilled at a later date.

Office: BU ID: BU12466  
Unique INC #: CR07-75-I Well Name: TREND  
Well #: 23-18  
Operator: TREND EXPLORATION I, LLC  
Case #: WYW145538 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3161.2 and Onshore Order No. 2, III A.2.d.

Remarks Date: 09/03/07

The Accumulator system does not have the minimum precharge on the accumulator bottles. To correct this violation comply with Onshore Order No. 2. III.A.2.d.

Office: BU ID: BU11975  
Unique INC #: CR07-40-I Well Name: SIGMA TAU BIG GEORGE UNIT  
Well #: 7-23  
Operator: ANADARKO PETROLEUM CORP  
Case #: WYW149537X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 and Conditions of Approval

Remarks Date: 05/04/07

Operator failed to call in a spud notice for well Big George Unit 7-23. To correct this violation submit a spud notice.

Office: BU ID: BU10928  
Unique INC #: CR07-16-DI Well Name: SIGMA TAU BIG GEORGE UNIT  
Well #: 5-23  
Operator: ANADARKO PETROLEUM CORP  
Case #: WYW149537X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (b)

Remarks Date: 01/18/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

The well site is not correctly identified. There is no sign. There is a survey stake with the well name, and operator name. There is no lease number or location information.

Office: BU ID: BU12504  
Unique INC #: CR07-79-I Well Name: TRIANGLE CBM UNIT N ADD  
Well #: 12-19 ID Date: 09/17/07  
Operator: CITATION OIL & GAS CORPORATION Effective Date: 09/25/07  
Case #: WYW152375X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS Abatement Date: 09/28/07  
Gravity: 3 Corrected Date: 09/28/07  
Authority Ref: 43 CFR 3161.2 and Conditions of Approval Followup Date: 09/28/07  
Remarks Date: 09/17/07 Extend Date:

The Conditions of Approval for the Triangle CBM Unit North POD require a self-contained, chemically treated porta-potty on location. There is no porta-potty on location for well # 12-19. To correct this violation comply with the Conditions of Approval.

Office: BU ID: BU12470  
Unique INC #: GDT07-47 Well Name: USFS WILDHORSE CREEK FEDERAL  
Well #: 42-19 ID Date: 09/05/07  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 09/05/07  
Case #: WYW162534X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: TRUJILLO Abatement Date: 09/05/07  
Gravity: 3 Corrected Date: 09/05/07  
Authority Ref: 3162.1(a) Followup Date: 09/05/07  
Remarks Date: 09/05/07 Extend Date:

You had failed to notify this office 24hr in advance of a spud date. Any other failure's to call in a spud will result in an assessment.

Office: BU ID: BU10901  
Unique INC #: JW07-14-I Well Name: GPE FEDERAL  
Well #: 15-4 ID Date: 01/16/07  
Operator: GPE ENERGY INC Effective Date: 01/16/07  
Case #: WYW152138 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALKER Abatement Date: 01/29/07  
Gravity: 3 Corrected Date: 01/29/07  
Authority Ref: Conditions of Approval Followup Date: 01/29/07  
Remarks Date: 01/16/07 Extend Date:

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Follow-up of drilling operations on Federal well 15-4 shows that the drilling pits are not fenced. Conditions of Approval require pits to be fenced on 3 sides during drilling operations and the fourth side when rig is released. Corrective Action: Install fence around all pits as required by the Conditions of Approval. Thank you

Office: CA		ID: CA2338
Unique INC #: CMH-07-12	Well Name: SE OKIE DRAW FEDERAL	
	Well #: 44-6	
Operator: TITAN RESOURCES CORPORATION		
Case #: WYW140262	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: HERNANDEZ	
Gravity: 3		
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 01/22/07

Under the approved APD Conditions of Approval, number 7 of the General Conditions of Approval states "A progress report must be filed once a month starting with the month the well was spud and continuing until the well is completed. The report must be filed by the 25th of each month on a Sundry Notice (Form 3160-5)." Repeated verbal requests for the Sundry Notices (progress reports) from Tim Collier have been ignored. Please submit the required paperwork for compliance.

Office: CA		ID: CA2437
Unique INC #: L07-39	Well Name: COLE CREEK	
	Well #: 31-17H	
Operator: SLAWSON EXPLORATION CO INC		
Case #: WYC060331	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: LONG	
Gravity: 3		
Authority Ref: Onshore.Oil & Gas Order No. 2. III., B.		

Remarks Date: 08/16/07

Surface casing run & cemented in above well was not that approved. 9.625", 36# J55, ST&C was run, 8.625", 24# was approved. Setting depth was 850', 500' was approved. Please submit Sundry Notice requesting variance from approved casing program in APD within 10 days from receipt of this notice. Request must include justification for variance. When violation has been corrected, sign and return original copy of this notice to the Casper Field Office. If you have any questions, please call Gale Long at (307) 261-7521 or (307) 262-0390.

Office: CA		ID: CA2308
Unique INC #: L07-02	Well Name: BLAYLOCK	
	Well #: 13-35A	
Operator: SOUTHWESTERN PRODUCTION CORP		
Case #: WYW140783	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: LONG	
Gravity: 3		
Authority Ref: Onshore Oil & Gas Order No. 2,III,A,2,a,iii.		

Remarks Date: 10/22/06

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Upper Kelly Cock & Drill String Safety Valves failed BOP Test. Please install new equipment or repair prior to above abatement date. Documentation that new or repaired equipment has been tested must be furnished to the Casper Field Office. See attachments.

Office: CA		ID: CA2411
Unique INC #: JAM-TITAN	Well Name: SE OKIE DRAW FEDERAL	
	Well #: 44-6	
Operator: TITAN RESOURCES CORPORATION		
Case #: WYW140262	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: MESROBIAN	
Gravity: 3		
Authority Ref: 43CFR3162.1(a)		

Remarks Date: 06/15/07

Rat Hole and mouse hole will be backfilled and compacted from bottom to top stated from the approved APD. Fill by abatement date.

Office: CB		ID: CB19605
Unique INC #: 07-RC-021	Well Name: GOLDEN LANE 17 FEDERAL	
	Well #: 2Y	
Operator: BEPCO LP		
Case #: NMNM02918	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$500	Inspector: CAFFALL	
Gravity: 1		
Authority Ref: 43 CFR 3163.1(b)(2)		

Remarks Date: 07/16/07

Well was drilled without an Approved Drilling Plan (APD).

Office: CB		ID: CB19424
Unique INC #: 07-CD-34A	Well Name: ROSS DRAW	
	Well #: 25	
Operator: WILLIAMSON J C		
Case #: NMNM0554499	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$4,500	Inspector: DE MONTIGNY/CAFFALL	
Gravity: 1		
Authority Ref: 43 CFR 3163.1 (b) (1)		

Remarks Date: 03/26/07

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

FOR FAILURE TO INSTALL BLOWOUT PREVENTER OR OTHER EQUIVALENT WELL CONTROL EQUIPMENT, AS REQUIRED BY THE APPROVED DRILLING PLAN, \$500 PER DAY FOR EACH DAY THAT THE VIOLATION EXISTED. NOT TO EXCEED TEN DAYS INCLUDING DAYS THE VIOLATION EXISTED PRIOR TO DISCOVERY, ON FRIDAY 03/23/07 ASSESSMENT IS CAPPED AT \$5,000. INSTALL HAND WHEELS ON RAM TYPE BOP AS INSTRUCTED 03/23/07. FAILURE TO INSTALL BY 03/27/07 WILL REQUIRE ALL ACTIVITIES TO BE SHUT DOWN UNTIL VIOLATION IS CORRECTED.

Office: CB		ID: CB19442
Unique INC #: 07-RH-04	Well Name: MOSAIC 34 FEDERAL	
	Well #: 1H	ID Date: 04/04/07
Operator: CHESAPEAKE OPERATING INC		Effective Date: 04/04/07
Case #: NMNM13074	FAC ID:	Abatement Date: 04/05/07
Form: I	FAC NAME:	Corrected Date: 04/06/07
Assessment: \$0	Inspector: HOSKINSON	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: OO#2.III.A.2.d		

Remarks Date: 04/04/07

No verification of Pre-Charge test for Accumulator. Per OO#2.III.A.2.d the Accumulator precharge pressure test shall be conducted prior to connecting to the BOP.

Office: CB		ID: CB19277
Unique INC #: 0612PS01	Well Name: AVALANCHE 4 FEDERAL	
	Well #: 1	ID Date: 12/18/06
Operator: EOG RESOURCES, INC.		Effective Date: 12/29/06
Case #: NMNM98169	FAC ID:	Abatement Date: 12/30/06
Form: I	FAC NAME:	Corrected Date: 12/23/06
Assessment: \$0	Inspector: SWARTZ	Followup Date: 12/23/06
Gravity: 3		Extend Date:
Authority Ref: Drilling Conditions of Approval		

Remarks Date: 12/18/06

Your federal property case: NM98169, name: Avalanche 4 Fed No. 1, in T16S-R29E, SWSE of Section 4 Eddy County, New Mexico is the subject of an on-the-ground production inspection. Found on 12/18/2006 at 1100hrs: The Bureau of Land Management general requirements and special stipulations attached to this well's approved Application for Permit to Drill or Reenter have been violated. In particular, the "CONDITIONS OF APPROVAL-DRILLING". The Section labeled "I. DRILLING OPERATIONS REQUIREMENTS:" requires notification "in sufficient time for a representative to witness: A. Spudding B. Cementing casing: 11 1/4 inch, 8 5/8 inch, and 5 1/2 inch. C. BOP tests The first and only BLM notification of drilling activity occurred 12/17/2006 concerning the cementing of the 8 5/8 casing. This notification did not allow sufficient BLM preparation for an I & E inspector to be present during any of the above mentioned operations. Correction of this situation will require - Prior to reaching a depth of 6000ft sufficient notice to the BLM inspector be given (505-627-0258) to witness these required supplemental operations: A. A mud weight equivalency test. Onshore Order #2.III.B.1.i. B. A chart recorded pressure test of the 8 5/8 inch casing to 70% of yield for 30 minutes with no more than 10 percent pressure decline. Onshore Order #2.III.B.1.i. C. A cement bond log of the 8 5/8 inch casing. D. A BOPE test by an independent service company. Onshore Order #2.III.A.. To access these quoted regulation(s) see <http://www.nm.blm.gov/>. Under Programs, click on Oil & Gas. Refer to resolution of this INC# by including its unique notice number (0612PS01) in the text of return correspondence within one week of completion of the required supplemental operations. Insert into that correspondence a brief summary of your compliance method.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: CB		ID: CB19278
Unique INC #: 07-WWI-001	Well Name: MIDNIGHT MATADOR	
	Well #: 3	ID Date: 12/20/06
Operator: FAIRWAY RESOURCES		Effective Date: 12/27/06
Case #: NMLC050158	FAC ID:	Abatement Date: 01/27/07
Form: I	FAC NAME:	Corrected Date: 02/15/07
Assessment: \$0	Inspector: WHITLOCK	Followup Date: 02/07/07
Gravity: 3		Extend Date: 03/01/07
Authority Ref: 43 CFR 3162.1 (a)/Drilling COA		

Remarks Date: 12/20/06

Failure to comply with drilling conditions of approval. Failure to tie back 5-1/2" production string into 8-5/8" surface casing. Submit sundry (Form 3160-5) detailing remedial action to bring well into compliance with Drilling COA.

Office: CB		ID: CB19441
Unique INC #: 07WWI002	Well Name: MOSSBERG FEDERAL	
	Well #: 1Y	ID Date: 04/06/07
Operator: OXY USA WTP LIMITED PTNRSHIP		Effective Date: 04/06/07
Case #: NMNM36975	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 06/28/07
Assessment: \$0	Inspector: WHITLOCK	Followup Date: 07/03/07
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1.a/43 CFR 3162.5-1.a		

Remarks Date: 04/06/07

FAILURE TO COMPLY WITH INSTRUCTIONS FROM AUTHORIZED OFFICER REGARDING USING 1/4 INCH PEA GRAVEL DURING ONE INCH OPERATIONS RESULTING IN INEFFECTIVE CEMENT JOB FOR THE 13-3/8" CASING. CEMENT WILL CIRCULATE ON 9-5/8" AND 7" CASING STRINGS. NO 1/4" PEA GRAVEL WILL BE USED IF REMEDIAL CEMENT WORK IS REQUIRED.

Office: CC		ID: CC1070
Unique INC #: RG07EG010A	Well Name: USA	
	Well #: 32-36	ID Date: 09/04/07
Operator: KERR-MCGEE ROCKY MOUNTAIN CORP		Effective Date: 09/04/07
Case #: COC37842	FAC ID:	Abatement Date: 09/04/07
Form: I	FAC NAME:	Corrected Date: 09/06/07
Assessment: \$0	Inspector: EGILLINGHAM	Followup Date: 06/07/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1		

Remarks Date: 09/04/07

09/04/07: Discovered through telephone conversations with Nancy McDonald, and follow up telephone calls to Phil Johnson and Travis DePorter, that pad location had already been built. APD Condition of Approval required both 7 day prior notification and 48 hour prior notification before construction pad. Corrective action is to follow all prescribed notification procedures on future wells. These procedures have been discussed with Phil Johnson, with email to Phil Johnson confirming who contacts are to be made to and when.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: CC			ID: CC1071
Unique INC #: RG07EG011A	Well Name: USA		
	Well #: 32-36	ID Date:	09/04/07
Operator: KERR-MCGEE ROCKY MOUNTAIN CORP		Effective Date:	09/04/07
Case #: COC37842	FAC ID:	Abatement Date:	09/04/07
Form: I	FAC NAME:	Corrected Date:	09/06/07
Assessment: \$0	Inspector: EGILLINGHAM	Followup Date:	06/07/07
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.5-1			

Remarks Date: 09/04/07

09/04/07: Discovered through telephone conversations with Nancy McDonald, and follow up telephone calls to Phil Johnson and Travis DePorter, that drilling operations had begun. APD Condition of Approval required both 7 day prior notification and 48 hour prior notification before commencing drilling operations. Corrective action is to follow all prescribed notification procedures on future wells. These procedures have been discussed with Phil Johnson, with email to Phil Johnson confirming who contacts are to be made to and when.

Office: CC			ID: CC1072
Unique INC #: RG07EG012A	Well Name: USA		
	Well #: 22-36	ID Date:	09/04/07
Operator: KERR-MCGEE ROCKY MOUNTAIN CORP		Effective Date:	09/04/07
Case #: COC37842	FAC ID:	Abatement Date:	09/04/07
Form: I	FAC NAME:	Corrected Date:	09/06/07
Assessment: \$0	Inspector: EGILLINGHAM	Followup Date:	09/06/07
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.5-1			

Remarks Date: 09/04/07

09/04/07: Discovered through telephone conversations with Nancy McDonald, and follow up telephone calls to Phil Johnson and Travis DePorter, that pad location had already been built. APD Condition of Approval required 48 hour prior notification before construction pad. Corrective action is to follow all prescribed notification procedures on future wells. These procedures have been discussed with Phil Johnson, with email to Phil Johnson confirming who contacts are to be made to and when.

Office: CC			ID: CC987
Unique INC #: RG07GH097	Well Name: BROWN		
	Well #: 1	ID Date:	06/05/07
Operator: ENERVEST OPERATING LLC		Effective Date:	
Case #: COC04135	FAC ID:	Abatement Date:	07/09/07
Form: I	FAC NAME:	Corrected Date:	07/05/07
Assessment: \$0	Inspector: HUNT	Followup Date:	09/24/07
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3164.1, O.O.#6,III.A.2.b			

Remarks Date: 06/05/07

Indications of Hydrogen Sulfide gas on the locations. Submit tested levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, this office, at (719) 269-8533.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: CC ID: CC1012  
Unique INC #: RG07GH122 Well Name: COPE, FEDERAL  
Well #: 1-16, 2-16X ID Date: 05/31/07  
Operator: ENERVEST OPERATING LLC Effective Date: 06/06/07  
Case #: COC12711 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT Abatement Date: 07/09/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b Corrected Date: 07/05/07  
Followup Date: 09/24/07

Remarks Date: 05/31/07

Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Office: CC ID: CC964  
Unique INC #: RG07GH077V Well Name: KITZMILLER FEDERAL  
Well #: 44-28 ID Date: 04/03/07  
Operator: BERRY PETROLEUM COMPANY Effective Date: 04/03/07  
Case #: COC13292 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT Abatement Date: 04/04/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O..#2, III.A.2.b.ii Corrected Date: 04/04/07  
Followup Date: 04/09/07

Remarks Date: 04/03/07

OPERATOR REPRESENTATIVE WAS ADVISED OF NEED TO INSTALL SECOND ADJUSTABLE CHOKE ON MANIFOD. WORK WAS COMPLETED WITHIN 24 HOURS. GHUNT

Office: CC ID: CC965  
Unique INC #: RG07GH078V Well Name: KITZMILLER FEDERAL  
Well #: 44-28 ID Date: 04/03/07  
Operator: BERRY PETROLEUM COMPANY Effective Date: 04/03/07  
Case #: COC13292 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT Abatement Date: 04/04/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O..#2, III.A.2.g. Corrected Date: 04/04/07  
Followup Date: 04/09/07

Remarks Date: 04/03/07

OPERATOR REPRESENTATIVE WAS ADVISED OF NEED TO INSTALL A VALVE IN THE CLOSING LINE OF THE ANNULAR BOPE, TO ACT AS A LOCKING DEVICE, WITHIN TWENTY FOUR HOURS OF NOTICE. WORK WAS COMPLETED WITHIN 24 HOURS. GHUNT

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: CC ID: CC966  
Unique INC #: RG07GH079V Well Name: KITZMILLER FEDERAL  
Well #: 44-28 ID Date: 04/04/07  
Operator: BERRY PETROLEUM COMPANY Effective Date: 04/04/07  
Case #: COC13292 FAC ID: Abatement Date: 04/04/07  
Form: I FAC NAME: Corrected Date: 04/04/07  
Assessment: \$0 Inspector: HUNT Followup Date: 04/04/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#2.III.B.1.g  
  
Remarks Date: 04/04/07  
NO WIPER PLUG ON LOCATION FOR USE IN CEMENT JOB. ORDERED WIPER PLUG USE TO PROTECT CEMENT INTEGRITY DURING DISPLACEMENT. JOB COMPLETED AFTER WIPER PLUG WAS BROUGHT TO SITE. GHUNT

Office: CC ID: CC990  
Unique INC #: RH07GH100 Well Name: STATE  
Well #: 1-15 ID Date: 06/05/07  
Operator: ENERVEST OPERATING LLC Effective Date: 06/05/07  
Case #: COC22244 FAC ID: Abatement Date: 07/09/07  
Form: I FAC NAME: Corrected Date: 07/05/07  
Assessment: \$0 Inspector: HUNT Followup Date: 09/25/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b  
  
Remarks Date: 06/05/07  
Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Office: CC ID: CC1019  
Unique INC #: RG07GH129 Well Name: THOMPSON-PORTER  
Well #: 1-10 ID Date: 05/30/07  
Operator: ENERVEST OPERATING LLC Effective Date: 06/07/07  
Case #: COC23228 FAC ID: Abatement Date: 07/09/07  
Form: I FAC NAME: Corrected Date: 07/05/07  
Assessment: \$0 Inspector: HUNT Followup Date: 09/24/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b  
  
Remarks Date: 05/30/07  
Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: CC ID: CC1022  
Unique INC #: RG07GH132 Well Name: HARTMETZ ID Date: 05/30/07  
Well #: 1-9 Effective Date: 07/06/07  
Operator: ENERVEST OPERATING LLC Abatement Date: 07/09/07  
Case #: COC26051 FAC ID: Corrected Date: 07/05/07  
Form: I FAC NAME: Followup Date: 09/24/07  
Assessment: \$0 Inspector: HUNT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b  
  
Remarks Date: 05/30/07  
Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Office: CC ID: CC1033  
Unique INC #: RG07GH143 Well Name: CHILDREN'S HOSP ID Date: 06/13/07  
Well #: 1 Effective Date: 06/26/07  
Operator: ENCANA OIL & GAS (USA) INC Abatement Date: 07/26/07  
Case #: COC26924 FAC ID: HOSP-1 Corrected Date: 08/17/07  
Form: I FAC NAME: CHILDRENS HOSP 1 Followup Date: 09/25/07  
Assessment: \$0 Inspector: HUNT Extend Date: 08/10/07  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b  
  
Remarks Date: 06/13/07  
Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location and 100 and 500 ppm radii of exposure information within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Office: CC ID: CC1008  
Unique INC #: RG07GH118 Well Name: PORTER ID Date: 05/31/07  
Well #: 1 Effective Date: 06/06/07  
Operator: ENERVEST OPERATING LLC Abatement Date: 07/09/07  
Case #: COC30152 FAC ID: Corrected Date: 07/05/07  
Form: I FAC NAME: Followup Date: 09/24/07  
Assessment: \$0 Inspector: HUNT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b  
  
Remarks Date: 05/31/07  
Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: CC			ID: CC994
Unique INC #: RG07GH104	Well Name: ROLLINS RUTHERFORD		
	Well #: 1A-20	ID Date:	05/31/07
Operator: ENERVEST OPERATING LLC		Effective Date:	06/06/07
Case #: COC30191	FAC ID:	Abatement Date:	07/09/07
Form: I	FAC NAME:	Corrected Date:	06/14/07
Assessment: \$0	Inspector: HUNT	Followup Date:	09/24/07
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b			

Remarks Date: 05/31/07

Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Office: CC			ID: CC1003
Unique INC #: RG07GH113	Well Name: LOFLIN		
	Well #: 1-8	ID Date:	05/31/07
Operator: ENERVEST OPERATING LLC		Effective Date:	06/06/07
Case #: COC36653	FAC ID:	Abatement Date:	07/09/07
Form: I	FAC NAME:	Corrected Date:	07/05/07
Assessment: \$0	Inspector: HUNT	Followup Date:	09/24/07
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3164.1, O.O. #6, III, A.2.b			

Remarks Date: 05/31/07

Indications of Hydrogen Sulfide gas on the locations. Submit levels of H2S for this location, within thirty days of notice. Questions regarding this request should be directed to Gene Hunt, of this office, at 719-269-8533.

Office: CR			ID: CR1198
Unique INC #: LSFO07-001	Well Name: YELLOWCAT FEDERAL UNIT		
	Well #: 32-4	ID Date:	09/21/07
Operator: JULANDER ENERGY COMPANY		Effective Date:	09/29/07
Case #: COC69282X	FAC ID:	Abatement Date:	09/29/07
Form: I	FAC NAME:	Corrected Date:	09/29/07
Assessment: \$0	Inspector: MCKINSTRY	Followup Date:	10/10/07
Gravity: 1		Extend Date:	
Authority Ref: 43 CFR 3162.1a 3162.3b 3162.5-1a			

Remarks Date: 09/25/07

On 9-21-07 Craig NRS inspected pad construction activities for the Yellow Cat 34-4 well. Operator's contractor (Valley Construction) did not have a copy of the approved APD onsite with the Surface Use Plan of Operations. The contractor was also using a two track access road that should have been blocked off for vehicle use as per requirements of the approved Application for Permit To Drill. Craig NRS instructed contractor where to block road which was done and where to scrape approved access road.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: DK		ID: DK6322
Unique INC #: IWM0702	Well Name: PVT. FRAZIER	
	Well #: 1-34H	ID Date: 04/10/07
Operator: ZENERGY INC		Effective Date: 04/10/07
Case #: NDM96361	FAC ID:	Abatement Date: 04/20/07
Form: I	FAC NAME:	Corrected Date: 04/12/07
Assessment: \$0	Inspector: BILL MCMANUS	Followup Date: 04/12/07
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3162.1		

Remarks Date: 04/10/07

Zenergy, INC on March 13, 2007 spudded the Pvt. Frazier 1-34H well on Federal lease NDM 96361 without notifying the Bureau of Land Management (BLM) Dickinson Field Office as required by the authorized officer. All wells on Federal Leases are and will be required to notify the bureau of Land Management when the well or wells are spudded, Failure to comply could lead to assessment or penalty. sign and return notice of Incidents of Noncompliance to this BLM office.

Office: FE		ID: FE13388
Unique INC #: 07MH004	Well Name: CHACO PLANT	
	Well #: 1	ID Date: 11/28/06
Operator: DUGAN PRODUCTION CORPORATION		Effective Date: 11/28/06
Case #: NMNM12027	FAC ID:	Abatement Date: 12/04/06
Form: I	FAC NAME:	Corrected Date: 12/04/06
Assessment: \$0	Inspector: HUNTLEY	Followup Date: 12/04/06
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 11/28/06

The operator shall perform operations and maintain equipment in a safe and workmanlike manner. The operator shall take all precautions necessary to provide adequate protection of life and the protection of property. During the plugging of this well, a BOP and related equipment (BOPE) were not used. BOP and BOPE are required to be used for plug and abandonment of wells for well control and safety reasons. This well has been plugged, so no action is required.

Office: FE		ID: FE13354
Unique INC #: 07CO001	Well Name: GRAMBLING A	
	Well #: 801S	ID Date: 11/02/06
Operator: ENERGEN RESOURCES CORPORATION		Effective Date: 11/02/06
Case #: NMNM013861	FAC ID:	Abatement Date: 11/02/06
Form: I	FAC NAME:	Corrected Date: 11/02/06
Assessment: \$1,000	Inspector: OLLOM C	Followup Date: 11/30/06
Gravity: 1		Extend Date:
Authority Ref: OOGO #2 III. A. 1; 43 CFR 3163.1(b)(1)		

Remarks Date: 11/02/06

Commencement of drilling without the approved Blow Out Preventer Equipment (BOPE) installed. The BOPE was nippled up 11/01/06. The accumulator hydraulic lines were not connected to the BOP while drilling operations were being conducted. The rig tool pusher resolved the violation on 11/02/06. Received Payment 11/14/06.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: FE ID: FE13758  
Unique INC #: 07CO008 Well Name: GAGE ID Date: 04/05/07  
Well #: 3F Effective Date: 04/05/07  
Operator: CONOCOPHILLIPS COMPANY Abatement Date: 04/06/07  
Case #: NMNM76141 FAC ID: Corrected Date: 04/06/07  
Form: I FAC NAME: Followup Date: 04/06/07  
Assessment: \$0 Inspector: OLLOM C Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil and Gas Order No 2, III. A. 1.  
Remarks Date: 04/05/07

Blowout preventer (BOP) and related equipment ( BOPE) shall be maintained in a manner necessary to assure well control. Numerous problems and failures were discovered during BOPE testing which makes it evident this equipment is not being maintained. Maintain equipment as necessary to pass future BOPE tests in a timely manner. H & P Rig #283.

Office: FE ID: FE13756  
Unique INC #: 07CO007 Well Name: GAGE ID Date: 04/06/07  
Well #: 3F Effective Date: 04/06/07  
Operator: CONOCOPHILLIPS COMPANY Abatement Date: 04/07/07  
Case #: NMNM76141 FAC ID: Corrected Date: 04/06/07  
Form: I FAC NAME: Followup Date: 04/06/07  
Assessment: \$0 Inspector: OLLOM C Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil and Gas Order No 2, III. A. 1. d.  
Remarks Date: 04/06/07

Minimum standards and enforcement provisions for accumulator precharge pressure test. This test shall be conducted prior to connecting the closing unit to the BOP stack and at least once every 6 months. The accumulator was tested and the precharge showed 500 psi. Each bottle was independently checked with the following readings: #1) 850, #2) 750, #3) 800, #4) 750, #5) 750 and #6) 750 psi. The desired precharge is 1,000 psi and the maximum acceptable precharge is 1,100 psi. The minimum acceptable precharge pressure is 900 psi. Correct each bottle independently so the unit will meet the minimum requirements. H & P Rig #283.

Office: FE ID: FE13528  
Unique INC #: 07MOW006 Well Name: NEBU ID Date: 02/10/07  
Well #: 340M Effective Date: 02/10/07  
Operator: DEVON ENERGY PRODUCTION CO LP Abatement Date: 02/10/07  
Case #: NMNM78402A FAC ID: Corrected Date: 02/10/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.e.  
Remarks Date: 02/13/07

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Corrected, no further action needed.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: FE		ID: FE13345
Unique INC #: 07MOW001	Well Name: SAN JUAN 30-6 UNIT	
	Well #: 34E	ID Date: 10/19/06
Operator: BURLINGTON RESOURCES O&G CO LP		Effective Date: 10/19/06
Case #: NMSF080714A	FAC ID:	Abatement Date: 10/19/06
Form: I	FAC NAME:	Corrected Date: 10/19/06
Assessment: \$0	Inspector: WADE	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: Onshore Order No. 2, III.A.2.e.		

Remarks Date: 10/19/06

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. CORRECTED 10/19/06.

Office: GJ		ID: GJ6171
Unique INC #: EF07030	Well Name:	
	Well #:	ID Date: 03/07/07
Operator: MARALEX RESOURCES INCORPORATED		Effective Date: 03/20/07
Case #: COC47677B	FAC ID: 29-2	Abatement Date: 04/19/07
Form: I	FAC NAME:	Corrected Date: 03/27/07
Assessment: \$0	Inspector: FANCHER	Followup Date: 04/19/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1(a)		

Remarks Date: 03/07/07

There is a hole just outside your burn on the northwest side, that presents a significant health and safety risk. Operators required to perform operations in a safe and workmanlike manner and take all precautions necessary to provide adequate protection for the health and safety of life. Please correct this hazard.

Office: GJ		ID: GJ6285
Unique INC #: EF07061	Well Name: ESMERELDA FEDERAL	
	Well #: 1-2-8-101	ID Date: 07/16/07
Operator: PETRO MEX LLC		Effective Date:
Case #: COC60770	FAC ID:	Abatement Date: 07/20/07
Form: I	FAC NAME:	Corrected Date: 07/20/07
Assessment: \$0	Inspector: FANCHER	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 2		

Remarks Date: 07/16/07

Removal of the kelley cock valve is prohibited. You will install one and retest it before you reach 3000'. At that time you must install a shorter kelley or be shut in.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GJ ID: GJ6306  
Unique INC #: EF07061D Well Name: ESMERELDA FEDERAL  
Well #: 1-2-8-101 ID Date: 07/16/07  
Operator: PETRO MEX LLC Effective Date: 07/16/07  
Case #: COC60770 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FANCHER  
Gravity: 3  
Authority Ref: Onshore Order No.2, III.A.2.a.ii.

Remarks Date: 07/16/07

CO man had removed kelly cock valve w/o approval. We allowed them to drill to 3000' or when new kelly arrived.

Office: GJ ID: GJ6155  
Unique INC #: CS07008 Well Name: VEGA FEDERAL  
Well #: 35-341 ID Date: 02/12/07  
Operator: DELTA PETROLEUM CORPORATION Effective Date: 02/28/07  
Case #: COC47696B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SNYDER  
Gravity: 1  
Authority Ref: 43 CFR 3162.3

Remarks Date: 02/12/07

II. DRILLING PROGRAM ACCORDING TO APD STATES: THE BLM GRAND JUNCTION OFFICE SHALL BE NOTIFIED AT LEAST TWENTY-FOUR HOURS PRIOR TO SPUD, BLM AT (970) 244-3000.....PLEASE SUBMIT ALL DAILY DRILLING REPORTS AND THE CEMENTING REPORT RECEIVED FROM CEMENTERS WHEN CASING WAS CEMENTED FOR WELL NO. 35-341 VEGA FEDERAL.

Office: GJ ID: GJ6156  
Unique INC #: CS07009 Well Name: VEGA FEDERAL  
Well #: 35-244 ID Date: 02/07/07  
Operator: DELTA PETROLEUM CORPORATION Effective Date: 02/28/07  
Case #: COC47696B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SNYDER  
Gravity: 1  
Authority Ref: 43 CFR 3162.3

Remarks Date: 02/07/07

II. DRILLING PROGRAM ACCORDING TO APD STATES: THE BLM GRAND JUNCTION OFFICE SHALL BE NOTIFIED AT LEAST TWENTY-FOUR HOURS PRIOR TO SPUD, BLM AT (970) 244-3000.....PLEASE SUBMIT ALL DAILY DRILLING REPORTS AND THE CEMENTING REPORT RECEIVED FROM CEMENTERS WHEN CASING WAS CEMENTED FOR WELL NO. 35-244 VEGA FEDERAL.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GJ		ID: GJ6154
Unique INC #: CS07007	Well Name: VEGA FEDERAL	
	Well #: 35-144	ID Date: 02/17/07
Operator: DELTA PETROLEUM CORPORATION		Effective Date: 02/28/07
Case #: COC47696B	FAC ID:	Abatement Date: 03/12/07
Form: I	FAC NAME:	Corrected Date: 03/12/07
Assessment: \$0	Inspector: SNYDER	Followup Date: 03/12/07
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.3		

Remarks Date: 02/17/07

II. DRILLING PROGRAM ACCORDING TO APD STATES: THE BLM GRAND JUNCTION OFFICE SHALL BE NOTIFIED AT LEAST TWENTY-FOUR HOURS PRIOR TO SPUD, BLM AT (970) 244-3000.....PLEASE SUBMIT ALL DAILY DRILLING REPORTS AND THE CEMENTING REPORT RECEIVED FROM CEMENTERS WHEN CASING WAS CEMENTED FOR WELL NO. 35-144 VEGA FEDERAL.

Office: GR		ID: GR1341
Unique INC #: 073005	Well Name: GHOST ISLAND FEDERAL	
	Well #: 2	ID Date: 12/05/06
Operator: DAVIS PETROLEUM CORPORATION		Effective Date: 12/05/06
Case #: WYW152258	FAC ID:	Abatement Date: 12/05/06
Form: I	FAC NAME:	Corrected Date: 12/05/06
Assessment: \$0	Inspector: MOFFETT	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: OO #2 III.A.2.e.		

Remarks Date: 12/05/06

Violation: No power to closing unit pumps. Corrective Action: Provide power to the closing unit pumps as required in Onshore Order #2. Prompt correction was achieved.

Office: GR		ID: GR1338
Unique INC #: 073002	Well Name: CS FEDERAL	
	Well #: 14100-4-31	ID Date: 10/17/06
Operator: WARREN E&P, INCORPORATED		Effective Date: 10/17/06
Case #: WYW160722X	FAC ID:	Abatement Date: 10/18/06
Form: I	FAC NAME:	Corrected Date: 10/17/06
Assessment: \$0	Inspector: MOFFETT	Followup Date: 10/18/06
Gravity: 1		Extend Date:
Authority Ref: OO#2 III.C.7.		

Remarks Date: 10/17/06

Violation: Flare lines were not the required distance from the well-bore. Corrective Action: Install flare lines as required according to Onshore Order #2.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GR ID: GR1337  
Unique INC #: 073001 Well Name: CS FEDERAL  
Well #: 14100-4-31  
Operator: WARREN E&P, INCORPORATED  
Case #: WYW160722X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MOFFETT  
Gravity: 3  
Authority Ref: OO#2 III.A.1.

Remarks Date: 10/19/06

Violation: Valve handles not installed on inside kill & inside choke valves. Corrective Action: Install valve handles as required per Onshore Order #2.

Office: GR ID: GR1351  
Unique INC #: 073014 Well Name: NORTH ANDERSON CANYON  
Well #: 12-30  
Operator: WHITING OIL AND GAS CORPORATIO  
Case #: WYW37294 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MOFFETT  
Gravity: 1  
Authority Ref: OO#2.III.A.2.e.

Remarks Date: 07/16/07

Violation: Air supply control valves to the air pumps on the accumulator found in the closed position. Resolution: Repair as necessary to bring system into compliance with OO#2 prior to drilling ahead.

Office: GR ID: GR1352  
Unique INC #: 073015 Well Name: NORTH ANDERSON CANYON  
Well #: 12-30  
Operator: WHITING OIL AND GAS CORPORATIO  
Case #: WYW37294 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MOFFETT  
Gravity: 3  
Authority Ref: OO#2.III.A.2.g.

Remarks Date: 07/16/07

Violation: No locking devices were installed on the rams of the BOP system. Resolution: Install locking devices as mandated by OO#2.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GR		ID: GR1374
Unique INC #: HN0805W	Well Name: HORSESHOE UNIT	
	Well #: 85-33	ID Date: 02/27/08
Operator: CABOT OIL & GAS CORPORATION		Effective Date: 02/27/08
Case #: WYW129627D	FAC ID:	Abatement Date: 02/28/08
Form: I	FAC NAME:	Corrected Date: 02/27/07
Assessment: \$0	Inspector: NEWSHAM	Followup Date: 02/28/08
Gravity: 3		Extend Date:
Authority Ref: APD Surface use plan Sec7) G)		

Remarks Date: 02/27/08

The reserve pit is only fenced along the back and half way down one side and not at all on the remaining side. Issued a written INC.

Office: GS		ID: GS6262
Unique INC #: 070163	Well Name: SHIDELER FEDERAL	
	Well #: 43D-29-692(9-29	ID Date: 06/14/07
Operator: BILL BARRETT CORPORATION		Effective Date: 06/14/07
Case #: COC56027	FAC ID:	Abatement Date: 06/15/07
Form: I	FAC NAME:	Corrected Date: 06/14/07
Assessment: \$0	Inspector: BAGBY	Followup Date: 06/15/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III A. 2. h.		

Remarks Date: 06/14/07

Minimum standards and enforcement provisions for remote controls. Remote controls shall be readily accessible to the driller. Remote control was not hooked up. Corrective action: Hook up remote control.

Office: GS		ID: GS6261
Unique INC #: 070162	Well Name: SHIDELER FEDERAL	
	Well #: 43D-29-692(9-29	ID Date: 06/14/07
Operator: BILL BARRETT CORPORATION		Effective Date: 06/14/07
Case #: COC56027	FAC ID:	Abatement Date: 06/15/07
Form: I	FAC NAME:	Corrected Date: 06/14/07
Assessment: \$0	Inspector: BAGBY	Followup Date: 06/15/07
Gravity: 3		Extend Date:
Authority Ref: O.O.#1 III.G.3.f.		

Remarks Date: 06/14/07

A copy of the approved Form 3160-3 and the pertinent drilling plan, along with any conditions of approval, shall be available at the drillsite to authorized or delegated representatives of the United States whenever active construction, drilling, or completion operations are under way. Obtain and have an approved copy of Form 3160-3 onsite.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6157
Unique INC #: 070093	Well Name: ENCANA RPE	
	Well #: 411-31-595	ID Date: 03/07/07
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 03/07/07
Case #: COC60234	FAC ID:	Abatement Date: 03/14/07
Form: I	FAC NAME:	Corrected Date: 03/07/07
Assessment: \$0	Inspector: BAGBY	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 03/07/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. The Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Spud Notice - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office the exact time and date of the spud of this well (RPE 411-31-595).

Office: GS		ID: GS6158
Unique INC #: 070094	Well Name: ENCANA RPE	
	Well #: 411-31-595	ID Date: 03/07/07
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 03/07/07
Case #: COC60234	FAC ID:	Abatement Date: 03/14/07
Form: I	FAC NAME:	Corrected Date: 03/14/07
Assessment: \$0	Inspector: BAGBY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 03/07/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. The Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Casing String and Cementing - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office a Casing Report detailing the size, grade, type, and weight used for the surface casing. 2. Submit to the Glenwood Springs Energy Office a Cement Report detailing the type, quantity, and yield of cement used when cementing the surface casing. Additionally, if you got cement returns to surface and the quantity.

Office: GS		ID: GS6227
Unique INC #: 070137	Well Name: CLOUGH RWF	
	Well #: 512-29	ID Date: 04/26/07
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 04/26/07
Case #: COC62978	FAC ID:	Abatement Date: 04/27/07
Form: I	FAC NAME:	Corrected Date: 04/26/07
Assessment: \$0	Inspector: BAGBY	Followup Date: 04/28/07
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. C. 7.		

Remarks Date: 04/26/07

All Flare systems shall be designed to gather and burn all gas. The Flare Line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. The flare lines did not discharge at least 100 feet from the well head. Additonally, there was no containment (flare pit) at the terminus of the lines. Construct and run flare lines to a flare pit at least 100 feet from the well head.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6031
Unique INC #: 070018	Well Name: LEVERICH FEDERAL	
	Well #: 31-07B (31-01)	ID Date: 10/17/06
Operator: PETROGULF CORPORATION		Effective Date: 10/17/06
Case #: COC64181	FAC ID:	Abatement Date: 10/18/06
Form: I	FAC NAME:	Corrected Date: 10/17/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 10/17/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. C. 7.		

Remarks Date: 10/17/06

All Flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. Violation: Flare lines were not hooked up to the choke manifold. Corrective Action: Hook flare line up.

Office: GS		ID: GS6125
Unique INC #: BB0701	Well Name: FEDERAL RWF	
	Well #: 324-9 (33-9)	ID Date: 01/25/07
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 01/25/07
Case #: COC62160	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 11/17/06
Assessment: \$0	Inspector: BARTER	Followup Date: 09/21/07
Gravity: 1		Extend Date:
Authority Ref:		

Remarks Date: 01/25/07

Contractor began construction before BLM sensitive plants were properly protected as required by COAs.

Office: GS		ID: GS6256
Unique INC #: 070157	Well Name: SHORE FEDERAL	
	Well #: 16-14 (PJ16)	ID Date: 06/11/07
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 06/11/07
Case #: COC01524	FAC ID:	Abatement Date: 06/12/07
Form: I	FAC NAME:	Corrected Date: 06/11/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 06/11/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with the other orders and instructions of the authorized officer. EnCana Oil and Gas (USA) Inc. failed to comply with the instructions of the authorized officer by not notifying the Glenwood Springs Energy Office personnel 24 hours prior to spudding the Shore Federal 16-14 (PJ16) well. Corrective Action: Provide the Glenwood Springs Energy Office with the exact time and date of the spud.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6257
Unique INC #: 070158	Well Name: SHORE FEDERAL	
	Well #: 16-14 (PJ16)	ID Date: 06/11/07
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 06/11/07
Case #: COC01524	FAC ID:	Abatement Date: 06/12/07
Form: I	FAC NAME:	Corrected Date: 06/11/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 06/11/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with the other orders and instructions of the authorized officer. EnCana Oil and Gas (USA) Inc. failed to comply with the instructions of the authorized officer by not notifying the Glenwood Springs Energy Office personnel 24 hours prior to running the surface casing. Corrective Action: Provide the Glenwood Springs Energy Office with pipe tally showing the size, grade, weight, and thread type of the piping ran for the surface casing. Additionally, provide the location of all centralizers, float collar, and shoe joint.

Office: GS		ID: GS6258
Unique INC #: 070159	Well Name: SHORE FEDERAL	
	Well #: 16-14 (PJ16)	ID Date: 06/11/07
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 06/11/07
Case #: COC01524	FAC ID:	Abatement Date: 06/12/07
Form: I	FAC NAME:	Corrected Date: 06/11/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 06/11/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with the other orders and instructions of the authorized officer. EnCana Oil and Gas (USA) Inc. failed to comply with the instructions of the authorized officer by not notifying the Glenwood Springs Energy Office personnel 24 hours prior to cementing the surface casing. Corrective Action: Provide the Glenwood Springs Energy Office with a cement report from the cementing company with the quantity, type, yield, and density of all cement(s) used for the surface casing. Additionally, provide the amount of cement that was returned to surface and all remedial actions taken.

Office: GS		ID: GS6259
Unique INC #: 070160	Well Name: SHORE FEDERAL	
	Well #: 16-14 (PJ16)	ID Date: 06/11/07
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 06/11/07
Case #: COC01524	FAC ID:	Abatement Date: 06/12/07
Form: I	FAC NAME:	Corrected Date: 06/11/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 06/11/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with the other orders and instructions of the authorized officer. EnCana Oil and Gas (USA) Inc. failed to comply with the instructions of the authorized officer by not notifying the Glenwood Springs Energy Office personnel 24 hours prior to Testing the BOP equipment. Corrective Action: Provide the Glenwood Springs Energy a copy of the BOP test and the pressure charts.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6110
Unique INC #: 070067	Well Name: PLATZER FEDERAL	
	Well #: 43D-27-692	ID Date: 01/10/07
Operator: BILL BARRETT CORPORATION		Effective Date: 01/10/07
Case #: COC15976	FAC ID:	Abatement Date: 01/11/07
Form: I	FAC NAME:	Corrected Date: 01/18/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 01/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 01/10/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations: with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. Notificatoion Requirements Casing String and Cementing - at least twenty-four (24) hors prior to running casing and cementing all casing strings. Properly notify the Glenwood Springs Energy Office of the running of casing and of cementing same at least 24 hours in advance. Provide tally of surface casing ran including depth ran, number of joints, weight and grade, position and length of shoe joint, and position of all centralizers and turbolizers. Complete cement report from the Cementing including the cement(s) used (types, yields, slurry weights, and water per sacks) and the volume of cement returned to surface. Additionally, if the plug was bumped and did it hold.

Office: GS		ID: GS6111
Unique INC #: 070068	Well Name: PLATZER FEDERAL	
	Well #: 43D-27-692	ID Date: 01/10/07
Operator: BILL BARRETT CORPORATION		Effective Date: 01/10/07
Case #: COC15976	FAC ID:	Abatement Date: 01/11/07
Form: I	FAC NAME:	Corrected Date: 01/11/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 01/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 01/10/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. Notification Requirements BOP and Related Equipment Tests - at least twenty four (24) hours prior to initiating pressure tests. Notify the Glenwood Springs Energy Office of the Testing of the BOP at least 24 hours in advance.

Office: GS		ID: GS6239
Unique INC #: 070145	Well Name: FEDERAL	
	Well #: 7-22D (7F)	ID Date: 05/23/07
Operator: NOBLE ENERGY INC		Effective Date: 05/23/07
Case #: COC23443	FAC ID:	Abatement Date: 05/31/07
Form: I	FAC NAME:	Corrected Date: 05/24/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 05/23/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. CONDITIONS OF APPROVAL APPLICATION FOR PERMIYT TO DRILL Spud Notice - at least twenty-four (24) hours prior to running casing and cementing all casing strings. Noble failed to notify this office (Glenwood Springs Energy Office) 24 prior to running and cementing the surface casing string. Corrective action: provide Cementing Company Cement Job Report and casing tally. Casing tally shall have size, weight, grade, and thread type of casing used. Along with location of all centralizers, turbolizers, and the float collar.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6236
Unique INC #: 070142	Well Name: FEDERAL	
	Well #: 7-22D (7F)	ID Date: 05/23/07
Operator: NOBLE ENERGY INC		Effective Date: 05/23/07
Case #: COC23443	FAC ID:	Abatement Date: 05/24/07
Form: I	FAC NAME:	Corrected Date: 05/23/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 05/24/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 05/23/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. CONDITIONS OF APPROVAL APPLICATION FOR PERMIYT TO DRILL Spud Notice - at least twenty-four (24) hours pre and prior to spudding the well. Noble failed to notify this office (Glenwood Springs Energy Office) 24 prior to spudding the well. Corrective action: provide the exact time and date of the spud and the Drilling Company name and the number of the rig used to drill the surface on this well.

Office: GS		ID: GS6246
Unique INC #: 070150	Well Name: FEDERAL	
	Well #: 7-22C (7F)	ID Date: 05/25/07
Operator: NOBLE ENERGY INC		Effective Date: 05/25/07
Case #: COC23443	FAC ID:	Abatement Date: 06/15/07
Form: I	FAC NAME:	Corrected Date: 05/30/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 05/25/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. Noble Energy, Inc. failed to obtain sundry approval to change the surface hole size from 12 1/4" as stated in the Approved Application for Permit to Drill to 11". Submit a sundry (form 3160-5) for approval for the change of surface hole size.

Office: GS		ID: GS6237
Unique INC #: 070143	Well Name: FEDERAL	
	Well #: 7-22C (7F)	ID Date: 05/23/07
Operator: NOBLE ENERGY INC		Effective Date: 05/23/07
Case #: COC23443	FAC ID:	Abatement Date: 05/24/07
Form: I	FAC NAME:	Corrected Date: 05/23/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 05/24/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 05/23/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. CONDITIONS OF APPROVAL APPLICATION FOR PERMIYT TO DRILL Spud Notice - at least twenty-four (24) hours pre and prior to spudding the well. Noble failed to notify this office (Glenwood Springs Energy Office) 24 prior to spudding the well. Corrective action: provide the exact time and date of the spud and the Drilling Company name and the number of the rig used to drill the surface on this well.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6238
Unique INC #: 070144	Well Name: FEDERAL	
	Well #: 7-22C (7F)	ID Date: 05/23/07
Operator: NOBLE ENERGY INC		Effective Date: 05/23/07
Case #: COC23443	FAC ID:	Abatement Date: 05/31/07
Form: I	FAC NAME:	Corrected Date: 05/24/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 05/23/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. CONDITIONS OF APPROVAL APPLICATION FOR PERMIYT TO DRILL Spud Notice - at least twenty-four (24) hours prior to running casing and cementing all casing strings. Noble failed to notify this office (Glenwood Springs Energy Office) 24 prior to running and cementing the surface casing string. Corrective action: provide Cementing Company Cement Job Report and casing tally. Casing tally shall have size, weight, grade, and thread type of casing used. Along with location of all centralizers, turbolizers, and the float collar.

Office: GS		ID: GS6317
Unique INC #: 070177	Well Name: FEDERAL	
	Well #: 7-43B (7G)	ID Date: 09/04/07
Operator: NOBLE ENERGY INC		Effective Date: 09/04/07
Case #: COC23443	FAC ID:	Abatement Date: 09/05/07
Form: I	FAC NAME:	Corrected Date: 09/04/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 09/04/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 09/04/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. CONDITIONS OF APPROVAL APPPLICATION FOR PERMIT TO DRILL BOP and Related - at least twenty-four (24) hours prior to initiating tests. Equipment Tests Operator failed to notify prior to testing of the BOP as per the Conditions of Approval. Corrective action submit copies of the test chart(s) and BOP Test report to this office, Curtail drilling operations until the report has been evaluated and permission from this office has been granted to proceed.

Office: GS		ID: GS6247
Unique INC #: 070151	Well Name: FEDERAL	
	Well #: 7-22D (7F)	ID Date: 05/25/07
Operator: NOBLE ENERGY INC		Effective Date: 05/25/07
Case #: COC23443	FAC ID:	Abatement Date: 06/15/07
Form: I	FAC NAME:	Corrected Date: 05/30/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 05/25/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. Noble Energy, Inc. failed to obtain sundry approval to change the surface hole size from 12 1/4" as stated in the Approved Application for Permit to Drill to 11". Submit a sundry (form 3160-5) for approval for the change of surface hole size.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6245
Unique INC #: 070149	Well Name: FEDERAL	
	Well #: 7-22B (7F)	ID Date: 05/25/07
Operator: NOBLE ENERGY INC		Effective Date: 05/31/07
Case #: COC23443	FAC ID:	Abatement Date: 06/15/07
Form: I	FAC NAME:	Corrected Date: 05/30/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 05/25/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. Noble Energy, Inc. failed to obtain sundry approval to change the surface hole size from 12 1/4" as stated in the Approved Application for Permit to Drill to 11". Submit a sundry (form 3160-5) for approval for the change of surface hole size.

Office: GS		ID: GS6047
Unique INC #: 070026	Well Name: FEDERAL GM	
	Well #: 443-4 (MV8-4)	ID Date: 10/24/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 10/24/06
Case #: COC24603	FAC ID:	Abatement Date: 10/25/06
Form: I	FAC NAME:	Corrected Date: 10/25/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 10/26/06
Gravity: 1		Extend Date:
Authority Ref: O.O.#2 III. A. 2. a. iii.		

Remarks Date: 10/24/06

-2 kill line valves, one of which shall be a check valve (2 inch minimum) Corrective Action: Install a complete valve in the kill line (valve body and VALVE HANDLES)

Office: GS		ID: GS6046
Unique INC #: 070025	Well Name: FEDERAL GM	
	Well #: 443-4 (MV8-4)	ID Date: 10/24/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 10/24/06
Case #: COC24603	FAC ID:	Abatement Date: 10/25/06
Form: I	FAC NAME:	Corrected Date: 10/25/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 10/26/06
Gravity: 1		Extend Date:
Authority Ref: O.O.#2 III. A. 2. a. iii.		

Remarks Date: 10/24/06

-A minimum of 2 choke line valves (2 inch minimum) Corrective Action: Install 2 complete choke line valves (valve bodies and VAVLE HANDLES)

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6048
Unique INC #: 070027	Well Name: FEDERAL GM	
	Well #: 443-4 (MV8-4)	ID Date: 10/24/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 10/24/06
Case #: COC24603	FAC ID:	Abatement Date: 10/25/06
Form: I	FAC NAME:	Corrected Date: 10/24/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 10/26/06
Gravity: 1		Extend Date:
Authority Ref: O.O.#2 III. A. 2. e.		

Remarks Date: 10/24/06

Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. O.O.#2 III. A. 2. c. ii. The 3M system shall have 2 independent power sources to close the preventers.  
Corrective Action: Ensure that both power source are on and available at all times.

Office: GS		ID: GS6049
Unique INC #: 070028	Well Name: FEDERAL GM	
	Well #: 443-4 (MV8-4)	ID Date: 10/24/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 10/24/06
Case #: COC24603	FAC ID:	Abatement Date: 10/25/06
Form: I	FAC NAME:	Corrected Date: 10/25/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 10/26/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2 III. C. 7.		

Remarks Date: 10/24/06

The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees,  
Corrective Action: Install turns that are targeted with running tees. AS THEY ARE ALREADY IN ZONES OF POTENTIAL GAS, THIS ACTION IS TO BE COMPLETED PRIOR TO THE NEXT WELL.

Office: GS		ID: GS6092
Unique INC #: 070050	Well Name: WILLIAMS GM	
	Well #: 643-35(GV21-35)	ID Date: 12/07/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 12/07/06
Case #: COC27743	FAC ID:	Abatement Date: 12/08/06
Form: I	FAC NAME:	Corrected Date: 12/07/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 12/11/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. g.		

Remarks Date: 12/07/06

A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. Corrective Action: Install a valve in the closing line as close as possible to the annular preventer.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6093
Unique INC #: 070051	Well Name: WILLIAMS GM	
	Well #: 643-35(GV21-35)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC27743	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. C.		

Remarks Date: 12/07/06

Sufficient quantities of mud materials shall be maintained or readily accessible for the purpose of assuring well control. Obtain sufficient quantities of mud materials and have them readily accessible.

Office: GS		ID: GS6316
Unique INC #: 070176	Well Name: RPE	
	Well #: 12-19-595	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC44963	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 08/27/07

The operating rights owner or operator , as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. DOWNHOLE CONDITIONS OF APPROVAL: Please contact Steve Ficklin (970-947-5213) or Jennifer Gallegos (970-947-5220) of the Glenwood Springs Energy office at least 24 hours: 1) pre- and post-spud Operator failed to notify as per the conditions of approval. Corrective action: 1. Submit the required notification. 2. Perform a CBL on the Surface casing and submit the log to this office for evaluation prior to drilling out the surface shoe.

Office: GS		ID: GS6099
Unique INC #: 070057	Well Name: FEDERAL GM	
	Well #: 22-35 (1-M-35)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC55363	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FICKLIN	
Gravity: 3		
Authority Ref: O.O. #2 III. A. 2. c. ii.		

Remarks Date: 12/14/06

The 3M system shall have 2 independent sources to close the preventers. Nitrogen bottles (3 minimum) may be 1 of the independent power sources and, if so, shall maintain a charge equal to the manufacturer's specifications.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6100
Unique INC #: 070058	Well Name: FEDERAL GM	
	Well #: 22-35 (1-M-35)	ID Date: 12/14/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 12/14/06
Case #: COC55363	FAC ID:	Abatement Date: 12/15/06
Form: I	FAC NAME:	Corrected Date: 12/14/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 12/15/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 12/14/06

Minimum standards and enforcement provisions for well control equipment. -Safety valve and subs to fit all drill string connections is use Have available on the rig floor safety valves as required and in the open position at all times.

Office: GS		ID: GS6098
Unique INC #: 070056	Well Name: FEDERAL GM	
	Well #: 22-35 (1-M-35)	ID Date: 12/14/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 12/14/06
Case #: COC55363	FAC ID:	Abatement Date: 12/14/06
Form: I	FAC NAME:	Corrected Date: 12/14/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 12/15/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 12/14/06

Minimum standards and enforcement provisions for well control equipment. - A minimum of 2 choke line valves ( 3 inch minimum) Install 2 complete choke line valves as per the requirement.

Office: GS		ID: GS6254
Unique INC #: 070155	Well Name: SHIDELER FEDERAL	
	Well #: 43D-29-692(9-29)	ID Date: 06/06/07
Operator: BILL BARRETT CORPORATION		Effective Date: 06/06/07
Case #: COC56027	FAC ID:	Abatement Date: 06/07/07
Form: I	FAC NAME:	Corrected Date: 06/06/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 06/06/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with the other orders and instructions of the authorized officer. Bill Barrett Corporation failed to comply with the instructions of the authorized officer by not notifying the Glenwood Springs Energy Office personnel 24 hours prior to cementing the surface casing. Corrective Action: Submit cement report from cementing company with the quantity, type, yield, density, and water requirements of cement(s) used in the cementing of the surface casing. Additionally, the amount of cement returned to surface if any and any remedial actions that were performed.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6255
Unique INC #: 070156	Well Name: SHIDELER FEDERAL	
	Well #: 43D-29-692(9-29)	ID Date: 06/06/07
Operator: BILL BARRETT CORPORATION		Effective Date: 06/06/07
Case #: COC56027	FAC ID:	Abatement Date: 06/07/07
Form: I	FAC NAME:	Corrected Date: 06/06/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 06/06/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with the other orders and instructions of the authorized officer. Bill Barrett Corporation failed to comply with the instructions of the authorized officer by not notifying the Glenwood Springs Energy Office personnel 24 hours prior to Testing the BOP Equipment. Corrective Action: Run a Cement bond log on the surface casing and submit the log to the Glenwood Springs Energy Office Petroleum Engineer for evaluation. After the Engineer has determined the casing cement meets the minimum requirements, then testing of the BOP Equipment may begin.

Office: GS		ID: GS6253
Unique INC #: 070154	Well Name: SHIDELER FEDERAL	
	Well #: 43D-29-692(9-29)	ID Date: 06/06/07
Operator: BILL BARRETT CORPORATION		Effective Date: 06/06/07
Case #: COC56027	FAC ID:	Abatement Date: 06/07/07
Form: I	FAC NAME:	Corrected Date: 06/06/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 06/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 06/06/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with lease terms, Onshore Oil and Gas Orders, NTL's; and with the other orders and instructions of the authorized officer. Bill Barrett Corporation failed to comply with the instructions of the authorized officer by not notifying the Glenwood Springs Energy Office personnel 24 hours prior to running the surface casing. Corrective Action: Submit casing tally with size, weight, grade, and thread type of casing ran. Additionally, it shall show location of centralizers, float collar, and shoe joint.

Office: GS		ID: GS6225
Unique INC #: 070136	Well Name: CHEVRON GM	
	Well #: 314-20	ID Date: 04/23/07
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 04/23/07
Case #: COC56545	FAC ID:	Abatement Date: 04/30/07
Form: I	FAC NAME:	Corrected Date: 05/03/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 05/04/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 04/23/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations: with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. CONDITIONS OF APPROVAL APPLICATION FOR PERMIT TO DRILL Please contact Steve Ficklin (970) 947-5213 or Jennifer Gallegos (970) 947-5220, of the Glenwood Springs Energy Office at least 24 hours: 1. pre- and post- spud 2. prior to running the surface and production casing 3. conducting the BOP test No notice of conducting BOP test was received by the Glenwood Springs Energy Office personnel. Corrective Action: Submit to this office copies of the BOP test results and copies of all charts from the test.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6224
Unique INC #: 070135	Well Name: CHEVRON GM	
	Well #: 314-20	ID Date: 04/23/07
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 04/23/07
Case #: COC56545	FAC ID:	Abatement Date: 04/30/07
Form: I	FAC NAME:	Corrected Date: 04/23/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 04/23/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 04/23/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. CONDITIONS OF APPROVAL APPLICATION FOR PERMIT TO DRILL Please contact Steve Ficklin (970) 947-5213 or Jennifer Gallegos (970) 947-5220, of the Glenwood Springs Energy Office at least 24 hours: 1. pre- and post- spud 2. prior to running the surface and production casing 3. conducting the BOP test No post-spud contact was received by the Glenwood Springs Energy Office personnel. Corrective Action: Submit an E-Mail with the exact time and date of the spud. An E-Mail has been received by this office with the time and date of the spud on 4/23/2007.

Office: GS		ID: GS6018
Unique INC #: 070005	Well Name: LEVERICH FEDERAL	
	Well #: 31-07A (31-01)	ID Date: 10/17/06
Operator: PETROGULF CORPORATION		Effective Date: 10/17/06
Case #: COC64181	FAC ID:	Abatement Date: 10/17/06
Form: I	FAC NAME:	Corrected Date: 10/17/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 10/18/06
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 10/17/06

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL'S; and with other orders and instructions of the authorized officeThe Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Spud Notice - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office the exact time and date of the spud of this well (Federal 31-41-14).

Office: GS		ID: GS6020
Unique INC #: 070007	Well Name: LEVERICH FEDERAL	
	Well #: 31-07A (31-01)	ID Date: 10/17/06
Operator: PETROGULF CORPORATION		Effective Date: 10/17/06
Case #: COC64181	FAC ID:	Abatement Date: 10/27/06
Form: I	FAC NAME:	Corrected Date: 10/27/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 12/15/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 10/17/06

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL'S; and with other orders and instructions of the authorized officeThe Approved Application for Permit to Drill Conditions of Approval Notification Requirements. BOP and Related Equipment Tests - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office a report and a copy of the chart(s) for the BOPE test.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS			ID: GS6019
Unique INC #: 070006	Well Name: LEVERICH FEDERAL		
	Well #: 31-07A (31-01)	ID Date:	10/17/06
Operator: PETROGULF CORPORATION		Effective Date:	10/17/06
Case #: COC64181	FAC ID:	Abatement Date:	10/27/06
Form: I	FAC NAME:	Corrected Date:	10/27/06
Assessment: \$0	Inspector: FICKLIN	Followup Date:	12/15/06
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 10/17/06

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL'S; and with other orders and instructions of the authorized officeThe Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Casing String and Cementing - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office a Casing Report detailing the size, grade, type, and weight used for the surface casing. 2. Submit to the Glenwood Springs Energy Office a Cement Report detailing the type, quantity, and yield of cement used when cementing the surface casing. Additionally, if you got cement returns to surface and the quantity.

Office: GS			ID: GS6023
Unique INC #: 070010	Well Name: LEVERICH FEDERAL		
	Well #: 31-07B (31-01)	ID Date:	10/17/06
Operator: PETROGULF CORPORATION		Effective Date:	10/17/06
Case #: COC64181	FAC ID:	Abatement Date:	10/27/06
Form: I	FAC NAME:	Corrected Date:	10/27/06
Assessment: \$0	Inspector: FICKLIN	Followup Date:	12/15/06
Gravity: 3		Extend Date:	
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 10/17/06

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL'S; and with other orders and instructions of the authorized officeThe Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Casing String and Cementing - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office a Casing Report detailing the size, grade, type, and weight used for the surface casing. 2. Submit to the Glenwood Springs Energy Office a Cement Report detailing the type, quantity, and yield of the cement used when cementing the surface casing. Additionally, if you got cement returned to surface and the quantity.

Office: GS			ID: GS6022
Unique INC #: 070009	Well Name: LEVERICH FEDERAL		
	Well #: 31-07B (31-01)	ID Date:	10/17/06
Operator: PETROGULF CORPORATION		Effective Date:	10/17/06
Case #: COC64181	FAC ID:	Abatement Date:	10/18/06
Form: I	FAC NAME:	Corrected Date:	10/17/06
Assessment: \$0	Inspector: FICKLIN	Followup Date:	10/18/06
Gravity: 1		Extend Date:	
Authority Ref: 43 CFR 3162.1 (a)			

Remarks Date: 10/17/06

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL'S; and with other orders and instructions of the authorized officeThe Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Spud Notice - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office the exact time and date of the spud of this well (Federal 31-41-22).

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6024
Unique INC #: 070011	Well Name: LEVERICH FEDERAL	
	Well #: 31-07B (31-01)	ID Date: 10/17/06
Operator: PETROGULF CORPORATION		Effective Date: 10/17/06
Case #: COC64181	FAC ID:	Abatement Date: 10/27/06
Form: I	FAC NAME:	Corrected Date: 10/27/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 12/15/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 10/17/06

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL'S; and with other orders and instructions of the authorized officeThe Approved Application for Permit to Drill Conditions of Approval Notification Requirements. BOP and Related Equipment Tests - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office a report and a copy of the chart(s) for the BOPE test.

Office: GS		ID: GS6021
Unique INC #: 070008	Well Name: LEVERICH FEDERAL	
	Well #: 31-07A (31-01)	ID Date: 10/17/06
Operator: PETROGULF CORPORATION		Effective Date: 10/17/06
Case #: COC64181	FAC ID:	Abatement Date: 10/27/06
Form: I	FAC NAME:	Corrected Date: 10/27/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 12/15/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 10/17/06

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL'S; and with other orders and instructions of the authorized officeThe Approved Application for Permit to Drill Conditions of Approval Notification Requirements. Casing String and Cementing - at least twenty-four (24) hours prior to spudding the well. Corrective action: 1. Submit to the Glenwood Springs Energy Office a Casing Report detailing the size, grade, type, and weight used for the production casing. 2. Submit to the Glenwood Springs Energy Office a Cement Report detailing the type, quantity, and yield of cement used when cementing the production casing. Additionally, copies of logs showing top of cement.

Office: GS		ID: GS6184
Unique INC #: 070111	Well Name: FIVE R FEDERAL	
	Well #: 14-5 (D14OU)	ID Date: 03/14/07
Operator: ENCANAS OIL & GAS (USA) INC		Effective Date: 03/14/07
Case #: COC66496X	FAC ID:	Abatement Date: 03/14/07
Form: I	FAC NAME:	Corrected Date: 03/14/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 03/19/07
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 03/14/07

Minimum standards and enforcement provisions for well control equipment. 3M systems: - 2 kill line valves, one of which shall be a check valve (2 inch minimum)\* Install complete valve(s) in the kill line as required by regulation. Complete valve(s) means all parts to the valve including the handle. Valve is not considered a valve unless it has a handle on it.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6186
Unique INC #: 070113	Well Name: FIVE R FEDERAL	
	Well #: 14-5 (D14OU)	ID Date: 03/14/07
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 03/14/07
Case #: COC66496X	FAC ID:	Abatement Date: 03/15/07
Form: I	FAC NAME:	Corrected Date: 03/14/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 03/19/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 03/14/07

Minimum standards and enforcement provisions for well control equipment. 3M systems: - 2 chokes (refer to diagram in Attachment 1) Install complete valve(s) in the choke manifold as per the regulations. Complete valve(s) means all parts to the valve including the handle. Valve is not considered a valve unless it has a handle on it.

Office: GS		ID: GS6185
Unique INC #: 070112	Well Name: FIVE R FEDERAL	
	Well #: 14-5 (D14OU)	ID Date: 03/14/07
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 03/14/07
Case #: COC66496X	FAC ID:	Abatement Date: 03/15/07
Form: I	FAC NAME:	Corrected Date: 03/14/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 03/19/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.		

Remarks Date: 03/14/07

Minimum standards and enforcement provisions for well control equipment. 3M systems: - 2 chokes Install complete choke(s) as required by regulation. Complete choke(s) means all parts to the choke including the handle. Choke is not considered a choke unless it has a handle on it.

Office: GS		ID: GS6169
Unique INC #: 070102	Well Name: HIDDEN CREEK WEST	
	Well #: 23-6(14-14)	ID Date: 03/07/07
Operator: LARAMIE ENERGY LLC		Effective Date: 03/07/07
Case #: COC66918	FAC ID:	Abatement Date: 03/08/07
Form: I	FAC NAME:	Corrected Date: 03/08/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 03/21/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1 (a)		

Remarks Date: 03/07/07

The operator shall conduct operations in a manner which protects the mineral resources, other natural resources, and the environmental quality. Failed to maintain 2 feet of freeboard in the reserve pit. Remove sufficient quantities of fluid from the reserve pit to maintain at least 2 feet of freeboard.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6101
Unique INC #: 070059	Well Name: HIDDEN CREEK WEST	
	Well #: 23-4(14-14)	ID Date: 12/14/06
Operator: LARAMIE ENERGY LLC		Effective Date: 12/14/06
Case #: COC66918	FAC ID:	Abatement Date: 12/15/06
Form: I	FAC NAME:	Corrected Date: 12/14/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 12/15/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. e..		

Remarks Date: 12/14/06

The 3M system shall have 2 independent power sources to close the preventers. Power for the closing unit pumps shall be available to the closing unit at all times so that the pump shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Turn the Air (second independent power source) on to the accumulator and maintain it on at all times.

Office: GS		ID: GS6168
Unique INC #: 070101	Well Name: HIDDEN CREEK WEST	
	Well #: 23-6(14-14)	ID Date: 03/07/07
Operator: LARAMIE ENERGY LLC		Effective Date: 03/07/07
Case #: COC66918	FAC ID:	Abatement Date: 03/08/07
Form: I	FAC NAME:	Corrected Date: 03/07/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 03/21/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. B. 1. d.		

Remarks Date: 03/07/07

(c. The surface casing shall be cemented back to surface either during the primary cement job or by remedial cementing.) All of the above described tests shall be recorded in the drilling log. The cementing of the surface casing was not recorded in the IADC (drilling log). Provide proof that the cement used was as per the APD and that the cement came up to surface and the amount of cement that was returned to surface.

Office: GS		ID: GS6164
Unique INC #: 070098	Well Name: HIDDEN CREEK WEST	
	Well #: 23-6(14-14)	ID Date: 03/07/07
Operator: LARAMIE ENERGY LLC		Effective Date: 03/07/07
Case #: COC66918	FAC ID:	Abatement Date: 03/08/07
Form: I	FAC NAME:	Corrected Date: 03/07/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 03/21/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. 2. d.		

Remarks Date: 03/07/07

Minimum standards and enforcement provisions for accumulator precharge pressure test. This test shall be conducted prior to connecting the closing unit to the BOP stack and at least once every 6 months. The Accumulator Precharge was last gauged 7/10/2006 more than 6 months prior. Gauge (test) the precharge and maintain record of the date.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS ID: GS6163  
Unique INC #: 070097 Well Name: HIDDEN CREEK WEST ID Date: 03/07/07  
Well #: 23-6(14-14) Effective Date: 03/08/07  
Operator: LARAMIE ENERGY LLC Abatement Date: 03/08/07  
Case #: COC66918 FAC ID: Corrected Date: 03/07/07  
Form: I FAC NAME: Followup Date: 03/21/07  
Assessment: \$0 Inspector: FICKLIN Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. C.

Remarks Date: 03/07/07

Sufficient quantities of mud materials shall be maintained or readily accessible for the purpose of assuring well control. Only six pallets of Barite were readily accessible. Maintain at least half the required amount accessible.

Office: GS ID: GS6165  
Unique INC #: 070099 Well Name: HIDDEN CREEK WEST ID Date: 03/07/07  
Well #: 23-6(14-14) Effective Date: 03/07/07  
Operator: LARAMIE ENERGY LLC Abatement Date: 03/08/07  
Case #: COC66918 FAC ID: Corrected Date: 03/08/07  
Form: I FAC NAME: Followup Date: 03/21/07  
Assessment: \$0 Inspector: FICKLIN Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. A. 2. i. vii.

Remarks Date: 03/07/07

Annular preventers shall be functionally operated at least weekly. Annular had not been functioned since the BOP test. Functionally operate the annular weekly. Record functioning annular in the IADC (drilling log).

Office: GS ID: GS6161  
Unique INC #: 070096 Well Name: HIDDEN CREEK WEST ID Date: 03/07/07  
Well #: 23-6(14-14) Effective Date: 03/07/07  
Operator: LARAMIE ENERGY LLC Abatement Date: 03/08/07  
Case #: COC66918 FAC ID: Corrected Date: 03/08/07  
Form: I FAC NAME: Followup Date: 03/21/07  
Assessment: \$0 Inspector: FICKLIN Extend Date:  
Gravity: 1  
Authority Ref: O.O. #2 III. C. 7.

Remarks Date: 03/07/07

All Flare systems shall be designed to gather and burn all gas. The Flare Line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. Flare Lines were not Anchored. Anchor the Flare Lines to prevent movement of the lines when in use.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: GS		ID: GS6113
Unique INC #: 070070	Well Name: PLATZER FEDERAL	
	Well #: 43D-27-692	ID Date: 01/17/07
Operator: BILL BARRETT CORPORATION		Effective Date: 01/17/07
Case #: COC69595	FAC ID:	Abatement Date: 01/18/07
Form: I	FAC NAME:	Corrected Date: 01/17/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 01/25/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 01/17/07

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulation; with the lease terms, Onshore Oil and Gas Orders, NTL's: and with other orders and instructions of the authorized officer. A copy of the approved application for permit to drill (APD), including the conditions of approval and accompanying surface use plan will be furnished to the field representative by the operator to insure compliance and will be available to authorized personnel at the drill site whenever active construction or drilling operations are underway. Furnish the field representative with a complete approved application for permit to drill (APD).

Office: GS		ID: GS6114
Unique INC #: 070071	Well Name: PLATZER FEDERAL	
	Well #: 43D-27-692	ID Date: 01/17/07
Operator: BILL BARRETT CORPORATION		Effective Date: 01/17/07
Case #: COC69595	FAC ID:	Abatement Date: 01/18/07
Form: I	FAC NAME:	Corrected Date: 01/17/07
Assessment: \$0	Inspector: FICKLIN	Followup Date: 01/25/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. c. ii.		

Remarks Date: 01/17/07

The 3M system shall have 2 independent power sources to close the preventers. Provide a second source of power to the accumulator in addition to the electric system. Ensure that the second and first sources of power are on and available at all times.

Office: HO		ID: HO11794
Unique INC #: SJC-A0207	Well Name: MEYER B-28 A COM A/C-2	
	Well #: 05	ID Date: 03/12/07
Operator: PLANTATION OPERATING LLC		Effective Date: 03/19/07
Case #: NMNM2511	FAC ID:	Abatement Date: 04/19/07
Form: I	FAC NAME:	Corrected Date: 04/10/07
Assessment: \$2,000	Inspector: CAFFEY	Followup Date: 04/10/07
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1b.		

Remarks Date: 03/12/07

Well was being drilled without an Approved Drilling Plan (APD)

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: HO		ID: HO11791
Unique INC #: SJC-A-0107	Well Name: NMGBSA UNIT	
	Well #: 348	ID Date: 03/12/07
Operator: APACHE CORPORATION		Effective Date: 03/19/07
Case #: NMNM85324X	FAC ID:	Abatement Date: 04/19/07
Form: I	FAC NAME:	Corrected Date: 04/20/07
Assessment: \$5,000	Inspector: CAFFEY	Followup Date: 04/20/07
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1b.2		

Remarks Date: 03/12/07

Well was drilled without an Approved Drilling Plan (APD)

Office: HO		ID: HO11751
Unique INC #: KAH-040-07	Well Name: CE LA MUNYON FED	
	Well #: 87, 88	ID Date: 03/05/07
Operator: POGO PRODUCING COMPANY		Effective Date: 03/12/07
Case #: NMLC030187	FAC ID:	Abatement Date: 03/20/07
Form: I	FAC NAME:	Corrected Date: 03/12/07
Assessment: \$0	Inspector: HASTON	Followup Date: 03/12/07
Gravity: 3		Extend Date:
Authority Ref: APD-Conditions of Approval-Drilling		

Remarks Date: 03/05/07

FAILURE TO COMPLY WITH "CONDITIONS OF APPROVAL-DRILLING" TO NOTIFY THE BUREAU OF LAND MANAGEMENT, HOBBS FIELD STATION OF NOTICE OF SPUD, NOTIFICATION WITH SUFFICIENT TIME FOR BLM REPRESENTATIVE TO WITNESS CEMENTING OF 8 5/8" SURFACE CASING AND NOTIFICATION OF BOP TEST WHICH WAS TO BE CONDUCTED BY AN INDEPENDENT SERVICE COMPANY. -- SIGN AND RETURN INCIDENT OF NONCOMPLIANCE AND RETURN TO THE HOBBS FIELD STATION, 414 W. TAYLOR, HOBBS, NM 88240. ON ALL FEDERAL WELLS DRILLED PROVIDE NOTIFICATION OF REQUIRED ACTIVITIES PER "CONDITIONS OF APPROVAL - DRILLING" (COA'S) TO APPROPRIATE OFFICE. FAILURE TO COMPLY WITH COA'S WILL RESULT IN MONETARY ASSESSMENTS.

Office: HO		ID: HO11531
Unique INC #: KAH-009-07	Well Name: HAWK A-4	
	Well #: 04	ID Date: 11/14/06
Operator: APACHE CORPORATION		Effective Date: 11/21/06
Case #: NMLC031741A	FAC ID:	Abatement Date: 12/15/06
Form: I	FAC NAME:	Corrected Date: 11/27/06
Assessment: \$0	Inspector: HASTON	Followup Date: 11/27/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 11/14/06

WELL IDENTIFICATION SIGN HAS WRONG FEDERAL LEASE SERIAL NUMBER "NM031741A". -- CORRECT INFORMATION ON WELL IDENTIFICATION SIGN TO REFLECT CORRECT FEDERAL LEASE SERIAL NUMBER "LC031741A".

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: HO ID: HO11922  
Unique INC #: KAH-055-07 Well Name: FEDERAL 4  
Well #: 02 ID Date: 04/19/07  
Operator: MAR OIL & GAS CORPORATION Effective Date: 04/26/07  
Case #: NMNM0100236A FAC ID: A Abatement Date: 05/24/07  
Form: I FAC NAME: #2 FEDERAL 4 BTRY Corrected Date: 06/04/07  
Assessment: \$0 Inspector: HASTON Followup Date: 06/04/07  
Gravity: 3 Extend Date: 06/25/07  
Authority Ref: OOGO #6.III.D.2.e

Remarks Date: 04/19/07

NO WIND DIRECTION INDICATOR INSTALLED AT BATTERY. -- INSTALL A WIND DIRECTION INDICATOR AT THIS BATTERY AND PROPERLY INSTALL DANGER SIGNS.

Office: HO ID: HO12146  
Unique INC #: KAH-076-07 Well Name: SOUTHEAST LUSK 34 FED  
Well #: 05 ID Date: 08/14/07  
Operator: EDGE PETROLEUM OPERATING CO,IN Effective Date: 08/21/07  
Case #: NMNM01135 FAC ID: Abatement Date: 09/21/07  
Form: I FAC NAME: Corrected Date: 09/27/07  
Assessment: \$0 Inspector: HASTON Followup Date: 09/27/07  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 08/14/07

WELL IDENTIFICATION SIGN DOES NOT CONTAIN ALL REQUIRED INFORMATION. -- ADD FEDERAL LEASE NUMBER "NM01135" TO WELL IDENTIFICATION SIGN (SEE ATTACHMENT)

Office: JA ID: JA2010  
Unique INC #: CB-07-019A Well Name: USA (MM) SWD  
Well #: 93 ID Date: 11/21/06  
Operator: EOG RESOURCES INCORPORATED Effective Date:  
Case #: LABLMA24527 FAC ID: Abatement Date: 11/22/06  
Form: I FAC NAME: Corrected Date: 11/21/06  
Assessment: \$0 Inspector: CHARLES R BOYD Followup Date: 11/22/06  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Oil & Gas Order #2, Part III.A.2.d

Remarks Date: 11/21/06

PRECHARGE ON ACCUMULATOR WAS FOUND TO BE BELOW THE MINIMUM ALLOWED BY REGULATION (850#). OPEERATOR IS ORDERED TO REPAIR AND BRING PRECHATGE INTO COMPLIANCE WITRH REGULATIONS. >OR = 900# AND <OR = 1100#)

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: JA ID: JA2007  
Unique INC #: CB-07-012A Well Name: USA ID Date: 11/02/06  
Well #: 71-ALT Effective Date: 11/02/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 11/03/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 11/03/06  
Form: I FAC NAME: Followup Date: 11/06/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.x  
  
Remarks Date: 11/02/06  
  
THE RIGHT WING VALVE ON THE CHOKE MANIFOLD JUST UPSTREAM FROM THE HYDRALIC CHOKE FAILED TO HOLD THE LOW PRESSURE TEST AS REQUIRED. OPERATOR IS ORDERED TO REPLACE THIS VALVE WITHIN 24 HOURS OF THIS NOTICE.

Office: JA ID: JA1939  
Unique INC #: CRB-06-004 Well Name: USA ID Date: 11/14/05  
Well #: 36-ALT Effective Date: 11/14/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 11/15/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 11/15/06  
Form: I FAC NAME: Followup Date: 11/16/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore O & G Order #2 Part III.A.2.d  
  
Remarks Date: 11/14/05  
  
PRECHARGE ON ACCUMULATOR WAS FOUND TO BE BELOW THE ALLOWABLE LIMITS AS SET FORTH IN THE ORDER. PRECHARGE MUST BE WITHIN THE RANGE OF NOT LESS THAN 900 PSI NOR GREATER THAN 1100 PSI. OPERATOR IS ORDERED TO REPAIR UNIT WITHIN 24 HOURS OF THIS NOTICE.

Office: KM ID: KM884  
Unique INC #: 07INC062 Well Name: SAGEBRUSH ID Date: 08/02/07  
Well #: 60-26 Effective Date: 08/02/07  
Operator: CABOT OIL & GAS CORPORATION Abatement Date:  
Case #: WYW24153 FAC ID: Corrected Date: 08/15/07  
Form: I FAC NAME: Followup Date: 10/12/07  
Assessment: \$250 Inspector: PRINGLE Extend Date:  
Gravity: 3  
Authority Ref: APD, COA ,#1.  
  
Remarks Date: 08/02/07

Cementing operations were not conducted according to the aproved plan in APD. The plan called for the tail cement to be class "G" cement with a yield of 1.17 CU.FT/ SK., looked up in the Halliburton Red Book calls for 15.8 ppg cement to be used. The cement that was actually used on the tail cementing was only 14.6 ppg cement.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: ME ID: ME2145  
Unique INC #: 07BH15MEFO Well Name: PICEANCE CREEK UNIT  
Well #: T87X-3G6  
Operator: EXXON MOBIL CORP ID Date: 11/21/06  
Case #: COC47666A Effective Date: 12/04/06  
Form: I Abatement Date: 12/11/06  
Assessment: \$250 FAC ID: Corrected Date: 12/11/06  
Gravity: 3 FAC NAME: Followup Date: 12/11/06  
Authority Ref: 43CFR 3162.1(a) Extend Date:  
  
Remarks Date: 11/21/06

43CFR 3162.1(a) General Requirements. operator has failed to comply with onshore oil and gas order no. 1. ( III.3.F.) A copy of the approved form 3160-3 and the pertinent drilling plan, along with any conditions of approval, shall be at the drill site.

Office: ME ID: ME2143  
Unique INC #: 07BH13MEFO Well Name: PICEANCE CREEK UNIT  
Well #: T87X-3G6  
Operator: EXXON MOBIL CORP ID Date: 11/21/06  
Case #: COC47666A Effective Date: 12/04/06  
Form: I Abatement Date: 12/11/06  
Assessment: \$250 FAC ID: Corrected Date: 12/11/06  
Gravity: 3 FAC NAME: Followup Date: 12/11/06  
Authority Ref: 43CFR 3162.1(a) Extend Date:  
  
Remarks Date: 11/21/06

43CFR 3162.1(a) General Requirements. Operator failed to follow verbal orders and instructions of the authorized officer. When cementing the surface casing, Leon Thomas was instructed to call me if there was any problems or if cement did not circulate to surface.

Office: ME ID: ME2144  
Unique INC #: 07BH14MEFO Well Name: PICEANCE CREEK UNIT  
Well #: T87X-3G6  
Operator: EXXON MOBIL CORP ID Date: 11/21/06  
Case #: COC47666A Effective Date: 12/04/06  
Form: I Abatement Date: 12/11/06  
Assessment: \$250 FAC ID: Corrected Date: 12/11/06  
Gravity: 3 FAC NAME: Followup Date: 12/11/06  
Authority Ref: 43 CFR 3162.1(a) Extend Date:  
  
Remarks Date: 11/21/06

43CFR 3162.1(a) General Requirements. Operator failed to comply with the conditions of approval. 24 hr notice is required prior to BOPE and casing string pressure tests.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: ME ID: ME2146  
Unique INC #: 07BH16MEFO Well Name: PICEANCE CREEK UNIT  
Well #: 297-10A5  
Operator: EXXON MOBIL CORP ID Date: 11/21/06  
Case #: COC47666A Effective Date: 12/04/06  
Form: I Abatement Date: 12/11/06  
Assessment: \$0 FAC ID: Corrected Date: 12/13/06  
Gravity: 3 FAC NAME: Followup Date: 12/13/06  
Authority Ref: 43CFR3162.6(a) Extend Date:  
  
Remarks Date: 11/21/06  
43CFR 3162.6 (a) Well site is not properly identified. No sign is posted.

Office: ME ID: ME2147  
Unique INC #: 07BK10MEFO Well Name: FLETCHER GULCH  
Well #: 3-13  
Operator: GENESIS GAS & OIL, LLC ID Date: 11/27/06  
Case #: COC68958X Effective Date: 12/04/06  
Form: I Abatement Date: 01/05/07  
Assessment: \$0 FAC ID: Corrected Date: 01/05/07  
Gravity: 1 FAC NAME: Followup Date: 01/05/07  
Authority Ref: 43CFR3162.1(a) Extend Date:  
  
Remarks Date: 11/27/06  
Failure to comply with the approved APD, I-Conditions of Approval #1: To contact the Petroleum Engineering technician 24 hours prior to running surface casing

Office: ME ID: ME2150  
Unique INC #: 07BK13MEFO Well Name: FLETCHER GULCH  
Well #: 3-13  
Operator: GENESIS GAS & OIL, LLC ID Date: 11/27/06  
Case #: COC68958X Effective Date: 12/04/06  
Form: I Abatement Date: 01/05/07  
Assessment: \$1,000 FAC ID: Corrected Date: 01/05/07  
Gravity: 1 FAC NAME: Followup Date: 01/05/07  
Authority Ref: 43CFR3162.1(a) Extend Date:  
  
Remarks Date: 11/27/06  
Failure to comply with the approved APD, I-Conditions of Approval #1: To contact the Petroleum Engineering technician 24 hours prior to running and cementing the production casing. Submit the casing tally and cement report by the abatement date.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: ME ID: ME2149  
Unique INC #: 07BK12MEFO Well Name: FLETCHER GULCH ID Date: 11/27/06  
Well #: 3-13 Effective Date: 12/04/06  
Operator: GENESIS GAS & OIL, LLC Abatement Date: 01/05/07  
Case #: COC68958X FAC ID: Corrected Date: 01/05/07  
Form: I FAC NAME: Followup Date: 01/05/07  
Assessment: \$1,000 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1(a)

Remarks Date: 11/27/06

Failure to comply with the approved APD, I-Conditions of Approval #1: To contact the Petroleum Engineering technician 24 hours prior to testing the BOP'S. Submit all of the test records by the abatement date.

Office: ME ID: ME2148  
Unique INC #: 07BK11MEFO Well Name: FLETCHER GULCH ID Date: 11/27/06  
Well #: 3-13 Effective Date: 12/04/06  
Operator: GENESIS GAS & OIL, LLC Abatement Date: 01/05/07  
Case #: COC68958X FAC ID: Corrected Date: 01/05/07  
Form: I FAC NAME: Followup Date: 01/05/07  
Assessment: \$1,000 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1(a)

Remarks Date: 11/27/06

Failure to comply with the approved APD, I-Conditions of Approval #1: To contact the Petroleum Engineering technician 24 hours prior to cementing the surface casing. Submit casing and cementing reports by the abatement date.

Office: MI ID: MI1537  
Unique INC #: JTW-07-026 Well Name: USA SMITH ID Date: 09/19/07  
Well #: 1 Effective Date: 09/21/07  
Operator: HEINRICH CARL Abatement Date: 09/28/07  
Case #: OHES46389 FAC ID: A Corrected Date: 09/26/07  
Form: I FAC NAME: USA SMITH Followup Date: 10/03/07  
Assessment: \$0 Inspector: WOOD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 09/19/07

The Area around the tanks, both inside and outside of the diked area, are overgrown with vegetation, and this creates a safety hazard, due to potential fires, as well as a tripping hazard. The area needs to be mowed and or weed whacked, and this should be done on a routine basis. Failure to comply will result in a monetary assessment.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: ML		ID: ML3467
Unique INC #: CD07-002	Well Name: BR EDEBURN	
	Well #: 14X-35	ID Date: 01/09/07
Operator: HEADINGTON OIL, LP		Effective Date: 01/10/07
Case #: MTM91390	FAC ID:	Abatement Date: 01/11/07
Form: I	FAC NAME:	Corrected Date: 01/11/07
Assessment: \$0	Inspector: DEVAULT/NANSEL	Followup Date: 01/12/07
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3164.1(b), O.O.#2.III.C.7.		

Remarks Date: 01/09/07

The flare system is not hooked up correctly. The flare line off the choke manifold only goes to the small gas buster in the 1st mud tank, and the line coming off the top of this is just set on top of this gas buster instead of being properly installed. Then this line comes down and ends next to the mud tank and shale shaker. The panic line from the manifold is just stubbed out about 15'. Gas coming from either one of these lines would leave the gas all around the mud tank and shaker. They have a large gas buster that had the gas line off the top run all the way to the flare pit. They just didn't run a line from the manifold to this buster. The only line that was run to this gas buster was from a tee in the flow line. According to Headington, they plan to run the line from the manifold to this main gas buster and run the panic line all the way out. The regulation states in part: All flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tés, and shall be positioned downwind of the prevailing wind direction and shall be anchored. The flare system shall have an effective method for ignition.

Office: ML		ID: ML3466
Unique INC #: CD07-001	Well Name: BR EDEBURN	
	Well #: 14X-35	ID Date: 01/09/07
Operator: HEADINGTON OIL, LP		Effective Date: 01/10/07
Case #: MTM91390	FAC ID:	Abatement Date: 01/11/07
Form: I	FAC NAME:	Corrected Date: 01/11/07
Assessment: \$0	Inspector: DEVAULT/NANSEL	Followup Date: 01/12/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3164.1(b), O.O.#2.III.A.2.g.		

Remarks Date: 01/09/07

There are no handwheels installed on the rams. The regulation states: "A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2,000 psi or greater."

Office: MO		ID: MO3575
Unique INC #: JB07004	Well Name: TANK CANYON	
	Well #: 1-9	ID Date: 01/22/07
Operator: RODDY PRODUCTION COMPANY INC		Effective Date: 02/05/07
Case #: UTU84347	FAC ID:	Abatement Date: 02/07/07
Form: I	FAC NAME:	Corrected Date: 02/09/07
Assessment: \$0	Inspector: J BROWN	Followup Date: 02/09/07
Gravity: 3		Extend Date: 02/09/07
Authority Ref: 43 CFR 3162.5-1a & APD surface use plan		

Remarks Date: 01/22/07

Failure to construct fence and install netting material as per APD approval.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: MR		ID: MR1385
Unique INC #: SJ-07-ML08	Well Name: SLICK ROCK FED	
	Well #: 8-23-43-17	ID Date: 04/16/07
Operator: ENCANAS OIL & GAS (USA) INC		Effective Date: 04/16/07
Case #: COC57063	FAC ID:	Abatement Date: 04/17/07
Form: I	FAC NAME:	Corrected Date: 04/17/07
Assessment: \$0	Inspector: LOPE	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: Onshore Order No 2,III.A.2.d		

Remarks Date: 04/16/07

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. The accumulator precharge pressure test shall be conducted prior to connecting the closing unit to the BOP stack and at least every 6 months. Perform test. Upon witnessing the accumulator function test, Single Jack Tester: Jim Hays and I discovered that out of 12 nitrogen bottles, at least 2 bottles had a leak and need to be fixed.

Office: MR		ID: MR1380
Unique INC #: SJC-ML-01	Well Name: HC FED	
	Well #: 7-14-44-14	ID Date: 10/27/06
Operator: ENCANAS OIL & GAS (USA) INC		Effective Date: 10/27/06
Case #: COC70179	FAC ID:	Abatement Date: 10/30/06
Form: I	FAC NAME:	Corrected Date: 09/26/07
Assessment: \$0	Inspector: LOPE	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: Onshore Order 2,III.A.2.d		

Remarks Date: 10/27/06

On October 19 & 20th, 2006, I witnessed the BOP test on this well. Scott Dayhoff with Rebel Testing Inc. did the test. When we did the accumulator function test we found there was 10 nitrogen bottles and 2 bottles were empty and 3 bottles had pressure of 1000#, 2 with 1050#, 2 with 900# and 1 with 1100#. I was told by Glenn Jochim, Encana Company Rep. that the nitrogen bottles would be on location, tested and installed, however today October 27, 2006, I got an email and the nitrogen bottles have not been replaced or filled and tested yet.

Office: NE		ID: NE3722
Unique INC #: JDH07012DI	Well Name: FEDERAL	
	Well #: 12-18	ID Date: 03/07/07
Operator: SLAWSON EXPLORATION CO INC		Effective Date: 03/08/07
Case #: WYW160866	FAC ID:	Abatement Date: 03/15/07
Form: I	FAC NAME:	Corrected Date: 03/15/07
Assessment: \$0	Inspector: HUTCHINSON	Followup Date: 03/30/07
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/07/07

Failure to comply with the Surface Use Conditions of Approval in the APD. Specifically item D.2. which requires the rat and mouse holes to be filled and compacted from bottom to top immediately upon release of the drilling rig from the location. The rat hole is currently open. An inspection summary with photos is enclosed for your reference.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: NE ID: NE3719  
Unique INC #: JDH07009DI Well Name: FEDERAL ID Date: 03/07/07  
Well #: 12-18 Effective Date: 03/08/07  
Operator: SLAWSON EXPLORATION CO INC Abatement Date: 03/28/07  
Case #: WYW160866 FAC ID: Corrected Date: 03/28/07  
Form: I FAC NAME: Followup Date: 03/30/07  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6

Remarks Date: 03/07/07

A well identification sign is not on the well site. Please install sign in accordance with 43 CFR 3162.6.

Office: NE ID: NE3720  
Unique INC #: JDH07010DI Well Name: FEDERAL ID Date: 03/07/07  
Well #: 12-18 Effective Date: 03/08/07  
Operator: SLAWSON EXPLORATION CO INC Abatement Date: 03/15/07  
Case #: WYW160866 FAC ID: Corrected Date: 03/15/07  
Form: I FAC NAME: Followup Date: 03/30/07  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 03/07/07

Failure to comply with the Surface Use Conditions of Approval in the APD. Specifically item B.11. which requires the reserve pit to be fenced on three sides during the drilling operation and the fourth side is to be fenced upon rig release. An inspection summary with photos is enclosed for your reference.

Office: NE ID: NE3721  
Unique INC #: JDH07011DI Well Name: FEDERAL ID Date: 03/07/07  
Well #: 12-18 Effective Date: 03/08/07  
Operator: SLAWSON EXPLORATION CO INC Abatement Date: 03/15/07  
Case #: WYW160866 FAC ID: Corrected Date: 03/15/07  
Form: I FAC NAME: Followup Date: 03/30/07  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 03/07/07

Failure to comply with the Surface Use Conditions of Approval in the APD. Specifically item D.1. which requires that all trash will be contained in a portable trash cage. No trash will be placed in the reserve pit. A pallet is currently in the pit along with other cups, etc. Some trash is also blown off the well pad to the south east. An inspection summary with photos is enclosed for your reference.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: PD		ID: PD2265
Unique INC #: 56DF091807	Well Name: WARBONNET	
	Well #: 6D1-9D	ID Date: 09/18/07
Operator: ULTRA RESOURCES INC		Effective Date: 09/19/07
Case #: WYW015316	FAC ID:	Abatement Date: 09/20/07
Form: I	FAC NAME:	Corrected Date: 09/29/07
Assessment: \$0	Inspector: FALLO	Followup Date: 09/29/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III.2.a.iv		

Remarks Date: 09/18/07

Found: During a drilling inspection of H&P Rig #286 it was found that the dart valve was missing the inside rod and thus inoperative. Corrective Action: The dart valve or inside BOP shall be available, in working order, and in the open position.

Office: PD		ID: PD2261
Unique INC #: 52DF082107	Well Name: GREEN RIVER BEND UNIT	
	Well #: 272-36H	ID Date: 08/21/07
Operator: EOG RESOURCES INCORPORATED		Effective Date: 08/24/07
Case #: WYW109537B	FAC ID:	Abatement Date: 09/05/07
Form: I	FAC NAME:	Corrected Date: 09/10/07
Assessment: \$0	Inspector: FALLO	Followup Date: 09/10/07
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)		

Remarks Date: 08/21/07

Found: During a cementing well inspection of rig # SST 17, on GRBU 272-36H, it was found no centralizers were ran on the intermediate casing string as required in the approved drilling plan. Corrective Action: The operating rights owner or operators shall comply with applicable laws and regulations: with the lease terms, Onshore Orders, NTL's, and with other orders and instructions of the authorized officer.

Office: PD		ID: PD2096
Unique INC #: 29DF092606	Well Name: GRB	
	Well #: 265-20H	ID Date: 09/26/06
Operator: EOG RESOURCES INCORPORATED		Effective Date: 10/03/06
Case #: WYW109537B	FAC ID:	Abatement Date: 10/03/06
Form: I	FAC NAME:	Corrected Date: 10/02/06
Assessment: \$0	Inspector: FALLO	Followup Date: 10/10/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III.C.7.		

Remarks Date: 09/26/06

Found: During a detailed rig inspection it was discovered the flare line(s) of True Rig #31 had no ignition source. Corrective action: The Flare system shall have an effective method for ignition. Where noncombustible gas is likely or expected to be vented, the system shall be provided supplemental fuel for ignition and to maintain a continuous flare.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: PD		ID: PD2262
Unique INC #: 53DF082907	Well Name: MESA	
	Well #: 14-18DD	ID Date: 08/29/07
Operator: ANSCHUTZ PINEDALE CORP		Effective Date: 08/30/07
Case #: WYW135123	FAC ID:	Abatement Date: 09/01/07
Form: I	FAC NAME:	Corrected Date: 08/29/07
Assessment: \$0	Inspector: FALLO	Followup Date: 09/10/07
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III.A.2.i.iv.D.		

Remarks Date: 08/29/07

Found: It was found that Ensign Rig 89 did not perform a BOP test at 30 day intervals as required by Onshore Order #2. Corrective Action: Rig was called and told to perform a BOP test as directed.

Office: PD		ID: PD2119
Unique INC #: 06DF112006	Well Name: JONAH FEDERAL	
	Well #: 27-4	ID Date: 11/20/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 11/21/06
Case #: WYW57521	FAC ID:	Abatement Date: 11/22/06
Form: I	FAC NAME:	Corrected Date: 11/21/06
Assessment: \$0	Inspector: FALLO	Followup Date: 11/21/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III.C.3.		

Remarks Date: 11/20/06

Found: During a detailed rig inspection of Ensign 76, it was discovered that while drilling in zones where high pressure may be encountered, the alarms for the flow and pit volume totalizers were off. According to Onshore Order #2, "When abnormal pressures are anticipated, electronic/mechanical mud monitoring equipment shall be required, which shall include as a minimum; pit volume totalizer (PVT); stroke counter; and flow sensor." Corrective action: When anticipating abnormal pressures all alarms shall be on and functional.

Office: PD		ID: PD2120
Unique INC #: 07DF112006	Well Name: JONAH FEDERAL	
	Well #: 27-4	ID Date: 11/20/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 11/22/06
Case #: WYW57521	FAC ID:	Abatement Date: 11/30/06
Form: I	FAC NAME:	Corrected Date: 12/01/06
Assessment: \$0	Inspector: FALLO	Followup Date: 12/01/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2 III.B.1.i.		

Remarks Date: 11/20/06

Found: During a detailed inspection of Ensign Rig #76, it was discovered that no pressure integrity test, or mud weight equivalency test, was preformed after setting surface casing. Corrective Action: Discovery happened after drilling more than twenty feet below the shoe; hence no MWE test will be required during this well. However, it is the insistence of the Pinedale Field Office to follow all regulations outlined in Onshore Order number 2. Including: O.O.#2 III.B.1.i., "On all exploratory wells, and on that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be preformed. Formation at the shoe shall be tested to a minimum of the mud weight equivalent anticipated to control the formation pressure to the next casing depth or at total depth of the well. This test shall be preformed before drilling more than 20 feet of new hole.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: PD		ID: PD2100
Unique INC #: 1RK1006	Well Name: TOT FEDERAL	
	Well #: 1	ID Date: 10/11/06
Operator: YATES PETROLEUM CORPORATION		Effective Date: 10/17/06
Case #: WYW143045	FAC ID:	Abatement Date: 10/20/06
Form: I	FAC NAME:	Corrected Date: 10/18/06
Assessment: \$0	Inspector: FALLON/KNIGHT	Followup Date: 10/20/06
Gravity: 3		Extend Date:
Authority Ref: O.O. 2.III.A.g.		

Remarks Date: 10/11/06

Found: During a BOP test on Cyclone Rig 2 on 10/02/2006, I informed the company man that the hand wheels needed to be installed on the valves of the choke manifold. On 10/11/2006 during a Detailed Inspection on Cyclone Rig 2, I found that a hand wheel was still not on the valve. Onshore Order 2 states that "A manual locking device, (i.e., hand wheels) or automatic locking device shall be installed on all systems of 2M or greater." Corrective Action: Repair and replace the hand wheel on the valve, as per Onshore Order #2.

Office: PD		ID: PD2098
Unique INC #: 01DF101106	Well Name: BILLY CANYON	
	Well #: 2-11	ID Date: 10/11/06
Operator: GASCO ENERGY INC		Effective Date: 10/12/06
Case #: WYW159279X	FAC ID:	Abatement Date: 10/12/06
Form: I	FAC NAME:	Corrected Date: 10/23/06
Assessment: \$0	Inspector: FALLON/KNIGHT	Followup Date: 10/26/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III.C.7.		

Remarks Date: 10/11/06

Found: During a detailed rig inspection of Nabors Rig # 267, it was discovered the flare line was not anchored and no source of ignition was present. According to Onshore Orders number 2, "...The Flare line discharge...and shall be anchored. The flare system shall have an effective method for ignition. Where noncombustible gas is likely or expected to be vented, the system shall be provided supplemental fuel for ignition and to maintain a continuous flare." Corrective Action: Please install effective method for ignition and anchor flare line.

Office: PD		ID: PD2099
Unique INC #: 02DF101106	Well Name: BILLY CANYON	
	Well #: 2-11	ID Date: 10/11/06
Operator: GASCO ENERGY INC		Effective Date: 10/17/06
Case #: WYW159279X	FAC ID:	Abatement Date: 10/17/06
Form: I	FAC NAME:	Corrected Date: 10/23/06
Assessment: \$0	Inspector: FALLON/KNIGHT	Followup Date: 10/26/06
Gravity: 3		Extend Date:
Authority Ref: O.O. # 2 III.A.2.xi.		

Remarks Date: 10/11/06

Found: During a detailed drilling inspection, documentation was missing in the driller's log book as follows: 1. Annular preventer activated weekly and recorded in the driller's log. 2. Pipe rams activated each trip and recorded in the driller's log. 3. Blind rams activated each trip and recorded in the driller's log. 4. BOP drills conducted weekly and recorded in the driller's log. Note: On a non-detailed inspection occurring 08/24/06, a hand-out was provided to Nabors Rig # 267 that detailed the requirements of documentation in the driller's log. This sheet was located on 10/11/06 in the co-man's trailer and was posted as requested by the inspector, in the dog house. Corrective action: Perform all the above described tests and/or drills and record in the driller's log book.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: PD		ID: PD2221
Unique INC #: 24DF040207	Well Name: YELLOW POINT	
	Well #: 42-13	ID Date: 04/02/07
Operator: ENCANA OIL & GAS USA INC		Effective Date: 04/11/07
Case #: WYW141883	FAC ID:	Abatement Date: 04/11/07
Form: I	FAC NAME:	Corrected Date: 04/11/07
Assessment: \$5,000	Inspector: FALLON/MCLAREN	Followup Date: 04/24/07
Gravity: 1		Extend Date:
Authority Ref: 43CFR3163.1(b)(2)		

Remarks Date: 04/02/07

Found: This well was directionally drilled without approval of the authorized officer. The well was permitted as a vertical well and production casing was cemented on 03/19/07. The Pinedale Field Office received a notice of intent sundry request on 03/22/2007, requesting the well be changed to a directional well. According to the attached Conditions of Approval, #3," Major deviations from the drilling plan require prior approval from the BLM." Assessments for this violation will be assessed at \$500.00/day from 03/10/07, the day drilling reportedly resumed from under the surface shoe, until 03/19/07 the day production casing was reportedly ran and cemented.

Office: PD		ID: PD2256
Unique INC #: MRM07001	Well Name: RIVERSIDE	
	Well #: 10D-23	ID Date: 07/25/07
Operator: ULTRA RESOURCES INC		Effective Date: 08/03/07
Case #: WYE026025	FAC ID:	Abatement Date: 08/06/07
Form: I	FAC NAME:	Corrected Date: 07/26/07
Assessment: \$0	Inspector: MCLAREN	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1		

Remarks Date: 07/25/07

Ultra Resources, Inc. has made unapproved changes to the drilling program on the Riverside 10D-23 well. The hole diameters, casing size, grade and weight has been changed for the surface and intermediate casings than approved on the APD. These changes have already been implemented by the drilling rig on location. The Conditions of Approval attached to the approved APD state on item #3 "Major deviations from the drilling plan require prior approval from the BLM." Changes to hole sizes and casings are considered major changes to the drilling plan. Conditions of approval are an order of the Authorized Officer; therefore Ultra Resources has failed to comply with an order of the authorized officer. Ultra Resources has submitted a sundry notice for approval that reflects these changes to the hole sizes and casing changes; therefore the corrective action required has been completed. This incident has been discussed by telephone with Terry Allen of Ultra Resources.

Office: PD		ID: PD2103
Unique INC #: LAW06072	Well Name: WARBONNET	
	Well #: 10A-10D	ID Date: 10/24/06
Operator: ULTRA RESOURCES INC		Effective Date: 10/25/06
Case #: WYW015314	FAC ID:	Abatement Date: 10/26/06
Form: I	FAC NAME:	Corrected Date: 10/26/06
Assessment: \$0	Inspector: WALDO	Followup Date: 10/26/06
Gravity: 3		Extend Date:
Authority Ref: OO 2.III.A.2.g.		

Remarks Date: 10/24/06

Problem: No handle on the valve installed in the closing line of the annular preventer to act as a locking device. Corrective action: Install handle on the valve installed on the annular preventer to act as a locking device.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: PD ID: PD2105  
Unique INC #: LAW06074 Well Name: WARBONNET  
Well #: 10A-10D ID Date: 10/25/06  
Operator: ULTRA RESOURCES INC Effective Date: 10/26/06  
Case #: WYW015314 FAC ID: Abatement Date: 10/27/06  
Form: I FAC NAME: Corrected Date: 10/26/06  
Assessment: \$0 Inspector: WALDO Followup Date: 10/26/06  
Gravity: 3 Extend Date:  
Authority Ref: OO2.III.A.2.i.xi.

Remarks Date: 10/25/06

Problem: Pipe and blind rams shall be activated each trip and recorded in the drilling log. Corrective action: Record function test of the pipe and blind rams in the drilling log when tripping. This function test need not be performed more than once a day.

Office: PD ID: PD2104  
Unique INC #: LAW06073 Well Name: WARBONNET  
Well #: 10A-10D ID Date: 10/25/06  
Operator: ULTRA RESOURCES INC Effective Date: 10/26/06  
Case #: WYW015314 FAC ID: Abatement Date: 10/27/06  
Form: I FAC NAME: Corrected Date: 10/26/06  
Assessment: \$0 Inspector: WALDO Followup Date: 10/26/06  
Gravity: 3 Extend Date:  
Authority Ref: OO2.III.A.2.g.

Remarks Date: 10/25/06

Problem: No hand wheels on the inside valves of the BOP to kill line and manifold. Corrective action: Install hand wheels on manual locking devices.

Office: PD ID: PD2106  
Unique INC #: LAW06075 Well Name: WARBONNET  
Well #: 14-14D ID Date: 10/25/06  
Operator: SWEPI LP Effective Date: 10/26/06  
Case #: WYW015314 FAC ID: Abatement Date: 10/27/06  
Form: I FAC NAME: Corrected Date: 10/26/06  
Assessment: \$0 Inspector: WALDO Followup Date: 10/26/06  
Gravity: 3 Extend Date:  
Authority Ref: OO2.III.A.2.i.xi.

Remarks Date: 10/25/06

Nabors 797 Problem: A BOP pit level drill shall be conducted weekly for each drilling crew and recored in the drilling log. Corrective action: Record drills in the drilling log.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: PD ID: PD2253  
Unique INC #: LAW07040 Well Name: WARBONNET  
Well #: 4B-11D  
Operator: ULTRA RESOURCES INC  
Case #: WYW016162 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO  
Gravity: 3  
Authority Ref: O.O. 2 III.A.2.g.

Remarks Date: 07/20/07

Problem: No hand wheels on the 10M BOP. Corrective action: A manual locking device (i.e. hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater.

Office: PD ID: PD2255  
Unique INC #: LAW07042 Well Name: WARBONNET  
Well #: 4B-11D  
Operator: ULTRA RESOURCES INC  
Case #: WYW016162 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO  
Gravity: 3  
Authority Ref: OO 2 III.A.2.a.v.

Remarks Date: 07/20/07

Problem: Choke manifold has only 2 chokes, one manual and one remote. Corrective action: 10 & 15M systems: - 3 chokes, one being remotely controlled. See attached diagram. Install additional choke when safe to do.

Office: PD ID: PD2254  
Unique INC #: LAW07041 Well Name: WARBONNET  
Well #: 4B-11D  
Operator: ULTRA RESOURCES INC  
Case #: WYW016162 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO  
Gravity: 3  
Authority Ref: OO 2 III.A.2.b.

Remarks Date: 07/20/07

Problem: No anchors on the choke lines. Corrective action: All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, and shall be anchored to prevent whip and reduce vibration.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: PD		ID: PD2260
Unique INC #: LAW07043	Well Name: MESA	
	Well #: 14-18DD	ID Date: 08/13/07
Operator: ANSCHUTZ PINEDALE CORP		Effective Date: 08/13/07
Case #: WYW135123	FAC ID:	Abatement Date: 08/14/07
Form: I	FAC NAME:	Corrected Date: 08/14/07
Assessment: \$0	Inspector: WALDO	Followup Date: 08/15/07
Gravity: 3		Extend Date:
Authority Ref: OO 2.III.A.2.a.v.		

Remarks Date: 08/13/07

Problem: No Pressure Gauge On Choke Manifold. Corrective Action: Install pressure gauge on Choke Manifold (mud serviceable)

Office: PD		ID: PD2110
Unique INC #: LAW06076	Well Name: WARBONNET	
	Well #: 1B-6DST	ID Date: 11/07/06
Operator: SWEPI LP		Effective Date: 11/08/06
Case #: WYW144996	FAC ID:	Abatement Date: 11/09/06
Form: I	FAC NAME:	Corrected Date: 11/08/06
Assessment: \$0	Inspector: WALDO	Followup Date: 11/20/06
Gravity: 3		Extend Date:
Authority Ref: OO#2 III.A.2.i.viii&xi.		

Remarks Date: 11/07/06

Nabors 169 Problem: Pipe rams activation not recorded in the driller's log. Corrective action: Record activation of pipe rams when tripping out of hole in driller's log.

Office: PD		ID: PD2111
Unique INC #: LAW06077	Well Name: WARBONNET	
	Well #: 1B-6DST	ID Date: 11/07/06
Operator: SWEPI LP		Effective Date: 11/08/06
Case #: WYW144996	FAC ID:	Abatement Date: 11/09/06
Form: I	FAC NAME:	Corrected Date: 11/08/06
Assessment: \$0	Inspector: WALDO	Followup Date: 11/20/06
Gravity: 3		Extend Date:
Authority Ref: OO#2 III.A.2.i.viii&xi.		

Remarks Date: 11/07/06

Nabors 169 Problem: Blind rams activation not recorded in driller's logs when tripping out of the hole. Corrective action: Record activation of Blind ram in driller's log.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RP		ID: RP5215
Unique INC #: 06RR	Well Name: SAN ISIDRO 16	
	Well #: 8	ID Date: 12/11/06
Operator: HIGH PLAINS PETROLEUM CORP		Effective Date: 12/11/06
Case #: NMNM105185	FAC ID:	Abatement Date: 12/11/06
Form: I	FAC NAME:	Corrected Date: 12/11/06
Assessment: \$0	Inspector: ROMERO	Followup Date: 12/26/06
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1 (b)(1)		

Remarks Date: 12/11/06

During cementing inspection it was noted that drilling operations were being conducted with no BOPE equipment installed. Install approved BOPE prior to commencing operations.

Office: RW		ID: RW4236
Unique INC #: JND07004	Well Name: WM KYLE	
	Well #: 1	ID Date: 07/26/07
Operator: SONOMA ENERGY CORPORATION		Effective Date:
Case #: WYC032201A	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 08/02/07
Assessment: \$0	Inspector: DULL	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 07/26/07

On June 15, 2005, in a telephone conversation between Mr. Robbie Walters and Jon Dull, Robbie Walters indicated that he would prepare a plugging and abandonment (P&A) procedure for the referenced wells. On June 29, 2005 Sundry Notices of Intent to Abandon, outlining the P&A procedure for each of the wells, were received by this office. On July 12, 2005 these sundries were approved by this office and returned to Sonoma Energy Corporation (Sonoma). Again on July 27, 2006, in a telephone conversation between Jon Dull and Robbie Walters, Robbie Walters said that he would submit sundries to this office outlining the time frame in which he intended to accomplish the approved P&A work. On September 12, 2006 we sent Sonoma Energy Corporation a certified letter. Unsuccessful delivery attempts of the certified letter were made on September 14 and 30, 2006. On October 3, 2006 the letter was returned to this office undelivered. On October 27, 2006 you received the letter via Federal Express (see attachment). In the letter Sonoma was ordered by the authorized officer to file a reasonable time plan in which you intend to accomplish the already approved P&A work for each of the referenced wells. On November 8, 2006 we received a Sundry Notices of Intent (SNOI) to recomplete each of the referenced wells. No time frame for accomplishing the newly proposed work was included within the SNOIs or your accompanying cover letter. On November 20, 2006 the SNOIs for each of the wells were returned to you approved with Conditions of Approval (COA) (see attachment). COA number 8 attached to each of the SNOIs states the following: This Notice of Intent to Recomplete the above referenced well is valid through June 30, 2007. Should the recompletion effort prove unsuccessful, Sonoma Energy Corporation will promptly proceed with plugging and abandonment of the subject well per previously approved abandonment procedure received by this office June 25, 2005 and approved by this office July 12, 2005. Should Sonoma Energy Corporation not be able to comply with the deadline set forth in this paragraph, this office must be notified adequately in advance of the deadline and Sonoma Energy Corporation must show justification for any requested time extension. Following COA number 8 the following statement was made: This is an order of the Authorized Officer. Failure to comply will result in the issuance of an incident of noncompliance pursuant to 43 CFR 3162.1(a). In accordance with 43 CFR 3165.3(b) you have the right to request an administrative review before the State Director regarding this order or an informal review of the technical or procedural aspects of this order may be requested of the issuing officer before initiating a formal review request. We consider Sonoma's disregard to the COAs attached to each of the SNOIs as 2 separate incidents of noncompliance. In a telephone conversation on July 26, 2007 between Robbie Walters and Jon Dull, Robbie Walters w

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW4240  
Unique INC #: AME26-2007 Well Name: CHAMBERS FEDERAL ID Date: 08/01/07  
Well #: 9-24 Effective Date: 08/01/07  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 08/08/07  
Case #: WYW110120 FAC ID: Corrected Date: 08/02/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: ELSER Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III. A. 2. d.

Remarks Date: 08/01/07

Accumulator bottles have not been precharge pressure tested within the last 6 months as required. Test bottles as per OO#2 III. A. 2. d.

Office: RW ID: RW4239  
Unique INC #: AME25-2007 Well Name: CHAMBERS FEDERAL ID Date: 08/01/07  
Well #: 9-24 Effective Date: 08/01/07  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 08/31/07  
Case #: WYW110120 FAC ID: Corrected Date: 08/16/07  
Form: I FAC NAME: Followup Date: 08/22/07  
Assessment: \$0 Inspector: ELSER Extend Date:  
Gravity: 3  
Authority Ref: COA

Remarks Date: 08/01/07

Culvert ends not marked. Install permanent markers at each end of the road culverts as per Conditions of Approval.

Office: RW ID: RW4251  
Unique INC #: AME32-2007 Well Name: WIND DANCER UNIT ID Date: 09/12/07  
Well #: 34-29 Effective Date: 09/12/07  
Operator: GMT EXPLORATION COMPANY LLC Abatement Date: 09/13/07  
Case #: WYW157385X FAC ID: Corrected Date: 09/12/07  
Form: I FAC NAME: Followup Date: 09/13/07  
Assessment: \$0 Inspector: ELSER Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III. C. 7.

Remarks Date: 09/12/07

Flare lines not properly anchored; no ignition source for flare system. Anchor flare lines and install flare ignition system.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW4243  
Unique INC #: AME27-2007 Well Name: CRESTON NOSE ID Date: 08/13/07  
Well #: 6-18 Effective Date: 08/13/07  
Operator: DEVON ENERGY PRODUCTION CO LP Abatement Date: 08/15/07  
Case #: WYW38437 FAC ID: Corrected Date: 08/15/07  
Form: I FAC NAME: Followup Date: 08/16/07  
Assessment: \$0 Inspector: ELSER Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III. A. 2. g.

Remarks Date: 08/13/07

Hand wheels not installed on choke manifold manual valves. Install hand wheels.

Office: RW ID: RW4247  
Unique INC #: AME30-2007 Well Name: COAL GULCH J ID Date: 08/16/07  
Well #: 50 Effective Date: 08/16/07  
Operator: BP AMERICA PRODUCTION COMPANY Abatement Date: 08/17/07  
Case #: WYW39294 FAC ID: Corrected Date: 08/17/07  
Form: I FAC NAME: Followup Date: 08/17/07  
Assessment: \$0 Inspector: ELSER Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III. A. 2. g.

Remarks Date: 08/16/07

Valve not installed on closing line of annular preventer. Install valve as per Onshore Order #2 III. A. 2. g.

Office: RW ID: RW4246  
Unique INC #: AME29-2007 Well Name: COAL GULCH J ID Date: 08/16/07  
Well #: 50 Effective Date: 08/16/07  
Operator: BP AMERICA PRODUCTION COMPANY Abatement Date: 08/17/07  
Case #: WYW39294 FAC ID: Corrected Date: 08/17/07  
Form: I FAC NAME: Followup Date: 08/17/07  
Assessment: \$0 Inspector: ELSER Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III. A. 2. d.

Remarks Date: 08/16/07

During BOP test the nitrogen bottles for the accumulator system failed to pass inspection. Bottles were also out of date for individual precharge pressure test. BP representaitve Steve Farnes agreed to have bottles brought into compliance by 1000 hrs on 8/17/07.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW3882  
Unique INC #: CWMC2406 Well Name: N BATTLE SPRINGS UNIT  
Well #: 1-31 ID Date: 08/28/06  
Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
Case #: WYW168845X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
Gravity: 3 Corrected Date: 10/11/06  
Authority Ref: APD- Add. Permit. Requirements Followup Date: 09/28/06  
Remarks Date: 08/28/06 Extend Date: 10/06/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 12 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 12 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Office: RW ID: RW3886  
Unique INC #: CWMC2706 Well Name: N BATTLE SPRINGS UNIT  
Well #: 1-31 ID Date: 08/28/06  
Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
Case #: WYW168845X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
Gravity: 3 Corrected Date: 10/03/06  
Authority Ref: APD- Add. Permit. Requirements Followup Date: 09/28/06  
Remarks Date: 08/28/06 Extend Date: 10/06/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 15 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 15 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Office: RW ID: RW3871  
Unique INC #: CWMC1906 Well Name: N BATTLE SPRINGS UNIT  
Well #: 1-31 ID Date: 08/28/06  
Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
Case #: WYW168845X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
Gravity: 3 Corrected Date: 10/11/06  
Authority Ref: APD-Add. Permit. Requirements Followup Date: 09/28/06  
Remarks Date: 08/28/06 Extend Date: 10/06/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 8 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 8 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW3887  
 Unique INC #: CWMC2806 Well Name: N BATTLE SPRINGS UNIT  
 Well #: 1-31 ID Date: 08/28/06  
 Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
 Case #: WYW168845X FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
 Gravity: 3 Corrected Date: 10/11/06  
 Authority Ref: APD- Add. Permit. Requirements Followup Date: 09/28/06  
 Extend Date: 10/06/06

Remarks Date: 08/28/06

A second culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 10 of 19. Neither culvert is installed at this time, 8-30-2006, 1400 hrs. Install second culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 10 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Office: RW ID: RW3874  
 Unique INC #: CWMC2106 Well Name: N BATTLE SPRINGS UNIT  
 Well #: 1-31 ID Date: 08/28/06  
 Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
 Case #: WYW168845X FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
 Gravity: 3 Corrected Date: 10/11/06  
 Authority Ref: APD- Add. Permit. Requirements Followup Date: 09/28/06  
 Extend Date: 10/06/06

Remarks Date: 08/28/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 10 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 10 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Office: RW ID: RW3873  
 Unique INC #: CWMC2006 Well Name: N BATTLE SPRINGS UNIT  
 Well #: 1-31 ID Date: 08/28/06  
 Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
 Case #: WYW168845X FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
 Gravity: 3 Corrected Date: 10/03/06  
 Authority Ref: APD-Add. Permit. Requirements Followup Date: 10/06/06  
 Extend Date: 10/06/06

Remarks Date: 08/28/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 9 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 9 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW3885  
 Unique INC #: CWMC2606 Well Name: N BATTLE SPRINGS UNIT  
 Well #: 1-31 ID Date: 08/28/06  
 Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
 Case #: WYW168845X FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
 Gravity: 3 Corrected Date: 10/11/06  
 Authority Ref: APD- Add. Permit. Requirements Followup Date: 09/28/06  
 Extend Date: 10/06/06

Remarks Date: 08/28/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 14 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 14 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Office: RW ID: RW3888  
 Unique INC #: CWMC2906 Well Name: N BATTLE SPRINGS UNIT  
 Well #: 1-31 ID Date: 08/28/06  
 Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
 Case #: WYW168845X FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
 Gravity: 3 Corrected Date: 10/11/06  
 Authority Ref: APD-Add. Permit. Requirements Followup Date: 09/28/06  
 Extend Date: 10/06/06

Remarks Date: 08/28/06

Gravel on road is not up to APD standards, as per the Additional Permitting Requirements, sub part Access Roads to be Constructed and Reconstructed, sub part 9. or not on road at all. Gravel road going to lease as per the Additional Permitting Requirements, sub part Access Roads to be Constructed and Reconstructed, sub part 9.

Office: RW ID: RW3884  
 Unique INC #: CWMC2506 Well Name: N BATTLE SPRINGS UNIT  
 Well #: 1-31 ID Date: 08/28/06  
 Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
 Case #: WYW168845X FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
 Gravity: 3 Corrected Date: 10/03/06  
 Authority Ref: APD- Add. Permit. Requirements Followup Date: 09/28/06  
 Extend Date: 10/06/06

Remarks Date: 08/28/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 13 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 13 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW4227  
Unique INC #: WJS14-2007 Well Name:  
Well #: ID Date: 07/18/07  
Operator: ANADARKO E & P COMPANY LP Effective Date: 07/25/07  
Case #: WYW110166 FAC ID: 1-6 Abatement Date: 08/24/07  
Form: I FAC NAME: FAIR FEDERAL Corrected Date: 08/27/07  
Assessment: \$0 Inspector: SAUERESSIG Followup Date: 08/27/07  
Gravity: 3 Extend Date:  
Authority Ref: OO#4.III.C.1.a

Remarks Date: 07/18/07

Theft hatch pressure seal not functioning.

Office: RW ID: RW3958  
Unique INC #: AW07-3 Well Name: WERTZ MCDERMOTT  
Well #: 10R ID Date: 12/16/06  
Operator: MERIT ENERGY COMPANY Effective Date: 12/16/06  
Case #: WYC029630B FAC ID: Abatement Date: 12/16/06  
Form: I FAC NAME: Corrected Date: 12/16/06  
Assessment: \$0 Inspector: WHITE Followup Date: 12/16/06  
Gravity: 3 Extend Date:  
Authority Ref: COA

Remarks Date: 12/16/06

The APD was not on location when inspected. Operator went to HQ and retrieved APD.

Office: RW ID: RW4238  
Unique INC #: AW07-19 Well Name: CHAMBERS FEDERAL  
Well #: 7-24 ID Date: 07/20/07  
Operator: ANADARKO E & P COMPANY LP Effective Date: 07/20/07  
Case #: WYW110120 FAC ID: Abatement Date: 08/31/07  
Form: I FAC NAME: Corrected Date: 08/16/07  
Assessment: \$0 Inspector: WHITE Followup Date: 08/21/07  
Gravity: 3 Extend Date:  
Authority Ref: COA

Remarks Date: 07/20/07

Mark culvert ends.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW3967  
Unique INC #: AW07-08 Well Name: BAUMGARTNER FEDERAL ID Date: 02/08/07  
Well #: 4-6 Effective Date: 02/08/07  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 02/09/07  
Case #: WYW110122 FAC ID: Corrected Date: 03/13/07  
Form: I FAC NAME: Followup Date: 04/03/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III.A.2.g.

Remarks Date: 02/08/07

No valve installed on closing line of Annular preventer. Install valve.

Office: RW ID: RW3964  
Unique INC #: AW07-05 Well Name: BAUMGARTNER FEDERAL ID Date: 02/08/07  
Well #: 4-6 Effective Date: 02/08/07  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 02/10/07  
Case #: WYW110122 FAC ID: Corrected Date: 03/13/07  
Form: I FAC NAME: Followup Date: 04/03/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: COA #7 (e)

Remarks Date: 02/08/07

Alot of trash on and off location. Remove all trash on and off location.

Office: RW ID: RW3965  
Unique INC #: AW07-06 Well Name: BAUMGARTNER FEDERAL ID Date: 02/08/07  
Well #: 4-6 Effective Date: 02/08/07  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 02/09/07  
Case #: WYW110122 FAC ID: Corrected Date: 03/13/07  
Form: I FAC NAME: Followup Date: 04/03/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III.A.2.b.

Remarks Date: 02/08/07

Flare line is not anchored. Anchor flare line to prevent whip and reduce vibration.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: RW ID: RW3966  
Unique INC #: AW07-07 Well Name: BAUMGARTNER FEDERAL ID Date: 02/08/07  
Well #: 4-6 Effective Date: 02/08/07  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 02/09/07  
Case #: WYW110122 FAC ID: Corrected Date: 03/13/07  
Form: I FAC NAME: Followup Date: 04/03/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: OO#2 III.A.2.g.

Remarks Date: 02/08/07

No hand wheels on ram preventers. Locking devices ( hand wheels) shall be installed on all systems of 2M or greater.

Office: RW ID: RW4234  
Unique INC #: AW07-18 Well Name: COAL GULCH ID Date: 07/30/07  
Well #: 3-32 Effective Date: 07/30/07  
Operator: DEVON ENERGY PRODUCTION CO LP Abatement Date: 08/27/07  
Case #: WYW13325 FAC ID: Corrected Date: 08/07/07  
Form: I FAC NAME: Followup Date: 08/21/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: COA

Remarks Date: 07/30/07

Trash on location.

Office: RW ID: RW4195  
Unique INC #: AW14-07 Well Name: RED DESERT ID Date: 06/01/07  
Well #: 14A-8 Effective Date: 06/01/07  
Operator: DEVON ENERGY PRODUCTION CO LP Abatement Date: 06/15/07  
Case #: WYW17125 FAC ID: Corrected Date: 06/08/07  
Form: I FAC NAME: Followup Date: 06/12/07  
Assessment: \$0 Inspector: WHITE Extend Date:  
Gravity: 3  
Authority Ref: C.O.A.

Remarks Date: 06/01/07

Pick up and contain all trash and debris.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: VE		ID: VE11634
Unique INC #: DK07015	Well Name: CWU	
	Well #: 1230-07	ID Date: 03/29/07
Operator: EOG RESOURCES INC		Effective Date: 03/29/07
Case #: UTU63013X	FAC ID:	Abatement Date: 05/01/07
Form: I	FAC NAME:	Corrected Date: 04/30/07
Assessment: \$0	Inspector: DONNA KENNEY	Followup Date: 04/30/07
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2, II, Q.,III,A,,2,b,ii,d,		

Remarks Date: 03/29/07

On a BOPE test that was conducted on March 29th and 30th, on rig SST2 it was found that the choke manifold system is not set up in accordance with what EOG shows in their APD and what the Bureau of Land Management requires in their federal register of rules and regulations. This issue was discussed earlier and no change or modification had been attempted, which has prompted the issuance of this INC. When tested, neither one of the manual or super choke held or showed any sign of flow control, all of the valves that were tested on the manifold, either were beaten open with a sledge hammer or a 36 " pipe wrench was used. This is not considered operational, especially in a well control situation. The testers had to man handle the valves off of the BOPE stack for the choke and kill lines, proper handles and servicing would help. The accumulator function test shows a consistant low nitrogen bottle psi ( bleed off test) around 600#. They have been putting for a good effort to get this resolved but it still needs to be corrected. Please address these issues listed above and correct by the abatement date. Thank you.

Office: WO		ID: WO2306
Unique INC #: 07-OL-04	Well Name: SHAD	
	Well #: 31	ID Date: 11/06/06
Operator: NANCE PETROLEUM CORPORATION		Effective Date: 11/06/06
Case #: WYB040027	FAC ID:	Abatement Date: 11/09/06
Form: I	FAC NAME:	Corrected Date: 11/09/06
Assessment: \$0	Inspector: LEAR	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: OO#2. III. C.7.		

Remarks Date: 11/06/06

Flare lines not Ran to Flare Pit. Add on to Flare lines, with in 24hrs.

Office: WO		ID: WO2305
Unique INC #: 07-OL-03	Well Name: SHAD	
	Well #: 31	ID Date: 11/06/06
Operator: NANCE PETROLEUM CORPORATION		Effective Date: 11/06/06
Case #: WYB040027	FAC ID:	Abatement Date: 11/09/06
Form: I	FAC NAME:	Corrected Date: 11/09/06
Assessment: \$0	Inspector: LEAR	Followup Date: 11/09/06
Gravity: 3		Extend Date:
Authority Ref: OO#2. III A. g.		

Remarks Date: 11/06/06

Manual locking devices not installed on BOP. Install with in 24hrs.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: WO ID: WO2303  
Unique INC #: 07-OL-02 Well Name: NORTH NIEBER ID Date: 11/03/06  
Well #: 19-1 Effective Date: 11/08/06  
Operator: CONTINENTAL RESOURCES INC Abatement Date: 11/08/06  
Case #: WYW0000006 FAC ID: Corrected Date: 11/07/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OO#2. III.A.2.h.

Remarks Date: 11/03/06

Remote control for BOP on Rig floor not hook up. OO#2.III.2.h. Hook up with in 24hrs.

Office: WO ID: WO2302  
Unique INC #: 07-OL-01 Well Name: NORTH NIEBER ID Date: 11/03/06  
Well #: 19-1 Effective Date: 11/07/06  
Operator: CONTINENTAL RESOURCES INC Abatement Date: 11/08/06  
Case #: WYW0000006 FAC ID: Corrected Date: 11/07/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OO#2. III.2.a.iii.

Remarks Date: 11/03/06

No handles on Kill line valve, no handle of drilling spool choke line valve. OO #2 III.A.2.iii. Install handles with in 24hrs.

Office: WO ID: WO2351  
Unique INC #: 07-OL-23 Well Name: YAZ FEDERAL ID Date: 05/22/07  
Well #: 3-28 Effective Date: 05/22/07  
Operator: JACK J GRYNBERG Abatement Date: 05/23/07  
Case #: WYW162651 FAC ID: Corrected Date: 05/23/07  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: OO#2.III.A.2.ii

Remarks Date: 05/22/07

Safety Valve not tested. Test Valve or replace with in 24 Hrs.

Safety and Drilling Related Violations (INCs) Issued During FY 2007  
As of March 3, 2011

Office: WO	Well Name: YAZ FEDERAL	ID: WO2352
Unique INC #: 07-OL-24	Well #: 3-28	ID Date: 05/22/07
Operator: JACK J GRYNBERG	FAC ID:	Effective Date: 05/25/07
Case #: WYW162651	FAC NAME:	Abatement Date: 05/25/07
Form: I	Inspector: LEAR	Corrected Date: 05/25/07
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.C.7.		

Remarks Date: 05/22/07

Flare line not ran to Pits, or Flare pit. Run Flare lines with 3 Days.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: BA ID: BA2376  
Unique INC #: 05-050-06I Well Name:  
Well #: 29 ID Date: 08/22/06  
Operator: OXY USA INCORPORATED Effective Date: 08/23/06  
Case #: CAS022384 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: 5 WHITE T Abatement Date: 08/23/06  
Gravity: 1 Remarks Date: 08/23/06 Corrected Date: 08/23/06  
Authority Ref: Conditions of Approval Followup Date: 08/24/06  
Extend Date:

Remarks Date: 08/23/06  
Ensign drilling rig #510 had a 90 degree turn on the divertor line. Verbal variance was given by BLM Petroleum Engineer Silvet Holcomb.

Office: BA ID: BA2377  
Unique INC #: 05-051-06I Well Name:  
Well #: 29 ID Date: 08/22/06  
Operator: OXY USA INCORPORATED Effective Date: 08/23/06  
Case #: CAS022384 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: 5 WHITE T Abatement Date: 08/23/06  
Gravity: 1 Remarks Date: 08/23/06 Corrected Date: 08/23/06  
Authority Ref: Conditions of Approval Followup Date: 08/24/06  
Extend Date:

Remarks Date: 08/23/06  
Ensign rig #510 had no remote control on rig floor as required on Conditions of Approval of APD. Remote control was installed and function tested while Inspectors Rod Sparks and Tom White conducted their drilling inspection.

Office: BA ID: BA2414  
Unique INC #: 05-052-06I Well Name:  
Well #: 29 ID Date: 08/22/06  
Operator: OXY USA INCORPORATED Effective Date: 08/23/06  
Case #: CAS022384 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: 5 WHITE T Abatement Date: 08/23/06  
Gravity: 3 Remarks Date: 08/22/06 Corrected Date: 08/23/06  
Authority Ref: 43 CFR 3164.1 Conditions of Approval Followup Date: 08/24/06  
Extend Date:

Remarks Date: 08/22/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Approved APD was not on location. Operator was notified and company representative brought approved APD to location.

Office: BU ID: BU9286  
Unique INC #: MB-06-02 Well Name: RMU  
Well #: 23-11 ID Date: 11/09/05  
Operator: OSBORN HEIRS CO Effective Date: 11/09/05  
Case #: WYW013356 FAC ID:  
Form: I FAC NAME:  
Assessment: \$1,500 Inspector: BLAKESLEY  
Gravity: 1  
Authority Ref: 43CFR3164.1 OSO#2IIIA2aiii

Remarks Date: 11/09/05

Blowout preventer (BOP) and related equipment (BOPE) shall be installed, maintained and tested in a manner necessary to insure control and shall be operational prior to drilling the surface casing shoe. Specifically: You failed to install and maintain the kill line on the BOP

Office: BU ID: BU9288  
Unique INC #: MB-06-03 Well Name: RMU  
Well #: 23-11 ID Date: 11/09/05  
Operator: OSBORN HEIRS CO Effective Date: 11/09/05  
Case #: WYW013356 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: OSO#2 III A 2 g  
Extend Date:

Remarks Date: 11/10/05

BOP shall be maintained in a manner necessary to assure well control. Specifically: Hand wheels were not installed on BOPE. You must install hand wheels on BOPE stack.

Office: BU ID: BU9291  
Unique INC #: MB-06-04 Well Name: RMU  
Well #: 23-11 ID Date: 11/09/05  
Operator: OSBORN HEIRS CO Effective Date: 11/09/05  
Case #: WYW013356 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: OO#2111.A.1  
Extend Date:

Remarks Date: 11/09/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

BOP shall be maintained in a manner necessary to assure well control. Specifically: The controls for operating the BOP are not readily accessible. You must remove the material in front of the controls so that they are readily accessible to the operator.

Office: BU ID: BU9289  
Unique INC #: M06-04 Well Name: RMU ID Date: 11/09/05  
Well #: 23-11 Effective Date: 11/09/05  
Operator: OSBORN HEIRS CO Abatement Date: 11/10/05  
Case #: WYW013356 FAC ID: Corrected Date: 11/10/05  
Form: I FAC NAME: Followup Date: 11/10/05  
Assessment: \$0 Inspector: BLAKESLEY Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1  
  
Remarks Date: 11/09/05

There was a significant amount of motor oil under the rig and running down the ditches. You must clean up the motor oil and keep it from reaching the reserve pit.

Office: BU ID: BU10070  
Unique INC #: MB-06-30 Well Name: SAND DRAW LOVE ID Date: 06/28/06  
Well #: 11-31WA Effective Date: 06/29/06  
Operator: PETRO-CANADA RES (USA) INC Abatement Date: 07/06/06  
Case #: WYW133614 FAC ID: Corrected Date: 07/06/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: BLAKESLEY Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.6(b)  
  
Remarks Date: 06/28/06

There is no well sign on this location. You must install a well sign that contains the following: the operators name, the Federal lease number, the legal survey, and the well name and number.

Office: BU ID: BU9273  
Unique INC #: MB-06-01 Well Name: KITTY SUEDKAMP ID Date: 11/03/05  
Well #: 14-30 Effective Date: 11/04/05  
Operator: WILLIAMS PRODUCTION RMT CO Abatement Date: 11/11/05  
Case #: WYW143547 FAC ID: Corrected Date: 11/10/05  
Form: I FAC NAME: Followup Date: 11/29/05  
Assessment: \$0 Inspector: BLAKESLEY Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)  
  
Remarks Date: 11/03/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

This well site is not properly identified. You must install a well sign that meets the requirements of 43 CFR 3162.6(b).

Office: BU ID: BU9408  
Unique INC #: MB-06-06 Well Name: BLACKBIRD  
Well #: 1 ID Date: 12/20/05  
Operator: DUNCAN OIL INC Effective Date: 12/20/05  
Case #: WYW143919 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: OSO#2,III.A.2.i.xi: and i.viii  
Remarks Date: 12/20/05  
Pipe rams were not activated each trip and recorded in the driller's log. You must activate the pipe rams each trip and record in the driller's log.

Office: BU ID: BU9407  
Unique INC #: MB-06-05 Well Name: BLACKBIRD  
Well #: 1 ID Date: 12/20/05  
Operator: DUNCAN OIL INC Effective Date: 12/20/05  
Case #: WYW143919 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: OSO#2, III. C.1.  
Remarks Date: 12/20/05  
You have failed to record the slow pump speed in the driller's log on each tour. You must record the slow pump speed in the driller's log on each tour.

Office: BU ID: BU9988  
Unique INC #: MB-06-22 Well Name: POWDER VALLEY U PVU GAMMA  
Well #: 42-6BG ID Date: 06/06/06  
Operator: LANCE OIL + GAS CO INC Effective Date: 06/06/06  
Case #: WYW149556X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: COA's  
Remarks Date: 06/06/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Pits are not 30' from the well bore. You must have 30' from the edge of the nearest pit to the well bore. This will be checked on subsequent locations.

Office: BU		ID: BU10130
Unique INC #: MB-06-34	Well Name: BEAR DRAW UNIT BETA BDU	
	Well #: 41-13BG	ID Date: 07/24/06
Operator: LANCE OIL + GAS CO INC		Effective Date: 07/25/06
Case #: WYW151909X	FAC ID:	Abatement Date: 07/26/06
Form: I	FAC NAME:	Corrected Date: 08/04/06
Assessment: \$0	Inspector: BLAKESLEY	Followup Date: 09/27/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 07/24/06

There is no well sign on this location. You must install a well sign that contains the following: the operator's name, the Federal lease number, the legal survey, and the well name and number.

Office: BU		ID: BU10172
Unique INC #: MB-06-36	Well Name: BEAR DRAW UNIT BETA BDU	
	Well #: 24-15BG	ID Date: 07/27/06
Operator: LANCE OIL + GAS CO INC		Effective Date: 07/27/06
Case #: WYW151909X	FAC ID:	Abatement Date: 08/03/06
Form: I	FAC NAME:	Corrected Date: 08/03/06
Assessment: \$0	Inspector: BLAKESLEY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 07/27/06

The well sign is incorrect. The quarter-quarter should read SE of SE, not NW of SW.

Office: BU		ID: BU10032
Unique INC #: MB-06-23	Well Name: MEADOW DRAW TEST CHRISTIAN	
	Well #: 1BG-9*	ID Date: 06/22/06
Operator: JM HUBER CORP		Effective Date: 06/23/06
Case #: WYW157761	FAC ID:	Abatement Date: 07/06/06
Form: I	FAC NAME:	Corrected Date: 06/23/06
Assessment: \$0	Inspector: BLAKESLEY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 06/22/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

The lease number on the well sign is not correct. You must have the correct lease number on the well sign. It should read Lease # WYW157761.

Office: BU ID: BU10536  
Unique INC #: MB-06-43 Well Name: KFC LOVE  
Well #: 23-13FAW  
Operator: EMERALD OPERATING COMPANY  
Case #: WYW39563 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)

ID Date: 09/01/06  
Effective Date: 09/01/06  
Abatement Date: 09/10/06  
Corrected Date: 09/10/06  
Followup Date:  
Extend Date:

Remarks Date: 09/01/06

There is no well sign on this location. You must put up a well sign that contains the following: legal land description, well name and number, operator name, and Federal lease number.

Office: BU ID: BU10532  
Unique INC #: MB-06-39 Well Name: KFC LOVE  
Well #: 12-13F  
Operator: EMERALD OPERATING COMPANY  
Case #: WYW39563 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: COA's

ID Date: 09/01/06  
Effective Date: 09/01/06  
Abatement Date: 09/07/06  
Corrected Date: 09/07/06  
Followup Date:  
Extend Date:

Remarks Date: 09/01/06

You have failed to fence all pits on location. Pits will be fenced to prevent wildlife and livestock from entering.

Office: BU ID: BU10534  
Unique INC #: MB-06-41 Well Name: KFC LOVE  
Well #: 14-13F  
Operator: EMERALD OPERATING COMPANY  
Case #: WYW39563 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY  
Gravity: 3  
Authority Ref: COA's

ID Date: 09/01/06  
Effective Date: 09/01/06  
Abatement Date: 09/02/06  
Corrected Date: 09/02/06  
Followup Date:  
Extend Date:

Remarks Date: 09/01/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

You do not have the pits fenced. You must fence all pits to keep wildlife and livestock out.

Office: BU		ID: BU10121
Unique INC #: MB-=06-33	Well Name: SAND DRAW LOVE	
	Well #: 14-41WA	
Operator: PETRO-CANADA RES (USA) INC		
Case #: WYW51875	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$5,000	Inspector: BLAKESLEY	
Gravity: 1		
Authority Ref: 43 CFR 3163.1(b) (2)		

Remarks Date: 07/20/06

You have drilled a well without an appproved location. Please refer to the attached instructions for guidance for correction.

Office: BU		ID: BU10067
Unique INC #: MB-06-27	Well Name: SAND DRAW LOVE	
	Well #: 14-41WA	
Operator: PETRO-CANADA RES (USA) INC		
Case #: WYW51875	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: 43 CFR3162.6(b)		

Remarks Date: 06/28/06

There is no well sign. You must install a well sign that contains the following: the operators name, the Federal lease number, the surveyed location, the well name and number.

Office: BU		ID: BU10063
Unique INC #: MB-06-24	Well Name: SAND DRAW LOVE	
	Well #: 14-31WA	
Operator: PETRO-CANADA RES (USA) INC		
Case #: WYW51875	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: 43CFR 3162.6(b)		

Remarks Date: 06/28/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

There is no well sign on location. You must install a well sign that contains the following: the operators name, the Federal lease number, the surveyed location, the well name and number.

Office: BU ID: BU10068  
Unique INC #: MB-06-28 Well Name: SAND DRAW LOVE  
Well #: 14-41WA ID Date: 06/28/06  
Operator: PETRO-CANADA RES (USA) INC Effective Date: 06/29/06  
Case #: WYW51875 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY Abatement Date: 07/06/06  
Gravity: 3 Corrected Date: 07/06/06  
Authority Ref: COA's Followup Date:  
Extend Date:

Remarks Date: 06/28/06

The nearest edge of the pit is not 30' from the well bore. The well bore must be 30' from the nearest edge of the pit.

Office: BU ID: BU10064  
Unique INC #: MB\_06-25 Well Name: SAND DRAW LOVE  
Well #: 14-31WA ID Date: 06/28/06  
Operator: PETRO-CANADA RES (USA) INC Effective Date: 06/29/06  
Case #: WYW51875 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BLAKESLEY Abatement Date: 07/06/06  
Gravity: 3 Corrected Date: 07/06/06  
Authority Ref: COA's Followup Date:  
Extend Date:

Remarks Date: 06/28/06

The well bore is not 30' from the edge of the nearest pit. The edge of the nearest pit must be 30' from the well bore.

Office: BU ID: BU10091  
Unique INC #: KAB0601 Well Name: CHU  
Well #: 7-11 ID Date: 07/05/06  
Operator: PRIMARY NATURAL RESOURCES INC Effective Date: 07/05/06  
Case #: 891012381A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BOGERS/ROTH Abatement Date: 07/06/06  
Gravity: 3 Corrected Date: 07/07/06  
Authority Ref: Followup Date: 07/07/06  
Extend Date:

Remarks Date: 07/05/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Supply Air Valve for the accumulator air jammer was in the closed position. Please see attached copy of Onshore Order #2, specifically OO2.III.A.e - highlighted for your convenience, and attached pictures. The pusher (Mark) and company man (Dusty) were informed of this violation while the inspectors were on location on 7/5/06 @ 1300hrs. The inspectors were assured that the problem would be fixed.

Office: BU ID: BU10093  
Unique INC #: KAB0603 Well Name: CHU  
Well #: 7-11 ID Date: 07/05/06  
Operator: PRIMARY NATURAL RESOURCES INC Effective Date: 07/05/06  
Case #: 891012381A FAC ID: Abatement Date: 07/06/06  
Form: I FAC NAME: Corrected Date: 07/07/06  
Assessment: \$0 Inspector: BOGERS/ROTH Followup Date: 07/07/06  
Gravity: 1 Extend Date:  
Authority Ref:

Remarks Date: 07/05/06

Flare Line system less than 100 feet. Please see attached copy of Onshore Order #2, specifically OO2.III.C.7 - highlighted for your convenience, and attached pictures. The pusher (Mark) and company man (Dusty) were informed of this violation while the inspectors were on location on 7/5/06. The inspectors were assured that the problem would be fixed.

Office: BU ID: BU10092  
Unique INC #: KAB0602 Well Name: CHU  
Well #: 7-11 ID Date: 07/05/06  
Operator: PRIMARY NATURAL RESOURCES INC Effective Date: 07/05/06  
Case #: 891012381A FAC ID: Abatement Date: 07/06/06  
Form: I FAC NAME: Corrected Date: 07/07/06  
Assessment: \$0 Inspector: BOGERS/ROTH Followup Date: 07/07/06  
Gravity: 3 Extend Date:  
Authority Ref:

Remarks Date: 07/05/06

Missing hand wheels. Please see attached copy of Onshore Order #2, specifically OO2.III.A.g - highlighted for your convenience, and attached pictures. The pusher (Mark) and company man (Dusty) were informed of this violation while the inspectors were on location on 7/5/06 @ 1300hrs. The inspectors were assured that the problem would be fixed.

Office: BU ID: BU10101  
Unique INC #: KAB0605 Well Name: CHU  
Well #: 7-11 ID Date: 07/05/06  
Operator: PRIMARY NATURAL RESOURCES INC Effective Date: 07/06/06  
Case #: 891012381A FAC ID: Abatement Date: 07/06/06  
Form: I FAC NAME: Corrected Date: 07/07/06  
Assessment: \$0 Inspector: BOGERS/ROTH Followup Date: 07/07/06  
Gravity: 3 Extend Date:  
Authority Ref:

Remarks Date: 07/05/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

No fence around the pit, required by APD. See attached pictures. The company man (Dusty) was informed of this violation while the inspectors were on location on 7/5/06 @ 1300hrs. The inspectors were assured that the problem would be fixed.

Office: BU		ID: BU10094
Unique INC #: KAB0604	Well Name: CHU	
	Well #: 7-11	
Operator: PRIMARY NATURAL RESOURCES INC		
Case #: 891012381A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$500	Inspector: BOGERS/ROTH	
Gravity: 1		
Authority Ref: 43CFR3163.1.(b).(1)		

Remarks Date: 07/05/06

Failure to install and maintain BOPE system. Specifically: Air supply was shut off to Accumulator Power source and hand wheels on BOP were not hooked up. NOTE: Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed and maintained, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). Shoe was drilled out 7-4-2006, inspected 7-5-2006 by Kimberly Bogers and Gary Roth. Discussed violations with company hand and pusher while on site. Cyclone #4 was the drilling rig on site.

Office: BU		ID: BU9352
Unique INC #: DC06-004	Well Name: TUIT DRAW CBM	
	Well #: 23-33	
Operator: MERIT ENERGY CO		
Case #: WYW107251	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Prod. Operations		

Remarks Date: 11/15/05

Production casing cement had fallen back 32' from the surface and the rig was drilling below the casing shoe. Conditions of Approval require all remedial work to be completed before drilling out the casing shoe. Remediate the cement by bringing it to ground level. (Drilling ceased immediately and the annulus was secured in the presence of the Inspector.) No further action is required on this INC except to sign, date and return this form.

Office: BU		ID: BU9353
Unique INC #: DC06-005	Well Name: TUIT DRAW CBM	
	Well #: 23-33	
Operator: MERIT ENERGY CO		
Case #: WYW107251	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Prod. Operations		

Remarks Date: 11/15/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

The rig on this well was drilling in coal below the casing shoe. Coal cuttings were blowing out the blooie line onto open ground beyond the blooie pit through a gap in the spoils pile. Conditions of Approval require all cuttings and circulating medium be contained in the pit. Reposition the spoil pile to close the gap and contain the cuttings. (Drilling ceased immediately and a backhoe repositioned the spoil pile in the presence of the Inspector). No further action is required on this INC except to sign, date and return this form.

Office: BU		ID: BU9411
Unique INC #: DC06-008	Well Name: BIG BEND I FEDERAL	
	Well #: 1-1*	
Operator: NORTH FINN, LLC		
Case #: WYW130116	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations		

Remarks Date: 12/20/05

The drill rig on this well was at 940 feet and the blooie line was not anchored. The Conditions of Approval (COA) state that the blooie line be securely anchored. Securely anchor the blooie line on this well. Verbal contact, via phone, between Darrel Cork and Neil Neumiller was made at 16:15 on 12/20/05 regarding this INC and the 24 hour abatement time.

Office: BU		ID: BU9410
Unique INC #: DC06-007	Well Name: BIG BEND I FEDERAL	
	Well #: 1-1*	
Operator: NORTH FINN, LLC		
Case #: WYW130116	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Onshore Oil And Gas Order No. 1, III., G.,3., f.		

Remarks Date: 12/20/05

There is no approved Federal Application for Permit to Drill (APD) on location at this well. Onshore Oil And Gas Order No. 1 states that a copy of the approved APD shall be available at the drillsite whenever active construction, drilling or completion operations are under way. Provide a copy of the approved Federal APD on this location. Verbal contact, via phone, between Darrel Cork and Neil Neumiller was made at 16:15 on 12/20/05 regarding this INC and the 24 hour abatement time.

Office: BU		ID: BU10208
Unique INC #: DC06-067	Well Name: BIG BEND I FEDERAL	
	Well #: 15-25	
Operator: NORTH FINN, LLC		
Case #: WYW137111	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations		

Remarks Date: 08/02/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Rig on this well was running Drill Pipe to drill thru the surface casing shoe at 124'. The flow line was not anchored. Conditions of Approval require the flow line be securely anchored. Corrective Action: Securely anchor the flow line. (This was done in the presence of the Inspector).

Office: BU ID: BU10210  
Unique INC #: DC06-070 Well Name: BIG BEND I FEDERAL  
Well #: 15-25 ID Date: 08/02/06  
Operator: NORTH FINN, LLC Effective Date: 08/11/06  
Case #: WYW137111 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CORK  
Gravity: 3  
Authority Ref: General Conditions of Approval  
Remarks Date: 08/02/06

The well was at 124 feet and the rig did not have an APD at the drill site. General Conditions of Approval require an approved APD be at the drill site during drilling operations. Corrective Action: Provide an approved APD at the drill site.

Office: BU ID: BU10507  
Unique INC #: DC06-080 Well Name: BIG BEND I FEDERAL  
Well #: 3-25 ID Date: 08/29/06  
Operator: NORTH FINN, LLC Effective Date: 08/29/06  
Case #: WYW137111 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CORK  
Gravity: 1  
Authority Ref: Onshore Oil and Gas Order #2, III., A., 1.  
Remarks Date: 08/29/06

The rig at this location was drilling at 350' without a rubber in the diverter. Corrective Action: Install a rubber in the diverter. Drilling stopped immediately and the rubber was installed in the presence of the inspector.

Office: BU ID: BU10501  
Unique INC #: DC06-076 Well Name: BIG BEND I FEDERAL  
Well #: 5-25 ID Date: 08/29/06  
Operator: NORTH FINN, LLC Effective Date: 09/08/06  
Case #: WYW137111 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CORK  
Gravity: 3  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations  
Remarks Date: 08/29/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

The drill rig has moved off this well but cement is not to surface on the production casing. Top of cement was measured at 22' below surface. Conditions of Approval require all remedial cementing work be completed before drilling out the casing shoe. Corrective action: Remediate the cement to surface using 1" if top of cement is below 30 feet. If top of cement is above 30', sakrete may be used.

Office: BU		ID: BU10128
Unique INC #: DC06-060	Well Name: BIG BEND I FEDERAL	
	Well #: 9-25	ID Date: 07/18/06
Operator: NORTH FINN, LLC		Effective Date: 07/18/06
Case #: WYW137111	FAC ID:	Abatement Date: 07/18/06
Form: I	FAC NAME:	Corrected Date: 07/18/06
Assessment: \$0	Inspector: CORK	Followup Date: 07/25/06
Gravity: 1		Extend Date:
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations		

Remarks Date: 07/18/06

The drill rig on this well was drilling at 340 feet and the flow line was not anchored. The Conditions of Approval (COA) state that the flow line be securely anchored. Corrective Action: Securely anchor the flow line on this well. This was done immediately in the presence of the inspector. Neal Neumiller was informed of this on 7/20/06. No further action is required except to return original of this document.

Office: BU		ID: BU10506
Unique INC #: DC06-078	Well Name: BIG BEND I FEDERAL	
	Well #: 3-25	ID Date: 08/29/06
Operator: NORTH FINN, LLC		Effective Date: 08/29/06
Case #: WYW137111	FAC ID:	Abatement Date: 08/29/06
Form: I	FAC NAME:	Corrected Date: 08/29/06
Assessment: \$0	Inspector: CORK	Followup Date: 08/29/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR, Subpart 3162.6, (a)		

Remarks Date: 08/29/06

There was no well identification sign at this drill site. Corrective Action: Provide a well identification sign at this well with the correct information on it per 43 CFR, 3162.6, (a). This was done immediately in the presence of the inspector.

Office: BU		ID: BU10504
Unique INC #: DC06-079	Well Name: BIG BEND I FEDERAL	
	Well #: 3-25	ID Date: 08/29/06
Operator: NORTH FINN, LLC		Effective Date: 08/29/06
Case #: WYW137111	FAC ID:	Abatement Date: 08/29/06
Form: I	FAC NAME:	Corrected Date: 08/29/06
Assessment: \$0	Inspector: CORK	Followup Date: 08/29/06
Gravity: 1		Extend Date:
Authority Ref: General Conditions of Approval		

Remarks Date: 08/29/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

The drill rig was drilling on this location and there was no APD on the well site. The Conditions of Approval state that an approved APD be at the drill site during drilling operations. Corrective Action: Provide an approved APD at the drill site. This was done immediately in the presence of the inspector.

Office: BU ID: BU10209  
Unique INC #: DC06-068 Well Name: BIG BEND I FEDERAL  
Well #: 15-25 ID Date: 08/02/06  
Operator: NORTH FINN, LLC Effective Date: 08/11/06  
Case #: WYW137111 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CORK  
Gravity: 3  
Authority Ref: Standard Conditions of Approval

Remarks Date: 08/02/06

The second half of the reserve pit at this well was not fenced. Conditions of Approval require the pit be adequately fenced during drilling operations.  
Corrective Action: Adequately fence the second half of the pit.

Office: BU ID: BU10502  
Unique INC #: DC06-077 Well Name: BIG BEND I FEDERAL  
Well #: 3-25 ID Date: 08/29/06  
Operator: NORTH FINN, LLC Effective Date: 08/29/06  
Case #: WYW137111 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CORK  
Gravity: 1  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations

Remarks Date: 08/29/06

The drill rig on this location was drilling at 350' and the flow line was not anchored. The Conditions of Approval state that the flow line be securely anchored. Corrective Action: Securely anchor the flow line. This was done immediately in the presence of the inspector.

Office: BU ID: BU10211  
Unique INC #: DC06-069 Well Name: BIG BEND I FEDERAL  
Well #: 15-25 ID Date: 08/02/06  
Operator: NORTH FINN, LLC Effective Date: 08/11/06  
Case #: WYW137111 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CORK  
Gravity: 3  
Authority Ref: 43 CFR, 3162.6, (a)

Remarks Date: 08/02/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

This well was drilling at 124 feet, and there was no well sign. Corrective Action: Provide, on location, a well identification sign with the required information.

Office: BU ID: BU10207  
Unique INC #: DC06-066 Well Name: BIG BEND I FEDERAL  
Well #: 15-25 ID Date: 08/02/06  
Operator: NORTH FINN, LLC Effective Date: 08/02/06  
Case #: WYW137111 FAC ID: Abatement Date: 08/02/06  
Form: I FAC NAME: Corrected Date: 08/02/06  
Assessment: \$0 Inspector: CORK Followup Date: 08/02/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations  
Remarks Date: 08/02/06

Rig on this well was running Drill Pipe to drill thru the surface casing shoe at 124'. The flow line was 15' long. Conditions of Approval require a 30' flow line. Corrective Action: Provide a 30' flow line (a 15' extension was added to the existing flow line in the presence of the Inspector).

Office: BU ID: BU10127  
Unique INC #: DC06-059 Well Name: BIG BEND I FEDERAL  
Well #: 9-25 ID Date: 07/18/06  
Operator: NORTH FINN, LLC Effective Date: 07/18/06  
Case #: WYW137111 FAC ID: Abatement Date: 07/18/06  
Form: I FAC NAME: Corrected Date: 07/18/06  
Assessment: \$0 Inspector: CORK Followup Date: 07/25/06  
Gravity: 1 Extend Date:  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations  
Remarks Date: 07/18/06

The drill rig on this well was drilling at 340 feet with a 15 foot flow line. The Conditions of Approval (COA) states that the flow line be a minimum of 30 feet. Corrective Action: Add an extension to the flow line to provide the 30 feet. This was done immediately in the presence of the inspector. Neal Neumiller was informed of this on 7/20/06. No further action is required except to return original of this document.

Office: BU ID: BU9603  
Unique INC #: DC06-019 Well Name: BULLWHACKER III BCU  
Well #: 34-22 ID Date: 02/28/06  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 03/16/06  
Case #: WYW149561X FAC ID: Abatement Date: 03/31/06  
Form: I FAC NAME: Corrected Date: 03/16/06  
Assessment: \$0 Inspector: CORK Followup Date: 04/12/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations  
Remarks Date: 02/28/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

The drill rig has moved off this well but cement is 9 foot below the surface on the production casing. Conditions of Approval require all remedial cementing work be completed before drilling out the casing shoe. Remediate the cement to surface using 1" if top of cement is below 30 feet. If top of cement is above 30', sakrete may be used.

Office: BU		ID: BU9492
Unique INC #: DC06-013	Well Name: HARTZOG DRAW CBM HARTZOG	
	Well #: 43-22BG	
Operator: CH4 ENERGY LLC		
Case #: WYW35757	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations		

Remarks Date: 01/18/06

The drill rig has moved off this well but cement is not to surface on the production casing. Running a tape down the annulus shows no cement within 39' of the surface. Conditions of Approval require all remedial cementing work be completed before drilling out the casing shoe. Remediate the cement to surface using 1", as the cement level is below 30'.

Office: BU		ID: BU9491
Unique INC #: DC06-011	Well Name: HARTZOG DRAW CBM HARTZOG	
	Well #: 43-22BG	
Operator: CH4 ENERGY LLC		
Case #: WYW35757	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Surface Use Conditions of Approval		

Remarks Date: 01/18/06

The pit fencing at this well is incomplete, the fence running along the spoils pile side of the pit is laying down on the ground. Conditions Of Approval require four sides to the pit fence upon completion of drilling and prior to rig release and that it be left up and maintained in adequate condition until the pit is closed. Adequately fence the spoils pile side of the pit.

Office: BU		ID: BU9493
Unique INC #: DC06-012	Well Name: HARTZOG DRAW CBM HARTZOG	
	Well #: 43-22BG	
Operator: CH4 ENERGY LLC		
Case #: WYW35757	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: CORK	
Gravity: 3		
Authority Ref: Surface Use Conditions of Approval		

Remarks Date: 01/18/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

The drill rig has moved off this location. There is excrement/toilet paper on the pit spoils pile. Conditions of Approval require sewage be placed in a self-contained, chemically treated porta-potty on location. Clean up the sewage.

Office: BU		ID: BU9490
Unique INC #: DC06-010	Well Name: HARTZOG DRAW CBM HARTZOG	
	Well #: 43-22BG	ID Date: 01/18/06
Operator: CH4 ENERGY LLC		Effective Date: 01/31/06
Case #: WYW35757	FAC ID:	Abatement Date: 02/20/06
Form: I	FAC NAME:	Corrected Date: 02/08/06
Assessment: \$0	Inspector: CORK	Followup Date: 02/08/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR, 3162.6, (a)		

Remarks Date: 01/18/06

A well identification sign is required at all Federal wells. Install a well identification sign at this well with the correct information on it per 43 CFR, 3162.6., (a).

Office: BU		ID: BU9495
Unique INC #: DC06-015	Well Name: HD CBM 1 HARTZOG	
	Well #: 34-15BG	ID Date: 01/18/06
Operator: XTO ENERGY INC		Effective Date: 02/01/06
Case #: WYW39178	FAC ID:	Abatement Date: 02/13/06
Form: I	FAC NAME:	Corrected Date: 01/31/06
Assessment: \$0	Inspector: CORK	Followup Date: 02/08/06
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations		

Remarks Date: 01/18/06

The drill rig has moved off this well but cement is not to surface on the production casing. Conditions of Approval require all remedial cementing work be completed before drilling out the casing shoe. Remediate the cement to surface using 1" if top of cement is below 30 feet. If top of cement is above 30', sakrete may be used.

Office: BU		ID: BU9496
Unique INC #: DC06-016	Well Name: HD CBM 1 HARTZOG	
	Well #: 34-15BG	ID Date: 01/18/06
Operator: XTO ENERGY INC		Effective Date: 02/01/06
Case #: WYW39178	FAC ID:	Abatement Date: 02/23/06
Form: I	FAC NAME:	Corrected Date: 01/31/06
Assessment: \$0	Inspector: CORK	Followup Date: 02/08/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR, Subpart 3162.6 (a)		

Remarks Date: 01/18/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

A well identification sign is required at all Federal wells. Install a well identification sign at this well with the correct information on it per 43 CFR, 3162.6., (a).

Office: BU ID: BU10110  
Unique INC #: DC06-058V Well Name: JEPSON DRAW I FEDERAL  
Well #: 14-35KC ID Date: 07/12/06  
Operator: WINDSOR ENERGY GROUP LLC Effective Date: 07/12/06  
Case #: WYW40002 FAC ID: Abatement Date: 07/12/06  
Form: I FAC NAME: Corrected Date: 07/12/06  
Assessment: \$0 Inspector: CORK Followup Date: 07/12/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations

Remarks Date: 07/12/06

Oral/verbal INC. The drill rig on this well was at 397 feet and the boloie line was not anchored. The Conditions of Approval (COA) state that the boloie line be securely anchored. Securely anchor the boloie line on this well. This was discussed on site, between Darrel Cork and Jim Gardner.

Office: BU ID: BU10129  
Unique INC #: DC06-061V Well Name: JEPSON DRAW I JOHNSON  
Well #: 21-35KC ID Date: 07/20/06  
Operator: WINDSOR ENERGY GROUP LLC Effective Date: 07/20/06  
Case #: WYW51886 FAC ID: Abatement Date: 07/20/06  
Form: I FAC NAME: Corrected Date: 07/20/06  
Assessment: \$0 Inspector: CORK Followup Date: 07/20/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations

Remarks Date: 07/20/06

Oral/verbal INC. The drill rig on this well was drilling at 450 feet and the flow line was not anchored. The Conditions of Approval (COA) state that the flow line be securely anchored. Corrective Action: Securely anchor the flow line on this well. This was done immediately in the presence of the inspector and Co. Man, Butch Skilling.

Office: BU ID: BU9494  
Unique INC #: DC06-014 Well Name: HARTZOG DRAW CBM HARTZOG  
Well #: 34-22BG ID Date: 01/18/06  
Operator: CH4 ENERGY LLC Effective Date: 02/01/06  
Case #: WYW59614 FAC ID: Abatement Date: 02/13/06  
Form: I FAC NAME: Corrected Date: 02/01/06  
Assessment: \$0 Inspector: CORK Followup Date: 02/08/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval for Coal Bed Methane Drilling and Production Operations

Remarks Date: 01/18/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

At the time of this inspection, the drill rig on this well was underreaming. There was not cement to surface in the annulus as the production casing was moving around freely with the rotating drill string. Conditions of Approval require all remedial cementing work be completed before drilling out the casing shoe. Remediate the cement to surface using 1" if top of cement is below 30 feet. If top of cement is above 30 feet, sakrete may be used.

Office: BU		ID: BU10531
Unique INC #: MH0657	Well Name: CAT SHADOW POPCORN CS	
	Well #: 4	ID Date: 09/05/06
Operator: YATES PETROLEUM CORP		Effective Date: 09/05/06
Case #: WYW131225	FAC ID:	Abatement Date: 09/30/06
Form: I	FAC NAME:	Corrected Date: 09/27/06
Assessment: \$500	Inspector: HAINES	Followup Date: 09/28/06
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3162.3-1 (c)		

Remarks Date: 09/05/06

On September 5, 2006, Yates informed the Buffalo Field Office that they had spud the Popcorn #4 at an unapproved location ( in Campbell County, WY). You shall submit a Notice of Intent of Abandonment and a sundry with the new well location accompanied by a new well plat prior to 9/ 30/06 to the Buffalo Field Office. If there are any question, please contact Mark Haines at 307-684-1065 or Mike Worden at 307-684-1100.

Office: BU		ID: BU9293
Unique INC #: MH0609	Well Name: SLPU FED	
	Well #: 14-17H	ID Date: 11/13/05
Operator: MEDICINE BOW OPERATING CO		Effective Date: 11/14/05
Case #: WYW144505	FAC ID:	Abatement Date: 11/18/05
Form: I	FAC NAME:	Corrected Date: 11/16/05
Assessment: \$0	Inspector: HAINES	Followup Date: 11/16/05
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.4-2(a)		

Remarks Date: 11/13/05

On 11/13/2005 Medicine Bow Operating failed to comply with 43 CFR 3162.4-2 by not running a cement bond log as requested . You shall run a cement bond log and supply the Buffalo Field Office a copy of this log, You shall give the Buffalo Field Office 24 hours notice before running this log. If there are any question contact Mark Haines at 307-684-1065, Dave Soule at 307-684-1103 or Dane Gayer at 307-684-1157.

Office: BU		ID: BU10024
Unique INC #: MH0645	Well Name: SLPU FED	
	Well #: 12-30H	ID Date: 06/19/06
Operator: MEDICINE BOW OPERATING CO		Effective Date: 06/20/06
Case #: WYW144513	FAC ID:	Abatement Date: 06/20/06
Form: I	FAC NAME:	Corrected Date: 06/20/06
Assessment: \$0	Inspector: HAINES	Followup Date: 06/20/06
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 06/19/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

You have failed to comply with the Conditions of Approval by not giving the Buffalo Field Office 24 hours notice prior of spudding. You shall comply with the Conditions of Approval on all future Federal wells. If there are any questions contact Mark Haines at 307-684-1065.

Office: BU ID: BU10403  
Unique INC #: MH0655 Well Name: SIGMA TAU ANADARKO FED  
Well #: 9-12 ID Date: 08/22/06  
Operator: ANADARKO PETROLEUM CORP Effective Date: 08/22/06  
Case #: WYW145617 FAC ID: Abatement Date: 09/15/06  
Form: I FAC NAME: Corrected Date: 08/22/06  
Assessment: \$0 Inspector: HAINES Followup Date: 08/30/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 08/22/06

During a field inspection, it was found that the drilling site was not properly identified. You shall install a well sign identifying the drilling site. If there are any question, contact Mark Haines at 307-684-1065.

Office: BU ID: BU9500  
Unique INC #: MH0619 Well Name: FALXA RED DRAW FALXA  
Well #: 23-22 ID Date: 01/30/06  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 01/30/06  
Case #: WYW146891 FAC ID: Abatement Date: 01/31/06  
Form: I FAC NAME: Corrected Date: 02/02/06  
Assessment: \$0 Inspector: HAINES Followup Date: 02/03/06  
Gravity: 1 Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 01/30/06

On 1/30/2006 during a field inspection it was found that the well control equipment was not in working order to control the well ( no rubbers in the diverter and the top plate was not installed) . Onshore Order# 2.III.A.2.a.i states " A well control device shall be installed at the surface that is capable of complete closure of the well bore. This device shall be closed whenever the well is unattended." . You have 24 hours to get the well control equipment in proper working order. If you fail to comply with the Conditions of Approval for well control equipment you are subject to immediate assessment of \$500 per day up to \$5,000.00( 43 CFR 3163.1(b)(1). I called Red Lufkin - Drilling Superintendent for Black Diamond and left a message on his cell phone, to let him know that I issued a Major Incident of Noncompliance. For questions please contact Mark Haines 307-684-1065.

Office: BU ID: BU9262  
Unique INC #: MH0605 Well Name: FALXA RED DRAW FEDERAL  
Well #: 34-26 ID Date: 11/01/05  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 11/02/05  
Case #: WYW146893 FAC ID: Abatement Date: 11/18/05  
Form: I FAC NAME: Corrected Date: 11/03/05  
Assessment: \$0 Inspector: HAINES Followup Date: 11/17/05  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 11/01/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

During a drilling inspection it was found that the well site was not identified. You shall install the proper well sign. If there are any questions contact Mark Haines at 307-684-1065 or Dave Soule at 307-684-1103.

Office: BU ID: BU9501  
Unique INC #: MH0620 Well Name: FALXA RED DRAW FEDERAL  
Well #: 23-26 ID Date: 02/01/06  
Operator: BLACK DIAMOND ENERGY INC Effective Date: 01/03/06  
Case #: WYW146893 FAC ID: Abatement Date: 02/13/06  
Form: I FAC NAME: Corrected Date: 02/02/06  
Assessment: \$0 Inspector: HAINES Followup Date: 02/03/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 02/01/06

On 2/1/2006 during the preformance of a Drilling Inspection it was found that you do not have cement to the surface on the Falxa Red Draw Federal 23-26 well. Inspector measured cement fallback at 20'. You shall run 1" pipe and cement surface casing to the surface on this well. If there are any questions contact Mark Haines at 307-684-1065.

Office: BU ID: BU10404  
Unique INC #: MH0656 Well Name: SIGMA TAU BIG GEORGE UNIT  
Well #: 21-21 ID Date: 08/22/06  
Operator: ANADARKO PETROLEUM CORP Effective Date: 08/22/06  
Case #: WYW149537X FAC ID: Abatement Date: 09/15/06  
Form: I FAC NAME: Corrected Date: 08/22/06  
Assessment: \$0 Inspector: HAINES Followup Date: 08/30/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 08/22/06

During a field inspection, it was found that the drilling site was not properly identified. You shall install a well sign identifying the drilling site. If there are any question, contact Mark Haines at 307 - 684 -1065.

Office: BU ID: BU9373  
Unique INC #: MH0616 Well Name: SCHOONOVER RD 3 FEDERAL  
Well #: 41-6 ID Date: 12/14/05  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 12/14/05  
Case #: WYW149799 FAC ID: Abatement Date: 12/15/05  
Form: I FAC NAME: Corrected Date: 12/14/05  
Assessment: \$0 Inspector: HAINES Followup Date: 12/15/05  
Gravity: 1 Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 12/14/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

You have failed to use the proper well control equipment on wqell 41-6. You shall install a diverter on this well before preforming any more work. If ther are any questions contact Mark Haines at 307-684-1065.

Office: BU		ID: BU9281
Unique INC #: MH0608	Well Name: CAT SHADOW SHADOW CS FEDERAL	
	Well #: 4	ID Date: 11/07/05
Operator: YATES PETROLEUM CORP		Effective Date: 11/08/05
Case #: WYW149799	FAC ID:	Abatement Date: 11/12/05
Form: I	FAC NAME:	Corrected Date: 11/11/05
Assessment: \$0	Inspector: HAINES	Followup Date: 11/14/05
Gravity: 3		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 11/07/05

During a field inspection it was found that there was human waste on the location. In the Conditions of Approval it states a portable self-contained chemical toilet will be provided for human waste. You shall install a toilet on location. If there are any questions contact Mark Haines at 307-684-1065 or Dave Soule at 307-684-1103.

Office: BU		ID: BU9785
Unique INC #: NL060018	Well Name: PETROX BIG GEORGE	
	Well #: 3-4	ID Date: 04/17/06
Operator: PETROX RESOURCES INC		Effective Date: 04/24/06
Case #: WYW145623	FAC ID:	Abatement Date: 05/24/06
Form: I	FAC NAME:	Corrected Date: 04/20/06
Assessment: \$0	Inspector: LOFGREN	Followup Date: 04/27/06
Gravity: 3		Extend Date:
Authority Ref: On Shore Order #2 Permit to drill		

Remarks Date: 04/17/06

In the approved permit to drill, all garbage must be properly disposed of by the operator. Garbage was found in pit used to drill the well. Please excavate all garbage from reserve pit and properly dispose of the refuse, then reclaim site as per the APD.

Office: BU		ID: BU10518
Unique INC #: NL060030	Well Name: SCHOONOVER RD WDW	
	Well #: 23-14WIW	ID Date: 08/29/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 08/30/06
Case #: WYW148333X	FAC ID:	Abatement Date: 09/27/06
Form: I	FAC NAME:	Corrected Date: 09/12/06
Assessment: \$0	Inspector: LOFGREN	Followup Date: 09/13/06
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.3-1(C)		

Remarks Date: 08/29/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

The operator shall submit to the authorized officer for approval an Application for Permit to Drill for each well. No drilling operations, nor surface disturbance preliminary thereto, may be commenced prior to the authorized officer's approval of the permit. Please submit Application for Permit to Drill for approval before resuming field work.

Office: BU ID: BU9614  
Unique INC #: RN-06-22 Well Name: HDU POD  
Well #: 2952 ID Date: 03/08/06  
Operator: XTO ENERGY INC Effective Date: 03/05/06  
Case #: 8910194240 FAC ID:  
Form: I FAC NAME:  
Assessment: \$2,500 Inspector: NAVARRETTE  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.1  
Abatement Date: 03/09/06  
Corrected Date: 03/09/06  
Followup Date: 03/09/06  
Extend Date:

Remarks Date: 03/08/06

Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and operational prior to drilling the surface casing shoe. The outside choke line valve does not have a handle. You must put a handle on this valve. (Notice was to Bob Dreiling on the location.)

Office: BU ID: BU9615  
Unique INC #: RN-06-23 Well Name: HDU POD  
Well #: 2952 ID Date: 03/08/06  
Operator: XTO ENERGY INC Effective Date: 03/08/06  
Case #: 8910194240 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NAVARRETTE  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)  
Abatement Date: 04/08/06  
Corrected Date: 03/09/06  
Followup Date: 03/09/06  
Extend Date:

Remarks Date: 03/09/06

This well does not have an identification sign. You must properly identify this well with a sign.

Office: BU ID: BU9613  
Unique INC #: RN-06-21 Well Name: HDU POD  
Well #: 2952 ID Date: 03/08/06  
Operator: XTO ENERGY INC Effective Date: 03/05/06  
Case #: 8910194240 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NAVARRETTE  
Gravity: 3  
Authority Ref: Onshore Order #2.III.A.1  
Abatement Date: 03/09/06  
Corrected Date: 03/09/06  
Followup Date: 03/09/06  
Extend Date:

Remarks Date: 03/08/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and be operational prior to drilling the surface casing shoe. The kill line valve at the BOP does not have a handle. You must put a handle on this valve.  
( Notice was to Bob Dreiling on the location.)

Office: BU		ID: BU9249
Unique INC #: RN-06-1	Well Name: TEAL FEDERAL	
	Well #: 1	ID Date: 10/25/05
Operator: YATES PETROLEUM CORP		Effective Date: 10/04/05
Case #: WYW141193	FAC ID:	Abatement Date: 10/26/05
Form: I	FAC NAME:	Corrected Date: 10/25/05
Assessment: \$5,000	Inspector: NAVARRETTE	Followup Date: 10/26/05
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3164.1 00#2.III.A.2.a.iii		

Remarks Date: 10/26/05

Blow out preventer (BOP) and related equipment(BOPE) shall be installed, maintained, and tested in a manner necessary to insure well control and shall be operational prior to drilling the surface casing shoe. Specifically: You failed to install and maintain kill line on BOP.

Office: BU		ID: BU10371
Unique INC #: RN-06-68	Well Name: FALXA RED DRAW ADD FEDERAL	
	Well #: 34-20L	ID Date: 08/16/06
Operator: BLACK DIAMOND ENERGY INC		Effective Date: 08/16/06
Case #: WYW146889	FAC ID:	Abatement Date: 08/16/06
Form: I	FAC NAME:	Corrected Date: 08/16/06
Assessment: \$0	Inspector: NAVARRETTE	Followup Date: 08/16/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 08/17/06

Failure to use hardhat on location. The operator shall take all necessary percation to proved edequate protection for the health and safety of life and protection of property.

Office: BU		ID: BU9562
Unique INC #: RN-06-20	Well Name: USFS CAMP CREEK FED	
	Well #: 41-7	ID Date: 02/27/06
Operator: BALLARD PETROLEUM HOLDINGS LLC		Effective Date: 02/27/06
Case #: WYW163041X	FAC ID:	Abatement Date: 02/27/06
Form: I	FAC NAME:	Corrected Date: 02/27/06
Assessment: \$2,000	Inspector: NAVARRETTE	Followup Date: 02/27/06
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2.A. III.iii		

Remarks Date: 02/28/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

You failed to install the kill line on the BOP. You drilled out the shoe 2/23/06 and the violation was discovered 2/27/06. You must install the kill line on the BOP and maintain in order to assure well control. Notice of violation and assessment was by phone on 2/27/06 at 1400 hours. (Violation was corrected at time of inspection)

Office: BU ID: BU9686  
Unique INC #: CR06-26-DI Well Name: HDU POD  
Well #: 1951 ID Date: 03/27/06  
Operator: XTO ENERGY INC Effective Date: 03/27/06  
Case #: 8910194240 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 (a) and 43 CFR 3162.5-2(a)

Remarks Date: 03/27/06

Drilling inspection on HDU 1951 shows the safety valve was in the closed position and not ready for use.

Office: BU ID: BU10061  
Unique INC #: CR06-67-DI Well Name: TWENTY MILE CREEK EATON  
Well #: 13-23CA ID Date: 06/28/06  
Operator: PETRO-CANADA RES (USA) INC Effective Date: 02/28/06  
Case #: WYW139677 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (a)

Remarks Date: 06/28/06

Well sign does not have the Lease number.

Office: BU ID: BU10106  
Unique INC #: CR06-70-DI Well Name: TWENTY MILE CREEK FEDERAL  
Well #: 12-43CA ID Date: 07/11/06  
Operator: PETRO-CANADA RES (USA) INC Effective Date: 07/12/06  
Case #: WYW139677 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 (a) and Conditions of Approval in APD.

Remarks Date: 07/11/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Well in being drilled on a location where surface disturbing activities are prohibited until after 7/31/2006. The well site is located in a prairie dog town that was not surveyed for Mountain Plover nesting.

Office: BU ID: BU9682  
Unique INC #: CR06-23-DI Well Name: NWHCU  
Well #: 40-12 ID Date: 03/27/06  
Effective Date: 03/28/06  
Operator: MEDICINE BOW OPERATING CO Abatement Date: 03/28/06  
Case #: WYW161166X FAC ID: Corrected Date: 03/28/06  
Form: I FAC NAME: Followup Date: 04/03/06  
Assessment: \$500 Inspector: ROSS Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3164.1 (a) and Onshore Order No. 2 III C.7.  
Remarks Date: 03/27/06

Drilling inspection of NWHCU 40-12 shows that there is no flare pit. Corrective action: Install flare pit 100 feet from well bore per Onshore Order No. 2.

Office: BU ID: BU9683  
Unique INC #: CR06-24-DI Well Name: NWHCU  
Well #: 40-12 ID Date: 03/27/06  
Effective Date: 03/28/06  
Operator: MEDICINE BOW OPERATING CO Abatement Date: 03/28/06  
Case #: WYW161166X FAC ID: Corrected Date: 03/27/06  
Form: I FAC NAME: Followup Date: 04/03/06  
Assessment: \$500 Inspector: ROSS Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3164.1 (a) and Onshore Order No. 2 III A.1.  
Remarks Date: 03/27/06

An inspection on well NWHCU 40-12 shows that the air supply to the air jammers on the pressure accumulator system was turned off.

Office: BU ID: BU9684  
Unique INC #: CR06-25-DI Well Name: NWHCU  
Well #: 40-12 ID Date: 03/27/06  
Effective Date: 03/28/06  
Operator: MEDICINE BOW OPERATING CO Abatement Date: 04/25/06  
Case #: WYW161166X FAC ID: Corrected Date: 04/03/06  
Form: I FAC NAME: Followup Date: 04/03/06  
Assessment: \$0 Inspector: ROSS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)  
Remarks Date: 03/27/06

Safety and Drilling Related Violations (INC)s Issued During FY 2006  
As of March 3, 2011

An inspection on well NWHCU 40-12 shows that the well sign does not have the Lease Number. The Location says township 45 N. instead of township 46 N.

Office: BU		ID: BU9730
Unique INC #: CR06-27-DI	Well Name: NWHCU	
	Well #: 40-12	
Operator: MEDICINE BOW OPERATING CO		
Case #: WYW161166X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$3,500	Inspector: ROSS	
Gravity: 1		
Authority Ref: 43 CFR 3164.1 (a) and Onshore Order No. 2 III A.1.		

Remarks Date: 04/03/06

An inspection on well NWHCU 40-12 shows that the air supply to the air jammers on the pressure accumulator system was turned off. The assessment is for each day after drilling out the surface casing shoe, less the day assessed on the first INC, number CR06-24-DI, for a total of seven days.

Office: BU		ID: BU9505
Unique INC #: GR0606A	Well Name: HDU POD	
	Well #: 1441	
Operator: XTO ENERGY INC		
Case #: 8910194240	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$1,500	Inspector: ROTH	
Gravity: 1		
Authority Ref: 43 CFR 3163.1(b)(1) & Onshore Order #2 III.A.1.		

Remarks Date: 02/02/06

Failure to install and maintain BOPE system. Specifically: Air supply was shut off to accumulator Power source and Floor Remote Control. NOTE: Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed and maintained, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). Shoe was drilled out 1-30-2006, inspected 2-2-2006.

Office: BU		ID: BU9506
Unique INC #: GR0606	Well Name: HDU POD	
	Well #: 1441	
Operator: XTO ENERGY INC		
Case #: 8910194240	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: ROTH	
Gravity: 1		
Authority Ref: Onshore Order #2 III.C.7.		

Remarks Date: 02/02/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Failure to install Flare line on BOPE system. Specifically: Flare line was not installed on choke manifold and ran out to a flare pit. Corrective action: Install flare line to run out not less than 100' and anchor in place into Flare pit.. Shoe was drilled out 1-30-2006, Inspected 2-2-2006 Corrected, sign and return original copy to the above address.

Office: BU ID: BU9552  
Unique INC #: GR0614 Well Name: SLPU FED  
Well #: 12-28H ID Date: 02/24/06  
Operator: MEDICINE BOW OPERATING CO Effective Date: 02/24/06  
Case #: WYW131217 FAC ID: Abatement Date: 02/24/06  
Form: I FAC NAME: Corrected Date: 02/24/06  
Assessment: \$0 Inspector: ROTH Followup Date: 02/24/06  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order #2, III.A.2.e.  
Remarks Date: 02/24/06

Failure to install and maintain BOPE system. Specifically: Hand Wheels (locking devices) on BOPE not installed. Corrective Action; Install Locking devices (Hand Wheels) . Company rep. was contacted and INC was corrected at time of inspection.

Office: BU ID: BU9550  
Unique INC #: GR0612 Well Name: SLPU FED  
Well #: 12-28H ID Date: 02/24/06  
Operator: MEDICINE BOW OPERATING CO Effective Date: 02/24/06  
Case #: WYW131217 FAC ID: Abatement Date: 02/24/06  
Form: I FAC NAME: Corrected Date: 02/24/06  
Assessment: \$0 Inspector: ROTH Followup Date: 02/24/06  
Gravity: 1 Extend Date:  
Authority Ref: Onshore Order #2, III.A.2.e.  
Remarks Date: 02/24/06

Failure to install and maintain BOPE system. Specifically: Air supply was shut off to accumulator Power source. Corrective Action; Open air supply valves and maintain in the open position. Company rep. was contacted and INC was corrected at time of inspection.

Office: BU ID: BU9549  
Unique INC #: GR0609A Well Name: SLPU FED  
Well #: 12-28H ID Date: 02/24/06  
Operator: MEDICINE BOW OPERATING CO Effective Date: 02/24/06  
Case #: WYW131217 FAC ID: Abatement Date: 02/24/06  
Form: I FAC NAME: Corrected Date: 02/24/06  
Assessment: \$3,500 Inspector: ROTH Followup Date: 02/24/06  
Gravity: 1 Extend Date:  
Authority Ref: Onshore Order #2, III.A.1.  
Remarks Date: 02/24/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Failure to install and maintain BOPE system. Specifically: Rig inspection of Cyclone #6 found 1 Major and 3 Minor violations. 1. Air supply was shut off to accumulator Power source (Major). 2. Manual 1" valve on Annular in the closed position (Minor). 3. Kill line not installed (Minor). 4. Hand wheels not installed on BOPE (Minor). Contacted company rep. to get corrected. NOTE: Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed and maintained, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). Shoe was drilled out 2-17-2006 @ 11:00am , inspected 2-24-2006 at 13:00

Office: BU		ID: BU9551
Unique INC #: GR0613	Well Name: SLPU FED	
	Well #: 12-28H	
Operator: MEDICINE BOW OPERATING CO		
Case #: WYW131217	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: ROTH	
Gravity: 3		
Authority Ref: Onshore Order #2, III.A.2.e.		

Remarks Date: 02/24/06

Failure to install and maintain BOPE system. Specifically: Manual 1" valve on annular preventer (locking device) was in the closed position. Corrective Action; Open valve and maintain in the open position. Company rep. was contacted and INC was corrected at time of inspection.

Office: BU		ID: BU9517
Unique INC #: GR0607A	Well Name: SLPU FED	
	Well #: 14-28H	
Operator: MEDICINE BOW OPERATING CO		
Case #: WYW131217	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$2,000	Inspector: ROTH	
Gravity: 1		
Authority Ref: Onshore Order #2III.C.7.		

Remarks Date: 02/08/06

Failure to install and maintain BOPE system. Specifically: Rig inspection of Cyclone #7 found Air supply was shut off to accumulator Power source. Driller opened valve. NOTE: Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed and maintained, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). Shoe was drilled out 2-3-2006 @ 23:30 , inspected 2-8-2006 at 09:30

Office: BU		ID: BU9553
Unique INC #: GR0615	Well Name: SLPU FED	
	Well #: 12-28H	
Operator: MEDICINE BOW OPERATING CO		
Case #: WYW131217	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: ROTH	
Gravity: 3		
Authority Ref: Onshore Order #2, III.A.2.e.		

Remarks Date: 02/24/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Failure to install and maintain BOPE system. Specifically: Kill line not installed on BOPE system. Corrective Action; Install 2" kill line and keep installed while drilling . Company rep. was contacted and INC was corrected at time of inspection.

Office: BU		ID: BU9519
Unique INC #: GR0608A	Well Name: SLPU FED	ID Date: 02/08/06
	Well #: 12-31H	Effective Date: 02/08/06
Operator: MEDICINE BOW OPERATING CO		Abatement Date: 02/08/06
Case #: WYW133607	FAC ID:	Corrected Date: 02/08/06
Form: I	FAC NAME:	Followup Date: 02/08/06
Assessment: \$5,000	Inspector: ROTH	Extend Date:
Gravity: 1		
Authority Ref: Onshore Order #2 III.C.7.		

Remarks Date: 02/08/06

Failure to install and maintain BOPE system. Specifically: Rig inspection of Cyclone #6 found Air supply was shut off to accumulator Power source. Pusher opened valve. NOTE: Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed and maintained, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). Shoe was drilled out -2006 , inspected 2-8-2006 at 12:45

Office: BU		ID: BU9294
Unique INC #: ALS-002-06	Well Name: N HOUSE CREEK MCBETH	ID Date: 11/14/05
	Well #: 13-18BG	Effective Date:
Operator: PENNACO ENERGY, INC.		Abatement Date: 12/14/05
Case #: WYW115682	FAC ID:	Corrected Date: 11/28/05
Form: I	FAC NAME:	Followup Date: 12/14/05
Assessment: \$0	Inspector: STRINGFIELD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.6 (a)(b)		

Remarks Date: 11/14/05

Inspection conducted on 11/10/05 and it was found that the approved well location was not properly identified. Corrective action: Correctly identify location according to attached regulations.

Office: BU		ID: BU9277
Unique INC #: ALS-001-06	Well Name: SAVAGETON II SAVAGETON	ID Date: 11/07/05
	Well #: 43-32	Effective Date: 11/12/05
Operator: LANCE OIL + GAS CO INC		Abatement Date: 12/07/05
Case #: WYW144503	FAC ID:	Corrected Date: 12/05/05
Form: I	FAC NAME:	Followup Date: 12/01/05
Assessment: \$0	Inspector: STRINGFIELD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.5-1		

Remarks Date: 11/07/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Conducted inspection on 11/3/05 and it was found that pit was oversprayed with cuttings from under-reemeing. According to Master Surface Plan, all drill cuttings must remain in the reserve pit. Overspray and cuttings are not allowed. You must take proper action to correct this problem.

Office: BU ID: BU9793  
Unique INC #: ALS-016-06 Well Name: HARTZOG DRAW CBM HARTZOG  
Well #: 41-17BG ID Date: 04/13/06  
Operator: CH4 ENERGY LLC Effective Date: 04/26/06  
Case #: WYW31325 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: STRINGFIELD  
Gravity: 3  
Authority Ref: 43 CFR 3162.6.a-b Abatement Date: 05/19/06  
Followup Date: 05/25/06  
Extend Date: 06/02/06

Remarks Date: 04/13/06

During a recent inspection it was found that the well sign does not have the correct federal lease number on it. Corrective Action: Fix the sign so that it shows the correct federal lease number.

Office: BU ID: BU9794  
Unique INC #: ALS-017-06 Well Name: HARTZOG DRAW CBM HARTZOG  
Well #: 14-8BG ID Date: 04/13/06  
Operator: CH4 ENERGY LLC Effective Date: 04/25/06  
Case #: WYW31325 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: STRINGFIELD  
Gravity: 3  
Authority Ref: 43 CFR 3162.6.a-b Abatement Date: 05/19/06  
Followup Date: 05/25/06  
Extend Date: 06/02/06

Remarks Date: 04/14/06

During a recent field inspection it was found that the well sign does not have the correct federal lease number. Corrective Action: Fix the sign so that it reflects the correct federal lease number.

Office: BU ID: BU9796  
Unique INC #: ALS-018-06 Well Name: HARTZOG DRAW CBM HARTZOG  
Well #: 23-30BG ID Date: 04/14/06  
Operator: CH4 ENERGY LLC Effective Date: 04/26/06  
Case #: WYW42595 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: STRINGFIELD  
Gravity: 3  
Authority Ref: 43 CFR 3162.6.a-b Abatement Date: 05/19/06  
Followup Date: 05/25/06  
Extend Date: 06/02/06

Remarks Date: 04/14/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

During a recent field inspection it was found that the well sign does not have the correct federal lease number on it. Corrective Action : Fix sign so that it reflects the correct federal lease number.

Office: BU		ID: BU9798
Unique INC #: ALS-019-06	Well Name: HARTZOG DRAW CBM HARTZOG	
	Well #: 14-30BG	ID Date: 04/14/06
Operator: CH4 ENERGY LLC		Effective Date: 04/26/06
Case #: WYW42595	FAC ID:	Abatement Date: 05/19/06
Form: I	FAC NAME:	Corrected Date: 05/25/06
Assessment: \$0	Inspector: STRINGFIELD	Followup Date: 06/02/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6.a-b		

Remarks Date: 04/14/06

During a recent field inspection it was found that the well sign does not have the correct federal lease number and API number. Corrective Action : Fix sign so that it reflects the correct federal lease number.

Office: BU		ID: BU10087
Unique INC #: 06GDT09	Well Name: HARTZOG DRAW CBM HARTZOG	
	Well #: 23-1BG	ID Date: 06/14/06
Operator: CH4 ENERGY LLC		Effective Date: 07/05/06
Case #: WYW16580	FAC ID:	Abatement Date: 07/31/06
Form: I	FAC NAME:	Corrected Date: 07/19/06
Assessment: \$0	Inspector: TRUJILLO	Followup Date: 07/21/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 06/14/06

For wells located on Federal & Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well. The sign shall include the well number, Operator name, lease serial number, communitization or unit number as appropriate, and the  $\frac{1}{4}\frac{1}{4}$  section, section, township and range. All identification shall be maintained in a legible condition and shall be clearly apparent to any person at or approaching the sales or transportation point.  
THIS SIGN HAS THE WRONG LEASE NIUMBER. IT HAS WYW016580 AND THE CORRECT ONE IS WYW16580 CAN YOU PLEASE CHANGE THE SIGN TO THE RIGHT ONE.

Office: BU		ID: BU10086
Unique INC #: 06GDT08	Well Name: HARTZOG DRAW CBM HARTZOG	
	Well #: 21-23BG	ID Date: 06/14/06
Operator: CH4 ENERGY LLC		Effective Date: 07/10/06
Case #: WYW35757	FAC ID:	Abatement Date: 07/31/06
Form: I	FAC NAME:	Corrected Date: 07/19/06
Assessment: \$0	Inspector: TRUJILLO	Followup Date: 07/21/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 06/14/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

For wells located on Federal & Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well. The sign shall include the well number, Operator name, lease serial number, communitization or unit number as appropriate, and the  $\frac{1}{4}\frac{1}{4}$  section, section, township and range. All identification shall be maintained in a legible condition and shall be clearly apparent to any person at or approaching the sales or transportation point. The well sign for this location should read WYW35757. The current sign reads WYW035757 and that wrong please change the sign.

Office: BU		ID: BU10085
Unique INC #: 06GDT07	Well Name: HARTZOG DRAW CBM HARTZOG	ID Date: 06/27/06
	Well #: 12-23BG	Effective Date: 07/10/06
Operator: CH4 ENERGY LLC		Abatement Date: 07/31/06
Case #: WYW35757	FAC ID:	Corrected Date: 07/19/06
Form: I	FAC NAME:	Followup Date: 07/21/06
Assessment: \$0	Inspector: TRUJILLO	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 06/27/06

For wells located on Federal & Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well. The sign shall include the well number, Operator name, lease serial number, communitization or unit number as appropriate, and the  $\frac{1}{4}\frac{1}{4}$  section, section, township and range. All identification shall be maintained in a legible condition and shall be clearly apparent to any person at or approaching the sales or transportation point. The well lease number is not right. The proper lease number is WYW35757. Please fix this problem.

Office: BU		ID: BU10641
Unique INC #: JW06-61-I	Well Name: SQUAW CREEK ADD SS	ID Date: 04/03/06
	Well #: 07WP-30	Effective Date: 04/03/06
Operator: PINNACLE GAS RESOURCES, INC		Abatement Date: 05/10/06
Case #: WYW138608	FAC ID:	Corrected Date: 05/10/06
Form: I	FAC NAME:	Followup Date: 05/10/06
Assessment: \$5,000	Inspector: WALKER	Extend Date:
Gravity: 1		
Authority Ref: 43CFR3163.1.b.2		

Remarks Date: 04/03/06

Per 43 CFR 3163.1.b.2 the above well was spud and surface casing set without an approved application for permit to drill. You must submit and APD for this well to this office no later than May 10, 2006. The well must remain shut-in until the APD is approved by the Authorized Officer.

Office: BU		ID: BU10644
Unique INC #: JW06-67-I	Well Name: SQUAW CREEK ADD SS	ID Date: 04/03/06
	Well #: 07WP-30	Effective Date: 04/03/06
Operator: PINNACLE GAS RESOURCES, INC		Abatement Date: 05/10/06
Case #: WYW138608	FAC ID:	Corrected Date: 05/10/06
Form: I	FAC NAME:	Followup Date: 05/15/06
Assessment: \$0	Inspector: WALKER	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.6.b		

Remarks Date: 04/03/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Field inspection shows that the above well does not have an identification sign. Corrective Action: Please install a sign at this well showing Operator name, well name and number, surveyed legal description and Federal lease number. Thank you

Office: BU ID: BU10643  
Unique INC #: JW06-66-I Well Name: SQUAW CREEK ADD SS  
Well #: 07CC-30\* ID Date: 04/03/06  
Operator: PINNACLE GAS RESOURCES, INC Effective Date: 04/03/06  
Case #: WYW138608 FAC ID: Abatement Date: 05/10/06  
Form: I FAC NAME: Corrected Date: 05/10/06  
Assessment: \$0 Inspector: WALKER Followup Date: 05/15/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6.b  
  
Remarks Date: 04/03/06

Field inspection shows that the above well does not have an identification sign. Corrective Action: Please install a sign at this well showing Operator name, well name and number, surveyed legal description and Federal lease number. Thank you

Office: BU ID: BU10642  
Unique INC #: JW06-62-I Well Name: SQUAW CREEK ADD SS  
Well #: 07CC-30\* ID Date: 04/03/06  
Operator: PINNACLE GAS RESOURCES, INC Effective Date: 04/03/06  
Case #: WYW138608 FAC ID: Abatement Date: 05/10/06  
Form: I FAC NAME: Corrected Date: 05/10/06  
Assessment: \$5,000 Inspector: WALKER Followup Date: 05/10/06  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3163.1.b.2  
  
Remarks Date: 04/03/06

Per 43 CFR 3163.1.b.2 the above well was spud and surface casing set without an approved application for permit to drill. You must submit and APD for this well to this office no later than May 10, 2006. The well must remain shut-in until the APD is approved by the Authorized Officer.

Office: BU ID: BU9335  
Unique INC #: JW06-09-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 12/21/05  
Form: I FAC NAME: Corrected Date: 12/19/05  
Assessment: \$0 Inspector: WALKER Followup Date: 12/21/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,a,iii  
  
Remarks Date: 11/22/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Drilling inspection of Pickrel Federal 24-35 shows that the well sign does not show the Federal lease number. Corrective Action: Please install Federal lease number WYW143758 to the well sign.

Office: BU ID: BU9338  
Unique INC #: JW06-11-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$2,000 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,C,7  
  
Remarks Date: 11/22/05

Drilling inspection of Pickrel Federal 24-35 shows that there is not a flare pit. Corrective Action: Install flare pit 100 feet from the well bore per Onshore Order No.2.

Office: BU ID: BU9339  
Unique INC #: JW06-12-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$0 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,h,i  
  
Remarks Date: 11/22/05

Drilling inspection of Pickrel Federal 24-35 shows that the BOPE test pressures and the activation of the pipe and blind rams are not recorded in the drillers log. Corrective Action: All BOPE and related tests must be recorded in the drillers log.

Office: BU ID: BU9331  
Unique INC #: JW06-05-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$0 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,a,iii  
  
Remarks Date: 11/22/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Drilling inspection of Pickrel Federal 24-35 shows that there was not a fill line hooked up to the preventor. Corrective Action: Install and maintain fill line to the preventer.

Office: BU ID: BU9332  
Unique INC #: JW06-06-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$0 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,a,iii

Remarks Date: 11/22/05

Drilling inspection of Pickrel Federal 24-35 shows that the kill line valve does not have a handle on it. Corrective Action: Install a handle on the kill line valve.

Office: BU ID: BU9333  
Unique INC #: JW06-07-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$0 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,a,iii

Remarks Date: 11/22/05

Drilling inspection of Pickrel Federal 24-35 shows that the inside choke line valve does not have a handle on it. Corrective Action: Install a handle on the inside choke line valve.

Office: BU ID: BU9329  
Unique INC #: JW06-03-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$2,000 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3164.1 OSO#2,III,A,2,a,i

Remarks Date: 11/22/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Blow out preventer (BOP) and related equipment (BOPE) shall be installed, maintained and tested in a manner necessary to ensure well control and shall be operational prior to drilling surface casing shoe. Specifically: The remote control for the BOP was not hooked up and operational.

Office: BU ID: BU9334  
Unique INC #: JW06-08-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$0 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,a,iii

Remarks Date: 11/22/05

Drilling inspection of Pickrel Federal 24-35 shows that the outside choke line valve does not have a handle on it. Corrective Action: Install a handle on the outside choke line valve.

Office: BU ID: BU9337  
Unique INC #: JW06-10-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$0 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,b,i

Remarks Date: 11/22/05

Drilling inspection of Pickrel Federal 24-35 shows the flare lines were not hooked up to the choke manifold. Corrective Action: Install and maintain flare lines to the choke manifold.

Office: BU ID: BU9330  
Unique INC #: JW06-04-I Well Name: PICKREL FEDERAL  
Well #: 24-35 ID Date: 11/22/05  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 11/22/05  
Case #: WYW143758 FAC ID: Abatement Date: 11/23/05  
Form: I FAC NAME: Corrected Date: 11/23/05  
Assessment: \$0 Inspector: WALKER Followup Date: 11/23/05  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1,a OSO#2,III,A,2,g

Remarks Date: 11/22/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Drilling inspection of Pickrel Federal 24-35 shows that the hand wheels for the BOP were not hooked up. Corrective Action: Please hook up hand wheels to the BOP.

Office: BU ID: BU9325  
Unique INC #: JW06-01-I Well Name: WILD HORSE CK MALLI ID Date: 11/21/05  
Well #: 12-24 Effective Date: 11/21/05  
Operator: MEDALLION EXPLORATION Abatement Date: 12/12/05  
Case #: WYW146326 FAC ID: Corrected Date: 12/07/05  
Form: I FAC NAME: Followup Date: 12/12/05  
Assessment: \$0 Inspector: WALKER Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.6(b)

Remarks Date: 11/21/05

Drilling inspection of Federal well 12-24 indicates that this well does not have a well sign. Corrective Action: Please install a well sign showing operator name, well name and number, surveyed legal description and Federal lease number. Thank you.

Office: BU ID: BU9327  
Unique INC #: JW06-02-I Well Name: WILD HORSE CK MALLI ID Date: 11/21/05  
Well #: 12-24 Effective Date: 11/21/05  
Operator: MEDALLION EXPLORATION Abatement Date: 12/12/05  
Case #: WYW146326 FAC ID: Corrected Date: 12/07/05  
Form: I FAC NAME: Followup Date: 12/08/05  
Assessment: \$0 Inspector: WALKER Extend Date:  
Gravity: 3  
Authority Ref: Conditions of Approval

Remarks Date: 11/21/05

Spud for this well was called in to this office for the 19th of November. Well was actually spudded on the 18th, 7" production casing was run and cemented on the 19th. Drilling operations were completed on the 21st. Conditions of Approval for federal wells require the operator to notify this office 24 hours in advance of spudding a well and for any cementing operations. Corrective Action: In the future Please notify this office 24 hours in advance of spudding a well or if the spud date and time changes. Thank you for your cooperation.

Office: CC ID: CC877  
Unique INC #: RG06EG001A Well Name: FERGUSON FEDERAL ID Date: 07/24/05  
Well #: 16-9-5-45 Effective Date: 07/24/05  
Operator: THE HOUSTON EXPLORATION COMPANY Abatement Date: 12/05/05  
Case #: COC67167 FAC ID: Corrected Date: 12/28/05  
Form: I FAC NAME: Followup Date: 02/01/06  
Assessment: \$5,000 Inspector: EGILLINGHAM Extend Date:  
Gravity: 1  
Authority Ref: CFR 3162.3-1(c)

Remarks Date: 12/08/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

--07/24/05: Operator (Loyd Bruce) reported well had been drilled on federal minerals without approval. --07/24/05: Ernie Gillingham gave operator verbal notification that operator would receive Incident of Noncompliance for violation and bill for assessment. Instructions were given via telephone call of the corrective actions that would be required for violation; 1) Submit "Application for Permit to Continue Operations on a Trespass well 2) Submit all available information related to well drilling activities 3) Submit Surface Use Plan explaining what surface disturbance was done, what reclamation work will be completed 4) Submit copy of Landowner Agreement 5) Submit a cultural report for all disturbed areas related to drilling of well. Report must be completed by a BLM certified contract archaeologist. --Operator notified additional information may be required after review of above information. Operator notified that approval of "Application for Permit to Continue Operations of Trespass Well" would include "Conditions of Approval" requirements that may include additional remedial work to meet BLM requirements. --08/22/05: Operator submitted "Application for Permit to Continue Operations of Trespass well" with partial information. --12/08/05: As of this date, review is still pending completion of NEPA analysis, and additional submissions by the operator. No landowner agreement has been furnished, and no cultural report has been received. --Contact Ernie Gillingham (719 269 8531) for questions related to this INC

Office: DK		ID: DK6312
Unique INC #: IDB06007	Well Name: 9210 JV-P WANNAGAN	
	Well #: 2-H	
Operator: BTA OIL PRODUCERS		
Case #: NDM93654	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: DEBBIE BOHLMAN	
Gravity: 3		
Authority Ref: 43 CFR 3164.1	Onshore Order #6 III.D.3.a	
Remarks Date: 06/20/06		

There is no danger sign at the well location warning the public of the potential H2S danger. Install a danger sign at the well location warning the public of the potential H2S danger.

Office: DK		ID: DK6311
Unique INC #: IDB06006	Well Name: 9210 JV-P WANNAGAN	
	Well #: 2-H	
Operator: BTA OIL PRODUCERS		
Case #: NDM93654	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: DEBBIE BOHLMAN	
Gravity: 3		
Authority Ref: 43 CFR 3164.1	Onshore Order #6 III.D.3.e	
Remarks Date: 06/20/06		

The wind direction indicator at the tank battery is not visible from the well location. Install a wind direction indicator at the well location.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GF		ID: GF2459
Unique INC #: DJ-05-01	Well Name: US	
	Well #: 27-10-25-18	ID Date: 11/17/05
Operator: DEVON ENERGY PRODUCTION CO.		Effective Date: 12/08/05
Case #: MTM1502	FAC ID:	Abatement Date: 12/28/05
Form: I	FAC NAME:	Corrected Date: 12/21/05
Assessment: \$0	Inspector: MITCHELL	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 11/17/05

Installing a pipeline without approval. Devon shall submit a cultural clearance for the referenced well.

Office: GJ		ID: GJ5402
Unique INC #: WB05001	Well Name: MY WAY RANCH FEDERAL	
	Well #: 31-13	ID Date: 04/04/05
Operator: LARAMIE ENERGY LLC		Effective Date: 04/04/05
Case #: COC65766	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 10/01/05
Assessment: \$0	Inspector: BANKERT	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3164.1 Onshore Order No.2 III. B.		

Remarks Date: 04/04/05

Review of the casing and cement record for the 31-13 indicates the surface casing and cement program were not conducted as approved in the APD. The APD surface casing setting depth was approved for 1000' and cemented to surface with 65/35 pozmix cement with additives. The records for the well show the surface casing was set to 1220' MD and cemented in two stages with the lead stage of HALCO type 5 with additives for a 12.3 ppg weight and tail stage with HALCO Type 5 80/20 pozmix and additives for a 14.2 ppg weight. Review of Laramie's APD's (both pending and approved) 10 point drilling plan show the surface casing and cementing programs are generic at best and do not give an accurate representation of the actual drilling program. The setting depths for the surface casings do not coincide with the directional programs. Laramie will submit revised drilling plans for all wells currently pending or to be drilled that reflects the actual drilling operations for the surface casing and cement program. Casing setting depths will be identified and will coincide with the directional plans. The cement program will identify each individual stage and will include the number of sacks, type of cement, including additives, yield, and weight, for each stage.

Office: GJ		ID: GJ5931
Unique INC #: EF06063	Well Name:	
	Well #:	ID Date: 07/11/06
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 07/27/06
Case #: COC48964A	FAC ID: 6302	Abatement Date: 08/28/06
Form: I	FAC NAME:	Corrected Date: 07/31/06
Assessment: \$0	Inspector: FANCHER	Followup Date: 08/03/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 07/11/06

All weed around the production equipment and well head shall be removed.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GR ID: GR1332  
Unique INC #: 063047 Well Name: BLUE FOREST UNIT  
Well #: 40-18 ID Date: 05/31/06  
Operator: CABOT OIL & GAS CORPORATION Effective Date: 05/31/06  
Case #: WYW090897X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MOFFETT Abatement Date: 06/01/06  
Gravity: 3 Corrected Date: 06/01/06  
Authority Ref: OO#2 III.A.2.d. Followup Date: 06/01/06  
Extend Date:

Remarks Date: 05/31/06

Violation: Accumulator failed pre-charge portion of test. Corrective Action: Replace or repair accumulator parts as necessary to ensure proper functioning capabilities as specified in OO#2.

Office: GR ID: GR1333  
Unique INC #: 063046 Well Name: BLUE FOREST UNIT  
Well #: 40-18 ID Date: 05/31/06  
Operator: CABOT OIL & GAS CORPORATION Effective Date: 05/31/06  
Case #: WYW090897X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MOFFETT Abatement Date: 06/01/06  
Gravity: 3 Corrected Date: 06/01/06  
Authority Ref: OO #2 III.A.2.f. Followup Date: 06/01/06  
Extend Date:

Remarks Date: 05/31/06

Violation: Accumulator failed pump capacity portion of test. Corrective Action: Replace or repair accumulator parts as necessary to ensure proper functioning capabilities as specified in OO#2.

Office: GR ID: GR1311  
Unique INC #: 063026 Well Name: JADE  
Well #: 10-11 ID Date: 01/06/06  
Operator: MAK-J ENERGY WYOMING LLC Effective Date: 01/06/06  
Case #: WYW88489 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MOFFETT Abatement Date: 01/07/06  
Gravity: 3 Corrected Date: 01/07/06  
Authority Ref: Onshore Order #2.III.A.2.h. Followup Date: 01/09/06  
Extend Date:

Remarks Date: 01/06/06

Violation: Remote control was not installed in accordance with Onshore Order #2. Corrective Action: Establish and maintain air supply to the remote on the rig floor.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GR ID: GR1312  
Unique INC #: 063027 Well Name: JADE ID Date: 01/06/06  
Well #: 10-11 Effective Date: 01/06/06  
Operator: MAK-J ENERGY WYOMING LLC Abatement Date: 01/07/06  
Case #: WYW88489 FAC ID: Corrected Date: 01/07/06  
Form: I FAC NAME: Followup Date: 01/09/06  
Assessment: \$0 Inspector: MOFFETT Extend Date:  
Gravity: 3  
Authority Ref: OO#2.III.A.2.g.

Remarks Date: 01/06/06

Violation: BOP equipment was not installed in accordance with Onshore Order #2. Corrective Action: Install valve in closing line to the annular.

Office: GR ID: GR1334  
Unique INC #: 616061 Well Name: MOSES FEDERAL ID Date: 06/16/06  
Well #: 22-12 Effective Date: 06/16/06  
Operator: TRUE OIL COMPANY Abatement Date:  
Case #: WYW0320711 FAC ID: Corrected Date: 06/16/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: TONER Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2III.A.2.a.iii.

Remarks Date: 06/16/06

There is not a pressure gauge in choke manifold at time of inspection. Install pressure gauge in a ccordance to O.O.#2

Office: GR ID: GR1335  
Unique INC #: 616062 Well Name: MOSES FEDERAL ID Date: 06/16/06  
Well #: 22-12 Effective Date: 06/16/06  
Operator: TRUE OIL COMPANY Abatement Date: 06/17/06  
Case #: WYW0320711 FAC ID: Corrected Date: 06/16/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: TONER Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2 III.A.2.c.ii

Remarks Date: 06/16/06

Air supply (2nd power source) was found turned off to the accumulator. Insure accumulator has 2 independent power sources available at all times in accordance with O.O.#2.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GR ID: GR1316  
Unique INC #: 063031 Well Name: RIFES RIM UNIT  
Well #: 13-10 ID Date: 01/31/06  
Operator: WARREN E&P, INCORPORATED Effective Date: 01/31/06  
Case #: WYW155917X FAC ID: Abatement Date: 02/02/06  
Form: I FAC NAME: Corrected Date: 02/02/06  
Assessment: \$0 Inspector: TONER Followup Date: 02/02/06  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2 III.A.2.i.ii.

Remarks Date: 01/31/06

On 1/31/06 inspector Moffett found that BOPE was not tested to APD approved pressure rating of 3000psi or 70% of internal yield pressure of casing in accordance with O.O.#2 III. A.2.i.ii. Corrective action: Tested BOPE to approved pressure rating on 2/2/2006. Company representative Bill Lee has complied with retesting of BOPE

Office: GR ID: GR1314  
Unique INC #: 063029 Well Name: RIFES RIM UNIT  
Well #: 13-10 ID Date: 01/24/06  
Operator: WARREN E&P, INCORPORATED Effective Date: 01/24/06  
Case #: WYW155917X FAC ID: Abatement Date: 01/25/06  
Form: I FAC NAME: Corrected Date: 01/24/06  
Assessment: \$0 Inspector: TONER Followup Date: 01/25/06  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2 III.A.h.

Remarks Date: 01/24/06

Violation: Upon inspection inspector found the accumulator remote control on rig floor was not operable. Clint Raby- Company representative immediately corrected violation prior to inspector leaving location.

Office: GR ID: GR1313  
Unique INC #: 063028 Well Name: RIFES RIM UNIT  
Well #: 13-10 ID Date: 01/24/06  
Operator: WARREN E&P, INCORPORATED Effective Date: 01/24/06  
Case #: WYW155917X FAC ID: Abatement Date: 01/25/06  
Form: I FAC NAME: Corrected Date: 01/24/06  
Assessment: \$0 Inspector: TONER Followup Date: 01/25/06  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2 III.A.c.ii.

Remarks Date: 01/24/06

Violation: Upon inspection inspector found only one power source available to Accumulator. Air supply had been shut to accumulator leaving only electricity as power supply. A 3M system accumulator requires two independent power supplies. Clint Raby- Company Representative immediately corrected action prior to inspector leaving location.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GR		ID: GR1323
Unique INC #: 063037	Well Name: BUSHBUCK UNIT	
	Well #: 30-34	ID Date: 03/22/06
Operator: MAK-J ENERGY WYOMING LLC		Effective Date: 03/22/06
Case #: WYW163051X	FAC ID:	Abatement Date: 04/22/06
Form: I	FAC NAME:	Corrected Date: 03/22/06
Assessment: \$0	Inspector: TONER	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O.#2 III.B.1.h.		

Remarks Date: 03/22/06

During a Drilling inspection, inspector found that surface casing had not been tested in accordance with Onshore Order #2. Could not perform any type of corrective action as the well is almost TD'd.

Office: GS		ID: GS5910
Unique INC #: 060023	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/29/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/29/06
Case #: COC41696	FAC ID:	Abatement Date: 06/30/06
Form: I	FAC NAME:	Corrected Date: 07/01/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 06/30/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. C. 7.		

Remarks Date: 06/29/06

All flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. Corrective action: Install flare system as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/29/2006 at 1200.

Office: GS		ID: GS5907
Unique INC #: 060020	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/29/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/29/06
Case #: COC41696	FAC ID:	Abatement Date: 06/30/06
Form: I	FAC NAME:	Corrected Date: 06/30/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 06/30/06
Gravity: 3		Extend Date:
Authority Ref: o.o#2 III. A. 2. a. iii.		

Remarks Date: 06/29/06

Minimum standards and enforcement provisions for well equipment. 3 M (3000 psi) system (required equipment) Kill line (2 inch minimum) Corrective action: install kill line as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/29/2006 at 1200.

Safety and Drilling Related Violations (INC)s Issued During FY 2006  
As of March 3, 2011

Office: GS		ID: GS5909
Unique INC #: 060022	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/29/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/29/06
Case #: COC41696	FAC ID:	Abatement Date: 06/30/06
Form: I	FAC NAME:	Corrected Date: 07/01/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 06/30/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. g.		

Remarks Date: 06/29/06

Minimum standards and enforcement provisions for locking devices. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative. Corrective action: Install valve as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/29/2006 at 1200.

Office: GS		ID: GS5915
Unique INC #: 060027	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/30/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/30/06
Case #: COC41696	FAC ID:	Abatement Date: 07/01/06
Form: I	FAC NAME:	Corrected Date: 07/01/06
Assessment: \$250	Inspector: BAGBY	Followup Date: 07/01/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2. III. A. 2. g.		

Remarks Date: 06/30/06

Minimum standards and enforcement provisions for locking devices. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative. Corrective action: Install valve as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/30/2006 at 1500.

Office: GS		ID: GS5908
Unique INC #: 060021	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/29/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/29/06
Case #: COC41696	FAC ID:	Abatement Date: 06/30/06
Form: I	FAC NAME:	Corrected Date: 06/30/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 06/30/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2 III. A. 2. h.		

Remarks Date: 06/29/06

Minimum standards and enforcement provisions for remote controls. Remote controls shall be readily accessible to the driller. Remote control for all 3M or greater systems shall be capable of closing all preventers. Corrective action: Install Remote control as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/29/2006 at 1200.

Safety and Drilling Related Violations (INC)s Issued During FY 2006  
As of March 3, 2011

Office: GS		ID: GS5914
Unique INC #: 060026	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/30/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/30/06
Case #: COC41696	FAC ID:	Abatement Date: 07/01/06
Form: I	FAC NAME:	Corrected Date: 07/01/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 07/01/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2. III. A. 2. a. iii.		

Remarks Date: 06/30/06

Minimum standards and enforcement provisions for well equipment. 3 M (3000 psi) system (required equipment). A minimum of 2 choke line valves (3 inch minimum) Corrective action: install complete choke line valves as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/30/2006 at 1500.

Office: GS		ID: GS5911
Unique INC #: 060024	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/29/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/29/06
Case #: COC41696	FAC ID:	Abatement Date: 06/30/06
Form: I	FAC NAME:	Corrected Date: 06/30/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 06/30/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1 (b)		

Remarks Date: 06/29/06

The operator shall exercise due care and diligence to assure that leasehold operations do not result in undue damage to surface or subsurface resources or surface improvements. Corrective action: Construct and/or install containment device at the end of flare lines capable of containing any and all possible fluid discharges and capable of diverting any burning from reaching surrounding vegetation in order to prevent undue damage to surface or subsurface resources or surface improvements. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/29/2006 at 1200.

Office: GS		ID: GS5916
Unique INC #: 060028	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/30/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/30/06
Case #: COC41696	FAC ID:	Abatement Date: 07/01/06
Form: I	FAC NAME:	Corrected Date: 07/01/06
Assessment: \$500	Inspector: BAGBY	Followup Date: 07/01/06
Gravity: 1		Extend Date:
Authority Ref: O.O.. #2. III. C. 7.		

Remarks Date: 06/30/06

All flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. Corrective action: Install flare system as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/30/2006 at 1500.

Safety and Drilling Related Violations (INC)s Issued During FY 2006  
As of March 3, 2011

Office: GS		ID: GS5913
Unique INC #: 060025	Well Name: GARFIELD COUNTY RWF	
	Well #: 441-20	ID Date: 06/30/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 06/30/06
Case #: COC41696	FAC ID:	Abatement Date: 07/01/06
Form: I	FAC NAME:	Corrected Date: 07/01/06
Assessment: \$0	Inspector: BAGBY	Followup Date: 07/01/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2. III. A. 2. a. iii.		

Remarks Date: 06/30/06

Minimum standards and enforcement provisions for well equipment. 3 M (3000 psi) system (required equipment) . 2 kill line valves, one of which shall be a check valve (2 inch minimum) Corrective action: install complete kill line valve as required in Onshore Oil and Gas Order No. 2. Stan Dudley (Williams Rep.) was informed of the issuance of this INC on 06/30/2006 at 1500.

Office: GS		ID: GS5707
Unique INC #: EF06001	Well Name: GARFIELD COUNTY RWF	
	Well #: 531-20	ID Date: 01/17/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 01/20/06
Case #: COC41696	FAC ID:	Abatement Date: 01/25/06
Form: I	FAC NAME:	Corrected Date: 01/25/06
Assessment: \$0	Inspector: FANCHER	Followup Date: 04/17/06
Gravity: 1		Extend Date:
Authority Ref: Onshore Order 2, III.B.		

Remarks Date: 01/17/06

The proposed casing and cementing programs shall be conducted as approved. We noticed that approved cement program had been changed. The approved tail and lead cement was not mixed to the approved weights. The Halliburton rep. said that Williams changed the requirement about 3 months ago. We require Sundry Notice for this change and an explanation of why the change was needed.

Office: GS		ID: GS5829
Unique INC #: EF06028	Well Name: FEDERAL PA	
	Well #: 13-26 (324-26)	ID Date: 03/21/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 03/26/05
Case #: COC66630	FAC ID:	Abatement Date: 03/27/06
Form: I	FAC NAME:	Corrected Date: 04/17/06
Assessment: \$0	Inspector: FANCHER	Followup Date: 04/17/06
Gravity: 1		Extend Date: 05/01/06
Authority Ref: Onshore Order No.2, III.B.1.c.		

Remarks Date: 03/21/06

The approved plan stated about 250 sxs of tail cement was to be used and about 803 sxs of lead cement would be used. The cement ordered and pumped did not circulate to surface as required. Bond logging/testing is required to determine the quality of the cementing job and remedial cement is still required by Onshore Orders.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GS		ID: GS5875
Unique INC #: 060008	Well Name: RWF	
	Well #: 543-17	ID Date: 05/10/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 05/10/06
Case #: COC50858	FAC ID:	Abatement Date: 05/10/06
Form: I	FAC NAME:	Corrected Date: 05/10/06
Assessment: \$0	Inspector: FICKLIN	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A. 2. C. ii.		

Remarks Date: 05/10/06

The 3M system shall have 2 independent power sources to close the preventers. Turn on all the required power sources for the closing unit pumps and maintain them on and available at all times.

Office: GS		ID: GS5874
Unique INC #: 060007	Well Name: RWF	
	Well #: 543-17	ID Date: 05/10/06
Operator: WILLIAMS PRODUCTION RMT CO		Effective Date: 05/10/06
Case #: COC50858	FAC ID:	Abatement Date: 05/10/06
Form: I	FAC NAME:	Corrected Date: 05/10/06
Assessment: \$0	Inspector: FICKLIN	Followup Date: 05/11/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. A. 2. e.		

Remarks Date: 05/10/06

Minimum standards and enforcement provisions for power availability. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the preset level. Turn on all the required power sources for the closing unit pumps and maintain them on and available at all times.

Office: GS		ID: GS5893
Unique INC #: 060017	Well Name: FEDERAL	
	Well #: 8-21A (8C)	ID Date: 06/07/06
Operator: NOBLE ENERGY INC		Effective Date: 06/07/06
Case #: COC58670	FAC ID:	Abatement Date: 06/08/06
Form: I	FAC NAME:	Corrected Date: 06/08/06
Assessment: \$0	Inspector: FICKLIN	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: O.O. #2 III. C. 7.		

Remarks Date: 06/07/06

All flare systems shall be designed to gather and burn all gas. The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. Install flare lines in compliance with regulations. Flare lines shall be in place prior to the surface shoe being drilled out.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GS ID: GS5889  
Unique INC #: 060013 Well Name: FEDERAL ID Date: 06/07/06  
Well #: 8-21A (8C) Effective Date: 06/07/06  
Operator: NOBLE ENERGY INC Abatement Date: 06/08/06  
Case #: COC58670 FAC ID: Corrected Date: 06/08/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: FICKLIN Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. A. 2. a. iii.

Remarks Date: 06/07/06

Minimum standards and enforcement provisions for well control equipment. Safety valve and subs to fit all drill string connections in use. Install a safety valve. Safety valve is to be located on the rig floor and ready to use (i.e. valve shall be in the open position and the appropriate handle available). Valve shall be in place prior to the surface shoe being drilled out.

Office: GS ID: GS5891  
Unique INC #: 060015 Well Name: FEDERAL ID Date: 06/07/06  
Well #: 8-21A (8C) Effective Date: 06/07/06  
Operator: NOBLE ENERGY INC Abatement Date: 06/08/06  
Case #: COC58670 FAC ID: Corrected Date: 06/07/06  
Form: I FAC NAME: Followup Date: 06/08/06  
Assessment: \$0 Inspector: FICKLIN Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. A. 2. h.

Remarks Date: 06/07/06

Minimum standards and enforcement provisions for remote controls. Remote controls shall be readily available to the driller. Remote controls for all 3M or greater systems shall be capable of closing all preventers. Install remote control. Assure the remote control is readily available. Remote control shall be installed and readily available prior to drilling out the surface shoe.

Office: GS ID: GS5892  
Unique INC #: 060016 Well Name: FEDERAL ID Date: 06/07/06  
Well #: 8-21A (8C) Effective Date: 06/07/06  
Operator: NOBLE ENERGY INC Abatement Date: 06/08/06  
Case #: COC58670 FAC ID: Corrected Date: 06/08/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: FICKLIN Extend Date:  
Gravity: 3  
Authority Ref: O.O. #2 III. A. 2. g.

Remarks Date: 06/07/06

Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e. hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. Install locking device (i.e. hand wheels) on the rams. Locking devices shall be in place prior to the surface shoe being drilled out.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: GS			ID: GS5890
Unique INC #: 060014	Well Name: FEDERAL		
	Well #: 8-21A (8C)		ID Date: 06/07/06
Operator: NOBLE ENERGY INC			Effective Date: 06/07/06
Case #: COC58670	FAC ID:		Abatement Date: 06/08/06
Form: I	FAC NAME:		Corrected Date: 06/07/06
Assessment: \$0	Inspector: FICKLIN		Followup Date: 06/08/06
Gravity: 3			Extend Date:
Authority Ref: O.O. #2 III. 2. a. iii.			

Remarks Date: 06/07/06

Minimum standards and enforcement provisions for well control equipment. Kill Line (2 inch minimum) Install a kill line. Kill line is to be connected to the BOPE stack at the drilling spool. Kill line shall be in place prior to the surface shoe being drilled out.

Office: GS			ID: GS5990
Unique INC #: 060056	Well Name: HELLS GULCH FEDERAL		
	Well #: 26-11(26-7)		ID Date: 08/31/06
Operator: LARAMIE ENERGY LLC			Effective Date: 08/31/06
Case #: COC66918	FAC ID:		Abatement Date: 09/01/06
Form: I	FAC NAME:		Corrected Date: 09/01/06
Assessment: \$0	Inspector: FICKLIN		Followup Date: 12/15/06
Gravity: 3			Extend Date:
Authority Ref: O.O. #2 III. A. c. ii.			

Remarks Date: 08/31/06

The 3M system (accumulator) shall have 2 independent power sources to close the preventers. Corrective Action: Provide 2 independent power sources to the accumulator and have both power sources available at all times.

Office: GS			ID: GS5992
Unique INC #: 060057	Well Name: HELL'S GULCH FEDERAL		
	Well #: 26-11(26-7)		ID Date: 08/31/06
Operator: LARAMIE ENERGY LLC			Effective Date: 08/31/06
Case #: COC66918	FAC ID:		Abatement Date: 09/01/06
Form: I	FAC NAME:		Corrected Date: 09/01/06
Assessment: \$0	Inspector: FICKLIN		Followup Date: 12/15/06
Gravity: 3			Extend Date:
Authority Ref: O.O. #2 III. A. 2. a. iii.			

Remarks Date: 08/31/06

Minimum standards and enforcement provisions for well control equipment. 3M System: - Safety valve and subs to fit all drill string connections in use. Corrective Action: A safety valve shall be located on the rig floor in the open position ready for use. The safety valve on the floor was an Inside BOP in the closed position.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: HO ID: HO11063  
Unique INC #: KAH-013-06 Well Name:  
Well #: ID Date: 02/24/06  
Operator: ENDEAVOR ENERGY RESOURCES LP Effective Date: 03/03/06  
Case #: NMLC065525 FAC ID: A Abatement Date: 03/31/06  
Form: I FAC NAME: ELLIOTT FIELDS Corrected Date: 03/07/06  
Assessment: \$0 Inspector: HASTON Followup Date: 03/10/06  
Gravity: 3 Extend Date:  
Authority Ref: OOGO #6.III.D.2.e  
  
Remarks Date: 02/24/06  
WIND DIRECTION INDICATOR AT BATTERY IS LAYING ON THE GROUND (SEE PICTURE). - INSTALL WIND DIRECTION INDICATOR AT THIS BATTERY.

Office: HO ID: HO11327  
Unique INC #: KAH-L62-06 Well Name: NEDU  
Well #: 242 ID Date: 06/12/06  
Operator: APACHE CORPORATION Effective Date: 06/19/06  
Case #: NMNM2512 FAC ID: Abatement Date: 07/19/06  
Form: I FAC NAME: Corrected Date: 06/30/06  
Assessment: \$0 Inspector: HASTON Followup Date: 07/25/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(b)  
  
Remarks Date: 06/12/06  
WELL IDENTIFICATION SIGN DOES NOT CONTAIN THE FEDERAL LEASE SERIAL NUMBER "NM2512" AND HAS FOOTAGE INFORMATION DIFFERENT FROM FOOTAGES ON APPLICATION FOR PERMIT TO DRILL.. -- CORRECT INFORMATION ON WELL IDENTIFICATION TO SHOW CORRECT FEDERAL LEASE SERIAL NUMBER "NM2512" AND CORRECT THE FOOTAGE ON SIGN TO REFLECT WHAT IS ON THE APD OR SUBMIT A SUNDRY NOTICE SHOWING THAT THE FOOTAGE ON THE WELL SIGN IS CORRECT.

Office: HO ID: HO11001  
Unique INC #: KAH-003-06 Well Name:  
Well #: ID Date: 01/30/06  
Operator: APACHE CORPORATION Effective Date: 02/07/06  
Case #: NMNM90161 FAC ID: A Abatement Date: 03/07/06  
Form: I FAC NAME: HAWK B-1 Corrected Date: 03/07/06  
Assessment: \$0 Inspector: HASTON Followup Date: 03/07/06  
Gravity: 3 Extend Date:  
Authority Ref: OOGO #6.III.D.2.e  
  
Remarks Date: 01/30/06  
WIND DIRECTION INDICATOR AT BATTERY NEEDS TO BE REPLACED. -- REPLACE WIND DIRECTION INDICATOR.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: JA ID: JA1965  
Unique INC #: CRB-06-005 Well Name: USA ID Date: 12/19/05  
Well #: 20 Effective Date: 12/19/06  
Operator: SAMSON CONTOUR ENERGY Abatement Date: 12/20/06  
Case #: LABLMA34425 FAC ID: Corrected Date: 12/23/05  
Form: I FAC NAME: Followup Date: 01/01/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date: 12/23/05  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii  
  
Remarks Date: 12/19/05

RECORDS REFLECT THAT THE OPERATOR FAILED TO FUNCTION THE PIPE AND BLIND RAMS AFTER THE BIT TRIP MADE ON 12-11-2005.  
OPERATOR IS ORDERED TO FURNISH A LETTER OF EXPLANATION CONCERNING THIS VIOLATION AND ANY ACTIONS TO BE TAKEN TO  
PREVENT ITS RE-OCCURRENCE.

Office: JA ID: JA1967  
Unique INC #: CRB-06-007 Well Name: USA ID Date: 12/19/05  
Well #: 20 Effective Date: 12/19/06  
Operator: SAMSON CONTOUR ENERGY Abatement Date: 12/20/06  
Case #: LABLMA34425 FAC ID: Corrected Date: 12/23/05  
Form: I FAC NAME: Followup Date: 01/01/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date: 12/23/05  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.vii  
  
Remarks Date: 12/19/05

OPERATOR FAILED TO FUNCTION THE ANNULAR PREVENTER AS REQUIRED DURING THE WEEK STARTING ON 12-2-2005 THRU 12-9-2005.  
SINCE THIS VIOLATION HAS BEEN CORRECTED BY THE TESTING OF THE BOP ON 12-13-2005, OPERATOR IS TO FURNISH A LETTER OF  
EXPLANATION CONCERNING THIS VIOLATION.

Office: JA ID: JA1966  
Unique INC #: CRB-06-006 Well Name: USA ID Date: 12/19/05  
Well #: 20 Effective Date: 12/19/06  
Operator: SAMSON CONTOUR ENERGY Abatement Date: 12/20/06  
Case #: LABLMA34425 FAC ID: Corrected Date: 12/23/05  
Form: I FAC NAME: Followup Date: 01/01/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii  
  
Remarks Date: 12/19/05

RECORDS REFLECT THAT THE OPERATOR FAILED TO FUNCTION THE PIPE AND BLIND RAMS AFTER THE BIT TRIP MADE ON 12-10-2005.  
OPERATOR IS ORDERED TO FURNISH A LETTER OF EXPLANATION CONCERNING THIS VIOLATION AND ANY ACTIONS TO BE TAKEN TO  
PREVENT ITS RE-OCCURRENCE.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: JA		ID: JA1968
Unique INC #: CRB-06-008	Well Name: USA	
	Well #: 20	ID Date: 12/19/05
Operator: SAMSON CONTOUR ENERGY		Effective Date: 12/19/06
Case #: LABLMA34425	FAC ID:	Abatement Date: 12/20/06
Form: I	FAC NAME:	Corrected Date: 12/23/05
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 01/01/06
Gravity: 3		Extend Date:
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1		

Remarks Date: 12/19/05

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 12-17-2005 AS REQUIRED. OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON FOR THE VIOLATION.

Office: JA		ID: JA1982
Unique INC #: CRB-06-28	Well Name: USA	
	Well #: 22	ID Date: 04/13/06
Operator: SAMSON CONTOUR ENERGY		Effective Date: 04/13/06
Case #: LABLMA34425	FAC ID:	Abatement Date: 04/14/06
Form: I	FAC NAME:	Corrected Date: 04/18/06
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 04/22/06
Gravity: 3		Extend Date: 04/18/06
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d		

Remarks Date: 04/13/06

ACCUMULATOR PRECHARGE WAS FOUND TO BE BELOW THE REQUIRED PRESSURE. PRECHARGE PRESSURE WAS RECORDED UPON INSPECTION TO BE 550 PSI WHICH WAS BELOW THE REQUIRED 900 PSI MINIMUM. OPERATOR IS ORDERED TO CORRECT THIS PRECHARGE PRESSURE WITH 24 HOURS AND BRING IT INTO COMPLIANCE WITH THE ORDER.

Office: JA		ID: JA1970
Unique INC #: CRB-06-021	Well Name: USA	
	Well #: 63-ALT	ID Date: 04/05/06
Operator: CHESAPEAKE OPERATING INC		Effective Date: 04/10/06
Case #: LABLMA54492	FAC ID:	Abatement Date: 04/14/06
Form: I	FAC NAME:	Corrected Date: 04/14/06
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 04/14/06
Gravity: 3		Extend Date:
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii		

Remarks Date: 04/05/06

PIPE AND BLIND RAMS WERE NOT FUNCTIONED AFTER BIT TRIP ON 3-20-06 (NIGHT TOUR-DANIEL HATCHER) AS REQUIRED. OPERATOR IS TO PERFORM THE NECESSARY FUNCTION AND/OR PROVIDE A LETTER DETAILING THE REASON FOR THE VIOLATION AND THE STEPS TO BE TAKEN IN THE FUTURE TO PREVENT SIMILAR VIOLATIONS.

Safety and Drilling Related Violations (INC)s Issued During FY 2006  
As of March 3, 2011

Office: JA ID: JA1973  
Unique INC #: CRB-06-024 Well Name: USA ID Date: 04/05/06  
Well #: 63-ALT Effective Date: 04/10/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 04/14/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 04/14/06  
Form: I FAC NAME: Followup Date: 04/14/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1  
  
Remarks Date: 04/05/06

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 03-25-2006 (DAY TOUR CHAD PEROT) AS REQUIRED.  
OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON  
FOR THE VIOLATION.

Office: JA ID: JA1958  
Unique INC #: CRB-06-009 Well Name: USA ID Date: 12/19/05  
Well #: 48-ALT Effective Date: 12/19/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 12/20/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 12/20/05  
Form: I FAC NAME: Followup Date: 12/23/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii  
  
Remarks Date: 12/19/05

OPERATOR FAILED TO FUNCTION THE PIPE AND BLIND RAMS AFTER THE BIT TRIP ON 12-16-2005 AND RECORD SAME IN THE IADC BOOK.  
OPERATOR IS ORDERED TO PERFORM THIS FUNCTION AS SOON AS REASONABLY POSSIBLE AND TO FURNISH A LETTER OF  
EXPLANATION CONCERNING THIS VIOLATION AND THE ACTIONS TAKEN TO PREVENT ITS RE-OCCURRENCE.

Office: JA ID: JA1979  
Unique INC #: CRB-06-16D Well Name: USA ID Date: 03/24/06  
Well #: 52-ALT Effective Date: 03/24/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 03/28/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 03/28/06  
Form: I FAC NAME: Followup Date: 03/28/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1  
  
Remarks Date: 03/24/06

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 03-17-2006 AS REQUIRED (DAY TOUR-AL RAY BARRETT).  
OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON  
FOR THE VIOLATION.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: JA ID: JA1980  
Unique INC #: CRB-06-16E Well Name: USA ID Date: 03/24/06  
Well #: 52-ALT Effective Date: 03/24/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 03/28/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 03/28/06  
Form: I FAC NAME: Followup Date: 03/28/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1  
  
Remarks Date: 03/24/06

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 03-18-2006 AS REQUIRED (DAY TOUR-AL RAY BARRETT).  
OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON  
FOR THE VIOLATION.

Office: JA ID: JA1969  
Unique INC #: CRB-06-16A Well Name: USA ID Date: 03/13/06  
Well #: 52-ALT Effective Date: 03/13/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 03/14/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 03/09/06  
Form: I FAC NAME: Followup Date: 03/09/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.B.1.i  
  
Remarks Date: 03/13/06

OPERATOR FAILED TO PERFORM MUD WEIGHT EQUIVALENCY TEST UPON DRILLING OUT BELOW THE SURFACE CASING SHOE..  
OPERATOR IS ORDERED TO PERFORM THIS TEST AS REQUIRED IMMEDIATELY.

Office: JA ID: JA1977  
Unique INC #: CRB-06-16B Well Name: USA ID Date: 03/13/06  
Well #: 52-ALT Effective Date: 03/13/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 03/14/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 03/14/06  
Form: I FAC NAME: Followup Date: 03/14/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii  
  
Remarks Date: 03/13/06

PIPE AND BLIND RAMS WERE NOT FUNCTIONED AFTER BIT TRIP AS REQUIRED (DAY TOUR JEFF CARR). OPERATOR IS TO PERFORM THE  
NECESSARY FUNCTION AND/OR PROVIDE A LETTER DETAILING THE REASON FOR THE VIOLATION AND THE STEPS TO BE TAKEN IN THE  
FUTURE TO PREVENT SIMILAR VIOLATIONS.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: JA		ID: JA1960
Unique INC #: CRB-06-016	Well Name: USA	ID Date: 03/07/06
	Well #: 52-ALT	Effective Date: 03/07/06
Operator: CHESAPEAKE OPERATING INC		Abatement Date: 03/08/06
Case #: LABLMA54492	FAC ID:	Corrected Date: 03/08/06
Form: I	FAC NAME:	Followup Date: 03/09/06
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 1		
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.a.vi		

Remarks Date: 03/07/06

DURING TESTING OPERATIONS, THE ANNULAR PREVENTER WAS FOUND TO BE DEFECTIVE IN ITS ABILITY TO HOLD THE REQUIRED PRESSURE TEST. OPERATOR IS ORDERED TO REPAIR THIS EQUIPMENT IMMEDIATELY AND RE-TEST SAME PRIOR TO THE DRILLING OUT OF THE SURFACE CASING SHOE.

Office: JA		ID: JA1971
Unique INC #: CRB-06-022	Well Name: USA	ID Date: 04/05/06
	Well #: 63-ALT	Effective Date: 04/10/06
Operator: CHESAPEAKE OPERATING INC		Abatement Date: 04/14/06
Case #: LABLMA54492	FAC ID:	Corrected Date: 04/14/06
Form: I	FAC NAME:	Followup Date: 04/14/06
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii		

Remarks Date: 04/05/06

PIPE AND BLIND RAMS WERE NOT FUNCTIONED AFTER BIT TRIP ON 3-27-06 (NIGHT TOUR-ALVIN TAYLOR) AS REQUIRED. OPERATOR IS TO PERFORM THE NECESSARY FUNCTION AND/OR PROVIDE A LETTER DETAILING THE REASON FOR THE VIOLATION AND THE STEPS TO BE TAKEN IN THE FUTURE TO PREVENT SIMILAR VIOLATIONS.

Office: JA		ID: JA1957
Unique INC #: CRB-06-12B	Well Name: USA	ID Date: 01/02/06
	Well #: 50-ALT	Effective Date: 01/02/06
Operator: CHESAPEAKE OPERATING INC		Abatement Date: 01/03/06
Case #: LABLMA54492	FAC ID:	Corrected Date: 01/02/06
Form: I	FAC NAME:	Followup Date: 01/03/06
Assessment: \$0	Inspector: CHARLES R BOYD	Extend Date:
Gravity: 3		
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d		

Remarks Date: 01/01/06

PRECHARGE PRESSURE ON ACCUMULATOR WAS FOUND TO BE 725 PSI WHICH IS BELOW THE REQUIRED PRESSURE RANGE OF 900-1100 PSI. OPERATOR IS THEREFORE ORDERED TO REPAIR THE ACCUMULATOR TO BRING THE PRECHARGE PRESSURE TO WITHIN THE REQUIRED PRESSURE RANGE AS REQUIRED BY THE ORDER.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: JA ID: JA1978  
Unique INC #: CRB-06-16C Well Name: USA ID Date: 03/24/06  
Well #: 52-ALT Effective Date: 03/24/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 03/28/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 03/28/06  
Form: I FAC NAME: Followup Date: 03/28/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1  
  
Remarks Date: 03/24/06

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 03-16-2006 AS REQUIRED (DAY TOUR-AL RAY BARRETT).  
OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON  
FOR THE VIOLATION.

Office: JA ID: JA1975  
Unique INC #: CRB-06-026 Well Name: USA ID Date: 04/05/06  
Well #: 63-ALT Effective Date: 04/10/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 04/14/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 04/14/06  
Form: I FAC NAME: Followup Date: 04/14/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1  
  
Remarks Date: 04/05/06

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 03-27-2006 (DAY TOUR CHAD PEROT) AS REQUIRED.  
OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON  
FOR THE VIOLATION.

Office: JA ID: JA1972  
Unique INC #: CRB-06-023 Well Name: USA ID Date: 04/05/06  
Well #: 63-ALT Effective Date: 04/10/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 04/14/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 04/14/06  
Form: I FAC NAME: Followup Date: 04/14/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1  
  
Remarks Date: 04/05/06

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 03-24-2006 (DAY TOUR CHAD PEROT) AS REQUIRED.  
OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON  
FOR THE VIOLATION.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: JA ID: JA1976  
Unique INC #: CRB-06-027 Well Name: USA ID Date: 04/05/06  
Well #: 63-ALT Effective Date: 04/10/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 04/14/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 04/14/06  
Form: I FAC NAME: Followup Date: 04/14/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.C.1  
  
Remarks Date: 04/05/06

OPERATOR FAILED TO RECORD THE SLOW PUMP SPEEDS IN THE IADC BOOK ON 03-28-2006 (DAY TOUR CHAD PEROT) AS REQUIRED.  
OPERATOR IS ORDERED TO RECORD INFORMATION, IF AVAILABLE AND SEND A LETTER OF EXPLANATION CONCERNING THE REASON  
FOR THE VIOLATION.

Office: JA ID: JA1959  
Unique INC #: CRB-06-12A Well Name: USA ID Date: 12/22/05  
Well #: 48-ALT Effective Date: 12/22/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 12/23/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 12/23/05  
Form: I FAC NAME: Followup Date: 12/23/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.viii  
  
Remarks Date: 12/22/05

OPERATOR FAILED TO FUNCTION THE PIPE AND BLIND RAMS AFTER THE BIT TRIP ON 12-19-2005 AND RECORD SAME IN THE IADC BOOK.  
OPERATOR IS ORDERED TO PERFORM THIS FUNCTION AS SOON AS REASONABLY POSSIBLE AND TO FURNISH A LETTER OF  
EXPLANATION CONCERNING THIS VIOLATION AND THE ACTIONS TAKEN TO PREVENT ITS RE-OCCURRENCE.

Office: JA ID: JA1995  
Unique INC #: CRB-06-40A Well Name: USA ID Date: 09/06/06  
Well #: 55-ALT Effective Date: 09/06/06  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 09/06/06  
Case #: LABLMA54492 FAC ID: Corrected Date: 09/06/06  
Form: I FAC NAME: Followup Date: 09/06/06  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.e  
  
Remarks Date: 09/06/06

POWER, BOTH AIR AND ELECTRIC, FOR THE CLOSING UNIT PUMPS WAS FOUND TO BE TURNED OFF. POWER FOR THE CLOSING UNIT  
MUST BE ON AT ALL TIMES.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: KM		ID: KM669
Unique INC #: 06INC013	Well Name: COW HOLLOW	
	Well #: 30-24	ID Date: 04/10/06
Operator: CABOT OIL & GAS CORPORATION		Effective Date: 04/11/06
Case #: WYW24154	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 01/10/06
Assessment: \$0	Inspector: BREWER	Followup Date: 04/10/06
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3162.5-1(a)		

Remarks Date: 04/10/06

Operator shall comply with approved drilling plan: Mountain Plover wildlife stipulations begin April 10.

Office: KM		ID: KM668
Unique INC #: 06INC012	Well Name: COW HOLLOW	
	Well #: 30-24	ID Date: 04/07/06
Operator: CABOT OIL & GAS CORPORATION		Effective Date: 04/11/06
Case #: WYW24154	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 04/07/06
Assessment: \$0	Inspector: BREWER	Followup Date: 04/11/06
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.A.2.d.		

Remarks Date: 04/07/06

The accumulator pre-charge pressure needs to be within maximum/minimum limit psi. specified: Test of BOPE completed on 4/4/06, needed to service bottles on 4/5, not done until 4/7.

Office: ME		ID: ME2130
Unique INC #: 06BH08MEFO	Well Name: PICEANCE CREEK UNIT	
	Well #: T35X-2G3	ID Date: 08/17/06
Operator: EXXON MOBIL CORP		Effective Date: 09/06/06
Case #: COC047666A	FAC ID:	Abatement Date: 09/06/06
Form: I	FAC NAME:	Corrected Date: 09/29/06
Assessment: \$0	Inspector: HORTON	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: cfr 3163.1 (a)		

Remarks Date: 08/17/06

Failed to follow approved drilling plan on surface casing hole size, APD approved hole size is 14 3/4". The well bore has approximatley 300 ft 17 1/2 hole, which this information had to be obtained from the floor hands on the rig. The Halliburton Engineers on location were un aware of this as well as any company representative.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: ME ID: ME2127  
Unique INC #: 06BH05MEFO Well Name: HELLS HOLE  
Well #: 19-1 ID Date: 08/28/06  
Operator: ROBERT L BAYLESS PRODUCER LLC Effective Date: 09/06/06  
Case #: COC66380 FAC ID: Abatement Date: 09/06/06  
Form: I FAC NAME: Corrected Date: 09/19/06  
Assessment: \$0 Inspector: HORTON Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 3163.1 (a)

Remarks Date: 08/28/06

Failed to comply with the conditions of approval on 24 hr notice prior to spud.

Office: ME ID: ME2128  
Unique INC #: 06BH06MEFO Well Name: HELLS HOLE  
Well #: 19-1 ID Date: 08/28/06  
Operator: ROBERT L BAYLESS PRODUCER LLC Effective Date: 09/06/06  
Case #: COC66380 FAC ID: Abatement Date: 09/06/06  
Form: I FAC NAME: Corrected Date: 09/19/06  
Assessment: \$250 Inspector: HORTON Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 3163.1 (a)

Remarks Date: 08/28/06

Failed to comply with the conditions of approval on 24 hr notice prior running surface casing.

Office: ME ID: ME2129  
Unique INC #: 06BH07MEFO Well Name: HELLS HOLE  
Well #: 19-1 ID Date: 08/28/06  
Operator: ROBERT L BAYLESS PRODUCER LLC Effective Date: 09/06/06  
Case #: COC66380 FAC ID: Abatement Date: 09/06/06  
Form: I FAC NAME: Corrected Date: 09/19/06  
Assessment: \$250 Inspector: HORTON Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: cfr 3163.1 (a)

Remarks Date: 08/28/06

Failed to comply with the conditions of approval on 24 hr notice prior to cementing surface pipe.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: ME ID: ME2121  
Unique INC #: 06BK08MEFO Well Name: FEDERAL TRW ID Date: 08/17/06  
Well #: 23-3-598 Effective Date: 08/28/06  
Operator: WILLIAMS PRODUCTION COMPANY Abatement Date: 08/28/06  
Case #: COC58688 FAC ID: Corrected Date: 08/28/06  
Form: I FAC NAME: Followup Date: 08/28/06  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 08/17/06

Failure to comply with the approved APD, conditions of approval, to notify the White River Field Office 24 hours prior to constructing the pad. Williams was instructed to notify the PET by telephone, with the numbers listed in the approved APD. Any further failures to notify will result in assessments.

Office: ME ID: ME2126  
Unique INC #: 06BK13MEFO Well Name: FEDERAL TRW ID Date: 08/17/06  
Well #: 23-3-598 Effective Date: 08/28/06  
Operator: WILLIAMS PRODUCTION COMPANY Abatement Date: 08/28/06  
Case #: COC58688 FAC ID: Corrected Date: 08/28/06  
Form: I FAC NAME: Followup Date: 08/28/06  
Assessment: \$1,000 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 08/17/06

Failure to comply with the approved APD, conditions of approval, to notify the White River Field Office 24 hours prior to pressure testing the surface casing shoe . Williams was instructed to notify the PET by telephone, with the numbers listed in the approved APD. Any further failures to notify will result in assessments.

Office: ME ID: ME2125  
Unique INC #: 06BK12MEFO Well Name: FEDERAL TRW ID Date: 08/17/06  
Well #: 23-3-598 Effective Date: 08/28/06  
Operator: WILLIAMS PRODUCTION COMPANY Abatement Date: 08/28/06  
Case #: COC58688 FAC ID: Corrected Date: 08/28/06  
Form: I FAC NAME: Followup Date: 08/28/06  
Assessment: \$1,000 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 08/17/06

Failure to comply with the approved APD, conditions of approval, to notify the White River Field Office 24 hours prior to testing the BOPs. . Williams was instructed to notify the PET by telephone, with the numbers listed in the approved APD. Any further failures to notify will result in assessments.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: ME ID: ME2124  
Unique INC #: 06BK11MEFO Well Name: FEDERAL TRW ID Date: 08/17/06  
Well #: 23-3-598 Effective Date: 08/28/06  
Operator: WILLIAMS PRODUCTION COMPANY Abatement Date: 08/28/06  
Case #: COC58688 FAC ID: Corrected Date: 08/28/06  
Form: I FAC NAME: Followup Date: 08/28/06  
Assessment: \$1,000 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 08/17/06

Failure to comply with the approved APD, conditions of approval, to notify the White River Field Office 24 hours prior to cementing the surface casing. .Williams was instructed to notify the PET by telephone, with the numbers listed in the approved APD. Any further failures to notify will result in assessments.

Office: ME ID: ME2122  
Unique INC #: 06BK09MEFO Well Name: FEDERAL TRW ID Date: 08/17/06  
Well #: 23-3-598 Effective Date: 08/28/06  
Operator: WILLIAMS PRODUCTION COMPANY Abatement Date: 08/28/06  
Case #: COC58688 FAC ID: Corrected Date: 08/28/06  
Form: I FAC NAME: Followup Date: 08/28/06  
Assessment: \$1,000 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 08/17/06

Failure to comply with the approved APD, conditions of approval, to notify the White River Field Office 24 hours prior to spudding the well.Williams was instructed to notify the PET by telephone, with the numbers listed in the approved APD. Any further failures to notify will result in assessments.

Office: ME ID: ME2123  
Unique INC #: 06BK10MEFO Well Name: FEDERAL TRW ID Date: 08/17/06  
Well #: 23-3-598 Effective Date: 08/28/06  
Operator: WILLIAMS PRODUCTION COMPANY Abatement Date: 08/28/06  
Case #: COC58688 FAC ID: Corrected Date: 08/28/06  
Form: I FAC NAME: Followup Date: 08/28/06  
Assessment: \$1,000 Inspector: KRAFT Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 08/17/06

Failure to comply with the approved APD, conditions of approval, to notify the White River Field Office 24 hours prior to running the surface casing. .Williams was instructed to notify the PET by telephone, with the numbers listed in the approved APD. Any further failures to notify will result in assessments.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: ME ID: ME2103  
Unique INC #: 06BK07MEFO Well Name: FEDERAL  
Well #: 399-1-1 ID Date: 04/19/06  
Operator: RIATA ENERGY INCORPORATED Effective Date: 04/27/06  
Case #: COC60758 FAC ID: Abatement Date: 04/27/06  
Form: I FAC NAME: Corrected Date: 04/27/06  
Assessment: \$500 Inspector: KRAFT Followup Date: 04/27/06  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 04/19/06

Failure to comply with the approved APD, to notify the Petroleum Engineering technician 24 hours prior to cementing the surface casing.

Office: ME ID: ME2102  
Unique INC #: 06BK06MEFO Well Name: FEDERAL  
Well #: 399-1-1 ID Date: 04/19/06  
Operator: RIATA ENERGY INCORPORATED Effective Date: 04/27/06  
Case #: COC60758 FAC ID: Abatement Date: 04/27/06  
Form: I FAC NAME: Corrected Date: 04/27/06  
Assessment: \$0 Inspector: KRAFT Followup Date: 04/27/06  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 04/27/06

Failure to comply with the approved APD to notify the Petroleum Engineering technician 24 hours prior to running surface casing. The next failure to notify will result in assessments.

Office: ME ID: ME2108  
Unique INC #: 06BK20MEFO Well Name: FIGURE FOUR UNIT  
Well #: 8003D A16 498 ID Date: 07/18/06  
Operator: ENCANA OIL & GAS (USA) INC Effective Date: 07/21/06  
Case #: COC66492X FAC ID: Abatement Date: 07/28/06  
Form: I FAC NAME: Corrected Date: 07/28/06  
Assessment: \$0 Inspector: KRAFT Followup Date: 07/28/06  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 07/18/06

Failure to comply with the approved APD. The conditions of approval states that if cement does not circulate to surface while cementing the surface casing a log, acceptable to the WRFO, will be run to determine the top of cement. The log was not run and the hole was topped off.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: ML ID: ML3543  
Unique INC #: CD05-15-3 Well Name: CEDAR HILLS ID Date: 11/04/05  
Well #: 21-10NH Effective Date: 11/04/05  
Operator: CONTINENTAL RESOURCES INC Abatement Date: 11/05/05  
Case #: MTM89699X FAC ID: Corrected Date: 11/04/05  
Form: I FAC NAME: Followup Date: 11/05/05  
Assessment: \$0 Inspector: DEVAULT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 11/04/05

Failed to comply with COA (E) in APD. No H2S equipment as required.

Office: ML ID: iML3425  
Unique INC #: IH06-11 Well Name: REID ID Date: 01/24/06  
Well #: 10-1 Effective Date: 01/27/06  
Operator: BALLARD PETROLEUM HOLDINGS LLC Abatement Date: 02/23/06  
Case #: 14200256CA18 FAC ID: Corrected Date: 02/01/06  
Form: I FAC NAME: Followup Date: 02/01/06  
Assessment: \$0 Inspector: IRENE HARRIS Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3164.1; OO #6,III.D.2.e.

Remarks Date: 01/24/06

Install a wind direction indicactor at this facility.

Office: ML ID: iML3423  
Unique INC #: IH06-10 Well Name: ID Date: 01/25/06  
Well #: Effective Date: 01/27/06  
Operator: BALLARD PETROLEUM HOLDINGS LLC Abatement Date: 02/23/06  
Case #: 1420256595 FAC ID: A Corrected Date: 02/01/06  
Form: I FAC NAME: #1 CUT HAIR Followup Date: 02/01/06  
Assessment: \$0 Inspector: IRENE HARRIS Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3164.1; OO #6, III.D.2.e.

Remarks Date: 01/25/06

Install a wind direction indicator at this facility.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: ML		ID: ML3431
Unique INC #: IH06-34-3	Well Name:	
	Well #:	
Operator: SLAWSON EXPLORATION CO INC		
Case #: MT020P3085C221	FAC ID: A	ID Date: 08/02/06
Form: I	FAC NAME: 34-22 WILSON	Effective Date: 08/09/06
Assessment: \$0	Inspector: IRENE HARRIS	Abatement Date: 09/04/06
Gravity: 3		Corrected Date: 08/22/06
Authority Ref: 43 CFR 3164.1	Onshore Order #4,III.C.1.c.	Followup Date: 08/25/06
		Extend Date:

Remarks Date: 08/02/06

Install a wind direction indicator at this facility. Informed the relief pumper, Darryl, on 8-2-06 @ 1150 hrs.

Office: PD		ID: PD1999
Unique INC #: 0602RC	Well Name: CABRITO	
	Well #: 67-25	
Operator: BP AMERICA PRODUCTION COMPANY		
Case #: WYW138889L	FAC ID:	ID Date: 02/03/06
Form: I	FAC NAME:	Effective Date:
Assessment: \$0	Inspector: CANTERBURY	Abatement Date: 04/01/06
Gravity: 3		Corrected Date: 02/13/06
Authority Ref: 43CFR3162.1(a)		Followup Date: 02/24/06
		Extend Date:

Remarks Date: 02/03/06

The flare pit was constructed in an location not approved in the Application for Permit to Drill.

Office: PD		ID: PD2092
Unique INC #: 25DF092706	Well Name: BCU	
	Well #: 200	
Operator: CHEVRON USA INC		
Case #: WYW109425J	FAC ID:	ID Date: 09/26/06
Form: I	FAC NAME:	Effective Date: 10/04/06
Assessment: \$0	Inspector: FALLON	Abatement Date: 10/05/06
Gravity: 3		Corrected Date: 09/27/06
Authority Ref: O.O.#2.III.A.2.xi.		Followup Date: 10/18/06
		Extend Date:

Remarks Date: 09/27/06

Found: During a detailed drilling inspection, documentation was missing on the IADC driller's log book as follows: 1. Annular preventer activated weekly and recorded in the driller's log. 2. Pipe rams activated each trip and recorded in the driller's log. 3. Blind rams activated each trip and recorded in the driller's log. 4. BOP drills conducted weekly and recorded in the driller's log. (One tour only reported with no time) Corrective action: Perform all the above described tests and/or drills and record in the driller's log book within 24hours or next trip as most appropriate..

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2095
Unique INC #: 28DF092606	Well Name: GRB	
	Well #: 265-20H	ID Date: 09/26/06
Operator: EOG RESOURCES INCORPORATED		Effective Date: 10/03/06
Case #: WYW109537B	FAC ID:	Abatement Date: 10/03/06
Form: I	FAC NAME:	Corrected Date: 09/26/06
Assessment: \$0	Inspector: FALLON	Followup Date: 10/10/06
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 III. A.2.xi.		

Remarks Date: 09/26/06

Found: During a detailed drilling inspection of True Rig #31 it was discovered documentation missing in the IADC driller's log book as follows: 1. BOP drills conducted weekly and recorded in the driller's log. (One tour of three reported ) 2. Pressure tests of the surface casing recorded in the driller's log. Corrective action: perform all the above described tests and/or drills and record in the driller's log book.

Office: PD		ID: PD2094
Unique INC #: 27DF092606	Well Name: GRB	
	Well #: 265-20H	ID Date: 09/26/06
Operator: EOG RESOURCES INCORPORATED		Effective Date: 10/03/06
Case #: WYW109537B	FAC ID:	Abatement Date: 10/03/06
Form: I	FAC NAME:	Corrected Date: 09/26/06
Assessment: \$0	Inspector: FALLON	Followup Date: 09/27/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2 III.A.1.		

Remarks Date: 09/26/06

Found: During a detailed rig inspection of True Rig #31, it was discovered the accumulator had one bank of nitrogen bottles isolated by a closed valve. Also closed was the manually operated suction shut-off valve to the air pumps. Corrective action: Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Maintain the above valves in the open position as necessary when drilling, unless servicing equipment or in transit.

Office: PD		ID: PD2097
Unique INC #: 30DF092609	Well Name: GRB	
	Well #: 265-20H	ID Date: 09/26/06
Operator: EOG RESOURCES INCORPORATED		Effective Date: 10/03/06
Case #: WYW109537B	FAC ID:	Abatement Date: 10/03/06
Form: I	FAC NAME:	Corrected Date: 09/26/06
Assessment: \$0	Inspector: FALLON	Followup Date: 10/10/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2 III.C.3.		

Remarks Date: 09/26/06

Found: During a detailed rig inspection of True Rig #31, it was discovered that while tripping out of the hole the alarms for the pit volume totalizers were off. According to Onshore Order #2, "When abnormal pressures are anticipated, electronic/mechanical mud monitoring equipment shall be required, which shall include as a minimum; pit volume totalizer (PVT); stroke counter; and flow sensor." Corrective action: When anticipating abnormal pressures all alarms shall be on and functional.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2005
Unique INC #: 14DF022206	Well Name: STUD HORSE BUTTE	
	Well #: 14B-23D	ID Date: 02/22/06
Operator: ULTRA RESOURCES INC		Effective Date: 02/27/06
Case #: WYW118155	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 03/01/06
Assessment: \$0	Inspector: FALLO	Followup Date: 03/03/06
Gravity: 1		Extend Date:
Authority Ref: O.O.#2.III.B.1.f.		

Remarks Date: 02/22/06

Found: During a Casing and cement inspection it was discovered that centralizers were placed inappropriately on the surface string. Centralizers were placed on the bottom (shoe joint), the second joint up(collars), and the fifth joint up the surface string. According to Onshore Orders #2.III.B.1.f, "Surface casing shall have centralizers on the bottom 3 joints of the casing (a minimum of 1 centralizer per joint, starting with the shoe joint)". Corrective Action: Follow all required placements of centralizers on subsequent wells.

Office: PD		ID: PD2068
Unique INC #: 15DF050906	Well Name: JONAH FEDERAL	
	Well #: 42-5	ID Date: 05/09/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 05/16/06
Case #: WYW125943	FAC ID:	Abatement Date: 05/16/06
Form: I	FAC NAME:	Corrected Date: 05/16/06
Assessment: \$0	Inspector: FALLO	Followup Date: 05/22/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.i.xi.		

Remarks Date: 05/09/06

Found: During a detailed rig inspection of Ensign Rig #68, it was discovered that BOP drills were not accurately reported on the IADC driller's log book. One crew was reported as 90 seconds, the other crew did not record performing a drill. Corrective Action: As per Onshore Order #2, "A BOPE pit level drill shall be conducted weekly for each drilling crew.", and furthermore, "All of the above described tests and/or drills shall be recorded in the drilling log."

Office: PD		ID: PD2069
Unique INC #: 16DF050906	Well Name: JONAH FEDERAL	
	Well #: 42-5	ID Date: 05/09/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 05/16/06
Case #: WYW125943	FAC ID:	Abatement Date: 05/16/06
Form: I	FAC NAME:	Corrected Date: 05/09/06
Assessment: \$0	Inspector: FALLO	Followup Date: 05/11/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2.III.C.7.		

Remarks Date: 05/09/06

Found: During a detailed rig inspection it was discovered the flare lines had no effective method for ignition. Corrective Action: As per Onshore Order #2, "The flare system shall have an effective method for ignition. Where noncombustible gas is likely or expected to be vented, the system shall be provided supplemental fuel for ignition and to maintain a continuous flare."

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2001
Unique INC #: 10DF022206	Well Name: STUD HORSE BUTTE	
	Well #: 123-20V	ID Date: 02/21/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 02/24/06
Case #: WYW125948	FAC ID:	Abatement Date: 02/24/06
Form: I	FAC NAME:	Corrected Date: 02/22/06
Assessment: \$0	Inspector: FALLO	Followup Date: 02/23/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.1.		

Remarks Date: 02/21/06

Found: During a detailed rig inspection of Ensign rig #8, approximately 200' above the over-pressure zone, the remote control choke (superchoke) in the choke manifold was inoperative. According to Onshore Order # 2.III.A.1., "Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. ...The BOP and related control equipment shall be suitable for operations in those areas which are subject to sub-freezing conditions." Corrected: This incident of noncompliance was corrected within the 24 hour abatement date.

Office: PD		ID: PD2003
Unique INC #: 12DF022206	Well Name: STUD HORSE BUTTE	
	Well #: 123-20V	ID Date: 02/21/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 02/24/06
Case #: WYW125948	FAC ID:	Abatement Date: 02/24/06
Form: I	FAC NAME:	Corrected Date: 02/22/06
Assessment: \$0	Inspector: FALLO	Followup Date: 02/23/06
Gravity: 1		Extend Date:
Authority Ref: O.O. #2.III.C.7.		

Remarks Date: 02/21/06

Found: During a detailed rig inspection of Ensign #8, it was discovered the middle flare line (bleed or panic line) exiting the choke manifold was disconnected. According to Onshore Order # O.O. #2.III.C.7., "The flare line(s) discharge shall be located not less than 100 feet from the well head, having straight lines unless turns are targeted with running tees, and shall be positioned downwind of the prevailing wind direction and shall be anchored. Corrected: Correction was made immediately upon discovery and the line was anchored at the end as requested by the inspector..

Office: PD		ID: PD2002
Unique INC #: 11DF022206	Well Name: STUD HORSE BUTTE	
	Well #: 123-20V	ID Date: 02/21/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 02/24/06
Case #: WYW125948	FAC ID:	Abatement Date: 02/24/06
Form: I	FAC NAME:	Corrected Date: 02/22/06
Assessment: \$0	Inspector: FALLO	Followup Date: 02/23/06
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.2.h.vii.		

Remarks Date: 02/21/06

Found: During a detailed rig inspection of Ensign #8, approximately 200' above the over-pressure zone, it was discovered the annular presenters has not been functioned in the last week and documented in the IADC driller's log book. According to Onshore Orders # O.O.# 2.III.A.2.h.vii., " Annular presenters shall be functionally operated at least weekly." According to Onshore Orders # O.O.# 2.III.A.2.h.xi, " All the above described tests and/or drills shall be recorded in the drilling log. Corrected: The incident of noncompliance was corrected before the abatement date.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2024
Unique INC #: MG2006-04	Well Name: STUD HORSE BUTTE	
	Well #: 14A-23D, 14B-23D	ID Date: 03/03/06
Operator: ULTRA RESOURCES INC		Effective Date: 03/03/06
Case #: WYW118155	FAC ID:	Abatement Date: 04/03/06
Form: I	FAC NAME:	Corrected Date: 03/07/06
Assessment: \$0	Inspector: GAMPER	Followup Date: 03/07/06
Gravity: 3		Extend Date:
Authority Ref: 43cfr3163		

Remarks Date: 03/03/06

Well pad not constructed per approved APD layout diagram. Specifically, soil storage locations not in correct place and cuttings pit and flowback pit are switched on the pad. Ultra to submit sundry requesting the additional disturbance and to explain how/why it happened. Ultra also to look at other approved location to determine if this could happen again and how they will prevent it from happening again.

Office: PD		ID: PD2020
Unique INC #: MG2006-02	Well Name: STUD HORSE BUTTE	
	Well #: 11A-23D	ID Date: 03/01/06
Operator: ULTRA RESOURCES INC		Effective Date: 03/01/06
Case #: WYW118155	FAC ID:	Abatement Date: 03/25/06
Form: I	FAC NAME:	Corrected Date: 03/23/06
Assessment: \$0	Inspector: GAMPER	Followup Date: 03/02/06
Gravity: 3		Extend Date:
Authority Ref: 43cfr3163.1		

Remarks Date: 03/01/06

Water well was not part of the approved SUP for this location and therefore, the water well was drilled on the SHB 11A-23D location without authorization. Water from this well may not be used during drilling or completion operations for any well on this location until authorization has been obtained from the AO of the BLM. An abatement date of March 21, 2006 has been set. Ultra will also need to explain how they will achieve maximum interim reclamaiton of this location due to location of water well on the fringe of the pad. Ultra must supply WY Permit Number.

Office: PD		ID: PD2021
Unique INC #: MG2006-03	Well Name: STUD HORSE BUTTE	
	Well #: 9A-21D	ID Date: 03/01/06
Operator: ULTRA RESOURCES INC		Effective Date: 02/22/06
Case #: WYW118155	FAC ID:	Abatement Date: 03/25/06
Form: I	FAC NAME:	Corrected Date: 03/23/06
Assessment: \$0	Inspector: GAMPER	Followup Date: 03/02/06
Gravity: 3		Extend Date:
Authority Ref: 43cfr3613.1		

Remarks Date: 03/01/06

Water well is not part of approved SUP for this location and therefore, the water well was drilled on the SHB 9A-21D location without authorization. WAter from this well may not be used during drilling or completion operations for any well on this location until authorization has been obtained from the AO of the BLM. An abatement date of March 21, 2006 has been set. Ultra will also need to explain how they will achieve maximum interim reclamaiton of this location due to location of water well on the fringe of the pad. Ultra must submit WY Permit Number.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD1994
Unique INC #: BL2006-001	Well Name: STUD HORSE BUTTE	
	Well #: 6-27MM	ID Date: 01/17/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 01/25/06
Case #: WYW102899	FAC ID:	Abatement Date: 02/02/06
Form: I	FAC NAME:	Corrected Date: 01/31/06
Assessment: \$5,000	Inspector: LANNING	Followup Date: 02/07/06
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1(b)(2)		

Remarks Date: 01/17/06

Ms. Karen Olson of your office recently submitted a Request for Exception to the raptor COA on the Stud Horse Butte 6-27MM APD. The SHB 6-27MM is located on federal oil and gas lease WYW102899 in Lot 6, Section 27, T. 29 N., R. 108 W., 6th P.M. and is operated by EnCana Oil and Gas (USA) Inc. Through our review of the Application for Permit to Drill (APD) for the exception request on January 17, 2006, we discovered that the current drilling operations on the SHB 6-27MM are being conducted in violation of a COA attached the APD that was approved on June 8, 2006. Specifically, activities, as detailed below, occurred during a period when such activities were prohibited by the COA for sage grouse winter concentration habitat protection. The SHB 6-27MM, as verified by a Sundry Notice submitted by EnCana on January 5, 2006, was spudded at 7:30 A.M. on December 30, 2005. Drilling was continuing as of the date of this letter. The COA for protection of sage grouse winter concentration habitat attached to the SHB 6-27MM specifically precludes disturbance and disruptive activities during the restriction period. Specifically the COA states: " Disturbance and disruptive activities are prohibited in sage grouse winter concentration areas from November 15th to March 14th. No exception to this COA to allow the current drilling activity was requested or granted. The violation was classified as a major violation and an Incident of Noncompliance (INC) No.BL2006-001 was issued on January 25, 2006. Pursuant to 43 CFR 3163.1(b)(2), which authorizes assessment of up to \$500 per day of violation, to a maximum of \$5,000.00, we are assessing a penalty of \$5,000.00 for this violation. In addition to the assessment noted herein, EnCana Oil & Gas (USA) Inc. is required to complete a survey of the sage grouse winter concentration habitat to determine current sage grouse activity. The survey shall be conducted over a ½ mile radius of the SHB 6-27MM well pad no later than February 2, 2006. Survey results shall be submitted to the BLM Pinedale Field Office by February 9, 2006. Due to the fact that the current drilling depth is below the surface casing depth, is within 1000 feet of total drilling depth (TD), there are no additional casing points until the production casing is set at the total well depth, and there would be a potential for well bore failure below the surface casing should drilling be stopped before TD is reached and the production casing is set, EnCana Oil and Gas (USA) Inc. is hereby authorized to continue drilling the SHB 6-27MM to total depth (11,400 feet), to set production casing, and to move the rig off location. EnCana is NOT authorized to conduct any operations on the SHB 6-27MM well pad that are not specifically related to drilling the SHB 6-27MM well to total depth and setting the production casing. The SHB 6-27MM well pad also contains the SHB 44-27. Other wells have been drilled (SHB 45-27) or are approved to be drilled (SHB 44

Office: PD		ID: PD2008
Unique INC #: NS-06-3	Well Name: WARBONNET	
	Well #: 11B-10DX	ID Date: 03/01/06
Operator: SWEPI LP		Effective Date: 03/01/06
Case #: WYW015314	FAC ID:	Abatement Date: 03/20/06
Form: I	FAC NAME:	Corrected Date: 03/01/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/02/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. When an operator moves a rig onto a previously spud well, our office shall be informed of the date the rig begins turning right. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2007
Unique INC #: NS-06-2	Well Name: WARBONNET	
	Well #: 12B-10D	ID Date: 03/01/06
Operator: SWEPI LP	FAC ID:	Effective Date: 03/01/06
Case #: WYW015314	FAC NAME:	Abatement Date: 03/20/06
Form: I		Corrected Date: 03/01/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/02/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. When an operator moves a rig onto a previously spud well, our office shall be informed of the date the rig begins turning right. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD		ID: PD2013
Unique INC #: NS-06-8	Well Name: RIVERSIDE	
	Well #: 8B-2D	ID Date: 03/01/06
Operator: ULTRA RESOURCES INC	FAC ID:	Effective Date: 03/01/06
Case #: WYW06270	FAC NAME:	Abatement Date: 03/20/06
Form: I		Corrected Date: 03/08/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/08/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD		ID: PD2015
Unique INC #: NS-06-10	Well Name: MESA	
	Well #: 9A-35D	ID Date: 03/01/06
Operator: ULTRA RESOURCES INC	FAC ID:	Effective Date: 03/01/06
Case #: WYW06286	FAC NAME:	Abatement Date: 03/20/06
Form: I		Corrected Date: 03/08/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/08/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2019
Unique INC #: NS-06-14	Well Name: MESA	
	Well #: 10A-35D	ID Date: 03/01/06
Operator: ULTRA RESOURCES INC		Effective Date: 03/01/06
Case #: WYW06286	FAC ID:	Abatement Date: 03/20/06
Form: I	FAC NAME:	Corrected Date: 03/08/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/08/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD		ID: PD2011
Unique INC #: NS-06-6	Well Name: MESA	
	Well #: 8A-35D	ID Date: 03/01/06
Operator: ULTRA RESOURCES INC		Effective Date: 03/01/06
Case #: WYW06286	FAC ID:	Abatement Date: 03/20/06
Form: I	FAC NAME:	Corrected Date: 03/08/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/08/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD		ID: PD2016
Unique INC #: NS-06-11	Well Name: MESA	
	Well #: 7B-34D	ID Date: 03/01/06
Operator: ULTRA RESOURCES INC		Effective Date: 03/01/06
Case #: WYW06286	FAC ID:	Abatement Date: 03/20/06
Form: I	FAC NAME:	Corrected Date: 03/08/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/08/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2010
Unique INC #: NS-06-5	Well Name: MESA	
	Well #: 7A-35D	
Operator: ULTRA RESOURCES INC		ID Date: 03/01/06
Case #: WYW06286	FAC ID:	Effective Date: 03/01/06
Form: I	FAC NAME:	Abatement Date: 03/20/06
Assessment: \$0	Inspector: N STURDEVANT	Corrected Date: 03/08/06
Gravity: 3		Followup Date: 03/08/06
Authority Ref: 43 CFR 3162.1(a)		Extend Date:

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD		ID: PD2012
Unique INC #: NS-06-7	Well Name: STUD HORSE BUTTE	
	Well #: 7C-23D	
Operator: ULTRA RESOURCES INC		ID Date: 03/01/06
Case #: WYW118155	FAC ID:	Effective Date: 03/01/05
Form: I	FAC NAME:	Abatement Date: 03/20/06
Assessment: \$0	Inspector: N STURDEVANT	Corrected Date: 03/08/06
Gravity: 3		Followup Date: 03/08/06
Authority Ref: 43 CFR 3162.1(a)		Extend Date:

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD		ID: PD2014
Unique INC #: NS-06-9	Well Name: STUD HORSE BUTTE	
	Well #: 13D-23D	
Operator: ULTRA RESOURCES INC		ID Date: 03/01/06
Case #: WYW118155	FAC ID:	Effective Date: 03/01/06
Form: I	FAC NAME:	Abatement Date: 03/20/06
Assessment: \$0	Inspector: N STURDEVANT	Corrected Date: 03/08/06
Gravity: 3		Followup Date: 03/08/06
Authority Ref: 43 CFR 3162.1(a)		Extend Date:

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD ID: PD2017  
Unique INC #: NS-06-12 Well Name: STUD HORSE BUTTE ID Date: 03/01/06  
Well #: 13A-23D Effective Date: 03/01/06  
Operator: ULTRA RESOURCES INC Abatement Date: 03/20/06  
Case #: WYW118155 FAC ID: Corrected Date: 03/08/06  
Form: I FAC NAME: Followup Date: 03/08/06  
Assessment: \$0 Inspector: N STURDEVANT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD ID: PD2018  
Unique INC #: NS-06-13 Well Name: STUD HORSE BUTTE ID Date: 03/01/06  
Well #: 7B-23D Effective Date: 03/01/06  
Operator: ULTRA RESOURCES INC Abatement Date: 03/20/06  
Case #: WYW118155 FAC ID: Corrected Date: 03/08/06  
Form: I FAC NAME: Followup Date: 03/08/06  
Assessment: \$0 Inspector: N STURDEVANT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD ID: PD2009  
Unique INC #: NS-06-4 Well Name: STUD HORSE BUTTE ID Date: 03/01/06  
Well #: 14A-23D Effective Date: 03/01/06  
Operator: ULTRA RESOURCES INC Abatement Date: 03/20/06  
Case #: WYW118155 FAC ID: Corrected Date: 03/08/06  
Form: I FAC NAME: Followup Date: 03/08/06  
Assessment: \$0 Inspector: N STURDEVANT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 03/01/06

Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Safety and Drilling Related Violations (INC)s Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2025
Unique INC #: NS-06-17	Well Name: STUD HORSE BUTTE	
	Well #: 112-20XV	ID Date: 03/10/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 03/10/06
Case #: WYW125948	FAC ID:	Abatement Date: 03/31/06
Form: I	FAC NAME:	Corrected Date: 03/20/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/20/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/10/06

BLM notified on 3/10/06 that Ensign rig 120 moved on location 3/10/06, and was spud previously. BLM office did not receive 24 hour notice prior to spud. Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is verbal drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval with written sundry (3160-5) of action supplied to the Pinedale Field Office with in 5 days of spud.

Office: PD		ID: PD2047
Unique INC #: NS-06-18	Well Name: CORONA	
	Well #: 59-31	ID Date: 04/03/06
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 04/03/06
Case #: WYW138876E	FAC ID:	Abatement Date: 04/17/06
Form: I	FAC NAME:	Corrected Date: 04/23/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 04/23/06
Gravity: 3		Extend Date: 04/25/06
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 04/03/06

BLM notified on 4/3/06 that H&P rig 180 moved on location 4/3/06, and was spud previously. BLM office did not receive 24 hour notice prior to spud. Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is verbal drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval with written sundry (3160-5) of action supplied to the Pinedale Field Office with in 5 days of spud.

Office: PD		ID: PD2022
Unique INC #: NS-06-15	Well Name: CABRITO	
	Well #: 70-19	ID Date: 03/07/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 03/07/06
Case #: WYW138889L	FAC ID:	Abatement Date: 03/30/06
Form: I	FAC NAME:	Corrected Date: 03/21/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/21/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/07/06

BLM inspector notified on 3/7/06 that this well spud 2/21/06. BLM office did not receive 24 hour notice prior to spud. Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval with written sundry (3160-5) of action supplied to the Pinedale Field Office with in 5 days of spud. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD		ID: PD2023
Unique INC #: NS-06-16	Well Name: CABRITO	
	Well #: 76-19	ID Date: 03/07/06
Operator: ENCANA OIL & GAS USA INC		Effective Date: 03/07/06
Case #: WYW138889L	FAC ID:	Abatement Date: 03/30/06
Form: I	FAC NAME:	Corrected Date: 03/21/06
Assessment: \$0	Inspector: N STURDEVANT	Followup Date: 03/21/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/07/06

BLM inspector notified on 3/7/06 that this well spud February 20, 2006. BLM office did not receive 24 hour notice prior to spud. Failure to notify Pinedale Field Office 24 hours in advance of well spud as required by the Conditions of Approval in the Application for Permit to Drill. BLM considers a spud to be the setting of conductor pipe for the well. Please note this does not require that a conventional drilling rig be located or moved on location. BLM considers this lack of notification a violation of the Application for Permit to Drill. An additional requirement, due to conductor pipe spuds being performed significantly ahead of moving drilling rigs onto wells, is drilling rig MOVE ON notification. Corrective action: Perform the 24 hour notice of spud as required by the Application of Permit to Drill Conditions of Approval with written sundry (3160-5) of action to be filed with Pinedale Field Office within 5 days. In addition please submit sundry notice (3160-5) of all spuds not previously reported by the abatement date stated above.

Office: PD		ID: PD2050
Unique INC #: LAW06053	Well Name: WARBONNET	
	Well #: 8B-10D	ID Date: 04/03/06
Operator: ULTRA RESOURCES INC		Effective Date: 04/04/06
Case #: WYW015314	FAC ID:	Abatement Date: 04/05/06
Form: I	FAC NAME:	Corrected Date: 04/04/06
Assessment: \$0	Inspector: WALDO	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O.2 III.A.2.a.v.		

Remarks Date: 04/03/06

Problem No functioning pressure gauge on choke manifold. Corrective action: Install pressure gauge on choke manifold according to onshore orders where all connections subjected to pressure shall be flanged, welded or clamped. Pressure gauges in the well control system shall be a type designed for drilling fluid service (O.O.2 III.A.2.b.iv).

Office: PD		ID: PD2051
Unique INC #: LAW06054	Well Name: WARBONNET	
	Well #: 8B-10D	ID Date: 04/03/06
Operator: ULTRA RESOURCES INC		Effective Date: 04/04/06
Case #: WYW015314	FAC ID:	Abatement Date: 04/05/06
Form: I	FAC NAME:	Corrected Date: 04/04/06
Assessment: \$0	Inspector: WALDO	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O. 2 III A.2.h.xi.		

Remarks Date: 04/03/06

Problem: Blind rams shall be activated each trip and recorded in the driller log. Corrective action: Record blind ram activation in the drillers log.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD ID: PD2049  
Unique INC #: LAW06056 Well Name: WARBONNET  
Well #: 8B-10D ID Date: 04/03/06  
Operator: ULTRA RESOURCES INC Effective Date: 04/04/06  
Case #: WYW015314 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date: 04/05/06  
Gravity: 3 Corrected Date: 04/04/06  
Authority Ref: O.O.2 III.A.2.g. Followup Date:  
Remarks Date: 04/03/06 Extend Date:

Problem: No valve in closing line of annular preventer to act as a locking device. Corrective action: Install valve in closing line of annular preventer with an attached handle.

Office: PD ID: PD2055  
Unique INC #: LAW06059 Well Name: MESA  
Well #: 7A-35D ID Date: 04/06/06  
Operator: ULTRA RESOURCES INC Effective Date: 04/07/06  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date: 04/08/06  
Gravity: 3 Corrected Date: 04/07/06  
Authority Ref: O.O.2 III.A.2.i.vii. Followup Date:  
Remarks Date: 04/06/06 Extend Date:

Problem: Annular preventers shall be functionally operated at least weekly and recorded in the driller log. Corrective action: Function annular preventers and record in drillers log as required.

Office: PD ID: PD2059  
Unique INC #: LAW06063 Well Name: MESA  
Well #: 7A-35D ID Date: 04/06/06  
Operator: ULTRA RESOURCES INC Effective Date: 04/07/06  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date: 04/08/06  
Gravity: 3 Corrected Date: 04/07/06  
Authority Ref: O.O.2 III.A.2.i.viii. Followup Date:  
Remarks Date: 04/06/06 Extend Date:

Problem: Pipe and blind rams shall be activated each trip and recorded in the drillers log (O.O.2 III.A.2.i.xi.). Not recorded in the driller log. Corrective action: Activate pipe and blind rams when tripping and record in the drillers log.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD ID: PD2054  
Unique INC #: LAW06058 Well Name: MESA  
Well #: 7A-35D ID Date: 04/06/06  
Operator: ULTRA RESOURCES INC Effective Date: 04/07/06  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date: 04/08/06  
Gravity: 3 Corrected Date: 04/07/06  
Authority Ref: O.O.2 III.A.2.i.ix. Followup Date:  
Extend Date:

Remarks Date: 04/06/06

Problem: A BOPE pit level drill shall be conducted weekly for each drilling crew and recorded in the drilling log. Corrective action: Perform drills and record in driller log.

Office: PD ID: PD2056  
Unique INC #: LAW06060 Well Name: MESA  
Well #: 7A-35D ID Date: 04/06/06  
Operator: ULTRA RESOURCES INC Effective Date: 04/07/06  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date: 04/08/06  
Gravity: 3 Corrected Date: 04/07/06  
Authority Ref: O.O.2 III.A.2.i.viii. Followup Date:  
Extend Date:

Remarks Date: 04/06/06

Problem: Pipe and blind rams shall be activated each trip and recorded in the drilling log (not recorded). Corrective action: Activate rams when tripping and record in drillers log.

Office: PD ID: PD2060  
Unique INC #: LAW06064 Well Name: MESA  
Well #: 10A-8D ID Date: 04/11/06  
Operator: QUESTAR EXPL & PROD CO PNDL Effective Date: 04/12/06  
Case #: WYW08589 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date: 04/13/06  
Gravity: 3 Corrected Date: 04/13/06  
Authority Ref: O.O.2 III.A.2.g. Followup Date:  
Extend Date:

Remarks Date: 04/11/06

Problem: No valve in the closing line of the annular. Corrective action: A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD ID: PD2061  
 Unique INC #: LAW06065 Well Name: MESA  
 Well #: 10A-8D ID Date: 04/11/06  
 Operator: QUESTAR EXPL & PROD CO PNDL Effective Date: 04/12/06  
 Case #: WYW08589 FAC ID: Abatement Date: 04/13/06  
 Form: I FAC NAME: Corrected Date: 04/13/06  
 Assessment: \$0 Inspector: WALDO Followup Date:  
 Gravity: 3 Extend Date:  
 Authority Ref: O.O.2. III.A.2.i.vii.

Remarks Date: 04/11/06

Problem: Not recording in the drillers log the annular preventers which shall be functionally operated at least weekly. Corrective action: Record annular functions at least weekly in the drillers log.

Office: PD ID: PD2043  
 Unique INC #: LAW06048 Well Name: WARBONNET  
 Well #: 10D-5D ID Date: 03/28/06  
 Operator: ULTRA RESOURCES INC Effective Date: 03/29/06  
 Case #: WYW144994 FAC ID: Abatement Date: 03/30/06  
 Form: I FAC NAME: Corrected Date: 03/30/06  
 Assessment: \$0 Inspector: WALDO Followup Date:  
 Gravity: 3 Extend Date:  
 Authority Ref: O.O.2 III.A.2.i.vii.

Remarks Date: 03/28/06

Problem: Annular preventer not activated weekly and recorded in the drillers log. Corrective action: Activate annular and record action in the drillers log.

Office: PD ID: PD2039  
 Unique INC #: LAW06044 Well Name: WARBONNET  
 Well #: 10D-5D ID Date: 03/28/06  
 Operator: ULTRA RESOURCES INC Effective Date: 03/29/06  
 Case #: WYW144994 FAC ID: Abatement Date: 03/30/06  
 Form: I FAC NAME: Corrected Date: 03/30/06  
 Assessment: \$0 Inspector: WALDO Followup Date:  
 Gravity: 3 Extend Date:  
 Authority Ref: O.O.#2 III.A.2.a.v

Remarks Date: 03/28/06

Problem: No pressure gauge on choke manifold (O.O.2 III.A.2.a.v.) Corrective action: Install pressure gauge on choke manifold according to Onshore Orders where all BOPE connections subjected to well pressure shall be flanged, welded or clamped. Note: Pressure gauges in the well control system shall be a type designed for drilling fluid service (O.O.2 III.A.2.b.iv.).

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD ID: PD2044  
Unique INC #: LAW06049 Well Name: WARBONNET ID Date: 02/28/06  
Well #: 10D-5D Effective Date: 03/29/06  
Operator: ULTRA RESOURCES INC Abatement Date: 03/30/06  
Case #: WYW144994 FAC ID: Corrected Date: 03/30/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WALDO Extend Date:  
Gravity: 3  
Authority Ref: O.O.2 III.C.7.

Remarks Date: 02/28/06

Problem: Flare system is not anchored. Corrective action: Anchor flar system.

Office: PD ID: PD2042  
Unique INC #: LAW06047 Well Name: WARBONNET ID Date: 03/28/06  
Well #: 10D-5D Effective Date: 03/29/06  
Operator: ULTRA RESOURCES INC Abatement Date: 03/30/06  
Case #: WYW144994 FAC ID: Corrected Date: 03/30/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WALDO Extend Date:  
Gravity: 3  
Authority Ref: O.O.2 III.A.2.e.

Remarks Date: 03/28/06

Problem: Air was not turned on to accumulator. Corrective action: Two independent sources of power are required for the accumulator on 5M BOP systems and greater. The power for the closing unit pumps shall be available to the unit at all times. Keep both power sources turned on.

Office: PD ID: PD2040  
Unique INC #: LAW Well Name: WARBONNET ID Date: 03/28/06  
Well #: 10D-5D Effective Date: 03/29/06  
Operator: ULTRA RESOURCES INC Abatement Date: 03/30/06  
Case #: WYW144994 FAC ID: Corrected Date: 03/30/06  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WALDO Extend Date:  
Gravity: 3  
Authority Ref: O.O.2 III.A.2.g.

Remarks Date: 03/28/06

Problem: No valve in closing line of the annular preventer to act as a locking device. Corrective action: Install valve in closing line of annular preventer with an attached handle.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PD ID: PD2041  
Unique INC #: LAW06046 Well Name: WARBONNET  
Well #: 10D-5D ID Date: 03/28/06  
Operator: ULTRA RESOURCES INC Effective Date: 03/29/06  
Case #: WYW144994 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WALDO Abatement Date: 03/30/06  
Gravity: 3 Corrected Date: 03/30/06  
Authority Ref: O.O.2.III.A.2.g. Followup Date:  
Extend Date:  
  
Remarks Date: 03/28/06  
Problem: No hand wheels on BOP equipment. Corrective action: Install manual locking device(i.e. hand wheels) or automatic locking device on all BOP systems of 2M or greater.

Office: PR ID: PR3484  
Unique INC #: WW06001 Well Name: PETERS POINT UNIT FEDERAL  
Well #: 4-12D-13-16 ID Date: 05/11/06  
Operator: BILL BARRETT CORPORATION Effective Date: 05/11/06  
Case #: UTU63014X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: W WILLIS Abatement Date: 05/13/06  
Gravity: 1 Corrected Date: 05/16/06  
Authority Ref: OO#2 III.A.2.g. Followup Date: 05/16/06  
Extend Date:  
  
Remarks Date: 05/17/06  
Handles on BOP not installed. 5/16/2006 On 2nd return trip found handles installed on BOP.

Office: PR ID: PR3485  
Unique INC #: WW06002 Well Name: PETERS POINT UNIT FEDERAL  
Well #: 4-12D-13-16 ID Date: 05/11/06  
Operator: BILL BARRETT CORPORATION Effective Date: 05/11/06  
Case #: UTU63014X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: W WILLIS Abatement Date: 05/13/06  
Gravity: 1 Corrected Date: 05/13/06  
Authority Ref: OO#2 III.2.g. Followup Date: 05/13/06  
Extend Date:  
  
Remarks Date: 05/11/06  
Valve Not Installed on Annular Preventer.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: PR ID: PR3488  
Unique INC #: WW06005 Well Name: PETERS POINT UNIT FEDERAL  
Well #: 4-12D-13-16  
Operator: BILL BARRETT CORPORATION  
Case #: UTU63014X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: W WILLIS  
Gravity: 1  
Authority Ref: OO#2 iii.A.2.h.

Remarks Date: 05/11/06

Remote BOP Closing Unit Not Fully Functional.

Office: PR ID: PR3487  
Unique INC #: WW06004 Well Name: PETERS POINT UNIT FEDERAL  
Well #: 4-12D-13-16  
Operator: BILL BARRETT CORPORATION  
Case #: UTU63014X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: W WILLIS  
Gravity: 3  
Authority Ref: OO#2 III.A.2.b.

Remarks Date: 05/11/06

Kill line not extended to outside edge of substructure.

Office: RW ID: RW3605  
Unique INC #: WA-50-06 Well Name: WAMSUTTER FEDERAL  
Well #: 80-24  
Operator: CABOT OIL & GAS CORPORATION  
Case #: WYW0178661 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ASHLINE  
Gravity: 3  
Authority Ref: C.O.A.

Remarks Date: 04/14/06

Conditions of approval call for four (4) culverts to be installed before drilling operation begin. Install all four (4) culverts as called for in the Conditions of approval.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: RW ID: RW3569  
Unique INC #: WA-39-06 Well Name: SIBERIA RIDGE ID Date: 03/16/06  
Well #: 32-14 Effective Date: 03/23/06  
Operator: WHITING OIL & GAS CORPORATION Abatement Date: 04/06/06  
Case #: WYW110335 FAC ID: Corrected Date: 04/06/06  
Form: I FAC NAME: Followup Date: 04/06/06  
Assessment: \$0 Inspector: ASHLINE Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.6(a)(b)(c)

Remarks Date: 03/16/06

Site is not properly identified. Put sign up.

Office: RW ID: RW3468  
Unique INC #: BA-04-06 Well Name: LOOKOUT WASH UNIT ID Date: 11/07/05  
Well #: 30-5 Effective Date: 11/12/05  
Operator: CABOT OIL & GAS CORPORATION Abatement Date: 12/12/05  
Case #: WYW141458X FAC ID: Corrected Date: 12/12/05  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: ASHLINE Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1(a) Conditions of approval in APD

Remarks Date: 11/07/05

A permanent marker is to be installed at both ends of all culverts to help prevent traffic from passing over the ends.

Office: RW ID: RW3469  
Unique INC #: BA-05-06 Well Name: LOOKOUT WASH UNIT ID Date: 11/07/05  
Well #: 30-5 Effective Date: 11/12/05  
Operator: CABOT OIL & GAS CORPORATION Abatement Date: 12/12/05  
Case #: WYW141458X FAC ID: Corrected Date: 12/12/05  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: ASHLINE Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1(a) Conditions of approval in APD.

Remarks Date: 11/07/05

Prior to moving the drilling equipment onto the well pad, the access road shall be thoroughly compacted, completed to an appropriate grade, and surfaced to the degree necessary to support heavy vehicular traffic during all drilling operations. This may include at a minimum the thorough compaction of the road's sub-base to at least 85% of its maximum dry density, prior to surfacing with a MINIMUM of a four (4) inch layer of compacted gravel.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: RW ID: RW3467  
Unique INC #: BA-03-06 Well Name: LOOKOUT WASH UNIT  
Well #: 30-5 ID Date: 11/07/05  
Operator: CABOT OIL & GAS CORPORATION Effective Date: 11/12/05  
Case #: WYW141458X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ASHLINE Abatement Date: 12/12/05  
Gravity: 3 Corrected Date: 12/12/05  
Authority Ref: 43CFR 3164.1(a) Conditions of approval in APD Followup Date:  
Remarks Date: 11/07/05 Extend Date:

Road is not up to minimum BLM standards. "The inside slope of the side ditches shall be 4:1. The bottom of the ditch shall be a smooth V, with no vertical cut in the bottom. A flat bottom ditch may be used where more fill material is needed to elevate the road. The outside slop of the ditch shall be 4:1.

Office: RW ID: RW3456  
Unique INC #: BSH06-2 Well Name: HANNA DRAW CBNG POD  
Well #: 2-2 ID Date: 10/20/05  
Operator: ANADARKO E & P COMPANY LP Effective Date: 10/20/05  
Case #: WYW148227 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HURST Abatement Date: 11/15/05  
Gravity: 3 Corrected Date: 11/15/05  
Authority Ref: Conditions of Approval Followup Date: 11/15/05  
Remarks Date: 10/20/05 Extend Date:

Access road is not gravelled prior to moving in rig as required. Gravel access road as required.

Office: RW ID: RW3915  
Unique INC #: SK-37-06 Well Name: ECHO SPRINGS FEDERAL  
Well #: 9-10D ID Date: 09/11/06  
Operator: SAMSON RESOURCES COMPANY Effective Date: 09/11/06  
Case #: WYW32958 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KING Abatement Date: 09/12/06  
Gravity: 3 Corrected Date: 09/13/06  
Authority Ref: OO#2 III.A.2.g Followup Date: 10/06/06  
Remarks Date: 09/11/06 Extend Date:

No handwheels are installed on the BOP

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: RW		ID: RW3916
Unique INC #: SK-38-06	Well Name: ECHO SPRINGS FEDERAL	ID Date: 09/11/06
	Well #: 9-10D	Effective Date: 09/11/06
Operator: SAMSON RESOURCES COMPANY		Abatement Date: 09/13/06
Case #: WYW32958	FAC ID:	Corrected Date: 09/13/06
Form: I	FAC NAME:	Followup Date: 10/06/06
Assessment: \$0	Inspector: KING	Extend Date:
Gravity: 1		
Authority Ref: OO#2 III.C.7.		

Remarks Date: 09/11/06

Flare line is not anchored Flare line is not equiped with any method for ignition. Flare line has one location between the gas buster and choke manifold that does not have a targeted tee and is using a 90 degree elbow.

Office: RW		ID: RW3917
Unique INC #: SK-39-06	Well Name: ECHO SPRINGS FEDERAL	ID Date: 09/11/06
	Well #: 9-10D	Effective Date: 09/11/06
Operator: SAMSON RESOURCES COMPANY		Abatement Date: 09/12/06
Case #: WYW32958	FAC ID:	Corrected Date: 09/13/06
Form: I	FAC NAME:	Followup Date: 10/06/06
Assessment: \$0	Inspector: KING	Extend Date:
Gravity: 3		
Authority Ref: OO#2 III.2.i.xi		

Remarks Date: 09/11/06

Documentation was not consistently documented for several tests/drills (touly mud test and slow pump speed, weekly BOP drills and Annular activation, Blind and Pipe Rams activation at each trip.

Office: RW		ID: RW3914
Unique INC #: CWMC3606	Well Name: FREWEN	ID Date: 09/08/06
	Well #: 2-1	Effective Date: 09/08/06
Operator: BP AMERICA PRODUCTION COMPANY		Abatement Date: 09/15/06
Case #: WYW107385	FAC ID:	Corrected Date: 09/14/06
Form: I	FAC NAME:	Followup Date: 09/14/06
Assessment: \$0	Inspector: MCCUNE	Extend Date:
Gravity: 3		
Authority Ref: APD-Surface Use Plan		

Remarks Date: 09/08/06

Fourth culvert on road is in place and not marked as per APD-Surface Use Plan, with a permanent marker on each end. Place fourth culvert at edge of location as per APD-Surface Use Plan and place permanent markers on each end of culvert 9-14-06 In conversation with Tim (BP) representative at Wamsutter, spoke with Travis Bargesten, this INC was cleared to let wing ditches take care of drainage in this location

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: RW ID: RW3910  
Unique INC #: CWMC3206 Well Name: FREWEN ID Date: 09/08/06  
Well #: 2-1 Effective Date: 09/08/06  
Operator: BP AMERICA PRODUCTION COMPANY Abatement Date: 09/15/06  
Case #: WYW107385 FAC ID: Corrected Date: 09/18/06  
Form: I FAC NAME: Followup Date: 10/27/06  
Assessment: \$0 Inspector: MCCUNE Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.5-1(a)(b)(c)

Remarks Date: 09/08/06

Fence is down on Reserve pit. Repair fence and maintain as long as reserve pit is not reclaimed.

Office: RW ID: RW3912  
Unique INC #: CWMC3406 Well Name: FREWEN ID Date: 09/08/06  
Well #: 2-1 Effective Date: 09/08/06  
Operator: BP AMERICA PRODUCTION COMPANY Abatement Date: 09/15/06  
Case #: WYW107385 FAC ID: Corrected Date: 09/18/06  
Form: I FAC NAME: Followup Date: 10/27/06  
Assessment: \$0 Inspector: MCCUNE Extend Date:  
Gravity: 3  
Authority Ref: APD-Surface Use Plan

Remarks Date: 09/08/06

Second culvert on road is not marked as per APD-Surface Use Plan, with a permanent marker on each end. Place permanent markers on each end of second culvert

Office: RW ID: RW3911  
Unique INC #: CWMC3306 Well Name: FREWEN ID Date: 09/08/06  
Well #: 2-1 Effective Date: 09/08/06  
Operator: BP AMERICA PRODUCTION COMPANY Abatement Date: 09/15/06  
Case #: WYW107385 FAC ID: Corrected Date: 09/18/06  
Form: I FAC NAME: Followup Date: 10/27/06  
Assessment: \$0 Inspector: MCCUNE Extend Date:  
Gravity: 3  
Authority Ref: APD-Surface Use Plan

Remarks Date: 09/08/06

Culvert at begining of road is not marked as per APD-Surface Use Plan, with a permanent marker on each end. Place permanent markers on each end of culvert

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: RW		ID: RW3913
Unique INC #: CWMC3506	Well Name: FREWEN	
	Well #: 2-1	ID Date: 09/08/06
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 09/08/06
Case #: WYW107385	FAC ID:	Abatement Date: 09/15/06
Form: I	FAC NAME:	Corrected Date: 09/18/06
Assessment: \$0	Inspector: MCCUNE	Followup Date: 10/27/06
Gravity: 3		Extend Date:
Authority Ref: APD-Surface Use Plan		

Remarks Date: 09/08/06

Third culvert on road is not marked as per APD-Surface Use Plan, with a permanent marker on each end. Place permanent markers on each end of Third culvert

Office: RW		ID: RW3909
Unique INC #: CWMC3106	Well Name: FREWEN	
	Well #: 2-1	ID Date: 09/08/06
Operator: BP AMERICA PRODUCTION COMPANY		Effective Date: 09/08/06
Case #: WYW107385	FAC ID:	Abatement Date: 09/08/06
Form: I	FAC NAME:	Corrected Date: 09/11/06
Assessment: \$0	Inspector: MCCUNE	Followup Date: 09/12/06
Gravity: 3		Extend Date:
Authority Ref: APD-General Permitting Requirements		

Remarks Date: 09/08/06

Failure to follow approved conditions as per APD, General Permitting Requirements, sub part 5. Also as stated in 3162.1(a) Comply with APD, General Permitting Requirements, sub part 5, notification of actions pertaining to casing and cementing as per permit. Penalties for this violation fall under 43 CFR 3160, Sub Part 3163.1(a)(2)(3)(5)(c)(d)

Office: RW		ID: RW3881
Unique INC #: CWMC2306	Well Name: N BATTLE SPRINGS UNIT	
	Well #: 1-31	ID Date: 08/28/06
Operator: J-W OPERATING COMPANY		Effective Date: 08/28/06
Case #: WYW168845X	FAC ID:	Abatement Date: 09/09/06
Form: I	FAC NAME:	Corrected Date: 09/16/06
Assessment: \$0	Inspector: MCCUNE	Followup Date: 09/28/06
Gravity: 3		Extend Date:
Authority Ref: APD- Add. Permit. Requirements		

Remarks Date: 08/28/06

Culvert is indicated in the Additional Permitting Requirements submitted by J W Operating for the road to the lease as per Road Plan/Profile, Sheet 11 of 19. No culvert is installed at this time, 8-30-2006, 1400 hrs. Install culvert as specified in APD for the lease North Battlesprings Unit 1-31, on the engineers plats labeled Road Plan/Profile, Sheet 11 of 19. As per section ADDITIONAL PERMITTING REQUIREMENTS, sub part SURFACE USE PLAN OF OPERATIONS, sub part Access Roads to be Constructed and Reconstructed, sub part 9. .

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: RW ID: RW3880  
Unique INC #: CWMC2206 Well Name: N BATTLE SPRINGS UNIT  
Well #: 1-31 ID Date: 08/28/06  
Operator: J-W OPERATING COMPANY Effective Date: 08/28/06  
Case #: WYW168845X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MCCUNE Abatement Date: 09/09/06  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6 (a), (b) Corrected Date: 09/28/06  
Followup Date: 09/28/06

Remarks Date: 08/28/06

No well identification sign on location. Place well identification on marker leading on to location.

Office: RW ID: RW3867  
Unique INC #: CWMC1706 Well Name: N BATTLE SPRINGS UNIT  
Well #: 1-31 ID Date: 08/30/06  
Operator: J-W OPERATING COMPANY Effective Date: 08/30/06  
Case #: WYW168845X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MCCUNE Abatement Date: 08/29/06  
Gravity: 3 Extend Date:  
Authority Ref: OO#1 III.G.3.f Corrected Date: 08/30/06  
Followup Date: 08/30/06

Remarks Date: 08/28/06

APD not on location. Obtain copy of APD and maintain on Location during drilling operations. Usual location is on board in top doghouse.

Office: RW ID: RW3687  
Unique INC #: CWMC1406 Well Name: TIERNEY  
Well #: 5-12 ID Date: 06/20/06  
Operator: DEVON ENERGY PRODUCTION CO LP Effective Date: 06/20/06  
Case #: WYW51982 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MCCUNE Abatement Date: 06/20/06  
Gravity: 3 Extend Date:  
Authority Ref: OSO 1.III.G.4./ b.9 Corrected Date: 06/21/06  
Followup Date: 09/28/06

Remarks Date: 06/20/06

After verbal issued to move mud trailer and mud pallets off pipeline, mud was again observed stacked off the location. Cease and desist stacking mud off location.

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Office: RW		ID: RW3686
Unique INC #: CWMC1306	Well Name: TIERNEY	
	Well #: 5-12	ID Date: 06/20/06
Operator: DEVON ENERGY PRODUCTION CO LP		Effective Date: 06/20/06
Case #: WYW51982	FAC ID:	Abatement Date: 06/21/06
Form: I	FAC NAME:	Corrected Date: 06/21/06
Assessment: \$0	Inspector: MCCUNE	Followup Date: 06/28/06
Gravity: 1		Extend Date:
Authority Ref: 43cfr 3163.1.a.3/6/b.2		

Remarks Date: 06/20/06

6-20-06 Crews have been using the pipeline as access road to rig location from the Wamsutter-Dad road. In a inspection performed on 6-12-06, the daylight crew was observed driving down the pipeline, subsequent to that, we had a meeting in the top dog house in which everyone present, including toolpusher, and both crews and company man, were informed not to drive on pipeline. There is evidence (tire tracks, and ruts) showing that the pipeline access is still being used by the rig personnel. Cease and desist all use of the pipeline access area immediately. Make access unusable for traffic immediately. As discussed today 6-20-06, between Gary Todd, Jerry Dickinson and Carl McCune, this practice is not in compliance with the lease terms, the approved APD and surface use plan, and is in violation of easements granted to others. To remedy this situation, the following were identified as steps to be taken: 1) Devon has already posted notices in the dog house and on location that anyone who is found to be driving on unapproved access roads could be immediately terminated and will not only not work on this location, but on any Devon location again. 2) Devon has contacted a rooustabout company to erect barriers off location to access the pipeline right of way. The BLM requests that a dike, berm, or temporary fence (with flags installed to prevent someone from driving into it after dark) be installed not only off the location, but off of Dad Road onto the pipeline right of way to stop the use of the right of way as access to the Devon well location. 3) The BLM will require that you also post signs on each end of the pipeline right of way (from Dad Road and off your location) stating that this road is closed to vehicle traffic. 4) The BLM will perform an inspection of the damage done to the Pipe line Right of way and will advise in the near future the steps that will be required of Devon to remediate the damage. These steps may include ripping and re-seeding the damaged area. Early estimates show that as much as 3/4 of a mile of damage has occurred.

Office: RW		ID: RW3486
Unique INC #: CR06-11-I	Well Name: SIBERIA RIDGE	
	Well #: 8-41	ID Date: 12/09/05
Operator: WHITING OIL & GAS CORPORATION		Effective Date: 12/09/05
Case #: WYW0312099	FAC ID:	Abatement Date: 01/15/06
Form: I	FAC NAME:	Corrected Date: 01/15/06
Assessment: \$0	Inspector: ROSS	Followup Date: 01/26/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3164.1 (a) and Conditions of Approval in APD		

Remarks Date: 12/09/05

Road is not graveled as required in the APD.

Office: RW		ID: RW3475
Unique INC #: CR06-03-DI	Well Name: SOUTH BAGGS UNIT	
	Well #: 52	ID Date: 11/21/05
Operator: MERIT ENERGY COMPANY		Effective Date: 11/29/05
Case #: WYW109696X	FAC ID:	Abatement Date: 12/09/05
Form: I	FAC NAME:	Corrected Date: 12/09/05
Assessment: \$0	Inspector: ROSS	Followup Date: 01/31/06
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3164.1 (a) and Onshore Order No. 1 III G.3.f.		

Remarks Date: 11/21/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Approved Form 3160-3 (APD) and the pertinent drilling plan, along with the conditions of approval, were not available on the drill site.

Office: RW ID: RW3401  
Unique INC #: CR05-76-I Well Name: ROAD CROSSING UNIT  
Well #: 1-31 ID Date: 09/15/05  
Operator: EOG RESOURCES INC Effective Date:  
Case #: WYW160210X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (a)

Remarks Date: 09/15/05

There is no well identification sign.

Office: RW ID: RW3490  
Unique INC #: CR06-10-I Well Name: WAMSUTTER FEDERAL  
Well #: 6-8 ID Date: 01/13/06  
Operator: ANADARKO E & P COMPANY LP Effective Date: 01/31/06  
Case #: WYW7173 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 (a) and Conditions of Approval in APD

Remarks Date: 01/13/06

No culverts were installed in access road as required in APD.

Office: RW ID: RW3452  
Unique INC #: PS0508 Well Name: KOP  
Well #: 40-22 ID Date: 10/25/05  
Operator: ENCANA OIL & GAS (USA) INC Effective Date:  
Case #: WYW114542 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SENA  
Gravity: 3  
Authority Ref: Condition of Approval

Remarks Date: 10/25/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

No culverts installed as per APD. Conditions of approval calls for 3 culverts to be installed, as per Exhibit 4 Access road map.

Office: RW ID: RW3461  
Unique INC #: PS0509 Well Name: BARREL SPRINGS FEDERAL  
Well #: 12-4 ID Date: 10/26/05  
Operator: COLEMAN OIL & GAS INCORPORATED Effective Date: 10/26/05  
Case #: WYW152712 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SENA  
Gravity: 3  
Authority Ref: Condition f Approval

Remarks Date: 10/26/05

No culvert installed as per APD. Conditions of Approval calls for one 18" culvert to be installed as per attachment/Topo Map B.

Office: RW ID: RW3466  
Unique INC #: PS0510 Well Name: BARREL SPRINGS FEDERAL  
Well #: 12-5 ID Date: 10/31/05  
Operator: COLEMAN OIL & GAS INCORPORATED Effective Date: 10/31/05  
Case #: WYW152712 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SENA  
Gravity: 3  
Authority Ref: Conditions of Approval

Remarks Date: 10/31/05

No Culvert installed as per APD. Conditions of Approval calls for one 18" culvert to be installed as per attachment/TOPO Map B.

Office: RW ID: RW3473  
Unique INC #: PS06-09 Well Name: BARREL SPRINGS FEDERAL  
Well #: 12-4 ID Date: 10/26/05  
Operator: COLEMAN OIL & GAS INCORPORATED Effective Date: 10/26/05  
Case #: WYW152712 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SENA  
Gravity: 3  
Authority Ref: 43CFR 3162.6(e)(b)(c)

Remarks Date: 10/26/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

There is no well sign on this location. Install a well sign containing all required information as specified in 43 CFR 3162.6.

Office: RW ID: RW3847  
Unique INC #: PS0603 Well Name: WAMSUTTER FEDERAL  
Well #: 8-13 ID Date: 08/17/06  
Operator: ANADARKO E & P COMPANY LP Effective Date: 08/17/06  
Case #: WYW7173 FAC ID: Abatement Date: 08/28/06  
Form: I FAC NAME: Corrected Date: 08/30/06  
Assessment: \$0 Inspector: SENA Followup Date: 08/30/06  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3163.1

Remarks Date: 08/17/06

In violation of the Conditions of Approval. BOPE required for the approved depth. The BOP and releated equipment shall be suitable for operations as approved.

Office: RW ID: RW3845  
Unique INC #: PS0601 Well Name: WAMSUTTER FEDERAL  
Well #: 8-13 ID Date: 08/17/06  
Operator: ANADARKO E & P COMPANY LP Effective Date: 08/17/06  
Case #: WYW7173 FAC ID: Abatement Date: 08/28/06  
Form: I FAC NAME: Corrected Date: 08/30/06  
Assessment: \$0 Inspector: SENA Followup Date: 08/30/06  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3163.1

Remarks Date: 08/17/06

Failed to notify running of production casing as per Conditions of Approval. Cement not in compliance with Conditions of Approval.

Office: RW ID: RW3846  
Unique INC #: PS0602 Well Name: WAMSUTTER FEDERAL  
Well #: 8-13 ID Date: 08/17/06  
Operator: ANADARKO E & P COMPANY LP Effective Date: 08/17/06  
Case #: WYW7173 FAC ID: Abatement Date: 08/28/06  
Form: I FAC NAME: Corrected Date: 08/30/06  
Assessment: \$0 Inspector: SENA Followup Date: 08/30/06  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3163.1

Remarks Date: 08/17/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

In violation of the terms of the lease and APD. Drilled beyond the approved depth in the APD. Failed to notify and get approval before exceeding the approved depth with a Sundry.

Office: RW ID: RW3478  
Unique INC #: PS0511 Well Name: DUCK LAKE  
Well #: 15-1 ID Date: 11/29/05  
Operator: DEVON ENERGY PRODUCTION CO LP Effective Date: 11/29/05  
Case #: WYW97572 FAC ID: Abatement Date: 12/29/05  
Form: I FAC NAME: Corrected Date: 12/29/05  
Assessment: \$0 Inspector: SENA Followup Date: 01/13/06  
Gravity: 3 Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 11/29/05

Missing one culvert as per APD. Conditions of Approval calls for two 18" culvert to be installed as per attachment/TOPO Map B.

Office: RW ID: RW3694  
Unique INC #: AW54-06 Well Name: COW CREEK UNIT  
Well #: 2 DEEP ID Date: 06/25/06  
Operator: DOUBLE EAGLE PETROLEUM Effective Date: 06/25/06  
Case #: WYW109471X FAC ID: Abatement Date: 07/16/06  
Form: I FAC NAME: Corrected Date: 06/26/06  
Assessment: \$0 Inspector: WHITE Followup Date: 06/29/06  
Gravity: 3 Extend Date:  
Authority Ref: COA

Remarks Date: 06/25/06

FLAIR PIT IS NOT FENCED. RESERVE PIT FENCE IS DOWN. FENCE FLAIR PIT AND REPAIR RESERVE PIT FENCE TO BLM SPECS.

Office: RW ID: RW3695  
Unique INC #: AW55-06 Well Name: COW CREEK UNIT  
Well #: 2 DEEP ID Date: 06/25/06  
Operator: DOUBLE EAGLE PETROLEUM Effective Date: 06/25/06  
Case #: WYW109471X FAC ID: Abatement Date: 07/05/06  
Form: I FAC NAME: Corrected Date: 06/26/06  
Assessment: \$0 Inspector: WHITE Followup Date: 06/29/06  
Gravity: 3 Extend Date:  
Authority Ref: 00#2 43CFR3160 III.A (b)

Remarks Date: 06/25/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Blooie lines are not anchored. Anchor blooie lines.

Office: RW			ID: RW3696
Unique INC #: AW56-06	Well Name: COW CREEK UNIT		
	Well #: 2 DEEP		
Operator: DOUBLE EAGLE PETROLEUM			
Case #: WYW109471X	FAC ID:		ID Date: 06/25/06
Form: I	FAC NAME:		Effective Date: 06/25/06
Assessment: \$0	Inspector: WHITE		Abatement Date: 07/04/06
Gravity: 1			Corrected Date: 06/26/06
Authority Ref: OO#242CFR3160 III.C.7.			Followup Date: 06/26/06
			Extend Date:

Remarks Date: 06/25/06

The flare shystem shall have an effective method of ignition. Install effective method of ignition.

Office: RW			ID: RW3732
Unique INC #: AW73-06	Well Name: ESPY FEDERAL		
	Well #: 1-22		
Operator: THOROFARE RESOURCES INC			
Case #: WYW109504A	FAC ID:		ID Date: 07/15/06
Form: I	FAC NAME:		Effective Date: 07/15/06
Assessment: \$0	Inspector: WHITE		Abatement Date: 07/20/06
Gravity: 3			Corrected Date: 07/17/06
Authority Ref: OO#2 III.A.2.g.			Followup Date: 07/17/06
			Extend Date:

Remarks Date: 07/15/06

No valve in closing line of annular preventer. Please install ball valve in closing line of annular preventer as close to annular as possible.

Office: RW			ID: RW3730
Unique INC #: AW71-06	Well Name: SOUTH BAGGS UNIT POD		
	Well #: 43-8-1292		
Operator: MERIT ENERGY COMPANY			
Case #: WYW109696X	FAC ID:		ID Date: 07/14/06
Form: I	FAC NAME:		Effective Date: 07/14/06
Assessment: \$0	Inspector: WHITE		Abatement Date: 07/31/06
Gravity: 3			Corrected Date: 07/25/06
Authority Ref: 43 CFR 3162.5-1(a)(b)(c)			Followup Date: 07/28/06
			Extend Date:

Remarks Date: 07/14/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Alot of trash on and around location. Please remove all trash from location and trash around location that has blown onto the range.

Office: RW		ID: RW3731
Unique INC #: AW72-06	Well Name: SOUTH BAGGS UNIT POD	
	Well #: 43-8-1292	
Operator: MERIT ENERGY COMPANY		
Case #: WYW109696X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WHITE	
Gravity: 3		
Authority Ref: COA		

Remarks Date: 07/14/06

One 18" culvert missing. Please install one 18" culvert and mark the ends.

Office: RW		ID: RW3829
Unique INC #: AW77-06	Well Name: LATHAM DRAW FEDERAL	
	Well #: 44-26	
Operator: ENCANA OIL & GAS (USA) INC		
Case #: WYW125919	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WHITE	
Gravity: 1		
Authority Ref: 43 CFR 3162.3-1(e)		

Remarks Date: 08/01/06

Sundry Notice was not submitted to the BLM to change the depth of the surface casing. All changes to the original APD must be submitted to the BLM in a timely manner BEFORE SPUDDING.

Office: RW		ID: RW3830
Unique INC #: AW78-06	Well Name: LATHAM DRAW FEDERAL	
	Well #: 44-26	
Operator: ENCANA OIL & GAS (USA) INC		
Case #: WYW125919	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WHITE	
Gravity: 3		
Authority Ref: COA		

Remarks Date: 08/01/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Ends of culverts not marked. A permanent marker is to be installed at both ends of all culverts to help prevent traffic from passing over the ends.

Office: RW ID: RW3672  
Unique INC #: AW43-06 Well Name: MOLITOR FEDERAL  
Well #: 1, 1Y, 2, 3  
Operator: YATES PETROLEUM CORP  
Case #: WYW132364 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (a)(b)(c)

Remarks Date: 06/13/06  
No sign on location. Place proper sign on location. Molitor Federal 2

Office: RW ID: RW3671  
Unique INC #: AW42-06 Well Name: MOLITOR FEDERAL  
Well #: 2  
Operator: YATES PETROLEUM CORP  
Case #: WYW132364 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE  
Gravity: 3  
Authority Ref: COA

Remarks Date: 06/13/06  
Ends of culverts not marked. Culvert ends must be marked.

Office: RW ID: RW3673  
Unique INC #: AW44-06 Well Name: MOLITOR FEDERAL  
Well #: 2  
Operator: YATES PETROLEUM CORP  
Case #: WYW132364 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITE  
Gravity: 3  
Authority Ref: COA

Remarks Date: 06/13/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Flair pit is not fenced. Fence flair pit according to BLM specs.

Office: RW		ID: RW3676
Unique INC #: AW47-06	Well Name: MOLITOR FEDERAL	
	Well #: 2	
Operator: YATES PETROLEUM CORP		
Case #: WYW132364	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WHITE	
Gravity: 3		
Authority Ref: COA		

Remarks Date: 06/13/06

Materials stored off location. Store all materials on location.

Office: RW		ID: RW3675
Unique INC #: AW46-06	Well Name: MOLITOR FEDERAL	
	Well #: 2	
Operator: YATES PETROLEUM CORP		
Case #: WYW132364	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WHITE	
Gravity: 3		
Authority Ref: 43 CFR 3162.6 (a)(b)(c)		

Remarks Date: 06/13/06

No sign on location. Place proper sign on location. Molitor Federal 2

Office: RW		ID: RW3674
Unique INC #: AW45-06	Well Name: MOLITOR FEDERAL	
	Well #: 2	
Operator: YATES PETROLEUM CORP		
Case #: WYW132364	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WHITE	
Gravity: 3		
Authority Ref: COA		

Remarks Date: 06/13/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

No gravel on road. Gravel road according to BLM specs.

Office:	RW	ID:	RW3816
Unique INC #:	AW74-06	Well Name:	WAMSUTTER RIM
		Well #:	34-7
Operator:	BP AMERICA PRODUCTION COMPANY		
Case #:	WYW149534	FAC ID:	
Form:	I	FAC NAME:	
Assessment:	\$0	Inspector:	WHITE
Gravity:	3		
Authority Ref:	COA		

Remarks Date: 07/29/06

Flare pit is not fenced. Fence flare pit to BLM specs.

Office:	RW	ID:	RW3817
Unique INC #:	AW75-06	Well Name:	WAMSUTTER RIM
		Well #:	34-7
Operator:	BP AMERICA PRODUCTION COMPANY		
Case #:	WYW149534	FAC ID:	
Form:	I	FAC NAME:	
Assessment:	\$0	Inspector:	WHITE
Gravity:	3		
Authority Ref:	COA		

Remarks Date: 07/29/06

Materials stored off location. Store all materials within lease boundary.

Office:	RW	ID:	RW3818
Unique INC #:	AW76-06	Well Name:	WAMSUTTER RIM
		Well #:	34-7
Operator:	BP AMERICA PRODUCTION COMPANY		
Case #:	WYW149534	FAC ID:	
Form:	I	FAC NAME:	
Assessment:	\$0	Inspector:	WHITE
Gravity:	3		
Authority Ref:	COA		

Remarks Date: 07/29/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Trash on and around location. Remove all trash from location and all trash that has blown off of location.

Office: VE ID: iVE11699  
Unique INC #: CT06028 Well Name:  
Well #:  
Operator: FIML NATURAL RESOURCES, LLC ID Date: 06/05/06  
Case #: 1420H625053 FAC ID: Effective Date: 06/08/06  
Form: I FAC NAME: Abatement Date: 07/10/06  
Assessment: \$0 Inspector: ALAN WALKER Corrected Date: 07/05/06  
Gravity: 3 Followup Date: Extend Date:  
Authority Ref: 43 CFR 3162.6(b)(c)

Remarks Date: 06/05/06

THE WELL SIGN FOR THE ABOVE WELL READS UTC/FNR LLC, THE APD WAS APPROVED FOR FIML NATURAL RESOURCES NOT THE ABOVE MENTIONED OPERATOR NAME. PLEASE CORRECT THE OPERATOR NAME ON THE WELL SIGN.

Office: VE ID: iVE11609  
Unique INC #: WO06034 Well Name:  
Well #:  
Operator: BERRY PETROLEUM COMPANY ID Date: 06/12/06  
Case #: 1420H623537 FAC ID: Effective Date: 06/12/06  
Form: I FAC NAME: Abatement Date: 06/13/06  
Assessment: \$0 Inspector: BILL OWENS Corrected Date: 06/13/06  
Gravity: 3 Followup Date: Extend Date:  
Authority Ref: 43 CFR 3162.1

Remarks Date: 06/12/06

HAND WHEELS ON BOP NOT HOOKED UP.

Office: VE ID: iVE11608  
Unique INC #: WO06036 Well Name:  
Well #:  
Operator: BERRY PETROLEUM COMPANY ID Date: 06/12/06  
Case #: 1420H623537 FAC ID: Effective Date: 06/12/06  
Form: I FAC NAME: Abatement Date: 06/12/06  
Assessment: \$0 Inspector: BILL OWENS Corrected Date: 06/13/06  
Gravity: 3 Followup Date: Extend Date:  
Authority Ref: 43 CFR 3162.1

Remarks Date: 06/12/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

NEED TO EXTEND FLARE LINES TO FLARE PIT.

Office: VE ID: iVE11610  
Unique INC #: WO06035 Well Name:  
Well #:  
Operator: BERRY PETROLEUM COMPANY ID Date: 06/12/06  
Case #: 1420H623537 FAC ID: Effective Date: 06/12/06  
Form: I FAC NAME: Abatement Date: 06/13/06  
Assessment: \$0 Inspector: BILL OWENS Corrected Date: 06/13/06  
Gravity: 3 Followup Date: Extend Date:  
Authority Ref: 43 CFR 3162.1

Remarks Date: 06/12/06

NEED TO DIG FLARE PIT.

Office: VE ID: iVE11716  
Unique INC #: WO06016 Well Name:  
Well #:  
Operator: BERRY PETROLEUM COMPANY ID Date: 03/14/06  
Case #: 1420H624947 FAC ID: Effective Date: 03/14/06  
Form: I FAC NAME: Abatement Date: 03/15/06  
Assessment: \$0 Inspector: BILL OWENS Corrected Date: 03/15/06  
Gravity: 3 Followup Date: Extend Date:  
Authority Ref: 43 CFR 3163.1

Remarks Date: 03/14/06

NEED TO CHARGE THREE (3) NITROGEN BOTTLES ON THE ACCUMULATOR.

Office: VE ID: VE11751  
Unique INC #: WO06031 Well Name: CWU  
Well #: 886-22 ID Date: 07/14/06  
Operator: EOG RESOURCES INC FAC ID: Effective Date: 07/14/06  
Case #: UTU63013AD FAC NAME: Abatement Date: 07/15/06  
Form: I Inspector: BILL OWENS Corrected Date: 07/14/06  
Assessment: \$0 Followup Date: Extend Date:  
Gravity: 3 Authority Ref: 43 CFR 3162.1

Remarks Date: 07/14/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

NEED TO INSTALL HANDWHEELS ON BOP RAMS

Office: VE ID: VE11752  
Unique INC #: WO06032 Well Name: CWU  
Well #: 886-22  
Operator: EOG RESOURCES INC  
Case #: UTU63013AD FAC ID:  
Form: I  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: BILL OWENS  
Authority Ref: 43 CFR 3160.1  
Remarks Date: 07/14/06  
NEED TO HOOK UP KILL LINE

Office: VE ID: iVE11800  
Unique INC #: WO06012 Well Name: RBU  
Well #: 7-23F  
Operator: XTO ENERGY INC  
Case #: UTU63054A FAC ID:  
Form: I  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: BILL OWENS  
Authority Ref: 43 CFR 3163.1  
Remarks Date: 01/06/06  
ONSHORE ORDER NO. 2 - REQUIRES CHOKES TO BE FLANGED, WELDED, OR CLAMPED.

Office: VE ID: iVE11799  
Unique INC #: WO06011 Well Name: RBU  
Well #: 7-23F  
Operator: XTO ENERGY INC  
Case #: UTU63054A FAC ID:  
Form: I  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: BILL OWENS  
Authority Ref: 43 CFR 3163.1  
Remarks Date: 01/06/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

ONSHORE ORDER NO. 2 - REQUIRES HAND WHEELS ON PIPE & BLIND RAMS.

Office: VE ID: iVE11798  
Unique INC #: WO06010 Well Name: RBU  
Well #: 7-23F ID Date: 01/06/06  
Operator: XTO ENERGY INC Effective Date: 01/06/06  
Case #: UTU63054A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BILL OWENS  
Gravity: 3  
Authority Ref: 43 CFR 3163.1 Abatement Date: 01/09/06  
Corrected Date: 01/30/06  
Followup Date: 01/30/06  
Extend Date:

Remarks Date: 01/06/06

ONSHORE ORDER NO. 2 REQUIRES RAM ACTIVATION TESTS TO BE RECORDED IN DRILLING LOG.

Office: VE ID: iVE11587  
Unique INC #: CT06029 Well Name: UTE TRIBAL  
Well #: 3-22-54 ID Date: 09/19/06  
Operator: BERRY PETROLEUM COMPANY Effective Date: 09/26/06  
Case #: 1420H623415 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CADE TAYLOR  
Gravity: 3  
Authority Ref: Abatement Date: 09/26/06  
Corrected Date: 09/26/06  
Followup Date: Extend Date:

Remarks Date: 09/19/06

DRILLING RIG FRONTIER #4 IS CURRENTLY DRILLING WITH A CLOSED SYSTEM WHICH HAS NOT BEEN APPROVED, NOR HAS A SUNDRY BEEN SENT IN FOR APPROVAL. PLEASE SUBMIT A SUNDRY REQUESTING APPROVAL FOR A CLOSED SYSTEM.

Office: VE ID: VE11860  
Unique INC #: JB06001 Well Name: FEDERAL ATCHEE RIDGE  
Well #: 22-13-25 ID Date: 10/24/05  
Operator: PIONEER NATURAL RESOURCES USA Effective Date: 10/24/05  
Case #: UTU79759X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JERRY BARNES  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1(a) Abatement Date: 10/24/05  
Corrected Date: 10/27/05  
Followup Date: Extend Date:

Remarks Date: 10/24/05

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

FAILURE TO CEMENT SURFACE CASING AS PER APD CONDITIONS OF APPROVAL. IT STIPULATED THAT THE TOP 200 FEET OF CASING ANNULUS WOULD BE NEAT CEMENT. THIS WAS NOT DONE

Office: VE ID: VE11862  
Unique INC #: JB06003 Well Name: FEDERAL ATCHEE RIDGE  
Well #: 22-13-25 ID Date: 10/24/05  
Operator: PIONEER NATURAL RESOURCES USA Effective Date: 10/24/05  
Case #: UTU79759X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JERRY BARNES Abatement Date: 10/24/05  
Gravity: 3 Corrected Date: 10/27/05  
Authority Ref: 43 CFR 3164.1, OOGO#2, III..A.2.i,ii Followup Date:  
Remarks Date: 10/24/05 Extend Date:

FAILURE TO MEET MINIMUM EQUIPMENT REQUIREMENTS FOR THE APPROVED 3M BOP. RIG HAS NO ANNULAR PREVENTER.

Office: VE ID: VE11861  
Unique INC #: JB06002 Well Name: FEDERAL ATCHEE RIDGE  
Well #: 22-13-25 ID Date: 10/24/05  
Operator: PIONEER NATURAL RESOURCES USA Effective Date: 10/24/05  
Case #: UTU79759X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JERRY BARNES Abatement Date: 10/24/05  
Gravity: 3 Corrected Date: 10/27/05  
Followup Date:  
Extend Date:  
Authority Ref: 43 CFR 3164.1, OOGO#2, III..A.2.i,ii

Remarks Date: 10/24/05

FAILURE TO TEST BOPE TO THE APPROVED WORKING PRESSURE OF THE APD. BOPE SHALL BE TESTED TO THE APPROVED WORKING PRESSURE IN THE APD.

Office: VE ID: VE11823  
Unique INC #: JPB06024 Well Name: STUMPJUMPER FED  
Well #: 11-23-23-33 ID Date: 03/16/06  
Operator: ENDURING RESOURCES LLC Effective Date: 03/16/06  
Case #: UTU73693 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JOHNNY BOWEN Abatement Date: 03/16/06  
Gravity: 1 Corrected Date: 03/29/06  
Followup Date:  
Extend Date:  
Authority Ref: 43 CFR 3164.1(a)(b), OOGO #2, III A 1

Remarks Date: 03/16/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

IMMEDIATE ASSESSMENT FOR NO BLOWOUT PREVENTER EQUIPMENT ON THIS WELL FROM 3-15-06 TO 3-16-06. WELL HAD NO METHOD OF CONTROL AND WAS AT A DEPTH OF 5746' ASSESSMENT IS FOR 2 DAYS AT \$500/DAY

Office: VE ID: VE11865  
Unique INC #: JPB06029 Well Name: HANGING ROCK  
Well #: 12-24-11-18  
Operator: ENDURING RESOURCES LLC  
Case #: UTU73704 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JOHNNY BOWEN  
Gravity: 3  
Authority Ref: 43CFR 3162.1(a), APD, 10-point plan, COAs  
Remarks Date: 04/03/06  
ACCORDING TO THE APD, SURFACE CASING IS TO BE RANT TO 320'. ACTUAL SURFACE CASING DEPTH WAS 2,134' FIELD OPERTAIONS SHOULD COMPLY WITH THE APD. A PROPOSAL ON FORM 3160-5 SHALL BE SUBMITTED TO AUTHORIZED OFFICER FOR APPROVAL.

Office: VE ID: VE11866  
Unique INC #: JPB06030 Well Name: HANGING ROCK  
Well #: 12-24-11-18  
Operator: ENDURING RESOURCES LLC  
Case #: UTU73704 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JOHNNY BOWEN  
Gravity: 3  
Authority Ref: 43CFR 3162.1(a), APD, 10-point plan, COAs  
Remarks Date: 04/03/06  
APD REQUIRES 9-5/8" 32.3# H-40 CASING. ACTUAL CASING USED WAS 8-5/8" 24# J-55 CASING. A PROPOSAL ON FORM 3160-5 SHALL BE SUBMITTED TO THE AUTHORIZED OFFICER FOR APPROVAL.

Office: VE ID: VE11828  
Unique INC #: JPB06040 Well Name: ARCHY BENCH  
Well #: 11-22-21-1  
Operator: ENDURING RESOURCES LLC  
Case #: UTU73903 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JOHNNY BOWEN  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a), COAS  
Remarks Date: 06/01/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

NOTIFY THE AUTHORIZED OFFICER 48 HOURS PRIOR TO SURFACE DISTURBING ACTIVITIES

Office: VE ID: VE11827  
Unique INC #: JPB06039 Well Name: ARCHY BENCH  
Well #: 11-22-21-1  
Operator: ENDURING RESOURCES LLC  
Case #: UTU73903 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JOHNNY BOWEN  
Gravity: 3  
Authority Ref: 43 CFR 3164.1(a)(b), OOGO #1, III.G.3.f  
Remarks Date: 06/01/06

A COPY OF THE APPROVED FORM 3160-3 WILL BE AVAILABLE ON LOCATION DURING DRILLING, CONSTRUCTION AND COMPLETION OPERATIONS.

Office: VE ID: VE11580  
Unique INC #: JPB06022 Well Name: BIG PACK  
Well #: 11-21-11-28  
Operator: ENDURING RESOURCES LLC  
Case #: UTU75099 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JOHNNY BOWEN  
Gravity: 1  
Authority Ref: 43CFR3164.1(a)(b) OOGO #2, III.A.2.a.ii  
Remarks Date: 01/24/06

CHOKE LINE INSIDE DIAMETER IS TO SMALL, THE ENTIRE CHOKE LINE NEEDS TO BE 3" INSIDE DIAMETER AND BE FLANGED, WELDED OR CLAMPED. PLEASE INSTALL PROPER CHOKE LINE TO ONSHORE ORDER #2 SPECIFICATIONS.

Office: VE ID: IVF11772  
Unique INC #: CRB06031 Well Name: UTE TRIBAL  
Well #: 11-25-56  
Operator: FIML NATURAL RESOURCES, LLC  
Case #: 1420H625065 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: RANDY BYWATER  
Gravity: 3  
Authority Ref:

Remarks Date: 09/12/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

EVERY WELL ON INDIAN OR FEDERAL LEASE AGREEMENTS SHALL HAVE A WELL IDENTIFICATION SIGN. ALL SIGNS SHALL BE MAINTAINED IN A LEGIBLE CONDITION, AND HAVE ALL REQUIRED INFORMATION.

Office: VE ID: iVE11771  
Unique INC #: CRB06030 Well Name: UTE TRIBAL  
Well #: 11-25-56 ID Date: 09/12/06  
Operator: FIML NATURAL RESOURCES, LLC Effective Date: 09/12/06  
Case #: 1420H625065 FAC ID: Abatement Date: 09/12/06  
Form: I FAC NAME: Corrected Date: 09/25/06  
Assessment: \$0 Inspector: RANDY BYWATER Followup Date: 10/21/09  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3164.1(a)

Remarks Date: 09/12/06

APPROVED COPY OF THE APD SHALL BE AT THE DRILLSITE WHENEVER ACTIVE CONSTRUCTION, DRILLING, OR COMPLETION OPERATIONS ARE UNDERWAY.

Office: WO ID: WO2275  
Unique INC #: 06/12/2006 Well Name: SO SPRING CREEK  
Well #: 070 ID Date: 09/15/06  
Operator: MARATHON OIL COMPANY Effective Date: 09/21/06  
Case #: WYW109710A FAC ID: Corrected Date: 09/16/06  
Form: I FAC NAME: Followup Date: 09/21/06  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref:

Remarks Date: 09/15/06

No hand wheels on Choke line valve, Kill line Valve. Corrective action: Install hand wheels by 9/21/2006

Office: WO ID: WO2274  
Unique INC #: 06-OL-11 Well Name: SO SPRING CREEK  
Well #: 070 ID Date: 09/15/06  
Operator: MARATHON OIL COMPANY Effective Date: 09/21/06  
Case #: WYW109710A FAC ID: Abatement Date: 09/21/06  
Form: I FAC NAME: Corrected Date: 09/17/06  
Assessment: \$0 Inspector: LEAR Followup Date: 09/21/06  
Gravity: 3 Extend Date:  
Authority Ref: CFR 3162.1 (a)

Remarks Date: 09/15/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

Failed to Build flare Pit, as stated in APD.

Office: WO	Well Name: SO SPRING CREEK	ID: WO2276
Unique INC #: 06-12-2006	Well #: 070	ID Date: 09/15/06
Operator: MARATHON OIL COMPANY	FAC ID:	Effective Date:
Case #: WYW109710A	FAC NAME:	Abatement Date: 09/21/06
Form: I	Inspector: LEAR	Corrected Date: 09/17/06
Assessment: \$0		Followup Date: 09/21/06
Gravity: 1		Extend Date:
Authority Ref:		

Remarks Date: 09/15/06

No Flare line to Flare Pit. Corrective action: Install Flare line by 9/21/2006

Office: WO	Well Name: SO SPRING CREEK	ID: WO2273
Unique INC #: 06-OL-10	Well #: 070	ID Date: 09/15/06
Operator: MARATHON OIL COMPANY	FAC ID:	Effective Date: 09/20/06
Case #: WYW109710A	FAC NAME:	Abatement Date: 09/21/06
Form: I	Inspector: LEAR	Corrected Date: 09/16/06
Assessment: \$0		Followup Date: 09/21/06
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 00. III.A. g.		

Remarks Date: 09/15/06

Manual locking device (i.e., handd wheels) not on BOP Corrective action: Install hand wheels by 9/21/2006

Office: WO	Well Name: EASTERN REACH	ID: WO2278
Unique INC #: 06KO08	Well #: 28-1	ID Date: 09/14/06
Operator: CONTINENTAL RESOURCES INC	FAC ID:	Effective Date: 09/14/06
Case #: WYW140332	FAC NAME:	Abatement Date: 09/18/06
Form: I	Inspector: LEAR/OLNEY	Corrected Date: 09/18/06
Assessment: \$0		Followup Date: 09/18/06
Gravity: 3		Extend Date:
Authority Ref: OO#2.III.A.2.g.		

Remarks Date: 09/14/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

During Health & Safety inspection found missing manual choke handle.

Office: WO ID: WO2279  
Unique INC #: 06KO09 Well Name: EASTERN REACH  
Well #: 28-1  
Operator: CONTINENTAL RESOURCES INC  
Case #: WYW140332 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR/OLNEY  
Gravity: 3  
Authority Ref: OO#2.III.A.2.g.

Remarks Date: 09/14/06

During Health & Safety inspection found missing annular locking device.

Office: WO ID: WO2277  
Unique INC #: 06KO07 Well Name: EASTERN REACH  
Well #: 28-1  
Operator: CONTINENTAL RESOURCES INC  
Case #: WYW140332 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR/OLNEY  
Gravity: 3  
Authority Ref: OO#2.III.A.2.g.

Remarks Date: 09/14/06

During Health & Safety inspection found missing choke line valve handle.

Office: WO ID: WO2271  
Unique INC #: 06KO06 Well Name: EASTERN REACH  
Well #: 28-1  
Operator: CONTINENTAL RESOURCES INC  
Case #: WYW140332 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR/OLNEY  
Gravity: 3  
Authority Ref: OO#2.III.A.2.g.

Remarks Date: 09/14/06

Safety and Drilling Related Violations (INCs) Issued During FY 2006  
As of March 3, 2011

During Health & Safety inspection found missing BOP hand wheels.

Office: WO	Well Name:	ID: WO2213
Unique INC #: 010-06-002	Well #: 34-43	ID Date: 10/12/05
Operator: BASIN RESOURCES CORPORATION	FAC ID:	Effective Date: 10/12/05
Case #: WYW144103	FAC NAME:	Abatement Date: 10/13/05
Form: I	Inspector: SWICK	Corrected Date: 10/13/05
Assessment: \$0		Followup Date: 10/13/05
Gravity: 1		Extend Date:
Authority Ref: 43CFR 3164.1 O.O. #2 III. B.		

Remarks Date: 10/12/05

Basin Resource had changed surface casing size without prior approval. From 9 5/8", 40# to 8 5/8", 24#.

Office: WO	Well Name:	ID: WO2212
Unique INC #: 010-06-001	Well #: 34-43	ID Date: 10/12/05
Operator: BASIN RESOURCES CORPORATION	FAC ID:	Effective Date: 10/12/05
Case #: WYW144103	FAC NAME:	Abatement Date: 10/13/05
Form: I	Inspector: SWICK	Corrected Date: 10/13/05
Assessment: \$0		Followup Date: 10/13/05
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3164.1 O.O. #1 III. G.3.f.		

Remarks Date: 10/12/05

Basin Resource had no Approved APD on location at the time of cement surface casing in well.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BA ID: BA2064  
Unique INC #: 03-005-05I Well Name: SEC 20 ID Date: 05/24/05  
Well #: 1236 Effective Date: 05/25/05  
Operator: MACPHERSON OIL COMPANY Abatement Date: 05/26/05  
Case #: CACA34219X FAC ID: Corrected Date: 05/24/05  
Form: I FAC NAME: Followup Date: 05/24/05  
Assessment: \$0 Inspector: 3 SPARKS R Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3163.1

Remarks Date: 05/24/05

6" (MINIMUM ID) DIVERTER LINE MUST NOT HAVE ANY INTERNAL RESTRICTIONS OR TURNS. DIVERTER ON CAZA RIG 507 HAD A 90 DEGREE TURN.

Office: BA ID: BA2065  
Unique INC #: 03-006-05I Well Name: SEC 20 ID Date: 05/24/05  
Well #: 1236 Effective Date: 05/25/05  
Operator: MACPHERSON OIL COMPANY Abatement Date: 05/26/05  
Case #: CACA34219X FAC ID: Corrected Date: 05/26/05  
Form: I FAC NAME: Followup Date: 05/27/05  
Assessment: \$0 Inspector: 3 SPARKS R Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3163.1

Remarks Date: 05/24/05

REMOTE CONTROLS SHALL BE CAPABLE OF CLOSING AND OPENING THE ANNULAR PREVENTER AND OPENING THE HYDRAULICALLY CONTROLLED VALVE. REMOTE CONTROLS ON CAZA RIG 509 WERE CAPABLE OF FUNCTION TESTING.

Office: BA ID: BA1937  
Unique INC #: 05-002-05I Well Name: USL ID Date: 10/21/04  
Well #: T.O. 2 Effective Date: 11/13/04  
Operator: TEXACO EXPLORATION & PROD INC Abatement Date: 12/03/04  
Case #: CAS037494 FAC ID: Corrected Date: 12/03/04  
Form: I FAC NAME: Followup Date: 12/04/04  
Assessment: \$0 Inspector: 5 SPARKS R Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a)

Remarks Date: 10/25/04

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

You have failed to give 24 hour notice prior to spudding USL TO-2. According to your APD's "General Conditions of Approval," Section 3 -- "Notice shall be given to the BLM, a minimum of 24 hours prior to commencing drilling/completion/recompletion/abandonment operations. Please send a letter describing how this problem will be corrected in future.

Office: BU		ID: BU8079
Unique INC #: MB-05-06	Well Name: JEFFERS DRAW THRONE	
	Well #: 7-11WA	
Operator: PRIMA OIL & GAS CO		
Case #: WYW146800	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 12/14/04

You have failed to identify the drill site. You must properly identify the drill site.

Office: BU		ID: BU8043
Unique INC #: MB-05-02	Well Name: HIGHLAND UNIT HU FED	
	Well #: 14-22	
Operator: LANCE OIL + GAS CO INC		
Case #: WYW151581X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: COA's		

Remarks Date: 11/30/04

You have failed to comply with the COA's, in having a 30' non-flammable blooie line. You must comply with the COA's by installing a 30' non-flammable blooie line.

Office: BU		ID: BU8056
Unique INC #: MB-05-03	Well Name: HIGHLAND UNIT HU FED	
	Well #: 14-22	
Operator: LANCE OIL + GAS CO INC		
Case #: WYW151581X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: Site Specific COA's		

Remarks Date: 12/06/04

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

You have failed to line the reserve pits on this location per Site Specific COA;s. You must line pits that are required to be lined. You must submit documentation to this office as to why these conditions were not met.

Office: BU		ID: BU8042
Unique INC #: MB-05-01	Well Name: COAL GULCH U CGU FED	
	Well #: 13-27	
Operator: LANCE OIL + GAS CO INC		
Case #: WYW152950X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 3		
Authority Ref: COA's		

Remarks Date: 11/30/04

You have failed to meet the COA's requirement for a 30' non-flammable blooie line. You must comply with the COA's and install a 30' non-falmmable blooie line.

Office: BU		ID: BU8156
Unique INC #: MB-05-08	Well Name: MONTGOMERY DRAW YONKEE	
	Well #: 34-41WA	
Operator: PETRO-CANADA RES (USA) INC		
Case #: WYW31336	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BLAKESLEY	
Gravity: 1		
Authority Ref: Site specific COA's		

Remarks Date: 01/31/05

You have failed to line the drilling pits as specified in the Site Specific COA's. (COA 2.3.3---#12). You must submit a letter to the Buffalo Field Office within 10 days. The letter must contain the reasons why this happened, how this happened, and what will be done in the future to make sure this incident is not repeated .

Office: BU		ID: BU7995
Unique INC #: KB05002	Well Name: N PLEASANTVILLE I D MANKIN	
	Well #: 43-35	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: WYW32227	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$500	Inspector: BRUS	
Gravity: 3		
Authority Ref: 43CFR3162.3-1(c)		

Remarks Date: 11/04/04

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Received a Sundry from Williams for the relocation of this well August 13, 2004. The sundry was received by the NRS 8-16-04. The company was notified that more information was required (ie map, cultural survey, etc.) 08-23-04. A new map was received in the office 08-26-04. The LIE noted Williams would require an exception location for the move. On 9-20-04, the LIE reported that the WOGCC approved the exception location for footages that did not agree with the footages on the location change sundry or well plat. The operator reported the well spudding 9-28-04. According to the Williams drilling foreman, Rex Lynde, BFO PET and NRS were on site in July to relocated the well. However, the sundry has not been approved as of today. The exception location approval from the WOGCC will have to be amended to the correct footages. I visited the location 11-2-04. The well was drilled - wellhead installed and the pit still open and fenced.

Office: BU		ID: BU8159
Unique INC #: LMF05-36I	Well Name: CDU	
	Well #: 140	ID Date: 02/02/05
Operator: MERITAGE ENERGY PARTNERS LLC		Effective Date: 02/02/05
Case #: 8910210760	FAC ID:	Abatement Date: 02/03/05
Form: I	FAC NAME:	Corrected Date: 02/03/05
Assessment: \$0	Inspector: FOX	Followup Date: 02/03/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 2 III.A.1.		

Remarks Date: 02/02/05

During a rig inspection on 2/2/05, it was discovered that the flare line and the off-side choke line were disconnected. The drilling crew was drilling at 3324 feet. This is in violation of Onshore Order 2 in that drilling had commenced without the approved BOPE installed. Ben Stromberge of Meritage Energy Partners LLC was contacted by telephone at 12:45. He was given notice that said violation needed to be corrected within twenty-four hours. Corrective action: install BOPE as required by Onshore Order 2. Please direct questions to Lisa-Marrie Fox at (307) 684-1052.

Office: BU		ID: BU7934
Unique INC #: MH0501	Well Name: WEST RECLUSE FED	
	Well #: 11-8W	ID Date: 10/04/04
Operator: NORTH FINN, LLC		Effective Date: 10/04/04
Case #: WYW129531	FAC ID:	Abatement Date: 10/11/04
Form: I	FAC NAME:	Corrected Date: 10/12/04
Assessment: \$0	Inspector: HAINES	Followup Date: 10/14/04
Gravity: 1		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 10/04/04

During a field inspection on 10/4/04 it was found that a 30' Blooie line was not being used. This is violation of the Conditions of Approval. You shall install and use a 30' Blooie Line. Failure to use the proper length of Blooie Line will lead to an immediate shut down of drilling operations. If there are any questions contact Mark Haines at 307 - 684 - 1065 or Lee Greaves at 307 - 684 - 1152.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BU		ID: BU7971
Unique INC #: MH0503	Well Name: PETROX BIG GEORGE	
	Well #: 7-6	ID Date: 10/19/04
Operator: PETROX RESOURCES INC		Effective Date: 10/19/04
Case #: WYW145623	FAC ID:	Abatement Date: 11/16/04
Form: I	FAC NAME:	Corrected Date: 10/20/04
Assessment: \$0	Inspector: HAINES	Followup Date: 10/21/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)(b)		

Remarks Date: 10/20/04

During a field inspection on 19/19/2004, it was found that a well sign was not installed. You shall install a well sign within 20 Days. If there are any question contact Mark Haines at 307-684-1065 or Rafael Navarette at 307-684-1165.

Office: BU		ID: BU7972
Unique INC #: MH0504	Well Name: PETROX BIG GEORGE	
	Well #: 7-6	ID Date: 10/19/04
Operator: PETROX RESOURCES INC		Effective Date: 10/19/04
Case #: WYW145623	FAC ID:	Abatement Date: 10/20/04
Form: I	FAC NAME:	Corrected Date: 10/19/04
Assessment: \$0	Inspector: HAINES	Followup Date: 10/20/04
Gravity: 1		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 10/20/04

On 10/19/2004 during a field inspection, it was found that a 30' Blooie Line was not being used. This is a violation of the Conditons of Approval. You shall install and use a 30' Blooie Line to the inside of the pit whenever drilling out from under the surface casing. Failure to do this will lead to an immediate assessment and shut down of all drilling operations. If there are any questions contact Mark Haines at 307-684-1065 or Rafeal Navarrette. ( Company Rep was contacted on 10/19/04)

Office: BU		ID: BU9050
Unique INC #: MH0556	Well Name: PETROX BIG GEORGE ADD	
	Well #: 2-1	ID Date: 08/18/05
Operator: PETROX RESOURCES INC		Effective Date: 08/18/05
Case #: WYW145623	FAC ID:	Abatement Date: 08/19/05
Form: I	FAC NAME:	Corrected Date: 08/19/05
Assessment: \$0	Inspector: HAINES	Followup Date: 08/19/05
Gravity: 1		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 08/18/05

The rig was drilling with a PVC pipe flowline. The conditons of approval state they must use a flowline constructed of a non-flammable material. It was also not 30' in length.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BU		ID: BU8941
Unique INC #: MH0558	Well Name: CCU CAT CREEK FEDERAL	
	Well #: 32-20	ID Date: 08/08/05
Operator: BILL BARRETT CORPORATION		Effective Date: 08/08/05
Case #: WYW152373X	FAC ID:	Abatement Date: 08/09/05
Form: I	FAC NAME:	Corrected Date: 08/08/05
Assessment: \$0	Inspector: HAINES	Followup Date: 08/09/05
Gravity: 1		Extend Date:
Authority Ref: Conditions of Approval		

Remarks Date: 08/08/05

On a field inspection it was found that the flowline was not 30' from the well bore. You shall install a 30' flowline within 24 hours.

Office: BU		ID: BU7969
Unique INC #: RN-05-1	Well Name: WEST RECLUSE FED	
	Well #: 12-9W	ID Date: 10/13/04
Operator: NORTH FINN, LLC		Effective Date: 10/13/04
Case #: WYW129531	FAC ID:	Abatement Date: 10/13/04
Form: I	FAC NAME:	Corrected Date: 10/13/04
Assessment: \$500	Inspector: NAVARRETTE	Followup Date: 10/13/04
Gravity: 1		Extend Date:
Authority Ref: Onshore Order #2		

Remarks Date: 10/13/04

During a field inspection on 10/13/04 it was found that the diverter head was on the well but no rubber was in the head . You have failed to comply with the Condition of Approval. You must install the diverter that is in working order. Failure to do so will be an immediate shut in of all operations within this POD (WEST RECLUSE) and incur assessment of \$500.00 per day from the day of drilling out the shoe. The rubbers were installed while the inspector was on location.

Office: BU		ID: BU8060
Unique INC #: RN-05-22	Well Name: MONTGOMERY DRAW FLOYD	
	Well #: 24-41WA	ID Date: 12/07/04
Operator: PRIMA OIL & GAS CO		Effective Date: 12/07/04
Case #: WYW131736	FAC ID:	Abatement Date: 01/03/05
Form: I	FAC NAME:	Corrected Date: 01/10/05
Assessment: \$0	Inspector: NAVARRETTE	Followup Date: 01/10/05
Gravity: 3		Extend Date:
Authority Ref: 43 CFR3162.5-1(b)		

Remarks Date: 12/08/04

Drill cutting and drilling foam were blown out the back of the pit and down the hill. You must clean up all the contaminated soils

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BU		ID: BU9171
Unique INC #: RN-05-168	Well Name: SLPU FED	
	Well #: 14-8H	ID Date: 08/30/05
Operator: MEDICINE BOW OPERATING CO		Effective Date: 08/30/05
Case #: WYW142812	FAC ID:	Abatement Date: 08/31/05
Form: I	FAC NAME:	Corrected Date: 09/01/05
Assessment: \$5,000	Inspector: NAVARRETTE	Followup Date: 09/01/05
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3164.1 OO#2.III.2.a.III		

Remarks Date: 09/29/05

Blow out preventer (BOP) and related equipment(BOPE) shall be installed, maintained , and tested in a manner necessary to insure well control and shall be in operational prior to drilling the surface casing shoe. Specifically: You failed to install and maintain kill line on BOP, and you failed to install the remote control.

Office: BU		ID: BU9170
Unique INC #: RN-05-171	Well Name: SLPU FED	
	Well #: 14-32H	ID Date: 08/30/05
Operator: MEDICINE BOW OPERATING CO		Effective Date: 08/31/05
Case #: WYW144513	FAC ID:	Abatement Date: 08/31/05
Form: I	FAC NAME:	Corrected Date: 08/31/05
Assessment: \$2,000	Inspector: NAVARRETTE	Followup Date: 08/31/05
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3164.1		

Remarks Date: 09/29/05

You have failed to install and maintain remote control. You must install the remote control and maintain it in working order per Oshore Order # 2 III.(h) remote control shall be readily accessible to the driller. Remote control for all 3M or graeter system shall be capable of closing all preventers.

Office: BU		ID: BU8006
Unique INC #: RN-05-2	Well Name: PETROX BIG GEORGE	
	Well #: 22-10	ID Date: 11/09/04
Operator: PETROX RESOURCES INC		Effective Date: 11/09/04
Case #: WYW145623	FAC ID:	Abatement Date: 11/16/04
Form: I	FAC NAME:	Corrected Date: 11/17/04
Assessment: \$0	Inspector: NAVARRETTE	Followup Date: 11/17/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 11/09/04

You have failed to maintain the well identification that was on a cardboard box in a legible condition. You must maintain all well identification in a legible condition

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BU ID: BU8007  
Unique INC #: RN-05-3 Well Name: PETROX BIG GEORGE ID Date: 11/09/04  
Well #: 22-10 Effective Date: 11/09/04  
Operator: PETROX RESOURCES INC Abatement Date: 11/16/04  
Case #: WYW145623 FAC ID: Corrected Date: 11/17/04  
Form: I FAC NAME: Followup Date: 11/17/04  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.5-1(b)

Remarks Date: 11/09/04

You failed to report the spill of drill cuttings and foam out the back of the pit . You must clean up this spill by removing all contaminated soils.

Office: BU ID: BU8014  
Unique INC #: RN-05-10 Well Name: PETROX BIG GEORGE ID Date: 11/16/04  
Well #: 5-3 Effective Date: 11/16/04  
Operator: PETROX RESOURCES INC Abatement Date: 11/22/04  
Case #: WYW145623 FAC ID: Corrected Date: 12/02/04  
Form: I FAC NAME: Followup Date: 12/02/04  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a) & condition of Approval

Remarks Date: 11/16/04

The casing is leaking thru the cement. You must log this well and repair the leaking of gas and water. You are required to call Rafael Navarrette at 307-684-1165, three hours before running any logs or cement.

Office: BU ID: BU8013  
Unique INC #: RN-05-9 Well Name: PETROX BIG GEORGE ID Date: 11/15/04  
Well #: 7-6 Effective Date: 11/15/04  
Operator: PETROX RESOURCES INC Abatement Date: 11/22/04  
Case #: WYW145623 FAC ID: Corrected Date: 11/30/04  
Form: I FAC NAME: Followup Date: 11/30/04  
Assessment: \$0 Inspector: NAVARRETTE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a) & condition of approval

Remarks Date: 11/16/04

You have failed to comply with the conditions of approval for cementing of casing. You must log this well and do the remedial cement. You are required to call Rafael Navarrette at 307-684-1165, three hours before running any logs or cement.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BU		ID: BU9104
Unique INC #: SAM40-05	Well Name: ALL NIGHT CK V TURNER	ID Date: 07/25/05
	Well #: 12-18	Effective Date: 07/25/05
Operator: WILLIAMS PRODUCTION RMT CO		Abatement Date: 07/25/05
Case #: WYW130590	FAC ID:	Corrected Date: 07/25/05
Form: I	FAC NAME:	Followup Date:
Assessment: \$0	Inspector: SHEPPARD	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.1/COAs		

Remarks Date: 07/25/05

Failed to report spud date 24 hours prior to spud according to the Conditions of approval. Corrective Action: All future spud dates must be reported 24 hours prior to spuds.

Office: BU		ID: BU8048
Unique INC #: JW05-11-I	Well Name: MUSTANG II POD	ID Date: 12/01/04
	Well #: 41-5WA	Effective Date: 12/01/04
Operator: CH4 ENERGY LLC		Abatement Date: 01/06/05
Case #: WYW129023	FAC ID:	Corrected Date: 12/10/04
Form: I	FAC NAME:	Followup Date: 12/14/04
Assessment: \$0	Inspector: WALKER	Extend Date:
Gravity: 3		
Authority Ref: 43CFR3162.6(b)		

Remarks Date: 12/01/04

Follow-up inspection of drilling location shows that well 41-5WA does not have a well sign. 43CFR3162.6(b) requires all federal wells be identified from the time they are spudded until they are permanently abandon. Corrective Action: Please install a permanent sign at well 41-5WA showing operator name, well name and number, Federal lease number and surveyed legal description. If you have any question call Jerry Walker at 307-684-1167. Thank you

Office: BU		ID: BU8424
Unique INC #: JW05-63-I	Well Name: SLPU FED	ID Date: 04/06/05
	Well #: 14-21H	Effective Date: 04/06/05
Operator: MEDICINE BOW OPERATING CO		Abatement Date: 04/07/05
Case #: WYW138435	FAC ID:	Corrected Date: 04/08/05
Form: I	FAC NAME:	Followup Date: 04/08/05
Assessment: \$0	Inspector: WALKER	Extend Date:
Gravity: 3		
Authority Ref: Onshore Order No.2,III,A,2,a		

Remarks Date: 04/06/05

On April 6, 2005, conducted drilling inspection of Federal well 14-21H. The kill side of the BOP stack did not have a kill line installed. The kill line was not available to be hooked up. Talked with Toolpusher about installing kill line. Corrective Action: The kill line must be installed at all times during drilling operations.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BU		ID: BU8425
Unique INC #: JW05-64-I	Well Name: SLPU FED	
	Well #: 14-21H	ID Date: 04/06/05
Operator: MEDICINE BOW OPERATING CO		Effective Date: 04/06/05
Case #: WYW138435	FAC ID:	Abatement Date: 04/07/05
Form: I	FAC NAME:	Corrected Date: 04/08/05
Assessment: \$0	Inspector: WALKER	Followup Date: 04/08/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Order No.2,III,A,2,a		

Remarks Date: 04/06/05

On April 6, 2005, conducted drilling inspection of Federal well 14-21H. The outside valve on the choke side of the BOP does not have a handle on it. Talked with Toolpusher about installing a handle on valve. Corrective Action: All valves on the BOP must have handles and be easy to operate during drilling operations.

Office: BU		ID: BU8423
Unique INC #: JW05-62-I	Well Name: SLPU FED	
	Well #: 14-21H	ID Date: 04/06/05
Operator: MEDICINE BOW OPERATING CO		Effective Date: 04/06/05
Case #: WYW138435	FAC ID:	Abatement Date: 04/22/05
Form: I	FAC NAME:	Corrected Date: 04/26/05
Assessment: \$0	Inspector: WALKER	Followup Date: 05/02/05
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.6(b)		

Remarks Date: 04/06/05

On April 6, 2005, conducted drilling inspection of Federal well 14-21H. Well does not have a well sign. 43CFR3162.6(b) requires a well to be identified from the day it is spudded until it is permanently abandon. Corrective Action: Please install a well sign showing Operator name, well name and number, Federal lease number and surveyed legal description. If you have any questions, please call Jerry Walker at 307-684-1167. Thank you

Office: BU		ID: BU8797
Unique INC #: JW05-81-I	Well Name: MUMMA DRAW WC FED	
	Well #: 09CW-23	ID Date: 05/25/05
Operator: CH4 ENERGY LLC		Effective Date: 05/25/05
Case #: WYW144496	FAC ID:	Abatement Date: 05/25/05
Form: I	FAC NAME:	Corrected Date: 05/25/05
Assessment: \$0	Inspector: WALKER	Followup Date: 05/25/05
Gravity: 3		Extend Date:
Authority Ref: COA's		

Remarks Date: 05/25/05

Drilling inspection of Well 43-23-5373CW shows that the nearest edge of the drilling pit is 18 feet from The well bore. BLM requires the nearest edge of the pit to be a minimum of 30 feet from the well bore. Corrective Action: In the future the nearest edge of all drilling pits shall be a minimum of 30 feet from the wellbore. Pits at wells 32-23 and 41-23 (already dug) will be allowed to be used as is to prevent additional surface disturbance

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: BU		ID: BU8796
Unique INC #: JW05-82-I	Well Name: MUMMA DRAW WC FED	
	Well #: 09CW-23	ID Date: 05/25/05
Operator: CH4 ENERGY LLC		Effective Date: 05/25/05
Case #: WYW144496	FAC ID:	Abatement Date: 05/25/05
Form: I	FAC NAME:	Corrected Date: 05/25/05
Assessment: \$0	Inspector: WALKER	Followup Date: 05/25/05
Gravity: 3		Extend Date:
Authority Ref: COA's		

Remarks Date: 05/25/05

Drilling inspection of Well 43-23-5373CW shows that the drilling pit was not fenced. BLM requires that drilling pits be fenced during drilling operations and after until pit is closed. Corrective Action: A Roustabout crew arrived and put up fence around drilling pit. In the future, Please Ensure that drilling pits are properly fenced during and after drilling operations. Thank you

Office: BU		ID: BU8022
Unique INC #: JW05-10-I	Well Name: MUSTANG M ODEGARD	
	Well #: 27ACKWA-3	ID Date: 11/16/04
Operator: DEVON ENERGY PRODUCTION CO, LP		Effective Date: 11/16/04
Case #: WYW3106	FAC ID:	Abatement Date: 12/22/04
Form: I	FAC NAME:	Corrected Date: 11/30/04
Assessment: \$0	Inspector: WALKER	Followup Date: 12/02/04
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.6(b)		

Remarks Date: 11/16/04

Inspection of location shows that well 27K-3 does not have a well sign. 43 CFR 3162.6 requires all Federal wells to have an identification sign from the time they are spudded until they are permanently abandon. Corrective Action: Install a sign that displays operator name, well name and number federal lease number and location. Thank you

Office: CA		ID: CA2221
Unique INC #: L05-15	Well Name:	
	Well #:	ID Date: 12/10/04
Operator: BREITBURN ENERGY COMPANY LLC		Effective Date: 12/22/04
Case #: WYW146610A	FAC ID: A	Abatement Date: 01/15/05
Form: I	FAC NAME: LOST DOME	Corrected Date: 12/21/04
Assessment: \$0	Inspector: LONG	Followup Date: 12/27/04
Gravity: 3		Extend Date:
Authority Ref: Onshore Oil & Gas Order No. 6,III,D,2,b.		

Remarks Date: 12/10/04

Stairs leading to top of oil tanks must be chained to restrict entry. Please install access restricting device(s) within above abatement period. (1/15/2005). Chain or gate should also be marked with hazard warning.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: CB ID: CB18043  
 Unique INC #: 04-JA-115 Well Name: WERSELL FEDERAL ID Date: 09/07/04  
 Well #: 2 Effective Date:  
 Operator: CIMAREX ENERGY CO Abatement Date: 10/07/04  
 Case #: NMNM0454018 FAC ID: Corrected Date: 10/15/04  
 Form: I FAC NAME: Followup Date: 10/15/04  
 Assessment: \$0 Inspector: AMOS Extend Date:  
 Gravity: 3  
 Authority Ref: ONSHORE ORDER 6.III.D.3.a,b, & c  
 Remarks Date: 09/07/04

THE ABOVE REFERENCED WELL DOES NOT MEET THE REQUIREMENTS OF ONSHORE ORDER. INSTALL H2S WARNING SIGN AT THE ENTRANCE TO WELL. LOCATION IS FENCED, FENCE IS DOWN IN A COUPLE OF AREAS. REPAIR FENCING. WATER DISPOSAL LINE CROSSING UNDER THE STATE HIGHWAY. SINAGE REQUIRED ON BOTH SIDES OF ROADWAY SHOWING H2S AND RESPONSIBLE PARTY, CONTACTS. COMPLY WITH REQUIREMENTS.

Office: CB ID: CB18175  
 Unique INC #: 05-JA-013 Well Name: ID Date: 10/29/04  
 Well #: Effective Date:  
 Operator: SOUTHWEST ROYALTIES INC Abatement Date: 12/02/04  
 Case #: NMNM14768B FAC ID: A Corrected Date: 12/28/04  
 Form: I FAC NAME: WILDERSPIN Followup Date: 12/28/04  
 Assessment: \$0 Inspector: AMOS Extend Date:  
 Gravity: 3  
 Authority Ref: ONSHORE ORDER 6.III.A.2.b  
 Remarks Date: 10/29/04

H2S CONCENTRATION EXCEEDS 100 PPM. OPERATOR REQUIRED TO SUBMIT H2S CONCENTRATION. IF GREATER THAN 100 PPM IN THE GAS STREAM A RADII OF EXPOSURE IS TO BE SUBMITTED FOR BOTH 100 PPM AND 500 PPM. SUBMIT CONCENTRATION AND R0E IF REQUIRED. INSTALL WARNING SIGNS AT FACILITY TO INCLUDE WINDSOCK.

Office: CB ID: CB18190  
 Unique INC #: 05-JA-020 Well Name: ID Date: 11/09/04  
 Well #: Effective Date:  
 Operator: VINTAGE DRILLING, L.L.C. Abatement Date: 12/09/04  
 Case #: NMNM71024X FAC ID: A, B Corrected Date: 12/29/04  
 Form: I FAC NAME: RJU CTB, RJU INJ PLANT Followup Date: 12/29/04  
 Assessment: \$0 Inspector: AMOS Extend Date:  
 Gravity: 3  
 Authority Ref: ONSHORE ORDER 6.III.A.2.b  
 Remarks Date: 11/09/04

PULLED H2S SAMPLE FROM GAS STREAM. SIGNIFICANT AMOUNT H2S, MAXED SAMPLE TUBE. TEST THE H2S CONCENTRATION OF THE GAS STREAM AND OIL STORAGE TANK (STV) FOR THE CENTRAL TANK BATTERY AND PROVIDE THE RESULTS TO THIS OFFICE. SUBMIT RADII OF EXPOSURE IF CONCENTRATION WARRANTS. INSTALL WINDSOCKS AT BOTH FACILITIES. H2S WARNING SIGNS NEED TO BE MAINTAINED, NO LONGER LEGIBLE FROM ANY DISTANCE.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: CB		ID: CB18563
Unique INC #: 05-DC-282	Well Name: MARINE 19 FEDERAL	
	Well #: 1	ID Date: 08/17/05
Operator: LATIGO PETROLEUM INC		Effective Date: 08/17/05
Case #: NMNM109756	FAC ID:	Abatement Date: 08/17/05
Form: I	FAC NAME:	Corrected Date: 08/18/05
Assessment: \$0	Inspector: CLEGHORN	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a), ONSHORE ORDER 2, III,A,2,g		

Remarks Date: 08/17/05

FAILURE TO COMPLY WITH ONSHORE ORDERS. FAILURE TO INSTALL A VALVE IN THE CLOSING LINE AS CLOSE AS POSSIBLE TO THE ANNULAR PREVENTER TO ACT AS A LOCKING DEVICE DURING DRILLING OPERATIONS. INSTALL VALVE ON ANNULAR PER ONSHORE ORDERS.

Office: CB		ID: CB18562
Unique INC #: 05-DC-281	Well Name: MARINE 19 FEDERAL	
	Well #: 1	ID Date: 08/17/05
Operator: LATIGO PETROLEUM INC		Effective Date: 08/17/05
Case #: NMNM109756	FAC ID:	Abatement Date: 08/17/05
Form: I	FAC NAME:	Corrected Date: 08/18/05
Assessment: \$0	Inspector: CLEGHORN	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a), APD COA'S		

Remarks Date: 08/17/05

FAILURE TO COMPLY WITH CONDITIONS OF APPROVAL. FAILURE TO NOTIFY BLM FOR A WELL SPUD, PRIOR TO SETTING CASINGS AND CEMENTING, AND BOP TESTS NOTIFY BLM IN SUFFICIENT TIME FOR A BLM REPRESENTATIVE TO WITNESS WELL SPUDS, PRIOR TO SETTING CASINGS AND CEMENTING, AND BOP TESTS, IN SUFFICIENT TIME FOR A BLM REPRESENTATIVE TO WITNESS. THE ON-CALL TELEPHONE NUMBER IS: 505-361-2822.. IF YOU HAVE ANY QUESTIONS CALL DON CLEGHORN AT 505-234-5906 OR JIM AMOS AT 505-234-5909.

Office: CB		ID: CB18572
Unique INC #: 05-DC-283	Well Name: BURCH KEELY UNIT	
	Well #: 384	ID Date: 08/24/05
Operator: MARBOB ENERGY CORPORATION		Effective Date: 08/24/05
Case #: NMNM88525X	FAC ID:	Abatement Date: 08/25/05
Form: I	FAC NAME:	Corrected Date: 08/25/05
Assessment: \$0	Inspector: CLEGHORN	Followup Date: 08/26/05
Gravity: 3		Extend Date:
Authority Ref: ONSHORE ORDER #2,III,A,2,b,iv		

Remarks Date: 08/24/05

COMMON LIQUID-FILLED PRESSURE GAUGE BEING USED ON CHOKE MANIFOLD--REPLACE PRESSURE GAUGE WITH TYPE DESIGNED FOR DRILLING FLUID SERVICE.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: CB ID: CB18573  
 Unique INC #: 05-DC-284 Well Name: BURCH KEELY UNIT ID Date: 08/24/05  
 Well #: 384 Effective Date: 08/24/05  
 Operator: MARBOB ENERGY CORPORATION Abatement Date: 08/25/05  
 Case #: NMNM88525X FAC ID: Corrected Date: 08/25/05  
 Form: I FAC NAME: Followup Date: 08/25/05  
 Assessment: \$0 Inspector: CLEGHORN Extend Date:  
 Gravity: 3  
 Authority Ref: ONSHORE ORDER #2,III,A,2,g

Remarks Date: 08/24/05

HAND WHEELS NOT ON BOP---INSTALL HAND WHEELS PER ONSHORE ORDERS.

Office: CB ID: CB18265  
 Unique INC #: 04-PS-085 Well Name: FEDERAL COM ID Date: 12/01/04  
 Well #: 2 Effective Date: 12/14/04  
 Operator: CHI OPERATING INCORPORATED Abatement Date: 01/04/05  
 Case #: NMNM0375257A FAC ID: Corrected Date: 01/14/05  
 Form: I FAC NAME: Followup Date: 01/14/05  
 Assessment: \$0 Inspector: SWARTZ Extend Date:  
 Gravity: 3  
 Authority Ref: APD - Conditions of Approvaldw

Remarks Date: 12/01/04

The SPECIAL DRILLING STIPULATIONS requirement to "construct a 3 ft. berm along the north edge of pad to prevent run-off to enter pad from adjacent drainage" has not been met. Construct the berm.

Office: CB ID: CB18263  
 Unique INC #: 04-PS-083 Well Name: FEDERAL COM ID Date: 12/01/04  
 Well #: 2 Effective Date: 12/14/04  
 Operator: CHI OPERATING INCORPORATED Abatement Date: 01/04/05  
 Case #: NMNM0375257A FAC ID: Corrected Date: 12/07/04  
 Form: I FAC NAME: Followup Date: 12/20/04  
 Assessment: \$0 Inspector: SWARTZ Extend Date:  
 Gravity: 3  
 Authority Ref: Onshore Order #1,III.G.3.f.

Remarks Date: 12/01/04

An approved drilling permit and was not on location during inspection of the surface casing cement procedure. Future continuation of this practice will be used to establish a "consistent pattern" as mentioned by 43 CFR 3160.0-5 and 3163.2(a)(b) when linked to other Application for Permit to Drill or Reenter (Condition of Approval) compliance issues. For regulation lookup quotes, see <http://www.nm.blm.gov/>, click Oil & Gas under "Programs", and select "Onshore Oil & Gas Operations". Acknowledge the receipt and knowledge of this documentation by your signature.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: CB		ID: CB18264
Unique INC #: 04-PS-084	Well Name: FEDERAL COM	
	Well #: 2	ID Date: 12/01/04
Operator: CHI OPERATING INCORPORATED		Effective Date: 12/14/04
Case #: NMNM0375257A	FAC ID:	Abatement Date: 01/04/05
Form: I	FAC NAME:	Corrected Date: 12/07/04
Assessment: \$0	Inspector: SWARTZ	Followup Date: 12/09/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 12/01/04

The requirement for a legible well sign installed and maintained in a conspicuous place from the spud date until final abandonment has been violated at the noted site. Install the required sign as per requirements. The following is an example of a satisfactory well sign: BLANK OIL COMPANY SMITH "A" FEDERAL WELL NO. 2 1980'FNL & 660'FEL, SEC 26, T17S, R33E API 30 015 12345 UNIT NO NM-12345 (use the lease NO if not in a UNIT) See regulations @ <http://www.nm.blm.gov/> under Programs click Oil & Gas , then Onshore Oil & Gas Operations.

Office: CB		ID: CB18244
Unique INC #: 04-PS-082	Well Name: PARKWAY DELAWARE UNIT	
	Well #: 306	ID Date: 11/30/04
Operator: ST MARY LAND & EXPLORATION CO		Effective Date: 12/09/04
Case #: NMNM88491X	FAC ID:	Abatement Date: 12/29/04
Form: I	FAC NAME:	Corrected Date: 12/06/04
Assessment: \$0	Inspector: SWARTZ	Followup Date: 12/09/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3160.1.a. , Conditions of Approval		

Remarks Date: 11/30/04

TThe drilling log for well #306 for the dates of 11/17/04 & 11/18/04 indicate that waiting on cement time was inadequate when compared to the approved Application for Permit to Drill or Deepen - Conditions of Approval, R-111-P Potash Area stipulation. This Incident of Noncompliance is for documentation only. It may be used to establish a "consistent pattern" as mentioned by 43 CFR 3160.0-5 and 3163.2(a)(b) if linked to future COA compliance issues. For regulation lookup quotes, see <http://www.nm.blm.gov/> , click Oil & Gas under "Programs", and select "Onshore Oil & Gas Operations". Acknowledge the receipt and knowledge of this documentation by your signature.

Office: CB		ID: CB18302
Unique INC #: 05-DW-005	Well Name: RUGER 31 FEDERAL	
	Well #: 1	ID Date: 12/09/04
Operator: MEWBOURNE OIL COMPANY		Effective Date: 12/09/04
Case #: NMNM13237	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 12/10/04
Assessment: \$0	Inspector: WHITLOCK	Followup Date: 12/10/04
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)/OO #2,III,A,2,h/43CFR3163.1(a)		

Remarks Date: 12/09/04

FAILURE TO COMPLY WITH WRITTEN ORDER 05-DW-005W. AS PER CONVERSATION WITH MICKEY YOUNG 12/9/05 @1500hrs. DRILLING MAY CONTINUE UNTIL YOU REACH A DEPTH OF 500' PRIOR TO REACHING THE TOP OF THE WOLF CAMP FORMATION. AT THAT TIME YOU MUST DO ONE OF THE FOLLOWING. 1) MOVE FLOOR CONTROLS TO THE DRILLING FLOOR AND PLACE READILY ACCESSIBLE TO THE DRILLER OR 2) HAVE A DECISION ON YOUR APPEAL THAT STATES THAT FLOOR CONTROL CAN REMAIN IN PLACE. IF FLOOR CONTROLS ARE MOVED CONTACT THIS OFFICE TO WITNESS TESTING OF CONTROLS. ALSO CONTACT THIS OFFICE WHEN 500' PRIOR TO WOLF CAMP HAS BEEN REACHED.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: FE ID: iFE13108  
Unique INC #: 05GLB001 Well Name: ENGLISH ID Date: 10/13/04  
Well #: 21 Effective Date: 10/22/04  
Operator: MOUNTAIN STATES PETRO CORP Abatement Date: 10/29/04  
Case #: I149IND7180 FAC ID: Corrected Date: 11/01/04  
Form: I FAC NAME: Followup Date: 11/11/04  
Assessment: \$0 Inspector: LESLIE-BOB Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 10/13/04

Upon a follow up inspection of this well, I noticed the area near the green pump jack had eroded from recent rains. If it should rain again, this pump jack may fall over. You must remove this pump jack from said location.

Office: FE ID: iFE13082  
Unique INC #: 70VU002 Well Name: ID Date: 09/21/04  
Well #: Effective Date: 10/05/04  
Operator: STONE ENERGY LLC Abatement Date: 10/15/04  
Case #: 1420603248 FAC ID: 2 Corrected Date: 11/12/04  
Form: I FAC NAME: DESERT CREEK Followup Date:  
Assessment: \$0 Inspector: UENTILLIE Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3162.5-3  
  
Remarks Date: 09/21/04

You must install and maintain at least 1 permanent wind indicator so that wind direction can be easily determined at or approaching the storage tank(s) . Currently there is no wind sock.

Office: GF ID: GF2407  
Unique INC #: AP-1-05 Well Name: FEDERAL ID Date: 09/27/04  
Well #: 2470-3 Effective Date: 09/30/04  
Operator: NOBLE ENERGY INC Abatement Date: 10/12/04  
Case #: MTM68678B FAC ID: Corrected Date: 10/20/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: PARROTT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1(a)  
  
Remarks Date: 09/27/04

Operator failed to notify the BLM Archaeologist prior to well pad or pipeline construction as instructed in the Conditions of Approval, Item 1 dated September 22, 2004. This INC cannot be abated since the well pad has been built and the well has been drilled. However, future failure to notify incidences will result in immediate shut down of any activity until the Condition is met sufficiently to the BLM Authorized Officer.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: GF		ID: GF2416
Unique INC #: AP-8-05	Well Name: MRFU	
	Well #: 1731-1	ID Date: 12/07/04
Operator: DECKER OPERATING COMPANY LLC		Effective Date: 12/22/04
Case #: MTM87569X	FAC ID:	Abatement Date: 01/20/05
Form: I	FAC NAME:	Corrected Date: 03/30/05
Assessment: \$0	Inspector: PARROTT	Followup Date: 02/25/05
Gravity: 3		Extend Date: 03/31/05
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 12/07/04

Operator created a new access road that was not approved in the APD. Operator must conduct a cultural inventory of the access road and submit a report by January 20, 2005. The unapproved access road goes north from the well head to the fence, turns east along the fence line, crosses through a gate and proceeds in a northwesterly direction to Well #831-1.

Office: GR		ID: GR1249
Unique INC #: 053003	Well Name: MARIANNE FEDERAL	
	Well #: 8-1	ID Date: 11/18/04
Operator: FANCHER OIL LLC		Effective Date: 11/19/04
Case #: WYW147921	FAC ID:	Abatement Date: 11/19/04
Form: I	FAC NAME:	Corrected Date: 11/19/04
Assessment: \$0	Inspector: DEVOSS	Followup Date: 11/19/04
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.1.		

Remarks Date: 11/18/04

During a Drilling Inspection performed on 11/15/04 inspector found that the flare lines were not installed as required by regulations. Inspector instructed Steve Barnes to instal equipment as required. A follow up inspection was performed on the 18th and the flare lines were not found to be installed properly. More specifically flare lines did not reach the flare pit. Steve Barnes was instructed to increase flare lines to reach the flare pit.

Office: GR		ID: GR1247
Unique INC #: 053001	Well Name: HALE	
	Well #: 1-13H	ID Date: 11/01/04
Operator: SWEPI LP		Effective Date: 11/05/04
Case #: WYW156257X	FAC ID:	Abatement Date: 11/05/04
Form: I	FAC NAME:	Corrected Date: 11/10/04
Assessment: \$0	Inspector: FICKLIN	Followup Date: 11/17/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1 (a)		

Remarks Date: 11/01/04

The operating rights owner or operator , as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. SWEPI LP dry hole spudded the Hale Fed. #1-13H (WYW 156257X, WYW 133068) with out notifying the Rock Springs Field Office 24 hrs. in advance as per the Conditions of Approval in the APD. The spud date and time will be reported verball to the appropriate BLM Resource Area Office within 24 hours before spudding. Corrective action: Report spud date and time to appropriate BLM Resource Area Office within 24 hours before spudding as per COA's.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: GR ID: GR1214  
Unique INC #: 043095 Well Name: BUTCHERKNIFE ID Date: 08/03/04  
Well #: 1-25 Effective Date: 08/11/04  
Operator: WESTERN NATURAL GAS INC Abatement Date: 08/31/04  
Case #: WYW95320 FAC ID: A Corrected Date: 09/28/05  
Form: I FAC NAME: BUTCHERKNIFE #1-25 Followup Date: 01/13/05  
Assessment: \$0 Inspector: FICKLIN Extend Date:  
Gravity: 3  
Authority Ref: O.O.#6 III.,D.,3.,e.

Remarks Date: 08/03/04

Location does not have a Wind Direction Indicator. Install Wind Direction Indicator as required by Onshore Order #6.

Office: GR ID: GR1237  
Unique INC #: 043115 Well Name: BUTCHERKNIFE ID Date: 09/01/04  
Well #: 1-25 Effective Date: 09/09/04  
Operator: WESTERN NATURAL GAS INC Abatement Date: 09/29/04  
Case #: WYW95320 FAC ID: A Corrected Date: 09/28/05  
Form: I FAC NAME: BUTCHERKNIFE #1-25 Followup Date: 01/13/05  
Assessment: \$250 Inspector: FICKLIN Extend Date:  
Gravity: 3  
Authority Ref: O.O.#6.,III.,D.,3.,e.

Remarks Date: 09/01/04

Location does not have a Wind Direction Indicator. Install Wind Direction Indicator as required by Onshore Oil and Gas Order #6.

Office: GR ID: GR1267  
Unique INC #: 053030 Well Name: FEDERAL ID Date: 09/14/05  
Well #: 1-28 Effective Date: 09/15/05  
Operator: EAST RESOURCES INCORPORATED Abatement Date: 09/15/05  
Case #: WYW163716X FAC ID: Corrected Date: 09/16/05  
Form: I FAC NAME: Followup Date: 09/15/05  
Assessment: \$0 Inspector: MOFFETT Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No.2 III.B.1.i.

Remarks Date: 09/14/05

Violation: A pressure integrity test was not performed as required. Perform required tests as mandated and record in the IADC.Corrective Action: Company rep, Mr. Paul Jones, was notified of the violation. No corrective action could be taken at this time, as several hundred feet of new hole had already been drilled. If recognized earlier, corrective action would have referenced Onshore Order No. 2.III.B.1.i.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: GS		ID: GS5392
Unique INC #: EF05027	Well Name: GMU	
	Well #: 26-14A (J26NW)	ID Date: 03/22/05
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 03/22/05
Case #: COC56608A	FAC ID:	Abatement Date: 03/23/05
Form: I	FAC NAME:	Corrected Date: 03/22/05
Assessment: \$0	Inspector: FANCHER	Followup Date: 03/23/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Order No. 2, III. A. 1. and 2. b. ii.		

Remarks Date: 03/22/05

A. Well Control Requirements 1. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). (2) Where noncompliance involves a minor violation, the authorized officer may subject the operating rights owner or operator, as appropriate, to an assessment of \$250 for failure to abate the violation or correct the default within the time allowed; ii. Choke manifold equipment configuration shall be functionally equivalent to the appropriate example diagram shown in Attachment 1 of this Order. In this case there was not a 3" choke line ran out to the pit.

Office: GS		ID: GS5393
Unique INC #: EF05028	Well Name: GMU	
	Well #: 26-14A (J26NW)	ID Date: 03/22/05
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 03/22/05
Case #: COC56608A	FAC ID:	Abatement Date: 03/23/05
Form: I	FAC NAME:	Corrected Date: 03/23/05
Assessment: \$0	Inspector: FANCHER	Followup Date: 03/23/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Order No. 2, III. A. 1. and 2. g.		

Remarks Date: 03/22/05

A. Well Control Requirements 1. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). (2) Where noncompliance involves a minor violation, the authorized officer may subject the operating rights owner or operator, as appropriate, to an assessment of \$250 for failure to abate the violation or correct the default within the time allowed; g. Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative. In this case the hand wheels on one side where not installed.

Office: GS		ID: GS5391
Unique INC #: EF05026	Well Name: GMU	
	Well #: 26-14A (J26NW)	ID Date: 03/22/05
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 03/22/05
Case #: COC56608A	FAC ID:	Abatement Date: 03/23/05
Form: I	FAC NAME:	Corrected Date: 03/23/05
Assessment: \$0	Inspector: FANCHER	Followup Date: 03/23/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Order No. 2, III. A. 1. and 2. a. iii.		

Remarks Date: 03/22/05

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

A. Well Control Requirements 1. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1). Stating: (1) If the violation or default is not corrected within the time allowed, the authorized officer may subject the operating rights owner or operator, as appropriate, to an assessment of not more than \$500 per day for each day nonabatement continues where the violation or default is deemed a major violation; (2) Where noncompliance involves a minor violation, the authorized officer may subject the operating rights owner or operator, as appropriate, to an assessment of \$250 for failure to abate the violation or correct the default within the time allowed; In this case, a minor violation, the Kill Mud Line was not connected and there was not a connector to connect it to.

Office: GS		ID: GS5695
Unique INC #: EF05041H	Well Name: FEDERAL RWF	
	Well #: 424-19 (24-19)	
Operator: WILLIAMS PRODUCTION RMT CO		
Case #: COC60132	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FANCHER	
Gravity: 3		
Authority Ref: Onshore Order No. 1, I.1.		

Remarks Date: 07/01/05

operators have the responsibility to see that their exploration, development, production, and construction operations are conducted in a manner which (1) conforms with applicable Federal laws and regulations (2) conforms with the lease terms, lease stipulations, and conditions of approval We require 24 hour notice for running surface casing and a 24 hour notice for BOP testing, unless we are present at the surface job. Email notice works fine for spuds. But we have no way of knowing when TD is reached unless we are notified. Please notify your company men or this requirement.

Office: GS		ID: GS5347
Unique INC #: EF05024	Well Name: TBI FEDERAL	
	Well #: 36-4 (PF36)	
Operator: ENCANA OIL & GAS (USA) INC		
Case #: COC66845	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FANCHER	
Gravity: 3		
Authority Ref: Onshore Order 2, III.A.1.iv.		

Remarks Date: 02/14/05

During a rig inspection we noted: that there was no Kill Line connected to BOP. Blowout preventer equipment (BOPE) shall be installed, used, maintained, ... to assure well control ... BOPE kill line must be installed to avoid assessment and shut down of operation.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: HO		ID: HO10626
Unique INC #: JM-001-05R	Well Name: JOHNS B FEDERAL	
	Well #: 06	ID Date: 07/19/05
Operator: CHISOS LTD	FAC ID:	Effective Date: 07/19/05
Case #: NMLC058408B	FAC NAME:	Abatement Date: 07/19/05
Form: I	Inspector: MCCORMICK	Corrected Date: 07/19/05
Assessment: \$0		Followup Date: 07/19/05
Gravity: 3		Extend Date:
Authority Ref: OOGO #2 III. B. 1. f.		

Remarks Date: 07/19/05

Onshore Order #2 states, surface casing shall have centralizers on the bottom three first joints of casing, minimum one per joint. Total of six were RIH, only one of the first joint. Future noncompliance will result in an assessment.

Office: JA		ID: JA1887
Unique INC #: CRB-05-009	Well Name: USA (MM)	
	Well #: 60	ID Date: 11/15/04
Operator: EOG RESOURCES INCORPORATED	FAC ID:	Effective Date: 11/15/04
Case #: LABLMA24527	FAC NAME:	Abatement Date: 11/16/04
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 11/16/04
Assessment: \$0		Followup Date: 11/19/04
Gravity: 3		Extend Date:
Authority Ref: ONSHORE OIL & GAS ORDER #2 PART III.C.4		

Remarks Date: 11/15/04

MUD TESTS NEED TO BE RECORDED IN THE IADC BOOK DAILY. OPERATOR IS ORDERED TO BEGIN THIS PRACTICE IMMEDIATELY.

Office: JA		ID: JA1943
Unique INC #: CRB-05-026	Well Name: USA (MM)	
	Well #: 62-ALT	ID Date: 04/08/05
Operator: EOG RESOURCES INCORPORATED	FAC ID:	Effective Date: 04/08/05
Case #: LABLMA24527	FAC NAME:	Abatement Date: 04/09/05
Form: I	Inspector: CHARLES R BOYD	Corrected Date: 04/08/05
Assessment: \$0		Followup Date: 04/11/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d		

Remarks Date: 04/08/05

PRECHARGE ON ACCUMULATOR IS BELOW THE ACCEPTABLE PRESSURE. PRECHARGE PRESSURE OF 825# WAS RECORDED.  
PRECHARGE PRESSURE MUST BE GREATER THAN OR EQUAL TO 900 PSI BUT MUST BE LESS THAN OR EQUAL TO 1100PSI. OPERATOR IS ORDERED TO REPAIR EQUIPMENT SO THAT THE PRECHARGE FALLS WITHIN THE ACCEPATABLE LIMITS.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: JA ID: JA1899  
 Unique INC #: CRB-05-004 Well Name: USA (MM) ID Date: 10/25/04  
 Well #: 60 Effective Date: 10/25/04  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 12/25/04  
 Case #: LABLMA24527 FAC ID: Corrected Date: 11/09/04  
 Form: I FAC NAME: Followup Date: 12/01/04  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: Onshore Oil & Gas Order #2 Part III.F  
 Remarks Date: 10/25/04

UPON INSPECTION IT WAS DISCOVERED THAT THE OPERATOR HAD CAUSED ADDITIONAL DISTURBANCE OUTSIDE THE AREA DELINEATED FOR THE WELL PAD. THIS DISTURBANCE RESULTED IN THE LOSS OF PINE TIMBER GROWTH ON THE EAST SIDE OF THE LOCATION IN AN AREA APPROXIMATELY 150' X 20'. ACCORDING TO THE OPERATOR THIS AREA WAS CLEARED TO ALLOW FOR THE LOWERING OF THE DERRICK AFTER THE SECOND WELL ON THIS PAD IS DRILLED. BAFB, BEING THE SURFACE MANAGEMENT AGENCY, WILL NEED TO ENFORCE THIS VIOLATION AND IMPOSE ANY PENALTIES THAT THEY FEEL ARE APPROPRIATE FOR THIS INFRACTION. I AM THEREFORE GIVING 60 DAYS AS THE ABATEMENT PERIOD FOR THIS VIOLATION. OPERATOR IS ADVISED TO SIGN AND RETURN THIS VIOLATION AS SOON AS THEY COMPLY WITH ANY ENFORCEMENT REQUIREMENTS GIVEN THEM BY BAFB.

Office: JA ID: JA1885  
 Unique INC #: CRB-05-003 Well Name: USA (MM) ID Date: 10/25/04  
 Well #: 68 Effective Date: 10/25/04  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 12/25/04  
 Case #: LABLMA24527 FAC ID: Corrected Date: 11/09/04  
 Form: I FAC NAME: Followup Date: 12/01/04  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: Onshore Oil & Gas Order #2 Part III.F

Remarks Date: 10/25/04  
 UPON INSPECTION IT WAS DISCOVERED THAT THE OPERATOR HAD CAUSED ADDITIONAL DISTURBANCE OUTSIDE THE AREA DELINEATED FOR THE WELL PAD. THIS DISTURBANCE RESULTED IN THE LOSS OF YOUNG PINE TIMBER GROWTH ON THE NORTH SIDE OF THE LOCATION IN AN AREA APPROXIMATELY 60' X 50'. ACCORDING TO THE OPERATOR THIS AREA WAS CLEARED TO ALLOW FOR THE LOWERING OF THE DERRICK AFTER THE WELL IS COMPLETED. THIS ACTION WAS A RESULT OF THE OPERATOR SKIDDING AHEAD AND DRILLING 3 WELLS ON THE SAME WELL PAD. BAFB, BEING THE SURFACE MANAGEMENT AGENCY, WILL NEED TO ENFORCE THIS VIOLATION AND IMPOSE ANY PENALTIES THAT THEY FEEL ARE APPROPRIATE FOR THIS INFRACTION. I AM THEREFORE GIVING 60 DAYS AS THE ABATEMENT PERIOD FOR THIS VIOLATION. OPERATOR IS ADVISED TO SIGN AND RETURN THIS VIOLATION AS SOON AS THEY COMPLY WITH ANY ENFORCEMENT REQUIREMENTS GIVEN THEM BY BAFB.

Office: JA ID: JA1886  
 Unique INC #: CRB-05-008 Well Name: USA (MM) ID Date: 11/15/04  
 Well #: 60 Effective Date: 11/15/04  
 Operator: EOG RESOURCES INCORPORATED Abatement Date: 11/16/04  
 Case #: LABLMA24527 FAC ID: Corrected Date: 11/16/04  
 Form: I FAC NAME: Followup Date: 11/19/04  
 Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
 Gravity: 3  
 Authority Ref: ONSHORE OIL & GAS ORDER #2 PART III.A.2.i. ix

Remarks Date: 11/15/04  
 THERE IS NO EVIDENCE THAT BOPE PIT LEVEL DRILLS ARE BEING CONDUCTED AND RECORDED IN THE DRILLING LOG (IADC BOOK). OPERATOR IS ORDERED TO BEGIN PERFORMING DRILLS AND RECORDING SAME IN THE DRILLING LOG IMMEDIATELY.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: JA		ID: JA1903
Unique INC #: CRB-05-018	Well Name: USA (MM)	
	Well #: 66-ALT	ID Date: 01/07/05
Operator: EOG RESOURCES INCORPORATED		Effective Date: 01/07/05
Case #: LABLMA24527	FAC ID:	Abatement Date: 01/08/05
Form: I	FAC NAME:	Corrected Date: 01/08/05
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 01/08/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d		

Remarks Date: 01/07/05

THE ACCUMULATOR PRECHARGE PRESSURE WAS FOUND TO BE BELOW THE MINIMUM LIMIT AS SPECIFIED IN THE ORDER. OPERATOR IS ORDERED TO HAVE THE ACCUMULATOR BOTTLES CHECKED TO MAKE SURE THAT THE PRECHARGE IN EACH IS ABOVE THE MINIMUM AS REQUIRED BY THE ORDER.

Office: JA		ID: JA1913
Unique INC #: CRB-05-030	Well Name: USA	
	Well #: 42-ALT	ID Date: 05/26/05
Operator: HUNT PETROLEUM CORPORATION		Effective Date: 05/26/05
Case #: LABLMA54490	FAC ID:	Abatement Date: 05/27/05
Form: I	FAC NAME:	Corrected Date: 05/26/05
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 05/27/05
Gravity: 3		Extend Date:
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d		

Remarks Date: 05/26/05

PRECHARGE ON ACCUMULATOR IS BELOW THE MINIMUM ALLOWED BY THE ORDER. OPERATOR IS ADVISED TO CORRECT THIS PROBLEMTO BRING THE PRECHARGE TO NOT LESS THAN 900 PSI AND NOT OVER 1100 PSI TO COMPLY WITH THE ORDER.

Office: JA		ID: JA1947
Unique INC #: CRB-05-035	Well Name: USA	
	Well #: 45-ALT	ID Date: 06/19/05
Operator: HUNT PETROLEUM CORPORATION		Effective Date: 06/19/05
Case #: LABLMA54490	FAC ID:	Abatement Date: 06/20/05
Form: I	FAC NAME:	Corrected Date: 06/20/05
Assessment: \$0	Inspector: CHARLES R BOYD	Followup Date: 06/20/05
Gravity: 3		Extend Date:
Authority Ref: Onshore O & G Order #2 Part III.A.2.d		

Remarks Date: 06/19/05

PRECHARGE PRESSURE ON ACCUMULATOR (850 PSI) IS BELOW THE MINIMUM ACCEPTABLE PRESSURE. PRECHARGE PRESSURE IS REQUIRED TO BE WITHIN THE RANGE FROM 900 PSI TO 1100 PSI. OPERATOR IS ORDERED TO REPAIR ACCUMULATOR AND BRING PRECHARGE PRESSURE INTO COMPLIANCE WITH THE ORDER.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: JA ID: JA1949  
Unique INC #: CRB-05-058 Well Name: USA ID Date: 09/18/05  
Well #: 45-ALT Effective Date: 09/18/05  
Operator: HUNT PETROLEUM CORPORATION Abatement Date: 09/19/05  
Case #: LABLMA54490 FAC ID: Corrected Date: 09/20/05  
Form: I FAC NAME: Followup Date: 09/21/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date: 09/20/05  
Gravity: 3  
Authority Ref: Onshore O & G Order #2 Part III.A.2.d  
  
Remarks Date: 09/18/05

PRECHARGE PRESSURE ON ACCUMULATOR (800 PSI) IS NOT WITHIN THE ACCEPTABLE RANGE OF THE ORDER. OPERATOR IS ORDERED TO REPAIR THE ACCUMULATOR PRECHARGE AND BRING IT INTO COMPLIANCE WITH THE ORDER. PRECHARGE PRESSURE MUST FALL IN THE RANGE OF NOT LESS THAN 900 PSI,NOR GREATER THAN 1100 PSI.

Office: JA ID: JA1944  
Unique INC #: CRB-05-052 Well Name: USA ID Date: 07/25/05  
Well #: 46-ALT Effective Date: 07/25/05  
Operator: HUNT PETROLEUM CORPORATION Abatement Date: 07/26/05  
Case #: LABLMA54490 FAC ID: Corrected Date: 07/26/05  
Form: I FAC NAME: Followup Date: 07/27/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore O & G Order #2 Part III.A.2.d  
  
Remarks Date: 07/25/05

PRECHARGE PRESSURE ON ACCUMULATOR (750 PSI) IS NOT WITHIN THE ACCEPTABLE RANGE OF THE ORDER. OPERATOR IS ORDERED TO REPAIR THE ACCUMULATOR PRECHARGE AND BRING IT INTO COMPLIANCE WITH THE ORDER. PRECHARGE PRESSURE MUST FALL IN THE RANGE OF NOT LESS THAN 900 PSI,NOR GREATER THAN 1100 PSI.

Office: JA ID: JA1904  
Unique INC #: CRB-05-019 Well Name: USA ID Date: 01/09/05  
Well #: 43-ALT Effective Date: 01/09/05  
Operator: HUNT PETROLEUM CORPORATION Abatement Date: 01/10/05  
Case #: LABLMA54490 FAC ID: Corrected Date: 01/10/05  
Form: I FAC NAME: Followup Date: 01/11/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d  
  
Remarks Date: 01/09/05

THE ACCUMULATOR PRECHARGE PRESSURE WAS FOUND TO BE BELOW THE MINIMUM LIMIT AS SPECIFIED IN THE ORDER. PRESSURE WAS FOUND TO BE 850 PSI, WHICH IS BELOW THE 900 PSI MINIMUM LIMIT. OPERATOR IS ORDERED TO HAVE THE ACCUMULATOR BOTTLES CHECKED TO MAKE SURE THAT THE PRECHARGE OF EACH IS ABOVE THE MINIMUM AS REQUIRED BY THE ORDER.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: JA ID: JA1890  
 Unique INC #: CRB-05-001 Well Name: USA (PARCEL 3)  
 Well #: 47 ID Date: 10/14/04  
 Operator: EOG RESOURCES INCORPORATED Effective Date: 10/14/04  
 Case #: LABLMA54491 FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: CHARLES R BOYD Abatement Date: 10/15/04  
 Gravity: 3 Extend Date:  
 Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d Corrected Date: 10/14/04  
 Followup Date: 10/15/04

Remarks Date: 10/14/04

PRECHARGE WAS FOUND TO BE BELOW THE MINIMUM ACCEPTABLE PRECHARGE PRESSURE. OPERATOR IS ORDERED TO REPAIR CLOSING UNIT SO THAT PRECHARGE IS WITHIN THE ACCEPTABLE RANGE OF > 900 PSI OR < 1100 PSI.

Office: JA ID: JA1891  
 Unique INC #: CRB-05-002 Well Name: USA (PARCEL 3)  
 Well #: 47 ID Date: 10/21/04  
 Operator: EOG RESOURCES INCORPORATED Effective Date: 10/21/04  
 Case #: LABLMA54491 FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: CHARLES R BOYD Abatement Date: 10/22/04  
 Gravity: 3 Extend Date:  
 Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.i.ii Corrected Date: 10/21/04  
 Followup Date: 10/22/04

Remarks Date: 10/21/04

THERE IS NO RECORD OF BOPE PIT LEVEL DRILL BEING CONDUCTED DURING THE PAST WEEK. OPERATOR IS ORDERED TO PERFORM THIS PROCEDURE AND DOCUMENT SAME IN THE WELL LOG (IADC BOOK) AS REQUIRED.

Office: JA ID: JA1893  
 Unique INC #: CRB-05-014 Well Name: USA  
 Well #: 33-ALT ID Date: 12/16/04  
 Operator: CHESAPEAKE OPERATING INC Effective Date: 12/16/04  
 Case #: LABLMA54492 FAC ID:  
 Form: I FAC NAME:  
 Assessment: \$0 Inspector: CHARLES R BOYD Abatement Date: 12/18/04  
 Gravity: 3 Extend Date:  
 Authority Ref: 43 CFR 3162.6.b Corrected Date: 12/17/04  
 Followup Date: 12/17/04

Remarks Date: 12/16/04

OPERATOR IS ORDERED TO OBTAIN SIGN FOR WELLSITE WITH ALL THE INFORMATION REQUIRED BY THE ORDER AND THE CONDITIONS OF APPROVAL AND MAINTAIN IT AT THE WELLSITE FOR THE LIFE OF THE WELL.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: JA ID: JA1900  
Unique INC #: CRB-05-015 Well Name: USA ID Date: 01/06/05  
Well #: 27-ALT Effective Date: 01/06/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 01/07/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 01/07/05  
Form: I FAC NAME: Followup Date: 01/07/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.g  
  
Remarks Date: 01/06/05  
  
A MANUAL LOCKING DEVICE (HAND WHEELS) HAVE NOT BEEN INSTALLED ON THE BOPE. OPERATOR IS ORDERED TO INSTALL THIS LOCKING DEVICE WITHIN 24 HOURS OF THIS NOTICE..

Office: JA ID: JA1892  
Unique INC #: CRB-05-013 Well Name: USA ID Date: 12/16/04  
Well #: 33-ALT Effective Date: 12/16/04  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 12/18/04  
Case #: LABLMA54492 FAC ID: Corrected Date: 12/17/04  
Form: I FAC NAME: Followup Date: 12/17/04  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #1 Part III.G.3.f  
  
Remarks Date: 12/16/04  
  
A COPY OF THE APPROVED APD AND CONDITIONS OF APPROVAL ARE NOT ON THE DRILLSITE AS REQUIRED BY THE ORDER. OPERATOR IS ORDERED TO OBTAIN A COPY OF THIS DOCUMENT AND HAVE IT AT THE WELLSITE WITHIN 48 HOURS OF THIS NOTICE.

Office: JA ID: JA1902  
Unique INC #: CRB-05-017 Well Name: USA ID Date: 01/11/05  
Well #: 27-ALT Effective Date: 01/11/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 01/16/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 01/14/05  
Form: I FAC NAME: Followup Date: 01/14/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.B.1.h  
  
Remarks Date: 01/11/05  
  
UPON REVIEWING THE DAILY DRILLING LOG, IT WAS DETERMINED THAT THE SURFACE CASING WAS NOT TESTED TO THE REQUIRED 1500 PSI AS REQUIRED BY THE ORDER AND SPECIFIED IN THE CONDITIONS OF APPROVAL OF THE APD. OPERATOR IS ORDERED TO TEST THE CASING TO 1500 PSI PRIOR TO RUNNING THE LONG STRING AND DOCUMENTING SAME IN THE DAILY DRILLING LOG.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: JA ID: JA1936  
Unique INC #: CRB-05-57A Well Name: USA ID Date: 09/14/05  
Well #: 49-ALT Effective Date: 09/14/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 09/15/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 09/15/05  
Form: I FAC NAME: Followup Date: 09/16/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.d  
Remarks Date: 09/14/05

PRECHARGE ON ACCUMULATOR WAS FOUND TO BE BELOW THE ALLOWABLE LIMITS AS SET FORTH IN THE ORDER. PRECHARGE MUST BE WITHIN THE RANGE OF NOT LESS THAN 900 PSI NOR GREATER THAN 1100 PSI. OPERATOR IS ORDERED TO REPAIR UNIT WITHIN 24 HOURS OF THIS NOTICE.

Office: JA ID: JA1901  
Unique INC #: CRB-05-016 Well Name: USA ID Date: 01/11/05  
Well #: 27-ALT Effective Date: 01/11/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 01/12/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 01/12/05  
Form: I FAC NAME: Followup Date: 01/13/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.h.xi  
Remarks Date: 01/11/05

UPON REVIEWING THE DAILY DRILLING LOG FOR THE TIME PERIOD BETWEEN 01-03-2005 AND 01-10-2005, THERE WAS NO EVIDENCE THAT A BOPE PIT LEVEL DRILL HAD BEEN DOCUMENTED BY EACH DRILLING CREW. OPERATOR IS THEREFORE ORDERED TO PERFORM THESE DRILLS AND DOCUMENT SAME IN THE DAILY DRILLING LOG.

Office: JA ID: JA1937  
Unique INC #: CR9B-05-05 Well Name: USA ID Date: 09/27/05  
Well #: 49-ALT Effective Date: 09/27/05  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 09/27/05  
Case #: LABLMA54492 FAC ID: Corrected Date: 09/27/05  
Form: I FAC NAME: Followup Date: 09/27/05  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.e  
Remarks Date: 09/27/05

POWER, BOTH ELECTRIC AND AIR, WAS FOUND TO BE SHUT OFF TO THE CLOSING UNIT. OPERATOR IS ORDERED TO CORRECT THIS VIOLATION IMMEDIATELY.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: ME		ID: ME2080
Unique INC #: 05BK01MEFO	Well Name: MALLARD	
	Well #: 4804	ID Date: 10/21/04
Operator: ENCANAS OIL & GAS (USA) INC		Effective Date: 10/21/04
Case #: COC62805	FAC ID:	Abatement Date: 10/22/04
Form: I	FAC NAME:	Corrected Date: 10/25/04
Assessment: \$500	Inspector: KRAFT	Followup Date: 11/04/04
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.5-1-(b)		

Remarks Date: 10/21/04

Failure to comply with a Notice of Noncompliance, number 05BK01MEFO, dated 10/21/2004. The contaminated soils were to be picked up and removed to an approved disposal site. Contaminated soils still remain on the corner of the location and the soils that were scraped up still remain on location.

Office: ME		ID: ME2082
Unique INC #: 05BK03MEFO	Well Name: MALLARD	
	Well #: 4804	ID Date: 10/21/04
Operator: ENCANAS OIL & GAS (USA) INC		Effective Date: 10/21/04
Case #: COC62805	FAC ID:	Abatement Date: 10/22/04
Form: I	FAC NAME:	Corrected Date: 12/03/04
Assessment: \$500	Inspector: KRAFT	Followup Date: 12/06/04
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.5-1-(b)		

Remarks Date: 10/21/04

Failure to comply with a Notice of Noncompliance, number 05BK01MEFO, dated 10/21/2004. The contaminated soils were to be picked up and removed to an approved disposal site. Contaminated soils still remain on the corner of the location and the soils that were scraped up still remain on location.

Office: ME		ID: ME2079
Unique INC #: 04MM04MEFO	Well Name: EUREKA UNIT	
	Well #: 8812C L20 397	ID Date: 09/28/04
Operator: ENCANAS OIL & GAS (USA) INC		Effective Date: 09/28/04
Case #: COC67628X	FAC ID:	Abatement Date: 09/29/04
Form: I	FAC NAME:	Corrected Date: 10/01/04
Assessment: \$0	Inspector: O'MARA	Followup Date: 10/01/04
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1(a)		

Remarks Date: 09/28/04

Production casing cement was not in accordance with the approved APD. The approved APD stated production cement was to be pumped into the surface casing. The operator elected to pump a lesser volume of cement. This was confirmed by the cement bond log dated August 10, 2004.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: ML ID: ML3544  
Unique INC #: CD05-15-2 Well Name: CEDAR HILLS ID Date: 11/04/05  
Well #: 21-10NH Effective Date: 11/04/05  
Operator: CONTINENTAL RESOURCES INC Abatement Date: 12/16/05  
Case #: MTM89699X FAC ID: Corrected Date: 01/04/05  
Form: I FAC NAME: Followup Date: 11/05/05  
Assessment: \$0 Inspector: DEVAULT Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 11/04/05

No well sign on location. At time of C and BO inspections, they had a paper sign but, that was now lost and no sign found.

Office: MR ID: iMR1359  
Unique INC #: SJ-05-DS29 Well Name: FLUME CANYON, UTE D ID Date: 02/01/05  
Well #: 1, 2X, 7 Effective Date: 02/06/05  
Operator: BENSON MONTIN GREER DRLG CORP Abatement Date: 02/26/05  
Case #: 142060463 FAC ID: Corrected Date: 02/08/05  
Form: I FAC NAME: Followup Date: 02/09/05  
Assessment: \$0 Inspector: SWANSON Extend Date:  
Gravity: 3  
Authority Ref: NTL-MDO91-1 Change2

Remarks Date: 02/01/05

Failure to remit copy of 2004 test by the stipulated date of 1/15/2005. (Phone message reminder 01/13/2005, Phone contact 01/25/2005)

Office: MR ID: iMR1369  
Unique INC #: SJ-05-DS37 Well Name: CINDER GULCH ID Date: 02/01/05  
Well #: 3 Effective Date: 02/01/05  
Operator: BURLINGTON RESOURCES O & G CU Abatement Date: 02/26/05  
Case #: 750891020 FAC ID: Corrected Date: 03/08/05  
Form: I FAC NAME: Followup Date: 02/28/05  
Assessment: \$0 Inspector: SWANSON Extend Date: 03/31/05  
Gravity: 3  
Authority Ref: NTL MDO-91-1 Change 2

Remarks Date: 02/01/05

Failure to remit 2004 bradenhead test by 1/15/2005

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: MR ID: iMR1371  
Unique INC #: SJ-05-DS41 Well Name: FLORIDA GAS ID Date: 02/11/05  
Well #: 1 Effective Date: 02/15/05  
Operator: MARALEX RESOURCES INC Abatement Date: 03/08/05  
Case #: COC53311 FAC ID: Corrected Date: 06/08/05  
Form: I FAC NAME: Followup Date: 03/23/10  
Assessment: \$0 Inspector: SWANSON Extend Date:  
Gravity: 3  
Authority Ref: NTL-MDO-91-1 Change 2  
  
Remarks Date: 02/11/05  
Failure to remit 2004 bradenhead test to the BLM office by January 15, 2005. Phoned 1/13/05 and 1/26/2005. Please Fax to 375.2338 or mail to BLM (Swanson) at PLC, 15 Burnett Ct, Durango, CO 81301

Office: MR ID: iMR1366  
Unique INC #: SJ-05-DS39 Well Name: UTE ID Date: 02/01/05  
Well #: 1 Effective Date: 02/06/05  
Operator: BURLINGTON RESOURCES O & G CO Abatement Date: 02/26/05  
Case #: I22IND2813 FAC ID: Corrected Date: 02/25/05  
Form: I FAC NAME: Followup Date: 02/28/05  
Assessment: \$0 Inspector: SWANSON Extend Date:  
Gravity: 3  
Authority Ref: NTL-MDO 91-1 Change 2  
  
Remarks Date: 02/01/05  
Failure to remit bradenhead test to BLM-Durango by 1/15/2005

Office: MR ID: iMR1363  
Unique INC #: SJ-05-DS33 Well Name: SO UTE ID Date: 02/01/05  
Well #: 45 Effective Date: 02/06/05  
Operator: SYNERGY OPERATING LLC Abatement Date: 02/26/05  
Case #: I22IND2825 FAC ID: Corrected Date: 02/03/05  
Form: I FAC NAME: Followup Date: 02/03/05  
Assessment: \$0 Inspector: SWANSON Extend Date:  
Gravity: 3  
Authority Ref: NTL-MDO 91-1 Change 1  
  
Remarks Date: 02/01/05  
Failure to comply with remitting Bradenhead test by 01/15/2005 to the authorized officer.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: MR ID: iMR1368  
Unique INC #: SJ-050DS36 Well Name: SO UTE ID Date: 02/01/05  
Well #: 39 Effective Date: 02/06/05  
Operator: BURLINGTON RESOURCES O & G CO Abatement Date: 02/26/05  
Case #: I22IND2825 FAC ID: Corrected Date: 02/25/05  
Form: I FAC NAME: Followup Date: 02/28/05  
Assessment: \$0 Inspector: SWANSON Extend Date:  
Gravity: 3  
Authority Ref: NTL-MDO 91-1 Change2

Remarks Date: 02/01/05

Failure to remit copy of 2004 Bradenhead test to the BLM-Durango by 1/15/2005

Office: MR ID: iMR1370  
Unique INC #: SJ-05-DS40 Well Name: UTE ID Date: 02/01/05  
Well #: 26 Effective Date: 02/06/05  
Operator: BURLINGTON RESOURCES O & G CO Abatement Date: 02/26/05  
Case #: I22IND2825 FAC ID: Corrected Date: 02/25/05  
Form: I FAC NAME: Followup Date: 02/28/05  
Assessment: \$0 Inspector: SWANSON Extend Date:  
Gravity: 3  
Authority Ref: NTL-MDO 91-1 Change 2

Remarks Date: 02/01/05

Failure to comply with written order to remediate gas well with excessive bradenhead pressure/flow 08/07/2003. Failure to comply with Inc SJ-05-DS25 dated 09/22/2004 with due date of 10/20/2004 and extended to 12/15/2004. Bradenhead pressure was witnessed 11/18/2004 at 36 psig. Burlington Resources Oil and Gas must remit plans for remediation by 02/26/2005. Failure to comply will result in assessments as outlined below in 43 CFR 3163.1a.

Office: MR ID: iMR1360  
Unique INC #: SJ-05-DS31 Well Name: LA POSTA ID Date: 02/01/05  
Well #: 1 Effective Date: 02/06/05  
Operator: BENSON MONTIN GREER DRLG CORP Abatement Date: 02/26/05  
Case #: SRMI4312 FAC ID: Corrected Date: 02/08/05  
Form: I FAC NAME: Followup Date: 02/09/05  
Assessment: \$0 Inspector: SWANSON Extend Date:  
Gravity: 3  
Authority Ref: NTL-MDO91-1 Change2

Remarks Date: 02/01/05

Failure to remit copy of 2004 bradenhead test by the stipulated date of 01/015/2005. (Phone Reminders 01/13/2005, 01/25/2005)

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: MR ID: iMR1361  
Unique INC #: SJ-05-DS30 Well Name: FLUME CANYON  
Well #: 3 ID Date: 02/01/05  
Operator: BENSON MONTIN GREER DRLG CORP Effective Date: 02/06/05  
Case #: SRMI4313 FAC ID: Abatement Date: 02/26/05  
Form: I FAC NAME: Corrected Date: 02/08/05  
Assessment: \$0 Inspector: SWANSON Followup Date: 02/09/05  
Gravity: 3 Extend Date:  
Authority Ref: NTL-MDO91-1 Change 2  
  
Remarks Date: 02/01/05  
Failure to remit Bradenhead test by 01/15/2005. (Phone reminder 1/13/2005 and 1/25/2005)

Office: MR ID: iMR1362  
Unique INC #: SJ-05-DS32 Well Name: DOROTHY GOULD  
Well #: 3 ID Date: 02/01/05  
Operator: BENSON MONTIN GREER DRLG CORP Effective Date: 02/06/05  
Case #: SRMI4318 FAC ID: Abatement Date: 02/26/05  
Form: I FAC NAME: Corrected Date: 02/08/05  
Assessment: \$0 Inspector: SWANSON Followup Date: 02/09/05  
Gravity: 3 Extend Date:  
Authority Ref: NTL MDO 91-1 Change 2  
  
Remarks Date: 02/01/05  
Failure to remit copy of 2004 Bradenhead test by 01/15/2005. (Phone contact 1/13/2005, 1/25/2005.)

Office: MR ID: iMR1364  
Unique INC #: SJ-05-DS34 Well Name: UTE  
Well #: 4 ID Date: 02/01/05  
Operator: BURLINGTON RESOURCES O & G CU Effective Date: 02/06/05  
Case #: SWI4013 FAC ID: Abatement Date: 02/26/05  
Form: I FAC NAME: Corrected Date: 02/25/05  
Assessment: \$0 Inspector: SWANSON Followup Date: 02/28/05  
Gravity: 3 Extend Date:  
Authority Ref: NTL-MDO-91-1 Change 2  
  
Remarks Date: 02/01/05  
Failure to remit 2004 Bradenhead test by 1/15/2005 to the BLM, Durango Office

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: MR ID: iMR1365  
 Unique INC #: SJ-05-DS38 Well Name: UTE ID Date: 02/01/05  
                           Well #: 6 Effective Date: 02/06/05  
 Operator: BURLINGTON RESOURCES O & G CU Abatement Date: 02/26/05  
 Case #: SWI4083 FAC ID: Corrected Date: 02/25/05  
 Form: I FAC NAME: Followup Date: 02/28/05  
 Assessment: \$0 Inspector: SWANSON Extend Date:  
 Gravity: 3  
 Authority Ref: NTL-MDO 91-1 Change 2  
 Remarks Date: 02/01/05  
 Failure to remit 2004 Bradenhead test to the BLM, Durango office by 01/15/2005

Office: MR ID: iMR1372  
 Unique INC #: SJ-05-DS42 Well Name: ID Date: 02/25/05  
                           Well #: Effective Date: 03/03/05  
 Operator: BP AMERICA PRODUCTION COMPANY Abatement Date: 03/24/05  
 Case #: SWI4293 FAC ID: 1E Corrected Date: 03/24/05  
 Form: I FAC NAME: CRAIG GAS UNIT Followup Date:  
 Assessment: \$0 Inspector: SWANSON Extend Date:  
 Gravity: 3  
 Authority Ref: 43CFR3163.2  
 Remarks Date: 02/25/05  
 Failure to remit sundry notice of intent to remediate Craig 1E gas well with bradenhead pressure of 464PSIG by 1/28/2005 as per certified letter of December 27, 2004. Please remit plans for this well by 03/24/2005

Office: NE ID: NE3520  
 Unique INC #: JDH04062DI Well Name: EMPIRE HOOLIGAN DRAW ID Date: 09/24/04  
                           Well #: 1-AH Effective Date: 09/27/04  
 Operator: JED OIL (USA) INC. Abatement Date: 10/29/04  
 Case #: WYW159316X FAC ID: Corrected Date: 10/29/04  
 Form: I FAC NAME: Followup Date: 10/29/04  
 Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.6 (a)  
 Remarks Date: 09/24/04

1. There was not a well sign on the well location. 43 CFR 3162.6 (a) requires every well within a Federal or Indian lease or supervised agreement to have a well identification sign. You are hereby issued a Notice of Incidence of Noncompliance No. JDH04062DI for failure to have a well sign in place. You must install a well sign in accordance with 43 CFR 3162.6 (a) & (b) by October 29, 2004.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: NE		ID: NE3521
Unique INC #: JDH04063DI	Well Name: EMPIRE HOOLIGAN DRAW	
	Well #: 1-AH	ID Date: 09/24/04
Operator: JED OIL (USA) INC.		Effective Date: 09/27/04
Case #: WYW159316X	FAC ID:	Abatement Date: 10/05/04
Form: I	FAC NAME:	Corrected Date: 10/05/04
Assessment: \$0	Inspector: HUTCHINSON	Followup Date: 10/05/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 09/24/04

Item (7)a. of the Surface Use Plan in the approved Application for Permit to Drill (APD) stated that the reserve pit would be fenced on three sides during the drilling operation and fenced on the fourth side when the well is suspended, completed or abandoned. You are hereby issued a Notice of Incidence of Noncompliance No. JDH04063DI for failure to comply with the provisions of the approved APD. (43 CFR 3162.1(a)) You must install a fence around the reserve pit in accordance with the provisions of the approved APD by October 5, 2004.

Office: PD		ID: PD1835
Unique INC #: 89DF072005	Well Name: MESA	
	Well #: 4-21D	ID Date: 07/20/05
Operator: QUESTAR EXPL & PROD CO PNDL		Effective Date: 07/20/05
Case #: WYW015315	FAC ID:	Abatement Date: 07/21/05
Form: I	FAC NAME:	Corrected Date: 07/21/05
Assessment: \$0	Inspector: FALLON	Followup Date: 07/27/05
Gravity: 3		Extend Date:
Authority Ref: O.O. #2.III. A.2.g.		

Remarks Date: 07/20/05

Found: During a Detailed rig inspection the BOP stack was found to have no handwheels on pipe or blind rams. The handwheels were previously found off, during BOP test, and Company man was notified then. Remarks: A manual locking device(i.e.,handwheels)or automatic locking devices shall be installed on all systems 2M or greater.

Office: PD		ID: PD1723
Unique INC #: 99DF092205	Well Name: STEWART POINT	
	Well #: 2A-28D	ID Date: 09/22/05
Operator: QUESTAR EXPL & PROD CO PNDL		Effective Date: 09/22/05
Case #: WYW08592	FAC ID:	Abatement Date: 09/23/05
Form: I	FAC NAME:	Corrected Date: 09/22/05
Assessment: \$0	Inspector: FALLON	Followup Date: 09/22/05
Gravity: 3		Extend Date:
Authority Ref: O.O. #2.III.A.2.g.		

Remarks Date: 09/22/05

During a follow up drilling inspection on True rig # 30, it was dicovered that the upper pipe ram had no handwheel on south side. A manual locking device (i.e., handwheels) or automatic locking device shall be installed on all systems of 2M or greater. Install handwheel as directed above.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: PD ID: PD1724  
Unique INC #: 100DF92205 Well Name: STEWART POINT  
Well #: 2A-28D ID Date: 09/22/05  
Operator: QUESTAR EXPL & PROD CO PNDL Effective Date: 09/22/05  
Case #: WYW08592 FAC ID: Abatement Date: 09/23/05  
Form: I FAC NAME: Corrected Date: 09/22/05  
Assessment: \$0 Inspector: FALLON Followup Date: 09/23/05  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2.III.A.2.g

Remarks Date: 09/22/05

During a follow up detailed rig inspection on True rig # 30, it was discovered the handwheels on the lower pipe ram, north side, were missing. A manual locking device (i.e., handwheels ) or an automatic locking device shall be installed on all systems of 2M or greater. Install handwheels as directed above.

Office: PD ID: PD1726  
Unique INC #: 102DF92205 Well Name: STEWART POINT  
Well #: 2A-28D ID Date: 09/22/05  
Operator: QUESTAR EXPL & PROD CO PNDL Effective Date: 09/22/05  
Case #: WYW08592 FAC ID: Abatement Date: 09/24/05  
Form: I FAC NAME: Corrected Date: 09/23/05  
Assessment: \$0 Inspector: FALLON Followup Date: 09/23/05  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2.III.i.xi.

Remarks Date: 09/22/05

True Rig # 30- Upon review of the driller's log during a detailed drill inspection it was determined BOPE drills were not being preformed and/or recorded in the driller's log on a weekly basis by all crews. A BOPE pit level drill shall be conducted weekly for each drilling crew. It is recommended to alternate BOPE drills while on bottom and while tripping out of the hole.

Office: PD ID: PD1725  
Unique INC #: 101DF92205 Well Name: STEWART POINT  
Well #: 2A-28D ID Date: 09/22/05  
Operator: QUESTAR EXPL & PROD CO PNDL Effective Date: 09/23/05  
Case #: WYW08592 FAC ID: Abatement Date: 09/23/05  
Form: I FAC NAME: Corrected Date: 09/22/05  
Assessment: \$0 Inspector: FALLON Followup Date: 09/23/05  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2. III.2.a.v.

Remarks Date: 09/22/05

During a follow up drilling inspection on True rig # 30, it was discovered that the remote kill line was not connected to run to the outer edge of the substructure. Remote kill line (2 inch minimum) shall run to the outer edge of the substructure and be unobstructed. Install kill line as directed above.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: PD		ID: PD1486
Unique INC #: 21DWF12200	Well Name: STUD HORSE BUTTE	
	Well #: 62-33	ID Date: 12/20/04
Operator: MCMURRY OIL LLC		Effective Date: 12/21/04
Case #: WYW125944	FAC ID:	Abatement Date: 01/15/05
Form: I	FAC NAME:	Corrected Date: 01/06/05
Assessment: \$0	Inspector: FALLO	Followup Date: 01/17/05
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.b.i.		

Remarks Date: 12/20/04

Minimum Standards and provisions for choke manifold equipment include," All Choke lines shall be straight unless turns use tee blocks or are targeted with running tees, and shall be anchored to reduce vibration". BOPE lines downstream of the HCR and upstream of the manifold system had an approximately 33 degree angle welded into choke line. Encana's company man, Dave was notified on 12/20/04 about violation. The twenty four hour abatement period was waved, and the new abatement period given was to complete the required work before drilling out surface on the next well. Furthermore in addressing the regulations regarding running and targeted tees, a written order will be submitted defining the minimum specifications required.

Office: PD		ID: PD1654
Unique INC #: 45DF030805	Well Name: STUD HORSE BUTTE	
	Well #: 37-33	ID Date: 03/08/05
Operator: ENCANA OIL & GAS USA INC		Effective Date: 03/08/05
Case #: WYW125944	FAC ID:	Abatement Date: 03/09/05
Form: I	FAC NAME:	Corrected Date: 03/12/05
Assessment: \$0	Inspector: FALLO	Followup Date: 03/15/05
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.2.a.iv		

Remarks Date: 03/08/05

Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface caasing shoe unless otherwise approved by the APD. Minimum standards and enforcement provisions for well control equipment include for a 5M system: 2 chokes with one remotely controlled from the rig floor. Caza 28 was found to have a remote superchoke not operable during a detailed rig inspection. Install the equipment as specified.

Office: PD		ID: PD1483
Unique INC #: 20DWF12160	Well Name: STUD HORSE BUTTE	
	Well #: 2-22	ID Date: 12/16/04
Operator: MCMURRY OIL LLC		Effective Date: 12/17/04
Case #: WYW127749	FAC ID:	Abatement Date: 12/18/04
Form: I	FAC NAME:	Corrected Date: 12/17/04
Assessment: \$0	Inspector: FALLO	Followup Date: 12/17/04
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.2.c.iii		

Remarks Date: 12/16/04

Initial Bop was not witnessed by BLM on Dec. 6th. During conversation on 12/06/04 it was discoved no accumulator function test was performed. Dave Fallon,(inspector), requested the test to be performed and was scheduled for 12/08/04 at noon. On 12/08/04 concerns were raised by company man of tight hole conditions. After checking with Roger Bankert (AFM BLM), it was agreed to delay test until next TOH. That trip was made on 12/16/04 and the function test failed precharge pressure ( @825psi ), and pump capacity, ( air pumps not functional ). Pending INC notice was given at 14:00 on 12/16/04. Corrective action has been taken and resolved within the abatement period, 12/17/04. If you have any questions regarding this I.N.C., please contact Dave fallon @ (307)367-5390 (office), or (307) 360-8376, (cell).

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: PD		ID: PD1480
Unique INC #: 19DWF12160	Well Name: STUD HORSE BUTTE	
	Well #: 2-22	ID Date: 12/16/04
Operator: MCMURRY OIL LLC		Effective Date: 12/17/04
Case #: WYW127749	FAC ID:	Abatement Date: 12/18/04
Form: I	FAC NAME:	Corrected Date: 12/17/04
Assessment: \$0	Inspector: FALLO	Followup Date: 12/17/04
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.2.d		

Remarks Date: 12/16/04

Initial Bop was not witnessed by BLM on Dec. 6th. During conversation on 12/06/04 it was discovered no Accumulator Function Test was performed. Dave Fallon,(inspector), requested the test to be performed and was scheduled for 12/08/04 at noon. On 12/08/04 concerns were raised by company man of tight hole conditions. After checking with Roger Bankert (AFM BLM), it was agreed to delay test until next TOH. That trip was made on 12/16/04 and the function test failed precharge pressure ( @825psi ), and pump capacity, ( air pumps not functional ). Pending INC notice was given at 14:00 on 12/16/04. Corrective action has been taken and resolved within the abatement period, 12/17/04. If you have any questions regarding this I.N.C., please contact Dave Fallon @ (307)367-5390 (office), or (307) 360-8376, (cell).

Office: PD		ID: PD1498
Unique INC #: 26DWF12220	Well Name: YELLOW POINT	
	Well #: 9-1	ID Date: 12/22/04
Operator: DEVON ENERGY PRODUCTION CO LP		Effective Date: 12/23/04
Case #: WYW148569	FAC ID:	Abatement Date: 12/23/04
Form: I	FAC NAME:	Corrected Date: 12/23/04
Assessment: \$0	Inspector: FALLO	Followup Date: 12/23/04
Gravity: 1		Extend Date:
Authority Ref: O.O.#2.III.C.7.		

Remarks Date: 12/22/04

All Flare systems shall be designed to gather and burn gas. The flare line(s) discharge shall be located not less than 100 feet from the well head. The Flare system shall have an effective method for ignition. The center flare line (panic) was found to be less than 100 feet from wellhead. There was not a effective method for ignition, ( flare bucket was out ).

Office: PD		ID: PD1497
Unique INC #: 25DWF12220	Well Name: YELLOW POINT	
	Well #: 9-1	ID Date: 12/22/04
Operator: DEVON ENERGY PRODUCTION CO LP		Effective Date: 12/23/04
Case #: WYW148569	FAC ID:	Abatement Date: 12/23/04
Form: I	FAC NAME:	Corrected Date: 12/23/04
Assessment: \$0	Inspector: FALLO	Followup Date: 12/23/04
Gravity: 3		Extend Date:
Authority Ref: O.O.#2.III.A.2.b.ii.		

Remarks Date: 12/22/04

Hydrolic adjustable choke, opposite manual choke in manifold system was not hooked up and functional. Choke manifold equipment configuration shall be functionally equivalent to the approximate example diagram in attachment 1 of On Shore Order #2, and in the A.P.D. for this well.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: PD ID: PD1499  
Unique INC #: 27DWF12220 Well Name: YELLOW POINT ID Date: 12/22/04  
Well #: 9-1 Effective Date: 12/23/04  
Operator: DEVON ENERGY PRODUCTION CO LP Abatement Date: 12/23/04  
Case #: WYW148569 FAC ID: Corrected Date: 12/23/04  
Form: I FAC NAME: Followup Date: 12/23/04  
Assessment: \$0 Inspector: FALLO Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2.III.2.a.iv.

Remarks Date: 12/22/04

Inside BOP valve on the floor was found to have a bent rod and inoperative. For a 5M system an inside BOP or float sub must be available.

Office: PD ID: PD1496  
Unique INC #: 24DWF12220 Well Name: YELLOW POINT ID Date: 12/22/04  
Well #: 9-1 Effective Date: 12/23/04  
Operator: DEVON ENERGY PRODUCTION CO LP Abatement Date: 12/23/04  
Case #: WYW148569 FAC ID: Corrected Date: 12/23/04  
Form: I FAC NAME: Followup Date: 12/23/04  
Assessment: \$0 Inspector: FALLO Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2.III.A.2.g

Remarks Date: 12/22/04

Minimum Standards and enforcement provisions for locking devices. A manual locking device (i.e., handwheels ) or automatic locking devices shall be installed on all systems 2M or greater. BOPE was found with no handwheels attached on pipe rams, blind rams, and manual gate valve upstream of HCR valve.

Office: PD ID: PD1776  
Unique INC #: LAW05033 Well Name: MESA ID Date: 07/28/05  
Well #: 15B-27D Effective Date: 07/28/05  
Operator: ULTRA RESOURCES INC Abatement Date: 08/05/05  
Case #: WYW06286 FAC ID: Corrected Date: 08/03/05  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WALDO Extend Date:  
Gravity: 3  
Authority Ref: O.O.2.III.A.2.1.ix

Remarks Date: 07/28/05

Violation: A BOPE pit level drill shall be conducted weekly for each drilling crew. Corrective action: Perform the necessary test or provide documentation.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: PD		ID: PD1775
Unique INC #: LAW05035	Well Name: MESA	
	Well #: 15B-27D	ID Date: 07/28/05
Operator: ULTRA RESOURCES INC		Effective Date: 07/28/05
Case #: WYW06286	FAC ID:	Abatement Date: 07/29/05
Form: I	FAC NAME:	Corrected Date: 07/28/05
Assessment: \$0	Inspector: WALDO	Followup Date: 10/03/05
Gravity: 1		Extend Date:
Authority Ref: 43CFR 3136.1		

Remarks Date: 07/28/05

VERBAL INC. Violation: A manual locking device (i.e. hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater.  
Corrective action: Install equipment as specified.

Office: PD		ID: PD1777
Unique INC #: LAW05034	Well Name: MESA	
	Well #: 15B-27D	ID Date: 07/28/05
Operator: ULTRA RESOURCES INC		Effective Date: 07/28/05
Case #: WYW06286	FAC ID:	Abatement Date: 08/05/05
Form: I	FAC NAME:	Corrected Date: 08/03/05
Assessment: \$0	Inspector: WALDO	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: O.O.2.III.A.2.I. ix		

Remarks Date: 07/28/05

Violation: No pressure gauge on choke manifold. Corrective action: Install equipment as specified.

Office: PD		ID: PD1512
Unique INC #: LAW05001	Well Name: STUD HORSE BUTTE	
	Well #: 48-33	ID Date: 01/20/05
Operator: MCMURRY OIL LLC		Effective Date: 01/21/05
Case #: WYW125944	FAC ID:	Abatement Date: 01/22/05
Form: I	FAC NAME:	Corrected Date: 01/21/05
Assessment: \$0	Inspector: WALDO	Followup Date: 01/21/05
Gravity: 3		Extend Date:
Authority Ref: O.O. #2 section III.A.2.f.		

Remarks Date: 01/20/05

Problem: While performing the capacity test of the accumulator pumps, the BOP closing unit did not meet the 2 minute test. During the witnessing of the BOP test on SHB 48-33, CAZA Rig #76, the Rig Tool Pusher and Brian of Double Jack testing found that the bottles could not be isolated and monitor the accumulator working pressure as it approached the desired 1100psi of a 3000psi working pressure system. The regulations state that each BOP closing unit shall be equipped with sufficient number and sizes of pumps so that, with the accumulator system isolated from service, the pumps shall be capable of opening the hydraulically-operated gate valve (if so equipped), plus closing the annular preventer on the smallest size drill pipe to be used within 2 minutes, and obtain a minimum of 200 psi above specified accumulator precharge pressure. Solution: Install or repair equipment such that the bottles can be isolated to check the capacity of the accumulator pumps and they operate within the 2 minutes required.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: PR		ID: PR3338
Unique INC #: DS05805	Well Name: PETERS POINT UNIT FEDERAL	
	Well #: 16-31D-12-17	ID Date: 11/15/04
Operator: BILL BARRETT CORPORATION		Effective Date: 11/18/04
Case #: UTU63014X	FAC ID:	Abatement Date: 11/23/04
Form: I	FAC NAME:	Corrected Date: 11/22/04
Assessment: \$0	Inspector: D STEPHENS	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1(a)		

Remarks Date: 11/15/04

BBC has failed to comply with APD COAs in which no construction/drilling activities are allowed from November 1 thru May 15 for Sage Grouse, Mule Deer, & Elk. All drilling, construction & completion activities will cease. All drilling, construction, & completion equipment will be removed from the location in a safe & prudent manner.

Office: PR		ID: PR3332
Unique INC #: DS05801	Well Name: PETERS POINT UNIT FEDERAL	
	Well #: 16-35-12-16	ID Date: 11/02/04
Operator: BILL BARRETT CORPORATION		Effective Date: 11/02/04
Case #: UTU63014X	FAC ID:	Abatement Date: 11/04/04
Form: I	FAC NAME:	Corrected Date: 11/15/04
Assessment: \$0	Inspector: D STEPHENS	Followup Date: 11/15/04
Gravity: 1		Extend Date: 11/10/04
Authority Ref: 43 CFR 3163.1(a)(3)		

Remarks Date: 11/02/04

Rigging up operations are to cease. Rig is to be moved off site. Drilling activities are not permitted by conditions of approval between November 1 - May 15.

Office: PR		ID: PR3337
Unique INC #: DS05804	Well Name: PRICKLY PEAR UNIT FEDERAL	
	Well #: 21-2-12-15	ID Date: 11/15/04
Operator: BILL BARRETT CORPORATION		Effective Date: 11/18/04
Case #: UTU79487X	FAC ID:	Abatement Date: 11/23/04
Form: I	FAC NAME:	Corrected Date: 11/22/04
Assessment: \$0	Inspector: D STEPHENS	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1(a)		

Remarks Date: 11/15/04

BBC has failed to comply with APD COAs in which no construction/drilling activities are allowed from November 1 thru May 15 for Sage Grouse, Mule Deer, & Elk. All drilling, construction & completion activities will cease. All drilling, construction, & completion equipment will be removed from the location in a safe & prudent manner.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: PR ID: PR3335  
Unique INC #: DS05802 Well Name: PRICKLY PEAR UNIT FEDERAL ID Date: 11/15/04  
Well #: 13-4-12-14 Effective Date: 11/18/04  
Operator: BILL BARRETT CORPORATION Abatement Date: 11/23/04  
Case #: UTU79487X FAC ID: Corrected Date: 11/22/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: D STEPHENS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1(a)

Remarks Date: 11/15/04

BBC has failed to comply with the APD COAs in which no construction/drilling activities are allowed from November 1 thru May 15 for Sage Grouse, Mule Deer, & Elk. All drilling, construction, & completion activities will cease. All drilling, construction, & completion equipment will be removed from location in a safe & prudent manner.

Office: PR ID: PR3336  
Unique INC #: DS05803 Well Name: PRICKLY PEAR UNIT FEDERAL ID Date: 11/15/04  
Well #: 12-24 Effective Date: 11/18/04  
Operator: BILL BARRETT CORPORATION Abatement Date: 11/23/04  
Case #: UTU79487X FAC ID: Corrected Date: 11/22/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: D STEPHENS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1(a)

Remarks Date: 11/15/04

BBC has failed to comply with APD COAs in which no construction/drilling activities are allowed from November 1 thru May 15 for Sage Grouse, Mule Deer, & Elk. All drilling, construction & completion activities will cease. All drilling, construction, & completion equipment will be removed from the location in a safe & prudent manner.

Office: PR ID: PR3409  
Unique INC #: DS06800 Well Name: ID Date: 09/29/05  
Well #: 34-1 Effective Date: 09/30/05  
Operator: WHITMAR EXPLORATION COMPANY Abatement Date: 09/30/05  
Case #: UTU80556 FAC ID: Corrected Date: 09/30/05  
Form: I FAC NAME: Followup Date: 09/30/05  
Assessment: \$1,000 Inspector: D STEPHENS Extend Date:  
Gravity: 1  
Authority Ref: 43CFR3163.1(a)(3)

Remarks Date: 09/29/05

Operator is to cease drilling operations and to place hole in safe condition. No further drilling operations are to take place until an approved APD is issued by BLM.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: RP		ID: iRP5175
Unique INC #: 05-RAR-001	Well Name: HOYT	
	Well #: 2C	ID Date: 11/04/04
Operator: PATINA OIL AND GAS VCORP		Effective Date: 11/04/04
Case #: JIC119	FAC ID:	Abatement Date: 11/04/04
Form: I	FAC NAME:	Corrected Date: 11/10/04
Assessment: \$0	Inspector: ROMERO	Followup Date: 11/10/04
Gravity: 1		Extend Date:
Authority Ref: OO #2,III.A.2.e		

Remarks Date: 11/04/04

The air supply ball valve to the accumulator was found in the off position. The rig personnel were advised and it was then noted that the relief valve leaked when in the on position. Rig personnel were advised to repair the system prior to placing it back in service. Repairs were accomplished on this date. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. per OO #2,III.A.2.e

Office: RP		ID: iRP5178
Unique INC #: 05-CAT-003	Well Name: JICARILLA APACHE B	
	Well #: 15E	ID Date: 11/05/04
Operator: ELM RIDGE RESOURCES INC		Effective Date: 11/05/04
Case #: JIC11	FAC ID:	Abatement Date: 11/06/04
Form: I	FAC NAME:	Corrected Date: 11/06/04
Assessment: \$0	Inspector: THOMAS	Followup Date: 11/06/04
Gravity: 3		Extend Date:
Authority Ref: Onshore Order # 2 III A. 2. g.		

Remarks Date: 11/05/04

No hand wheels installed. Install the hand wheels. g. Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater.

Office: RP		ID: iRP5177
Unique INC #: 05-CAT-002	Well Name: JICARILLA APACHE B	
	Well #: 15E	ID Date: 11/05/04
Operator: ELM RIDGE RESOURCES INC		Effective Date: 11/05/04
Case #: JIC11	FAC ID:	Abatement Date: 11/06/04
Form: I	FAC NAME:	Corrected Date: 11/06/04
Assessment: \$0	Inspector: THOMAS	Followup Date: 11/06/04
Gravity: 1		Extend Date:
Authority Ref: Onshore Order # 2 III A. 1.		

Remarks Date: 11/05/04

No air to koomey unit. e. Minimum standards and enforcement provisions for power availability. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: RP ID: iRP5176  
 Unique INC #: 05-CAT-001 Well Name: JICARILLA APACHE B ID Date: 11/05/04  
 Well #: 15E Effective Date: 11/05/04  
 Operator: ELM RIDGE RESOURCES INC Abatement Date: 11/06/04  
 Case #: JIC11 FAC ID: Corrected Date: 11/06/04  
 Form: I FAC NAME: Followup Date: 11/06/04  
 Assessment: \$0 Inspector: THOMAS Extend Date:  
 Gravity: 1  
 Authority Ref: Onshore Order # 2 III A. 1.

Remarks Date: 11/05/04

Valve shut off to koomey bottles with no pressure in them. 1. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD. Commencement of drilling without the approved BOPE installed, unless otherwise approved, shall subject the operator to immediate assessment under 43 CFR 3163.1(b)(1).

Office: RP ID: iRP5194  
 Unique INC #: 05-CAT-015 Well Name: JICARILLA 93 ID Date: 01/27/05  
 Well #: 2A Effective Date: 01/27/05  
 Operator: WILLIAMS PRODUCTION COMPANY Abatement Date: 01/28/05  
 Case #: JIC93 FAC ID: Corrected Date: 01/27/05  
 Form: I FAC NAME: Followup Date: 01/27/05  
 Assessment: \$0 Inspector: THOMAS Extend Date:  
 Gravity: 3  
 Authority Ref: Onshore Order # 2 III.

Remarks Date: 01/27/05

Hand wheels not instaled. Install all the handwheels on the BOP arms. g. Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative.

Office: RW ID: RW3279  
 Unique INC #: WA-01-05 Well Name: RED DESERT ID Date: 01/27/05  
 Well #: 20-4 Effective Date: 01/27/05  
 Operator: ANADARKO E & P COMPANY LP Abatement Date: 02/10/05  
 Case #: WYW134358 FAC ID: Corrected Date: 01/31/05  
 Form: I FAC NAME: Followup Date: 01/31/05  
 Assessment: \$0 Inspector: ASHLINE Extend Date:  
 Gravity: 3  
 Authority Ref: coa

Remarks Date: 01/27/05

Two culverts that were required in the APD were not put in the access road.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: RW ID: RW3284  
Unique INC #: WA-02-05 Well Name: FIVE MILE DITCH  
Well #: 13-20  
Operator: DEVON ENERGY PRODUCTION CO LP ID Date: 02/03/05  
Case #: WYW145716 Effective Date: 02/03/05  
Form: I Abatement Date: 02/28/05  
FAC ID:  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: ASHLINE Corrected Date: 02/21/05  
Authority Ref: Conditions Of Approval Followup Date: 03/02/05  
Extend Date:

Remarks Date: 02/03/05

Culverts on access road are not marked as per Conditions Of Approval.

Office: RW ID: RW3295  
Unique INC #: WA-04-05 Well Name: MUSTANG SALLY  
Well #: 1-9  
Operator: GMT ENERGY CORP ID Date: 02/09/05  
Case #: WYW161559X Effective Date: 02/09/05  
Form: I Abatement Date: 04/22/05  
FAC ID:  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: ASHLINE Corrected Date: 02/28/05  
Authority Ref: Additional Permitting Requirement in APD Followup Date: 09/12/05  
Extend Date:

Remarks Date: 02/10/05

There are NO culverts in the access road. APD calls for five (5).

Office: RW ID: RW3290  
Unique INC #: WA-03-05 Well Name: COAL GULCH  
Well #: 11-20  
Operator: DEVON ENERGY PRODUCTION CO LP ID Date: 02/08/05  
Case #: WYW7174 Effective Date: 02/08/05  
Form: I Abatement Date: 03/07/05  
FAC ID:  
Assessment: \$0 FAC NAME:  
Gravity: 3 Inspector: ASHLINE Corrected Date: 03/28/05  
Authority Ref: Conditions Of Approval Followup Date: 03/29/05  
Extend Date:

Remarks Date: 02/08/05

Conditions Of Approval calls for three (3) culverts. Presently there are only Two (2). The two culverts that are there do not have end markers as per the Conditions Of Approval.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: RW ID: RW3280  
Unique INC #: BSH05-03 Well Name: RED DESERT ID Date: 01/28/05  
Well #: 20-4 Effective Date: 01/28/05  
Operator: ANADARKO E & P COMPANY LP Abatement Date: 02/15/05  
Case #: WYW134358 FAC ID: Corrected Date: 02/07/05  
Form: I FAC NAME: Followup Date: 02/10/05  
Assessment: \$0 Inspector: HURST Extend Date:  
Gravity: 3  
Authority Ref: COA

Remarks Date: 01/28/05

APD requires access road to be graveled prior to moving in rig. Gravel road per COA.

Office: RW ID: RW3240  
Unique INC #: BSH04-23 Well Name: BROWN COW AR FEDERAL 1491 ID Date: 10/19/04  
Well #: 14-12 Effective Date: 10/19/04  
Operator: MERIT ENERGY COMPANY Abatement Date: 10/19/04  
Case #: WYW156218X FAC ID: Corrected Date: 10/19/04  
Form: I FAC NAME: Followup Date: 11/30/04  
Assessment: \$0 Inspector: HURST Extend Date:  
Gravity: 3  
Authority Ref: C.O.A.

Remarks Date: 10/19/04

Failed to notify Authorized Officer of BOPE test as required in Conditions of Approval. Notify Authorized Officer of operations in time frame specified.

Office: RW ID: RW3397  
Unique INC #: CR05-65-I Well Name: MARICHAL FEDERAL ID Date: 07/25/05  
Well #: 2 Effective Date: 07/29/05  
Operator: YATES PETROLEUM CORP Abatement Date:  
Case #: WYW134370 FAC ID: Corrected Date: 07/30/05  
Form: I FAC NAME: Followup Date: 09/15/05  
Assessment: \$0 Inspector: ROSS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 (a) and Application for Permit to Drill

Remarks Date: 07/25/05

There is no gravel on the lease access road as required by the APD.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: RW ID: RW3396  
Unique INC #: CR05-66-I Well Name: MARICHAL FEDERAL  
Well #: 2 ID Date: 07/25/05  
Operator: YATES PETROLEUM CORP Effective Date: 07/29/05  
Case #: WYW134370 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS Abatement Date:  
Gravity: 3 Corrected Date: 07/30/05  
Authority Ref: 43 CFR 3164.1 (a) and Application for Permit to Drill Followup Date: 09/15/05  
Remarks Date: 07/25/05 Extend Date:  
There are no culverts in the lease access road as specified in the APD.

Office: RW ID: RW3302  
Unique INC #: CR05-28-I Well Name: ECHO SPRINGS FEDERAL  
Well #: 7-24 ID Date: 02/16/05  
Operator: SAMSON RESOURCES COMPANY Effective Date: 02/24/05  
Case #: WYW32958 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS Abatement Date: 07/15/05  
Gravity: 3 Corrected Date: 07/15/05  
Followup Date: 01/16/06  
Authority Ref: 43 CFR 3164.1(a) and General Permitting Requirements in APD.  
Extend Date:  
Remarks Date: 02/16/05

Culverts were not installed in the access road as required in the General Permitting Requirements in the APD. Additional remarks: Construction activities are prohibited during the period of March 1 to June 30 for the protection of sage-grouse nesting areas. The abatement date takes this into consideration.

Office: RW ID: RW3291  
Unique INC #: PS05-03 Well Name: C G ROAD UNIT  
Well #: 4-4 ID Date: 02/07/05  
Operator: BP AMERICA PRODUCTION COMPANY Effective Date: 02/07/05  
Case #: WYW121147X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SENA Abatement Date: 03/06/05  
Gravity: 3 Corrected Date: 02/15/05  
Followup Date: 03/02/05  
Extend Date:  
Authority Ref: Conditions of Approval

Remarks Date: 02/07/05  
Missing one culvert. Conditions of approval called for two culverts.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: RW ID: RW3283  
Unique INC #: PS05-02W Well Name: STANDARD DRAW  
Well #: 2-32 ID Date: 01/29/05  
Operator: DEVON ENERGY PRODUCTION CO LP Effective Date: 01/29/05  
Case #: WYW42193 FAC ID: Abatement Date: 02/21/05  
Form: I FAC NAME: Corrected Date: 02/07/05  
Assessment: \$0 Inspector: SENA Followup Date: 02/07/05  
Gravity: 3 Extend Date:  
Authority Ref: CONDITIONS OF APPROVAL

Remarks Date: 01/29/05

Failed to comply with the conditions of approval in the APD. Failure to line the reserve pit. PLEASE SEE ATTACHED LETTER FROM MR. TRAVIS BARGSTEN.

Office: RW ID: RW3235  
Unique INC #: CT-106-R04 Well Name: BARREL SPRINGS UNIT  
Well #: 11-12 ID Date: 09/29/04  
Operator: DEVON ENERGY PRODUCTION CO LP Effective Date: 09/29/04  
Case #: WYW029047 FAC ID: Abatement Date: 10/04/04  
Form: I FAC NAME: Corrected Date: 10/04/04  
Assessment: \$0 Inspector: THOMAS Followup Date: 10/07/04  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. 2. h.

Remarks Date: 09/29/04

No remote controls for the BOP equipment. h. Minimum standards and enforcement provisions for remote controls. Remote controls shall be readily accessible to the driller. Remote controls for all 3M or greater systems shall be capable of closing all preventers. Remote controls for 5M or greater systems shall be capable of both opening and closing all preventers. Master controls shall be at the accumulator and shall be capable of opening and closing all preventers and the choke line valve (if so equipped). No remote control for a 2M system is required.

Office: VE ID: VE11293  
Unique INC #: CJ05023 Well Name: NORTH DUCK CREEK  
Well #: 102-26 ID Date: 11/16/04  
Operator: EOG RESOURCES INC Effective Date: 11/16/04  
Case #: UTU9613 FAC ID: Abatement Date: 11/22/04  
Form: I FAC NAME: Corrected Date: 11/17/04  
Assessment: \$0 Inspector: CLIFF JOHNSON Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 11/16/04

Onshore Order #2 III.A.2.a.iii. Well Control Requirements 1. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, Maintained, and tested in manner necessary to assure well control and shall be in place and operational. The kill line valve handle was wallowed out and would not turn valve stem to close valve in a timely manner. Using a pipe wrench is not acceptable practice. Replace handle or valve to make operational.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: WO ID: WO2172  
Unique INC #: 010-05-002 Well Name: CORRAL CREEK FEDERAL ID Date: 11/28/04  
Well #: 30-21 Effective Date: 12/01/04  
Operator: CABOT OIL & GAS CORPORATION Abatement Date: 12/01/04  
Case #: WYW149310 FAC ID: Corrected Date: 12/01/04  
Form: I FAC NAME: Followup Date: 11/30/04  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1(a)

Remarks Date: 11/28/04

Failed to notify the Worland BLM Office as to the time of the running of surface casing on Corral Creek #30-21 as directed in the COA'S of the APD for this well.

Office: WO ID: WO2171  
Unique INC #: 010-05-001 Well Name: CORRAL CREEK FEDERAL ID Date: 11/28/04  
Well #: 30-21 Effective Date: 12/01/04  
Operator: CABOT OIL & GAS CORPORATION Abatement Date: 12/01/04  
Case #: WYW149310 FAC ID: Corrected Date: 12/01/04  
Form: I FAC NAME: Followup Date: 11/30/04  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1 (a)

Remarks Date: 11/30/04

Failed to notify the Worland BLM Office as to the time of spudding of Corral Creek #30-21 as directed in the COA'S of the APD for this well.

Office: WO ID: WO2173  
Unique INC #: 010-05-003 Well Name: CORRAL CREEK FEDERAL ID Date: 11/28/04  
Well #: 30-21 Effective Date: 12/01/04  
Operator: CABOT OIL & GAS CORPORATION Abatement Date: 12/01/04  
Case #: WYW149310 FAC ID: Corrected Date: 12/01/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: LEAR Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1(a)

Remarks Date: 11/28/04

Failed to conform with the terms approved in the APD of well #30-21 for the cementing of the surface casing.

Safety and Drilling Related Violations (INCs) Issued During FY 2005  
As of March 3, 2011

Office: WO ID: WO2176  
Unique INC #: 010-05-004 Well Name: CORRAL CREEK FEDERAL ID Date: 12/01/04  
Well #: 30-21 Effective Date: 12/01/04  
Operator: CABOT OIL & GAS CORPORATION Abatement Date: 12/03/04  
Case #: WYW149310 FAC ID: Corrected Date: 12/04/04  
Form: I FAC NAME: Followup Date: 12/04/04  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3163.1 (a)

Remarks Date: 12/01/04

Failed to notify the Worland BLM Office of changing the surface casing from 95/8" 36#, to 85/8" 32# at Corral Creek #30-21. As directed in the COA's of the APD.

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Office: BA		ID: BA1815	
Unique INC #:	02-001-04	Well Name: MAXWELL	ID Date: 12/16/03
		Well #: 412	Effective Date: 12/16/03
Operator:	AERA ENERGY LLC	FAC ID:	Abatement Date: 12/31/03
Case #:	CAS019392	FAC NAME:	Corrected Date: 12/28/03
Form:	I	Inspector: 2 SPARKS R	Followup Date: 12/28/03
Assessment:	\$0		Extend Date:
Gravity:	3		
Authority Ref:	43 CFR 3162.1(a)		

Remarks Date: 12/16/03

KENAI, RIG #4 WAS INSPECTED ON 12/16/03 AND WAS FOUND TO BE IN VIOLATION OF THE CONDITIONS OF APPROVAL (COA), ATTACHED TO THE APPLICATION FOR PERMIT TO DRILL (APD). IT WAS NOTED THAT THERE ARE TWO 90 DEGREE BENDS IN THE 6" DIVERTER LINE. THE COA's SAID THERE WAS TO BE NO TURNS IN THE LINE. YOU HAVE UNTIL 12/31/03 TO CORRECT THIS ISSUE AND COME INTO COMPLIANCE.

Office: BU		ID: BU7634	
Unique INC #:	MB-04-18	Well Name: SOUTH PORCUPINE	ID Date: 07/27/04
		Well #: 43-4	Effective Date:
Operator:	MERIT ENERGY CO	FAC ID:	Abatement Date: 07/28/04
Case #:	WYW7526	FAC NAME:	Corrected Date: 07/28/04
Form:	I	Inspector: BLAKESLEY	Followup Date: 08/25/04
Assessment:	\$0		Extend Date:
Gravity:	3		
Authority Ref:	43 CFR 3162.6 (b)		

Remarks Date: 07/27/04

Well site is not properly identified. You must install a well sign that meets the requirements of 43 CFR 3162.6(b).

Office: BU		ID: BU7635	
Unique INC #:	MB-04-19	Well Name: SOUTH PORCUPINE	ID Date: 07/27/04
		Well #: 34-4	Effective Date:
Operator:	MERIT ENERGY CO	FAC ID:	Abatement Date: 07/28/04
Case #:	WYW7526	FAC NAME:	Corrected Date: 07/28/04
Form:	I	Inspector: BLAKESLEY	Followup Date: 08/25/04
Assessment:	\$0		Extend Date:
Gravity:	3		
Authority Ref:	43 CFR 3162.6 (b)		

Remarks Date: 07/27/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Well site not properly identified. You must install a well sign that meets the requirements of 43 CFR 3162.6 (b).

Office: BU	ID: BU7632
Unique INC #: MB-04-16	Well Name: SOUTH PORCUPINE
	Well #: 23-4
Operator: MERIT ENERGY CO	
Case #: WYW7526A	FAC ID:
Form: I	FAC NAME:
Assessment: \$0	Inspector: BLAKESLEY
Gravity: 3	
Authority Ref: 43 CFR 3162.6 (b)	
Remarks Date: 07/27/04	

Well site is not properly identified. You must place a well sign on location that meets the requirements of 43 CFR 3162.6 (b).

Office: BU	ID: BU7633
Unique INC #: MB-04-17	Well Name: SOUTH PORCUPINE
	Well #: 14-4
Operator: MERIT ENERGY CO	
Case #: WYW7526A	FAC ID:
Form: I	FAC NAME:
Assessment: \$0	Inspector: BLAKESLEY
Gravity: 3	
Authority Ref: 43 CFR 3162.6 (b)	
Remarks Date: 07/27/04	

No well sign on location. You must put up a well sign that meets the requirements of 43 CFR 3162.6 (b).

Office: BU	ID: BU7636
Unique INC #: MB-04-20	Well Name: SOUTH PORCUPINE
	Well #: 23-4
Operator: MERIT ENERGY CO	
Case #: WYW7526A	FAC ID:
Form: I	FAC NAME:
Assessment: \$0	Inspector: BLAKESLEY
Gravity: 3	
Authority Ref: Conditions of Approval	
Remarks Date: 07/27/04	

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Blooie line on diverter head is not of proper length. You must have a blooie line with a minimun length of 30 '

Office: BU	Well Name: BIG BEND FED STRAT	ID: BU7472
Unique INC #: MH/04/20	Well #: 9-21	ID Date: 05/31/04
Operator: NORTH FINN, LLC	FAC ID:	Effective Date: 06/01/04
Case #: WYW132277	FAC NAME:	Abatement Date: 06/16/04
Form: I	Inspector: HAINES	Corrected Date: 06/01/04
Assessment: \$0		Followup Date: 06/02/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 05/31/04

On 5/31/2004 during a field inspection it was found that a well sign was not installed. The company representative was informed to install a well sign. If there are any questions contact Mark Haines at 307-684- 1065 or Lee Greaves at 307-684-1152 .

Office: BU	Well Name: BATES CR CRITTENDEN CS	ID: BU7230
Unique INC #: RN-04-29	Well #: 2	ID Date: 04/08/04
Operator: YATES PETROLEUM CORP	FAC ID:	Effective Date: 04/08/04
Case #: WYW129019	FAC NAME:	Abatement Date: 04/12/04
Form: I	Inspector: NAVARRETTE	Corrected Date: 04/19/04
Assessment: \$0		Followup Date: 04/19/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 04/08/04

The well is not identified with a well sign. You must properly identify this well with a well sign that includes the operator, federal lease number, 1/4 1/4, section, township and range on it. The sign must be maintained in a legible condition.

Office: BU	Well Name: BATES CR CRITTENDEN CS	ID: BU7231
Unique INC #: RN-04-30	Well #: 2	ID Date: 04/08/04
Operator: YATES PETROLEUM CORP	FAC ID:	Effective Date: 04/08/04
Case #: WYW129019	FAC NAME:	Abatement Date: 04/12/04
Form: I	Inspector: NAVARRETTE	Corrected Date: 04/19/04
Assessment: \$0		Followup Date: 04/19/04
Gravity: 3		Extend Date:
Authority Ref: APD		

Remarks Date: 04/08/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The drilling pit is not fenced. You must have a fence up around the drilling pits as soon as they are put in.

Office: BU	Well Name: ANTELOPE BRIDLE BIT	ID: BU7194
Unique INC #: RN-04-18	Well #: 32-31	ID Date: 03/09/04
Operator: WILLIAMS PRODUCTION RMT CO	FAC ID:	Effective Date: 03/09/04
Case #: WYW142772	FAC NAME:	Abatement Date: 03/09/04
Form: I	Inspector: NAVARRETTE	Corrected Date: 03/14/04
Assessment: \$0		Followup Date: 03/14/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/10/04

The drilling pit is only 10 feet from well bore. This is a violation of the Approved driling plan. In the future on all wells the nearest edge of the pits must be a minimum of 30 feet from the well bore.

Office: BU	Well Name: ANTELOPE BRIDLE BIT	ID: BU7197
Unique INC #: RN-04-21	Well #: 34-31	ID Date: 03/09/04
Operator: WILLIAMS PRODUCTION RMT CO	FAC ID:	Effective Date: 03/09/04
Case #: WYW142772	FAC NAME:	Abatement Date: 03/09/04
Form: I	Inspector: NAVARRETTE	Corrected Date: 03/15/04
Assessment: \$0		Followup Date: 03/15/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(b)		

Remarks Date: 03/10/04

The drilling pit is only 10 feet from well bore. This is a violation of the Approved driling plan. In the future on all wells the nearest edge of the pits must be a minimum of 30 feet from the well bore.

Office: BU	Well Name: TIBBS DRAW OEDEKOVEN	ID: BU7277
Unique INC #: SAM22-04	Well #: 11LW-30	ID Date: 04/14/04
Operator: JM HUBER CORP	FAC ID:	Effective Date: 04/15/04
Case #: WYW132516	FAC NAME:	Abatement Date: 05/04/04
Form: I	Inspector: SHEPPARD	Corrected Date: 05/04/04
Assessment: \$0		Followup Date: 05/06/04
Gravity: 1		Extend Date:
Authority Ref: OO#2.III.B.1		

Remarks Date: 04/14/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Failure to follow approved Application Permit to Drill using 5 1/2", 14# production casing. You must submit a Sundry with all the casing specifications on the 14# casing requesting a variance from the approved APD.

Office: BU	Well Name: TIBBS DRAW OEDEKOVEN	ID: BU7278
Unique INC #: SAM23-04	Well #: 1LW-30	ID Date: 04/14/04
Operator: JM HUBER CORP	FAC ID:	Effective Date: 04/15/04
Case #: WYW138439	FAC NAME:	Abatement Date: 05/04/04
Form: I	Inspector: SHEPPARD	Corrected Date: 05/04/04
Assessment: \$0		Followup Date: 05/06/04
Gravity: 1		Extend Date:
Authority Ref: OO#2.III.B.1		

Remarks Date: 04/14/04

Failure to follow the approved Application Permit to Drill by using 5 1/2", 14# production casing. You must submit a Sundry with all the specifications on the 14# casing requesting a variance from the approved APD.

Office: BU	Well Name: TIBBS DRAW OEDEKOVEN	ID: BU7279
Unique INC #: SAM24-04	Well #: 7LW-30	ID Date: 04/14/04
Operator: JM HUBER CORP	FAC ID:	Effective Date: 04/15/04
Case #: WYW138439	FAC NAME:	Abatement Date: 05/04/04
Form: I	Inspector: SHEPPARD	Corrected Date: 05/04/04
Assessment: \$0		Followup Date: 05/06/04
Gravity: 1		Extend Date:
Authority Ref: OO#2.III.B.1		

Remarks Date: 04/14/04

Failure to follow the approved Application Permit to Drill by using 5 1/2", 14# production casing. You must submit a Sundry with all the specifications on the 14# casing requesting a variance from the approved APD.

Office: BU	Well Name: TIBBS DRAW OEDEKOVEN	ID: BU7278
Unique INC #: SAM21-04	Well #: 5LW-29	ID Date: 04/14/04
Operator: JM HUBER CORP	FAC ID:	Effective Date: 04/15/04
Case #: WYW140243	FAC NAME:	Abatement Date: 05/04/04
Form: I	Inspector: SHEPPARD	Corrected Date: 05/04/04
Assessment: \$0		Followup Date: 05/06/04
Gravity: 1		Extend Date:
Authority Ref: OO#2.III.B.1		

Remarks Date: 04/14/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Failure to follow the approved Application Permit to Drill by using 5 1/2", 14.0# production casing. You must submit a Sundry with all the specifications on the 14# casing requesting a variance from the approved APD.

Office: CB ID: CB17233  
Unique INC #: 04-JA-028 Well Name:  
Well #: ID Date: 12/10/03  
Operator: MACK ENERGY CORPORATION Effective Date:  
Case #: NMLC029020G FAC ID: A Abatement Date: 01/11/04  
Form: I FAC NAME: DEXTER-1 Corrected Date: 12/22/03  
Assessment: \$0 Inspector: AMOS Followup Date: 01/13/04  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 6.III.D.1.c & e  
Remarks Date: 12/10/03

H2S WARNING SIGN IS NOT PRESENT ON THIS LOCATION. INSTALL WARNING SIGN WITHIN 50 FEET OF STORAGE TANK. WIND DIRECTION INDICATOR (SOCK) IS NO LONGER ADEQUATE. REPLACE SOCK.

Office: CB ID: CB17441  
Unique INC #: 04-JA-076 Well Name: NORTH SQUARE LAKE UNIT  
Well #: 194 ID Date: 01/16/04  
Operator: CBS OPERATING CORPORATION Effective Date:  
Case #: NMNM101360X FAC ID: Abatement Date: 01/26/04  
Form: I FAC NAME: Corrected Date: 01/16/04  
Assessment: \$0 Inspector: AMOS Followup Date: 01/16/04  
Gravity: 3 Extend Date:  
Authority Ref: APD COA, 43 CFR 3162.1.a  
Remarks Date: 01/16/04

FAILURE TO COMPLY WITH APPLICATION TO DRILL, CONDITIONS OF APPROVAL (COA). COA REQUIRES NOTIFICATION ON SPUDDING, CEMENTING CASING (BOTH SURFACE AND PRODUCTION), AND BOP TESTS. THIS IS THE LATEST OF SIX WELLS WHERE THE BLM WAS NOT NOTIFIED. ANY FUTURE FAILURES FROM RECEIPT OF THIS NOTICE WILL RESULT IN ASSESSMENTS AT THE RATE OF \$250.00 PER VIOLATION.

Office: CB ID: CB17151  
Unique INC #: 04-DC-093 Well Name:  
Well #: ID Date: 11/24/03  
Operator: BROTHERS PRODUCTION CO INC Effective Date: 11/24/03  
Case #: NMLC029388D FAC ID: A Abatement Date: 12/19/03  
Form: I FAC NAME: JOHNSON B Corrected Date: 12/15/03  
Assessment: \$0 Inspector: CLEGHORN Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.1, O.O. 6.III,D,2 (e)  
Remarks Date: 11/24/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

WIND SOCK HAS DETERIORATED---REPLACE WIND DIRECTION INDICATOR AS NECESSARY.

Office: CB ID: CB17506  
Unique INC #: 04-DC-179 Well Name: TURNER A  
Well #: 32 ID Date: 02/10/04  
Operator: MERIT ENERGY COMPANY Effective Date: 02/13/04  
Case #: NMLC029395A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLEGHORN  
Gravity: 3  
Authority Ref: 43 CFR 3162.1, 43 CFR 3162.6 (b)

Remarks Date: 02/10/04

INCORRECT FOOTAGES ON WELL SIGN. APPLY CORRECT FOOTAGES ON WELL SIGN.

Office: CB ID: CB17318  
Unique INC #: 04-DC-139 Well Name:  
Well #: ID Date: 12/29/03  
Operator: MERIT ENERGY COMPANY Effective Date: 12/29/03  
Case #: NMLC029395B FAC ID: A  
Form: I FAC NAME: TURNER B NORTH  
Assessment: \$0 Inspector: CLEGHORN  
Gravity: 3  
Authority Ref: 43 CFR 3162.1, O.O. 6,III,D,2(e)

Remarks Date: 12/29/03

WIND SOCK HAS DETERIORATED-REPLACE WIND DIRECTION INDICATOR AS NECESSARY.

Office: CB ID: CB17462  
Unique INC #: 04-DC-156 Well Name:  
Well #: ID Date: 01/27/04  
Operator: MERIT ENERGY COMPANY Effective Date: 01/29/04  
Case #: NMLC029426A FAC ID: A  
Form: I FAC NAME: H E WEST A  
Assessment: \$0 Inspector: CLEGHORN  
Gravity: 3  
Authority Ref: 43 CFR 3162.1, O.O. 6,III,D,2(e)

Remarks Date: 01/27/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

WIND SOCK HAS DETERIORATED---REPLACE WIND DIRECTION INDICATOR AS NECESSARY.

Office: CB ID: CB17505  
Unique INC #: 04-DC-178 Well Name: DAZED BDZ FEDERAL COM  
Well #: 1 ID Date: 02/10/04  
Operator: YATES PETROLEUM CORPORATION Effective Date: 02/13/04  
Case #: NMNM0230377B FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLEGHORN  
Gravity: 3  
Authority Ref: 43 CFR 3162.1, 43 CFR 3162.6 (b)

Remarks Date: 02/10/04

INCORRECT LEASE NUMBER ON WELL SIGN--APPLY CORRECT LEASE NUMBER TO WELL SIGN.

Office: CB ID: CB17886  
Unique INC #: 04-GH-114 Well Name:  
Well #: ID Date: 06/02/04  
Operator: WEBB OIL COMPANY Effective Date:  
Case #: NMLC028990A FAC ID: A  
Form: I FAC NAME: CREEK FEDERAL  
Assessment: \$0 Inspector: HUNT  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, O.O.#6, III.D.

Remarks Date: 06/02/04

DUE TO AMOUNT OF H2S IN VENT GAS, THE BATTERY NEEDS TO BE EQUIPPED WITH A WIND DIRECTION INDICATOR TO PROVIDE CORRECT SAFETY INFORMATION TO PEOPLE APPROACHING THE SALES POINT. INSTALL WIND DIRECTION INDICATOR AT THE BATTERY WITHIN 20 DAYS OF NOTICE.

Office: CB ID: CB17655  
Unique INC #: 04-GH-088 Well Name:  
Well #: ID Date: 03/18/04  
Operator: CONCHO EXPLORATION INC Effective Date:  
Case #: NMNM33437 FAC ID: A  
Form: I FAC NAME: PMS 8 FED BATTERY  
Assessment: \$0 Inspector: HUNT  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.D.3.e

Remarks Date: 03/18/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

REQUIRED WIND DIRECTION INDICATOR AT THE BATTERY IS IN DISREPAIR. REPAIR THE WIND DIRECTION INDICATOR WITHIN 20 DAYS OF NOTICE.

Office: CB ID: CB17374  
Unique INC #: 04-PS-016 Well Name: MESA FEDERAL  
Well #: 1 ID Date: 01/07/04  
Operator: THOMPSON CLEO J Effective Date: 01/07/04  
Case #: NMLC064490 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SWARTZ  
Gravity: 3  
Authority Ref: O.O.2,III.A.2.h  
Abatement Date: 01/08/04  
Corrected Date: 01/08/04  
Followup Date: 01/08/04  
Extend Date:

Remarks Date: 01/07/04

The accumulator remote control failed to close the annular preventer during the function test. Repair the remote control.

Office: CB ID: CB17373  
Unique INC #: 04-PS-015 Well Name: MESA FEDERAL  
Well #: 1 ID Date: 01/07/04  
Operator: THOMPSON CLEO J Effective Date: 01/07/04  
Case #: NMLC064490 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SWARTZ  
Gravity: 3  
Authority Ref: O.O.2,III.A.2.c.iii  
Abatement Date: 07/08/04  
Corrected Date: 01/08/04  
Followup Date: 01/08/04  
Extend Date:

Remarks Date: 01/07/04

The air powered acummulator pump failed to pump during the required accumulator function test. Repair the air powered pump.

Office: CB ID: CB17675  
Unique INC #: 04-PS-021 Well Name: SUNDANCE FEDERAL  
Well #: 25 ID Date: 04/14/04  
Operator: POGO PRODUCING COMPANY Effective Date:  
Case #: NMNM104730 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SWARTZ  
Gravity: 3  
Authority Ref: Onshore Order #1.III.G.3.f.  
Abatement Date: 04/16/04  
Corrected Date: 04/23/04  
Followup Date: 04/27/04  
Extend Date:

Remarks Date: 04/14/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

A copy of the approved Form 3160-3 and the pertinate drilling plan, along with any conditions of approval is not on location. This paper work "shall be be available at the drillsite". Provide the drilling plan onsite.

Office: CB ID: CB17676  
Unique INC #: 04-PS-022 Well Name: SUNDANCE FEDERAL  
Well #: 25 ID Date: 04/14/04  
Effective Date: 04/15/04  
Operator: POGO PRODUCING COMPANY Abatement Date: 04/16/04  
Case #: NMNM104730 FAC ID: Corrected Date: 04/15/04  
Form: I FAC NAME: Followup Date: 04/16/04  
Assessment: \$0 Inspector: SWARTZ Extend Date:  
Gravity: 1  
Authority Ref: Approved Application to Drill

Remarks Date: 04/14/04

The approved APD requires a 3M system as stated in Onshore Order #2.III.A.2.a.iii. and Order #2.III.A.2.h. The BOPE on this well lacks an annular preventer and remote control. Install the equipment. If not corrected before operations are in compliance an assessment of \$500 per day for each day that the violation existed, not to exceed \$5,000 per 43 CFR 3163.1(b)(1) may be required.

Office: CB ID: CB17932  
Unique INC #: 04-PS-048 Well Name: HIGH HOG 9 FEDERAL  
Well #: 1 ID Date: 07/16/04  
Effective Date: 07/16/04  
Operator: CABAL ENERGY CORPORATION Abatement Date: 07/17/04  
Case #: NMNM62171 FAC ID: Corrected Date: 07/18/04  
Form: I FAC NAME: Followup Date: 07/29/04  
Assessment: \$0 Inspector: SWARTZ Extend Date:  
Gravity: 3  
Authority Ref: O.O.#2.III.A.2.f.

Remarks Date: 07/16/04

The accumulator recharge pump(s) output is not adequate for this installation. Replace or repair the pump(s).

Office: CB ID: CB18069  
Unique INC #: 04-PS-050 Well Name: PATTON 18 FEDERAL  
Well #: 3 ID Date: 09/17/04  
Effective Date: 09/20/04  
Operator: POGO PRODUCING COMPANY Abatement Date: 10/08/04  
Case #: NMNM89819 FAC ID: Corrected Date: 09/29/04  
Form: I FAC NAME: Followup Date: 10/20/04  
Assessment: \$0 Inspector: SWARTZ Extend Date:  
Gravity: 3  
Authority Ref: O.O. 2.III.B.1.g.

Remarks Date: 09/17/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Cementing operations were not conducted according to Onshore Order 2. Specifically a wiper plug was not used to prevent contamination of the tail cement. Future continuation of this practice will result in the requirement of cement bond logs and possible recementing.

Office: CR		ID: CR1186
Unique INC #: LSFO04-004	Well Name: FOX FEDERAL	
	Well #: 1-13	
Operator: JUSTIN ENERGY LLC		
Case #: COC59908	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: EAGAN	
Gravity: 3		
Authority Ref: Onshore Order #2 3 A2i II		

Remarks Date: 08/24/04

Operator had APD approved 5000 psi BOP system tested to only 3000 psi using a plug. Operator or his designated agent must have BOP system tested to 5000 psi with a plug (and 2500 psi for annular BOP test) within next trip out of hole or before drilling out next run intermediate casing as per the requirements of Onshore Order #2 3 A 2i II

Office: DK		ID: DK6104
Unique INC #: IDB04001	Well Name:	
	Well #:	
Operator: WESTPORT OIL & GAS COMPANY LP		
Case #: CANW063	FAC ID: A	
Form: I	FAC NAME: USA VOLKMANN 1X	
Assessment: \$0	Inspector: DEBBIE BOHLMAN	
Gravity: 3		
Authority Ref: 43 CFR 3164.1	OO#6 III.D.3.e.	

Remarks Date: 01/12/04

There is no wind direction indicator on location. Install wind direction indicator as necessary. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK		ID: DK6156
Unique INC #: IDB04033	Well Name:	
	Well #:	
Operator: AGATE PETROLEUM INCORPORATED		
Case #: NDM32772	FAC ID: A	
Form: I	FAC NAME: MULE CREEK FED 1X-18	
Assessment: \$0	Inspector: DEBBIE BOHLMAN	
Gravity: 3		
Authority Ref: 43 CFR 3164.1	ONSHORE ORDER #6 III.D.3.e	

Remarks Date: 05/20/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Wind direction indicator needs to be replaced (see attached photo). The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: FE ID: FE12140  
Unique INC #: 03AVJ102 Well Name: WF FEDERAL 21  
Well #: 1 ID Date: 09/26/03  
Operator: RICHARDSON OPERATING CO Effective Date: 10/13/03  
Case #: NMNM25857 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMISON  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 11/13/03  
Corrected Date: 10/17/03  
Followup Date: 10/17/03  
Extend Date:

Remarks Date: 09/26/03

You must install and maintain adequate guards around your pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property. Replace Beltguard

Office: FE ID: iFE12850  
Unique INC #: 04MK09 Well Name: NV NAVAJO 24  
Well #: 1 ID Date: 06/09/04  
Operator: RICHARDSON OPERATING CO Effective Date: 06/09/04  
Case #: 14206032198 FAC ID:  
Form: I FAC NAME:  
Assessment: \$500 Inspector: KECMAN  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3163.1 b 1  
Abatement Date: 06/09/04  
Corrected Date: 06/09/04  
Followup Date: 06/09/04  
Extend Date:

Remarks Date: 06/14/04

For failure to install blowout preventer as required by the approved drilling plan. The BOP was not installed during the running of the production casing string into the wellbore. The above inspector arrived when approximately half of the production casing was in the wellbore.

Office: FE ID: iFE12988  
Unique INC #: 04GLB024 Well Name: ENGLISH  
Well #: 12 ID Date: 08/05/04  
Operator: MOUNTAIN STATES PETRO CORP Effective Date: 08/18/04  
Case #: I149IND7180 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LESLIE-BOB  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 09/17/04  
Corrected Date: 09/14/04  
Followup Date: 10/13/04

Remarks Date: 08/05/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

You must install and maintain adequate guards around your pumping unit in accordance with API Standards to ensure the protection of health and safety of life and the protection of property. You must erect guards around the pumping unit, currently no guards near well sign (see photo).

Office: FE ID: FE13058  
Unique INC #: 04CO0060 Well Name: ROSA UNIT  
Well #: 268A ID Date: 04/13/04  
Effective Date: 09/13/04  
Operator: WILLIAMS PRODUCTION CO LLC Abatement Date: 09/13/04  
Case #: NMSF078773 FAC ID: Corrected Date: 09/13/04  
Form: I FAC NAME: Followup Date: 09/13/04  
Assessment: \$0 Inspector: OLLOM C Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a) Onshore Order #2. III. A. 2. e.

Remarks Date: 04/13/04

Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. The air to one pump was turned off and the electrical power source to the unit was turned off. The power sources were turned on. This is for your information only. No further action is required.

Office: FE ID: FE13019  
Unique INC #: 04CO0059 Well Name: F-RPC 19  
Well #: 1 ID Date: 08/25/04  
Effective Date: 08/25/04  
Operator: RICHARDSON OPERATING CO Abatement Date: 08/30/04  
Case #: NMSF079065 FAC ID: Corrected Date: 09/07/04  
Form: I FAC NAME: Followup Date: 09/07/04  
Assessment: \$0 Inspector: OLLOM C Extend Date:  
Gravity: 1  
Authority Ref: O.O.2.III.A.e.

Remarks Date: 08/25/04

The accumulator unit shall have two independant power sources to close the preventers. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. The system on location utilized air from the rigs air supply and had no secondary power source to automatically start up and pressurize the system should air be lost so that the preventers could be closed. This must be corrected prior to spudding the next hole.

Office: FE ID: FE12967  
Unique INC #: 04JIR003 Well Name: ROSA  
Well #: 100E ID Date: 07/20/04  
Effective Date: 08/03/04  
Operator: WILLIAMS PRODUCTION CO LLC Abatement Date: 09/03/04  
Case #: NMSF078766 FAC ID: Corrected Date: 09/02/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: RUYBALID Extend Date:  
Gravity: 3  
Authority Ref: 3265.5-1a

Remarks Date: 07/20/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The gate on the fence surrounding the tank is missing. The operator shall conduct operations which protects wildlife.

Office: FE ID: FE13068  
Unique INC #: 04MOW025 Well Name: NEGRO CANYON  
Well #: 101S ID Date: 09/20/04  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 09/20/04  
Case #: NMNM111921 FAC ID: Abatement Date: 09/20/04  
Form: I FAC NAME: Corrected Date: 09/20/04  
Assessment: \$0 Inspector: WADE Followup Date: 09/22/04  
Gravity: 1 Extend Date:  
Authority Ref: 42 CFR 3162.1(a)

Remarks Date: 09/20/04

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing Onshore Order No. 2, III.A.2.e. Air power was shut off. (Aztec WS #301) Resolved.

Office: FE ID: FE13080  
Unique INC #: 04MOW027 Well Name: NEGRO CANYON  
Well #: 101S ID Date: 09/24/04  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 09/24/04  
Case #: NMNM111921 FAC ID: Abatement Date: 09/24/04  
Form: I FAC NAME: Corrected Date: 09/24/04  
Assessment: \$0 Inspector: WADE Followup Date: 09/27/04  
Gravity: 1 Extend Date:  
Authority Ref: 42 CFR 3162.1(a)

Remarks Date: 09/24/04

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing Onshore Order No. 2, III.A.2.e. Air power was shut off. (Aztec WS #301) this is the second violation of this in 4 days. First was on 9/20/04. Resolved.

Office: FE ID: FE13069  
Unique INC #: 04MOW026 Well Name: NEGRO CANYON  
Well #: 101S ID Date: 09/20/04  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 09/20/04  
Case #: NMNM111921 FAC ID: Abatement Date: 09/20/04  
Form: I FAC NAME: Corrected Date: 09/20/04  
Assessment: \$0 Inspector: WADE Followup Date: 09/22/04  
Gravity: 1 Extend Date:  
Authority Ref: 42 CFR 3162.1(a)

Remarks Date: 09/20/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Fill line not connected while tripping Onshore Order No. 2, III.A.2.a.ii. Resolved.

Office: FE ID: FE13092  
Unique INC #: 04MOW028 Well Name: NEBU  
Well #: 406A  
Operator: DEVON ENERGY PRODUCTION CO LP  
Case #: NMNM78402D FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 1  
Authority Ref: 43 CFR 3162.1(a)

ID Date: 09/30/04  
Effective Date: 09/30/04  
Abatement Date: 09/30/04  
Corrected Date: 09/30/04  
Followup Date: 10/04/04  
Extend Date:

Remarks Date: 09/30/04

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Air and electric were turned off for repairs to air compressor and were not returned to service after repair were completed. Resolved.

Office: FE ID: FE12965  
Unique INC #: 04MOW019 Well Name: SAN JUAN 32-7 UNIT  
Well #: 207A  
Operator: CONOCOPHILLIPS COMPANY  
Case #: NMNM78423A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.C.1.

ID Date: 07/21/04  
Effective Date: 07/21/01  
Abatement Date: 07/22/04  
Corrected Date: 07/22/04  
Followup Date:  
Extend Date:

Remarks Date: 07/21/04

Slow pump speed and pressure not recorded in daily drilling report for each tour. Resolved 7/22/04

Office: FE ID: FE12964  
Unique INC #: 04MOW018 Well Name: SAN JUAN 32-7 UNIT  
Well #: 207A  
Operator: CONOCOPHILLIPS COMPANY  
Case #: NMNM78423A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.d.

ID Date: 07/21/04  
Effective Date: 07/21/01  
Abatement Date: 07/22/04  
Corrected Date: 07/22/04  
Followup Date:  
Extend Date:

Remarks Date: 07/21/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Accumulator working pressure below Minimum acceptable operating pressure found 1100 psi, Minimum acceptable operating pressure 1500 psi. Resolved 7/22/04

Office: FE ID: FE12960  
Unique INC #: 04MOW015 Well Name: SAN JUAN 32-7 UNIT  
Well #: 207A ID Date: 07/21/04  
Effective Date: 07/21/01  
Operator: CONOCOPHILLIPS COMPANY Abatement Date: 07/22/04  
Case #: NMNM78423A FAC ID: Corrected Date: 07/21/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order No. 2, III.A.2.e.

Remarks Date: 07/21/04

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing, electric was turned off. Power was turned back on same day.

Office: FE ID: FE12962  
Unique INC #: 04MOW016 Well Name: SAN JUAN 32-7 UNIT  
Well #: 207A ID Date: 07/21/04  
Effective Date: 07/21/01  
Operator: CONOCOPHILLIPS COMPANY Abatement Date: 07/22/04  
Case #: NMNM78423A FAC ID: Corrected Date: 07/22/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.i.vi

Remarks Date: 07/21/04

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. One choke line not installed. Resolved 7/22/04

Office: FE ID: FE12963  
Unique INC #: 04MOW017 Well Name: SAN JUAN 32-7 UNIT  
Well #: 207A ID Date: 07/21/04  
Effective Date: 07/21/01  
Operator: CONOCOPHILLIPS COMPANY Abatement Date: 07/22/04  
Case #: NMNM78423A FAC ID: Corrected Date: 07/22/04  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.d.

Remarks Date: 07/21/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Accumulator working pressure below Minimum acceptable operating pressure found 1100 psi, Minimum acceptable operating pressure 1500 psi. Resolved 7/22/04

Office: FE ID: FE12961  
Unique INC #: 04MOW014V Well Name: SAN JUAN 32-7 UNIT  
Well #: 207A ID Date: 07/21/04  
Operator: CONOCOPHILLIPS COMPANY Effective Date: 07/21/01  
Case #: NMNMT78423A FAC ID: Abatement Date: 07/22/04  
Form: I FAC NAME: Corrected Date: 07/21/04  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No. 2, III.A.2.i.vi

Remarks Date: 07/21/04

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Kill line valve not tested prior to drilling out of the surface casing shoe. Verbal warning issued.

Office: GR ID: GR1241  
Unique INC #: 043119 Well Name: PR FED  
Well #: 15101 SE 29 ID Date: 09/27/04  
Operator: WARREN E&P, INCORPORATED Effective Date: 09/27/04  
Case #: WYW158218X FAC ID: Abatement Date: 09/27/04  
Form: I FAC NAME: Corrected Date: 09/27/04  
Assessment: \$0 Inspector: DEVOSS Followup Date: 09/29/04  
Gravity: 1 Extend Date:  
Authority Ref: O.O.#2.,A.,e.

Remarks Date: 09/27/04

Air supply to Koomey pump was shut off.

Office: GR ID: GR1166  
Unique INC #: 043042 Well Name: BRADY DEEP UNIT  
Well #: 41-PH0S ID Date: 04/12/04  
Operator: ANADARKO E&P COMPANY LP Effective Date: 04/14/04  
Case #: WYW090922H FAC ID: Abatement Date: 04/23/04  
Form: I FAC NAME: Corrected Date: 04/19/04  
Assessment: \$0 Inspector: FICKLIN Followup Date: 06/24/04  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#6.,III.,D.,3.,a.

Remarks Date: 04/12/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

There are no H2S Warning Signs on the location. Install Warning Signs as required by Onshore Oil and Gas Order #6.

Office: GR ID: GR1165  
Unique INC #: 043041 Well Name: BRADY DEEP UNIT  
Well #: 42-PHOS  
Operator: ANADARKO E&P COMPANY LP  
Case #: WYW090922H FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 3  
Authority Ref: O.O. #6.,III.,D.,3.,a.  
Remarks Date: 04/12/04

There are no H2S Warning Signs on the location. Install Warning Signs as required by Onshore Oil and Gas Order #6.

Office: GR ID: GR1124  
Unique INC #: 043008 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 3  
Authority Ref: OO#1, III, G., 4., a., (5)  
Remarks Date: 11/14/03

Mud weight not as specified in APD. Increase Mud weight to specified range.

Office: GR ID: GR1119  
Unique INC #: 043003 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 3  
Authority Ref: OO#2, III, A., 2., b., iv  
Remarks Date: 11/14/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

No Gauge on Choke manafold. Install mud service gauge on choke manafold.

Office: GR ID: GR1118  
Unique INC #: 043002 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 3  
Authority Ref: OO#2, III, A., 2., a., iii  
Remarks Date: 11/14/03  
Kill line not installed. Install kill line as required.

Office: GR ID: GR1120  
Unique INC #: 043004 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 3  
Authority Ref: OO#2, III, A., 2., g  
Remarks Date: 11/14/03  
Manaul locking devices not installed on blind and pipe rams. Install locking devices on blind and pipe rams.

Office: GR ID: GR1123  
Unique INC #: 043007 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 1  
Authority Ref: OO#2, III, C., 7.  
Remarks Date: 11/14/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Flare lines not anchored. Anchor flare lines.

Office: GR ID: GR1121  
Unique INC #: 0430005 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 3  
Authority Ref: OO#2, III, A., 2., h  
Remarks Date: 11/14/03  
Remote control on floor not operable. Install air to remote control.

Office: GR ID: GR1122  
Unique INC #: 043006 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: FICKLIN  
Gravity: 3  
Authority Ref: OO#2, III, C., 2.  
Remarks Date: 11/14/03  
No visual mud monitoring equipment installed. Install visual mud monitoring equipment.

Office: GR ID: GR1112  
Unique INC #: 043001 Well Name: PRFED (3-30)  
Well #: 15101-3-30  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW131432 FAC ID:  
Form: I FAC NAME:  
Assessment: \$1,000 Inspector: FICKLIN  
Gravity: 1  
Authority Ref: OO#2, III, A, 1  
Remarks Date: 11/14/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

On 11/14/2003 arrived on PR Federal 15101-3-30, WYW131432, SWSW, Sec. 30, T15N, R101W. Found the following: Bolts missing from the flange between drilling spool and well head. Bolts missing from flanges on choke line. No handles on BOPE valves. Choke handle missng. Choke manafold gauge missing. Flare lines not anchored. Kill line not installed. Remote controls on floor not operable (air line not installed). Manual locking devices not installed on blind and pipe rams. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well controll and shall be in place and operational. Install all related (BOPE) equipment as required.

Office: GR		ID: GR1139
Unique INC #: 04022	Well Name: MONELL UNIT	
	Well #: 33-26	
Operator: ANADARKO E&P COMPANY LP		
Case #: 891008645A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: LEAR	
Gravity: 3		
Authority Ref: O.O.2.,III.,A.,2.,c.,xi		

Remarks Date: 02/18/04

All of the above described tests and/or drills shall be recorded in the drilling log. Record BOP test data in IADC Book.

Office: GR		ID: GR1135
Unique INC #: 043019	Well Name: MONELL UNIT	
	Well #: 33-26	
Operator: ANADARKO E&P COMPANY LP		
Case #: 891008645A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: LEAR	
Gravity: 3		
Authority Ref: O.O.2.III.,A.,2.,g.		

Remarks Date: 02/18/04

Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automiatic locking devices shall be installed on all systems of 2M or greater. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative. Install locking device (hand wheels) on the pipe rams and the blind rams of the BOP.

Office: GR		ID: GR1149
Unique INC #: 043025	Well Name: MONELL UNIT	
	Well #: 33-26	
Operator: ANADARKO E&P COMPANY LP		
Case #: 891008645A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: LEAR	
Gravity: 3		
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 02/18/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The operating rights owner or operator, as appropriate, shall comply with applicable laws and regulations; with the lease terms, Onshore Oil and Gas Orders, NTL's; and with other orders and instructions of the authorized officer. As stated in the Conditions of Approval: Drilling/Completion/Producing Operating Standards, #6 A BOPE pit level drill shall be conducted by each drilling crew within 24 hours of drilling out from under the surface casing and weekly thereafter.

Office: GR ID: GR1137  
Unique INC #: 043021 Well Name: MONELL UNIT  
Well #: 33-26  
Operator: ANADARKO E&P COMPANY LP  
Case #: 891008645A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR  
Gravity: 3  
Authority Ref: O.O.2.III.,A.,2.,a.,iii.

Remarks Date: 02/18/04  
Pressure gauge on choke manifold. Install pressure gauge on choke manifold.

Office: GR ID: GR1136  
Unique INC #: 043020 Well Name: MONELL UNIT  
Well #: 33-26  
Operator: ANADARKO E&P COMPANY LP  
Case #: 891008645A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR  
Gravity: 1  
Authority Ref: O.O.2.,III.,2.,a.,iii

Remarks Date: 02/18/04  
Choke line valves not in operating condition. Install hand wheels on valves

Office: GR ID: GR1148  
Unique INC #: 043024 Well Name: MONELL UNIT  
Well #: 33-26  
Operator: ANADARKO E&P COMPANY LP  
Case #: 891008645A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LEAR  
Gravity: 3  
Authority Ref: O.O.2.III.,C.,1.

Remarks Date: 02/18/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Record slow pump speed on daily drilling report after mudding up. Record slow pump speed (kill speed) on IADC report book.

Office: GR ID: GR1134  
Unique INC #: 043018 Well Name: MONELL UNIT  
Well #: 33-26 ID Date: 02/18/04  
Operator: ANADARKO E&P COMPANY LP Effective Date: 02/18/04  
Case #: 891008645A FAC ID: Abatement Date: 02/19/04  
Form: I FAC NAME: Corrected Date: 02/18/04  
Assessment: \$0 Inspector: LEAR Followup Date: 02/19/04  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2.,III.,2.,b.,i.

Remarks Date: 02/18/04

All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, and shall be anchored to prevent whip and reduce vibration. Effectively anchor flare lines to prevent whipping and reduce vibrations.

Office: GR ID: GR1138  
Unique INC #: 043022 Well Name: MONELL UNIT  
Well #: 33-26 ID Date: 02/18/04  
Operator: ANADARKO E&P COMPANY LP Effective Date: 02/18/04  
Case #: 891008645A FAC ID: Abatement Date: 02/19/04  
Form: I FAC NAME: Corrected Date: 02/18/04  
Assessment: \$0 Inspector: LEAR Followup Date: 01/19/04  
Gravity: 3 Extend Date:  
Authority Ref: O.O.2.III.,A.,2.,h.

Remarks Date: 02/18/04

Remote controls shall be readily accessible to the driller. Remote controls for all 3M or greater systems shall be capable of closing all preventers. Hook up remote controls on drill floor.

Office: GR ID: GR1200  
Unique INC #: 20040708 Well Name: DEBRUGGE  
Well #: 2-1 ID Date: 07/08/04  
Operator: INFINITY OIL & GAS OF WYOMING Effective Date: 07/08/04  
Case #: WYW028211 FAC ID: Abatement Date: 07/09/04  
Form: I FAC NAME: Corrected Date: 07/08/04  
Assessment: \$0 Inspector: TONER Followup Date: 07/08/04  
Gravity: 3 Extend Date:  
Authority Ref: o.o.#2.,III.,A.,1.

Remarks Date: 07/08/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The safety valve was not maintained in place during drilling operations.

Office: GR	Well Name: RHODE ISLAND RED FEDERAL	ID: GR1179
Unique INC #: 043055	Well #: 4-27	ID Date: 05/17/04
Operator: BALLARD PETROLEUM HOLDINGS LLC	FAC ID:	Effective Date: 05/17/04
Case #: WYW158659	FAC NAME:	Abatement Date: 05/19/04
Form: I	Inspector: TONER	Corrected Date: 05/19/04
Assessment: \$0		Followup Date: 05/19/04
Gravity: 3		Extend Date:
Authority Ref: OO&GO#2.III A. 2. b.ii		

Remarks Date: 05/17/04

While performing a Drilling Inspection, BLM inspector Casey Toner found the following violations according to Onshore Oil and Gas Order #2: 1. Choke manifold not configured to approved specifications.

Office: GS	Well Name: FEDERAL	ID: GS4998
Unique INC #: CS04026V	Well #: GM 341-8	ID Date: 05/14/04
Operator: WILLIAMS PRODUCTION RMT CO	FAC ID:	Effective Date: 05/14/04
Case #: COC49043	FAC NAME:	Abatement Date: 06/14/04
Form: I	Inspector: SNYDER	Corrected Date: 05/28/04
Assessment: \$0		Followup Date: 05/28/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 05/14/04

WELL SITE IS NOT PROPERLY IDENTIFIED. INSTALL A SIGN WITH THE NAME OF THE OPERATOR, LEASE/SERIAL NUMBER, SURVEYED DESCRIPTION (QUARTER/QUARTER), SECTION, TOWNSHIP AND RANGE.

Office: GS	Well Name: FEDERAL	ID: GS4999
Unique INC #: CS04027V	Well #: GM 341-8	ID Date: 05/14/04
Operator: WILLIAMS PRODUCTION RMT CO	FAC ID:	Effective Date: 05/14/04
Case #: COC49043	FAC NAME:	Abatement Date: 05/14/04
Form: I	Inspector: SNYDER	Corrected Date: 05/14/04
Assessment: \$0		Followup Date: 05/14/04
Gravity: 3		Extend Date:
Authority Ref: ONSHORE ORDER NO. 2 III.A.1.		

Remarks Date: 05/14/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

THE OPERATOR IS REQUIRED TO CONDUCT ALL OPERATIONS IN A SAFE AND WORKMANLIKE MANNER. THE OBSERVED EQUIPMENT AND ARRANGEMENT IS NOT EQUIVALENT TO AT LEAST WHAT HAD ORIGINALLY BEEN APPROVED. (VALVE IS NOT INSTALLED IN CLOSING LINE OF ANNULAR PREVENTER.)

Office: GS ID: GS5000  
Unique INC #: CS04028V Well Name: FEDERAL  
Well #: GM 341-8  
Operator: WILLIAMS PRODUCTION RMT CO  
Case #: COC49043 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SNYDER  
Gravity: 3  
Authority Ref: ONSHORE ORDER NO. 2 A.2.(g)

Remarks Date: 05/14/04

THE OPERATOR IS REQUIRED TO CONDUCT ALL OPERATIONS IN A SAFE AND WORKMANLIKE MANNER. THE AUTOMATIC CONTROLS ARE NOT INSTALLED OR FUNCTIONAL. (HANDWHEELS ARE NOT INSTALLED ON BOPE).

Office: GS ID: GS5046  
Unique INC #: CS04045 Well Name: HMU  
Well #: 19-3B (F19)  
Operator: ENCANA OIL & GAS (USA) INC  
Case #: COC55972E FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SNYDER  
Gravity: 3  
Authority Ref: 43 CFR 3162.3-2(a)

Remarks Date: 06/22/04

A PROPOSAL FOR FURTHER WELL OPERATIONS SHALL BE SUBMITTED BY THE OPERATOR ON FORM 3160-5 FOR APPROVAL BY THE AUTHORIZED OFFICER PRIOR TO COMMENCING OPERATIONS. (CHANGE OF PLANS ON APD FOR APPROVED DEPTH FOR SETTING SURFACE CASING WAS NOT SUBMITTED BEFORE OPERATIONS COMMENCED; APD STATED 840' TD - CHANGED TO 1725' TD.)

Office: HO ID: HO9846  
Unique INC #: SJC-95-04 Well Name: ALLIED 93  
Well #: 01  
Operator: DUGAN PRODUCTION CORPORATION  
Case #: NMNM0103893 FAC ID: A  
Form: I FAC NAME: ALLIED 93  
Assessment: \$0 Inspector: CAFFEY  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 / OO&GO#6 III.D.c.2

Remarks Date: 05/13/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

H2S concentration in the Stock tanks is in excess of 500 ppm. Batterys do not have proper warning signs. - Install proper warning signs and chain or mark all stairs and ladders leading to top of tanks. See attached regulation for specific requirements. Failure to comply may result in monetary assessments.

Office: HO ID: HO9845  
Unique INC #: ASC-132-04 Well Name:  
Well #: ID Date: 05/13/04  
Operator: DUGAN PRODUCTION CORPORATION Effective Date:  
Case #: NMLC065151 FAC ID: A, B Abatement Date: 06/17/04  
Form: I FAC NAME: BILBREY 23 BATTERY, BILBREY 51 B, Corrected Date: 06/04/04  
Assessment: \$0 Inspector: CORTEZ Followup Date: 06/16/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 / OO&GO#6 III.D.c.2

Remarks Date: 05/13/04

H2S concentration in the Stock tanks is in excess of 500 ppm. Batterys do not have proper warning signs. - Install proper warning signs and chain or mark all stairs and ladders leading to top of tanks. See attached regulation for specific requirements. Failure to comply may result in monetary assessments.

Office: HO ID: HO9842  
Unique INC #: ASC-129-04 Well Name:  
Well #: ID Date: 05/13/04  
Operator: DUGAN PRODUCTION CORPORATION Effective Date:  
Case #: NMLC068035 FAC ID: A Abatement Date: 06/17/04  
Form: I FAC NAME: BROWN 35 BATTERY Corrected Date: 06/04/04  
Assessment: \$0 Inspector: CORTEZ Followup Date: 06/16/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 / OO&GO#6 III.D.c.2.

Remarks Date: 05/13/04

H2S concentration in the Stock tanks is in excess of 500 ppm. Batterys do not have proper warning signs. - Install proper warning signs and chain or mark all stairs and ladders leading to top of tanks. See attached regulation for specific requirements. Failure to comply may result in monetary assessments.

Office: HO ID: HO9843  
Unique INC #: ASC-130-04 Well Name:  
Well #: ID Date: 05/13/04  
Operator: DUGAN PRODUCTION CORPORATION Effective Date:  
Case #: NMNM066884A FAC ID: A Abatement Date: 06/17/04  
Form: I FAC NAME: BROWN 84 BATTERY Corrected Date: 06/04/04  
Assessment: \$0 Inspector: CORTEZ Followup Date: 06/16/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 / OO&GO#6 III.D.c.2.

Remarks Date: 05/13/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

H2S concentration in the Stock tanks is in excess of 500 ppm. Batterys do not have proper warning signs. - Install proper warning signs and chain or mark all stairs and ladders leading to top of tanks. See attached regulation for specific requirements. Failure to comply may result in monetary assessments.

Office: HO		ID: HO8629
Unique INC #: ASC-007-04	Well Name:	
	Well #:	
Operator: SOUTHWEST ROYALTIES INC		
Case #: NMNM14204	FAC ID: A, B	
Form: I	FAC NAME: GONZALES FED. 31 BATTERY, GONZ/	
Assessment: \$0	Inspector: CORTEZ	
Gravity: 3		
Authority Ref: 43 CFR 3164.1 / OO&GO#6 III.D.a.&e.		

Remarks Date: 10/02/03

Wind socks are missing from holder. - Replace the wind socks on both batterys. Failure to comply may result in monetary assessments.

Office: HO		ID: HO9844
Unique INC #: ASC-131-04	Well Name:	
	Well #:	
Operator: DUGAN PRODUCTION CORPORATION		
Case #: NMNM16369	FAC ID: A	
Form: I	FAC NAME: YATES 69 BATTERY	
Assessment: \$0	Inspector: CORTEZ	
Gravity: 3		
Authority Ref: 43 CFR 3164.1 / OO&GO#6 III.D.c.2		

Remarks Date: 05/13/04

H2S concentration in the Stock tanks is in excess of 500 ppm. Batterys do not have proper warning signs. - Install proper warning signs and chain or mark all stairs and ladders leading to top of tanks. See attached regulation for specific requirements. Failure to comply may result in monetary assessments.

Office: HO		ID: HO9248
Unique INC #: DEG-058-04	Well Name: RED HILLS NORTH UNIT	
	Well #: 309	
Operator: EOG RESOURCES INCORPORATED		
Case #: NMNM104037X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: GEYER	
Gravity: 3		
Authority Ref: 43CFR3162.4-1(a)		

Remarks Date: 02/12/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Violation: Failure to submit requested information. Corrective Action: Submit accumulator recharge report.

Office: HO	Well Name: STRING BEAN FEDERAL COM	ID: HO9130
Unique INC #: DEG-035-04	Well #: 1	ID Date: 02/02/04
Operator: MARBOB ENERGY CORPORATION	FAC ID:	Effective Date: 02/03/04
Case #: NMNM35612	FAC NAME:	Abatement Date: 02/23/04
Form: I	Inspector: GEYER	Corrected Date: 02/09/04
Assessment: \$0		Followup Date: 02/10/04
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.4-1(a)		

Remarks Date: 02/02/04

Please submit 5.5 inch production casing tally.

Office: HO	Well Name:	ID: HO8704
Unique INC #: KAH-012-04	Well #:	ID Date: 10/15/03
Operator: CAMPBELL & HEDRICK	FAC ID: A	Effective Date: 10/21/03
Case #: NMLC032096A	FAC NAME: LOCKHART	Abatement Date: 11/23/03
Form: I	Inspector: HASTON	Corrected Date: 11/20/03
Assessment: \$0		Followup Date: 11/20/03
Gravity: 3		Extend Date:
Authority Ref: OOGO #6.III.D.2.e		

Remarks Date: 10/15/03

NO WIND DIRECTION INDICATOR INSTALLED AT BATTERY. - INSTALL A WIND DIRECTION INDICATOR AT THIS BATTERY. FAILURE TO COMPLY WITHIN ABATEMENT PERIOD MAY RESULT IN THE ISSUANCE OF MONETARY ASSESSMENTS

Office: HO	Well Name:	ID: HO8729
Unique INC #: KAH-017-04	Well #:	ID Date: 10/21/03
Operator: CAMPBELL & HEDRICK	FAC ID: A	Effective Date: 10/28/03
Case #: NMLC032591C	FAC NAME: HARDY FEDERAL	Abatement Date: 11/28/03
Form: I	Inspector: HASTON	Corrected Date: 11/10/03
Assessment: \$0		Followup Date: 11/10/03
Gravity: 3		Extend Date:
Authority Ref: OOGO #6.III.D.2.e		

Remarks Date: 10/21/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

NO WIND DIRECTION INDICATOR INSTALLED AT BATTERY. - INSTALL A WIND DIRECTION INDICATOR AT THIS BATTERY.

Office: HO ID: HO8809  
Unique INC #: JCM-001-04 Well Name: FARNSWORTH A  
Well #: 04 ID Date: 11/10/03  
Effective Date: 11/15/03  
Operator: SOUTHWEST ROALTIES INC Abatement Date: 12/06/03  
Case #: NMLC030180A FAC ID: Corrected Date: 11/25/03  
Form: I FAC NAME: Followup Date: 12/02/03  
Assessment: \$0 Inspector: MCCORMICK Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 a&b  
Remarks Date: 11/10/03

There was no well sign on location to properly identify the site. Install a sign with proper identification on well site within abatement period. Failure to comply will result in monetary assessments.

Office: HO ID: HO9868  
Unique INC #: JCM-093-04 Well Name: RIO BLANCO 33 FED  
Well #: 02 ID Date: 05/23/04  
Effective Date: 05/23/04  
Operator: DEVON ENERGY CORPORATION Abatement Date: 05/23/04  
Case #: NMNM111769 FAC ID: Corrected Date: 05/23/04  
Form: I FAC NAME: Followup Date: 05/23/04  
Assessment: \$0 Inspector: MCCORMICK Extend Date:  
Gravity: 3  
Authority Ref: APD General Requirements III 1.  
Remarks Date: 05/23/04

Failure to comply with APD General Requirements to have a well sign at above stated location from spud date. A temporary cardboard sign was made and erected on location when the violation was detected. Ensure all future wells comply with all APD general requirements that apply, see attached requirements. Failure to comply will result in monetary assessment.

Office: JA ID: JA1850  
Unique INC #: CRB-04-020 Well Name: USA  
Well #: 36-ALT ID Date: 07/06/04  
Effective Date: 07/06/04  
Operator: HUNT PETROLEUM CORPORATION Abatement Date: 07/06/04  
Case #: LABLMA54490 FAC ID: Corrected Date: 07/06/04  
Form: I FAC NAME: Followup Date: 07/06/04  
Assessment: \$0 Inspector: CHARLES R BOYD Extend Date:  
Gravity: 1  
Authority Ref: Onshore Oil & Gas Order #2 Part III.A.2.e  
Remarks Date: 07/06/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

POWER FOR CLOSING UNIT PUMPS SHALL BE AVAILABLE TO THE UNIT AT ALL TIMES. AIR VALVE FROM TANK TO UNIT WAS FOUND IN CLOSED POSITION. OPERATOR IS ORDERED TO OPEN VALVE TO PROVIDE AIR FOR CLOSING UNIT PUMPS.

Office: ME ID: ME2035  
Unique INC #: 04BK03MEFO Well Name: PICEANCE CREEK UNIT  
Well #: T18X-12G1  
Operator: EXXON MOBIL CORP ID Date: 03/28/04  
Case #: COC47666A Effective Date: 03/30/04  
Form: I Abatement Date: 03/31/04  
Assessment: \$250 FAC ID: Corrected Date: 03/31/04  
Gravity: 3 FAC NAME: Followup Date: 04/01/04  
Inspector: KRAFT Extend Date:  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 03/28/04

Failure to comply with Onshore Order #2,III,c,iii. The fluid reservoir capacity shall be double the usable fluid volume of the accumulater system capacity, and on a 5M system with the third ram an additional 50 percent safety factor will be used.

Office: ME ID: ME2036  
Unique INC #: 04BK04MEFO Well Name: PINTO GULCH FEDERAL  
Well #: T68X-18G  
Operator: EXXON MOBIL CORP ID Date: 03/30/04  
Case #: COC58002 Effective Date: 03/30/04  
Form: I Abatement Date: 03/31/04  
Assessment: \$250 FAC ID: Corrected Date: 03/31/04  
Gravity: 3 FAC NAME: Followup Date: 04/01/04  
Inspector: KRAFT Extend Date:  
Authority Ref: 43CFR3162.1\*-(a)

Remarks Date: 03/30/04

Failure to comply with Onshore Order #2,III,c,iii. The fluid reservoir capacity shall be double the usable fluid volume of the accumulater system capacity, and on a 5M system with the third ram an additional 50 percent safety factor will be used.

Office: ME ID: ME2077  
Unique INC #: 04BK19MEFO Well Name: FIGURE FOUR UNIT  
Well #: 8008B A24 498  
Operator: ENCANA OIL & GAS (USA) INC ID Date: 07/27/04  
Case #: COC66492X Effective Date: 07/27/04  
Form: I Abatement Date: 07/27/04  
Assessment: \$0 FAC ID: Corrected Date: 07/27/04  
Gravity: 3 FAC NAME: Followup Date: 07/27/04  
Inspector: KRAFT Extend Date:  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 07/27/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Failure to comply with the approved APD, to notify the BLM 24 hours prior to running the production casing.

Office:	ME	ID:	ME2078
Unique INC #:	04BK20MEFO	Well Name:	FIGURE FOUR UNIT
		Well #:	8008B A24 498
Operator:	ENCANA OIL & GAS (USA) INC	ID Date:	07/27/04
Case #:	COC66492X	Effective Date:	07/27/04
Form:	I	Abatement Date:	07/27/04
Assessment:	\$0	Corrected Date:	07/27/04
Gravity:	3	Followup Date:	07/27/04
Authority Ref:	43CFR3162.1-(a)	Extend Date:	

Remarks Date: 07/27/04

Failure to comply with the approved APD, to notify the BLM 24 hours prior to cementing the production casing.

Office:	ME	ID:	ME2027
Unique INC #:	03MM57MEFO	Well Name:	FEDERAL
		Well #:	12-18
Operator:	TWIN ARROW INCORPORATED	ID Date:	10/02/03
Case #:	COC10551	Effective Date:	10/03/03
Form:	I	Abatement Date:	
Assessment:	\$0	Corrected Date:	10/09/03
Gravity:	3	Followup Date:	10/23/03
Authority Ref:	43 CFR 3163.1(a)	Extend Date:	

Remarks Date: 10/02/03

The approved APD states the BLM is to be notified 24 hours prior to pumping surface cement. Twin Arrow, Inc failed to provide this information.

Office:	ME	ID:	ME2029
Unique INC #:	03MM59MEFO	Well Name:	FEDERAL
		Well #:	12-18
Operator:	TWIN ARROW INCORPORATED	ID Date:	10/02/03
Case #:	COC10551	Effective Date:	10/03/03
Form:	I	Abatement Date:	
Assessment:	\$0	Corrected Date:	10/09/03
Gravity:	3	Followup Date:	10/23/03
Authority Ref:	43 CFR 3163.1(a)	Extend Date:	

Remarks Date: 10/02/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The approved APD states the BLM is to be notified 24 hours prior to testing the BOP system. Twin Arrow, Inc failed to provide this information.

Office: ME	Well Name: FEDERAL	ID: ME2028
Unique INC #: 03MM58MEFO	Well #: 12-18	ID Date: 10/02/03
Operator: TWIN ARROW INCORPORATED	FAC ID:	Effective Date: 10/03/03
Case #: COC10551	FAC NAME:	Abatement Date:
Form: I	Inspector: O'MARA	Corrected Date: 10/09/03
Assessment: \$0		Followup Date: 10/23/03
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 10/02/03

The approved APD states the BLM is to be notified 24 hours prior to pumping production cement. Twin Arrow, Inc failed to provide this information.

Office: ME	Well Name: FIGURE FOUR UNIT	ID: ME2030
Unique INC #: 04MM01MEFO	Well #: 8009B I25 498	ID Date: 10/16/03
Operator: ENCANA OIL & GAS (USA) INC	FAC ID:	Effective Date: 11/26/03
Case #: COC66492X	FAC NAME:	Abatement Date:
Form: I	Inspector: O'MARA	Corrected Date: 11/26/03
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3163.1(a)		

Remarks Date: 10/16/03

The APD was approved with a DV tool during the surface cementing operations. No DV tool was used.

Office: ML	Well Name: PINE	ID: ML3286
Unique INC #: IH441-1	Well #: 24-30EH	ID Date: 05/21/04
Operator: ENCORE OPERATING LP	FAC ID:	Effective Date: 05/21/04
Case #: MTM87125	FAC NAME:	Abatement Date: 06/01/04
Form: I	Inspector: HARRIS/DEVAULT	Corrected Date: 05/28/04
Assessment: \$0		Followup Date: 06/02/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a) and	43 CFR 3162.5-1(a)	

Remarks Date: 05/21/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The 7" 29# intermediate casing was not run according to the Conditions of Approval on the APD. The Conditions of Approval stated that HCL80/LTC casing must be run from 5200' to 6150'. According to a field inspection conducted on May 21, 2004, 7" 29# P110 casing was run from 5286' to 5983'. The company representative on location was informed of this. Prior to the drilling of other wells, the Conditions of Approval with the APD must be read and followed.

Office: NE ID: NE3403  
Unique INC #: JDH04002DI Well Name: WYNIA  
Well #: 32-15-2 ID Date: 10/28/03  
Effective Date: 10/28/03  
Operator: L & J OPERATING INCORPORATED Abatement Date: 10/29/03  
Case #: WYW029374 FAC ID: Corrected Date: 10/29/03  
Form: I FAC NAME: Followup Date: 10/31/03  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 10/28/03

A copy of the approved drilling plan must be on location. I discussed this with Tom Knight and he will have a copy onsite by 10/29/2003. Please sign and return white copy of INC when corrections are made.

Office: NE ID: NE3405  
Unique INC #: JDH04004DI Well Name: WYNIA  
Well #: 32-15-2 ID Date: 10/28/03  
Effective Date: 10/28/03  
Operator: L & J OPERATING INCORPORATED Abatement Date: 10/29/03  
Case #: WYW029374 FAC ID: Corrected Date: 10/29/03  
Form: I FAC NAME: Followup Date: 10/31/03  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 10/28/03

The reserve pit is not fenced on three sides as required by the APD. I discussed this with Tom Knight and he will have the reserve pit fenced by 10/29/2003. Since this is only a day light operation, in addition to fencing the reserve pit on three sides, the fence should be constructed in such a way as to prevent entry by wildlife and livestock when drilling personnel are not on site. Please sign and return white copy of INC when corrections are made.

Office: NE ID: NE3406  
Unique INC #: JDH04005DI Well Name: WYNIA  
Well #: 32-15-2 ID Date: 11/05/03  
Effective Date: 11/05/03  
Operator: L & J OPERATING INCORPORATED Abatement Date: 11/12/03  
Case #: WYW029374 FAC ID: Corrected Date: 10/29/03  
Form: I FAC NAME: Followup Date: 10/31/03  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1

Remarks Date: 11/05/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The access road to the well site was not constructed as approved. Specifically, the access road was constructed along an existing pipeline right-of-way instead of along the ridge line to the south as was approved in the Application for Permit to Drill. (APD) Please file a sundry notice stating this change by 12 November 2003. If you have any questions concerning this issue, please contact Rod Randall or Jim Hutchinson at 307-746-6600. Map enclosed.

Office: NE ID: NE3404  
Unique INC #: JDH04003DI Well Name: WYNIA  
Well #: 32-15-2 ID Date: 10/28/03  
Effective Date: 10/28/03  
Operator: L & J OPERATING INCORPORATED Abatement Date: 10/29/03  
Case #: WYW029374 FAC ID: Corrected Date: 10/29/03  
Form: I FAC NAME: Followup Date: 10/31/03  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6

Remarks Date: 10/28/03

There is not a well sign at the well site. I discussed this with Tom Knight and he will have a well sign in place by 10/29/2003. Please sign and return white copy of INC when corrections are made.

Office: NE ID: NE3498  
Unique INC #: JDH04058DI Well Name: GREASEWOOD  
Well #: #9 ID Date: 06/02/04  
Effective Date: 06/02/04  
Operator: O'BRIEN ENERGY RESOURCES CORP. Abatement Date: 06/03/04  
Case #: WYW147251 FAC ID: Corrected Date: 06/03/04  
Form: I FAC NAME: Followup Date: 06/03/04  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 Onshore Order No. 2 III. A.2.g.

Remarks Date: 06/02/04

The hand wheels for the manual locking device were not installed on the ram preventers. The Onshore Order does require these hand wheels to be in place. Will be corrected by Carl Jessup and Melvin Patnaude of Cyclone Drilling Company by 06/03/2004.

Office: NE ID: NE3499  
Unique INC #: JDH04059DI Well Name: GREASEWOOD  
Well #: #9 ID Date: 06/02/04  
Effective Date: 06/02/04  
Operator: O'BRIEN ENERGY RESOURCES CORP. Abatement Date: 06/03/04  
Case #: WYW147251 FAC ID: Corrected Date: 06/03/04  
Form: I FAC NAME: Followup Date: 06/03/04  
Assessment: \$0 Inspector: HUTCHINSON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 Onshore Order No. 2 III. A.2.a.ii.

Remarks Date: 06/02/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The kill line was not connected to the kill side of the BOP stack. The Onshore Order does require the kill line to be connected to the kill side of the BOP stack. Will be corrected by Carl Jessup and Melvin Patnaude of Cyclone Drilling Company by 06/03/2004.

Office: NE ID: NE3496  
Unique INC #: JDH04056DI Well Name: GREASEWOOD  
Well #: #9 ID Date: 06/02/04  
Operator: O'BRIEN ENERGY RESOURCES CORP. Effective Date: 06/02/04  
Case #: WYW147251 FAC ID: Abatement Date: 06/02/04  
Form: I FAC NAME: Corrected Date: 06/02/04  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 06/02/04  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1 Onshore Order No. 2 III. A.2.e  
Remarks Date: 06/02/04

The power was turned off to the accumulator pump on the BOPE system. The accumulator pressure reading was zero on all gauges. Power to the accumulator pumps must be available to the unit at all times. Corrected upon request by Carl Jessup and Melvin Patnaude of Cyclone Drilling Company.

Office: NE ID: NE3500  
Unique INC #: JDH04060DI Well Name: GREASEWOOD  
Well #: #9 ID Date: 06/02/04  
Operator: O'BRIEN ENERGY RESOURCES CORP. Effective Date: 06/02/04  
Case #: WYW147251 FAC ID: Abatement Date: 06/03/04  
Form: I FAC NAME: Corrected Date: 06/03/04  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 06/03/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 Onshore Order No. 2 III. A.2.h.xi.  
Remarks Date: 06/02/04

BOP test pressures, casing test pressures and BOP drills not recorded in IADC drilling log. The Onshore Order does require these items to be recorded in the drilling log. Will be corrected by Carl Jessup and Melvin Patnaude of Cyclone Drilling Company by 06/03/2004.

Office: NE ID: NE3501  
Unique INC #: JDH04061DI Well Name: GREASEWOOD  
Well #: #9 ID Date: 06/02/04  
Operator: O'BRIEN ENERGY RESOURCES CORP. Effective Date: 06/02/04  
Case #: WYW147251 FAC ID: Abatement Date: 06/03/04  
Form: I FAC NAME: Corrected Date: 06/03/04  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 06/03/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6(a)  
Remarks Date: 06/02/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The drill site was not properly identified. The cardboard well sign was illegible. Will be corrected by Carl Jessup and Melvin Patnaude of Cyclone Drilling Company by 06/03/2004.

Office: NE ID: NE3497  
Unique INC #: JDH04057DI Well Name: GREASEWOOD  
Well #: #9 ID Date: 06/02/04  
Operator: O'BRIEN ENERGY RESOURCES CORP. Effective Date: 06/02/04  
Case #: WYW147251 FAC ID: Abatement Date: 06/03/04  
Form: I FAC NAME: Corrected Date: 06/03/04  
Assessment: \$0 Inspector: HUTCHINSON Followup Date: 06/03/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 Onshore Order No. 2 III. A.2.b.iv.

Remarks Date: 06/02/04

There was not a pressure gauge installed in the choke manifold. The Onshore Order does require a mud service gauge installed in the choke manifold. Will be corrected by Carl Jessup and Melvin Patnaude of Cyclone Drilling Company by 06/03/2004.

Office: PD ID: PD1385  
Unique INC #: 11DWF92204 Well Name: MESA  
Well #: 6-6 ID Date: 09/22/04  
Operator: QUESTAR EXPL & PROD CO PNDL Effective Date: 09/27/04  
Case #: WYW08589 FAC ID: Abatement Date: 09/28/04  
Form: I FAC NAME: Corrected Date: 09/28/04  
Assessment: \$0 Inspector: FALLON/WILLIS Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: O.O.#2.III.A.2.V

Remarks Date: 09/22/04

On a 10M BOP and BOPE system, the remote kill line (2 inch minimum) shall run to the outer edge of the substructure and be unobstructed.

Office: PD ID: PD1383  
Unique INC #: WW-04-05 Well Name: MESA  
Well #: 6-18 ID Date: 09/21/04  
Operator: ANSCHUTZ PINEDALE CORP Effective Date: 09/22/04  
Case #: WYW135123 FAC ID: Abatement Date: 09/28/04  
Form: I FAC NAME: Corrected Date: 09/28/04  
Assessment: \$0 Inspector: FALLON/WILLIS Followup Date: 09/29/04  
Gravity: 3 Extend Date:  
Authority Ref:

Remarks Date: 09/21/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

The well APD indicated BOP test charts shall be recorded in the drilling log and test charts, with individual test results identified shall be maintained on location while drilling and shall be maintained on location while drilling and shall be made available to a BLM representative upon request. The above charts were not recorded nor available on location or made available to a BLM representative. Corrective action: Maintain record as per well APD.

Office: PD		ID: PD1353
Unique INC #: WW-04-02	Well Name: ANTELOPE	
	Well #: 5-5	ID Date: 08/31/04
Operator: STONE ENERGY CORP		Effective Date: 09/01/04
Case #: WYW133051	FAC ID:	Abatement Date: 09/02/04
Form: I	FAC NAME:	Corrected Date: 09/02/04
Assessment: \$0	Inspector: WILLIS	Followup Date: 09/02/04
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 2.III.A.2.g		

Remarks Date: 08/31/04

During detailed inspection observed valve in the closing line of the annular preventor was not installed. Noted valve installed in open line. "Onshore order requires"....A valve shall be installed in the closing line as close as possible to the annular preventor to act as a locking device. Corrective action: install the equipment as specified.

Office: RP		ID: iRP4920
Unique INC #: 04-RAR-001	Well Name: JICARILLA	
	Well #: 5C	ID Date: 04/14/04
Operator: ENERGEN RESOURCES CORP		Effective Date: 04/14/04
Case #: JIC94	FAC ID:	Abatement Date: 04/14/04
Form: I	FAC NAME:	Corrected Date: 04/20/04
Assessment: \$0	Inspector: ROMERO	Followup Date: 04/20/04
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 04/14/04

During drilling rig inspection it was noted that drill/well site was not identified. \*\*Company (Aztec) representative Joel Muniz then installed a temporary paper sign pending the arrival of permanent well sign. All wells located on Federal and Indian lands shall have a well identification sign. The sign must include all information outlined per 43 CFR 3162.6(b). Please contact this office if further information is needed. RAR

Office: RW		ID: RW3032
Unique INC #: WA04-01	Well Name: STANDARD DRAW	
	Well #: 14-1R	ID Date: 10/27/03
Operator: WESTPORT OIL & GAS CO LP		Effective Date: 11/01/03
Case #: WYW110278	FAC ID:	Abatement Date: 12/15/03
Form: I	FAC NAME:	Corrected Date: 11/14/03
Assessment: \$0	Inspector: ASHLINE	Followup Date: 11/24/03
Gravity: 3		Extend Date:
Authority Ref: 43CFR 3162.6(a)		

Remarks Date: 10/27/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Site not properly identified. No sign.

Office: RW ID: RW3026  
Unique INC #: CT-005-R04 Well Name: ROBBERS GULCH  
Well #: 9-23  
Operator: DEVON ENERGY PRODUCTION CO LP  
Case #: WYW110369 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: Onshore Order # 2 III. A. g.  
  
Remarks Date: 10/14/03  
Floor safety valve is closed. Open the floor valve.

Office: RW ID: RW3025  
Unique INC #: CT-004-R04 Well Name: ROBBERS GULCH  
Well #: 9-23  
Operator: DEVON ENERGY PRODUCTION CO LP  
Case #: WYW110369 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: Onshore Order # 2 III. A. 2. g.  
  
Remarks Date: 10/14/03  
Install all BOP handwheels.

Office: RW ID: RW3034  
Unique INC #: CT-012-R04 Well Name: WEST WILD ROSE FEDERAL  
Well #: 11-10  
Operator: FOREST OIL CORPORATION  
Case #: WYW124401 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: Onshore Order # 2 III. A. 2. e.  
  
Remarks Date: 10/28/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Air is shut off to the Koomy air pumps. Open and keep open the air valve to the Koomy air pumps.

Office: RW ID: RW3035  
Unique INC #: CT-013-R04 Well Name: WEST WILD ROSE FEDERAL  
Well #: 11-10 ID Date: 10/28/03  
Operator: FOREST OIL CORPORATION Effective Date: 10/28/03  
Case #: WYW124401 FAC ID: Abatement Date: 11/16/03  
Form: I FAC NAME: Corrected Date: 10/28/03  
Assessment: \$0 Inspector: THOMAS Followup Date: 10/28/03  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. 2. G.  
  
Remarks Date: 10/28/03  
BOP hand wheels not installed. Install BOP hand wheels.

Office: RW ID: RW3033  
Unique INC #: CT-011-R04 Well Name: WEST WILD ROSE FEDERAL  
Well #: 11-10 ID Date: 10/28/03  
Operator: FOREST OIL CORPORATION Effective Date: 10/28/03  
Case #: WYW124401 FAC ID: Abatement Date: 11/16/03  
Form: I FAC NAME: Corrected Date: 11/16/03  
Assessment: \$0 Inspector: THOMAS Followup Date: 11/16/03  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-1 (a)  
  
Remarks Date: 10/28/03  
Access road is not graveled. As per the conditions of approval in the APD the access road will be surfaced with 4" of gravel PRIOR to moving in the drilling rig on to the pad.

Office: RW ID: RW3027  
Unique INC #: CT-006-R04 Well Name: GAMBLERS RESERVOIR FEDERAL  
Well #: 14-33 ID Date: 10/17/03  
Operator: TOM BROWN INC Effective Date: 10/17/03  
Case #: WYW132972 FAC ID: Abatement Date: 10/25/03  
Form: I FAC NAME: Corrected Date: 10/22/03  
Assessment: \$0 Inspector: THOMAS Followup Date: 10/22/03  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. b. i.  
  
Remarks Date: 10/17/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Choke line between BOP and choke manifold has a wellded turn in the line. All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, and shall be anchored to prevent whip and reduce vibration.

Office: RW ID: RW3029  
Unique INC #: CT-008-R04 Well Name: GAMBLERS RESERVOIR FEDERAL  
Well #: 14-33 ID Date: 10/17/03  
Operator: TOM BROWN INC Effective Date: 10/17/03  
Case #: WYW132972 FAC ID: Abatement Date: 10/18/03  
Form: I FAC NAME: Corrected Date: 10/18/03  
Assessment: \$0 Inspector: THOMAS Followup Date: 10/18/03  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. g.  
Remarks Date: 10/17/03  
Valve installed on annular open line. A valve shall be installed in the closing line as close as possible to the annular preventor to act as a locking device.

Office: RW ID: RW3028  
Unique INC #: CT-007-R04 Well Name: GAMBLERS RESERVOIR FEDERAL  
Well #: 14-33 ID Date: 10/17/03  
Operator: TOM BROWN INC Effective Date: 10/17/03  
Case #: WYW132972 FAC ID: Abatement Date: 10/18/03  
Form: I FAC NAME: Corrected Date: 10/18/03  
Assessment: \$0 Inspector: THOMAS Followup Date: 10/18/03  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. e.  
Remarks Date: 10/17/03  
Air line to accumulator air pumps not installed. Power for the closing unit pumps shall be available to the unit at all times.

Office: RW ID: RW3219  
Unique INC #: CT-096-R04 Well Name: CRESTON JUNCTION  
Well #: 13-10 ID Date: 09/22/04  
Operator: NANCE PETROLEUM CORPORATION Effective Date: 09/22/04  
Case #: WYW133666 FAC ID: Abatement Date: 09/24/04  
Form: I FAC NAME: Corrected Date: 09/24/04  
Assessment: \$0 Inspector: THOMAS Followup Date: 09/24/04  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. 2. g.  
Remarks Date: 09/22/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

No Hand wheels on the BOP arms. g. Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater.

Office: RW ID: RW3221  
Unique INC #: CT-098-R04 Well Name: CRESTON JUNCTION  
Well #: 13-10  
Operator: NANCE PETROLEUM CORPORATION  
Case #: WYW133666 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: Onshore Order # 2 III. A. 2. e.  
  
Remarks Date: 09/22/04  
  
Air is shut off to the koomey air driven pumps. e. Minimum standards and enforcement provisions for power availability. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level.

Office: RW ID: RW3223  
Unique INC #: CT-100-R04 Well Name: CRESTON JUNCTION  
Well #: 13-10  
Operator: NANCE PETROLEUM CORPORATION  
Case #: WYW133666 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: Onshore Order # 2 III. A. 1.  
  
Remarks Date: 09/22/04  
  
No pressure on the annular pressure guage indicating that the controls of the koomey unit will not close the annular when functioned. 1. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD.

Office: RW ID: RW3220  
Unique INC #: CT-097-R04 Well Name: CRESTON JUNCTION  
Well #: 13-10  
Operator: NANCE PETROLEUM CORPORATION  
Case #: WYW133666 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: Onshore Order # 2 III. A. 2. g.  
  
Remarks Date: 09/22/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

No valve installed in the closing line of the annular preventer. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device. This valve shall be maintained in the open position and shall be closed only when the power source for the accumulator system is inoperative.

Office: RW ID: RW3224  
Unique INC #: CT-101-R04 Well Name: CRESTON JUNCTION  
Well #: 13-10 ID Date: 09/22/04  
Operator: NANCE PETROLEUM CORPORATION Effective Date: 09/22/04  
Case #: WYW133666 FAC ID: Abatement Date: 09/24/04  
Form: I FAC NAME: Corrected Date: 09/24/04  
Assessment: \$0 Inspector: THOMAS Followup Date: 09/24/04  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. 1.

Remarks Date: 09/22/04

One of the components of the koomey is leaking off the stored pressure of the koomey unit. Fix the leaking component. 1. Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe unless otherwise approved by the APD.

Office: RW ID: RW3222  
Unique INC #: CT-099-R04 Well Name: CRESTON JUNCTION  
Well #: 13-10 ID Date: 09/22/04  
Operator: NANCE PETROLEUM CORPORATION Effective Date: 09/22/04  
Case #: WYW133666 FAC ID: Abatement Date: 09/24/04  
Form: I FAC NAME: Corrected Date: 09/24/04  
Assessment: \$0 Inspector: THOMAS Followup Date: 09/24/04  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. 2. h.

Remarks Date: 09/22/04

Air is not turned on or hooked up to the remote controls of the koomey unit. h. Minimum standards and enforcement provisions for remote controls. Remote controls shall be readily accessible to the driller. Remote controls for all 3M or greater systems shall be capable of closing all preventers. Remote controls for 5M or greater systems shall be capable of both opening and closing all preventers. Master controls shall be at the accumulator and shall be capable of opening and closing all preventers and the choke line valve (if so equipped). No remote control for a 2M system is required

Office: RW ID: RW3063  
Unique INC #: CT-019-R04 Well Name: RED DESERT  
Well #: 20-3 ID Date: 01/27/04  
Operator: ANADARKO E & P COMPANY LP Effective Date: 02/06/04  
Case #: WYW134358 FAC ID: Abatement Date: 03/04/04  
Form: I FAC NAME: Corrected Date: 02/04/04  
Assessment: \$0 Inspector: THOMAS Followup Date: 02/06/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-1 (a) (b) (c)

Remarks Date: 01/27/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Remove the nitrogen trailer from the location. It is not part of the production equipment.

Office: RW ID: RW3175  
Unique INC #: CT-087-R04 Well Name: LOOKOUT WASH UNIT  
Well #: 40-32V  
Operator: CABOT OIL & GAS CORPORATION ID Date: 08/27/04  
Case #: WYW141458X FAC ID: Effective Date: 08/27/04  
Form: I FAC NAME: Abatement Date: 08/31/04  
Assessment: \$0 Inspector: THOMAS Corrected Date: 08/30/04  
Gravity: 3 Followup Date: 08/30/04  
Authority Ref: Onshore Order # 2 III. 2. h. Extend Date:  
  
Remarks Date: 08/27/04

Remote controls not working. h. Minimum standards and enforcement provisions for remote controls. Remote controls shall be readily accessible to the driller. Remote controls for all 3M or greater systems shall be capable of closing all preventers. Remote controls for 5M or greater systems shall be capable of both opening and closing all preventers.

Office: RW ID: RW3176  
Unique INC #: CT-088-R04 Well Name: LOOKOUT WASH UNIT  
Well #: 40-32V  
Operator: CABOT OIL & GAS CORPORATION ID Date: 08/27/04  
Case #: WYW141458X FAC ID: Effective Date: 08/27/04  
Form: I FAC NAME: Abatement Date: 08/31/04  
Assessment: \$0 Inspector: THOMAS Corrected Date: 08/30/04  
Gravity: 3 Followup Date: 08/30/04  
Authority Ref: Onshore Order # 2 III. 2. e. Extend Date:  
  
Remarks Date: 08/27/04

Koomey triplex pump does not work. Fix the Koomey triplex pump. e. Minimum standards and enforcement provisions for power availability. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level.

Office: RW ID: RW3174  
Unique INC #: CT-086-R04 Well Name: LOOKOUT WASH UNIT  
Well #: 40-32V  
Operator: CABOT OIL & GAS CORPORATION ID Date: 08/27/04  
Case #: WYW141458X FAC ID: Effective Date: 08/27/04  
Form: I FAC NAME: Abatement Date: 08/31/04  
Assessment: \$0 Inspector: THOMAS Corrected Date: 08/30/04  
Gravity: 3 Followup Date: 08/30/04  
Authority Ref: Onshore Order # 2 III. 2. g. Extend Date:  
  
Remarks Date: 08/27/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

No hand wheels on the BOP. Install the hand wheels on the BOP arms. g. Minimum standards and enforcement provisions for locking devices. A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater.

Office: RW ID: RW3177  
Unique INC #: CT-089-R04 Well Name: LOOKOUT WASH UNIT  
Well #: 40-32V  
Operator: CABOT OIL & GAS CORPORATION ID Date: 08/27/04  
Case #: WYW141458X FAC ID: Effective Date: 08/27/04  
Form: I FAC NAME: Abatement Date: 08/31/04  
Assessment: \$0 Inspector: THOMAS Corrected Date: 08/30/04  
Gravity: 3 Followup Date: 08/30/04  
Authority Ref: Onshore Order # 2 III. 2. e. Extend Date:  
  
Remarks Date: 08/27/04

Koomey air pumps have the air supply shut off. Leave the valve open on the air pumps so that they work automatically. e. Minimum standards and enforcement provisions for power availability. Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level.

Office: RW ID: RW3023  
Unique INC #: CT-002-R04 Well Name: MONUMENT LAKE  
Well #: 1  
Operator: YATES PETROLEUM CORP ID Date: 10/15/03  
Case #: WYW142997 FAC ID: Effective Date: 10/15/03  
Form: I FAC NAME: Abatement Date: 10/16/03  
Assessment: \$0 Inspector: THOMAS Corrected Date: 10/15/03  
Gravity: 3 Followup Date: 10/15/03  
Authority Ref: Onshore Order # 2 III. A. 2. g. Extend Date:  
  
Remarks Date: 10/15/03

No BOP handwheels installed. Install BOP handwheels.

Office: RW ID: RW3024  
Unique INC #: CT-003-R04 Well Name: MONUMENT LAKE  
Well #: 1  
Operator: YATES PETROLEUM CORP ID Date: 10/15/03  
Case #: WYW142997 FAC ID: Effective Date: 10/15/03  
Form: I FAC NAME: Abatement Date: 10/16/03  
Assessment: \$0 Inspector: THOMAS Corrected Date: 10/15/03  
Gravity: 3 Followup Date: 10/15/03  
Authority Ref: Onshore Order # 2 III. A. 2. g. Extend Date:  
  
Remarks Date: 10/15/03

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Floor valve was in the closed position. Open the floor valve.

Office: RW	Well Name: MONUMENT LAKE	ID: RW3022
Unique INC #: CT-001-R04	Well #: 1	ID Date: 10/15/03
Operator: YATES PETROLEUM CORP	FAC ID:	Effective Date: 10/15/03
Case #: WYW142997	FAC NAME:	Abatement Date: 11/03/03
Form: I	Inspector: THOMAS	Corrected Date: 10/22/03
Assessment: \$0		Followup Date: 10/22/03
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (a)		

Remarks Date: 10/15/03

No well identification sign. Put a complete and correct well sign in a conspicuous place on the well site.

Office: TU	Well Name: BEN WACOCHE	ID: iTU22296
Unique INC #: LK0457	Well #: 10, 11, 14, 19, 4, 6, 7, 8, 9	ID Date: 04/09/04
Operator: PETCO PETROLEUM CORPORATION	FAC ID: A	Effective Date: 04/16/04
Case #: 21271	FAC NAME: BEN WACOCHE	Abatement Date: 05/16/04
Form: I	Inspector: KEYES	Corrected Date: 05/06/04
Assessment: \$0		Followup Date: 06/04/04
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.5-3		

Remarks Date: 04/09/04

Please install a wind sock at your tank battery.

Office: TU	Well Name: BULLER	ID: TU23055
Unique INC #: LK04134	Well #: 23-346	ID Date: 08/20/04
Operator: COMBINED RESOURCES CORPORATION	FAC ID: A	Effective Date: 08/27/04
Case #: OKNM74640	FAC NAME: BULLER	Abatement Date: 09/27/04
Form: I	Inspector: KEYES	Corrected Date: 09/09/04
Assessment: \$0		Followup Date: 09/16/04
Gravity: 3		Extend Date:
Authority Ref: NTL 96-01		

Remarks Date: 08/20/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Please install a bird and bat protector (screen cone) over the stack of your heater treater.

Office: TU ID: iTU22188  
Unique INC #: LK037 Well Name: SWEET UNIT  
Well #: 6 FEE WELLS  
Operator: BILLY B OIL COMPANY  
Case #: OKNM78546X FAC ID: A  
Form: I FAC NAME: SWEET UNIT  
Assessment: \$0 Inspector: KEYES  
Gravity: 3  
Authority Ref: 43CFR3162.5-3  
Remarks Date: 03/01/04  
Please remove all pipe, valves and other related material from the tank battery area that is not being used in the operation of the battery.

Office: TU ID: iTU22596  
Unique INC #: LK0488 Well Name: SALLY PINEHILL  
Well #: 1-A, 1-B, 2-A, 2-B, 3-A, 4-A  
Operator: J & J JACKSON O & G INC  
Case #: OKNM78898 FAC ID: A  
Form: I FAC NAME: S.PINEHILL  
Assessment: \$0 Inspector: KEYES  
Gravity: 3  
Authority Ref: 43CFR3162.5-3  
Remarks Date: 05/13/04  
Please secure the cat walk ladder. Make repairs to ensure the ladder does not move when climbing.

Office: TU ID: TU23210  
Unique INC #: MWS-04-002 Well Name: TODD  
Well #: 1-H  
Operator: ELLORA OPERATING LP  
Case #: TXNM89745 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SILVA  
Gravity: 3  
Authority Ref: 43CFR 3160.0.5(3)  
Remarks Date: 08/31/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Failure to follow a Written Order. No berm around location ansilt fencing as per APD.

Office: TU ID: TU23211  
Unique INC #: MWS-04-003 Well Name: TODD  
Well #: 1-H  
Operator: ELLORA OPERATING LP  
Case #: TXNM89745 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SILVA  
Gravity: 3  
Authority Ref: 43CFR 3162.6  
Remarks Date: 08/31/04  
No well sign.

Office: TU ID: TU23209  
Unique INC #: MWS-04-001 Well Name: TODD  
Well #: 1-H  
Operator: ELLORA OPERATING LP  
Case #: TXNM89745 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SILVA  
Gravity: 3  
Authority Ref: 43CFR 3160.0.5(3)  
Remarks Date: 08/31/04  
Failure to follow a Written Order. Did not notify BLM Rep prior to pad construction as per APD.

Office: TU ID: TU23208  
Unique INC #: MWS-04-006 Well Name:  
Well #:  
Operator: ELLORA OPERATING LP  
Case #: TXNM96785 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SILVA  
Gravity: 3  
Authority Ref: 43CFR 3162.6  
Remarks Date: 08/31/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

No well sign.

Office: VE ID: VE10641  
Unique INC #: AW04005 Well Name: PLEASANT VALLEY  
Well #: 4-8-9-17 ID Date: 03/08/04  
Operator: INLAND PRODUCTION COMPANY Effective Date: 03/08/04  
Case #: UTU74477X FAC ID: Abatement Date: 03/10/04  
Form: I FAC NAME: Corrected Date: 03/10/04  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3162.1(a) APD point #9 Surface use plan  
Remarks Date: 03/08/04  
The pit is not fenced to meet the requirements of the Standard Operating Practices for your drilling program. Bring fence up to standards.

Office: VE ID: VE10867  
Unique INC #: CJ04002 Well Name: BONANZA  
Well #: 9-23-41-11 ID Date: 05/19/04  
Operator: THE HOUSTON EXLPORATION CO Effective Date: 05/26/04  
Case #: UTU74426 FAC ID: Abatement Date:  
Form: I FAC NAME: Corrected Date: 06/17/04  
Assessment: \$0 Inspector: CLIFF JOHNSON Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3162.3-1(c)(e)  
Remarks Date: 05/19/04  
43CFR3162.3-1 (c) The operator shall submit to the authorized officer for approval an Application for Permit to Drill for each well. No drilling operations, nor surface disturbance preliminary thereto, may be commenced prior to the authorized officer's approval of the permit. (e) A drilling plan may be modified from time to time as circumstances may warrant, with the approval of the authorized officer. This procedure was not followed. Future changes need to be addressed in a timely manner to accommodate a reasonable time for research by the authorized officer. An emergency phone call just prior to running casing does not meet this time frame.

Office: VE ID: VE10866  
Unique INC #: CJ04001 Well Name: BONANZA  
Well #: 9-23-41-11 ID Date: 05/19/04  
Operator: THE HOUSTON EXLPORATION CO Effective Date: 05/26/04  
Case #: UTU74426 FAC ID: Abatement Date:  
Form: I FAC NAME: Corrected Date: 05/25/04  
Assessment: \$0 Inspector: CLIFF JOHNSON Followup Date: 05/25/04  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3162.6(a)(b)  
Remarks Date: 05/19/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

3162.6 Well and facility identification. (a) Every well within a Federal or Indian lease or supervised agreement shall have a well identification sign. All signs shall be maintained in a legible condition. (b) For wells located on Federal and Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well, other than those permanently abandoned. The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer.

Office: VE		ID: VE10620
Unique INC #: DK04010	Well Name: NORTH CHAPITA	
	Well #: 220-5	
Operator: EOG RESOURCES INC		ID Date: 02/26/04
Case #: UTU41370	FAC ID:	Effective Date: 03/02/04
Form: I	FAC NAME:	Abatement Date: 03/05/04
Assessment: \$0	Inspector: DONNA KENNEY	Corrected Date: 03/05/04
Gravity: 3		Followup Date: 03/05/04
Authority Ref: 43 CFR 3162.5, Onshore Order #2,III,A,2,h.		Extend Date:

Remarks Date: 02/26/04

On a detailed rig inspection done on 02/26/2004, it was discovered that the remote panel did not have any supply pressure showing on the gauge to activate the panel. The BOPE test was not witnesses and they were in the middle if drilling, so we could not test panel. Please test remote panel when acceptable and verify it in the driller log.

Office: VE		ID: VE10869
Unique INC #: DK04042	Well Name: FEDERAL	
	Well #: 11-21-9-19	
Operator: PANNONIAN ENERGY INC		ID Date: 05/19/04
Case #: UTU78433	FAC ID:	Effective Date: 05/24/04
Form: I	FAC NAME:	Abatement Date: 05/28/04
Assessment: \$0	Inspector: DONNA KENNEY	Corrected Date: 07/06/04
Gravity: 3		Followup Date: 07/06/04
Authority Ref: 43 CFR 3162.3-1 (c),(e)		Extend Date:

Remarks Date: 05/19/04

On arriving on location for a BOPE inspection, it was discovered that the surface casing had been changed from the original Approval for Drilling permit .The company representative indicated to me that the Denver office had submitted a sundry to our Vernal office for the change. Upon doing research, I could not find a sundry for this well. Also we have no specifications for this type of casing and will need some technical data supplied to our office , plus a sundry notice for the change and approval. Surface casing was not run in accordance with the Approved Application for Permit to Drill (APD). Operator ran 8 5/8" 28# M50 casing instead of 9 5/8" 36# J-55 as was required. Operator shall comply with all requirements of the approved APD. Please file a sundry notice (Form 3160-5) to request approval for casing change. Further, please submit technical specifications for the 8 5/8" 28# M50 casing that was used.

Office: VE		ID: VE10864
Unique INC #: JS04021	Well Name: CWU	
	Well #: 872-30	
Operator: EOG RESOURCES INC		ID Date: 05/18/04
Case #: UTU63013X	FAC ID:	Effective Date: 05/18/04
Form: I	FAC NAME:	Abatement Date: 05/18/04
Assessment: \$0	Inspector: JAMIE SPARGER	Corrected Date: 05/18/04
Gravity: 3		Followup Date:
Authority Ref: 43 CFR 3162.1 (a); 3162-3 (b); 3164.1(a) (b); Onshore Order #1, I.		Extend Date:

Remarks Date: 05/18/04

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Operator failed to drill, case, and cement well in accordance with the APD requirements. The APD was approved to drill the surface hole to +/- 250', run 48# 13 3/8" surface casing and cement same to surface with class "G" cement. Then intermediate casing of 9 5/8" 36# was to be run to +/- 2,100' and cemented with a lead and tail cement. BOPs were to be installed on the 13 3/8" surface casing and tested prior to drilling out the shoe. Instead, 40' of 14" conductor was run then 2,239' of 9 5/8" 36# surface casing was run and cemented with type IV cement to surface. No BOPs were installed. The operator shall drill, case, cement, etc., wells as they are approved, or obtain approval to change plans prior to conducting the operations. Please notify Jamie Sparger at 435-781-4502 before cellar is dug out and cellar ring is installed to enable us to verify the cementing of the conductor casing.

Office: VE		ID: VE10822
Unique INC #: JS04011	Well Name: GORGE SPRING	
	Well #: 1	ID Date: 05/03/04
Operator: RETAMCO OPERATING INCORPORATED		Effective Date: 05/04/04
Case #: UTU72067	FAC ID:	Abatement Date: 05/04/04
Form: I	FAC NAME:	Corrected Date: 05/20/04
Assessment: \$5,000	Inspector: JAMIE SPARGER	Followup Date:
Gravity: 1		Extend Date:
Authority Ref: 43 CFR 3163.1 (b), (2); 43 CFR 3162.3-1 (a), (c) and (d); 43 CFR 3164.1(a) and (b); 43 CFR 31		

Remarks Date: 05/03/04

The operator is in violation of Federal regulations by constructing an access road, building a location, and spudding a well without first obtaining approval to do so. In an attempt to drill the Gorge Spring #1 well, the operator upgraded approximately 3,000' of existing "two track" road, built a location, and spud a well at SENW, Section 12, Township 15 South, Range 24 East, SLB&M. This is the wrong site for the Gorge Spring #1 well. The correct site, as surveyed, is 1245' FNL, 965' FEL (NENE) Section 14, Township 15 South, Range 24 East, SLB&M. Therefore, since the operator has upgraded an access road, built a location, and spud a well on Bureau of Land Management surface and Federal minerals without first obtaining approval, the operator shall be assessed Five Hundred Dollars (\$500.00) per day for each day that the violation existed. As per 43 CFR 3163.1 (b), (2) this assessment begins on the day surface disturbance commenced (March 19, 2004) and ends on the day the BLM discovered the noncompliance (May 3, 2004). The violation existed for 46 days at \$500.00 per day for a total assessment of \$23,000.00. As per 3163.1 (b), (2) this assessment is hereby capped at \$5,000.00. A billing for this assessment is attached. Please see these applicable regulations: 43 CFR 3162.3-1 (a), (c) and (d); 43 CFR 3164.1 (a) and (b); 43 CFR 3162.1 (a); 43 CFR 3162.3 (b); Onshore Order #1, I and II; 43 CFR 3163.1 (b), (2)

Office: VE		ID: VE10570
Unique INC #: JPB04001	Well Name: WRU GB	
	Well #: 9MU-9-8-22	ID Date: 12/08/03
Operator: QEP UNTA BASIN INC		Effective Date: 12/23/03
Case #: UTU63021X	FAC ID:	Abatement Date: 02/15/04
Form: I	FAC NAME:	Corrected Date: 12/10/03
Assessment: \$0	Inspector: JOHNNY BOWEN	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (a),(b),(c)		

Remarks Date: 12/08/03

No well sign on above well location. All wells on Federal lands must be identified with a legible well sign. Please install the appropriate sign by the above abatement date.

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Office: VE ID: iVE10766  
Unique INC #: KK04007 Well Name: ANKERPONT ID Date: 04/08/04  
Well #: 35-224 Effective Date: 04/20/04  
Operator: EL PASO PROD OIL & GAS CO Abatement Date: 05/20/04  
Case #: UTU58864 FAC ID: Corrected Date: 04/26/04  
Form: I FAC NAME: Followup Date: 04/28/04  
Assessment: \$0 Inspector: KIM KETTLE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (b)

Remarks Date: 04/08/04

The lease serial number, 14-20-H62-2888, on the Ankerpont 25-224 well sign is incorrect. 43 CFR 3162.6(b) states, "The well sign shall include the well number, the name of the operator, the lease serial number...." Please take corrective action by properly identifying the lease serial number as 14-20-H62-3011.

Office: VE ID: iVE10929  
Unique INC #: KK04019 Well Name: TRIBAL ID Date: 06/22/04  
Well #: 5-209 Effective Date: 06/22/04  
Operator: EL PASO PROD OIL & GAS CO Abatement Date: 06/22/04  
Case #: UTU58875 FAC ID: Corrected Date: 06/22/04  
Form: I FAC NAME: Followup Date: 06/23/04  
Assessment: \$0 Inspector: KIM KETTLE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order 2, III.2.e.

Remarks Date: 06/22/04

The air supply to the accumulator air pumps was turned off. The independent power source for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start. Please make sure the air supply is available to the accumulator.

Office: VE ID: iVE10889  
Unique INC #: CRB04022 Well Name: UTE TRIBAL ID Date: 05/25/04  
Well #: 9-31-54 Effective Date: 05/25/04  
Operator: BERRY PETROLEUM COMPANY Abatement Date:  
Case #: 1420H624946 FAC ID: Corrected Date: 06/01/04  
Form: I FAC NAME: Followup Date: 06/01/04  
Assessment: \$0 Inspector: RANDY BYWATER Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3162.3-1 (c)

Remarks Date: 05/25/04

Failure to follow approved A.P.D. and S.O.P. sec. 4 proposed casing and cementing program. Amend S.O.P. to correct cementing procedure.

Safety and Drilling Related Violations (INCs) Issued During FY 2004  
As of March 3, 2011

Office: WO ID: WO2150  
Unique INC #: 010-04-023 Well Name: COLE FED ID Date: 07/27/04  
Well #: 1-26 Effective Date: 07/28/04  
Operator: ENERGYTEC INC Abatement Date: 07/29/04  
Case #: WYW145710 FAC ID: Corrected Date: 07/29/04  
Form: I FAC NAME: Followup Date: 08/02/04  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O.# 2 III. A.2.b.iv.

Remarks Date: 07/27/04

During drilling inspection 7/27/04, I found choke manifold with improper pressure gauge. This gauge has to be of mud service type. Energy Tec has 24hrs to replace this gauge.

Office: WO ID: WO2151  
Unique INC #: 010-04-024 Well Name: COLE FED ID Date: 07/27/04  
Well #: 1-26 Effective Date: 07/28/04  
Operator: ENERGYTEC INC Abatement Date: 07/29/04  
Case #: WYW145710 FAC ID: Corrected Date: 07/29/04  
Form: I FAC NAME: Followup Date: 08/02/04  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O.# 2 III. A.2.i.xi.

Remarks Date: 07/27/04

During drilling inspection, 7/27/04, found entries in IADC log to be incomplete on well control testing and surface casing. IADC log needs to have all the correct information recorded.

Office: WO ID: WO2149  
Unique INC #: 010-04-022 Well Name: COLE FED ID Date: 07/27/04  
Well #: 1-26 Effective Date: 07/28/04  
Operator: ENERGYTEC INC Abatement Date: 07/29/04  
Case #: WYW145710 FAC ID: Corrected Date: 07/30/04  
Form: I FAC NAME: Followup Date: 08/02/04  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O.#1 III.G.3.f.

Remarks Date: 07/27/04

During drilling inspection on 7/27/04, I found the APD to be incomplete, Energy Tec has 24hrs from receipt of this notice to have a complete APD on location.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: AN		ID: AN59
Unique INC #: TL03-005	Well Name: NICOLAI CREEK UNIT	
	Well #: 9	ID Date: 09/10/03
Operator: AURORA GAS LLC.		Effective Date: 09/10/03
Case #: AKAA8426	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 09/10/03
Assessment: \$0	Inspector: LAWLOR	Followup Date: 09/18/03
Gravity: 3		Extend Date:
Authority Ref: OO #1.I.(2)		

Remarks Date: 09/10/03

Aurora Gas LLC failed to notify the Bureau of Land Management verbally twenty-four hours in advance of running surface casing. Condition of Approval #3 for this well clearly states 'Notify this office verbally at least 24 hours prior to running casing and cementing'. Onshore Order #1 states 'The lessee/operator shall comply with the following requirements: Lessees and operators have the responsibility to see that their exploration, development, production, and construction operations are conducted in a manner which (1) conforms with applicable Federal laws and regulations and with State and local laws and regulations to the extent that such State and local laws are applicable to operations on Federal or Indian leases; (2) conforms with the lease terms, lease stipulations, and conditions of approval'. Failure to notify the BLM Anchorage Field Office in the future can lead to suspension of operations.

Office: AN		ID: AN60
Unique INC #: TL03-006	Well Name: NICOLAI CREEK UNIT	
	Well #: 9	ID Date: 09/11/03
Operator: AURORA GAS LLC.		Effective Date: 09/11/03
Case #: AKAA8426	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 09/11/03
Assessment: \$0	Inspector: LAWLOR	Followup Date: 09/18/03
Gravity: 3		Extend Date:
Authority Ref: OO #1. II		

Remarks Date: 09/11/03

Aurora Gas LLC failed to notify the Bureau of Land Management of changes in the cementing program. Onshore Order #1 states 'Lessees and operators, as well as their contractors and subcontractors, shall not commence any operation or construction activity on a lease, other than cultural resource inventories and surveying and staking well locations on Federal and Indian lands, without the prior approval of the authorized officer of BLM, except for certain subsequent operations (see Section IV. of this Order). The terms and conditions of an approved permit and drilling plan, or other plan, shall not be altered unless BLM first has approved an amended or supplemental permit and/or plan covering any such modifications'. Failure to receive prior approval for any changes in the Application for Permit to Drill can lead to suspension of operations.

Office: BA		ID: BA1698
Unique INC #: 01-011-03	Well Name: GOVERNMENT	
	Well #: G-2922	ID Date: 02/14/03
Operator: TEXACO CALIFORNIA INCORPORATED		Effective Date: 02/18/03
Case #: CAS019382	FAC ID:	Abatement Date: 03/09/03
Form: I	FAC NAME:	Corrected Date: 03/04/03
Assessment: \$0	Inspector: 1 GARNAND	Followup Date: 03/04/03
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 02/14/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Incident of noncompliance has been issued for not giving a 24 hour notice of starting operations on well #2922. You must give 24 hour notice as specified in Conditions of Approval. Sign INC and return to Bakersfield BLM office.

Office: BA ID: BA1748  
Unique INC #: 02-010-03 Well Name: ALTA-VEDDER  
Well #: 35A ID Date: 03/20/03  
Operator: PLAINS EXPL & PROD CO Effective Date: 03/20/03  
Case #: CACA26739X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: 2 SPARKS R Abatement Date: 03/21/03  
Gravity: 3 Corrected Date: 03/26/03  
Authority Ref: 43 CFR 3162.1 (a) Followup Date: 03/26/03  
Extend Date:

Remarks Date: 03/20/03

IT WAS NOTED THAT THERE WAS NOT A REMOTE CONTROL TO ACTIVATE THE BOP EQUIPMENT ON THE RIG FLOOR (STIPULATED IN APPROVED APD) OF WESTERN WELL, RIG #48. YOU MUST INSTALL A REMOTE CONTROL PRIOR TO BEGINNING OPERATIONS ON THE NEXT WELL. PLEASE SIGN THE WHITE COPY AND RETURN TO THIS OFFICE.

Office: BA ID: BA1669  
Unique INC #: 04-005-03 Well Name: USL  
Well #: 24 ID Date: 01/15/03  
Operator: TEXACO EXPLORATION & PROD INC Effective Date: 02/13/03  
Case #: CAS037494 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: 4 DAVIS Abatement Date: 03/05/03  
Gravity: 3 Corrected Date: 03/05/03  
Authority Ref: 43 CFR 3162.3-2(a) Followup Date: 03/05/03  
Extend Date:

Remarks Date: 01/15/03

ChevronTexaco altered the casing (ran a new liner) in the subject well prior to notifying the BLM or receiving approval. It is required, and it is important that this office receives a Sundry Notice (Form 3160-5) requesting any down hole work prior to the start of that work in order to determine that this work will not adversely effect Federal Minerals and so that the Bureau of Land Management can remain current in its mechanical information for future down hole operations. Therefore, it is necessary that you submit a letter that explains this oversight and the methods you have installed to prevent any future occurrence.

Office: BU ID: BU6430  
Unique INC #: MB-03-07 Well Name: USFS WILD HORSE CREEK FED  
Well #: 2-18 ID Date: 02/18/03  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 02/19/03  
Case #: WYW141187 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NAVARRETTE/BLAK Abatement Date: 02/20/03  
Gravity: 3 Corrected Date: 02/20/03  
Authority Ref: Onshore Order #2 A vii (b) (i) Followup Date:  
Extend Date:

Remarks Date: 02/19/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

On inspection choke bleed-off lines were not adequately secured. The choke bleed-off lines must be securely anchored. (Violation-see attached)

Office: BU		ID: BU6428
Unique INC #: MB-03-05	Well Name: USFS WILD HORSE CREEK FED	
	Well #: 2-18	ID Date: 02/18/03
Operator: BALLARD PETROLEUM HOLDINGS LLC		Effective Date: 02/19/03
Case #: WYW141187	FAC ID:	Abatement Date: 02/20/03
Form: I	FAC NAME:	Corrected Date: 02/20/03
Assessment: \$0	Inspector: NAVARRETTE/BLAK	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 III		

Remarks Date: 02/19/03

On inspection operator wheels were not in place to operate BOP. This was corrected on 2-18-03. (Violation- see attached)

Office: BU		ID: BU6425
Unique INC #: MB-03-02	Well Name: USFS WILD HORSE CREEK FED	
	Well #: 2-18	ID Date: 02/18/03
Operator: BALLARD PETROLEUM HOLDINGS LLC		Effective Date: 02/18/03
Case #: WYW141187	FAC ID:	Abatement Date: 02/18/03
Form: I	FAC NAME:	Corrected Date: 02/20/03
Assessment: \$0	Inspector: NAVARRETTE/BLAK	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 III 2 (a) iii		

Remarks Date: 02/19/03

2-18-03 On inspection Kill line was not hooked up. This was corrected on 2-18-03. (Violation- see attached)

Office: BU		ID: BU6426
Unique INC #: MB-03-03	Well Name: USFS WILD HORSE CREEK FED	
	Well #: 2-18	ID Date: 02/18/03
Operator: BALLARD PETROLEUM HOLDINGS LLC		Effective Date: 02/19/03
Case #: WYW141187	FAC ID:	Abatement Date: 02/20/03
Form: I	FAC NAME:	Corrected Date: 02/20/03
Assessment: \$0	Inspector: NAVARRETTE/BLAK	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: Application for Permit to Drill		

Remarks Date: 02/19/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

2-18-03 On rig inspection it was found that there was no flare pit. This is not in accordance with the approved APD. A flare pit must be constructed.

Office: BU ID: BU6427  
Unique INC #: MB-03-04 Well Name: USFS WILD HORSE CREEK FED  
Well #: 2-18 ID Date: 02/18/03  
Operator: BALLARD PETROLEUM HOLDINGS LLC Effective Date: 02/19/03  
Case #: WYW141187 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NAVARRETTE/BLAK  
Gravity: 1  
Authority Ref: Onshor Order #2 III 2 (a) iii  
Remarks Date: 02/19/03

On inspection manifold choke valves were unable to be shut or opened. This was witnessed by two BLM inspectors and photos were taken. These manifold choke valves will be put in operable condition, and the valves will be retested with in 24 hrs. or the operations will be suspended. Verbal notice was given to Dave McCoskery, and Mike Perius by telephone @1000 hrs. on 2-19-03. It was also requested that this Inspector be given notice when the retesting of these valves take place so the test can be witnessed by BLM. (Violations- see attached)

Office: BU ID: BU6248  
Unique INC #: RN-03-55 Well Name: HART DRAW FEDERAL  
Well #: 1 ID Date: 11/18/02  
Operator: BELLEVUE RESOURCES INC Effective Date: 11/18/02  
Case #: WYW126203 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: NAVARRETTE/HAIN  
Gravity: 1 Extend Date:  
Authority Ref: APD / Onshore Order #2  
Remarks Date: 11/19/02  
Kill line was not hooked up. You must hookup kill line immediately.

Office: BU ID: BU6433  
Unique INC #: GR-07-03 Well Name: BONE PILE UNIT - CBM FED  
Well #: 41-13 ID Date: 02/19/03  
Operator: WESTPORT OIL & GAS CO LP Effective Date: 02/19/03  
Case #: WYW126561 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROTH  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-2  
Remarks Date: 02/19/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Failure to maintain well control. Specifically; Well head lock ring is not on well head. Corrective Action; Replace well head lock ring.

Office: BU		ID: BU6432
Unique INC #: GR-06-03	Well Name: BELL ROAD TRIPP FED	
	Well #: 11-12	ID Date: 02/19/03
Operator: WESTPORT OIL & GAS CO LP		Effective Date: 02/19/03
Case #: WYW126561	FAC ID:	Abatement Date: 03/17/03
Form: I	FAC NAME:	Corrected Date: 02/27/03
Assessment: \$0	Inspector: ROTH	Followup Date: 03/10/03
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-2		

Remarks Date: 02/19/03

Failure to maintain well control. Specifically; Well head lock ring is not on well head. Corrective Action; Replace well head lock ring.

Office: BU		ID: BU6179
Unique INC #: SDS0302BF	Well Name: TREND FEDERAL	
	Well #: 17-1	ID Date: 10/23/02
Operator: TREND EXPLORATION I, LLC		Effective Date: 10/23/02
Case #: WYW138421	FAC ID:	Abatement Date: 10/24/02
Form: I	FAC NAME:	Corrected Date: 10/24/02
Assessment: \$0	Inspector: SOULE/BLAKESLEY	Followup Date: 10/24/02
Gravity: 3		Extend Date:
Authority Ref: Onshore Order #2 III.A.c.ii		

Remarks Date: 10/23/02

The air was shut off to the air pump. When air was turned on the pump did not function. Repair or replace back up pump and maintain in accordance to Onshore Order No. 2.

Office: BU		ID: BU6267
Unique INC #: JW03-07I	Well Name: KITTY G 20 MILE	
	Well #: 42W-903	ID Date: 12/10/02
Operator: DEVON ENERGY PRODUCTION CO, LP		Effective Date: 12/10/02
Case #: WYW0103453	FAC ID:	Abatement Date: 01/10/03
Form: I	FAC NAME:	Corrected Date: 12/26/02
Assessment: \$0	Inspector: WALKER	Followup Date: 01/06/03
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.6(b)		

Remarks Date: 12/10/02

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Sign at well 42W-903 shows incorrect Federal lease number and Quarter/Quarter Corrective Action: Please correct well sign to show correct Federal lease number WYW0103453 and correct Quarter/Quarter SENE per 43CFR3162.6(b). Thank you

Office: CB ID: CB16067  
Unique INC #: 03-JA-018 Well Name:  
Well #: ID Date: 12/27/02  
Operator: WESTALL RAY Effective Date:  
Case #: NMLC029392B FAC ID: C Abatement Date: 01/30/03  
Form: I FAC NAME: HINKLE B #8 Corrected Date: 01/06/03  
Assessment: \$0 Inspector: AMOS Followup Date: 01/06/03  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER 6.III.D.2.e  
Remarks Date: 12/27/02  
TANK IS NOT EQUIPPED WITH WINDSOCK. INSTALL WINDSOCK.

Office: CB ID: CB16070  
Unique INC #: 03-JA-021 Well Name:  
Well #: ID Date: 12/27/02  
Operator: WESTALL RAY Effective Date:  
Case #: NMLC029392B FAC ID: D Abatement Date: 01/30/03  
Form: I FAC NAME: HINKLE B #11 Corrected Date: 01/06/03  
Assessment: \$0 Inspector: AMOS Followup Date: 01/06/03  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER 6.III.D.2.e  
Remarks Date: 12/27/02  
TANK IS NOT EQUIPPED WITH WINDSOCK. INSTALL WINDSOCK.

Office: CB ID: CB16553  
Unique INC #: 03-JA-118 Well Name: MALCO A  
Well #: 5 ID Date: 04/16/03  
Operator: AMTEX ENERGY INCORPORATED Effective Date:  
Case #: NMLC065478B FAC ID: Abatement Date: 04/30/03  
Form: I FAC NAME: Corrected Date: 04/22/03  
Assessment: \$0 Inspector: AMOS Followup Date: 04/22/03  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.1.a, COA  
Remarks Date: 04/16/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

FAILURE TO NOTIFY THIS OFFICE PRIOR TO SPUD AND SURFACE CASING JOB. CONDITIONS OF THE APD REQUIRE NOTIFICATION GIVING THE INSPECTION STAFF AMPLE TIME TO WITNESS OPERATIONS. NOTIFY THIS OFFICE AT 505-361-2822 AT LEASE TWO (2) HOURS PRIOR TO CEMENTING THE PRODUCTION CASING. ANY QUESTIONS CONTACT JIM AMOS AT 505-234-5909.

Office: CB ID: CB16246  
Unique INC #: 03-JA-072 Well Name:  
Well #:  
Operator: THOMPSON CLEO J ID Date: 01/16/03  
Case #: NMNM71065X Effective Date: 01/21/03  
Form: I FAC ID: A Abatement Date: 02/16/03  
Assessment: \$0 FAC NAME: W SQUARE LAKE Corrected Date: 02/03/03  
Gravity: 3 Inspector: AMOS Followup Date: 02/19/03  
Authority Ref: ONSHORE ORDER 6.III.D.1.c Extend Date:  
  
Remarks Date: 01/16/03  
H2S CONCENTRATION IN GAS STREAM EXCEEDS 100 PPM. SUBMIT H2S CONCENTRATION OF STOCK TANKS. H2S WARNING SIGNS ARE REQUIRED AT FACILITIES WHICH EXCEED 100 PPM H2S. INSTALL SIGNS WITHIN 50 FEET OF TANKAGE.

Office: CB ID: CB16921  
Unique INC #: 03-DC-027 Well Name: TODD 22F FEDERAL  
Well #: 6 ID Date: 08/17/03  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM0405444A FAC ID: Abatement Date: 08/18/03  
Form: I FAC NAME: Corrected Date: 08/28/03  
Assessment: \$0 Inspector: CLEGHORN Followup Date: 08/28/03  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER 2.III.A.2.d  
  
Remarks Date: 08/17/03

ACCUMULATOR PRECHARGE PRESSURE TEST NOT PERFORMED AS PER ONSHORE ORDER 2. ACCUMULATOR BOTTLES WERE SERVICED ON 8/17/03 WITH ONE ACCUMULATOR BOTTLE HAVING 750 PSI AND THE OTHER HAVING 800 PSI PRIOR TO BEING SERVICED TO 1100 PSI. MINIMUM STANDARDS AND ENFORCEMENT PROVISIONS FOR ACCUMULATOR PRECHARGE PRESSURE TEST. THIS TEST SHALL BE CONDUCTED PRIOR TO CONNECTING THE CLOSING UNIT TO THE BOP STACK AND AT LEAST ONCE EVERY 6 MONTHS. THE ACCUMULATOR PRESSURE SHALL BE CORRECTED IF THE MEASURED PRECHARGE PRESSURE IS FOUND TO BE ABOVE OR BELOW THE MAXIMUM OR MINIMUM LIMITS.

Office: CB ID: CB16917  
Unique INC #: 03-DC-023 Well Name: TODD 22F FEDERAL  
Well #: 6 ID Date: 08/17/03  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM0405444A FAC ID: Abatement Date: 08/18/03  
Form: I FAC NAME: Corrected Date: 02/28/03  
Assessment: \$0 Inspector: CLEGHORN Followup Date: 02/28/03  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER 2.IIIA.2.h  
  
Remarks Date: 08/17/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

AIR SUPPLY TO FLOOR CONTROLS FOR BOP WAS IN OFF POSITION THEREBY MAKING REMOTE CONTROLS INOPERABLE. REMOTE CONTROLS FOR ALL 3M OR GREATER SYSTEMS SHALL BE CAPABLE OF CLOSING ALL PREVENTERS, AT ANYTIME. TAKE NECESSARY ACTION AS TO PREVENT CLOSURE OF AIR SUPPLY VALVE DURING DRILLING OPERATIONS AS PER ONSHORE ORDER #2.

Office: CB ID: CB16919  
Unique INC #: 03-DC-025 Well Name: TODD 22F FEDERAL  
Well #: 6 ID Date: 08/17/03  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM040544A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLEGHORN Abatement Date: 08/18/03  
Gravity: 3 Corrected Date: 02/28/03  
Authority Ref: APD STIPULATIONS Followup Date: 02/28/03  
Extend Date:

Remarks Date: 08/17/03

APD SPECIFIED THAT AN INDEPENDENT TESTER IS TO BE USED TO TEST BOP TO APPROVED STACK WORKING PRESSURE OF 3000 PSI. PERFORM TESTS ON BOP AND ASSOCIATED EQUIPMENT AS PER SIGNED APD. APD STIPULATIONS AND ONSHORE ORDER 2. RAM TYPE PREVENTERS AND ASSOCIATED EQUIPMENT SHALL BE TESTED TO APPROVED STACK WORKING PRESSURE IF ISOLATED BY A TEST PLUG OR TO 70% OF INTERNAL YIELD PRESSURE OF CASING IF BOP STACK IS NOT ISOLATED FROM CASING. RECORD IN IADC (DRILLING LOG) ALL APPROPRIATE TEST AS PER OO 2.

Office: CB ID: CB16926  
Unique INC #: 03-DC-029A Well Name: TODD 22F FEDERAL  
Well #: 6 ID Date: 08/17/03  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM040544A FAC ID:  
Form: I FAC NAME:  
Assessment: \$3,000 Inspector: CLEGHORN Abatement Date: 08/18/03  
Gravity: 3 Corrected Date: 08/28/03  
Authority Ref: 43 CFR 3163.1.b.1 Followup Date: 08/28/03  
Extend Date:

Remarks Date: 08/17/03

BLOWOUT PREVENTER AND RELATED EQUIPMENT WAS NOT INSTALLED, USED, MAINTAINED AND TESTED IN A MANNER NECESSARY TO ASSURE WELL CONTROL AS PER THE APD, ONSHORE ORDER 2 AND 43 CFR 3162, THEREFORE YOU ARE ASSESSED AT A RATE OF \$500 PER DAY FOR EACH DAY THAT THE VIOLATION EXISTED. INCLUDING DAYS THE VIOLATION EXISTED PRIOR TO DISCOVERY, NOT TO EXCEED \$5000. CORRECT ALL VIOLATIONS AND PAY ASSESSMENT AS PER FED REG.

Office: CB ID: CB16922  
Unique INC #: 03-DC-028 Well Name: TODD 22F FEDERAL  
Well #: 6 ID Date: 08/17/03  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM040544A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLEGHORN Abatement Date: 08/18/03  
Gravity: 3 Corrected Date: 08/28/03  
Authority Ref: ONSHORE ORDER 2.III.A.2.g Followup Date: 08/28/03  
Extend Date:

Remarks Date: 08/17/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

1" BALL VALVE INSTALLED IN THE OPENING SIDE OF ANNULAR

Office: CB ID: CB16918  
Unique INC #: 03-DC-024 Well Name: TODD 22F FEDERAL  
Well #: 6 ID Date: 08/17/03  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM0405444A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLEGHORN  
Gravity: 3  
Authority Ref: ONSHORE ORDER 2.III.A.2.i.ii  
Remarks Date: 08/17/03  
THE ONLY ENTRY IN IADC (DRILLING LOG) WAS "TEST BOP". ENTRY IN LOG INADEQUATE AS TO SHOW WHICH EQUIPMENT WAS TESTED. TO WHAT PSI THE EQUIPMENT WAS TESTED, IF ANY REPAIRS WERE REQUIRED AND THE AMOUNT OF TIME EACH COMPONENT WAS TESTED. ENTER ALL TESTS AND /OR DRILLS IN IADC (DRILLING LOG) AS PER ONSHORE ORDER #2.

Office: CB ID: CB16920  
Unique INC #: 03-DC-026 Well Name: TODD 22F FEDERAL  
Well #: 6 ID Date: 08/17/03  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM0405444A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLEGHORN  
Gravity: 3  
Authority Ref: ONSHORE ORDER 2.III.A.2.i.k.III  
Remarks Date: 08/17/03  
PIPE AND BLIND RAMS WERE NOT ACTIVATED ON BIT TRIP AS IADC (DRILLER LOG). PIPE AND BLIND RAMS SHALL BE ACTIVATED EACH TRIP, HOWEVER THIS FUNCTION NEED NOT BE PERFORMED MORE THAN ONCE A DAY. RECORD ALL TEST AND/OR DRILLS IN IADC (DRILLERS LOF) AS PER ONSHORE ORDER 2.

Office: CB ID: CB16769  
Unique INC #: 03-GH-150 Well Name:  
Well #: ID Date: 06/26/03  
Operator: READ & STEVENS INCORPORATED Effective Date:  
Case #: NMNM0486 FAC ID: A Abatement Date: 07/18/03  
Form: I FAC NAME: NIX FEDERAL BATTERY Corrected Date: 06/28/03  
Assessment: \$0 Inspector: HUNT Followup Date: 09/16/03  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6, III.D.2.e  
Remarks Date: 06/26/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

WIND DIRECTION INDICATOR NEEDS REPAIRED/ REPLACED. REPAIR/ REPLACE THE WIND DIRECTION INDICATOR WITHIN TWENTY DAYS OF NOTICE.

Office: CB ID: CB16510  
Unique INC #: 03-PS-016 Well Name: WIZARD FEDERAL  
Well #: 3 ID Date: 03/29/03  
Operator: CHI OPERATING INCORPORATED Effective Date: 04/04/03  
Case #: NMLC063613 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SWARTZ  
Gravity: 3  
Authority Ref: 43 CFR 3162.6  
Remarks Date: 03/29/03

Well does not have an identification sign. Install a legible sign in a conspicuous place. The sign shall include the well number, the name of the operator, the lease serial number, the surveyed location, and API number.

Office: CB ID: CB16486  
Unique INC #: 03-PS-010 Well Name:  
Well #: ID Date: 03/14/03  
Operator: ST MARY LAND & EXPLORATION CO Effective Date:  
Case #: NMNM88491X FAC ID: B, C, D  
Form: I FAC NAME: PDU TRACT 1 BATTERY, PDU TRACT  
Assessment: \$0 Inspector: SWARTZ  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, O.O. #6.III.D.3.a.&b.  
Remarks Date: 03/14/03

Facility windsock(s) and H2S Danger Signs are tattered or in poor condition. Install, repair, or replace wind direction indicator(s) and H2S signs as necessary for Tract 1, Tract 2, and Tract 7-8 Batterys.

Office: CB ID: CB16272  
Unique INC #: 03-DW-035 Well Name: POKER LAKE UNIT  
Well #: 181 ID Date: 01/21/03  
Operator: BASS ENTERPRISES PRODUCTION CO Effective Date: 01/21/03  
Case #: NMNM71016X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WHITLOCK  
Gravity: 3  
Authority Ref: 43CFR3162.1/ONSHORE ORDER #2,III,A,h  
Remarks Date: 01/21/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

WHILE DRILLING KEY #37 SHUT OFF AIR SUPPLY TO REMOTE FLOOR CONTROLS ON B.O.P. MAINTAIN AIR SUPPLY ON FLOOR CONTROL SO AS TO MAKE FLOOR CONTROLS FUNCTIONAL. NOTICE GIVEN TO JIMMY LEWIS 1/21/03 @1400 HRS.

Office: CB ID: CB16273  
Unique INC #: 03-DW-036 Well Name: POKER LAKE UNIT  
Well #: 181 ID Date: 01/21/03  
Operator: BASS ENTERPRISES PRODUCTION CO Effective Date: 01/21/03  
Case #: NMNM71016X FAC ID: Abatement Date: 01/22/03  
Form: I FAC NAME: Corrected Date: 01/24/03  
Assessment: \$0 Inspector: WHITLOCK Followup Date: 01/24/03  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3162.1/ONSHORE ORDER #2,III,A,e

Remarks Date: 01/21/03

WHILE DRILLING KEY #37 SHUT OFF AIR SUPPLY TO THE ACCUMULATOR PUMPS. MAINTAIN AIR SUPPLY ON ACCUMULATOR PUMPS AT ALL TIMES SO THAT THE PUMPS SHALL AUTOMATICALLY START WHEN THE CLOSING VALVE MANIFOLD PRESSURE HAS DECREASED TO THE PRE-SET LEVEL. NOTICE GIVEN TO JIMMY LEWIS 1/21/03 @1400 HRS.

Office: CC ID: CC814  
Unique INC #: RG03EG005A Well Name: NOAA  
Well #: 11-32 ID Date: 08/27/03  
Operator: ENCANA ENERGY RESOURCES INC Effective Date: 08/27/03  
Case #: COC30024 FAC ID: Abatement Date: 08/27/03  
Form: I FAC NAME: Corrected Date: 08/27/03  
Assessment: \$0 Inspector: EGILLINGHAM Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 1; G; 3

Remarks Date: 09/30/03

08/27/03: 11:15A: Operator did not have complete copy of APD and Conditions of Approval at Drill site location. Corrective Action: Furnish copy of APD to drill site location, keep posted in readily available spot for viewing by drill hands / and BLM inspectors. 08/27/03: 02:00P: Operator had APD brought to location, and INC was abated (elg)

Office: CC ID: CC813  
Unique INC #: RG03EG004A Well Name: NOAA  
Well #: 11-32 ID Date: 08/27/03  
Operator: ENCANA ENERGY RESOURCES INC Effective Date: 08/27/03  
Case #: COC30024 FAC ID: Abatement Date: 08/27/03  
Form: I FAC NAME: Corrected Date: 08/27/03  
Assessment: \$0 Inspector: EGILLINGHAM Followup Date: 09/30/03  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR 3162.1(a)

Remarks Date: 08/27/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

08/27/03: INC was delivered verbally at 11:15a over telephone to Pat Marx. Operator had not tested BOP pressure to required 1200psi prior to drilling out shoe of surface casing. \_\_Corrective action: Either shut in well bore, place plug, and test BOP to required pressure, or furnish necessary information to Duane Spencer of the BLM Colorado State Office, with adequate detail to show 450psi BOP test was adequate provide necessary control incase use of BOP is required. \_\_NOTE: Pat Marx of EnCana provided necessary information to BLM, 450psi was determined to be adequate. Duane Spencer confirmed this information to inspector in field (E Gillingham), and operations were allowed to resume. (elg)

Office: CR		ID: CR1181
Unique INC #: LSRA03-002	Well Name: NINE MILE	
	Well #: 2-1	
Operator: TIPPERARY OIL & GAS CORP		
Case #: COC55659	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: EAGAN	
Gravity: 3		
Authority Ref: 43CFR3160 OO&GO#2IIIAg		

Remarks Date: 05/13/03

Operator's rig was drilling without Handwheels installed on BOP stack. Hand wheels were installed while PET was onsite.

Office: CR		ID: CR1180
Unique INC #: LSR003-001	Well Name: NINE MILE	
	Well #: 2-1	
Operator: TIPPERARY OIL & GAS CORP		
Case #: COC55659	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: EAGAN	
Gravity: 1		
Authority Ref: 43CFR3160 OO&G Order#2IIIA.IV		

Remarks Date: 05/13/03

Operator's rig was drilling without the kill line installed at the check valve flange. Well was shut in and operator installed the kill line while PET was onsite.

Office: DK		ID: DK5996
Unique INC #: IWM0223	Well Name: V 6 11 2002HARRIS	
	Well #: 1	
Operator: CAMWEST II LP		
Case #: NDM029556	FAC ID: A	
Form: I	FAC NAME: V. HARRIS 1	
Assessment: \$0	Inspector: BILL MCMANUS	
Gravity: 3		
Authority Ref: 43 CFR 1364.1 OO#6 D.3.e		

Remarks Date: 09/16/02

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

no wind direction indicator installed at tank battery and well site. Install wind direction indicator at tank battery and well site. Green copy is operator's copy

Office: DK ID: DK5997  
Unique INC #: IWM0224 Well Name: BECKEDAHL F  
Well #: 3, 35-15  
Operator: CARL H NORDSTRAND  
Case #: NDM029565 FAC ID: A  
Form: I FAC NAME: BECKEDAHL F  
Assessment: \$0 Inspector: BILL MCMANUS  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III D.3.e

ID Date: 09/12/02  
Effective Date: 09/23/02  
Abatement Date: 11/23/02  
Corrected Date: 11/26/02  
Followup Date: 11/26/02  
Extend Date:

Remarks Date: 09/16/02

No wind direction indicators on tank battery or well locations. Install wind direction indicators at tank battery and well location. Green copy is operator's copy

Office: DK ID: DK6032  
Unique INC #: IDH03011 Well Name: FEDERAL  
Well #: 13-30  
Operator: WESTPORT OIL & GAS COMPANY LP  
Case #: NDM14393 FAC ID: A  
Form: I FAC NAME: FEDERAL 13-30  
Assessment: \$0 Inspector: DENNIS HANNUM  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, D, 1, c.

ID Date: 02/04/03  
Effective Date: 02/07/03  
Abatement Date: 03/06/03  
Corrected Date: 02/19/03  
Followup Date: 02/21/03  
Extend Date:

Remarks Date: 02/04/03

No wind direction indicator. Must install wind direction indicator so that wind direction can be easily determined from anywhere on location. The green copy is the operators copy.

Office: DK ID: DK6069  
Unique INC #: IDH03020 Well Name:  
Well #:  
Operator: PRIDE ENERGY COMPANY  
Case #: NDM88437 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: DENNIS HANNUM  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, D, 2, e

ID Date: 07/29/03  
Effective Date: 08/01/03  
Abatement Date: 10/01/03  
Corrected Date: 09/20/03  
Followup Date: 09/20/03  
Extend Date:

Remarks Date: 07/29/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

No wind direction indicator. Must install wind direction indicator so that wind direction can be easily determined from anywhere on location. Talked to Mr. Mathew Pride about this matter 7/29/03. The green copy is the operators copy.

Office: DK ID: DK6072  
Unique INC #: IDH03021 Well Name:  
Well #:  
Operator: CONTINENTAL RESOURCES INC ID Date: 08/04/03  
Case #: NDM88457 FAC ID: Effective Date: 08/08/03  
Form: I FAC NAME: Abatement Date: 09/12/03  
Assessment: \$0 Inspector: DENNIS HANNUM Corrected Date: 08/11/03  
Gravity: 3 Followup Date: 08/12/03  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, A, 2 Extend Date:  
Remarks Date: 08/04/03

No Radius of Exposure Calculations. Must submit to this office, by sundry notice (fed. form 3160-5), Radius of Exposure Calculations. Talked to Mr. Russel Atkins about this matter 8/4/03. The green copy is the operators copy.

Office: DK ID: DK5978  
Unique INC #: IWM0222 Well Name:  
Well #:  
Operator: L & J OPERATING INCORPORATED ID Date: 09/03/02  
Case #: SDM39501 FAC ID: A Effective Date: 09/16/02  
Form: I FAC NAME: WULF FEDERAL 1 & 2 Abatement Date: 10/16/02  
Assessment: \$0 Inspector: MC MANUS Corrected Date: 11/23/02  
Gravity: 3 Followup Date: 11/23/02  
Authority Ref: 43 CFR 3164.1 OO#6 III.D.3.e Extend Date: 11/16/02  
Remarks Date: 09/10/02

No wind direction indicator. Now that the Wulf Fed. #2 well is producing, a wind direction indicator is required. Install wind direction indicator by Oct. 16,2002

Office: DK ID: DK5999  
Unique INC #: IMK03001 Well Name: CHSU BW  
Well #: 21-26SH 16 ID Date: 09/29/02  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 10/11/02  
Case #: NDM86282 FAC ID: Abatement Date: 10/31/02  
Form: I FAC NAME: Corrected Date: 10/02/02  
Assessment: \$0 Inspector: MIKE KOLLING Followup Date: 10/10/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.3-2 43 CFR 3164.1  
Remarks Date: 10/02/02

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Failure to comply with section 4 of the 8 point plan in the approved Application for Permit to Drill (APD), which states 9 5/8 inch - 36# casing will be used. on September 29, 2002, six hundred and fifty one feet of 9 5/8 inch - 32.3# casing along with 9/8 inch - 36# casing was placed in the well bore and cemented in. Submit on a sundry notice justifying your deviation from the APD.

Office: FE		ID: FE11762
Unique INC #: 03VRB004	Well Name: NEBU	
	Well #: 307M	
Operator: DEVON ENERGY PRODUCTION CO LP		
Case #: NMSF079010	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: BALDERAZ	
Gravity: 3		
Authority Ref: APD GeneralStip I-7		

Remarks Date: 02/24/03

Operator failed to notify the BLM 24 hours prior to spudding as required by APD. This INC will be complied with as soon as operator returns signed copy back, by returning signed INC operator verifies this requirement will not be violated in future operations.

Office: FE		ID: FE12081
Unique INC #: 03GEF195	Well Name: ALLISON UNIT	
	Well #: 107S	
Operator: BURLINGTON RESOURCES O&G CO LP		
Case #: NMNM78372C	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FITZPATRICK	
Gravity: 3		
Authority Ref: 43 CFR 3162.1		

Remarks Date: 06/19/03

Operator failed to give BLM 24 hr. notice prior to commencing cementing operations on 9 5/8" casing in accordance with the approved APD. Well Allison Unit # 107. Lease # NMSF078459B. Casing is to beset at 2400 hrs. 06/19/03. BLM was contacted at 0920 hrs. 06/19/03. Contractor is Baicat rig # 5. Failure to comply in the future is subject to monetary penalty under 43 CFR 3163.1

Office: FE		ID: FE12072
Unique INC #: 03GEF194	Well Name: SAN JUAN 30-5 UNIT	
	Well #: 29M	
Operator: CONOCOPHILLIPS COMPANY		
Case #: NMSF080538	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: FITZPATRICK	
Gravity: 3		
Authority Ref: 43CFR3162.1		

Remarks Date: 06/19/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Operator failed to give BLM 24 hr. notice prior to commencing cementing operations on 9 5/8" casing in accordance with the approved APD. Well San Juan 30-5 Unit, number 29 M ,lease number NMSF080538, Casing was set at 0415 hrs. 06/19/03. BLM was contacted at 1800 hrs. 06/18/03. Contractor is KEY Energy, Rig number 47. Failure to comply in the future is subject to monetary penalty under 43 CFR 3163.1

Office: FE ID: FE11492  
Unique INC #: 03AVJ003 Well Name: WESTWATER FEDERAL 6  
Well #: 1 ID Date: 12/16/02  
Effective Date: 12/16/02  
Operator: SITTA R E Abatement Date: 01/05/03  
Case #: NMNM62579 FAC ID: 1 Corrected Date: 12/16/02  
Form: I FAC NAME: WESTWATER FEDERAL 6 Followup Date: 12/16/02  
Assessment: \$0 Inspector: JAMISON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Remarks Date: 12/16/02

The lessee/operator shall perform operations and maintain equipment in a safe and workman-like manner. The operator shall take all precautions necessary to provide adequate protection for the health and safety of life and the protection of property. Repair fence around pump jack

Office: FE ID: FE11897  
Unique INC #: 03AVJ038 Well Name: DODD GEIGER  
Well #: 1 ID Date: 05/07/03  
Effective Date: 05/08/03  
Operator: ELM RIDGE RESOURCES INC Abatement Date: 05/30/03  
Case #: NMNM67094 FAC ID: Corrected Date: 05/20/03  
Form: I FAC NAME: Followup Date: 06/02/03  
Assessment: \$0 Inspector: JAMISON Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Remarks Date: 05/07/03  
Reinstall pump jack guard

Office: FE ID: iFE11864  
Unique INC #: 03LDJ0009 Well Name: LEAH MARIE  
Well #: 3 ID Date: 04/01/03  
Effective Date: 04/30/03  
Operator: DUGAN PRODUCTION CORPORATION Abatement Date: 05/27/03  
Case #: NMNM55113 FAC ID: Corrected Date: 05/12/03  
Form: I FAC NAME: Followup Date: 05/27/03  
Assessment: \$0 Inspector: JARAMILLO L Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Remarks Date: 04/01/03

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

The operator must install and maintain adequate guards around the pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property. Install guard around pumpjack fly-wheel.

Office: FE		ID: FE11864
Unique INC #: 03LDJ0009	Well Name: LEAH MARIE	
	Well #: 3	ID Date: 04/01/03
Operator: DUGAN PRODUCTION CORPORATION		Effective Date: 04/30/03
Case #: NMNM55113	FAC ID:	Abatement Date: 05/27/03
Form: I	FAC NAME:	Corrected Date: 05/12/03
Assessment: \$0	Inspector: JARAMILLO L	Followup Date: 05/27/03
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 04/01/03

The operator must install and maintain adequate guards around the pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property. Install guard around pumpjack fly-wheel.

Office: FE		ID: FE11423
Unique INC #: MCK0101	Well Name: FLORANCE	
	Well #: 66F	ID Date: 11/29/02
Operator: XTO ENERGY INC		Effective Date: 12/05/02
Case #: NMNM03380	FAC ID:	Abatement Date: 12/09/02
Form: I	FAC NAME:	Corrected Date: 12/08/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/21/02. At this time, it was noted that the fence around the reserve pit did not meet the minimum requirements. A phone call was made to Mr. Jeff Patton on 11/21/02 at 10:45 am informing him of the need for corrective measures at this location. A follow up inspection on 11/29/02, found that the fence had not been repaired. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must construct and maintain a legal fence around the reserve pit which complies with the required stipulations .

Office: FE		ID: FE11429
Unique INC #: MCK0107	Well Name: FLORANCE	
	Well #: 64F	ID Date: 11/29/02
Operator: XTO ENERGY INC		Effective Date: 12/05/02
Case #: NMNM03380	FAC ID:	Abatement Date: 12/09/02
Form: I	FAC NAME:	Corrected Date: 12/08/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/29/02

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the drilling line and debris located inside the reserve pit.

Office: FE		ID: FE11428
Unique INC #: MCK0106	Well Name: FLORANCE D	
	Well #: 4B	ID Date: 11/29/02
Operator: XTO ENERGY INC		Effective Date: 12/05/02
Case #: NMNM03380	FAC ID:	Abatement Date: 12/09/02
Form: I	FAC NAME:	Corrected Date: 12/07/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the debris located inside the reserve pit.

Office: FE		ID: FE11432
Unique INC #: MCK0110	Well Name: FLORANCE	
	Well #: 64M	ID Date: 11/29/02
Operator: XTO ENERGY INC		Effective Date: 12/05/02
Case #: NMNM03380	FAC ID:	Abatement Date: 12/09/02
Form: I	FAC NAME:	Corrected Date: 12/09/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the debris located inside the reserve pit.

Office: FE		ID: FE11422
Unique INC #: MCK0100	Well Name: FLORANCE	
	Well #: 66F	ID Date: 11/27/02
Operator: XTO ENERGY INC		Effective Date: 12/05/02
Case #: NMNM03380	FAC ID:	Abatement Date: 12/09/02
Form: I	FAC NAME:	Corrected Date: 12/08/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 12/02/02

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

An inspection of this well location was conducted on 11/21/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. A phone call was made to Mr. Jeff Patton on 11/21/02 at 10:45 am informing him of the need for corrective measures at this location. A follow up inspection on 11/29/02, found that the refuse and trash on the location had not been removed. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the debris located inside the reserve pit. An inspection of this well location was conducted on 11/21/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. A phone call was made to Mr. Jeff Patton on 11/21/02 at 10:45 am informing him of the need for corrective measures at this location. A follow up inspection on 11/29/02, found that the refuse and trash on the location had not been removed. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the debris located inside the reserve pit.

Office: FE		ID: FE11430
Unique INC #: MCK0108	Well Name: FLORANCE	
	Well #: 64F	ID Date: 11/29/02
Operator: XTO ENERGY INC		Effective Date: 12/05/02
Case #: NMNM03380	FAC ID:	Abatement Date: 12/09/02
Form: I	FAC NAME:	Corrected Date: 12/08/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/21/02. At this time, it was noted that the fence around the reserve pit did not meet the minimum requirements. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must construct and maintain a legal fence around the reserve pit which complies with the required stipulations. Additionally, because there is an accumulation of oil in the pit, you must cover the pit with a net of a suitable material to prevent entry into the pit by birds.

Office: FE		ID: FE11431
Unique INC #: MCK0109	Well Name: FLORANCE	
	Well #: 64F	ID Date: 11/29/02
Operator: XTO ENERGY INC		Effective Date: 12/05/02
Case #: NMNM03380	FAC ID:	Abatement Date: 12/09/02
Form: I	FAC NAME:	Corrected Date: 12/08/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that the soils and vegetation behind the reserve pit (NW) had been covered with oil/parrafin during the completion phase of this well. Therefore, you must take action to remove the oil/parrafin from the surrounding vegetation and affected soils at this location.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: FE ID: FE11424  
Unique INC #: MCK0102 Well Name: FLORANCE D ID Date: 11/29/02  
Well #: 13B Effective Date: 12/05/02  
Operator: XTO ENERGY INC Abatement Date: 12/09/02  
Case #: NMNM03380 FAC ID: Corrected Date: 12/06/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. In accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the drilling line on the south side of the locaiton and the debris located inside the reserve pit.

Office: FE ID: FE11433  
Unique INC #: MCK0111 Well Name: FLORANCE ID Date: 11/29/02  
Well #: 64M Effective Date: 12/05/02  
Operator: XTO ENERGY INC Abatement Date: 12/09/02  
Case #: NMNM03380 FAC ID: Corrected Date: 12/09/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that the reserve pit was not netted satisfactorily and the blow pit was not fenced at all. Therefore, in accordance with the stipulations caontained in the approved Application for Permit to Drill, you must construct and maintain a legal fence around the reserve pit and blow pit which complies with the required stipulations. Additionally, because there is an accumulation of oil in the reserve pit , you must cover the pit with a net of a suitable material to prevent entry by birds.

Office: FE ID: FE11434  
Unique INC #: MCK0112 Well Name: DAWSON A ID Date: 11/21/02  
Well #: 1F Effective Date: 12/05/02  
Operator: XTO ENERGY INC Abatement Date: 12/09/02  
Case #: NMNM05791 FAC ID: Corrected Date: 12/08/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/21/02

An inspection of this well location was conducted on 11/21/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. A phone call was made to Mr. Jeff Patton on 11/21/02 at 10:45 am informing him of the need for corrective measures at this location. A follow up inspection on 11/29/02, found that the refuse and trash on the location had not been removed. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the debris located inside the reserve pit.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: FE ID: FE11435  
Unique INC #: MCK0113 Well Name: DAWSON A ID Date: 11/21/02  
Well #: 1F Effective Date: 12/05/02  
Operator: XTO ENERGY INC Abatement Date: 12/09/02  
Case #: NMNM05791 FAC ID: Corrected Date: 12/08/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/21/02

An inspection of this well location was conducted on 11/21/02. At this time, it was noted that there was an accumulation of oil in the reserve pit and the blow pit. A phone call was made to Mr. Jeff Patton on 11/21/02 at 10:45 am informing him of the need for corrective measures at this location. A follow up inspection on 11/29/02, found that the blow pit was not completely netted. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must completely net the blow pit to prevent entry by birds.

Office: FE ID: FE10882  
Unique INC #: MCK02037 Well Name: SAN JUAN 31-6 UNIT ID Date: 11/27/01  
Well #: 27 Effective Date: 12/04/01  
Operator: CONOCOPHILLIPS COMPANY Abatement Date: 12/26/01  
Case #: NMNM78421B FAC ID: 27 Corrected Date: 12/10/02  
Form: I FAC NAME: SAN JUAN 31-6 UNIT Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/28/01

The fence around the water disposal pit needs to be repaired. Currently, the fence is not in compliance with applicable standards.

Office: FE ID: FE10884  
Unique INC #: MCK02039 Well Name: SAN JUAN 31-6 UNIT ID Date: 11/27/01  
Well #: 44E Effective Date: 12/04/01  
Operator: CONOCOPHILLIPS COMPANY Abatement Date: 12/26/01  
Case #: NMNM78421B FAC ID: Corrected Date: 12/10/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/28/01

All unguarded pits containing fluid will be fenced with woven wire. All fencing must be a legal fence in accordance with New Mexico State Law. Currently, the fence around the blow pit is not in compliance.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: FE		ID: FE11479
Unique INC #: MCK201	Well Name: CAMPOS 4	
	Well #: 3	ID Date: 12/10/02
Operator: ELM RIDGE RESOURCES INC		Effective Date: 12/16/02
Case #: NMSF078272	FAC ID:	Abatement Date: 12/20/02
Form: I	FAC NAME:	Corrected Date: 12/20/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 12/10/02

An inspection of this well location was conducted on 12/10/02. At this time it was noted that there was refuse and trash on and around the well location that requires removal. Therefore, in accordance with the approved Application for Permit to Drill, all refuse and trash on the above referenced location, including the trash in the reserve pit, must be removed and deposited in an approved disposal site.

Office: FE		ID: FE11478
Unique INC #: MCK200	Well Name: CAMPOS 4	
	Well #: 3	ID Date: 12/10/02
Operator: ELM RIDGE RESOURCES INC		Effective Date: 12/16/02
Case #: NMSF078272	FAC ID:	Abatement Date: 12/20/02
Form: I	FAC NAME:	Corrected Date: 12/20/02
Assessment: \$0	Inspector: KELLY	Followup Date: 01/02/03
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 12/10/02

An inspection of this well location was conducted on 12/10/02. At this time it was noted that the fence around the reserve pit was not constructed in accordance with the approved stipulations. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, a fence must be constructed and maintained which meets the requirements of a legal fence in accordance with New Mexico State Law and/or Onshore Order #7.

Office: FE		ID: FE11420
Unique INC #: 02MCK001	Well Name: F-RPC 20	
	Well #: 3	ID Date: 11/21/02
Operator: RICHARDSON OPERATING CO		Effective Date: 11/28/02
Case #: NMSF079065	FAC ID:	Abatement Date: 11/28/02
Form: I	FAC NAME:	Corrected Date: 12/23/02
Assessment: \$250	Inspector: KELLY	Followup Date: 11/30/02
Gravity: 3		Extend Date: 12/26/02
Authority Ref: 3162.5		

Remarks Date: 11/21/02

An inspection was conducted on this well on 11/21/02. The fence around the reserve pit was found to be poorly constructed and falling down. Trash was also found on and around the location. A telephone call was made to the operators office at 4 pm on 11/21/02 informing them of the situation and advising them to rebuild the fence and remove the trash from the location. A follow up inspection on 11/25/02 at 4:45 pm found that no attempt had been made to bring the location into compliance. Therefore, you must rebuild the fence in accordance with the stipulations contained in the approved application for permit to drill. This requires that a fence that meets the definition of a legal fence in accordance with New Mexico State Law be constructed around the reserve pit. A follow up inspection on 11/30/02, at 5:00 pm found that no attempt to correct the violations had been made. Therefore, because the violation identified above has not been corrected within the timeframe allowed, an assessment is imposed for failure to comply with an order of the authorized officer. You are given until 12/26/02 to come into full compliance with this order. Failure to comply within the specified timeframe will result in civil penalties.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: FE ID: FE11425  
Unique INC #: MCK0103 Well Name: BOLACK C ID Date: 11/29/02  
Well #: 13B Effective Date: 12/05/02  
Operator: XTO ENERGY INC Abatement Date: 12/09/02  
Case #: NMSF079232 FAC ID: Corrected Date: 12/08/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the debris located inside the reserve pit.

Office: FE ID: FE11426  
Unique INC #: MCK0104 Well Name: SCHWERDTFEGER A ID Date: 11/29/02  
Well #: 3F Effective Date: 12/05/02  
Operator: XTO ENERGY INC Abatement Date: 12/09/02  
Case #: NMSF079319 FAC ID: Corrected Date: 12/07/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the debris located inside the reserve pit.

Office: FE ID: FE11427  
Unique INC #: MCK0105 Well Name: SCHWERDTFEGER A ID Date: 11/29/02  
Well #: 13B Effective Date: 12/05/02  
Operator: XTO ENERGY INC Abatement Date: 12/09/02  
Case #: NMSF079319 FAC ID: Corrected Date: 12/07/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/29/02

An inspection of this well location was conducted on 11/29/02. At this time, it was noted that there was refuse and trash on and around the location that required removal. Therefore, in accordance with the stipulations contained in the approved Application for Permit to Drill, you must clean up and remove all refuse and trash on the above referenced location, including the drilling line and debris located inside the reserve pit.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: FE		ID: iFE11765
Unique INC #: 03TLP0005	Well Name: CHARLY HEIRS COM	
	Well #: 1	ID Date: 03/10/03
Operator: XTO ENERGY INC		Effective Date: 03/17/03
Case #: NOOC14203606	FAC ID:	Abatement Date:
Form: I	FAC NAME:	Corrected Date: 03/10/03
Assessment: \$0	Inspector: PIXLEY	Followup Date: 03/12/03
Gravity: 3		Extend Date:
Authority Ref: APD General Requirements I G.		

Remarks Date: 03/10/03

03/08/2003: At 11:11 A.M. I was notified that Charley Heirs #1 would be cemented about sundown by Dennis Elrod. At approximately 17:00 P.M. hours or 5 P.M. I left for the rig site and arrived at 6 P.M. and at that time was told it would be around 9 P. M. I came back to the location at 9 P.M. and was told this time they had only drilled 20 feet of hole and it would be sunday morning some time, but they would call me.I left my card with the driller and one of his hands was standing there when I requested That I be called 1 hour prior to the cementing of the surface casing. At 12:00 noon I arrived on location and was advised the cementing job had already taken place and everyone had been notified but myself. I had specifically left my card with my home number with the driller and the XTO representative already had my number since he had called me on 03/08/2003.

Office: FE		ID: iFE11766
Unique INC #: 03TLP0006	Well Name: CHARLY HEIRS COM	
	Well #: 1	ID Date: 03/11/03
Operator: XTO ENERGY INC		Effective Date: 03/11/03
Case #: NOOC14203606	FAC ID:	Abatement Date: 03/11/03
Form: I	FAC NAME:	Corrected Date: 03/11/03
Assessment: \$0	Inspector: PIXLEY	Followup Date: 03/11/03
Gravity: 3		Extend Date:
Authority Ref: 3162.1		

Remarks Date: 03/11/03

The choke manifold was not installed as stipulated in the APD. The operator had not requested a variance from the APD requirements and therefore this was a violation of the APD.

Office: FE		ID: FE11789
Unique INC #: 03MOW043	Well Name: MUDGE A	
	Well #: 11B	ID Date: 03/28/03
Operator: BP AMERICA PRODUCTION CO.		Effective Date: 03/28/03
Case #: NMSF078040	FAC ID:	Abatement Date: 03/28/03
Form: I	FAC NAME:	Corrected Date: 03/28/03
Assessment: \$0	Inspector: WADE	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 03/28/03

Failure to comply with the General Requirements for Oil and Gas Operations on Federal and Indian Leases(Approved Application for Permit to Drill) I. General, 7. The Field Office Manager (Inspection and Enforcement Section, phone Number(505-599-8907) is to be notified at least 24 hours in advance of any cementing or plugging operations so that a BLM representative may witness the operations.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: FE ID: iFE11390  
Unique INC #: 03MOW001 Well Name: EAST BISTI COAL 8 ID Date: 11/07/02  
Well #: 1R Effective Date: 11/15/02  
Operator: ELM RIDGE RESOURCES INC Abatement Date: 11/26/02  
Case #: NMSF078062A FAC ID: Corrected Date: 11/26/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)

Remarks Date: 11/07/02

Drill site not properly Identified, for wells located on Federal & Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well. The sign shall include the well number, Operator name, lease serial number, communization or unit number as appropriate, and the 1/4 1/4 section, section, township and range. All identification shall be maintained in a legible condition and shall be clearly apparent to any person at or approaching the well site.

Office: FE ID: FE11390  
Unique INC #: 03MOW001 Well Name: EAST BISTI COAL 8 ID Date: 11/07/02  
Well #: 1R Effective Date: 11/15/02  
Operator: ELM RIDGE RESOURCES INC Abatement Date: 11/26/02  
Case #: NMSF078062A FAC ID: Corrected Date: 11/26/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)

Remarks Date: 11/07/02

Drill site not properly Identified, for wells located on Federal & Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well. The sign shall include the well number, Operator name, lease serial number, communization or unit number as appropriate, and the 1/4 1/4 section, section, township and range. All identification shall be maintained in a legible condition and shall be clearly apparent to any person at or approaching the well site.

Office: FE ID: FE11391  
Unique INC #: 03MOW002 Well Name: EAST BISTI COAL 8 ID Date: 11/07/02  
Well #: 1R Effective Date: 11/08/02  
Operator: ELM RIDGE RESOURCES INC Abatement Date: 11/08/02  
Case #: NMSF078062A FAC ID: Corrected Date: 11/08/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.e.

Remarks Date: 11/07/02

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. No secondary power source on accumulator. Production casing has been set and rig being moved to yard for work. No corrective action at this time.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: FE ID: FE11392  
Unique INC #: 03MOW003 Well Name: EAST BISTI COAL 8 ID Date: 11/07/02  
Well #: 1R Effective Date: 11/08/02  
Operator: ELM RIDGE RESOURCES INC Abatement Date: 11/08/02  
Case #: NMSF078062A FAC ID: Corrected Date: 11/08/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 11/07/02  
Whip checks on high pressure hoses not properly installed. Production casing has been set and rig was moving to yard for repairs. No corrective action at this time.

Office: FE ID: iFE11392  
Unique INC #: 03MOW003 Well Name: EAST BISTI COAL 8 ID Date: 11/07/02  
Well #: 1R Effective Date: 11/08/02  
Operator: ELM RIDGE RESOURCES INC Abatement Date: 11/08/02  
Case #: NMSF078062A FAC ID: Corrected Date: 11/08/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 11/07/02  
Whip checks on high pressure hoses not properly installed. Production casing has been set and rig was moving to yard for repairs. No corrective action at this time.

Office: FE ID: iFE11391  
Unique INC #: 03MOW002 Well Name: EAST BISTI COAL 8 ID Date: 11/07/02  
Well #: 1R Effective Date: 11/08/02  
Operator: ELM RIDGE RESOURCES INC Abatement Date: 11/08/02  
Case #: NMSF078062A FAC ID: Corrected Date: 11/08/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order No. 2, III.A.2.e.  
  
Remarks Date: 11/07/02  
Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. No secondary power source on accumulator. Production casing has been set and rig being moved to yard for work. No corrective action at this time.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: GF		ID: iGF2121
Unique INC #: PEW2302	Well Name: ATLANTIC	
	Well #: 3-5	ID Date: 06/06/02
Operator: K2 AMERICA CORPORATION		Effective Date: 06/10/02
Case #: 142002517442	FAC ID:	Abatement Date: 07/10/02
Form: I	FAC NAME:	Corrected Date: 10/16/02
Assessment: \$0	Inspector: WAGES	Followup Date: 12/04/02
Gravity: 3		Extend Date: 11/18/02
Authority Ref: 43 CFR 3162.1(a)		

Remarks Date: 07/25/02

Operator appealed written order. Order was affirmed in part and vacated in part. Operator ordered to submit recompletion report and plans for additional work on the well in lieu of immediate plugging operations. Operator not required to conduct flow test, Operator failed to provide recompletion report and sundry for additional work or plugging. Operator ordered to flow test the well, conduct a downhole temperature survey if hydrates are believed to be preventing the well from flowing, submit a recompletion report with the flow test information, and submit a sundry for plugging if the well is not capable of production in paying quantities., downhole temperature survey, provide copies of third-party flow test results, or submit an NIA.

Office: GR		ID: GR1070
Unique INC #: 033005	Well Name: COPPER RIDGE UNIT	
	Well #: 10-3	ID Date: 02/18/03
Operator: ANADARKO E&P COMPANY LP		Effective Date: 02/18/03
Case #: WYW156470X	FAC ID:	Abatement Date: 02/19/03
Form: I	FAC NAME:	Corrected Date: 02/18/03
Assessment: \$0	Inspector: DULETSKY	Followup Date: 02/18/03
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3164.1(b), O.O. #2. III. A. 1.		

Remarks Date: 02/18/03

There are no flare lines run from the choke manifold to the flare pit. Onshore Oil & Gas Order #2, section III. A. 1. states in part: "Blowout preventer (BOP) and related equipment (BOPE) shall be installed, used, maintained, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe, unless otherwise approved by the APD." All Blowout Preventer Equipment (BOPE) including the flare lines, shall remain in place until the wellbore is secure with casing and cement, or with cement plugs in accordance with an approved plugging procedure.

Office: GS		ID: GS4291
Unique INC #: JF03054	Well Name: HMU	
	Well #: 10-1B(A10B)	ID Date: 05/28/03
Operator: ENCANA OIL & GAS (USA) INC		Effective Date: 06/09/03
Case #: COC55972E	FAC ID:	Abatement Date: 06/27/03
Form: I	FAC NAME:	Corrected Date: 05/29/03
Assessment: \$0	Inspector: FRANCIS	Followup Date: 06/10/03
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1 (a)		

Remarks Date: 05/28/03

Failure to meet notification requirements identified in the Application for permit to drill,which requires a 24 hour notice before spudding,running and cementing of casing strings and BOP test. You will be required to submit your spud notice,casing strapping,cementing and BOP test reports by date identified.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: GS ID: GS4293  
Unique INC #: JF03056 Well Name: HMU ID Date: 05/28/03  
Well #: 10-1D(A10) Effective Date: 06/09/03  
Operator: ENCANA OIL & GAS (USA) INC Abatement Date: 06/27/03  
Case #: COC55972E FAC ID: Corrected Date: 05/29/03  
Form: I FAC NAME: Followup Date: 06/10/03  
Assessment: \$0 Inspector: FRANCIS Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1 (a)

Remarks Date: 05/28/03

Failure to meet notification requirements identified in the Application for permit to drill, which requires a 24 hour notice before spudding, running and cementing of casing strings and BOP test. You will be required to submit your spud notice, casing strapping, cementing and BOP test reports by date identified.

Office: GS ID: GS4290  
Unique INC #: JF03053 Well Name: HMU ID Date: 05/28/03  
Well #: 10-2D(A10B) Effective Date: 06/09/03  
Operator: ENCANA OIL & GAS (USA) INC Abatement Date: 06/27/03  
Case #: COC55972E FAC ID: Corrected Date: 05/29/03  
Form: I FAC NAME: Followup Date: 06/10/03  
Assessment: \$0 Inspector: FRANCIS Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1 (a)

Remarks Date: 05/28/03

Failure to meet notification requirements identified in the Application for permit to drill, which requires a 24 hour notice before spudding, running and cementing of casing strings and BOP test. You will be required to submit your spud notice, casing strapping, cementing and BOP test reports by date identified.

Office: GS ID: GS4295  
Unique INC #: JF03058 Well Name: HMU ID Date: 05/28/03  
Well #: 10-2B(A10B) Effective Date: 06/09/03  
Operator: ENCANA OIL & GAS (USA) INC Abatement Date: 06/27/03  
Case #: COC55972X FAC ID: Corrected Date: 05/29/03  
Form: I FAC NAME: Followup Date: 06/10/03  
Assessment: \$0 Inspector: FRANCIS Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1 (a)

Remarks Date: 05/28/03

Failure to meet notification requirements identified in the application for permit to drill, which requires a 24 hour notice before spudding, running and cementing of casing strings and BOP test. You will be required to submit your spud notice, casing strapping, cementing and BOP test reports by date identified.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: HO		ID: HO7563
Unique INC #: ASC-I19-02	Well Name: FEDERAL 31-G	
	Well #: 02	ID Date: 08/08/02
Operator: CONCHO OIL & GAS CORPORATION		Effective Date: 08/26/02
Case #: NMNM67110	FAC ID:	Abatement Date: 10/15/02
Form: I	FAC NAME:	Corrected Date: 10/15/02
Assessment: \$0	Inspector: CORTEZ	Followup Date: 09/24/02
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3 / 3163.1(a)		

Remarks Date: 08/08/02

Failure to comply with written order to re-install belt guard or extend the guard rails to safeguard the pumping unit. - Comply with original order. Failure to do so will result in monetary assessments.

Office: HO		ID: HO8191
Unique INC #: KAH-068-03	Well Name:	
	Well #:	ID Date: 04/28/03
Operator: APACHE CORPORATION		Effective Date: 05/05/03
Case #: NMLC065525A	FAC ID: A	Abatement Date: 06/05/03
Form: I	FAC NAME: ELLIOTT FED	Corrected Date: 05/23/03
Assessment: \$0	Inspector: HASTON	Followup Date: 05/29/03
Gravity: 3		Extend Date:
Authority Ref: OOGO #6.D.2.e		

Remarks Date: 04/28/03

NO WIND DIRECTION INDICATOR INSTALLED AT BATTERY. -- INSTALL A WIND DIRECTION INDICATOR AT THIS BATTERY. FAILURE TO COMPLY WITHIN ABATEMENT PERIOD MAY RESULT IN THE ISSUANCE OF MONETARY ASSESSMENTS.

Office: HO		ID: HO8213
Unique INC #: KAH-076-03	Well Name:	
	Well #:	ID Date: 04/28/03
Operator: MCELVAIN OIL & GAS PROP INC		Effective Date: 05/08/03
Case #: NMLC065525B	FAC ID: A, B	Abatement Date: 06/08/03
Form: I	FAC NAME: MONTEREY 5,6&7, MONTEREY FED 1	Corrected Date: 06/03/03
Assessment: \$0	Inspector: HASTON	Followup Date: 06/03/03
Gravity: 3		Extend Date:
Authority Ref: OOGO #6.III.D.2.e		

Remarks Date: 04/28/03

NO WIND DIRECTION INDICATOR INSTALLED AT BATTERY. - INSTALL A WIND DIRECTION INDICATOR AT THIS BATTERY. FAILURE TO COMPLY WITHIN ABATEMENT PERIOD MAY RESULT IN THE ISSUANCE OF MONETARY ASSESSMENTS

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: HO		ID: HO8318
Unique INC #: KAH-098-03	Well Name:	
	Well #:	ID Date: 05/12/03
Operator: F & M OIL & GAS COMPANY		Effective Date: 05/16/03
Case #: NMNM38473A	FAC ID: A	Abatement Date: 06/16/03
Form: I	FAC NAME: FEDERAL 7	Corrected Date: 06/16/03
Assessment: \$0	Inspector: HASTON	Followup Date: 06/16/03
Gravity: 3		Extend Date:
Authority Ref: OOGO #6.III.D.2.e		

Remarks Date: 05/12/03

NO WIND DIRECTION INDICATOR INSTALLED AT BATTERY. - INSTALL A WIND DIRECTION INDICATOR AT THIS BATTERY. FAILURE TO COMPLY WITHIN ABATEMENT PERIOD MAY RESULT IN THE ISSUANCE OF MONETARY ASSESSMENTS.

Office: ME		ID: ME1949
Unique INC #: 03MM36MEFO	Well Name: SOUTHEAST RANGELY	
	Well #: 1000	ID Date: 02/04/03
Operator: EL PASO PROD OIL & GAS CO		Effective Date: 02/10/03
Case #: COC64236	FAC ID:	Abatement Date: 02/11/03
Form: I	FAC NAME:	Corrected Date: 02/20/03
Assessment: \$0	Inspector: KRAFT	Followup Date: 02/20/03
Gravity: 1		Extend Date: 02/27/03
Authority Ref: 3162.1(a)		

Remarks Date: 02/04/03

The blooie line discharge is to be 100 feet from the wellbore and securely anchored during the air/mist drilling of the surface hole. This requirement for air/mist drilling was included on a BLM approved sundry notice submitted by El Paso Production Oil & Gas Company representative Cheryl Cameron dated November 21, 2002.

Office: ME		ID: ME1948
Unique INC #: 03MM35MEFO	Well Name: SOUTHEAST RANGELY	
	Well #: 1000	ID Date: 02/04/03
Operator: EL PASO PROD OIL & GAS CO		Effective Date: 02/10/03
Case #: COC64236	FAC ID:	Abatement Date: 02/11/03
Form: I	FAC NAME:	Corrected Date: 02/20/03
Assessment: \$0	Inspector: KRAFT	Followup Date: 02/20/03
Gravity: 1		Extend Date: 02/27/03
Authority Ref: 3162.1(a)		

Remarks Date: 02/04/03

Spark arresters on engines or water cooled exhausts were not found on location during the air/mist drilling of the surface hole. This requirement for air/mist drilling was included on a BLM approved sundry notice submitted by El Paso Production Oil & Gas Company representative Cheryl Cameron dated November 21, 2002.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: ME ID: ME1950  
Unique INC #: 03MM37MEFO Well Name: SOUTHEAST RANGELY  
Well #: 1000 ID Date: 02/04/03  
Operator: EL PASO PROD OIL & GAS CO Effective Date: 02/10/03  
Case #: COC64236 FAC ID: Abatement Date: 02/11/03  
Form: I FAC NAME: Corrected Date: 02/20/03  
Assessment: \$0 Inspector: KRAFT Followup Date: 02/20/03  
Gravity: 1 Extend Date: 02/27/03  
Authority Ref: 3162.1(a)

Remarks Date: 02/04/03

An automatic igniter or continuous pilot light must be installed on the blooie line during the air/mist drilling of the surface hole. This requirement for air/mist drilling was included on a BLM approved sundry notice submitted by El Paso Production Oil & Gas Company representative Cheryl Cameron dated November 21, 2002.

Office: ME ID: ME1947  
Unique INC #: 03MM38MEFO Well Name: SOUTHEAST RANGELY  
Well #: 1000 ID Date: 02/04/03  
Operator: EL PASO PROD OIL & GAS CO Effective Date: 02/10/03  
Case #: COC64236 FAC ID: Abatement Date: 02/11/03  
Form: I FAC NAME: Corrected Date: 02/20/03  
Assessment: \$0 Inspector: KRAFT Followup Date: 02/20/03  
Gravity: 1 Extend Date: 02/27/03  
Authority Ref: 3162.1(a)

Remarks Date: 02/04/03

Mud circulating equipment, water, and mud materials must be sufficient to maintain the capacity of the hole and circulating tanks or pits during the air/mist drilling of the surface hole. This requirement for air/mist drilling was included on a BLM approved sundry notice submitted by El Paso Production Oil & Gas Company representative Cheryl Cameron dated November 21, 2002.

Office: ME ID: ME2009  
Unique INC #: 03BK66MEFO Well Name: PINYON RIDGE FEDERAL  
Well #: 41-30-03-96 ID Date: 06/06/03  
Operator: KLT GAS INC Effective Date: 06/10/03  
Case #: COC65811 FAC ID: Abatement Date: 06/30/03  
Form: I FAC NAME: Corrected Date: 06/30/03  
Assessment: \$0 Inspector: KRAFT Followup Date: 06/30/03  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR3162.6-(a)

Remarks Date: 06/06/03

Every well within a federal or Indian lease shall have a well identification sign. All signs shall be maintained in a legible condition.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: ME ID: ME2015  
Unique INC #: 03BK68MEFO Well Name: PINYON RIDGE FEDERAL ID Date: 06/06/03  
Well #: 24-30-03-96 Effective Date: 06/10/03  
Operator: KLT GAS INC Abatement Date: 06/30/03  
Case #: COC65811 FAC ID: Corrected Date: 06/30/03  
Form: I FAC NAME: Followup Date: 06/30/03  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.6-(a)

Remarks Date: 06/06/03

Every well within a federal or Indian lease shall have a well identification sign. All signs shall be maintained in a legible condition.

Office: ME ID: ME2014  
Unique INC #: 03BK67MEFO Well Name: PINYON RIDGE FEDERAL ID Date: 06/06/03  
Well #: 32-30-03-96 Effective Date: 06/10/03  
Operator: KLT GAS INC Abatement Date: 06/30/03  
Case #: COC65811 FAC ID: Corrected Date: 06/30/03  
Form: I FAC NAME: Followup Date: 06/30/03  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.6-(a)

Remarks Date: 06/06/03

Every well within a federal or Indian lease shall have a well identification sign. All signs shall be maintained in a legible condition.

Office: ME ID: ME1962  
Unique INC #: 03MM46MEFO Well Name: FIGURE FOUR UNIT ID Date: 03/17/03  
Well #: 8002D B14 498 Effective Date: 03/24/03  
Operator: ENCANA OIL & GAS (USA) INC Abatement Date:  
Case #: COC66492X FAC ID: Corrected Date: 03/24/03  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: O'MARA Extend Date:  
Gravity: 3  
Authority Ref: 3162.1(a)

Remarks Date: 03/17/03

Encana well-site drilling superintendent failed to provide 24 hour notice of blow-out preventer pressure test to BLM inspector on March 16, 2003. (This 24 hour notice is specified in the approved APD signed February 13, 2003). The superintendent gave a 2.5 hour notice.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: ME		ID: ME1961
Unique INC #: 03MM45MEFO	Well Name: FIGURE FOUR UNIT	
	Well #: 8002D B14 498	
Operator: ENCANA OIL & GAS (USA) INC		
Case #: COC66492X	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: O'MARA	
Gravity: 3		
Authority Ref: 43 CFR 3162.1		

Remarks Date: 03/14/03

Operator violated approved Application to Drill by drilling a 12.25" surface hole instead of the approved 14.75" surface hole.

Office: ML		ID: iML3196
Unique INC #: BK-03-01	Well Name: BERCIER	
	Well #: 10-9	
Operator: NANCE PETROLEUM CORP		
Case #: 142002568299	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$5,000	Inspector: CHUCK LAAKSO	
Gravity: 1		
Authority Ref: 43 CFR 3163.1(b)(2)		

Remarks Date: 01/10/03

We received an APD for subject well which was approved 12/2/03 by the Montana Board of Oil and Gas Conservation. After reviewing permit, it was determined that the wellsite is located on Allotted Indian Lease 14-20-0246-8299. We called operator to notify them that because the well is on Indian minerals, a federal APD is required. We were informed that the well was being drilled and it was a dry hole. On 1/10/03 we received a request from the operator for plugging procedures for the well. Drilling without approval warrants an immediate assessment of \$500 per day for each day the violation exists. The well was spud on 12/6/02, and has already been plugged, the operator was assessed the maximum of \$5000 (\$500 for 10 days). Bill for Collection for \$5000 accompanied by the INC.

Office: MR		ID: iMR1367
Unique INC #: SJ-05-DS35	Well Name: CARTER UTE	
	Well #: 4	
Operator: BURLINGTON RESOURCES O & G CU		
Case #: 142015113A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: SWANSON	
Gravity: 3		
Authority Ref: NTL MDL 91-1 Change2		

Remarks Date: 02/01/05

Failure to remit copy of 2004 bradenhead test by 1/15/2005 to BLM-Durango Office.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: PD ID: PD1000  
 Unique INC #: JJ0104 Well Name: STUD HORSE BUTTE ID Date: 01/22/01  
 Well #: 1-21 Effective Date: 01/23/01  
 Operator: ULTRA PETROLEUM Abatement Date: 02/22/01  
 Case #: WYW118155 FAC ID: Corrected Date: 03/18/03  
 Form: I FAC NAME: Followup Date: 03/18/03  
 Assessment: \$0 Inspector: John James Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.6 (b)  
 Remarks Date: 01/22/01  
 Well sign has no 1/4 1/4

Office: RO ID: RO7788  
 Unique INC #: 06003JH022 Well Name: ID Date: 07/23/03  
 Well #: Effective Date: 07/24/03  
 Operator: THRESHOLD DEVELOPMENT COMPANY Abatement Date: 07/24/03  
 Case #: NMNM99009 FAC ID: Corrected Date: 07/28/03  
 Form: I FAC NAME: Followup Date:  
 Assessment: \$0 Inspector: HOGWOOD Extend Date:  
 Gravity: 3  
 Authority Ref: APD

Remarks Date: 07/23/03  
 THE APD FOR THE ABOVE WELL STATES THAT A FRESH WATER SYSTEM WILL BE USED AT LEAST TO A DEPTH OF 2,000'. BRINE WATER HAS BEEN HAULED AND PUT INTO THE DRILLING PIT. IT MUST BE REMOVED WITHIN 24 HOURS FROM RECEIPT OF THIS NOTIFICATION, AND REPLACED WITH FRESH WATER PRIOR TO STATUS OF DRILLING OPERATIONS.

Office: RW ID: RW2845  
 Unique INC #: CT-017-R03 Well Name: HAYSTACK ID Date: 12/11/02  
 Well #: 33R Effective Date: 12/19/02  
 Operator: GMT ENERGY CORP Abatement Date: 01/08/03  
 Case #: WYW125284 FAC ID: Corrected Date: 01/02/03  
 Form: I FAC NAME: Followup Date: 01/09/03  
 Assessment: \$0 Inspector: THOMAS Extend Date:  
 Gravity: 3  
 Authority Ref: 43 CFR 3162.6 (a) (b) (c)

Remarks Date: 12/11/02  
 NO WELL IDENTIFICATION SIGN ON LEASE. PUT WELL IDENTIFICATION SIGN WITH COMPLETE AND CORRECT INFORMATION ON IT IN A CONSPICUOUS PLACE ON LEASE.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: RW ID: RW2868  
Unique INC #: CT--026-R0 Well Name: DELANEY RIM ID Date: 02/05/03  
Well #: 2 Effective Date: 02/14/03  
Operator: FLYING J OIL & GAS INC Abatement Date: 03/05/03  
Case #: WYW126749 FAC ID: Corrected Date: 03/18/03  
Form: I FAC NAME: Followup Date: 03/18/03  
Assessment: \$0 Inspector: THOMAS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (a) (b) (c)

Remarks Date: 02/05/03

No well identification sign. Put a well identification sign with complete and correct information on it in a conspicuous place on the well location.

Office: RW ID: RW3018  
Unique INC #: CT-104-R03 Well Name: LITTLE ROBBERS FEDERAL ID Date: 09/17/03  
Well #: 19-16 Effective Date: 09/17/03  
Operator: PETROGULF CORPORATION Abatement Date: 09/18/03  
Case #: WYW130160 FAC ID: Corrected Date: 09/18/03  
Form: I FAC NAME: Followup Date: 09/18/03  
Assessment: \$0 Inspector: THOMAS Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order # 2 III. A. 2. e

Remarks Date: 09/17/03

Kommey system power turned off. Repair kommey system so that both electric and air can be turned on and left on.

Office: RW ID: RW2857  
Unique INC #: CT-022-R-0 Well Name: BATTLE FEDERAL ID Date: 01/24/03  
Well #: 1-27 Effective Date: 01/31/03  
Operator: SAMSON RESOURCES COMPANY Abatement Date: 02/20/03  
Case #: WYW147023 FAC ID: Corrected Date: 02/07/03  
Form: I FAC NAME: Followup Date: 02/07/03  
Assessment: \$0 Inspector: THOMAS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3161.2, 43 CFR 312.3-1 f

Remarks Date: 01/24/03

Reserve pit is not fenced on all four (4) sides. Install fencing on all four (4) sides of the reserve pit.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: TU ID: iTU20783  
Unique INC #: 03JFD004 Well Name: REDMOON  
Well #: 7-29 ID Date: 01/06/03  
Operator: CHESAPEAKE OPERATING INC Effective Date: 01/06/03  
Case #: 14202057672 FAC ID: Abatement Date: 01/06/03  
Form: I FAC NAME: Corrected Date: 01/06/03  
Assessment: \$0 Inspector: JOHNSON Followup Date: 01/07/03  
Gravity: 1 Extend Date:  
Authority Ref: Title43CFR3162.5-1(a,b)

Remarks Date: 01/09/03

The operator was required to remove the discharge line from the rig to the Washita River and stop discharging fluid into the Washita River. We assessed the operator \$2500.00.

Office: TU ID: iTU20749  
Unique INC #: 03JFD001 Well Name:  
Well #: ID Date: 12/19/02  
Operator: KWB OIL PROPERTY MANAGEMENT Effective Date: 12/20/02  
Case #: I51IND51534 FAC ID: A Abatement Date: 12/20/02  
Form: I FAC NAME: EYE BEAR Corrected Date: 12/20/02  
Assessment: \$0 Inspector: JOHNSON Followup Date: 12/20/02  
Gravity: 3 Extend Date:  
Authority Ref: Title43CFR3162.5-1(a,b,c,e)

Remarks Date: 12/26/02

You are instructed to remove and dispose of in an authorized disposal site all carcasses of dead livestock on the lease hold. As per Title43CFR3162.5-1 (a,b,c,e). This is to be done by the close of business 12/20/2002.

Office: VE ID: VE10260  
Unique INC #: CJ03039 Well Name: CIGE  
Well #: 186 ID Date: 04/08/03  
Operator: WESTPORT OIL & GAS COMPANY LP Effective Date: 04/15/03  
Case #: UTU63047A FAC ID: Abatement Date: 05/08/03  
Form: I FAC NAME: Corrected Date: 04/22/03  
Assessment: \$0 Inspector: CLIFF JOHNSON Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6 (b)(c)

Remarks Date: 04/08/03

Well sign had an incorrect 1/4 1/4 identification. Please correct by having sign changed to show correct 1/4 1/4. Please refer to surveyors plat attached.

Safety and Drilling Related Violations (INCs) Issued During FY 2003  
As of March 3, 2011

Office: VE		ID: VE10549
Unique INC #: DK03202	Well Name: GB	ID Date: 08/08/03
	Well #: 11M-27-8-21	Effective Date: 08/08/03
Operator: SHENANDOAH ENERGY INC		Abatement Date: 08/09/03
Case #: UTU0803	FAC ID:	Corrected Date: 08/09/03
Form: I	FAC NAME:	Followup Date: 08/09/03
Assessment: \$0	Inspector: DONNA KENNEY	Extend Date:
Gravity: 3		
Authority Ref: Onshore Oder #2 ,II,Q.		

Remarks Date: 08/08/03

Hand wheel valves on choke manifold system are hard to operate by hand and require pipe wrenches and at least two guys to open or close. Please repair or replace so they operate and function as they were designed.

Office: VE		ID: VE9905
Unique INC #: JS03001	Well Name: OU GB	ID Date: 01/10/03
	Well #: 12W-9-8-22	Effective Date: 01/10/03
Operator: SHENANDOAH ENERGY INC		Abatement Date: 02/13/03
Case #: UTU63021X	FAC ID:	Corrected Date: 02/06/03
Form: I	FAC NAME:	Followup Date:
Assessment: \$0	Inspector: JAMIE SPARGER	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3162.6 (a), (b)		

Remarks Date: 01/13/03

The lease number presently on your well sign is UTU43915. This number is incorrect. The correct lease number is UTU74494. Please remove the incorrect number and add the correct. Further, this well is also within Unit #UTU63021X. Once oil is produced and if the oil is stored on this location, the Unit number (UTU63021X) will need to be included on the well sign as per 43 CFR 3162.6 (c).

Office: VE		ID: VE10458
Unique INC #: JB03092	Well Name: HUMPBACK	ID Date: 07/15/03
	Well #: 8-25-8-17	Effective Date:
Operator: INLAND PRODUCTION COMPANY		Abatement Date: 07/15/03
Case #: UTU76189X	FAC ID:	Corrected Date: 07/15/03
Form: I	FAC NAME:	Followup Date:
Assessment: \$0	Inspector: JERRY BARNES	Extend Date:
Gravity: 3		
Authority Ref: 43 CFR 3164.1(a) & OOGO No.2 Section III.A.2.iii.B		

Remarks Date: 07/15/03

Failure to test BOP after changing pipe rams from 4.5 to 5.5 inch to run casing.

Safety and Drilling Related Violations (INC)s Issued During FY 2002  
As of March 3, 2011

Office: BA ID: BA1612  
Unique INC #: 05-045-02 Well Name: SEC 20 ID Date: 08/28/02  
Well #: 1120 Effective Date: 08/28/02  
Operator: MACPHERSON OIL COMPANY Abatement Date: 08/29/02  
Case #: CACA34219X FAC ID: Corrected Date: 08/29/02  
Form: I FAC NAME: Followup Date: 08/29/02  
Assessment: \$0 Inspector: 5 GARNAND G Extend Date:  
Gravity: 3  
Authority Ref: Onshore #2III(A)1.

Remarks Date: 08/28/02

Bolts and nuts where missing off the casing head spool. Blowout preventer and related equipment shall be installed, used, maintained in a manner necessary to assure well control. Install bolts and nuts on casing head spool. Sign INC and return to Bakersfield field office.

Office: BU ID: BU5957  
Unique INC #: NS-02-005 Well Name: USFS PINEY CANYON VEG ID Date: 08/20/02  
Well #: 43-25 Effective Date: 08/20/02  
Operator: CONTINENTAL INDUSTRIES, LC Abatement Date: 08/20/02  
Case #: WYW67220A FAC ID: Corrected Date: 09/04/02  
Form: I FAC NAME: Followup Date: 08/20/02  
Assessment: \$1,000 Inspector: STURDEVANT Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3163.1(b)(2)

Remarks Date: 08/20/02

Drilling operations were commenced on August 19, 2002 and continued into August 20, 2002, until BLM shut-down at 9:45am, without prior approval of the Application for Permit to Drill. 43 CFR 3163.1(b)(2) "For drilling without approval, \$500.00 per day for each day that the violation existed, including days the violation existed prior to discovery..."

Office: CA ID: CA2066  
Unique INC #: L02-16 Well Name: LIBERATOR FEDERAL ID Date: 08/27/02  
Well #: 7-20 Effective Date: 09/03/02  
Operator: CONTINENTAL INDUSTRIES LC Abatement Date: 09/06/02  
Case #: WYW126102 FAC ID: Corrected Date: 09/02/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: LONG Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.3-1(c)

Remarks Date: 08/29/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Surface disturbance was initiated on above cited wellsite and/or access road prior to approval of Application for Permit to Drill by the Authorized Officer, Casper Field Office. Please halt activity until APD has been approved and a copy delivered to dirt contractor. When violation has been corrected, please sign original copy of this notice and return to the Casper Field Office.

Office: CA ID: CA1959  
Unique INC #: L02-05 Well Name: LOST DOME FEDERAL  
Well #: 6-H ID Date: 11/19/01  
Operator: BREITBURN ENERGY COMPANY, LLC Effective Date: 11/26/01  
Case #: WYW146610X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LONG  
Gravity: 3  
Authority Ref: Onshore Oil & Gas Order No. 1, III.,G.,f.

Remarks Date: 11/19/01

Approved APD and Drilling Plan is not on location. Among other things, APD stipulates that well no. 2 is to be shut-in during drilling operations and that well no. 5 is to be protected from damage caused by drilling operations. Please furnish a complete copy of the APD for above cited well to drilling foreman at wellsite upon receipt of this notice. You were notified by voicemail at 1230, 11/19/2001. SEE ALSO: Approved APD, General Conditions of Approval, item no. 4.

Office: CB ID: CB15339  
Unique INC #: 02-JA-014 Well Name: BIG TANK 33 FEDERAL  
Well #: 1 ID Date: 10/06/01  
Operator: SOUTHWESTERN ENERGY PRODUCTION Effective Date:  
Case #: NMLC028936D FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: AMOS  
Gravity: 3  
Authority Ref: 43 CFR 3162.6b  
Extend Date:

Remarks Date: 10/06/01

Well location is not properly identified. Need to install a well sign. Sign is to include the Operator, Well Name and Number, The Federal Lease Number, and the legal discription, Quarter/Quarter, Section, Township and Range. The State of New Mexico requires the API number.

Office: CB ID: CB15340  
Unique INC #: 02-JA-015 Well Name: BIG TANK 33 FEDERAL  
Well #: 1 ID Date: 10/06/01  
Operator: SOUTHWESTERN ENERGY PRODUCTION Effective Date:  
Case #: NMLC028936D FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: AMOS  
Gravity: 3  
Authority Ref: APD Condition of Approval  
Extend Date:

Remarks Date: 10/06/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Reserve pits are to be fenced on three sides with the fourth side fenced as soon as rig moves off location. Fence three sides of reserve pit.

Office: CB ID: CB15686  
Unique INC #: 02-DE-144 Well Name: BEECH FEDERAL  
Well #: 1, 2 ID Date: 01/10/02  
Operator: MACK ENERGY CORPORATION Effective Date:  
Case #: NMLC058181 FAC ID: M, O Abatement Date: 02/10/02  
Form: I FAC NAME: BEECH FED # 1, BEECH FED. #2 Corrected Date: 01/28/02  
Assessment: \$0 Inspector: EARLY Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER # 6,111.2. (A&B)

Remarks Date: 06/24/02

ON THE BEECH FEDERAL TANK BATTERYS FAILURE TO SUBMIT H2S RADII OF EXPOSURE FOR THE BEECH FEDERAL TANK BATTERYS 1&2.  
AND IF NECESSARY PUBLIC PROTECTION PLAN AS PER ONSHORE ORDER # 6. RADII OF EXPOSURE SUBMITTED ON THE 1/28/2002.

Office: CB ID: CB15683  
Unique INC #: 02-DE-149 Well Name: BEECH FEDERAL  
Well #: 1 ID Date: 01/10/02  
Operator: MACK ENERGY CORPORATION Effective Date:  
Case #: NMLC058181 FAC ID: M Abatement Date: 02/10/02  
Form: I FAC NAME: BEECH FED # 1 Corrected Date: 02/04/02  
Assessment: \$0 Inspector: EARLY Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 06/24/02

ON THE BEECH FEDERAL WELL # 1 NO BELT OR COUNTER WEIGHT GUARDS AROUND PUMP JACK. INSTALL GUARDS AROUND PUMP  
JACK. FOLLOWUP INSPECTION ON THE 1/9/2002.

Office: CB ID: CB15701  
Unique INC #: 02-DE-140 Well Name: BERRY A  
Well #: 27 ID Date: 12/18/01  
Operator: SDX RESOURCES INCORPORATED Effective Date:  
Case #: NMNM025527A FAC ID: B, K Abatement Date: 01/15/02  
Form: I FAC NAME: BERRY/BERRYA Corrected Date: 01/02/02  
Assessment: \$0 Inspector: EARLY Followup Date: 01/02/02  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER#6.111.A.2.(A&B)

Remarks Date: 06/26/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

ON THE TRIGG FEDERAL AND THE BERRY A FEDERAL TANK BATTERY. FAILURE TO SUBMIT H2S RADII EXPOSURE. SUBMIT RADII OF EXPOSURE, AND IF NECESSARY PUBLIC PROTECTION PLAN AS PER ONSHORE ORDER # 6.

Office: CB ID: CB15702  
Unique INC #: 02-DE-141 Well Name: BERRY A  
Well #: 27 ID Date: 12/18/01  
Operator: SDX RESOURCES INCORPORATED Effective Date:  
Case #: NMNM025527A FAC ID: B, K Abatement Date: 01/15/02  
Form: I FAC NAME: BERRY/BERRYA Corrected Date: 01/02/02  
Assessment: \$0 Inspector: EARLY Followup Date: 01/02/02  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER#6.111.A.2.(A&B)

Remarks Date: 06/26/02

ON THE BERRY A FEDERAL TANK BATTERY. FAILURE TO SUBMIT H2S RADII EXPOSURE. SUBMIT RADII OF EXPOSURE AND IF NECESSARY PUBLIC PROTECTION PLAN AS PER ONSHORE ORDER # 6

Office: CB ID: CB15847  
Unique INC #: 02-GH-100 Well Name:  
Well #: ID Date: 08/12/02  
Operator: YATES PETROLEUM CORPORATION Effective Date:  
Case #: NMNM81218 FAC ID: A Abatement Date: 09/12/02  
Form: I FAC NAME: BRANNIGAN ANF BATTERY Corrected Date: 09/12/02  
Assessment: \$0 Inspector: HUNT Followup Date: 02/25/04  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.A.2.a

Remarks Date: 08/12/02

Production battery has higher than 100 ppm in the gas stream. Calculate and submit the 100 ppm and 500 ppm radius of exposure for the facility, within thirty days of notice. Also, if applicable, submit copy of Public Protection Plan for this facility within thirty days of notice.

Office: DK ID: DK5924  
Unique INC #: IWM0216 Well Name: RUSCH  
Well #: 1, 2R ID Date: 07/18/02  
Operator: WARD WILLISTON COMPANY Effective Date: 08/01/02  
Case #: CANW103 FAC ID: A Abatement Date: 09/01/02  
Form: I FAC NAME: RUSCH 1 & 2R Corrected Date: 08/07/02  
Assessment: \$0 Inspector: BILL MCMANUS Followup Date: 08/07/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 OO#6 III D.1 c.

Remarks Date: 07/25/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

WIND DIRECTION INDICATORS ARE MISSING AT THE BATTERY AND WELLS. INSTALL WIND DIRECTION INDICATORS AT THE BATTERY AND WELLS

Office: DK ID: DK5925  
Unique INC #: IWM0217 Well Name:  
Well #:  
Operator: WARD WILLISTON COMPANY ID Date: 07/18/02  
Case #: CANW103 Effective Date: 08/01/02  
Form: I FAC ID: A Abatement Date: 08/15/02  
Assessment: \$0 FAC NAME: RUSCH 1 & 2R Corrected Date: 08/07/02  
Gravity: 3 Inspector: BILL McMANUS Followup Date: 08/07/02  
Extend Date:  
Authority Ref: 43 CFR 3164.1 OO#6 III D.1 c.

Remarks Date: 07/25/02  
Flare ignitor not in working order. Repair flare system to safely gather and burn hydrogen sulfide gas

Office: DK ID: DK5922  
Unique INC #: IWM0214 Well Name: KIMBERLY  
Well #: 13-7HZ ID Date: 07/17/02  
Operator: SLAWSON EXPLORATION CO INC Effective Date: 08/01/02  
Case #: NDM85848 FAC ID: Abatement Date: 09/01/02  
Form: I FAC NAME: Corrected Date: 08/28/02  
Assessment: \$0 Inspector: BILL McMANUS Followup Date: 08/28/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164/1 OO#6 III D.3c.

Remarks Date: 07/25/02  
NO HYDROGEN SULFIDE DANGER SIGN AT THE KIMBERLY 13-7 WELL . INSTALL A HYDROGEN SULFIDE DANGER SIGN AT THE KIMBERLY 13-7 WELL

Office: DK ID: DK5921  
Unique INC #: IWM0213 Well Name: KIMBERLY  
Well #: 13-7HZ ID Date: 07/17/02  
Operator: SLAWSON EXPLORATION CO INC Effective Date: 08/01/02  
Case #: NDM85848 FAC ID: Abatement Date: 09/01/02  
Form: I FAC NAME: Corrected Date: 08/28/02  
Assessment: \$0 Inspector: BILL McMANUS Followup Date: 08/28/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 OO#6 III D.3c.

Remarks Date: 07/25/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

WIND DIRECTION INDICATOR IS MISSING AT THE KIMBERLY 13-7 WELL INSTALL A WIND DIRECTION INDICATOR AT THE KIMBERLY 13-7 WELL

Office: DK ID: DK5950  
Unique INC #: IDB02056 Well Name: PAPINEAU USA  
Well #: 1 ID Date: 07/30/02  
Operator: PAUL B RANKIN INC Effective Date: 08/08/02  
Case #: NDM30596 FAC ID: A Abatement Date: 09/08/02  
Form: I FAC NAME: PAPINEAU USA 1 Corrected Date: 08/08/02  
Assessment: \$0 Inspector: DEBBIE BOHLMAN Followup Date: 08/19/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 OO#6 III.D.2.c

Remarks Date: 08/01/02

No H2S danger sign installed at location. Install H2S danger sign at location per Onshore Order #6 III.D.3.a. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5949  
Unique INC #: IDB02055 Well Name:  
Well #: ID Date: 07/30/02  
Operator: PAUL B RANKIN INC Effective Date: 08/08/02  
Case #: NDM30596 FAC ID: A Abatement Date: 09/08/02  
Form: I FAC NAME: PAPINEAU USA 1 Corrected Date: 08/08/02  
Assessment: \$0 Inspector: DEBBIE BOHLMAN Followup Date: 08/19/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 OO#6 III.D.3.e

Remarks Date: 08/01/02

Wind direction indicator needs to be replaced. Replace wind direction indicator as required in Onshore Order #6 III D.3.e. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5937  
Unique INC #: IDB02047 Well Name: ABEL USA  
Well #: 3 ID Date: 07/23/02  
Operator: EAGLE OPERATING INCORPORATED Effective Date: 08/08/02  
Case #: NDM33880 FAC ID: Abatement Date: 09/08/02  
Form: I FAC NAME: Corrected Date: 08/08/02  
Assessment: \$0 Inspector: DEBBIE BOHLMAN Followup Date: 08/22/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 OO #6 III.D.3.a

Remarks Date: 08/01/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

No H2S danger sign installed at well location. Install H2S danger sign at well location per Onshore Order #6 III.D.3.a. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5932  
Unique INC #: IDB02042 Well Name: DELORES USA  
Well #: 1 ID Date: 07/23/02  
Effective Date: 08/08/02  
Operator: EAGLE OPERATING INCORPORATED Abatement Date: 09/08/02  
Case #: NDM33880 FAC ID: Corrected Date: 08/08/02  
Form: I FAC NAME: Followup Date: 08/22/02  
Assessment: \$0 Inspector: DEBBIE BOHLMAN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO #6 III.D.3.a

Remarks Date: 08/01/02

No H2S danger sign installed at well location. Install H2S danger sign at well location per Onshore Order #6 III.D.3.a. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5933  
Unique INC #: IDB02043 Well Name: DELORES USA  
Well #: 2 ID Date: 07/23/02  
Effective Date: 08/08/02  
Operator: EAGLE OPERATING INCORPORATED Abatement Date: 09/08/02  
Case #: NDM33880 FAC ID: Corrected Date: 08/08/02  
Form: I FAC NAME: Followup Date: 08/22/02  
Assessment: \$0 Inspector: DEBBIE BOHLMAN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO #6 III.D.3.a

Remarks Date: 08/01/02

No H2S danger sign installed at well location. Install H2S danger sign at well location per Onshore Order #6 III.D.3.a. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5936  
Unique INC #: IDB02046 Well Name: ABEL USA  
Well #: 2 ID Date: 07/23/02  
Effective Date: 08/08/02  
Operator: EAGLE OPERATING INCORPORATED Abatement Date: 09/08/02  
Case #: NDM33880 FAC ID: Corrected Date: 08/08/02  
Form: I FAC NAME: Followup Date: 08/22/02  
Assessment: \$0 Inspector: DEBBIE BOHLMAN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO #6 III.D.3.a

Remarks Date: 08/01/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

No H2S danger sign installed at well location. Install H2S danger sign at well location per Onshore Order #6 III.D.3.a. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5935  
Unique INC #: IDB02045 Well Name: DELORES USA  
Well #: 4 ID Date: 07/23/02  
Operator: EAGLE OPERATING INCORPORATED Effective Date: 08/08/02  
Case #: NDM33880 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: DEBBIE BOHLMAN  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO #6 III.D.3.a  
Followup Date: 08/22/02  
Extend Date:

Remarks Date: 08/01/02

No H2S danger sign installed at well location. Install H2S danger sign at well location per Onshore Order #6 III.D.3.a. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5934  
Unique INC #: IDB02044 Well Name: DELORES USA  
Well #: 3 ID Date: 07/23/02  
Operator: EAGLE OPERATING INCORPORATED Effective Date: 08/08/02  
Case #: NDM33880 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: DEBBIE BOHLMAN  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO #6 III.D.3.a  
Followup Date: 08/22/02  
Extend Date:

Remarks Date: 08/01/02

No H2S danger sign installed at well location. Install H2S danger sign at well location per Onshore Order #6 III.D.3.a. The green copy of the Notice of Incidents of Noncompliance is the operator copy.

Office: DK ID: DK5807  
Unique INC #: IDH01012 Well Name: FEDERAL  
Well #: 20-14 ID Date: 09/10/01  
Operator: HEADINGTON OIL LIMITED PRTNR Effective Date: 09/14/01  
Case #: NDM78010 FAC ID: A  
Form: I FAC NAME: FEDERAL 20-14  
Assessment: \$0 Inspector: DENNIS HANNUM  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, A, 2  
Followup Date: 11/20/01  
Extend Date: 11/30/01

Remarks Date: 09/10/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

No Radius of Exposure calculations. Must submit to this office, by Sundry Notice, Radius of Exposure calculations. Called and talked to Mr. Mike Hagel about this matter 9/10/2001. The green copy is the operators copy.

Office: FE ID: iFE11171  
Unique INC #: 02AVJ068 Well Name: NAVAJO 14  
Well #: 2 ID Date: 07/01/02  
Effective Date: 07/01/02  
Operator: Abatement Date: 07/02/02  
Case #: 14206032198 FAC ID: Corrected Date: 07/02/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMISON Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3160.0-5

Remarks Date: 07/01/02  
violation of approved APD drain reserve pit. place steel or fiberglass pit. Follow approved APD on all special stipulations. After drilling Richardson Operating Co. has 24hrs to back fill pit.

Office: FE ID: FE11224  
Unique INC #: 02MK012 Well Name: FEDERAL BLANCETT COM C  
Well #: 1 ID Date: 08/12/02  
Effective Date: 08/13/02  
Operator: KOCH EXPLORATION COMPANY Abatement Date: 09/05/02  
Case #: NMNM86333 FAC ID: Corrected Date: 08/15/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KECMAN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 08/13/02  
There is a small gas leak from a regulator on the left water tank. You must repair this leak.

Office: FE ID: FE10842  
Unique INC #: MCK02027 Well Name: WALKER KOCH  
Well #: 1C ID Date: 11/09/01  
Effective Date: 11/14/01  
Operator: BURLINGTON RESOURCES O&G CO LP Abatement Date: 11/16/01  
Case #: NMNM014110 FAC ID: Corrected Date: 11/14/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KELLY Extend Date:  
Gravity: 3  
Authority Ref: 3162.5-1

Remarks Date: 11/09/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

All unguarded pits containing fluid will be fenced with woven wire. All fencing must be a legal fence in accordance with New Mexico State Law. Upon completion of the well, the reserve pit will be covered with screening or netting and remain covered until the pit is reclaimed. Currently, the fence does not meet the requirements of a legal fence and lacks screening or netting.

Office:	FE	ID:	FE10844
Unique INC #:	MCK02029	Well Name:	WALKER KOCH
		Well #:	1C
Operator:	BURLINGTON RESOURCES O&G CO LP	ID Date:	11/09/01
Case #:	NMNM014110	Effective Date:	11/14/01
Form:	I	Abatement Date:	11/16/01
Assessment:	\$0	Corrected Date:	11/16/01
Gravity:	3	Followup Date:	
Authority Ref:	3162.5-1	Extend Date:	

Remarks Date: 11/09/01

Well location will be maintained in a workmanlike manner with due regard for safety, conservation and appearance. Currently, there is an area behind the blowdown pit that was contaminated during the completion of this well. This area must be thoroughly cleaned up to prevent the contaminated soil and vegetation from migrating down the arroyo and into the stock pond.

Office:	FE	ID:	FE10843
Unique INC #:	MCK02028	Well Name:	WALKER KOCH
		Well #:	1C
Operator:	BURLINGTON RESOURCES O&G CO LP	ID Date:	11/09/01
Case #:	NMNM014110	Effective Date:	11/14/01
Form:	I	Abatement Date:	11/16/01
Assessment:	\$0	Corrected Date:	11/14/01
Gravity:	3	Followup Date:	
Authority Ref:	3162.5-1	Extend Date:	

Remarks Date: 11/09/01

Well location will be maintained in a workmanlike manner with due regard for safety, conservation and appearance. Currently, there is refuse on and around this location that must be removed. (drilling line, plastic sheeting, timbers, etc.)

Office:	FE	ID:	FE10950
Unique INC #:	MCK02222	Well Name:	SAN JUAN 30-6 UNIT
		Well #:	94M
Operator:	BURLINGTON RESOURCES O&G CO LP	ID Date:	06/03/02
Case #:	NMNM02151A	Effective Date:	06/10/02
Form:	I	Abatement Date:	06/29/02
Assessment:	\$0	Corrected Date:	06/26/02
Gravity:	3	Followup Date:	
Authority Ref:	3162.5-1	Extend Date:	

Remarks Date: 06/03/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

The construction of the fence and corner post of the reserve pit on the southeast corner is unacceptable. The fence and corner post must be brought into compliance with the stipulations contained in the approved Application for Permit to Drill.

Office: FE		ID: FE10951
Unique INC #: MCK02223	Well Name: SAN JUAN 30-6 UNIT	
	Well #: 94M	ID Date: 06/03/02
Operator: BURLINGTON RESOURCES O&G CO LP		Effective Date: 06/10/02
Case #: NMNM02151A	FAC ID:	Abatement Date: 06/29/02
Form: I	FAC NAME:	Corrected Date: 06/29/02
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 06/03/02

All refuse on and around this well location must be removed. An inspection of the subject well location on 6/3/02, identified discarded cans, casing collars, and cement blocks in the reserve pit at this site.

Office: FE		ID: FE10851
Unique INC #: MCK02031	Well Name: SAN JUAN 30-6 UNIT	
	Well #: 114M	ID Date: 11/12/01
Operator: BURLINGTON RESOURCES O&G CO LP		Effective Date: 11/16/01
Case #: NMNM06283	FAC ID:	Abatement Date: 11/20/01
Form: I	FAC NAME:	Corrected Date: 11/20/01
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/13/01

All unguarded pits containing fluid will be fenced with woven wire. All fencing must be a legal fence in accordance with New Mexico State Law. Upon completion of the well, the reserve pit will be covered with screening or netting and remain covered until the pit is reclaimed. Currently, the fence does not meet the standard for a legal fence and the pit has not been screened or netted.

Office: FE		ID: FE10853
Unique INC #: MCK02032	Well Name: SAN JUAN 30-6 UNIT	
	Well #: 114M	ID Date: 11/12/01
Operator: BURLINGTON RESOURCES O&G CO LP		Effective Date: 11/16/01
Case #: NMNM06283	FAC ID:	Abatement Date: 11/20/01
Form: I	FAC NAME:	Corrected Date: 11/16/01
Assessment: \$0	Inspector: KELLY	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 11/13/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Well area and leases premises will be maintained in a workmanlike manner with due regard to safety, conservation and appearance. Currently, there is a sump on location that contains water. In order to protect livestock and wildlife in the area, the water must be removed and the sump eliminated. The operator responded: " Location was inspected, no sump was found". This is because between the time the INC was written and the time the operator went to check on the well, the location had been bladed and the location cleaned up. There are pictures in the well file to substantiate this INC.

Office: FE		ID: FE10850
Unique INC #: MCK02030	Well Name: SAN JUAN 30-6 UNIT	
	Well #: 114M	
Operator: BURLINGTON RESOURCES O&G CO LP		
Case #: NMNM06283	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KELLY	
Gravity: 3		
Authority Ref: 3162.5-1		

Remarks Date: 11/13/01

The unsecured Hydrochloric Acid drums stored on this location present an environmental hazard. To eliminate this hazard, the chemical drums must be removed from this location .

Office: FE		ID: FE10701
Unique INC #: MCK02014	Well Name: SAN JUAN 32-5 UNIT	
	Well #: 11B	
Operator: ENERGEN RESOURCES CORPORATION		
Case #: NMNM78422A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KELLY	
Gravity: 3		
Authority Ref: 3162.5-1		

Remarks Date: 10/25/01

All unguarded pits containing liquid will be fenced with woven wire. Drilling pits will be fenced on three sides and once the rig leaves the location, the fourth side will be fenced. All fencing must be a legal fence in accordance with New Mexico State Law. Upon completion of the well, the reserve pit will be covered with screening or netting and remain covered until the pit is reclaimed.

Office: FE		ID: FE10704
Unique INC #: MCK02015	Well Name: SAN JUAN 32-5 UNIT	
	Well #: 11B	
Operator: ENERGEN RESOURCES CORPORATION		
Case #: NMNM78422A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: KELLY	
Gravity: 3		
Authority Ref: 3162.5-1		

Remarks Date: 10/25/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Well location will be maintained in a workmanlike manner with due regard for safety, conservation and appearance. Currently, there is refuse on this location that must be removed.

Office: FE ID: FE10708  
Unique INC #: MCK02019 Well Name: SAN JUAN 32-5 UNIT  
Well #: 6C ID Date: 10/24/01  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 11/01/01  
Case #: NMSF079011 FAC ID: Abatement Date: 11/23/01  
Form: I FAC NAME: Corrected Date: 11/19/01  
Assessment: \$0 Inspector: KELLY Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 3162.5-1

Remarks Date: 10/25/01

Well location will be maintained in a workmanlike manner with due regard for safety, conservation and appearance. Currently, there is refuse on this location that must be removed.

Office: FE ID: FE10706  
Unique INC #: MCK02017 Well Name: SAN JUAN 32-5 UNIT  
Well #: 19 ID Date: 10/24/01  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 11/01/01  
Case #: NMSF079011 FAC ID: Abatement Date: 11/23/01  
Form: I FAC NAME: Corrected Date: 11/19/01  
Assessment: \$0 Inspector: KELLY Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 3162.5-1

Remarks Date: 10/25/01

Well location will be maintained in a workmanlike manner with due regard for safety, conservation and appearance. Currently, there is refuse on this location that must be removed.

Office: FE ID: FE10705  
Unique INC #: MCK02016 Well Name: SAN JUAN 32-5 UNIT  
Well #: 19 ID Date: 10/24/01  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 11/01/01  
Case #: NMSF079011 FAC ID: Abatement Date: 11/23/01  
Form: I FAC NAME: Corrected Date: 11/19/01  
Assessment: \$0 Inspector: KELLY Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 3162.5-1

Remarks Date: 10/25/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

All unguarded pits containing fluid will be fenced with woven wire. Drilling pits will be fenced on three sides and once the rig leaves the location, the fourth side will be fenced. All fencing must be a legal fence in accordance with New Mexico State Law. Upon completion of the well, the reserve pit will be covered with screening or netting and remain covered until the pit is reclaimed.

Office: FE	Well Name: SAN JUAN 32-5 UNIT	ID: FE10707
Unique INC #: MCK02018	Well #: 6C	ID Date: 10/24/01
Operator: ENERGEN RESOURCES CORPORATION	FAC ID:	Effective Date: 11/01/01
Case #: NMSF079011	FAC NAME:	Abatement Date: 11/23/01
Form: I	Inspector: KELLY	Corrected Date: 11/19/01
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 3162.5-1		

Remarks Date: 10/25/01

All unguarded pits containing fluid will be fenced with woven wire. Drilling pits will be fenced on three sides and once the rig leaves the location, the fourth side will be fenced. All fencing must be a legal fence in accordance with New Mexico State Law. Upon completion of the well, the reserve pit will be covered with screening or netting and remain covered until the pit is reclaimed.

Office: FE	Well Name:	ID: iFE10890
Unique INC #: 02GLB023	Well #:	ID Date: 11/29/01
Operator: CENTRAL RESOURCES INC	FAC ID: A	Effective Date: 12/07/01
Case #: UTU68928A	FAC NAME: TANK BATTERY 58	Abatement Date: 01/06/02
Form: I	Inspector: LESLIE-BOB	Corrected Date: 01/06/02
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1		

Remarks Date: 11/30/01

The operator shall exercise due care and diligence to assure that the leasehold operations do not result in undue damage to surface or subsurface resources. All excess equipment must be removed from the lease or stored in an approved facility. You must apply for this facility as per BLM and Indian regulations. You must remove the two abandoned tanks located approximately 1/4 mile west of Tank Battery 58 (see photo).

Office: FE	Well Name:	ID: iFE10889
Unique INC #: 02GLB022	Well #:	ID Date: 11/29/01
Operator: CENTRAL RESOURCES INC	FAC ID: E	Effective Date: 12/07/01
Case #: UTU68928A	FAC NAME:	Abatement Date: 12/17/01
Form: I	Inspector: LESLIE-BOB	Corrected Date: 12/17/01
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-3		

Remarks Date: 11/30/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

You must install and maintain at least 1 permanent wind indicator so that wind direction can be easily determined at or approaching the storage tanks (see photo).

Office: FE ID: iFE10888  
Unique INC #: 02GLB021 Well Name:  
Well #: ID Date: 11/29/01  
Operator: CENTRAL RESOURCES INC Effective Date: 12/07/01  
Case #: UTU68928A Abatement Date: 12/17/01  
Form: I FAC ID: A Corrected Date: 12/17/01  
Assessment: \$0 FAC NAME: TANK BATTERY 58 Followup Date:  
Gravity: 3 Inspector: LESLIE-BOB Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 11/30/01

You must install and maintain at least 1 permanent wind indicator so that wind direction can be easily determined at or approaching the storage tanks(s) (see photo).

Office: FE ID: iFE10893  
Unique INC #: 02GLB026 Well Name:  
Well #: ID Date: 11/29/01  
Operator: CENTRAL RESOURCES INC Effective Date: 12/07/01  
Case #: UTU68928A Abatement Date: 12/17/01  
Form: I FAC ID: B Corrected Date: 12/17/01  
Assessment: \$0 FAC NAME: Followup Date:  
Gravity: 3 Inspector: LESLIE-BOB Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 11/30/01

You must install and maintain at least 1 permanent wind indicator so that wind direction can be easily determined at or approaching the storage tanks (see photo).

Office: FE ID: FE10907  
Unique INC #: 02MOW037 Well Name: NYE FEDERAL  
Well #: 1B ID Date: 01/04/02  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 01/04/02  
Case #: NMNM021126 FAC ID: Abatement Date: 01/04/02  
Form: I FAC NAME: Corrected Date: 01/04/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/21/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

The operator is required to conduct all operations in a safe and workmanlike manner. The automatic controls are not installed or functional. Please check and secure all high pressure hoses with safety chain hobbles.. Corrected

Office: FE ID: FE10902  
Unique INC #: 02MOW032 Well Name: NYE FEDERAL  
Well #: 1B  
Operator: ENERGEN RESOURCES CORPORATION  
Case #: NMNM021126 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2. III.a.2.h.

Remarks Date: 05/21/02

The operator is required to conduct all operations in a safe and workmanlike manner. The hand wheels were not connected. Corrected.

Office: FE ID: FE10903  
Unique INC #: 02MOW033 Well Name: NYE FEDERAL  
Well #: 1B  
Operator: ENERGEN RESOURCES CORPORATION  
Case #: NMNM021126 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2. III.C.1.

Remarks Date: 05/21/02

The slow pump speed was not being recorded in the Drillers Report. Corrected.

Office: FE ID: FE10901  
Unique INC #: 02MOW031 Well Name: NYE FEDERAL  
Well #: 1B  
Operator: ENERGEN RESOURCES CORPORATION  
Case #: NMNM021126 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2. III.a.2.e.

Remarks Date: 05/21/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Accumulator power (air) not connected, power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Corrected.

Office: FE ID: FE10900  
Unique INC #: 02MOW030 Well Name: NYE FEDERAL  
Well #: 1B ID Date: 01/04/02  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 01/04/02  
Case #: NMNM021126 FAC ID: Abatement Date: 01/04/02  
Form: I FAC NAME: Corrected Date: 01/04/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No. 2. III.a.2.a.

Remarks Date: 05/21/02

A well control device shall be installed at the surface that is capable of complete closure of the wellbore. Please install a drill string safety valve and/or inside BOP valve, and maintain in an open position on the rig floor. Corrected same day.

Office: FE ID: FE10905  
Unique INC #: 02MOW035 Well Name: NYE FEDERAL  
Well #: 1B ID Date: 01/04/02  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 01/04/02  
Case #: NMNM021126 FAC ID: Abatement Date: 01/04/02  
Form: I FAC NAME: Corrected Date: 01/04/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No. 2. III.A.2.ii.

Remarks Date: 05/21/02

The lessee/operator shall take immediate steps and use necessary resources to maintain or restore control of any well in which the pressure equilibrium has become unbalanced. The observed fill lines were not properly installed or operable as required by the approved APD permit.

Office: FE ID: FE10906  
Unique INC #: 02MOW036 Well Name: NYE FEDERAL  
Well #: 1B ID Date: 01/04/02  
Operator: ENERGEN RESOURCES CORPORATION Effective Date: 01/04/02  
Case #: NMNM021126 FAC ID: Abatement Date: 01/04/02  
Form: I FAC NAME: Corrected Date: 01/04/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No. 2. III.A.2.ii.

Remarks Date: 05/21/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Choke manifold pressure gauge not rated for mud service

Office: FE ID: FE10641  
Unique INC #: 01MOW130 Well Name: JACQUEZ  
Well #: 331 ID Date: 09/18/01  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 09/24/01  
Case #: NMNM87141 FAC ID: 331 Abatement Date: 10/29/01  
Form: I FAC NAME: JACQUEZ Corrected Date: 10/09/01  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3132.6(b)

Remarks Date: 09/24/01

For wells located on Federal & Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well. The sign shall include the well number, Operator name, lease serial number, communitization or unit number as appropriate, and the  $\frac{1}{4}\frac{1}{4}$  section, section, township and range. All identification shall be maintained in a legible condition and shall be clearly apparent to any person at or approaching the sales or transportation point.

Office: FE ID: FE11286  
Unique INC #: 02MOW087 Well Name: SAN JUAN 28-7 UNIT  
Well #: 242F ID Date: 09/10/02  
Operator: CONOCOPHILLIPS COMPANY Effective Date: 09/10/02  
Case #: NMSF078417A FAC ID: Abatement Date: 09/10/02  
Form: I FAC NAME: Corrected Date: 09/10/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No. 2.III.A.2.e.

Remarks Date: 09/13/02

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing. Repaired before inspector left location.

Office: FE ID: FE11285  
Unique INC #: 02MOW086 Well Name: SAN JUAN 28-7 UNIT  
Well #: 242F ID Date: 09/10/02  
Operator: CONOCOPHILLIPS COMPANY Effective Date: 09/10/02  
Case #: NMSF078417A FAC ID: Abatement Date: 09/10/02  
Form: I FAC NAME: Corrected Date: 09/10/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No. 2.III.A.2.b.ii.

Remarks Date: 09/13/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

The lessee/operator shall take immediate steps and use necessary resources to maintain or restore control of any well in which the pressure equilibrium has become unbalanced. The observed manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. "Fill Line" Repaired before inspector left location.

Office: FE		ID: FE11287
Unique INC #: 02MOW088	Well Name: SAN JUAN 28-7 UNIT	
	Well #: 242F	
Operator: CONOCOPHILLIPS COMPANY		
Case #: NMSF078417A	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WADE	
Gravity: 3		
Authority Ref: 43 CFR 3162.3-1 e.		

Remarks Date: 09/13/02

Failure to obtain prior approval to modify an Approved Application for Permit to Drill. Change in tail cement quality, quantity and properties. Field approval granted by Mike Wade. Submit sundry notice requesting formal approval for to change tail cement quality, quantity and properties.

Office: FE		ID: FE10913
Unique INC #: 02MOW038	Well Name: HOWELL C	
	Well #: 3B	
Operator: BURLINGTON RESOURCES O&G CO LP		
Case #: NMSF078580	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WADE	
Gravity: 3		
Authority Ref: Onshore Order No. 2. III.A.2.b.ii.		

Remarks Date: 05/21/02

The lessee/operator shall take immediate steps and use necessary resources to maintain or restore control of any well in which the pressure equilibrium has become unbalanced. The observed manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. Choke lines not anchored - Fixed

Office: FE		ID: FE10915
Unique INC #: 02MOW040	Well Name: HOWELL C	
	Well #: 3B	
Operator: BURLINGTON RESOURCES O&G CO LP		
Case #: NMSF078580	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: WADE	
Gravity: 3		
Authority Ref: Onshore Order No. 2 III.A.2e.		

Remarks Date: 05/21/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Accumulator power (air) not connected, power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Corrected.

Office: FE ID: FE10916  
Unique INC #: 02MOW041 Well Name: HOWELL C  
Well #: 3B  
Operator: BURLINGTON RESOURCES O&G CO LP  
Case #: NMSF078580 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2 III.C.1.

Remarks Date: 05/21/02

The slow pump speed was not being recorded in the Drillers Report. Corrected

Office: FE ID: FE10914  
Unique INC #: 02MOW039 Well Name: HOWELL C  
Well #: 3B  
Operator: BURLINGTON RESOURCES O&G CO LP  
Case #: NMSF078580 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2 III.A.2.h.

Remarks Date: 05/21/02

The operator is required to conduct all operations in a safe and workmanlike manner. The automatic controls are not installed or functional. Please check the rig floor controls, master control, and BOPE for hand wheels or autolocks .One hand wheel not installed - Fixed

Office: FE ID: FE10917  
Unique INC #: 02MOW042 Well Name: HOWELL C  
Well #: 3B  
Operator: BURLINGTON RESOURCES O&G CO LP  
Case #: NMSF078580 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref: Onshore Order No. 2 III.A.2.f.

Remarks Date: 05/21/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Minimum standards and enforcement provisions for accumulator pump capacity. Each BOP closing unit shall be equipped with sufficient number and sizes of pumps so that, with the accumulator system isolated from service, the pumps shall be capable of opening the hydraulically-operated gate valve (if so equipped), plus closing the annular preventer on the smallest size drill pipe to be used within 2 minutes, and obtain a minimum of 200 psi above specified accumulator precharge pressure. Manual pump not functional.

Office: FE ID: FE10909  
Unique INC #: 02MOW077 Well Name: FLORANCE  
Well #: 30M ID Date: 04/03/02  
Effective Date: 04/03/02  
Operator: BP AMERICA PRODUCTION CO. Abatement Date: 04/05/02  
Case #: NMSF078596A FAC ID: Corrected Date: 04/05/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/21/02

The operator is required to conduct all operations in a safe and workmanlike manner. The automatic controls are not functional. Would have to send someone down to the master controls to lift a flapper plate. Violation was corrected within 1 hour by disconnecting the remote controls as not required on 2M system..

Office: FE ID: FE10908  
Unique INC #: 02MOW076 Well Name: FLORANCE  
Well #: 30M ID Date: 04/03/02  
Effective Date: 04/03/02  
Operator: BP AMERICA PRODUCTION CO. Abatement Date: 04/05/02  
Case #: NMSF078596A FAC ID: Corrected Date: 04/05/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/21/02

The operator is required to conduct all operations in a safe and workmanlike manner. Secondary accumulator power (air) not connected. Violation corrected air was reconnected within 1 hour.

Office: FE ID: FE10911  
Unique INC #: 02MOW079 Well Name: FLORANCE  
Well #: 30M ID Date: 04/03/02  
Effective Date: 04/03/02  
Operator: BP AMERICA PRODUCTION CO. Abatement Date: 04/05/02  
Case #: NMSF078596A FAC ID: Corrected Date: 04/05/02  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WADE Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order No. 2. III.A.2.h

Remarks Date: 05/21/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

The operator is required to conduct all operations in a safe and workmanlike manner. Install hand wheels for manual locks on BOP. .Violation was corrected prior to resumption of drilling.

Office: FE ID: FE10910  
Unique INC #: 02MOW078 Well Name: FLORANCE  
Well #: 30M ID Date: 04/03/02  
Operator: BP AMERICA PRODUCTION CO. Effective Date: 04/03/02  
Case #: NMSF078596A FAC ID: Abatement Date: 04/05/02  
Form: I FAC NAME: Corrected Date: 04/05/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/21/02

The operator is required to conduct all operations in a safe and workmanlike manner. Please check and secure all high pressure hoses with safety chain hobbles. Violation was corrected prior to resumption of drilling.

Office: FE ID: FE10912  
Unique INC #: 02MOW080 Well Name: FLORANCE  
Well #: 30M ID Date: 04/03/02  
Operator: BP AMERICA PRODUCTION CO. Effective Date: 04/03/02  
Case #: NMSF078596A FAC ID: Abatement Date: 04/05/02  
Form: I FAC NAME: Corrected Date: 04/05/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: Onshore Orded No. 2. III.2.b.ii.

Remarks Date: 05/21/02

The lessee/operator shall take immediate steps and use necessary resources to maintain or restore control of any well in which the pressure equilibrium has become unbalanced. The observed manifold, choke, kill, mud gauge and fill lines are not properly installed or operable as required by the approved APD permit. Violations was corrected prior to resumption of drilling

Office: FE ID: FE11288  
Unique INC #: 02MOW001F Well Name: ROSA UNIT  
Well #: 164B ID Date: 09/05/02  
Operator: WILLIAMS PRODUCTION CO LLC Effective Date: 09/05/02  
Case #: NMSF078772 FAC ID: Abatement Date: 09/06/02  
Form: I FAC NAME: Corrected Date: 09/06/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No.2.III.A.2.b.ii.

Remarks Date: 09/13/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

The lessee/operator shall take immediate steps and use necessary resources to maintain or restore control of any well in which the pressure equilibrium has become unbalanced. The observed manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit.  
"Choke line and Kill line"

Office: FE ID: FE11289  
Unique INC #: 02MOW002F Well Name: ROSA UNIT  
Well #: 164B ID Date: 09/05/02  
Operator: WILLIAMS PRODUCTION CO LLC Effective Date: 09/05/02  
Case #: NMSF078772 FAC ID: Abatement Date: 09/06/02  
Form: I FAC NAME: Corrected Date: 09/06/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 09/13/02

The operator is required to conduct all operations in a safe and workmanlike manner. The automatic controls are not installed or functional. Please check and secure all high pressure hoses with safety chain hobbles.

Office: FE ID: FE11290  
Unique INC #: 02MOW003F Well Name: ROSA UNIT  
Well #: 164B ID Date: 09/05/02  
Operator: WILLIAMS PRODUCTION CO LLC Effective Date: 09/05/02  
Case #: NMSF078772 FAC ID: Abatement Date: 09/06/02  
Form: I FAC NAME: Corrected Date: 09/05/02  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order No.2, III.A.2.e.

Remarks Date: 09/13/02

Blowout preventer and related equipment shall be installed, and tested in a manner necessary to assure well control and shall be in place and operational prior to drilling the surface casing shoe. Power for the closing unit pumps shall be available to the unit so that the pumps shall automatically start when the closing

Office: HO ID: HO7390  
Unique INC #: ASC-015-02 Well Name: SV BOBWHITE FED  
Well #: 01 ID Date: 03/15/02  
Operator: CONCHO OIL & GAS CORPORATION Effective Date: 07/10/02  
Case #: MNMN9414 FAC ID: Abatement Date: 08/05/02  
Form: I FAC NAME: Corrected Date: 08/06/02  
Assessment: \$0 Inspector: ASC/AJM Followup Date: 08/06/02  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3163.1(a) / 3162.5-3

Remarks Date: 06/28/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Failure to comply with written order #ASC-L13-02 to safeguard the pumping unit. - Extend the pumping unit guardrails to safeguard personell from the exposed belts and flywheel on the gas motor. Failure to comply will result in the issuance of monetary assessment.

Office: JA		ID: JA1631
Unique INC #: BRB02003	Well Name: USA 20-8	
	Well #: 1	ID Date: 07/26/02
Operator: DENBURY ONSHORE LLC		Effective Date: 07/26/02
Case #: MSES51259X	FAC ID:	Abatement Date: 07/30/02
Form: I	FAC NAME:	Corrected Date: 07/03/02
Assessment: \$0	Inspector: BOTELER	Followup Date: 07/31/02
Gravity: 3		Extend Date:
Authority Ref: ONSHORE ORDER 2		

Remarks Date: 07/29/02

An approved copy of your " Application For Permit To Drill " well #20-8 #1 is required to be on drill site location . No copy of this permit was found at drill site , therefore , you are required to post your approved APD at wellsite .

Office: MI		ID: MI1160
Unique INC #: JTW-01-010	Well Name: USA	
	Well #: 1-A	ID Date: 06/28/01
Operator: NORTHWOOD ENERGY CORP		Effective Date: 07/02/01
Case #: OHES27596	FAC ID: A	Abatement Date: 08/10/01
Form: I	FAC NAME:	Corrected Date: 11/29/01
Assessment: \$0	Inspector: WOOD	Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162		

Remarks Date: 07/02/01

THE FLYWHEEL ON THE PUMPING UNIT IS EXPOSED, AND PRESENTS A SAFETY HAZARD TO PERSONNEL WORKING AROUND THE UNIT, AND TO ANY MEMBERS OF THE PUBLIC WHO MAY BE IN THE AREA. FENCE THE PUMPING UNIT TO INHIBIT ENTRY INTO THE HAZARD AREA.

Office: ML		ID: ML3100
Unique INC #: IH381-1	Well Name:	
	Well #:	ID Date: 05/09/02
Operator: PRAIRIE ENERGY INC		Effective Date: 05/20/02
Case #: CANCR546	FAC ID: A	Abatement Date: 06/30/02
Form: I	FAC NAME: STRASHEIM #3-3	Corrected Date: 08/29/02
Assessment: \$0	Inspector: IRENE HARRIS	Followup Date: 08/29/02
Gravity: 3		Extend Date: 08/30/02
Authority Ref: 43 CFR 3164.1	Onshore Order #6,III.D.3.e	

Remarks Date: 05/13/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

No wind direction indicator on location. You need to install a wind direction indicator. A letter dtd May 15, 2002 from Prairie Energy stated that they no longer own the well and that the new owner as of January 1, 2002, Staghorn Resources LLC, was forwarded this BLM notice.

Office: ML ID: ML3099  
Unique INC #: IH380-2 Well Name:  
Well #:  
Operator: SANNES RONALD M & MARGARET A ID Date: 05/09/02  
Case #: MTM87315 FAC ID: A Effective Date: 05/20/02  
Form: I FAC NAME: IVERSON 1-13 Abatement Date: 06/30/02  
Assessment: \$0 Inspector: IRENE HARRIS Corrected Date: 08/29/02  
Gravity: 3 Followup Date: 08/29/02  
Authority Ref: 43 CFR 3164.1 Onshore Order #6.III.D.3.e Extend Date: 08/30/02  
  
Remarks Date: 05/13/02  
No wind direction indicator on location. You need to install a wind direction indicator.

Office: ML ID: ML3136  
Unique INC #: JB404-4 Well Name:  
Well #:  
Operator: STAGHORN RESOURCES LLC ID Date: 07/26/02  
Case #: MTBIL042177A FAC ID: A Effective Date: 08/08/02  
Form: I FAC NAME: GOV'T MCGHEE Abatement Date: 09/08/02  
Assessment: \$0 Inspector: JOHN BRAMHALL Corrected Date: 09/09/02  
Gravity: 3 Followup Date: 09/09/02  
Authority Ref: 43 CFR 3164.1 Onshore Order No. 6 III.D.3. Extend Date:  
  
Remarks Date: 07/30/02  
No wind sock or warning sign at this facility. Production facilities that contain 100 ppm or more of H2S must have Danger signs posted on or within 50 feet of the facility and at least one wind direction indicator (sock).

Office: PD ID: PD1055  
Unique INC #: 0102JJ Well Name: RIVERSIDE  
Well #: 4-10 ID Date: 06/11/02  
Operator: ULTRA RESOURCES INC Effective Date: 06/11/02  
Case #: WYW06270 FAC ID: Abatement Date: 06/11/02  
Form: I FAC NAME: Corrected Date: 06/11/02  
Assessment: \$0 Inspector: JAMES Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: III.A.1.  
  
Remarks Date: 06/17/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Dart valve was closed on the rig floor

Office: PD ID: PD1056  
Unique INC #: 0202JJ Well Name: RIVERSIDE  
Well #: 4-10  
Operator: ULTRA RESOURCES INC  
Case #: WYW06270 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMES  
Gravity: 3  
Authority Ref: III.A.1.

Remarks Date: 06/17/02

10 M system was in use and the trip tank was not hooked up during the trip

Office: PD ID: PD1064  
Unique INC #: 0902JJ Well Name: MESA  
Well #: 7-28  
Operator: ANSCHUTZ EXPLORATION CORP  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMES  
Gravity: 3  
Authority Ref: OSO#2 III.A.2.g.

Remarks Date: 06/19/02

Hand wheels not on BOP's

Office: PD ID: PD1063  
Unique INC #: 0802JJ Well Name: MESA  
Well #: 7-28  
Operator: ANSCHUTZ EXPLORATION CORP  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMES  
Gravity: 3  
Authority Ref: 43CFR 3162.5-1

Remarks Date: 06/19/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Trash all over the location

Office: PD ID: PD1061  
Unique INC #: 0602JJ Well Name: MESA  
Well #: 7-28 ID Date: 10/17/01  
Operator: ANSCHUTZ EXPLORATION CORP Effective Date: 10/17/01  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$3,000 Inspector: JAMES  
Gravity: 1  
Authority Ref: OSO #2 III.A.2.e.  
  
Remarks Date: 06/19/02  
Air valve was off to the air pumps.

Office: PD ID: PD1062  
Unique INC #: 0702JJ Well Name: MESA  
Well #: 7-28 ID Date: 10/17/01  
Operator: ANSCHUTZ EXPLORATION CORP Effective Date: 10/17/01  
Case #: WYW06286 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMES  
Gravity: 1  
Authority Ref: OSO #2 III.A.1.  
  
Remarks Date: 06/19/02  
Kill line not hooked up

Office: RP ID: iRP4088  
Unique INC #: 02-TDM-009 Well Name: JICARILLA 95  
Well #: 4C ID Date: 04/08/02  
Operator: ENERGEN RESOURCES CORP Effective Date:  
Case #: JIC95 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: MUNIZ  
Gravity: 3  
Authority Ref: 43CFR 3162.6  
  
Remarks Date: 05/17/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

For wells located on Federal or Indian lands, the operator shall properly identify, by a sign in a conspicuous place, each well on the lease. The sign shall include the well number, the name of the operator, the lease serial number, communitization number or unit number as appropriate and the quarter-quarter section, section, township and range.

Office: RW ID: RW2640  
Unique INC #: CR02-03-I Well Name: CG ROAD  
Well #: 10 S-1 ID Date: 11/20/01  
Operator: BP AMERICA PRODUCTION COMPANY Effective Date: 11/27/01  
Case #: WYW121147X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS Abatement Date: 11/30/01  
Gravity: 3 Corrected Date: 11/30/01  
Authority Ref: 43 CFR 3164.1 (a) and Onshore Order No 1 III G. 3. f. Followup Date: 12/26/01  
Remarks Date: 11/26/01 Extend Date:  
Approved Application for Permit to Drill was not on location during construction of lease access road and well pad.

Office: RW ID: RW2641  
Unique INC #: CR02-04-I Well Name: CG ROAD  
Well #: 10 S-1 ID Date: 11/20/01  
Operator: BP AMERICA PRODUCTION COMPANY Effective Date: 11/27/01  
Case #: WYW121147X FAC ID:  
Form: I FAC NAME:  
Assessment: \$500 Inspector: ROSS Abatement Date: 11/30/01  
Gravity: 1 Corrected Date: 11/30/01  
Authority Ref: 43 CFR 3162.1 (c) and 43 CFR 3163.1 (b) (2) Followup Date: 12/26/01  
Remarks Date: 11/26/01 Extend Date:  
Surface disturbance was commenced prior to the authorized officer's approval of the Application of Permit to Drill. Immediate assessment. You are in violation of 43 CFR 3163.1.

Office: RW ID: RW2693  
Unique INC #: CT-024-R02 Well Name: RED DESERT  
Well #: 10-1 ID Date: 02/28/02  
Operator: RME PETROLEUM COMPANY Effective Date: 02/28/02  
Case #: WYW023757 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS Abatement Date: 03/01/02  
Gravity: 3 Corrected Date: 02/28/02  
Authority Ref: Onshore Order # 2 III. A. 2. g. Followup Date: 03/01/02  
Remarks Date: 02/28/02 Extend Date:

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

One hand wheel not installed. Install all hand wheels on the BOP equipment.

Office: RW ID: RW2694  
Unique INC #: CT-025-R02 Well Name: RED DESERT  
Well #: 10-1 ID Date: 02/28/02  
Operator: RME PETROLEUM COMPANY Effective Date: 02/28/02  
Case #: WYW023757 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: Onshore Order # 2 III. A. 2. g.

Remarks Date: 05/29/02

Valve on open line of the annular preventor. Install valve on the close line of the annular preventer.

Office: RW ID: RW2643  
Unique INC #: CT-004-R02 Well Name: CHAMBERS FEDERAL  
Well #: 4-24 ID Date: 11/26/01  
Operator: RME PETROLEUM COMPANY Effective Date: 11/26/01  
Case #: WYW110120 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 1  
Authority Ref: Onshore Order # 2 III. A. 2. a. iv.

Remarks Date: 11/28/01

Remotely controlled choke not able to be controlled from the floor. Fix the remotely controlled choke to be able to be controlled from the floor.

Office: RW ID: RW2642  
Unique INC #: CT-003-R02 Well Name: CHAMBERS FEDERAL  
Well #: 4-24 ID Date: 11/26/01  
Operator: RME PETROLEUM COMPANY Effective Date: 11/26/01  
Case #: WYW110120 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 1  
Authority Ref: Onshore Order # 2 III. A. 2. a. iv.

Remarks Date: 11/28/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Dart valve failed to hold test pressure while testing all BOP equipment to 5,000 psi. Fix the dart valve or replace with a different dart valve. In either of these two fixes the dart valve will be tested to 5,000 psi without leak off. The test chart shall be available at the rig.

Office: RW ID: RW2644  
Unique INC #: CT-005-R02 Well Name: CHAMBERS FEDERAL  
Well #: 4-24 ID Date: 11/26/01  
Operator: RME PETROLEUM COMPANY Effective Date: 11/26/01  
Case #: WYW110120 FAC ID: Abatement Date: 11/28/01  
Form: I FAC NAME: Corrected Date: 11/29/01  
Assessment: \$0 Inspector: THOMAS Followup Date: 11/29/01  
Gravity: 1 Extend Date: 11/29/01  
Authority Ref: Onshore Order # 2 III. A. 2. h.

Remarks Date: 11/28/01

Remote controls for 5M or greater systems shall be capable of closing all preventors. Fix the remote controls to be capable of closing all preventors.

Office: RW ID: RW2771  
Unique INC #: CT-065R-02 Well Name: LOOKOUT FEDERAL  
Well #: 13-4 ID Date: 09/04/02  
Operator: TOM BROWN INC Effective Date: 09/04/02  
Case #: WYW79628 FAC ID: Abatement Date: 09/05/02  
Form: I FAC NAME: Corrected Date: 09/05/02  
Assessment: \$0 Inspector: THOMAS Followup Date: 09/05/02  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order # 2 III. A. 2. g.

Remarks Date: 09/04/02

Handwheels not installed on the BOP. Install handwheels on the BOP.

Office: TU ID: TU20380  
Unique INC #: 02GO0O3 Well Name: SCHROEDER FEDERAL  
Well #: 1-23D ID Date: 05/17/02  
Operator: DOMINION OK TX EXPL + PROD INC Effective Date: 05/17/02  
Case #: OKNM31420 FAC ID: Abatement Date: 05/18/02  
Form: I FAC NAME: Corrected Date: 05/18/02  
Assessment: \$0 Inspector: OGDEN Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: CFR3164.1(b) Onshore Order 2

Remarks Date: 08/27/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

The chokes on the manifold was found to be inadequate as prescribed in Onshore Order #2.

Office: TU ID: TU20381  
Unique INC #: 02GO004 Well Name: SCHROEDER FEDERAL  
Well #: 1-23D  
Operator: DOMINION OK TX EXPL + PROD INC  
Case #: OKNM31420 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: OGDEN  
Gravity: 3  
Authority Ref: CFR3164.1(b) Onshore Order 2

Remarks Date: 08/27/02

No flair line was found as required in Onshore Order#2.

Office: TU ID: TU20379  
Unique INC #: 02GO002 Well Name: SCHROEDER FEDERAL  
Well #: 1-23D  
Operator: DOMINION OK TX EXPL + PROD INC  
Case #: OKNM31420 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: OGDEN  
Gravity: 3  
Authority Ref: CFR3164.1(b) Onshore Order 2

Remarks Date: 08/27/02

No hand wheels or auto lock found as required in Onshore Order #2.

Office: TU ID: TU20378  
Unique INC #: 02GO001 Well Name: SCHROEDER FEDERAL  
Well #: 1-23D  
Operator: DOMINION OK TX EXPL + PROD INC  
Case #: OKNM31420 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: OGDEN  
Gravity: 3  
Authority Ref: CFR3164.1(b) Onshore Order 2

Remarks Date: 08/27/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

No remote to the BOP found on the rig floor as required in Onshore Order #2.

Office: VE ID: iVE9425  
Unique INC #: AW02026 Well Name: UTE TRIBAL  
Well #: 15-25-55 ID Date: 08/10/02  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 08/18/02  
Case #: 1420H623537 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ALAN WALKER  
Gravity: 3  
Authority Ref: 43CFR3162.6(a)(b)

Remarks Date: 08/12/02

Violation: No well sign on location. Corrective Action: Instaul a well sign that contains all information required by the above stated Federal Regulation.

Office: VE ID: iVE9424  
Unique INC #: AW02025 Well Name: UTE TRIBAL  
Well #: 16-14-55 ID Date: 08/10/02  
Operator: WILLIAMS PRODUCTION RMT CO Effective Date: 08/16/02  
Case #: 1420H624728 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ALAN WALKER  
Gravity: 3  
Authority Ref: 43CFR3162.6(a)(b)

Remarks Date: 08/12/02

Violation: No well sign. Corrective Action: Instaul a well sign with all information required by above stated Federal Regulation.

Office: VE ID: VE9593  
Unique INC #: AW02031 Well Name: FEDERAL  
Well #: 23-21-9-19 ID Date: 09/16/02  
Operator: PANNONIAN ENERGY INC Effective Date: 09/16/02  
Case #: UTU78433 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ALAN WALKER  
Gravity: 3  
Authority Ref: 43CFR3162.6(b)

Remarks Date: 09/16/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

Violation: No well sign on Location. Corrective Action: Place a well sign in a Conspicuous place. The sign shall include the well number, the name of the operator, the lease serial number, & the surveyed location, quarter-quarter section, section, township, and range.

Office: VE ID: VE9594  
Unique INC #: AW02030 Well Name: FEDERAL  
Well #: 23-21-9-19  
Operator: PANNONIAN ENERGY INC  
Case #: UTU78433 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ALAN WALKER  
Gravity: 3  
Authority Ref: 43CFR3162.1(a) A.P.D. Surface Use Plan Point 9. B.  
Remarks Date: 09/16/02  
Point 9 (B) of the Surface uses plan requires that the pit be fenced on three sides during drilling operations. Corrective Action : Fence the reserve pit to standards in point 9 B of the A.P.D. Surface use plan.

Office: VE ID: iVE9178  
Unique INC #: CJ02001 Well Name: TABBEE  
Well #: 3-120  
Operator: EL PASO PROD OIL & GAS CO  
Case #: UTU60731 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLIFF JOHNSON  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)  
Remarks Date: 05/20/02  
OPERATOR SHALL PROPERLY IDENTIFY BY A SIGN IN A CONSPICUOUS PLACE, EACH WELL.

Office: VE ID: VE9215  
Unique INC #: CJ02003 Well Name: OU GB  
Well #: 7W-19-8-22  
Operator: SHENANDOAH ENERGY INC  
Case #: UTU65404 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: CLIFF JOHNSON  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)  
Remarks Date: 05/28/02

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

OPERATOR SHALL PROPERLY IDENTIFY BY A SIGN IN A CONSPICUOUS PLACE, EACH WELL. PLEASE INSTALL SIGN BY THE ABATEMENT DATE.

Office: VE ID: iVE9203  
Unique INC #: JS02013 Well Name: PAWWINNEE  
Well #: 3-181 ID Date: 03/02/02  
Operator: EL PASO PROD OIL & GAS CO Effective Date: 03/02/02  
Case #: UTU58877 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMIE SPARGER  
Gravity: 3  
Authority Ref: 43CFR3164.1(a)(b), OO#2, III.A.f  
Remarks Date: 05/23/02  
ACCUMULATOR PUMP TEST FAILED @2:35. YOU ARE REQUIRED TO BE ABLE TO OPEN HCR VALVE, CLOSE ANNULAR ON SMALLEST DRILL PIPE TO BE USED AND OBTAIN 200# ABOVE PRECHARGE (1200). YOU MUST CORRECT THIS DEFICIENCY BY THE ABOVE REFERENCED ABATEMENT DATE (3-15-02).

Office: WO ID: WO1989  
Unique INC #: 010-02-C2 Well Name: FIREBRICK UNIT  
Well #: 24 ID Date: 11/20/01  
Operator: EQUITY OIL CO Effective Date: 11/20/01  
Case #: WYW133848A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SWICK/BAKER  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O. #6 III.C.4.a.iii.  
Remarks Date: 11/27/01  
The flare line mouth shall not be less than 150' from the well bore for H2S bearing gas. The flare line shall be staked down properly. Equity Oil Co. has 24hrs. to correct this violation., The flare line was extended to proper length and staked down.

Office: WO ID: WO1990  
Unique INC #: 010-02-C3 Well Name: FIREBRICK UNIT  
Well #: 24 ID Date: 11/20/01  
Operator: EQUITY OIL CO Effective Date: 11/20/01  
Case #: WYW133848A FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SWICK/BAKER  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O. #6 III.C.4.a.iv.  
Remarks Date: 11/27/01

Safety and Drilling Related Violations (INCs) Issued During FY 2002  
As of March 3, 2011

The flare system has no suitable means of ignition. Equity Oil Co. has 24hrs. to install an ignition system on the flare.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: BA ID: BA1150  
Unique INC #: 02-006-01 Well Name: ALTA-VEDDER ID Date: 10/19/00  
Well #: 46L Effective Date: 10/26/00  
Operator: STOCKER RESOURCES INCORPORATED Abatement Date: 11/07/00  
Case #: CACA26739X FAC ID: Corrected Date: 11/08/00  
Form: I FAC NAME: Followup Date: 11/08/00  
Assessment: \$0 Inspector: RODNEY SPARKS Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2, III, A, 2, e

Remarks Date: 10/25/00

Electric switch on accumulator is in the "OFF" position. On future drilling wells the electric switch on accumulator must be in the "ON" position. No further action is required for this well. Sign and return the white copy to the BLM Office.

Office: BA ID: BA1149  
Unique INC #: 02-005-01 Well Name: ALTA-VEDDER ID Date: 10/19/00  
Well #: 46L Effective Date: 10/26/00  
Operator: STOCKER RESOURCES INCORPORATED Abatement Date: 11/07/00  
Case #: CACA26739X FAC ID: Corrected Date: 11/08/00  
Form: I FAC NAME: Followup Date: 11/08/00  
Assessment: \$0 Inspector: RODNEY SPARKS Extend Date:  
Gravity: 3  
Authority Ref: APD Conditions of Approval

Remarks Date: 10/25/00

No remote control on rig floor, 10 bolts are missing from wellhead flange. On future drilling wells remote control must be on rig floor and all bolts to wellhead flange must be installed. No further action is required for this well. Sign and return the white copy to the BLM Office.

Office: BA ID: BA1148  
Unique INC #: 02-004-01 Well Name: ALTA-VEDDER ID Date: 10/19/00  
Well #: 46L Effective Date: 10/26/00  
Operator: STOCKER RESOURCES INCORPORATED Abatement Date: 11/07/00  
Case #: CACA26739X FAC ID: Corrected Date: 11/08/00  
Form: I FAC NAME: Followup Date: 11/08/00  
Assessment: \$0 Inspector: RODNEY SPARKS Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2, III,A,2,a,ii

Remarks Date: 10/25/00

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

No fill up line above preventer. Install fill up line above preventer on all future drilling wells. No further action is required on this well. Sign white copy and return to the BLM Office.

Office: BA ID: BA1151  
Unique INC #: 02-007-01 Well Name: ALTA-VEDDER  
Well #: 46L ID Date: 10/19/00  
Operator: STOCKER RESOURCES INCORPORATED Effective Date: 10/26/00  
Case #: CACA26739X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: RODNEY SPARKS  
Gravity: 3  
Authority Ref: APD Conditions of Approval

Remarks Date: 10/25/00

No B.O.P. function or pressure tests are recorded in drilling log book. On future drilling wells the B.O.P. function and pressure tests must be recorded in the drilling log book. No further action is required on this well. Sign and return white copy to the BLM Office.

Office: BA ID: BA1154  
Unique INC #: 02-009-01 Well Name: ALTA-VEDDER  
Well #: 46L ID Date: 10/19/00  
Operator: STOCKER RESOURCES INCORPORATED Effective Date: 10/26/00  
Case #: CACA26739X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: RODNEY SPARKS  
Gravity: 3  
Authority Ref: Onshore Order #2,III,C,1

Remarks Date: 10/25/00

Slow pump rate is not recorded in drilling log book. On future drilling wells the slow pump rate must be recorded in the drilling log book. No further action is required on this well. Sign and return the white copy to the BLM Office.

Office: BA ID: BA1147  
Unique INC #: 02-003-01 Well Name: ALTA-VEDDER  
Well #: 46L ID Date: 10/19/00  
Operator: STOCKER RESOURCES INCORPORATED Effective Date: 10/26/00  
Case #: CACA26739X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: RODNEY SPARKS  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 10/25/00

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Kill line not hobbled. Kill line must be hobbled on future drilling wells. No further action is required on this well. Sign and return the white copy to the BLM Office.

Office: BA ID: BA1152  
Unique INC #: 02-008-01 Well Name: ALTA-VEDDER  
Well #: 46L ID Date: 10/19/00  
Operator: STOCKER RESOURCES INCORPORATED Effective Date: 10/26/00  
Case #: CACA26739X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: RODNEY SPARKS Abatement Date: 11/07/00  
Gravity: 3 Corrected Date: 11/08/00  
Authority Ref: Onshore Order #2,III,A,2,h,xi Followup Date: 11/08/00  
Extend Date:

Remarks Date: 10/25/00

No B.O.P. crew drills are recorded in the drilling log book. On future drilling wells all B.O.P. crew drills must be recorded in the drilling log book. No further action is required for this well. Sign and return the white copy to the BLM Office.

Office: BU ID: BU5357  
Unique INC #: KB/01/24 Well Name: NORTH KITTY TWENTY MILE  
Well #: 11-29AN ID Date: 06/26/01  
Operator: KENNEDY OIL Effective Date: 07/12/01  
Case #: WYW044377 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BRYCE Abatement Date: 08/16/01  
Gravity: 3 Corrected Date: 08/13/01  
Authority Ref: 3162.6(b) Followup Date: 08/13/01  
Extend Date:

Remarks Date: 07/03/01

Failure to maintain a well sign at the 11-29B well. 43 CFR 3162.6(b) states For wells located on Federal lands or minerals, the operator shall properly identify, by a sign in a conspicuous place each well. The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location, quarter quarter section, section, township and range. Your attention to this matter is appreciated.

Office: BU ID: BU5065  
Unique INC #: NL000005 Well Name: S DRY GULCH MCCREERY, S DRY GULCH WOLFF  
Well #: 10-27, 11-27, 5-26, 6-26, 6-27, 7-27, 8-27 ID Date: 12/13/00  
Operator: ANCHOR BAY CORPORATION Effective Date: 12/20/00  
Case #: WYW130586 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LOFGREN Abatement Date: 12/30/00  
Gravity: 3 Corrected Date: 01/16/01  
Authority Ref: 43CFR3162.6(b) Followup Date: 01/31/01  
Extend Date:

Remarks Date: 12/14/00

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Each well must have legible, conspicuous sign on location from the time the well is spudded until it is plugged and abandoned. The sign must include well number, operator, lease number, legal location including quarter-quarter, section, township, and range

Office: BU		ID: BU5064
Unique INC #: NL000004	Well Name: ROURKE	
	Well #: 44-29-49-71	
Operator: MEDALLION EXPLORATION		
Case #: WYW147273	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: LOFGREN	
Gravity: 3		
Authority Ref: OSO #2 Application to Drill		

Remarks Date: 12/14/00

Reserve pits must be fenced on three sides.

Office: BU		ID: BU5063
Unique INC #: NL000003	Well Name: ROURKE	
	Well #: 44-29-49-71	
Operator: MEDALLION EXPLORATION		
Case #: WYW147273	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: LOFGREN	
Gravity: 3		
Authority Ref: 43CFR3162.6(b)		

Remarks Date: 12/14/00

From the time the well is spudded until it is plugged and abandoned, a legible well sign must be in a conspicuous place on location. The well sign must include the well number, the name of the operator, the lease serial number and the quarter-quarter, section, township, and range.

Office: BU		ID: BU5218
Unique INC #: RN-01-56	Well Name: BONE PILE IV CABALLO	
	Well #: 30-34	
Operator: MTG OPERATING CO		
Case #: WYW147276	FAC ID:	
Form: I	FAC NAME:	
Assessment: \$0	Inspector: NAVARRETTE	
Gravity: 3		
Authority Ref: 34 CFR 3162.1(a)		

Remarks Date: 05/16/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

The fence around the drilling pit is down. You must put the fence back up and keep it up until the pit is closed.

Office: BU	Well Name: BONE PILE IV CABALLO	ID: BU5219
Unique INC #: RN-01-57	Well #: 30-34	ID Date: 05/15/01
Operator: MTG OPERATING CO	FAC ID:	Effective Date: 05/15/01
Case #: WYW147276	FAC NAME:	Abatement Date: 05/17/01
Form: I	Inspector: NAVARRETTE	Corrected Date: 05/16/01
Assessment: \$0		Followup Date:
Gravity: 3		Extend Date:
Authority Ref: 34 CFR 3162.5-1		

Remarks Date: 05/16/01

There is coal cutting are around well and all over location. You must clean up all the location .

Office: BU	Well Name: WESTGATE II DURHAM RANCH	ID: BU5358
Unique INC #: GR-01-17	Well #: 32-4-4572	ID Date: 07/03/01
Operator: LANCE OIL + GAS CO INC	FAC ID:	Effective Date: 07/09/01
Case #: WYW104539	FAC NAME:	Abatement Date: 07/13/01
Form: I	Inspector: ROTH	Corrected Date: 07/13/01
Assessment: \$0		Followup Date: 07/17/01
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 07/05/01

Failure to properly identify well. Specifically; There is not a sign at well location. Corrective action; Install a well sign in a conspicuous place that meets the minimum standards of 43 CFR 3162.6.

Office: BU	Well Name: DURHAM RANCH	ID: BU5362
Unique INC #: GR-01-20	Well #: 12-10-4572	ID Date: 07/03/01
Operator: LANCE OIL + GAS CO INC	FAC ID:	Effective Date: 07/08/01
Case #: WYW104539	FAC NAME:	Abatement Date: 07/13/01
Form: I	Inspector: ROTH	Corrected Date: 07/13/01
Assessment: \$0		Followup Date: 07/17/01
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(a)		

Remarks Date: 07/05/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Failure to properly identify well. Specifically; There is not a sign at well location. Corrective action; Install a well sign in a conspicuous place that meets the minimun standards of 43 CFR 3162.6.

Office: BU ID: BU5360  
Unique INC #: GR-01-19 Well Name: WESTGATE II DURHAM RANCH  
Well #: 41-9-4572  
Operator: LANCE OIL + GAS CO INC  
Case #: WYW130581  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)  
FAC ID:  
FAC NAME:  
Inspector: ROTH  
ID Date: 07/03/01  
Effective Date: 07/08/01  
Abatement Date: 07/13/01  
Corrected Date: 07/13/01  
Followup Date: 07/17/01  
Extend Date:

Remarks Date: 07/05/01

Failure to properly identify well. Specifically; There is not a sign at well location. Corrective action; Install a well sign in a conspicuous place that meets the minimun standards of 43 CFR 3162.6.

Office: BU ID: BU5359  
Unique INC #: GR-01-18 Well Name: WESTGATE II DURHAM RANCH  
Well #: 21-4-4572  
Operator: LANCE OIL + GAS CO INC  
Case #: WYW130581  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)  
FAC ID:  
FAC NAME:  
Inspector: ROTH  
ID Date: 07/03/01  
Effective Date: 07/08/01  
Abatement Date: 07/13/01  
Corrected Date: 07/13/01  
Followup Date: 07/17/01  
Extend Date:

Remarks Date: 07/05/01

Failure to properly identify well. Specifically; There is not a sign at well location. Corrective action; Install a well sign in a conspicuous place that meets the minimun standards of 43 CFR 3162.6.

Office: BU ID: BU5364  
Unique INC #: GR-01-21 Well Name: WESTGATE II DURHAM RANCH  
Well #: 32-5-4572  
Operator: LANCE OIL + GAS CO INC  
Case #: WYW151705  
Form: I  
Assessment: \$0  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a)  
FAC ID:  
FAC NAME:  
Inspector: ROTH  
ID Date: 07/03/01  
Effective Date: 07/08/01  
Abatement Date: 07/13/01  
Corrected Date: 07/13/01  
Followup Date: 07/17/01  
Extend Date:

Remarks Date: 07/05/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Failure to maintain fence around drilling pit. Specifically; One side of the fenced pit at the said well site is down. Corrective action; Put fence back up and maintain it until pit is closed, per Approved surface use plan.

Office: BU		ID: BU5095
Unique INC #: JW01-016V	Well Name: ROLAND FEDERAL	
	Well #: 2	ID Date: 01/28/01
Operator: G & H PRODUCTION CO, LLC		Effective Date: 01/28/01
Case #: WYW131222	FAC ID:	Abatement Date: 01/29/01
Form: I	FAC NAME:	Corrected Date: 01/29/01
Assessment: \$0	Inspector: WALKER	Followup Date: 01/29/01
Gravity: 3		Extend Date:
Authority Ref: Onshore Order No.2,III,A,2,f		

Remarks Date: 01/28/01

Accumulator pumps are not capable of obtaining a minimum of 200 psi above the specified accumulator precharge pressure. Corrective Action: Repair and replace equipment as specified within 24 hours of this notice per Onshore Order No.2,III,A,2,f.

Office: CA		ID: CA1848
Unique INC #: JM01-3	Well Name: BURR FEDERAL	
	Well #: 6-4	ID Date: 11/06/00
Operator: BURR OIL & GAS INCORPORATED		Effective Date:
Case #: WYW134935	FAC ID:	Abatement Date: 11/13/00
Form: I	FAC NAME:	Corrected Date: 11/09/00
Assessment: \$0	Inspector: MESROBIAN	Followup Date: 11/09/00
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-2b		

Remarks Date: 11/06/00

Operator drilled well directionally greater than 18 degrees. This significantly deviates more than 10 degrees from the vertical or projected bottom hole location which could result a bottom hole location less than 200 feet from the spacing unit or lease boundary without prior written approval from the authorized officer. In this case a survey must be submitted to this office with prior approval from State Oil/Gas Commission on the spacing approval as well as submitting a required directional survey. Please submit data within the required abatement time.

Office: CB		ID: CB15025
Unique INC #: 01-JA-126	Well Name:	
	Well #:	ID Date: 07/06/01
Operator: GUADALUPE OPERATING LLP		Effective Date: 07/11/01
Case #: NMLC063567	FAC ID: B	Abatement Date: 08/06/01
Form: I	FAC NAME: YATES FEDERAL BATTERY	Corrected Date: 07/25/01
Assessment: \$0	Inspector: AMOS	Followup Date: 08/10/01
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 6.III.D.c & e		

Remarks Date: 07/06/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

H2S warning signs are not in place. Install H2S warning signs and windsock.

Office: CB	Well Name:	ID: CB15026
Unique INC #: 01-JA-127	Well #:	ID Date: 07/06/01
Operator: GUADALUPE OPERATING LLP	FAC ID: B	Effective Date: 07/11/01
Case #: NMLC063567	FAC NAME: YATES FEDERAL BATTERY	Abatement Date: 08/06/01
Form: I	Inspector: AMOS	Corrected Date: 07/25/01
Assessment: \$0		Followup Date: 08/10/01
Gravity: 3		Extend Date:
Authority Ref: Onshore Order 6.III.D.b		

Remarks Date: 07/06/01

Fencing around facility is not being maintained. Repair fencing and place a gate or chain across the ladder.

Office: CB	Well Name:	ID: CB14662
Unique INC #: 01-CQ-006	Well #:	ID Date: 01/03/01
Operator: WESTALL RAY	FAC ID: A	Effective Date: 01/08/01
Case #: MNM23002	FAC NAME: LLANO FED. #1	Abatement Date: 02/03/01
Form: I	Inspector: Cathleen Queen	Corrected Date: 01/19/01
Assessment: \$0		Followup Date: 01/19/01
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.1(a), Onshore Order 6.III.D.2.e.		

Remarks Date: 01/04/01

Missing or damaged windsock. Install new windsock.

Office: CB	Well Name:	ID: CB14406
Unique INC #: 00-DW-277	Well #:	ID Date: 09/06/00
Operator: JEHOVAH JIREH OIL COMPANY	FAC ID: SALDR	Effective Date: 09/07/00
Case #: MNM71028X	FAC NAME: SALADAR	Abatement Date: 10/10/00
Form: I	Inspector: Duncan Whitlock	Corrected Date: 10/13/00
Assessment: \$0		Followup Date: 10/13/00
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.1/ONSHORE ORDER #6,III,D,2,F		

Remarks Date: 09/07/00

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

FACILITY IS NOT FENCED TO RESTRICT ACCESS DUE TO H2S. A MINIMUM 5-FOOT CHAIN-LINK, OR 5 STRAND BARBED WIRE OR COMPARABLE TYPE FENCE AND GATE THAT RESTRICTS PUBLIC ACCESS SHALL BE INSTALL AT FACILITY. AS PER ONSHORE ORDER #6.

Office: CB ID: CB14460  
Unique INC #: 00-GH-482 Well Name:  
Well #: ID Date: 09/21/00  
Operator: BASS ENTERPRISES PRODUCTION CO Effective Date:  
Case #: NMLC067144 FAC ID: L Abatement Date: 10/20/00  
Form: I FAC NAME: N.INDIAN FLATS BASS FED BATT. Corrected Date: 10/12/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 10/12/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.D.2e

Remarks Date: 09/22/00

WIND DIRECTION INDICATOR NEEDS REPAIR TO OPERATE CORRECTLY. REPAIR/REPLACE THE WIND DIRECTION INDICATOR.

Office: CB ID: CB14484  
Unique INC #: 00-GH-495 Well Name: NIX FEDERAL  
Well #: 3 ID Date: 09/26/00  
Operator: READ & STEVENS INCORPORATED Effective Date:  
Case #: NMNM0486 FAC ID: A Abatement Date: 10/27/00  
Form: I FAC NAME: NIX FEDERAL BATTERY Corrected Date: 10/12/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 10/12/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1,O.O.#6,III.D.2.

Remarks Date: 09/26/00

BECAUSE THE STORAGE TANKS CONTAIN GREATER THAN 500 PPM H2S, THE STAIRS NEED TO BE CHAINED OR MARKED TO RESTRICT ENTRY AS REQUIRED IN ONSHORE ORDERS.

Office: CB ID: CB14486  
Unique INC #: 00-GH-497 Well Name: NIX FEDERAL  
Well #: 3 ID Date: 09/26/00  
Operator: READ & STEVENS INCORPORATED Effective Date:  
Case #: NMNM0486 FAC ID: A Abatement Date: 10/27/00  
Form: I FAC NAME: NIX FEDERAL BATTERY Corrected Date: 10/12/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 10/12/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1,O.O.#6,III.D.2.e

Remarks Date: 09/26/00

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

NO WIND DIRECTION INDICATOR IS INSTALLED AT THE BATTERY. INSTALL A WIND DIRECTION INDICATOR WHICH SATISFIES THE ONSHORE ORDER REFERENCED ABOVE.

Office: CB ID: CB14485  
Unique INC #: 00-GH-496 Well Name: NIX FEDERAL  
Well #: 3 ID Date: 09/26/00  
Operator: READ & STEVENS INCORPORATED Effective Date:  
Case #: NMNM0486 FAC ID: A Abatement Date: 10/27/00  
Form: I FAC NAME: NIX FEDERAL BATTERY Corrected Date: 10/12/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 10/12/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1,O.O.#6,III.D.2.c

Remarks Date: 09/26/00

CORRECT H2S DANGER SIGNS ARE NOT INSTALLED ON OR WITHIN 50 FEET OF THE TANKS, CLEARLY VISIBLE TO PERSONS APPROACHING THE SALES POINT. INSTALL CORRECT SIGNS PROPERLY AS REQUIRED IN ONSHORE ORDERS.

Office: CB ID: CB14859  
Unique INC #: 01-GH-076 Well Name: MUNCHKIN FEDERAL  
Well #: 1 ID Date: 04/16/01  
Operator: CHI OPERATING INCORPORATED Effective Date:  
Case #: NMNM0560353 FAC ID: Abatement Date: 04/18/01  
Form: I FAC NAME: Corrected Date: 04/30/01  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 04/30/01  
Gravity: 1 Extend Date:  
Authority Ref: APD STIPULATIONS OF APPROVAL

Remarks Date: 04/18/01

OIL ON DRILLING RESERVE PITS PRESENTS HAZARD TO WILDLIFE IN AREA. ALSO, COMPLETION PIT LINERS ARE BELOW LEVEL OF LIQUIDS IN THE PITS AND THEY CONTAIN OIL AS WELL. REMOVE ALL LIQUIDS FROM THE PITS WITHIN 48 HOURS OF NOTICE. VERBAL NOTICE GIVEN TO COMPANY REPRESENTATIVE ON 4/16/01 AT 1500 HOURS.

Office: CB ID: CB14797  
Unique INC #: 01-GH-050 Well Name: POCO LOCO 8 FED COM  
Well #: 1 ID Date: 03/16/01  
Operator: HARVEY E YATES COMPANY Effective Date:  
Case #: NMNM105334 FAC ID: Abatement Date: 04/19/01  
Form: I FAC NAME: Corrected Date: 04/05/01  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 04/05/01  
Gravity: 3 Extend Date:  
Authority Ref: APD STIPULATIONS OF APPROVAL

Remarks Date: 03/19/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

DRILLING RESERVE PIT LINERS ARE TORN/BLOWN DOWN BELOW THE LEVEL OF LIQUIDS. REMOVE LIQUIDS FROM THE PIT WITHIN 48 HOURS. IF PIT IS TO BE USED DURING SUBSEQUENT COMPLETION/TESTING OPERATIONS, REPAIR LINERS PRIOR TO USE. ALSO, REMOVE JUNK PIPE,CASING, CABLES, STEEL, PALLETS FROM THE LOCATION WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB14669  
Unique INC #: 01-GH-025 Well Name: LOGAN DRAW 20 FEDERAL  
Well #: 1 ID Date: 01/09/01  
Operator: MURCHISON OIL & GAS INC Effective Date:  
Case #: NMNM12690 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: Eugene Hunt  
Gravity: 3  
Authority Ref: APD STIPULATIONS OF APPROVAL  
Remarks Date: 01/09/01

UNUSED/ JUNK PIPE,CABLE, PALLETS,THREAD PROTECTORS ON LOCATION. REMOVE AND/OR CONTAIN AS PER STIPULATIONS OF APPROVAL. ALSO, PIT LINER MATERIAL IS BELOW THE LIQUID LEVEL IN THE PITS. REMOVE LIQUIDS WITHIN 48 HOURS OF NOTICE.

Office: CB ID: CB14794  
Unique INC #: 01-GH-047 Well Name: TAYLOR UNIT  
Well #: 18 ID Date: 03/06/01  
Operator: WESTALL RAY Effective Date:  
Case #: NMNM71048X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: Eugene Hunt  
Gravity: 3  
Authority Ref: APD STIPULATIONS OF APPROVAL  
Remarks Date: 03/16/01

UNUSED/ JUNK PIPE, CASING, BELT GUARD ON LOCATION. REMOVE WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB14592  
Unique INC #: 01-GH-011 Well Name: MCKITTRICK FED  
Well #: 1Y ID Date: 10/31/00  
Operator: NEARBURG PRODUCING COMPANY Effective Date:  
Case #: NMNM90998 FAC ID: A Abatement Date: 11/22/00  
Form: I FAC NAME: MCKITTRICK FED COM 1Y Corrected Date: 11/22/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 11/22/00  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3164.1,O.O.#6.III.D.2.  
Remarks Date: 11/01/00

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

HIGH H2S IN TANKS AND GAS STREAM WILL REQUIRE THAT THE BATTERY BE EQUIPPED WITH THE FOLLOWING TO COMPLY WITH  
ONSHORE ORDERS: 1)INSTALL PROPER WARNING SIGNS ON OR WITHIN 50 FEET OF THE TANKS AND VISIBLE TO ANY PEOPLE  
APPROACHING THE SALES SPOT, 2) INSTALL A WIND DIRECTION INDICATOR, AND 3)CHAIN OR MARK THE STAIRS TO RESTRICT ENTRY BY  
PERSONNEL. ALL WORK TO BE COMPLETED WITHIN TWENTY WORKING DAYS OF NOTICE.

Office: CB ID: CB14593  
Unique INC #: 01-GH-012 Well Name: MCKITTRICK FED  
Well #: 1Y ID Date: 10/31/00  
Operator: NEARBURG PRODUCING COMPANY Effective Date:  
Case #: NMNM90998 FAC ID: A Abatement Date: 12/01/00  
Form: I FAC NAME: MCKITTRICK FED COM 1Y Corrected Date: 09/13/01  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 11/06/01  
Gravity: 3 Extend Date: 09/15/01  
Authority Ref: 43CFR 3164.1,O.O.#6.III.A.2.

Remarks Date: 11/01/00

RADII OF EXPOSURE FOR H2S HAS NOT BEEN RECEIVED IN THIS OFFICE FOR THIS LEASE. SUBMIT WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB14661  
Unique INC #: 01-GH-024 Well Name: BURRO FEDERAL  
Well #: 1 ID Date: 01/04/01  
Operator: MANZANO OIL CORPORATION Effective Date:  
Case #: NMNM92143 FAC ID: Abatement Date: 02/05/01  
Form: I FAC NAME: Corrected Date: 02/05/01  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 02/12/01  
Gravity: 3 Extend Date:  
Authority Ref: apd stipulations of approval

Remarks Date: 01/04/01

WELLSITE HAS LOOSE PIT LINER MATERIAL, PILES OF TRASH, DISCARDED OIL BARREL, AND PIPE WHICH NEEDS TO BE REMOVED.  
REMOVE ALL TRASH AND JUNK, AND REPAIR THE PIT LINER WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB14975  
Unique INC #: 01-GH-098 Well Name: DALE H PARKE A TR 2  
Well #: 27 ID Date: 06/08/01  
Operator: PREMIER OIL & GAS INCORPORATED Effective Date:  
Case #: NMLC029020A FAC ID: Abatement Date: 06/15/01  
Form: I FAC NAME: Corrected Date: 06/13/01  
Assessment: \$0 Inspector: HUNT Followup Date: 07/10/01  
Gravity: 3 Extend Date:  
Authority Ref: APD STIPULATIONS OF APPROVAL

Remarks Date: 06/12/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

DRILLING RESERVE PITS ARE NOT PROPERLY FENCED ON ALL SIDES. INSTALL FENCE AS REQUIRED IN APD WITHIN 48 HOURS OF NOTICE. ALSO, BAGS, TRASH, THREAD PROTECTORS, PIPE ON LOCATION. REMOVE WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB14973  
Unique INC #: 01-GH-097 Well Name: BRIGHAM H  
Well #: 5 ID Date: 06/08/01  
Operator: MACK ENERGY CORPORATION Effective Date: 06/12/01  
Case #: NMLC029342H FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT Abatement Date: 06/15/01  
Gravity: 3 Corrected Date: 06/15/01  
Authority Ref: APD STIPULATIONS OF APPROVAL Followup Date: 07/10/01  
Extend Date:

Remarks Date: 06/12/01

TOO MUCH OIL IN FRONT PITS. REMOVE OIL WITHIN 48 HOURS OF NOTICE. ALSO, TRASH AND THREAD PROTECTORS IN THE PITS.  
REMOVE WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB15038  
Unique INC #: 01-GH-130 Well Name: MARALO 34 FEDERAL  
Well #: 4 ID Date: 07/03/01  
Operator: FASKEN OIL & RANCH LTD Effective Date:  
Case #: NMLC072015C FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT Abatement Date: 08/10/01  
Gravity: 3 Corrected Date: 08/09/01  
Authority Ref: APD STIPULATIONS OF APPROVAL Followup Date: 11/06/01  
Extend Date:

Remarks Date: 07/10/01

UNUSED CASING AND PALLETS ON LOCATION. REMOVE WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB14969  
Unique INC #: 01-GH-094 Well Name: PARKE MCINTYRE FED  
Well #: 10 ID Date: 06/05/01  
Operator: PREMIER OIL & GAS INCORPORATED Effective Date:  
Case #: NMNM0384577 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT Abatement Date: 06/08/01  
Gravity: 3 Corrected Date: 06/08/01  
Authority Ref: APD STIPULATIONS OF APPROVAL Followup Date: 06/13/01  
Extend Date:

Remarks Date: 06/06/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

DRILLING RESERVE PIT FENCING IS NOT COMPLETED ON ALL SIDES OF THE PITS. INSTALL FENCING WITHIN 48 HOURS OF NOTICE TO PROTECT LIVESTOCK AND WILDLIFE IN THE AREA. ALSO, TRASH, BARRELS FOUND IN THE PITS. REMOVE.

Office: CB ID: CB14964  
Unique INC #: 01-GH-09 Well Name: DIVERSE FEDERAL  
Well #: 4 ID Date: 06/01/01  
Operator: LIMARK CORPORATION Effective Date:  
Case #: NMNM11038 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT  
Gravity: 3  
Authority Ref: APD STIPULATIONS OF APPROVAL  
Remarks Date: 06/04/01

FRONT DRILLING/COMPLETION PIT LINER MATERIALS ARE BELOW THE LEVEL OF LIQUIDS CONTAINED IN THE PITS. REMOVE ALL LIQUIDS FROM THE PIT WITHIN 48 HOURS OF NOTICE. PITS ARE NOT TO BE USED UNTIL CAPABLE OF HOLDING LIQUIDS WITHOUT CONTAMINATION OF SURROUNDING SOIL.

Office: CB ID: CB14965  
Unique INC #: 01-GH-093 Well Name: DIVERSE FEDERAL  
Well #: 4 ID Date: 06/01/01  
Operator: LIMARK CORPORATION Effective Date:  
Case #: NMNM11038 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT  
Gravity: 3  
Authority Ref: 43 CFR 3162.5, APD STIPULATIONS OF APPROVAL  
Remarks Date: 06/04/01

UNUSED/ JUNK PIPE, FITTINGS, CASING, THREAD PROTECTORS, TRASH ON LOCATION. ALSO, TRASH HAS BEEN THROWN INTO THE PITS INSTEAD OF BEING PLACED IN CONTAINMENT TRAILER. REMOVE ALL UNUSED/JUNK EQUIPMENT AND TRASH FROM THE LOCATION WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB14966  
Unique INC #: 01-GH-092 Well Name: DIVERSE FEDERAL  
Well #: 4 ID Date: 06/01/01  
Operator: LIMARK CORPORATION Effective Date:  
Case #: NMNM11038 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: HUNT  
Gravity: 3  
Authority Ref: APD STIPULATIONS OF APPROVAL  
Remarks Date: 06/04/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

FRONT DRILLING/ COMPLETION PIT LINER MATERIAL IS BELOW THE LEVEL OF LIQUIDS CONTAINED IN THE PITS. REMOVE ALL LIQUIDS FROM THE PITS WITHIN 48 HOURS OF NOTICE. PITS ARE NOT TO BE USED UNTIL CAPABLE OF HOLDING THE LIQUIDS WITHOUT CONTAMINATION OF SURROUNDING SOILS.

Office: CB ID: CB15157  
Unique INC #: 01-GH-135 Well Name:  
Well #: ID Date: 07/27/01  
Operator: YATES PETROLEUM CORPORATION Effective Date:  
Case #: NMNM85354 FAC ID: SGC2 Abatement Date: 08/27/01  
Form: I FAC NAME: 2-SMITH GAS COM Corrected Date: 07/31/01  
Assessment: \$0 Inspector: HUNT Followup Date: 08/08/01  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.D.2e  
Remarks Date: 07/30/01  
WIND DIRECTION INDICATOR IS IN NEED OF REPAIR TO OPERATE CORRECTLY. REPAIR/ REPLACE THE WIND DIRECTION INDICATOR WITHIN TWENTY DAYS OF NOTICE.

Office: CB ID: CB14820  
Unique INC #: 01-JA-081 Well Name: ICA 31 FEDERAL  
Well #: 1 ID Date: 03/25/01  
Operator: NADEL & GUSSMAN Effective Date: 03/26/01  
Case #: NMNM0400512A FAC ID: Abatement Date: 03/26/01  
Form: I FAC NAME: Corrected Date: 03/30/01  
Assessment: \$0 Inspector: James Amos Followup Date: 03/30/01  
Gravity: 1 Extend Date:  
Authority Ref: Onshore Order 2.III.A.2.g  
Remarks Date: 03/26/01  
Failure to install a valve in the closing line as close as possible to the annular preventer to act as a locking device. Notified Gordon Baker on 3/26/01 at 1500 hours giving 24 hours to install.

Office: CB ID: CB14817  
Unique INC #: 01-JA-079 Well Name: ICA 31 FEDERAL  
Well #: 1 ID Date: 03/25/01  
Operator: NADEL & GUSSMAN Effective Date: 03/26/01  
Case #: NMNM0400512A FAC ID: Abatement Date: 03/26/01  
Form: I FAC NAME: Corrected Date: 03/30/01  
Assessment: \$0 Inspector: James Amos Followup Date: 03/30/01  
Gravity: 1 Extend Date:  
Authority Ref: Onshore Order 2.III.A.2.a.iii  
Remarks Date: 03/26/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Failure to install second kill line valve (check) as per onshore order. Notified Gordon Baker 3/26/01 at 1500 hours giving 24 hours to install valves.

Office: CB ID: CB14819  
Unique INC #: 01-JA-080 Well Name: ICA 31 FEDERAL  
Well #: 1 ID Date: 03/25/01  
Operator: NADEL & GUSSMAN Effective Date: 03/26/01  
Case #: NMNM0400512A Abatement Date: 03/26/01  
Form: I FAC ID: Corrected Date: 03/30/01  
Assessment: \$0 FAC NAME: Followup Date: 03/30/01  
Gravity: 1 Inspector: James Amos Extend Date:  
Authority Ref: Onshore Order 2.III.A.2.a.iii  
  
Remarks Date: 03/26/01  
Choke line not equipped with a second valve as per Onshore Order. Notified Gordon Baker on 3/26/01 at 1500 hours to itninstall wihtin 24 hours.

Office: CB ID: CB14783  
Unique INC #: 01-JA-062 Well Name: ROG FEDERAL  
Well #: 1 ID Date: 03/15/01  
Operator: REMUDA OPERATING CO Effective Date: 03/19/01  
Case #: NMNM0556290 FAC ID: A Abatement Date: 04/15/01  
Form: I FAC NAME: ROG FEDERAL #1 Corrected Date: 04/09/01  
Assessment: \$0 Inspector: James Amos Followup Date: 04/09/01  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 03/15/01  
Pumpjack is not equipped with counterweight guards. Install guards.

Office: CB ID: CB14790  
Unique INC #: 01-JA-067 Well Name: ROG FEDERAL  
Well #: 1 ID Date: 03/15/01  
Operator: REMUDA OPERATING CO Effective Date: 03/19/01  
Case #: NMNM0556290 FAC ID: A Abatement Date: 04/15/01  
Form: I FAC NAME: ROG FEDERAL #1 Corrected Date: 04/09/01  
Assessment: \$0 Inspector: James Amos Followup Date: 04/09/01  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 6.III  
  
Remarks Date: 03/15/01

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

H2S warning signs and wind socks are no longer present on location. Install warning sign and wind sock.

Office: CC	Well Name: FEDERAL ALBATROSS	ID: CC726
Unique INC #: RG01EG015A	Well #: 33-12	ID Date: 08/07/01
Operator: DIVERSIFIED OPERATING CORP	FAC ID: PLOVER, WILD-H	Effective Date: 08/07/01
Case #: COC28088	FAC NAME: FED N WILDHORSE 7-28, PLOVER,OS	Abatement Date: 08/24/01
Form: I	Inspector: EGILLINGHAM	Corrected Date: 08/15/01
Assessment: \$0		Followup Date: 08/27/01
Gravity: 3		Extend Date:
Authority Ref: 43CFR3162.5-1(a)		

Remarks Date: 08/08/01

07/07/01; Terry Cammon was notified via phone of failure of dirt contractor to follow plan as specified in Conditions of Approval in APD, Forest Service conditions # 2 & # 3. Corrective action is call and schedule onsite prior to any additional operations at location with Forest Service personnel. Forest service personnel will determine and specify any changes from current constructed location, and operator will follow those specifications. Operator will notify BLM of completion meeting and concurrence of Forest Service on continued operations prior to moving in drill rig. Forest Service primary contact is Steve Curry (970 346 5003). Primary BLM contact is Ernie Lee Gillingham (719 269 8531). (elg)

Office: CC	Well Name: ALLEN	ID: CC713
Unique INC #: RG01EG012A	Well #: 43-7	ID Date: 05/23/01
Operator: SAMEDAN OIL CORPORATION	FAC ID:	Effective Date: 05/23/01
Case #: COC43584	FAC NAME:	Abatement Date: 07/01/01
Form: I	Inspector: EGILLINGHAM	Corrected Date: 07/01/01
Assessment: \$500		Followup Date: 04/26/06
Gravity: 1		Extend Date:
Authority Ref: 43CFR3162.3-1(C) Drilling Applications		

Remarks Date: 06/14/01

Operator notified BLM office of non intentional surface work completed on federal well site on 05/23/01. Operator voluntarily ceased all work upon discovery of situation. Operator has notified BLM of intention to drill upon lease in location of existing disturbance. Corrective action is to furnish all necessary information in conformance with 43CFR3160 regulations related to Application for Permit to Drill (APD). All application information must be completed and submitted by 07/01/01. Operator must follow all "Conditions of Approval" set in APD approval. Should operator fail to obtain an approved APD, or decide not to drill well, operator must furnish this BLM office a Sundry Notice (SN) with specific details for plan to complete reclamation of location. Upon review of such SN, operator will be given instruction for final reclamation procedures by BLM. (elg) A bill for the \$500 assessment will follow after this INC notification. Please wait and pay assessment with billing. If operator has any questions related to this INC, please contact Ernie Gillingham at telephone number 719 269 8531.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: CR ID: CR1167  
Unique INC #: 01-001 Well Name: FEDERAL 26-12-89 ID Date: 10/10/00  
Well #: 1 Effective Date: 10/17/00  
Operator: PHILLIPS PETROLEUM COMPANY Abatement Date: 10/17/00  
Case #: COC61760 FAC ID: Corrected Date: 10/25/00  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: Jim Wood Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1(a)

Remarks Date: 10/11/00

The access road onto this well pad was not constructed as approved in the APD. The road does not need to be rebuilt, but the BLM wants to remind you that all activities shall be conducted as approved, in the APD, unless a variance is requested through a sundry notice. If you have questions or concerns please call Jim Wood at 970-826-5093.

Office: DK ID: DK5798  
Unique INC #: WM0124 Well Name: RUSCH ID Date: 08/09/01  
Well #: 1, 2R Effective Date: 08/17/01  
Operator: WARD WILLISTON COMPANY Abatement Date: 09/17/01  
Case #: CANW103 FAC ID: A Corrected Date: 08/22/01  
Form: I FAC NAME: RUSCH 1 & 2R Followup Date: 08/22/01  
Assessment: \$0 Inspector: BILL MCMANUS Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, 00#6 III.D3.e

Remarks Date: 08/10/01

Wind direction indicator (wind sock) is missing. Install a wind direction indicator on Rusch tank battery.

Office: DK ID: DK5808  
Unique INC #: IDH01013 Well Name: T.R.FEDERAL ID Date: 09/06/01  
Well #: 1-10 Effective Date: 09/14/01  
Operator: CHOCTAW II OIL & GAS LTD Abatement Date: 10/17/01  
Case #: NDM19152 FAC ID: B Corrected Date: 09/24/01  
Form: I FAC NAME: T.R. FEDERAL 1-10 Followup Date:  
Assessment: \$0 Inspector: DENNIS HANNUM Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, A, 2

Remarks Date: 09/10/01

No Radius of Exposure calculations. Must submit to this office, by Sundry Notice, Radius of Exposure calculations. Called and talked to Mr. Tim Lechner about this matter 9/7/2001. The green copy is the operators copy.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: DK ID: DK5823  
Unique INC #: IDH01018 Well Name: FEDERAL  
Well #: 33-20 ID Date: 09/19/01  
Operator: FH PETROLEUM CORPORATION Effective Date: 09/20/01  
Case #: NDM30568 FAC ID: Abatement Date: 09/21/01  
Form: I FAC NAME: Corrected Date: 09/22/01  
Assessment: \$0 Inspector: DENNIS HANNUM Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1 O.S.O. # 2, IV, I  
Remarks Date: 09/20/01

3M Choke Manifold Equipment does not have three separate lines to the pit and/or separator. Must configure 3M Choke Manifold Equipment so as to conform to Onshore Oil and Gas Order No. 2, and have three separate lines to the pit and/or to the separator. Talked to Mr. Leon Lippert about this matter 9/20/01 The green copy is the operators copy.

Office: DK ID: DK5822  
Unique INC #: IDH01017 Well Name: FEDERAL  
Well #: 33-20 ID Date: 09/19/01  
Operator: FH PETROLEUM CORPORATION Effective Date: 09/20/01  
Case #: NDM30568 FAC ID: Abatement Date: 09/21/01  
Form: I FAC NAME: Corrected Date: 09/21/01  
Assessment: \$0 Inspector: DENNIS HANNUM Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1 O.S.O. # 2, III, D, 2  
Remarks Date: 09/20/01

No Separation equipment for Drill Stem Test. Must install Separator for Drill Stem Test. Talked to Mr. Leon Lippert about this matter 9/19/01. The green copy is the operators copy.

Office: DK ID: DK5821  
Unique INC #: IDH01016 Well Name: FEDERAL  
Well #: 33-20 ID Date: 09/18/01  
Operator: FH PETROLEUM CORPORATION Effective Date: 09/18/01  
Case #: NDM30568 FAC ID: Abatement Date: 09/20/01  
Form: I FAC NAME: Corrected Date: 09/21/01  
Assessment: \$0 Inspector: DENNIS HANNUM Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1 O. S. O. # 2, III, C, 7  
Remarks Date: 09/19/01

No Flare Ignitor system. Must install flare ignitor. Talked to Mr. Leon Lippert about this matter 9/18/2001. The green copy is the operators copy.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: DK ID: DK5818  
Unique INC #: IDH01014 Well Name: STEARNS  
Well #: 14-15H  
Operator: CITATION OIL & GAS CORPORATION  
Case #: NDM85863 FAC ID: A  
Form: I FAC NAME: STEARNS 14-15H  
Assessment: \$0 Inspector: DENNIS HANNUM  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, D, 1, c  
Remarks Date: 09/17/01

Flare ignitor not in operable condition. Must repair or replace flare ignitor system and put in good working order. Talked to Mr. Dale Schaff about this matter 9/13/01. the green copy is the operators copy.

Office: DK ID: DK5705  
Unique INC #: IKDW00031 Well Name: WRRMU  
Well #: 14-27H  
Operator: BURLINGTON RESOURCES OIL & GAS  
Case #: NDM84451X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. D. 3. a.  
Remarks Date: 09/19/00

NO H2S DANGER SIGN AT THE WRRMU 14-27H WELLHEAD LOCATION. POST H2S DANGER SIGN AT THE 14-27H WELLHEAD LOCATION.

Office: DK ID: DK5704  
Unique INC #: IKDW00030 Well Name: BN  
Well #: 7-21  
Operator: BURLINGTON RESOURCES OIL & GAS  
Case #: NDM84451X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. D. 3. e.  
Remarks Date: 09/19/00

WIND DIRECTION INDICATOR AT THE BN 7-21 LOCATION NOT IN WORKING ORDER. INSTALL OR REPAIR WIND DIRECTION INDICATOR AT THE BN 7-21 LOCATION.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: FE ID: iFE10547  
Unique INC #: 01GLB027 Well Name:  
Well #: ID Date: 08/17/01  
Operator: ROBERT L BAYLESS PRODUCER LLC Effective Date: 08/24/01  
Case #: 14206035035 FAC ID: A Abatement Date: 09/03/01  
Form: I FAC NAME: TOCITO DOME CENTRAL Corrected Date: 09/04/01  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 08/17/01

You must install and maintain at least one permanent wind indicator so that wind direction can be easily determined at or approaching the storage tank(s). Currently the wind indicator is torn.

Office: FE ID: iFE10302  
Unique INC #: 01GLB17 Well Name:  
Well #: ID Date: 04/18/01  
Operator: U S OIL GAS INCORPORATED Effective Date: 04/26/01  
Case #: UTU68932A FAC ID: E Abatement Date: 05/26/01  
Form: I FAC NAME: WMU "B" TB Corrected Date: 05/17/01  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 04/19/01

You must install and maintain at least one permanent wind indicator so that wind direction can be easily determined at or approaching the storage tank(s).

Office: FE ID: FE10445  
Unique INC #: 01HDL0013 Well Name: MCILROY  
Well #: 1R ID Date: 07/10/01  
Operator: GILBREATH NORMAN L Effective Date: 07/11/01  
Case #: NMSF080390A FAC ID: Abatement Date: 07/11/01  
Form: I FAC NAME: Corrected Date: 07/12/01  
Assessment: \$0 Inspector: LUJAN Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order #2 III.A.2.g.  
  
Remarks Date: 07/11/01

A manual locking device (i.e., hand wheels) or automatic locking devices shall be installed on all systems of 2M or greater.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: FE ID: FE10446  
Unique INC #: 01HDL0014 Well Name: MCILROY ID Date: 07/10/01  
Well #: 1R Effective Date: 07/11/01  
Operator: GILBREATH NORMAN L Abatement Date: 07/11/01  
Case #: NMSF080390A FAC ID: Corrected Date: 07/12/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: LUJAN Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III.A.2.b.i.

Remarks Date: 07/11/01

All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, and shall be anchored to prevent whip and reduce vibration. Manifold line needs to be rerouted.

Office: FE ID: FE10444  
Unique INC #: 01HDL0012 Well Name: MCILROY ID Date: 07/10/01  
Well #: 1R Effective Date: 07/11/01  
Operator: GILBREATH NORMAN L Abatement Date: 07/11/01  
Case #: NMSF080390A FAC ID: Corrected Date: 07/12/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: LUJAN Extend Date:  
Gravity: 1  
Authority Ref: Onshore Order #2 III.A.2.a.

Remarks Date: 07/11/01

A well control device shall be installed at the surface that is capable of the complete closure of the wellbore. Please install a drill string safety valve and/or inside BOP valve and maintain in a open position on the rig floor.

Office: GR ID: GR995  
Unique INC #: 013039 Well Name: FESTUS ID Date: 08/15/01  
Well #: 1 Effective Date: 08/15/01  
Operator: YATES PETROLEUM CORPORATION Abatement Date: 08/15/01  
Case #: WYW152920X FAC ID: Corrected Date: 08/15/01  
Form: I FAC NAME: Followup Date: 08/15/01  
Assessment: \$0 Inspector: DEVAULT Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3164,1(b),O.O.2.III.A.2.e

Remarks Date: 08/20/01

Air valve to air pumps shut off.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: HO ID: HO6811  
Unique INC #: ASC-027-01 Well Name: TOLES FED ID Date: 04/09/01  
Well #: 01 Effective Date: 04/16/01  
Operator: CHI OPERATING INCORPORATED Abatement Date: 05/02/01  
Case #: NMNM067693A FAC ID: A Corrected Date: 04/27/01  
Form: I FAC NAME: TOLES FEDERAL BATTERY Followup Date: 04/27/01  
Assessment: \$0 Inspector: Andy Cortez Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1(a)

Remarks Date: 04/12/01

Failure to comply with written order on H2s warnings. - Install a wind sock on the battery and appropriate poison gas warning signs. Failure to comply may result in monetary assessments.

Office: HO ID: HO6813  
Unique INC #: ASC-029-01 Well Name: TOLES FED ID Date: 04/09/01  
Well #: 01 Effective Date: 04/16/01  
Operator: CHI OPERATING INCORPORATED Abatement Date: 05/02/01  
Case #: NMNM067693A FAC ID: A Corrected Date: 04/27/01  
Form: I FAC NAME: TOLES FEDERAL BATTERY Followup Date: 04/27/01  
Assessment: \$0 Inspector: Andy Cortez Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1(a)

Remarks Date: 04/12/01

Failure to comply with written order to remove the weed infestation. It creates a fire hazard and a hiding place for snakes.- Remove the weed infestation from the well & battery areas. Failure to comply may result in monetary assessments.

Office: HO ID: HO6812  
Unique INC #: ASC-028-01 Well Name: TOLES FED ID Date: 04/09/01  
Well #: 01 Effective Date: 04/16/01  
Operator: CHI OPERATING INCORPORATED Abatement Date: 05/02/01  
Case #: NMNM067693A FAC ID: A Corrected Date: 04/27/01  
Form: I FAC NAME: TOLES FEDERAL BATTERY Followup Date: 04/27/01  
Assessment: \$0 Inspector: Andy Cortez Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1(a)

Remarks Date: 04/12/01

Failure to comply with written order to replace fence gate. - The gate on it is incomplete, broken, and will not close. Replace gate. Failure to comply may result in monetary assessments.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: HO ID: HO6460  
Unique INC #: PAH-077-00 Well Name: HANAGAN D FED ID Date: 08/31/00  
Well #: 02 Effective Date:  
Operator: MARKS & GARNER PRODUCTION CU Abatement Date: 09/30/00  
Case #: NMNM01917 FAC ID: Corrected Date: 10/10/00  
Form: I FAC NAME: Followup Date: 10/10/00  
Assessment: \$0 Inspector: Patricia Hutchings Extend Date: 10/15/00  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 08/31/00

PUMPING UNIT HAS EXPOSED BELTS SHEAVES, AND COUNTERWEIGHTS. SAFEGUARD THE PUMPING UNIT BY INSTALLING ENCLOSURES AND BELT GUARDS TO PROVIDE ADEQUATE PROTECTION FOR THE HEALTH AND SAFETY OF LIFE.

Office: ME ID: ME1799  
Unique INC #: 01BK50MEFO Well Name: WHITE RIVER DOME ID Date: 08/28/01  
Well #: 20-11 Effective Date: 08/28/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 09/14/01  
Case #: COC0127535 FAC ID: Corrected Date: 09/14/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 09/19/01

Failure to comply with Onshore Order #2-b-i. All choke lines shall be straight lines unless turns use tee blocks or are targeted with running tees, Witnessed the BOPE test. The hose had been removed and a targeted tee had been installed. The test was good. No further action required., and shall be anchored to prevent whip and reduce vibration.

Office: ME ID: ME1800  
Unique INC #: 01BK51MEFO Well Name: WHITE RIVER DOME ID Date: 08/28/01  
Well #: 20-11 Effective Date: 08/28/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 09/14/01  
Case #: COC0127535 FAC ID: Corrected Date: 09/14/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 09/13/01

Failure to comply with Onshore Order #2-d-g. A manual locking device (hand wheels) or automatic locking devices shall be installed on all 2M or greater systems., Witnessed the BOPE test. New hand wheels were made up and installed. No further action required.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: ME ID: ME1801  
Unique INC #: 01BK52MEFO Well Name: WHITE RIVER DOME ID Date: 08/28/01  
Well #: 20-11 Effective Date: 08/28/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 09/14/01  
Case #: COC0127535 FAC ID: Corrected Date: 09/14/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 09/19/01

Failure to comply with Onshore Order 2-d-g. A valve shall be installed in the closing line as close as possible to the annular preventer to act as a locking device., Witnessed the BOPE test. The closing side of the annular preventer had a valve installed. No further action required.

Office: ME ID: ME1802  
Unique INC #: 01BK53MEFO Well Name: WHITE RIVER DOME ID Date: 08/28/01  
Well #: 20-11 Effective Date: 08/28/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 09/14/01  
Case #: COC0127535 FAC ID: Corrected Date: 09/14/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 09/13/01

Failure to comply with the Onshore Order #2-b-i. The choke line valves must be functional and should open and close without using a hammer or cheater pipe., Witnessed a BOPE test. All the choke line valves were functional and passed the pressure test. No further action required.

Office: ME ID: ME1746  
Unique INC #: 01BK37MEFO Well Name: ANT HILL UNIT ID Date: 05/09/01  
Well #: 25-42 Effective Date: 05/09/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 05/10/01  
Case #: COC9226 FAC ID: Corrected Date: 05/09/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 05/15/01

Failure to comply with Onshore Order #2 Part III. The kill line was not hooked up to the kill line valve.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: ME ID: ME1745  
Unique INC #: 01BK36MEFO Well Name: ANT HILL UNIT ID Date: 05/09/01  
Well #: 25-42 Effective Date: 05/09/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 05/10/01  
Case #: COC9226 FAC ID: Corrected Date: 05/09/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 05/15/01

Failure to comply with Onshore Order #2-Part III. The fill line was not hooked up above the upper most preventer.

Office: ME ID: ME1747  
Unique INC #: 01BK38MEFO Well Name: ANT HILL UNIT ID Date: 05/09/01  
Well #: 25-42 Effective Date: 05/09/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 05/10/01  
Case #: COC9226 FAC ID: Corrected Date: 05/09/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 05/15/01

Failure to comply with Onshore Order # 2-Part III-A. The lines leading from the choke manifold were not hooked up and lashed down.

Office: ME ID: ME1744  
Unique INC #: 01BK35MEFO Well Name: ANT HILL UNIT ID Date: 05/09/01  
Well #: 25-42 Effective Date: 05/09/01  
Operator: TOM BROWN INCORPORATED Abatement Date: 05/10/01  
Case #: COC9226 FAC ID: Corrected Date: 05/09/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: KRAFT Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 05/15/01

Failure to comply with Onshore Order #2, part III-A. The hand-wheels were not installed on the BOP.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: ME ID: ME1688  
Unique INC #: 01BK03MEFO Well Name: WRD FEDERAL ID Date: 10/03/00  
Well #: 6-26 Effective Date: 10/03/00  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 10/04/00  
Case #: COC0127537 FAC ID: Corrected Date: 10/04/00  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: billy kraft Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 10/31/00

Conducted followup on 10/04/00, Failure to comply with Onshore Order #2. The kill line was not hooked up to the well head. Within 24 hours install the kill line in the required area., violation wasa corrected as required.

Office: ME ID: ME1687  
Unique INC #: 01BK02MEFO Well Name: WRD FEDERAL ID Date: 10/03/00  
Well #: 6-26 Effective Date: 10/03/00  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 10/04/00  
Case #: COC0127537 FAC ID: Corrected Date: 10/04/00  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: billy kraft Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 10/31/00

Failure to comply with Onshore Order #2. The annular preventer was not equipped with a valve on the closing side. Install the valve within 24 hours of the verbal Inc., Followed up on the Inc on 10/04/2000. Violation was corrected as required.

Office: ME ID: ME1686  
Unique INC #: 01BK01MEFO Well Name: WRD FEDERAL ID Date: 10/03/00  
Well #: 6-26 Effective Date: 10/03/00  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 10/04/00  
Case #: COC0127537 FAC ID: Corrected Date: 10/04/00  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: billy kraft Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 10/31/00

Failure to comply with Onshore Order #2. the choke lines were not hooked up to the manifold. Hook up the choke lines to run to the required facilities. This is a verbal Inc. to be corrected in 24 hours., Violation was corrected as required.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: ME ID: ME1689  
Unique INC #: 01BK04MEFO Well Name: WRD FEDERAL ID Date: 10/03/00  
Well #: 6-26 Effective Date: 10/03/00  
Operator: CHESAPEAKE OPERATING INC Abatement Date: 10/04/00  
Case #: COC0127537 FAC ID: Corrected Date: 10/04/00  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: billy kraft Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.1-(a)

Remarks Date: 10/31/00

Failure to comply with Onshore Order #2. The floor valve and inside BOP valve were not available on the rig floor. Within 24 hours have the valves on the floor ready for use.

Office: MI ID: MI1170  
Unique INC #: JTW011V Well Name: MNF ID Date: 09/20/01  
Well #: 18 Effective Date: 09/20/01  
Operator: CABOT OIL & GAS CORP Abatement Date: 09/20/01  
Case #: WVBLMA017120 FAC ID: Corrected Date: 09/20/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: WOOD Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1

Remarks Date: 10/04/01

Instructed operator to hobble air discharge lines from compressor.

Office: ML ID: ML2906  
Unique INC #: LTR-INC-01 Well Name: BERRY ID Date: 09/13/00  
Well #: 11-4 Effective Date: 09/22/00  
Operator: HEADINGTON OIL, LP Abatement Date: 10/22/00  
Case #: MTM89335 FAC ID: Corrected Date: 11/03/00  
Form: I FAC NAME: Followup Date: 11/03/00  
Assessment: \$500 Inspector: CHUCK LAAKSO Extend Date: 11/20/00  
Gravity: 1  
Authority Ref: 43 CFR 3162.3-1(c)

Remarks Date: 09/15/00

Drilling without approval; issued assessment of \$500 per day for each day the violation exists; maximum assessment of \$5000. No shut-in issued because it was determined to be inadvertent. Bill for Collection number A324052 was sent with letter INC. SDR No. 922-01-01 reduced assessment from \$5000 to a total of \$500 on 10/18/00. A new bill for collection will be issued.

Safety and Drilling Related Violations (INC)s Issued During FY 2001  
As of March 3, 2011

Office: MR			ID: iMR1140
Unique INC #: SJ-01-33V	Well Name: UMT		
	Well #: 2	ID Date:	05/17/01
Operator: RIM OFFSHORE INC		Effective Date:	05/21/01
Case #: 14206042399	FAC ID: 2	Abatement Date:	06/15/01
Form: I	FAC NAME: UMT	Corrected Date:	08/17/01
Assessment: \$0	Inspector: GRAY-LOPE	Followup Date:	
Gravity: 3		Extend Date:	08/17/01
Authority Ref: 43 CFR 3162.5-3			

Remarks Date: 05/21/01

The lessee/operator shall perform operations and maintain equipment in a safe and workman-like manner. Please correct the following: Stairwell by the oil & water tanks need to be put back up, there is chemical stains under the hose that is connected to the engine, the 3" exhaust pipe (from the pumpjack's engine) needs to be raised or open to atmosphere, as is, it's making black stain on the ground, Tank #6933 sales vlv close to the tank has chemical stains under the vlv, catch barrel might help. Tank #6933 BS & W valve has chemical stains under the valve on ground. Earthen pit NE of separator needs to be cleaned out. Separator 4" exhaust pipe needs a bird screen.

Office: MR			ID: iMR1062
Unique INC #: SJ-01-07	Well Name: BOBCAT, ROADRUNNER		
	Well #: 13-13, 14-14, 23-31	ID Date:	02/20/01
Operator: RIM OFFSHORE INC		Effective Date:	03/05/01
Case #: MOOC14203874	FAC ID:	Abatement Date:	03/23/01
Form: I	FAC NAME:	Corrected Date:	08/17/01
Assessment: \$0	Inspector: GRAY-LOPE	Followup Date:	
Gravity: 3		Extend Date:	08/17/01
Authority Ref: 43 CFR 3162.5-3			

Remarks Date: 02/26/01

The lessee/operator shall perform operations and maintain equipment in a safe and workman-like manner. Well #13-13 has oil stains around hearter treater, oil stains on ground and under the sales line Tank #GI-1969 and water tank and catch barrel on sales line from oil tank is 3/4 full and oil stains around barrel needs to be cleaned up and 1/2" rubber hose that connected to engine for pumpjack is leaking. Has a puddle of chemical under the stand. It has a wire around the hose instead of clamp and so that is where the leak is from. Well #23-31 has chemical stain on the ground on the northeast side of the wellhead and Well #14-14 has some old fly-wheel belts and trash on the location.

Office: MR			ID: iMR1060
Unique INC #: SJ-01-05	Well Name: ROADRUNNER		
	Well #: 23-31	ID Date:	02/20/01
Operator: RIM OFFSHORE INC		Effective Date:	03/05/01
Case #: MOOC14203874	FAC ID:	Abatement Date:	03/25/01
Form: I	FAC NAME:	Corrected Date:	08/17/01
Assessment: \$0	Inspector: GRAY-LOPE	Followup Date:	
Gravity: 3		Extend Date:	08/17/01
Authority Ref: 43 CFR 3162.5-3			

Remarks Date: 02/26/01

The lessee/operator shall perform operations and maintain equipment in a safe and workman-like manner. Please install a tank for disposal pit with net or screen as a cover for the pit. At the present time there is an earthen pit.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: PD ID: PD1032  
Unique INC #: 2001CD2 Well Name: SAND DRAW FEDERAL  
Well #: 9-11 ID Date: 08/01/01  
Operator: AMOCO PRODUCTION COMPANY Effective Date: 08/01/01  
Case #: WYW130317 FAC ID: Abatement Date: 08/01/01  
Form: I FAC NAME: Corrected Date: 08/01/01  
Assessment: \$0 Inspector: DEVAULT Followup Date: 08/01/01  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1(b), O.O.2.III.A.2.e.  
  
Remarks Date: 08/09/01  
The air was turned off to the air pumps on the accumulator. I reamed the tool pusher & Co man. The pusher explained the air had been on but must have inadvertently been shut off while doing maintenance earlier in the day.

Office: PD ID: PD998  
Unique INC #: MO010 Well Name: JONAH FEDERAL  
Well #: 6-5 ID Date: 10/14/00  
Operator: MCMURRY OIL COMPANY Effective Date: 10/14/00  
Case #: WYW125943 FAC ID: Abatement Date: 12/15/00  
Form: I FAC NAME: Corrected Date: 12/14/00  
Assessment: \$0 Inspector: OMARA Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1  
  
Remarks Date: 12/22/00  
Order #2 III A.2.g - A manual device (ie., hand wheels) shall be installed on all systems 2M or greater. Upon inspection, manual locking devices were not installed. In addition, the BOP stack was covered with ice.

Office: RW ID: RW2479  
Unique INC #: CR01-15-I Well Name: HIGH POINT  
Well #: 8-1 ID Date: 03/05/01  
Operator: COLEMAN OIL & GAS INCORPORATED Effective Date: 03/16/01  
Case #: WYW36319 FAC ID: Abatement Date: 04/16/01  
Form: I FAC NAME: Corrected Date: 04/02/01  
Assessment: \$0 Inspector: ROSS Followup Date: 04/02/01  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.6 (a), (b) and (c)  
  
Remarks Date: 03/07/01  
Well site is not identified: no sign.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: RW ID: RW2481  
Unique INC #: CR01-17-I Well Name: FALCONE FEDERAL  
Well #: 20-22  
Operator: CABOT OIL & GAS CORPORATION  
Case #: WYW40475 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: ROSS  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)

Remarks Date: 03/08/01

Well site is not identified: No sign.

Office: RW ID: RW2469  
Unique INC #: RFO-101901 Well Name: SUN DOG UNIT (DRY COW CREEK)  
Well #: 10-8  
Operator: PETROLEUM DEVELOPMENT CORP  
Case #: WYW116679 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: SOULE  
Gravity: 1  
Authority Ref: Onshore Order #2 A.2. a. vii

Remarks Date: 02/28/01

A hole was cut in casing for the cement to flow out of during the production casing job. BOPs can not function as needed with a window cut in the casing.  
DO NOT cut holes in the casing, secure the well per Onshore Order #2.

Office: TU ID: iTU20229  
Unique INC #: LK0013 Well Name:  
Well #:  
Operator: NBI SERVICES INC  
Case #: 142002071424 FAC ID: A  
Form: I FAC NAME: WHITE  
Assessment: \$0 Inspector: KEYES  
Gravity: 3  
Authority Ref: 43CFR3162.5-3

Remarks Date: 03/14/01

Your tank battery has unused equipment and piping cluttering this area, Please remove all unused materials from the lease.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: TU ID: iTU20238  
Unique INC #: LK0022 Well Name: COLE ID Date: 03/29/01  
Well #: 1 Effective Date: 04/05/01  
Operator: CASE SALES COMPANY INC Abatement Date: 05/05/01  
Case #: I51IND55025 FAC ID: Corrected Date: 05/01/01  
Form: I FAC NAME: Followup Date: 05/01/01  
Assessment: \$0 Inspector: KEYES Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.5-3  
  
Remarks Date: 03/29/01  
Please place a belt guard on your pump jack.

Office: TU ID: iTU20236  
Unique INC #: LK0020 Well Name: ID Date: 03/29/01  
Well #: Effective Date: 04/05/01  
Operator: DELONG OIL & GAS COMPANY Abatement Date: 05/05/01  
Case #: OKNM78539X FAC ID: A Corrected Date: 04/10/01  
Form: I FAC NAME: ETU Followup Date: 05/02/01  
Assessment: \$0 Inspector: KEYES Extend Date:  
Gravity: 3  
Authority Ref: 43CFR3162.5-3  
  
Remarks Date: 03/29/01  
Keep your cat walk free of hoses and clutter.

Office: TU ID: iTU20279  
Unique INC #: 00036-FDS Well Name: BLACKWOLF ID Date: 07/23/01  
Well #: 1 Effective Date: 07/25/01  
Operator: WARREN AMERICAN OIL COMPANY Abatement Date: 08/25/01  
Case #: OKNM78723 FAC ID: A Corrected Date: 08/01/01  
Form: I FAC NAME: BLACKWOLF Followup Date:  
Assessment: \$0 Inspector: SHOUN Extend Date:  
Gravity: 1  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 09/05/01

The weeds were cut so as to not present a danger to workman or to the product stored on lease., Weeds and grass are so high they present a danger to the workman and to the product stored on the lease.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE8794  
Unique INC #: AW01025 Well Name: HSB FEDERAL  
Well #: 26-3 ID Date: 05/10/01  
Operator: COASTAL OIL & GAS CORPORATION Effective Date: 05/10/01  
Case #: UTU38401 FAC ID: Abatement Date: 05/11/01  
Form: I FAC NAME: Corrected Date: 05/11/01  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: 43CFR3162.1(c) onshore order 2 part IIIA.e.  
Remarks Date: 05/21/01  
Violation: Power for the closing unit not sufficient to operate closing unit. Corrective Action: Increase power supply to closing unit and notify ( Alan Walker at 828-4501) Power supply must be sufficient to start & stop automatically.

Office: VE ID: iVE8676  
Unique INC #: AW01011 Well Name: HCU  
Well #: 3-28F ID Date: 03/14/01  
Operator: DOMINION EXPL & PRODUCTION INC Effective Date: 03/14/01  
Case #: UTU76784A FAC ID: Abatement Date: 03/30/01  
Form: I FAC NAME: Corrected Date: 03/20/01  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43cfr 3162.1 onshore order#2partIII.A.i. ix&xi  
Remarks Date: 03/19/01  
A BOP PIT LEVEL DRILL SHALL BE CONDUCTED WEEKLY FOR EACH DRILLING CERW, AND SHALL BE RECORDED IN THE DRILLING LOG.

Office: VE ID: VE8692  
Unique INC #: AW01012 Well Name: KENNEDY WASH FEDERAL  
Well #: 14-1 ID Date: 02/27/01  
Operator: COASTAL OIL & GAS CORPORATION Effective Date: 02/27/01  
Case #: UTU78855X FAC ID: Abatement Date: 03/01/01  
Form: I FAC NAME: Corrected Date: 03/01/01  
Assessment: \$0 Inspector: ALAN WALKER Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.1(a), OO#2, III A.(g)  
Remarks Date: 03/29/01  
Hand wheels missing. Put hand wheels on double gate preventor.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE9039  
Unique INC #: JS01069 Well Name: WV  
Well #: 9W-23-8-21 ID Date: 06/21/01  
Operator: SHENANDOAH ENERGY INC Effective Date: 06/21/01  
Case #: UTU025963 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMIE SPARGER Abatement Date: 06/21/01  
Gravity: 3 Corrected Date: 06/21/01  
Authority Ref: 43cfr3164.1(a)(b),OO#2,III,A,2,g Followup Date:  
Remarks Date: 08/16/01 Extend Date:  
  
One hand wheel is not on BOP stack rams as required. All four hand wheels shall be kept on rams as required.

Office: VE ID: VE9041  
Unique INC #: JS01071 Well Name: NDC  
Well #: 167-28 ID Date: 06/21/01  
Operator: EOG RESOURCES INC Effective Date: 06/21/01  
Case #: UTU0803 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMIE SPARGER Abatement Date: 06/21/01  
Gravity: 3 Corrected Date: 06/21/01  
Followup Date:  
Authority Ref: 43cfr3164.1(a)(b),OO#2,III,A,2,g Extend Date:  
  
Remarks Date: 08/16/01  
  
Three of the four hand wheels that are required are not on the BOP rams. Please install all required hand wheels and keep them on.

Office: VE ID: VE9043  
Unique INC #: JS01068 Well Name: NDC  
Well #: 167-28 ID Date: 06/21/01  
Operator: EOG RESOURCES INC Effective Date: 06/21/01  
Case #: UTU0803 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: JAMIE SPARGER Abatement Date: 06/21/01  
Gravity: 3 Corrected Date: 06/21/01  
Followup Date:  
Authority Ref: 43cfr3164.1(a)(b),OO#2,III,A,2,e Extend Date:  
  
Remarks Date: 08/16/01  
  
The accumulator air pumps air supply is turned off. The air pump is one of the mandatory, independent power sources and the air supply must be kept on.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE9042  
Unique INC #: JS01067 Well Name: NDC ID Date: 06/21/01  
Well #: 167-28 Effective Date: 06/21/01  
Operator: EOG RESOURCES INC Abatement Date: 06/21/01  
Case #: UTU0803 FAC ID: Corrected Date: 06/21/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43cfr3164.1(a)(b),OO#2,III,A,2,e

Remarks Date: 08/16/01

Kill line is disconnected. Please connect kill line and maintain it in an operational mode.

Office: VE ID: iVE8663  
Unique INC #: JS01014 Well Name: ARCHEE ID Date: 02/26/01  
Well #: 1-117 Effective Date: 02/26/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 02/27/01  
Case #: UTU60747 FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Onshore Order #2 III. A. 2. i. xi.

Remarks Date: 02/27/01

The BOPE pit level drills are not being recorded in the driller's log. Drills are to be conducted once a week for each drilling crew and recorded in the driller's log.

Office: VE ID: iVE8662  
Unique INC #: JS01013 Well Name: ARCHEE ID Date: 02/26/01  
Well #: 1-117 Effective Date: 02/26/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 02/27/01  
Case #: UTU60747 FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Onshore Order #2 III. A. 2. g.

Remarks Date: 02/27/01

One of the four required hand wheels for the BOP rams is not installed. All required hand wheels must be in working order, installed, and kept in place.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: iVE8664  
Unique INC #: JS01015 Well Name: ARCHEE ID Date: 02/26/01  
Well #: 1-117 Effective Date: 02/26/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 02/27/01  
Case #: UTU60747 FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Onshore Order #2 III. A. 2. i. viii.  
Remarks Date: 02/27/01

Blind rams activations, during trips, are not being recorded in driller's log. Blind rams are to be activated each trip (but not more than once per day). Said activations are to be recorded in the driller's log.

Office: VE ID: VE8821  
Unique INC #: JS01066 Well Name: WV ID Date: 05/28/01  
Well #: 1W-23-8-21 Effective Date: 05/28/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 05/29/01  
Case #: UTU63043C FAC ID: Corrected Date: 05/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3164.1(a)(b)  
Remarks Date: 06/20/01

The air supply to the air pump back up power source for the accuulator is turned off. The air supplu shall be opened for the pumps all the time. Onshore order No. 2. III. A. c.ii 3M.

Office: VE ID: VE8820  
Unique INC #: JS01065 Well Name: WV ID Date: 05/28/01  
Well #: 1W-23-8-21 Effective Date: 05/28/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 05/29/01  
Case #: UTU63043C FAC ID: Corrected Date: 05/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3164.1(a)(b)  
Remarks Date: 06/20/01

No hand whells on BOP. Hand whells shall be installed and kept installed as required. Onshore order N0. 2. III. A. g.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE9040  
Unique INC #: JS01070 Well Name: WV ID Date: 06/21/01  
Well #: 2W-18-8-22 Effective Date: 06/21/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 06/21/01  
Case #: UTU63043C FAC ID: Corrected Date: 06/21/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43cfr3164.1(a)(b),OO#2.III,A

Remarks Date: 08/16/01

Kill line is disconnected. Crew is tripping out the hole. Kill line shall be hooked up and operational at all times.

Office: VE ID: VE8805  
Unique INC #: JS01065A Well Name: WV ID Date: 05/29/01  
Well #: 1W-23-8-21 Effective Date: 05/29/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 06/29/01  
Case #: UTU63043C FAC ID: Corrected Date: 06/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$250 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1(A)2, OO#2, III.A.G.

Remarks Date: 05/31/01

HANDWHEELS THAT WILL FUNCTION AS HANDWHEELS ARE NOT INSTALLED AS REQUIRED. FUNCTIONING HANDWHEELS MUST BE INSTALLED AND KEPT INSTALLED. PAID BILL A510309 \$250.00 7/31/01

Office: VE ID: VE8818  
Unique INC #: JS01063 Well Name: WVFU ID Date: 05/28/01  
Well #: 3W-14-8-21 Effective Date: 05/28/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 05/29/01  
Case #: UTU63043X FAC ID: Corrected Date: 05/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3164.1(a)(b)

Remarks Date: 06/20/01

Kill line is disconnected and not available for use. Kill line shall be connected and kept that way. Onshore order no. 2. III. A. a. iii, 3M.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE8816  
Unique INC #: JS01061 Well Name: WVFU ID Date: 05/28/01  
Well #: 3W-14-8-21 Effective Date: 05/28/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 05/29/01  
Case #: UTU63043X FAC ID: Corrected Date: 05/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3164.1(a)(b)

Remarks Date: 06/20/01

No mud pressure gauge on choke manifold. Gauge will be installed as required. Also stud missing on manifold tee block. Stud will be installed tight. Onshore order No. 2, III. A. 2. a. iii. 3M system.

Office: VE ID: VE8815  
Unique INC #: JS01060 Well Name: WVFU ID Date: 05/28/01  
Well #: 3W-14-8-21 Effective Date: 05/28/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 05/29/01  
Case #: UTU63043X FAC ID: Corrected Date: 05/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3162.6(a)(b)

Remarks Date: 06/20/01

No well sign as required by regulations. Well sign must be installed.

Office: VE ID: VE8806  
Unique INC #: JS01061A Well Name: WVFU ID Date: 05/29/01  
Well #: 3W-14-8-21 Effective Date: 05/29/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 06/29/01  
Case #: UTU63043X FAC ID: Corrected Date: 06/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$250 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3163.1, OO#2, III, A, C iii

Remarks Date: 05/31/01

YOU WERE ORDERED TO INSTALL A MUD PRESSURE GAUGE ON THE CHOKE MANIFOLD. A WELL HEAD TYPE GAUGE WAS INSTALLED. REGULATIONS SPECIFICALLY REQUIRE A MUD SERVICE GAUGE. INSTALL THE APPROPRIATE GAUGE. PAID BILL A510308  
7/30/2001

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE8817  
Unique INC #: JS01062 Well Name: WVFU ID Date: 05/28/01  
Well #: 3W-14-8-21 Effective Date: 05/28/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 05/29/01  
Case #: UTU63043X FAC ID: Corrected Date: 05/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3164.1(a)(b)

Remarks Date: 06/20/01

Independent power source for accumulator is nitrogen backup bottles. There are only two ready for use. You are required to have a minium o f three bottles. Onshore order no. 2. III. A. c. ii 3M.

Office: VE ID: VE8819  
Unique INC #: JS01064 Well Name: WVFU ID Date: 05/28/01  
Well #: 3W-14-8-21 Effective Date: 05/28/01  
Operator: SHENANDOAH ENERGY INC Abatement Date: 05/29/01  
Case #: UTU63043X FAC ID: Corrected Date: 05/29/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 cfr 3164.1(a)(b)

Remarks Date: 06/20/01

Dill string safety valve is on the floor in the closet position. The safety valve shall be maintained in the open position when not in use. Onshore order no. 2. III. A. a. iii 3M.

Office: VE ID: VE8660  
Unique INC #: JS01011 Well Name: NBU ID Date: 02/26/01  
Well #: 351 Effective Date: 02/26/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 02/27/01  
Case #: UTU63047A FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Onshore Order #2 III. A. 2. h. viii.

Remarks Date: 02/26/01

Blind rams activations, during trips, are not being recorded in driller's log. Blind rams are to be activated each trip (but not more than once per day). Said activations are to be recorded in the driller's log.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE8657  
Unique INC #: JS01008 Well Name: NBU ID Date: 02/26/01  
Well #: 351 Effective Date: 02/26/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 02/27/01  
Case #: UTU63047A FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Onshore Order #2 III. A. 2. a. iii  
Remarks Date: 02/26/01  
The kill line is disconnected. Kill line shall be hooked up and ready for use at all times .

Office: VE ID: VE8658  
Unique INC #: JS01009 Well Name: NBU ID Date: 02/26/01  
Well #: 351 Effective Date: 02/26/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 02/26/01  
Case #: UTU63047A FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Onshore Order #2 III. A. 2. h.  
Remarks Date: 02/26/01

The blind rams master control (located at the accumulator) is securely chained in the neutral position. The blind rams are incapable of being functioned from the remote control panel. The blind rams are incapable of being functioned from the master control panel without first removing the chain. The blind rams must be able to be functioned from both the master and remote control panels. Remove the chain and lose it.

Office: VE ID: VE8659  
Unique INC #: JS01010 Well Name: NBU ID Date: 02/26/01  
Well #: 351 Effective Date: 02/26/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 02/27/01  
Case #: UTU63047A FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: JAMIE SPARGER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.1 (a); Onshore Order #2 III. A. 2. g.  
Remarks Date: 02/26/01

The pipe and blind rams hand wheels are not installed. Three of the four required hand wheels are not in place. Further, one hand wheel is broken and incapable of being installed. All required hand wheels must be in working order, installed, and kept in place.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: VE ID: VE8691  
Unique INC #: CRB01006 Well Name: NBU ID Date: 02/28/01  
Well #: 343 Effective Date: 02/28/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 03/01/01  
Case #: UTU63047A FAC ID: Corrected Date: 03/01/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: RANDY BYWATER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#2, III, A.2.g  
  
Remarks Date: 03/29/01  
One hand wheel on pipe rams not hooked up. No joint on end of handle. Make needed repairs and hook up to ram.

Office: VE ID: VE8690  
Unique INC #: CRB01005 Well Name: NBU ID Date: 02/28/01  
Well #: 343 Effective Date: 02/28/01  
Operator: COASTAL OIL & GAS CORPORATION Abatement Date: 03/01/01  
Case #: UTU63047A FAC ID: Corrected Date: 02/28/01  
Form: I FAC NAME: Followup Date:  
Assessment: \$0 Inspector: RANDY BYWATER Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, OO#2, III,A.b. & u.  
  
Remarks Date: 03/28/01  
Need mud service gauge in choke manifold.

Office: WO ID: WO1960  
Unique INC #: 010-01-118 Well Name: HOC USA ID Date: 08/28/01  
Well #: 7-1 Effective Date: 08/28/01  
Operator: HUNT OIL COMPANY Abatement Date: 08/29/01  
Case #: WYW147032 FAC ID: Corrected Date: 08/29/01  
Form: I FAC NAME: Followup Date: 08/29/01  
Assessment: \$0 Inspector: R BANKERT Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2 Sec III.A.2.a.iii  
  
Remarks Date: 08/29/01

On 8/27/01 R. Bankert was informed that kill line would be installed. On 8/28/01 inspection revealed kill line still not installed due to delivery problems. Hunt Oil has 24 hours to install proper kill line.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: WO ID: WO1962  
Unique INC #: 010-01-120 Well Name: HOC USA ID Date: 08/28/01  
Well #: 7-1 Effective Date: 08/28/01  
Operator: HUNT OIL COMPANY Abatement Date: 08/29/01  
Case #: WYW147032 FAC ID: Corrected Date: 08/29/01  
Form: I FAC NAME: Followup Date: 09/10/01  
Assessment: \$0 Inspector: R BANKERT Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2 Sec III.A.2.g  
  
Remarks Date: 08/29/01

On 8/27/01 R. Bankert informed Hunt Oil and Farnsworth drilling hand wheels are required. On 8/28/01 inspection revealed hand wheels not available due to delivery problems. Hunt Oil has 24 hours to install hand wheels.

Office: WO ID: WO1961  
Unique INC #: 010-01-119 Well Name: HOC USA ID Date: 08/28/01  
Well #: 7-1 Effective Date: 08/28/01  
Operator: HUNT OIL COMPANY Abatement Date: 08/29/01  
Case #: WYW147032 FAC ID: Corrected Date: 08/29/01  
Form: I FAC NAME: Followup Date: 08/29/01  
Assessment: \$0 Inspector: R BANKERT Extend Date:  
Gravity: 3  
Authority Ref: Onshore Order #2 Sec III.A.2.a.iii  
  
Remarks Date: 08/29/01

On 8/27/01 R. Bankert was informed that 3" choke line would be installed. On 8/28/01 inspection revealed choke line not installed due to delivery problems. Hunt Oil has 24 hours to install 3" choke line.

Office: WO ID: WO1920  
Unique INC #: 010-01-080 Well Name: HOWELL USA ID Date: 05/15/01  
Well #: 35-5 Effective Date: 05/15/01  
Operator: HOWELL PETROLEUM CORPORATION Abatement Date: 05/16/01  
Case #: MTBIL026964 FAC ID: Corrected Date: 05/16/01  
Form: I FAC NAME: Followup Date: 05/17/01  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43CFR 3164.1 O.O.#1, III.G.3.f.  
  
Remarks Date: 05/16/01

Howell Petroleum did not have an APPD on location. Howell has until 5/16/01 to provide an APPD at the drill site.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: WO ID: WO1832  
Unique INC #: 010-00-090 Well Name:  
Well #: ID Date: 09/29/00  
Operator: HOWELL PETROLEUM CORPORATION Effective Date: 09/29/00  
Case #: MTBI038144 FAC ID: Abatement Date: 09/30/00  
Form: I FAC NAME: Corrected Date: 10/01/00  
Assessment: \$0 Inspector: SWICK Followup Date: 10/04/00  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1 O.O.2 III C. 7  
  
Remarks Date: 10/02/00  
The flare system is not installed from the choke manifold to the flare pit. Howell Petroleum has 24hrs. to install flare lines from date of inspection.

Office: WO ID: WO1864  
Unique INC #: 010-01-019 Well Name:  
Well #: 018-4 ID Date: 01/03/01  
Operator: WAGNER & BROWN LIMITED Effective Date: 01/03/01  
Case #: WYW0320078 FAC ID: B Abatement Date: 02/05/01  
Form: I FAC NAME: WELL 18-4 Corrected Date: 01/26/01  
Assessment: \$0 Inspector: SWICK Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3164.1 O.O.#6 III.D.2.e.  
  
Remarks Date: 01/04/01  
The wind sock and pole are laying on the dike near the tanks. The wind sock is also badly torn. (see photo). Wagner&Brown has until Feb. 5, 2001 to reset the pole and repair or replace the wind sock., The windsock was replaced, and it and the pole were reinstalled on the tank battery.

Office: WO ID: WO1863  
Unique INC #: 010-01-025 Well Name: FEDERAL COSEKA  
Well #: 012-1 ID Date: 01/03/01  
Operator: WAGNER & BROWN LIMITED Effective Date: 01/03/01  
Case #: WYW110817 FAC ID: L Abatement Date: 02/05/01  
Form: I FAC NAME: COSEKA 12-1 Corrected Date: 02/20/01  
Assessment: \$0 Inspector: SWICK Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3164.1 O.O.#6 III D.2.e.  
  
Remarks Date: 01/04/01  
The wind sock mounted on the tanks is torn to pieces, and tangled to the pole. (see photo). Wagner&Brown has until Feb.5,2001 to repair this. The windsock was reinstalled on the tank battery.

Safety and Drilling Related Violations (INCs) Issued During FY 2001  
As of March 3, 2011

Office: WO ID: WO1852  
Unique INC #: 010-01-020 Well Name: CC FEDERAL ID Date: 11/14/00  
Well #: 002-2 Effective Date: 11/14/00  
Operator: CONTINENTAL RESOURCES INC Abatement Date: 11/17/00  
Case #: WYW29763C FAC ID: Corrected Date: 11/17/00  
Form: I FAC NAME: Followup Date: 11/17/00  
Assessment: \$0 Inspector: SWICK Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.O.#2 III.A.i.

Remarks Date: 11/15/00

During BOP tests, upper kelly cock valve would not test, Cyclone Drilling will replace valve in 3 days.

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Office: BA ID: BA1049  
Unique INC #: 03-024-00 Well Name: USL ID Date: 03/23/00  
Well #: 41R Effective Date: 03/24/00  
Operator: AERA ENERGY LLC Abatement Date: 05/16/00  
Case #: CACA28423 FAC ID: Corrected Date: 04/19/00  
Form: I FAC NAME: Followup Date: 05/15/00  
Assessment: \$0 Inspector: DONALD MOREN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 03/24/00

You were found to be in violation of 43 CFR 3162.6(b). The sign for well #41R did not have the correct well number, the location, or the lease serial number. "the operator shall properly identify, by sign in a conspicuous place, each well,... The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range...)" Install a proper well identification sign.

Office: BA ID: BA1002  
Unique INC #: 03-017-00 Well Name: USL ID Date: 02/02/00  
Well #: 31R Effective Date: 02/04/00  
Operator: AERA ENERGY LLC Abatement Date: 03/29/00  
Case #: CACA28423 FAC ID: Corrected Date: 03/23/00  
Form: I FAC NAME: Followup Date: 03/23/00  
Assessment: \$0 Inspector: DONALD MOREN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(b)

Remarks Date: 02/07/00

You were found to be in violation of 43CFR 3162.6(b). "...the operator shall properly identify, by a sign in a conspicuous place, each well,... The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location,..." Install a proper well identification sign.

Office: BA ID: BA1097  
Unique INC #: 05-024-00 Well Name: SEC 20 ID Date: 05/09/00  
Well #: 3 Effective Date: 05/12/00  
Operator: MACPHERSON OIL COMPANY Abatement Date: 07/07/00  
Case #: CACA34219X FAC ID: Corrected Date: 06/06/00  
Form: I FAC NAME: Followup Date: 06/13/00  
Assessment: \$0 Inspector: DONALD MOREN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)

Remarks Date: 05/12/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

You were found to be in violation of 43 CFR 3162.6(a). The well identification sign for the Section 20 #3 is not legible. "Every well within a Federal or Indian lease or supervised agreement shall have a well identification sign. All signs shall be maintained in a legible condition." Install a legible well identification sign.

Office: BA ID: BA1098  
Unique INC #: 05-025-00 Well Name: SEC 20 ID Date: 05/09/00  
Well #: 3-A Effective Date: 05/12/00  
Operator: MACPHERSON OIL COMPANY Abatement Date: 07/07/00  
Case #: CACA34219X FAC ID: Corrected Date: 07/05/00  
Form: I FAC NAME: Followup Date: 07/05/00  
Assessment: \$0 Inspector: DONALD MOREN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6

Remarks Date: 05/12/00

You were found to be in violation of 43 CFR 3162.6. There is no well identification sign for the Section 20 #3a well. "Every well within a Federal or Indian lease or supervised agreement shall have a well identification sign. ...The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range...), ...the sign shall include the unit or communitization name or number." Install a well identification sign.

Office: BA ID: BA1096  
Unique INC #: 05-023-00 Well Name: BELL ONE ID Date: 05/05/00  
Well #: 16 Effective Date: 05/12/00  
Operator: MACPHERSON OIL COMPANY Abatement Date: 07/07/00  
Case #: CACA34219X FAC ID: Corrected Date: 06/06/00  
Form: I FAC NAME: Followup Date: 06/13/00  
Assessment: \$0 Inspector: DONALD MOREN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6(a)

Remarks Date: 05/12/00

You were found to be in violation of 43 CFR 3162.6(a). The well identification sign for the Bell One #16 is not legible. "Every well within a Federal or Indian lease or supervised agreement shall have a well identification sign. All signs shall be maintained in a legible condition." Install a legible well identification sign.

Office: BA ID: BA1099  
Unique INC #: 05-026-00 Well Name: SEC 20 ID Date: 05/10/00  
Well #: WD 2 Effective Date: 05/12/00  
Operator: MACPHERSON OIL COMPANY Abatement Date: 07/07/00  
Case #: CACA34219X FAC ID: Corrected Date: 06/13/00  
Form: I FAC NAME: Followup Date: 06/13/00  
Assessment: \$0 Inspector: DONALD MOREN Extend Date:  
Gravity: 3  
Authority Ref: 43 CFR 3162.6

Remarks Date: 05/12/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

You were found to be in violation of 43 CFR 3162.6. There is no well identification sign for the Section 20 #WD2 well. "Every well within a Federal or Indian lease or supervised agreement shall have a well identification sign. The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range...), ...the sign shall include the unit or communicationization name or number." Install a well identification sign.

Office: BA		ID: BA987
Unique INC #: 03-012-00	Well Name: DOME TUMBADOR	
	Well #: 7	ID Date: 01/25/00
Operator: NUEVO ENERGY COMPANY		Effective Date: 01/25/00
Case #: CAS019389A	FAC ID:	Abatement Date: 03/23/00
Form: I	FAC NAME:	Corrected Date: 01/28/00
Assessment: \$0	Inspector: DONALD MOREN	Followup Date: 01/28/00
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6 (b)		

Remarks Date: 01/27/00

You were found to be in violation of 43 CFR 3162.6 (b). "For wells located on Federal and Indian lands, the operator shall properly indentify, by a sign in a conspicuous place, each well, other than those permanently abandoned. The well sign shall include the well number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section , township ansd range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds)." Install a proper well identification sign.

Office: BA		ID: BA999
Unique INC #: 05-016-00	Well Name: LACKIE USL	
	Well #: A-1	ID Date: 02/03/00
Operator: SAM ENTERPRISES INCORPORATED		Effective Date: 02/15/00
Case #: CALA054899	FAC ID:	Abatement Date: 03/06/00
Form: I	FAC NAME:	Corrected Date: 02/04/00
Assessment: \$0	Inspector: GEORGE GARCIA	Followup Date: 02/04/00
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 02/07/00

Well sign does not display lease number. All well signs on federal leases must display the lease number, the operator, Qtr.-Qtr., Section, Township, Range. Add the lease number to the well sign to gain compliance.

Office: BA		ID: BA1001
Unique INC #: 05-010-00	Well Name: SNOW	
	Well #: 1	ID Date: 02/03/00
Operator: SAM ENTERPRISES INCORPORATED		Effective Date: 02/16/00
Case #: CALA084342	FAC ID:	Abatement Date: 03/06/00
Form: I	FAC NAME:	Corrected Date: 02/04/00
Assessment: \$0	Inspector: GEORGE GARCIA/CHRIS C	Followup Date: 02/04/00
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.6(b)		

Remarks Date: 02/07/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Well sign does not display lease number. All well signs on federal leases must display the lease number, the operator, Qtr.-Qtr., Section, Township, and Range. Add the lease number to the well sign to gain compliance.

Office: BA		ID: BA1120
Unique INC #: 04-069-00	Well Name: PIONEER FLANK	
	Well #: 1	ID Date: 07/31/00
Operator: IVANHOE ENERGY USA INC		Effective Date: 08/22/00
Case #: CALA044931	FAC ID:	Abatement Date: 09/11/00
Form: I	FAC NAME:	Corrected Date: 09/05/00
Assessment: \$4,000	Inspector: MICHAEL DAVIS	Followup Date: 09/05/00
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.3-1 and APD Conditions of Approval		

Remarks Date: 08/22/00

Letter sent 08/14/00 referencing written order to remove parked trailers, vehicles, and truck-trailers from disturbed area and also required you to install the protective fencing and remove all equipment from all unauthorized areas in reference to the drilling well pad on Pioneer Flank #1. Areas that were disturbed must be scarified and reseeded in December of 2000 or as prescribed by Russ Lewis, Surface Specialist. For failure to comply with 43 CFR 3162.3-3, the APD COA's and for causing unauthorized surface disturbance on Federal surface prior to drilling, Ivanhoe is assessed \$500.00 per day for 8 days from July 28, 2000 through August 4, 2000 (\$500.00 x 8 = \$4,000.00) pursuant to 43 CFR 3163(1)(b)(2). You are hereby given 20 calendar days from receipt of this notice, no later than September 11, 2000 to send a check in the amount of \$4,000.00.

Office: BA		ID: BA744
Unique INC #: 02-026-98	Well Name:	
	Well #:	ID Date: 03/26/98
Operator: UNITED ENERGY INCORPORATED		Effective Date: 03/31/98
Case #: CAS037269	FAC ID: A	Abatement Date: 04/30/98
Form: I	FAC NAME: POSO CREEK TANK FARM	Corrected Date: 03/16/00
Assessment: \$250	Inspector: PATRICK BUSTOS	Followup Date: 04/30/98
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1(c)		

Remarks Date: 03/26/98

For failure to comply with written notice #02-016-98, you are assessed \$250.00. See Attached copy of INC #02-016-98.

Office: BA		ID: BA745
Unique INC #: 02-027-98	Well Name:	
	Well #:	ID Date: 03/26/98
Operator: UNITED ENERGY INCORPORATED		Effective Date: 03/31/98
Case #: CAS037269	FAC ID: A	Abatement Date: 04/30/98
Form: I	FAC NAME: POSO CREEK TANK FARM	Corrected Date: 03/16/00
Assessment: \$0	Inspector: PATRICK BUSTOS	Followup Date: 04/30/98
Gravity: 3		Extend Date:
Authority Ref: 43 CFR 3162.5-1		

Remarks Date: 03/26/98

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Environmental protection. Operator must conduct operations to protect against fire hazards, soil erosion, and unauthorized emissions. Also, the operator must protect natural resources and the environment. Remove all oil from the basin around the transfer pump on the west side of tank #20S285.

Office: BA ID: BA729  
Unique INC #: 02-016-98 Well Name:  
Well #:  
Operator: UNITED ENERGY INCORPORATED  
Case #: CAS037269 FAC ID: A  
Form: I FAC NAME: POSO CREEK TANK FARM  
Assessment: \$0 Inspector: PATRICK BUSTOS  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1

Remarks Date: 02/10/98

Environmental protection. Operator must conduct operations to protect against fire hazards, soil erosion, and unauthorized emissions. Also, the operator must protect natural resources and the environment. Repair the leak either in the fuel oil tank or the pump, whichever is causing the chronic puddling within the containment berm.

Office: BA ID: BA763  
Unique INC #: 02-046-98 Well Name:  
Well #:  
Operator: UNITED ENERGY INCORPORATED  
Case #: CAS037269 FAC ID: A  
Form: I FAC NAME: POSO CREEK TANK FARM  
Assessment: \$0 Inspector: PATRICK BUSTOS  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-1

Remarks Date: 04/28/98

Environmental protection. Operator must conduct operations to protect against fire hazards, soil erosion, and unauthorized emissions. Also, the operator must protect natural resources and the environment. Remove oil from the 5 / 5 gallon buckets located near the truck loading area at the sales facility.

Office: BA ID: BA764  
Unique INC #: 02-047-98 Well Name:  
Well #:  
Operator: UNITED ENERGY INCORPORATED  
Case #: CAS037269 FAC ID: A  
Form: I FAC NAME: POSO CREEK TANK FARM  
Assessment: \$0 Inspector: PATRICK BUSTOS  
Gravity: 3  
Authority Ref: 43 CFR 3163.2(g)(2)

Remarks Date: 05/01/98

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

For failure to comply with written notice number 02-026-98 (attached). The noncompliance was not abated within the time allowed by the second notice. The initial proposed penalty for a minor violation under paragraph (a) (43 CFR 3163.2(a)(2)) of this section shall be at the rate of \$50 per day beginning with the date of the second notice (3/26/98).

Office: BA		ID: BA758
Unique INC #: 02-040-98	Well Name:	
	Well #:	
Operator: UNITED ENERGY INCORPORATED		
Case #: CAS037269	FAC ID: A	ID Date: 04/20/98
Form: I	FAC NAME: POSO CREEK TANK FARM	Effective Date: 04/20/98
Assessment: \$250	Inspector: PATRICK BUSTOS	Abatement Date: 05/22/98
Gravity: 3		Corrected Date: 03/16/00
Authority Ref: 43 CFR 3163.1(a)(2)		Followup Date: 05/22/98
		Extend Date:

Remarks Date: 04/20/98

For failure to comply with written notice number 02-031-98 (attached), you are assessed \$250.00.

Office: BU		ID: BU4752
Unique INC #: KB/00/16	Well Name: FEDERAL	
	Well #: 27-13	
Operator: TORCH E & P COMPANY		
Case #: WYW137102	FAC ID:	ID Date: 03/16/00
Form: I	FAC NAME:	Effective Date: 03/29/00
Assessment: \$0	Inspector: BRYCE	Abatement Date: 04/17/00
Gravity: 3		Corrected Date: 03/21/00
Authority Ref: 43 CFR 3162.6.b.		Followup Date: 03/26/00
		Extend Date:

Remarks Date: 03/20/00

Failure to maintain a legible sign on the Federal 27-13 Well. Specifically: For wells located on Federal Lands or Minerals, the operator shall properly identify, by a sign in a conspicuous place, each well, other than those permanently abandoned. The well sign shall include the well number, the name of the operator, the lease serial number, the quarter quarter section, section, township and range. Your attention to this matter is appreciated.

Office: CB		ID: CB12902
Unique INC #: 99-CQ-1180	Well Name:	
	Well #:	
Operator: YATES PETROLEUM CORPORATION		
Case #: NMNM84612	FAC ID: VV	ID Date: 09/01/99
Form: I	FAC NAME: BINGER AKU #1	Effective Date:
Assessment: \$0	Inspector: Cathleen Queen	Abatement Date: 10/02/99
Gravity: 3		Corrected Date: 11/19/99
Authority Ref: 43 CFR 3162.5-3		Followup Date: 11/19/99
		Extend Date:

Remarks Date: 09/02/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Excessive growth of vegetation around production equipment and oil storage tanks. Remove excessive vegetation.

Office: CB ID: CB13024  
Unique INC #: 00-DE-44 Well Name: BAXTER FED C  
Well #: 1, 2 ID Date: 10/22/99  
Operator: JOE MELTON DRILLING CO, INC Effective Date:  
Case #: NMLC029438A FAC ID: A Abatement Date: 11/29/99  
Form: I FAC NAME: BAXTER C Corrected Date: 11/02/99  
Assessment: \$0 Inspector: Don Early Followup Date: 11/02/99  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 O. O. # 6.D.2.E

Remarks Date: 10/25/99

ON THE BAXTER C TANK BATTERY NO PERMANENT WIND DIRECTION INDICATOR ON LOCATION. INSTALL AT LEAST ( 1 ) PERMANENT WIND DIRECTION INDECATOR SO WIND DIRECTION CAN BE EASILY DETERMINED AT OR APPOACHING THE STORAGE TANKS.

Office: CB ID: CB13913  
Unique INC #: 00-DE-205 Well Name: JL-35 FEDERAL  
Well #: 1 ID Date: 06/30/00  
Operator: SNOW OPERATING COMPANY INC Effective Date:  
Case #: NMLC062029 FAC ID: 35 Abatement Date: 07/28/00  
Form: I FAC NAME: JL 35 Corrected Date: 08/03/00  
Assessment: \$0 Inspector: Don Early Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: ONSHORE ORDER # 6.D.2.E 43CFR31623164.1

Remarks Date: 07/03/00

ON THE J.L. "35" FEDERAL TANK BATTERY NO PERMANENT WIND DIRECTION INDICATOR ON LOCATION.INSTALL AT LEAST (1) PERMANENT WIND DIRECTION INDICATOR SO WIND DIRECTION CAN BE EASILY DETERMINED AT OR APPOACHING THE STORAGE TANKS.

Office: CB ID: CB12916  
Unique INC #: 99-DE 1194 Well Name: YATES B  
Well #: 1 ID Date: 09/02/99  
Operator: EOG RESOURCES, INC. Effective Date:  
Case #: NMNM021096 FAC ID: L Abatement Date: 10/04/99  
Form: I FAC NAME: YATES B Corrected Date: 11/04/99  
Assessment: \$0 Inspector: Don Early Followup Date: 11/04/99  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 09/03/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

PUMP JACK ON THE YATES B WELL # 1 NO BELT OR COUNTER WEIGHT GUARD AROUND PUMP JACK. INSTALL GUARDS AROUND PUMP JACK.

Office: CB ID: CB12988  
Unique INC #: 00-DE-008 Well Name: NORTH SQUARE LAKE UNIT  
Well #: 92 ID Date: 10/06/99  
Operator: GLEN PLEMONS Effective Date:  
Case #: NMNM05186 FAC ID: L Abatement Date: 11/11/99  
Form: I FAC NAME: Corrected Date: 11/04/99  
Assessment: \$0 Inspector: Don Early Followup Date: 11/04/99  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 10/07/99

NO COUNTER WEIGHT GUARDS AROUND PUMP JACK ON THE FEATHERSTONE FEDERAL # 1 WELL. INSTALL GUARDS AROUND THE COUNTER WEIGHT ON THE PUMP JACK.

Office: CB ID: CB13745  
Unique INC #: 00-DE-193 Well Name: ALSCOTT FEDERAL, SIVLEY FEDERAL  
Well #: 1, 2 ID Date: 05/31/00  
Operator: VINTAGE DRILLING, L.L.C. Effective Date:  
Case #: NMNM56426 FAC ID: A, L Abatement Date: 06/30/00  
Form: I FAC NAME: Corrected Date: 06/22/00  
Assessment: \$0 Inspector: Don Early Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 ONSHORE ORDER # 6.D.2.E  
  
Remarks Date: 06/01/00

ON THE ALSCOTT AND SIVLEY TANK BATTERY NEED PERMANENT WIND DIRECTION INDICATOR ON LOCATION. INSTALL AT LEAST (1) PERMANENT WIND DIRECTION INDICATOR SO WIND DIRECTION CAN BE EASILY DETERMINED AT OR APPROACHING THE STORAGE TANKS.

Office: CB ID: CB13750  
Unique INC #: 00-DE-198 Well Name: SIVLEY FEDERAL  
Well #: 1 ID Date: 05/31/00  
Operator: VINTAGE DRILLING, L.L.C. Effective Date:  
Case #: NMNM56426 FAC ID: A, L Abatement Date: 06/30/00  
Form: I FAC NAME: Corrected Date: 06/22/00  
Assessment: \$0 Inspector: Don Early Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 06/01/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

ON THE SIVLEY WELL # 1 NO COUNTER WEIGHT GUARDS AROUND PUMP JACK. INSTALL GUARDS OR INSTALL FENCING AROUND PUMP JACK.

Office: CB ID: CB14404  
Unique INC #: 00-DW-276 Well Name:  
Well #:  
Operator: JEHOVAH JIREH OIL COMPANY ID Date: 09/06/00  
Case #: NMNM71028X FAC ID: SALDR Effective Date: 09/07/00  
Form: I FAC NAME: SALADAR Abatement Date: 10/10/00  
Assessment: \$0 Inspector: Duncan Whitlock Corrected Date: 09/25/00  
Gravity: 3 Followup Date: 09/25/00  
Authority Ref: 43CFR3162.1/ONSHORE ORDER #6,III,D,2,E Extend Date:  
Remarks Date: 09/07/00

ALL STAIRS/LADDERS LEADING TO THE TOP OF STORAGE TANKS SHALL BE CHAINED AND/OR MARKED TO RESTRICT ENTRY. PLACE A CHAIN WITH A SIGN LEADING UP STAIRS SO AS TO RESTRICT ENTRY DO TO H2S CONCENTRATIONS.

Office: CB ID: CB14403  
Unique INC #: 00-DW-275 Well Name:  
Well #:  
Operator: JEHOVAH JIREH OIL COMPANY ID Date: 09/06/00  
Case #: NMNM71028X FAC ID: SALDR Effective Date: 09/07/00  
Form: I FAC NAME: SALADAR Abatement Date: 10/10/00  
Assessment: \$0 Inspector: Duncan Whitlock Corrected Date: 09/25/00  
Gravity: 3 Followup Date: 09/25/00  
Authority Ref: 43CFR3162.1/ONSHORE ORDER #6,III,D,2,E Extend Date:  
Remarks Date: 09/07/00

NO PERMANENT WIND DIRECTION INDICATORS AT FACILITY. INSTALL PERMANENT WIND DIRECTIN INDICATOR AS PER ONSHORE ORDER #6.

Office: CB ID: CB13479  
Unique INC #: 00-GH-223 Well Name:  
Well #:  
Operator: EGL RESOURCES INC ID Date: 02/29/00  
Case #: NMLC050797 FAC ID: A, B Effective Date:  
Form: I FAC NAME: 13 FED 16 BATTERY, 14 FED 3 BATTE Abatement Date: 03/31/00  
Assessment: \$0 Inspector: Eugene Hunt Corrected Date: 04/07/00  
Gravity: 3 Followup Date: 04/07/00  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.A.2. Extend Date:  
Remarks Date: 03/01/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

ONSHORE ORDERS REQUIRE THAT FOR EACH NEW FACILITY HAVING AN H2S CONCENTRATION GREATER THAN 100 PPM IN THE GAS STREAM, THE OPERATOR SHALL CALCULATE AND SUBMIT THE 100 PPM AND THE 500 PPM RADII OF EXPOSURE AND SUBMIT THE CALCULATIONS WITHIN 30 DAYS OF CONSTRUCTION AND INITIAL USE. SUBMIT RADII OF EXPOSURE FOR THESE FACILITIES WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB13480  
Unique INC #: 00-GH-224 Well Name:  
Well #: ID Date: 02/29/00  
Operator: EGL RESOURCES INC Effective Date:  
Case #: NMLC050797 FAC ID: A, B Abatement Date: 03/21/00  
Form: I FAC NAME: 13 FED 16 BATTERY, 14 FED 3 BATTE Corrected Date: 03/21/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 03/21/00  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.A.2.

Remarks Date: 03/01/00

ONSHORE ORDER #6 REQUIRES THAT ANY TANK BATTERY HAVING STORAGE TANK H2S VAPORS IN EXCESS OF 500 PPM BE EQUIPPED WITH CORRECT WARNING SIGNS, WIND DIRECTION INDICATORS, AND SIGNS OR BARRIERS ON THE STAIRWAYS ENTRANCE WHICH RESTRICT ENTRY. INSTALL CORRECT H2S WARNING SIGNS ON OR WITHIN 50FEET OF THE STORAGE TANKS AT EACH BATTERY, INSTALL A WIND DIRECTION INDRIATOR AT EACH BATTERY, AND INSTALL CHAINS OR BARRIERS WHICH RESTRICT THE ENTRY TO THE STAIRS, ALL WITHIN TWENTY DAYS OF NOTICE. ALL EQUIPMENT SHOULD BE INSTALLED SUCH THAT PERSONS APPROACHING THE SALES POINTS CAN EASILY SEE THE WARNING EQUIPMENT AND INDICATORS.

Office: CB ID: CB13643  
Unique INC #: 00-GH-295 Well Name:  
Well #: ID Date: 05/08/00  
Operator: DEVON ENERGY PRODUCTION CO L P Effective Date:  
Case #: NMNM101344 FAC ID: A Abatement Date: 06/08/00  
Form: I FAC NAME: STATE BO COM #1 BATTERY Corrected Date: 05/09/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 05/09/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-1

Remarks Date: 05/08/00

BERM EROSION HAS RENDERED THE GATE INOPERABLE FOR ENTRANCE TO THE BATTERY. REPAIR BERM AND/ OR GATE TO ALLOW SAFE ENTRY BY PERSONNEL.

Office: CB ID: CB13893  
Unique INC #: 00-GH-359 Well Name: HACKBERRY 29 FED  
Well #: 1 ID Date: 06/28/00  
Operator: CONCHO RESOURCES INC Effective Date:  
Case #: NMNM97118 FAC ID: A Abatement Date: 07/31/00  
Form: I FAC NAME: HACKBERRY 29 FED BTYY. Corrected Date: 07/31/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 07/31/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.D.2.e.

Remarks Date: 06/29/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

REQUIRED WIND DIRECTION INDICATOR IS IN DISREPAIR. REPAIR/ REPLACE THE WIND DIRECTION EQUIPMENT TO CONFORM TO REQUIREMENTS SET FORTH IN THE ONSHORE ORDERS.

Office: CB ID: CB13892  
Unique INC #: 00-GH-358 Well Name: HACKBERRY 29 FED  
Well #: 1 ID Date: 06/28/00  
Operator: CONCHO RESOURCES INC Effective Date:  
Case #: NMNM97118 FAC ID: A Abatement Date: 07/31/00  
Form: I FAC NAME: HACKBERRY 29 FED BTTY. Corrected Date: 07/05/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 07/05/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.D.3.a.

Remarks Date: 06/29/00

TANKS ARE NOT EQUIPPED WITH CORRECT DANGER SIGNS REGARDING THE PRESENCE OF H2S IN THE TANKS AND ON THE LOCATION. INSTALL CORRECT SIGNS ON OR WITHIN 50 FEET OF THE TANKS, EASILY VISIBLE TO PEOPLE APPROACHING THE SALES POINT OF THE OIL.

Office: CB ID: CB13891  
Unique INC #: 00-GH-357 Well Name: HACKBERRY 29 FED  
Well #: 1 ID Date: 06/28/00  
Operator: CONCHO RESOURCES INC Effective Date:  
Case #: NMNM97118 FAC ID: A Abatement Date: 07/31/00  
Form: I FAC NAME: HACKBERRY 29 FED BTTY. Corrected Date: 09/13/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 10/04/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#6,III.A.2.a.

Remarks Date: 09/08/00

RADIUS OF EXPOSURE OF H2S HAS NOT BEEN SUBMITTED FOR THIS LOCATION. SUBMIT ACCURATE RADII OF EXPOSURE FOR THIS LOCATION, AS SPECIFIED IN ONSHORE ORDERS REFERENCED ABOVE., WELL IS STILL SI. NEED TO CALL TERRI STATHEM

Office: CB ID: CB13404  
Unique INC #: 00-GH-198 Well Name: REMINGTON FED  
Well #: 1, 2, 3 ID Date: 02/02/00  
Operator: CHI OPERATING INCORPORATED Effective Date:  
Case #: NMNM9818 FAC ID: A Abatement Date: 03/06/00  
Form: I FAC NAME: REMINGTON FEDERAL BATTERY Corrected Date: 03/06/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 03/06/00  
Gravity: 1 Extend Date:  
Authority Ref: 43 CFR 3164.1, O.O.#4,III.C.1.

Remarks Date: 02/04/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

GAUGE HATCH LID VACUUM RELIEF PORT MECHANISM ON TANK 35372 NEEDS REPAIRED TO OPERATE CORRECTLY. REPAIR/ REPLACE THE EQUIPMENT AS NEEDED TO OPERATE CORRECTLY, WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB13405  
Unique INC #: 00-GH-199 Well Name: REMINGTON FED  
Well #: 1, 2, 3 ID Date: 02/02/00  
Operator: CHI OPERATING INCORPORATED Effective Date:  
Case #: NMNM9818 FAC ID: A Abatement Date: 03/06/00  
Form: I FAC NAME: REMINGTON FEDERAL BATTERY Corrected Date: 03/06/00  
Assessment: \$0 Inspector: Eugene Hunt Followup Date: 03/06/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 02/04/00

STAIRWAY AND GAUGING PLATFORM ON TANK 35370 IS NOT CONNECTED AND/OR SET SAFELY FOR USE BY PERSONNEL GAUGING AND ISOLATING THE TANK. INSTALL/ REPAIR THE STIRWAY TO SAFELY ALLOW ACCESS TO THE TANKAGE WITHIN THIRTY DAYS OF NOTICE.

Office: CB ID: CB13771  
Unique INC #: 00-JA-145 Well Name: ELIZONDO A FED  
Well #: 1 ID Date: 06/12/00  
Operator: SNOW OIL & GAS INCORPORATED Effective Date: 06/19/00  
Case #: NMNM0354232 FAC ID: C Abatement Date: 07/12/00  
Form: I FAC NAME: ELIZONDO A Corrected Date: 06/29/00  
Assessment: \$0 Inspector: James Amos Followup Date: 06/29/00  
Gravity: 3 Extend Date:  
Authority Ref: Onshore Order 6.III.D.3

Remarks Date: 06/16/00

H2S concentration @ 200 PPM STV. Install warning signs and wind sock.

Office: DK ID: DK5576  
Unique INC #: IWM0004 Well Name: PROBST FED  
Well #: 12-10 ID Date: 10/26/99  
Operator: WASCANA OIL AND GAS INC Effective Date: 11/05/99  
Case #: NDM26003 FAC ID: A Abatement Date: 11/30/99  
Form: I FAC NAME: PROBST FED 12-10 Corrected Date: 12/03/99  
Assessment: \$0 Inspector: BILL MCMANUS Followup Date: 12/03/99  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 OO36 III.3.e.

Remarks Date: 10/27/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

wind sock is torn. replace or repair wind sock.

Office: DK ID: DK5668  
Unique INC #: IWM0018 Well Name: FEDERAL  
Well #: 1-827, 42-27  
Operator: MERIT ENERGY COMPANY  
Case #: SDM54158 FAC ID: A  
Form: I FAC NAME: FEDERAL 1-827  
Assessment: \$0 Inspector: BILL MCMANUS  
Gravity: 3  
Authority Ref: 43CFR3164.1 00#6 III D.3.c

Remarks Date: 08/11/00

No danger sign posted within 50 feet of oil storage tanks to alert the public of potential hydrogen sulfide gas. Gas analysis submitted to BLM on Oct. 28, 1999 showed on site hydrogen sulfide gas 130 PPM. Install Hydrogen Sulfide warning sign or signs within in 50 feet of oil storage tanks.

Office: DK ID: DK5642  
Unique INC #: IDH00025 Well Name: FEDERAL  
Well #: 3-4  
Operator: CITATION OIL & GAS CORPORATION  
Case #: NDM31262 FAC ID: B  
Form: I FAC NAME: FEDERAL 3-4  
Assessment: \$0 Inspector: DENNIS HANNUM  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, D, 1,c

Remarks Date: 05/31/00

Flare ignitor not in operable condition. Must repair or replace flare ignitor system and put in good working order. Talked to Mr. Eugene Dowhaniuk about this matter 5/23/2000 The green copy is the operators copy., Flare ignitor was working 5/26/2000

Office: DK ID: DK5643  
Unique INC #: IDH00026 Well Name: FEDERAL  
Well #: 3-1  
Operator: CITATION OIL & GAS CORPORATION  
Case #: NDM31262 FAC ID: A  
Form: I FAC NAME: FEDERAL 3-1  
Assessment: \$0 Inspector: DENNIS HANNUM  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, D, 1,c

Remarks Date: 05/23/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Flare ignitor not in operable condition. Must repair or replace flare ignitor system and put in good working order. Talked to Mr. Eugene Dowhaniuk about this matter 5/23/2000. The green copy is the operators copy., Flare ignitor was working 5/26/2000

Office: DK ID: DK5644  
Unique INC #: IDH00027 Well Name: FEDERAL  
Well #: 15-2 ID Date: 05/22/00  
Operator: CITATION OIL & GAS CORPORATION Effective Date: 05/23/00  
Case #: NDM31262 FAC ID: C Abatement Date: 06/23/00  
Form: I FAC NAME: FEDERAL 15-2 Corrected Date: 05/25/00  
Assessment: \$0 Inspector: DENNIS HANNUM Followup Date: 05/26/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, D, 1,c

Remarks Date: 05/31/00

Flare ignitor not in operable condition. Must repair or replace flare ignitor system and put in good working order. Talked to Mr. Eugene Dowhaniuk about this matter 5/23/2000. The green copy is the operators copy., Flare ignitor was working 5/26/2000

Office: DK ID: DK5606  
Unique INC #: IDH00011 Well Name: L B FEDERAL B  
Well #: 1 ID Date: 03/15/00  
Operator: CITATION OIL & GAS CORPORATION Effective Date: 03/21/00  
Case #: NDM63077 FAC ID: B Abatement Date: 04/12/00  
Form: I FAC NAME: L B FEDERAL B 1 Corrected Date: 04/05/00  
Assessment: \$0 Inspector: DENNIS HANNUM Followup Date: 04/11/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 O.S.O. # 6, III, D, 1, c

Remarks Date: 04/20/00

Flare ignitor not in operable condition. Must repair or replace flare ignitor system and put in good working order. Talked to Mr. Eugene Dowhaniuk about this matter 3/15/00. The green copy is the operators copy., Flare ignitor working, repaired

Office: DK ID: DK5665  
Unique INC #: IKAW00007 Well Name: SFTU  
Well #: 9-23 ID Date: 08/08/00  
Operator: WESTPORT OIL & GAS COMPANY LP Effective Date: 08/16/00  
Case #: NDM24445 FAC ID: Abatement Date: 09/16/00  
Form: I FAC NAME: Corrected Date: 08/22/00  
Assessment: \$0 Inspector: KAREN WOLF Followup Date: 09/07/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1 OO#6, III.A.2.a.

Remarks Date: 08/09/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Submit Radius of Exposure Calculations for the #9-23.

Office: DK ID: DK5664  
Unique INC #: IKAW00006 Well Name: SFTU  
Well #: 12-35  
Operator: WESTPORT OIL & GAS COMPANY LP  
Case #: NDM75073 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KAREN WOLF  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, OO#6, III.A.2.a.  
Remarks Date: 08/09/00  
Submit Radius of Exposure Calculations for the #12-35.

Office: DK ID: DK5663  
Unique INC #: IKAW00005 Well Name: SFTU  
Well #: 40-26  
Operator: WESTPORT OIL & GAS COMPANY LP  
Case #: NDM85994 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KAREN WOLF  
Gravity: 3  
Authority Ref: 43 CFR 3164.1, OO#6 III.A.2.a.  
Remarks Date: 08/09/00  
Submit Radius of Exposure Calculations for the #40-26.

Office: DK ID: DK5684  
Unique INC #: IKDW00024 Well Name: FEDERAL  
Well #: 1-26  
Operator: NANCE PETROLEUM CORPORATION  
Case #: NDM36309 FAC ID: C  
Form: I FAC NAME: FEDERAL 1-26  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. D. 3. e.  
Remarks Date: 09/06/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

WIND DIRECTION INDICATOR AT THE FEDERAL 1-26 LOCATION NOT IN WORKING ORDER. INSTALL OR REPAIR THE WIND DIRECTION INDICATOR AT THE FEDERAL 1-26 LOCATION.

Office: DK ID: DK5662  
Unique INC #: IKDW00022 Well Name: NORMA FEE  
Well #: 43-6  
Operator: SUMMIT RESOURCES INCORPORATED  
Case #: NDM70181CA FAC ID: F  
Form: I FAC NAME: NORMA FEE 43-6  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (b)

ID Date: 08/03/00  
Effective Date: 08/14/00  
Abatement Date: 10/02/00  
Corrected Date: 08/15/00  
Followup Date: 08/28/00  
Extend Date:

Remarks Date: 08/07/00

WELL SIGN INCOMPLETE AT THE NORMA FEE 43-6 LOCATION. SIGN NEEDS TO INCLUDE THE FEDERAL LEASE NUMBER NDM70181CA.

Office: DK ID: DK5594  
Unique INC #: IKDW00002 Well Name:  
Well #:  
Operator: PAUL B RANKIN INC  
Case #: NDM70190CA FAC ID: A  
Form: I FAC NAME: ANDERSON FED  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. A. 2.a.

ID Date: 01/13/00  
Effective Date: 01/21/00  
Abatement Date: 02/25/00  
Corrected Date: 01/24/00  
Followup Date: 02/09/00  
Extend Date:

Remarks Date: 01/13/00

NO RADIUS OF EXPOSURE FOR H2S. SUBMIT RADIUS OF EXPOSURE CALCULATIONS FOR 100 AND 500 PPM.

Office: DK ID: DK5669  
Unique INC #: IKDW00023 Well Name: SIL UNIT 9  
Well #: 9-1  
Operator: PETRO-HUNT LLC  
Case #: NDM80033 FAC ID: A  
Form: I FAC NAME: SIL UNIT 9 9-1  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. D. 3. a.

ID Date: 08/16/00  
Effective Date: 08/30/00  
Abatement Date: 10/06/00  
Corrected Date: 08/24/00  
Followup Date: 09/21/00  
Extend Date:

Remarks Date: 08/22/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

NO H2S DANGER SIGN AT THE SILURIAN UNIT 9, WELLHEAD 9-1 LOCATION. POST H2S DANGER SIGN AS REQUIRED.

Office: DK ID: DK5685  
Unique INC #: IKDW00025 Well Name: FEDERAL  
Well #: 12-15 ID Date: 08/31/00  
Operator: DEVON ENERGY CORPORATION Effective Date: 09/13/00  
Case #: NDM82198 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. A. 2. a.  
Abatement Date: 10/28/00  
Corrected Date: 09/19/00  
Followup Date: 10/04/00  
Extend Date:

Remarks Date: 09/06/00

NO RADIUS OF EXPOSURE FOR H2S. SUBMIT RADIUS OF EXPOSURE CALCULATIONS FOR THE 100 AND, IF APPLICABLE, THE 500 PPM RADIUS OF EXPOSURE.

Office: DK ID: DK5654  
Unique INC #: IKDW00019 Well Name: STEARNS  
Well #: 14-15H ID Date: 06/20/00  
Operator: CITATION OIL & GAS CORPORATION Effective Date: 07/06/00  
Case #: NDM85863 FAC ID: A  
Form: I FAC NAME: STEARNS 14-15H  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (b)  
Abatement Date: 08/25/00  
Corrected Date: 07/17/00  
Followup Date: 08/29/00  
Extend Date:

Remarks Date: 06/27/00

WELL SIGN INCOMPLETE AT THE STEARNS 14-15H LOCATION. SIGN NEEDS TO INCLUDE THE FEDERAL LEASE NUMBER NDM85863CA

Office: DK ID: DK5656  
Unique INC #: IKDW00021 Well Name: STEARNS  
Well #: 14-15H ID Date: 06/20/00  
Operator: CITATION OIL & GAS CORPORATION Effective Date: 07/06/00  
Case #: NDM85863 FAC ID: A  
Form: I FAC NAME: STEARNS 14-15H  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#7 III. B. 1. a.  
Abatement Date: 08/25/00  
Corrected Date: 07/06/00  
Followup Date: 08/29/00  
Extend Date:

Remarks Date: 06/27/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

NO WATER DISPOSAL APPROVAL. SUBMIT ON A SUNDAY NOTICE FOR APPROVAL TO DISPOSE WATER FROM THE STEARNS 14-15H.

Office: DK ID: DK5655  
Unique INC #: IKDW00020 Well Name: STEARNS  
Well #: 14-15H  
Operator: CITATION OIL & GAS CORPORATION  
Case #: NDM85863 FAC ID: A  
Form: I FAC NAME: STEARNS 14-15H  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. A. 2. a.  
ID Date: 06/20/00  
Effective Date: 07/06/00  
Abatement Date: 08/25/00  
Corrected Date: 07/05/00  
Followup Date: 08/29/00  
Extend Date:

Remarks Date: 06/27/00

NO RADIUS OF EXPOSURE FOR H2S. SUBMIT RADIUS OF EXPOSURE CALCULATIONS FOR THE 100 AND, IF APPLICABLE, THE 500 PPM RADIUS OF EXPOSURE.

Office: DK ID: DK5653  
Unique INC #: IKDW00018 Well Name: STEARNS  
Well #: 14-15H  
Operator: CITATION OIL & GAS CORPORATION  
Case #: NDM85863 FAC ID: A  
Form: I FAC NAME: STEARNS 14-15H  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. D. 3. e.  
ID Date: 06/20/00  
Effective Date: 07/06/00  
Abatement Date: 08/25/00  
Corrected Date: 07/06/00  
Followup Date: 08/29/00  
Extend Date:

Remarks Date: 06/27/00

NO WIND DIRECTION INDICATOR AT STEARNS 14-15H LOCATION. INSTALL OR REPAIR WIND DIRECTION INDICATOR AT STEARNS 14-15H LOCATION.

Office: DK ID: DK5652  
Unique INC #: IKDW00017 Well Name: STEARNS  
Well #: 14-15H  
Operator: CITATION OIL & GAS CORPORATION  
Case #: NDM85863 FAC ID: A  
Form: I FAC NAME: STEARNS 14-15H  
Assessment: \$0 Inspector: KEVIN WEILER  
Gravity: 3  
Authority Ref: 43 CFR 3164.1 OO#6 III. D. 3. a.  
ID Date: 06/20/00  
Effective Date: 07/06/00  
Abatement Date: 08/25/00  
Corrected Date: 07/06/00  
Followup Date: 08/29/00  
Extend Date:

Remarks Date: 06/27/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

NO H2S DANGER SIGN AT THE STEARNS 14-15H LOCATION. POST H2S SIGN AS REQUIRED.

Office: FE ID: iFE9774  
Unique INC #: 00DB023 Well Name: ENGLISH  
Well #: 34 ID Date: 03/22/00  
Operator: MOUNTAIN STATES PETRO CORP Effective Date: 03/31/00  
Case #: I149IND7180 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BENNALLIE Abatement Date: 04/24/00  
Gravity: 3 Corrected Date: 04/07/00  
Authority Ref: 43 CFR 3162.5-3 Followup Date:  
Extend Date:

Remarks Date: 03/24/00

You must install and maintain adequate guards around your pumping unit in accordance with API Standards to ensure the protection of health and safety of life and the protection of property.

Office: FE ID: iFE9778  
Unique INC #: 00DB027 Well Name: ENGLISH  
Well #: 21 ID Date: 03/22/00  
Operator: MOUNTAIN STATES PETRO CORP Effective Date: 03/31/00  
Case #: I149IND7180 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: BENNALLIE Abatement Date: 04/24/00  
Gravity: 3 Corrected Date: 04/07/00  
Followup Date:  
Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 03/24/00

You must install and maintain adequate guards around your pumping unit in accordance with API Standards to ensure the protection of health and safety of life and the protection of property.

Office: FE ID: iFE9937  
Unique INC #: 00GLB058 Well Name:  
Well #: ID Date: 08/31/00  
Operator: MARMAC PETROLEUM COMPANY Effective Date: 09/12/00  
Case #: 14206032034 FAC ID: A Abatement Date: 09/22/00  
Form: I FAC NAME: MANY ROCKS Corrected Date: 09/22/00  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 09/05/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

You must install and maintain at least 1 permanent wind indicator so that wind direction can be easily determined at or approaching the storage tanks(s). Currently the wind indicator is faded and worn.

Office: FE ID: iFE9935  
Unique INC #: 00GLB056 Well Name: NAV TRIBE IND F  
Well #: 121 ID Date: 08/31/00  
Operator: MARMAC PETROLEUM COMPANY Effective Date: 09/12/00  
Case #: 14206032034 FAC ID: Abatement Date: 09/22/00  
Form: I FAC NAME: Corrected Date: 09/22/00  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 09/05/00

You must install/replace and maintain adequate belt guards on your pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property (see photograph).

Office: FE ID: iFE9613  
Unique INC #: 00GLB005 Well Name: OLD TRADING POST  
Well #: 1 ID Date: 02/18/00  
Operator: DUGAN PRODUCTION CORPORATION Effective Date: 02/29/00  
Case #: 14206032085 FAC ID: Abatement Date: 03/30/00  
Form: I FAC NAME: Corrected Date: 03/15/00  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 02/22/00

You must install/replace and maintain adequate belt guards on your pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property. See attached photograph.

Office: FE ID: iFE9656  
Unique INC #: 00GLB013 Well Name:  
Well #: ID Date: 02/29/00  
Operator: HART OIL & GAS INCORPORATED Effective Date: 03/08/00  
Case #: 142060365 FAC ID: A Abatement Date: 04/07/00  
Form: I FAC NAME: Corrected Date: 04/07/00  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.7-2

Remarks Date: 03/01/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

The equipment on the lease shall be sized and maintained so as to provide proper handling of production. You must repair the top of tank #GI-7223, it's deteriorated and is caving in.

Office: FE ID: iFE9797  
Unique INC #: 00GLB043 Well Name: HGU  
Well #: 28 ID Date: 05/25/00  
Operator: CENTRAL RESOURCES INC Effective Date: 06/02/00  
Case #: NMNM78393X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LESLIE-BOB  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 07/02/00  
Corrected Date: 06/16/00  
Followup Date:  
Extend Date:

Remarks Date: 05/26/00

You must install/replace and maintain adequate belt guards on your pumping unit in accordance with API Standards to ensure the protection of health and safety of life and the protection of property (see attached picture).

Office: FE ID: iFE9798  
Unique INC #: 00GLB044 Well Name: HGU  
Well #: 57 ID Date: 05/25/00  
Operator: CENTRAL RESOURCES INC Effective Date: 06/02/00  
Case #: NMNM78393X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LESLIE-BOB  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 07/02/00  
Corrected Date: 07/02/00  
Followup Date:  
Extend Date:

Remarks Date: 05/26/00

You must install/replace and maintain adequate belt guards on your pumping unit in accordance with API Standards to ensure the protection of health and safety of life and the protection of property (see attached picture).

Office: FE ID: iFE9746  
Unique INC #: 00GLB040 Well Name: HGU  
Well #: 42 ID Date: 05/11/00  
Operator: CENTRAL RESOURCES INC Effective Date: 05/23/00  
Case #: NMNM78393X FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: LESLIE-BOB  
Gravity: 3  
Authority Ref: 43 CFR 3162.5-3  
Abatement Date: 06/22/00  
Corrected Date: 06/14/00  
Followup Date:  
Extend Date:

Remarks Date: 05/16/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

You must install/replace and maintain adequate belt guards on your pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property.

Office: FE ID: iFE9795  
Unique INC #: 00GLB041 Well Name:  
Well #:  
Operator: CENTRAL RESOURCES INC ID Date: 05/25/00  
Case #: NMNM78393X FAC ID: B-1 Effective Date: 06/02/00  
Form: I FAC NAME: TANK BATTERY B-1 Abatement Date: 07/02/00  
Assessment: \$0 Inspector: LESLIE-BOB Corrected Date: 06/15/00  
Gravity: 3 Followup Date:  
Authority Ref: 43 CFR 3162.5-3 Extend Date:

Remarks Date: 05/26/00

You must erect and maintain adequate guards around your tank battery in accordance with API Standards to ensure the protection of health and safety of life and the protection of property (see picture).

Office: FE ID: iFE9745  
Unique INC #: 00GLB039 Well Name: HGU  
Well #: 42 ID Date: 05/11/00  
Operator: CENTRAL RESOURCES INC Effective Date: 05/23/00  
Case #: NMNM78393X FAC ID: Abatement Date: 06/22/00  
Form: I FAC NAME: Corrected Date: 06/15/00  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/16/00

You must install and maintain adequate guards around your pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property.

Office: FE ID: iFE9316  
Unique INC #: 99GLB045 Well Name: GOTHIC MESA UNIT  
Well #: 7-41 ID Date: 09/22/99  
Operator: CENTRAL RESOURCES INC Effective Date: 10/01/99  
Case #: UTU68928A FAC ID: Abatement Date: 10/31/99  
Form: I FAC NAME: Corrected Date: 10/29/99  
Assessment: \$0 Inspector: LESLIE-BOB Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 09/24/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

You must maintain adequate guards around your pumping unit in accordance with API standards to ensure the protection of health and safety of life and the protection of property. The fencing (nearest Wellhead) is in need of repairs.

Office: FE		ID: iFE9322
Unique INC #: 99GLB051	Well Name:	
	Well #:	
Operator: CENTRAL RESOURCES INC		
Case #: UTU68928A	FAC ID: B	ID Date: 09/22/99
Form: I	FAC NAME:	Effective Date: 10/01/99
Assessment: \$0	Inspector: LESLIE-BOB	Abatement Date: 10/31/99
Gravity: 3		Corrected Date: 10/29/99
Authority Ref: 43 CFR 3162.5-3		Followup Date:
		Extend Date:

Remarks Date: 09/24/99

A danger sign shall be posted on or within 50 feet of the storage tanks(s) to alert the public of the potential of H2S danger. The sign shall be painted in high-visibility red, black and white. The sign shall read: DANGER-POISON GAS-HYDROGEN SULFIDE or equivalent language, where appropriate, bilingual or multilingual warning signs shall be used. Currently the sign is on the ground near tanks.

Office: FE		ID: iFE9681
Unique INC #: 00GLB019	Well Name:	
	Well #:	
Operator: EXXONMOBIL OIL CORP		
Case #: UTU68931A	FAC ID: 0008	ID Date: 02/17/00
Form: I	FAC NAME: RATHERFORD	Effective Date: 03/14/00
Assessment: \$0	Inspector: LESLIE-BOB	Abatement Date: 03/24/00
Gravity: 3		Corrected Date: 04/06/00
Authority Ref: Onshore Order #6/43 CFR 3162.5-3		Followup Date:
		Extend Date:

Remarks Date: 03/07/00

You must install and maintain at least 1 permanent wind indicator so that wind direction can be easily determined at or approaching the storage tank(s). Currently the wind indicator is fairly worn.

Office: FE		ID: FE9930
Unique INC #: 00MOW028	Well Name: NEBU	
	Well #: 311	
Operator: BURLINGTON RESOURCES O&G CO LP		
Case #: NMNM03358	FAC ID:	ID Date: 08/27/00
Form: I	FAC NAME:	Effective Date: 08/30/00
Assessment: \$0	Inspector: WADE	Abatement Date: 08/30/00
Gravity: 1		Corrected Date: 08/28/00
Authority Ref:		Followup Date:
		Extend Date:

Remarks Date: 08/30/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically when the closing valve manifold pressure has decreased to the pre-set level. Was corrected before inspector left location.

Office: FE ID: FE9928  
Unique INC #: 00MOW026 Well Name: NEBU  
Well #: 311 ID Date: 08/24/00  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 08/25/00  
Case #: NMNM03358 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref:

Remarks Date: 08/25/00

The operator is required to conduct all operations in a safe and workmanlike manner. Please check and properly secure all high pressure hoses with safety chain hobbles. Correction action started before inspector left location.

Office: FE ID: FE9929  
Unique INC #: 00MOW027 Well Name: NEBU  
Well #: 311 ID Date: 08/24/00  
Operator: BURLINGTON RESOURCES O&G CO LP Effective Date: 08/25/00  
Case #: NMNM03358 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 1  
Authority Ref:

Remarks Date: 08/25/00

Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically when the closing valve manifold pressure has decreased to the pre-set level. Was corrected before inspector left location.

Office: FE ID: FE9951  
Unique INC #: 00MOW34 Well Name: ROSA UNIT  
Well #: 153A ID Date: 09/07/00  
Operator: WILLIAMS PRODUCTION CO LLC Effective Date: 09/08/00  
Case #: NMSF078769 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref:

Remarks Date: 09/08/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Record slow pump speed on daily drilling report after mudding up.

Office: FE ID: FE9952  
Unique INC #: 00MOW033 Well Name: ROSA UNIT  
Well #: 153A  
Operator: WILLIAMS PRODUCTION CO LLC  
Case #: NMSF078769 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 1  
Authority Ref:

Remarks Date: 09/08/00

Power for the closing unit pumps shall be available to the unit at all times so that the pumps shall automatically start when the closing valve manifold pressure has decreased to the pre-set level. Was corrected before inspector left location.

Office: FE ID: FE9950  
Unique INC #: 00MOW031 Well Name: ROSA UNIT  
Well #: 153A  
Operator: WILLIAMS PRODUCTION CO LLC  
Case #: NMSF078769 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref:

Remarks Date: 09/08/00

The operator is required to conduct all operations in a safe and workmanlike manner. The automatic controls are not installed or functional. Please check and secure all high pressure hoses with safety chain hobbles. Was corrected before inspector left location.

Office: FE ID: FE9947  
Unique INC #: 00MOW029 Well Name: ROSA UNIT  
Well #: 153A  
Operator: WILLIAMS PRODUCTION CO LLC  
Case #: NMSF078769 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: WADE  
Gravity: 3  
Authority Ref:

Remarks Date: 09/08/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

The lessee/operator shall take immediate steps and use necessary resources to maintain or restore control of any well in which the pressure equilibrium has become unbalanced. The observed manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. One of two choke lines not run to pit. Was corrected before inspector left location.

Office: FE ID: FE9948  
Unique INC #: 00MOW030 Well Name: ROSA UNIT  
Well #: 153A ID Date: 09/07/00  
Operator: WILLIAMS PRODUCTION CO LLC Effective Date: 09/08/00  
Case #: NMSF078769 FAC ID: Abatement Date: 09/08/00  
Form: I FAC NAME: Corrected Date: 09/08/00  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref:

Remarks Date: 09/08/00

The lessee/operator shall take immediate steps and use necessary resources to maintain or restore control of any well in which the pressure equilibrium has become unbalanced. The observed manifold, choke, kill, and fill lines are not properly installed or operable as required by the approved APD permit. Pressure gauge on choke manifold not rated for drilling mud. Was corrected before inspector left location.

Office: FE ID: FE9949  
Unique INC #: 00MOW032 Well Name: ROSA UNIT  
Well #: 153A ID Date: 09/07/00  
Operator: WILLIAMS PRODUCTION CO LLC Effective Date: 09/08/00  
Case #: NMSF078769 FAC ID: Abatement Date: 09/08/00  
Form: I FAC NAME: Corrected Date: 09/08/00  
Assessment: \$0 Inspector: WADE Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref:

Remarks Date: 09/08/00

The operator is required to conduct all operations in a safe and workmanlike manner. The automatic controls are not installed or functional. Please check the rig floor controls, master control, and BOPE for hand wheels or autolocks. "Hand Wheels" Was corrected before

Office: HO ID: HO6374  
Unique INC #: ASC-115-00 Well Name: LOOMIS USA A  
Well #: 01 ID Date: 08/03/00  
Operator: SHACKELFORD OIL COMPANY Effective Date: 08/09/00  
Case #: NMLC070335 FAC ID: Abatement Date: 09/08/00  
Form: I FAC NAME: Corrected Date: 09/12/00  
Assessment: \$0 Inspector: ANDY CORTEZ Followup Date: 09/12/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 08/04/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

OPEN TOP FIBERGLASS TANK HAS APPROXIMATELY 2' OF OIL. DEAD BIRDS IN TANK. ---- EMPTY TANK OF FLUIDS OR SCREEN TOP OF TANK WITH MESH WIRE, WEBBING, OR OTHER SUITABLE NETTING. FAILURE TO COMPLY WITHIN THE ABATEMENT PERIOD COULD RESULT IN MONETARY ASSESSMENTS.

Office: HO ID: HO6382  
Unique INC #: ASC-122-00 Well Name:  
Well #:  
Operator: SHACKELFORD OIL COMPANY ID Date: 08/03/00  
Case #: NMLC070335 FAC ID: A Effective Date: 08/09/00  
Form: I FAC NAME: LOOMIS A BTRY Abatement Date: 09/08/00  
Assessment: \$0 Inspector: ANDY CORTEZ Corrected Date: 09/12/00  
Gravity: 3 Followup Date: 09/12/00  
Authority Ref: 43 CFR 3162.5-3 Extend Date:  
  
Remarks Date: 08/04/00  
  
LADDER AT TANKS 80706(4209) & (4210) IS NOT STABLE. -- REPAIR AND STABILIZE THE LADDER AND MAINTAIN TO PROVIDE ADEQUATE PROTECTION FOR HEALTH AND SAFETY. FAILURE TO COMPLY WITH ABATEMENT PERIOD COULD RESULT IN MONETARY ASSESSMENTS.

Office: HO ID: HO6377  
Unique INC #: ASC-117-00 Well Name:  
Well #:  
Operator: SHACKELFORD OIL COMPANY ID Date: 08/03/00  
Case #: NMLC070335 FAC ID: A Effective Date: 08/09/00  
Form: I FAC NAME: LOOMIS A BTRY Abatement Date: 09/08/00  
Assessment: \$0 Inspector: ANDY CORTEZ Corrected Date: 09/12/00  
Gravity: 3 Followup Date: 09/12/00  
Authority Ref: 43 CFR 3164.1; OOGO #6.III.D.3.e Extend Date:  
  
Remarks Date: 08/04/00  
  
OIL STORAGE FACILITY IS NOT EQUIPPED WITH OPERATIONAL WIND INDICATOR(S). -- INSTALL, REPAIR OR REPLACE WIND DIRECTION INDICATOR(S) AS NECESSARY. FAILURE TO COMPLY WITHIN ABATEMENT PERIOD COULD RESULT IN MONETARY ASSESSMENTS.

Office: HO ID: HO6065  
Unique INC #: ASC-069-00 Well Name: BC FEDERAL  
Well #: 02, 03 ID Date: 05/02/00  
Operator: MACK ENERGY CORPORATION Effective Date: 05/08/00  
Case #: NMLC029405A FAC ID: Abatement Date: 06/21/00  
Form: I FAC NAME: Corrected Date: 06/21/00  
Assessment: \$0 Inspector: Andy Cortez Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 05/04/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Electric pumping unit has unprotected counterweights. - Safeguard the pumping unit by installing guard rails or similar enclosures., Inc corrected

Office: HO ID: HO6280  
Unique INC #: ASC-095-00 Well Name: ILES FD  
Well #: 01 ID Date: 06/27/00  
Operator: WALSH & WATTS INCORPORATED Effective Date: 07/03/00  
Case #: NMLC064150 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: Andy Cortez Abatement Date: 08/01/00  
Gravity: 3 Corrected Date: 08/01/00  
Authority Ref: 43 CFR 3164.1/OO&GO #3 III.A.1.g. Followup Date: 08/01/00  
Remarks Date: 06/28/00 Extend Date:

Gas pumping unit guard rail does not isolate the motor. The flywheel is exposed. - Safeguard the pumping unit by extending the guard rails further back to isolate the flywheel.

Office: HO ID: HO5941  
Unique INC #: ASC-059-00 Well Name:  
Well #: ID Date: 03/10/00  
Operator: MIDLAND OPERATING INCORPORATED Effective Date: 03/14/00  
Case #: NMNM01124 FAC ID: A Abatement Date: 04/26/00  
Form: I FAC NAME: WILLARD BEATY BATTERY Corrected Date: 04/18/00  
Assessment: \$0 Inspector: Andy Cortez Followup Date: 04/18/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.1/OO&GO #6 III.D.3.e.

Remarks Date: 03/10/00

Wind sock is missing. - Replace the wind sock on the pole.failure to comply may result in monetary assessments.

Office: HO ID: HO5895  
Unique INC #: ASC-038-00 Well Name: FEDERAL MA  
Well #: 01 ID Date: 03/07/00  
Operator: MACK ENERGY CORPORATION Effective Date: 03/10/00  
Case #: NMNM016796 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: Andy Cortez Abatement Date: 04/24/00  
Gravity: 3 Corrected Date: 04/18/00  
Authority Ref: 43 CFR 3162.5-3 Followup Date: 04/18/00  
Remarks Date: 03/07/00 Extend Date:

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Pumping unit has exposed belts which the rail enclosers do not cover. - Install belt guards or extend the rail encloser past the motor & belts.

Office: HO ID: HO5896  
Unique INC #: ASC-039-00 Well Name:  
Well #:  
Operator: MACK ENERGY CORPORATION ID Date: 03/07/00  
Case #: NMNM016796 FAC ID: A Effective Date: 03/10/00  
Form: I FAC NAME: FEDERAL MA #1 BTRY. Abatement Date: 04/24/00  
Assessment: \$0 Inspector: Andy Cortez Corrected Date: 04/18/00  
Gravity: 3 Followup Date: 04/18/00  
Authority Ref: NTL 93 RDO/ 43 CFR 3164.2 Extend Date:  
  
Remarks Date: 03/07/00  
Exhaust stack on heater treater is not screened. - Modify the open-vent exhaust stack on the heater treater with conical screening in such a manner as to discourage birds from perching or nesting.

Office: HO ID: HO5851  
Unique INC #: ASC-035-00 Well Name:  
Well #:  
Operator: MANZANO OIL CORPORATION ID Date: 02/15/00  
Case #: NMNM0245247 FAC ID: C Effective Date: 04/05/00  
Form: I FAC NAME: EDITH FED.#3 BTRY. Abatement Date: 03/21/00  
Assessment: \$0 Inspector: Andy Cortez Corrected Date: 03/21/00  
Gravity: 3 Followup Date: 03/21/00  
Authority Ref: NTL 93 RDO/43 CFR 3164.2 Extend Date:  
  
Remarks Date: 02/23/00  
Exhaust on heater treater is not equipped with bird perching/nesting prevention equipment. - Modify the open-vent exhaust stack with conical screening in such a manner as to discourage birds from perching or nesting.

Office: HO ID: HO5850  
Unique INC #: ASC-025-00 Well Name:  
Well #:  
Operator: MANZANO OIL CORPORATION ID Date: 02/15/00  
Case #: NMNM0245247 FAC ID: A Effective Date: 04/05/00  
Form: I FAC NAME: EDITH FED.#1 BTRY Abatement Date: 03/21/00  
Assessment: \$0 Inspector: Andy Cortez Corrected Date: 03/21/00  
Gravity: 3 Followup Date: 03/21/00  
Authority Ref: NTL 93 RDO/43 CFR 3164.2 Extend Date:  
  
Remarks Date: 02/23/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

The cone on the heater treater exhaust stack is up-side down which defeats the purpose of the cone.- Reinstall the cone in the correct position. Failure to comply may result in monetary assessments.

Office: HO ID: HO5933  
Unique INC #: ASC-051-00 Well Name:  
Well #:  
Operator: J & J SERVICES INCORPORATED ID Date: 03/10/00  
Case #: NMNM04411 FAC ID: A Effective Date: 03/14/00  
Form: I FAC NAME: HAMILTON A BTRY. Abatement Date: 04/26/00  
Assessment: \$0 Inspector: Andy Cortez Corrected Date: 03/30/00  
Gravity: 3 Followup Date: 03/30/00  
Authority Ref: NTL 93-RDO/43 CFR 3164.2 Extend Date:  
  
Remarks Date: 03/10/00

Exhaust stack on the heater treater is not screened. - Modify the open vent exhaust stack with conical screening in such a manner as to discourage birds from perching or nesting.

Office: HO ID: HO5903  
Unique INC #: ASC-046-00 Well Name:  
Well #:  
Operator: MACK ENERGY CORPORATION ID Date: 03/06/00  
Case #: NMNM080258 FAC ID: A Effective Date: 03/10/00  
Form: I FAC NAME: LYNX C #2 BTRY Abatement Date: 04/24/00  
Assessment: \$0 Inspector: Andy Cortez Corrected Date: 04/18/00  
Gravity: 3 Followup Date: 04/18/00  
Authority Ref: OO&43 CFR 3164.1 / OO&GO #6 III.D.3.e. Extend Date:  
  
Remarks Date: 03/07/00

Wind sock is torn. - Replace the wind sock.

Office: HO ID: HO6093  
Unique INC #: ASC-079-00 Well Name: FEDERAL 33  
Well #: 02 ID Date: 05/08/00  
Operator: FREDONIA RESOURCES INC Effective Date: 05/10/00  
Case #: NMNM23020 FAC ID: A Abatement Date: 06/22/00  
Form: I FAC NAME: FEDERAL 33 BRTY. Corrected Date: 06/22/00  
Assessment: \$0 Inspector: Andy Cortez Followup Date: 06/22/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3  
  
Remarks Date: 05/08/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Water tank screen fell in. - Rescreen the top of the water tank.

Office: HO ID: HO6096  
Unique INC #: ASC-082-00 Well Name: FEDERAL 33  
Well #: 02 ID Date: 05/08/00  
Operator: FREDONIA RESOURCES INC Effective Date: 05/10/00  
Case #: NMNM23020 FAC ID: A Abatement Date: 06/22/00  
Form: I FAC NAME: FEDERAL 33 BRTY. Corrected Date: 06/22/00  
Assessment: \$0 Inspector: Andy Cortez Followup Date: 06/22/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 05/08/00

Battery fence is sagging & down in parts. - Restore the barbed wire fence to operational standards.

Office: HO ID: HO5970  
Unique INC #: ASC-064-00 Well Name: LM B-4 PN QN UN  
Well #: 03 ID Date: 03/20/00  
Operator: DUKE OIL & GAS INCORPORATED Effective Date: 03/27/00  
Case #: NMNM70972B FAC ID: Abatement Date: 05/04/00  
Form: I FAC NAME: Corrected Date: 04/20/00  
Assessment: \$0 Inspector: Andy Cortez Followup Date: 04/20/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5-3

Remarks Date: 03/23/00

Pumping unit has exposed belts. - Safeguard the pumping unit by extending the fence enclosures or installing the belt guards. Failure to comply may result in monetary assessments.

Office: HO ID: HO5573  
Unique INC #: ASC-098-99 Well Name:  
Well #: ID Date: 09/21/99  
Operator: SPENCE ENERGY COMPANY Effective Date: 09/21/99  
Case #: NMNM72512 FAC ID: A Abatement Date: 10/20/99  
Form: I FAC NAME: FEDERAL "25" BTRY. Corrected Date: 10/18/99  
Assessment: \$125 Inspector: Andy Cortez Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3163.1(a)

Remarks Date: 09/23/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Failure to comply with INC # ASC-069-99 to screen the heater treater exhaust. - Correct the original INC. Failure to comply may result in issuance of civil penalties.

Office: HO ID: HO5494  
Unique INC #: ASC-069-99 Well Name:  
Well #: ID Date: 08/02/99  
Operator: SPENCE ENERGY COMPANY Effective Date: 08/09/99  
Case #: NMNM72512 FAC ID: A Abatement Date: 09/21/99  
Form: I FAC NAME: FEDERAL "25" BTRY. Corrected Date: 10/18/99  
Assessment: \$0 Inspector: Andy Cortez Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3164.2 / NTL 93 RDO

Remarks Date: 08/04/99

Exhaust stack on the horizontal heater treater is not equipped with bird perching/nesting equipment. - Modify the open-vent exhaust stack with conical screening in such a manner as to discourage birds from perching or nesting.

Office: HO ID: HO6152  
Unique INC #: PAH-032-00 Well Name: ELLIOTT B-17  
Well #: 02 ID Date: 05/25/00  
Operator: CONOCO INCORPORATED Effective Date:  
Case #: NMLC032573B FAC ID: Abatement Date: 06/14/00  
Form: I FAC NAME: Corrected Date: 06/19/00  
Assessment: \$0 Inspector: Patricia Hutchings Followup Date: 06/19/00  
Gravity: 3 Extend Date:  
Authority Ref: 00&G0 #6 III.D.3.e

Remarks Date: 05/25/00

OIL STORAGE FACILITY OPERATIONAL WIND INDICATOR NEEDS TO BE REPLACED. INSTALL, REPAIR, OR REPLACE WIND INDICATOR AS NECESSARY.

Office: HO ID: HO6103  
Unique INC #: PAH-021-00 Well Name: CP FALBY B  
Well #: 01 ID Date: 05/09/00  
Operator: TEXACO EXPLORATION & PROD INC Effective Date:  
Case #: NMLC033706B FAC ID: Abatement Date: 06/09/00  
Form: I FAC NAME: Corrected Date: 06/01/00  
Assessment: \$0 Inspector: Patricia Hutchings Followup Date: 06/01/00  
Gravity: 3 Extend Date:  
Authority Ref: 43CFR 3162.5-3

Remarks Date: 05/09/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

TWO IDLE STOCK TANKS ARE STORED ON THIS LOCATION. THE SOUTH STOCK HAS THE HATCH DOOR OFF ON THE GROUND CAUSING SOME SAFETY CONCERNS. THE NORTH TANK HAS ONE BOLT HOLDING THE HATCH ON. INSTALL THE HATCH ON THE SOUTH TANK AND SECURE THE HATCH ON THE NORTH TANK.

Office: HO ID: HO6113  
Unique INC #: PAH-026-00 Well Name:  
Well #: ID Date: 05/12/00  
Operator: ZIA ENERGY INCORPORATED Effective Date:  
Case #: NMLC061446 FAC ID: A Abatement Date: 06/12/00  
Form: I FAC NAME: PENROSE FED. Corrected Date: 06/05/00  
Assessment: \$0 Inspector: Patricia Hutchings Followup Date: 06/05/00  
Gravity: 3 Extend Date:  
Authority Ref: 43 CFR 3162.5

Remarks Date: 05/12/00

THE NORTH 500 BBL STORAGE OVERFLOW STOCK TANK HAS HOLES ON THE TOP. REPAIR THE HOLES ON THE TOP OF THE OVERFLOW STORAGE STOCK TANK.

Office: HO ID: HO6151  
Unique INC #: PAH-031-00 Well Name:  
Well #: ID Date: 05/24/00  
Operator: SDX RESOURCES INCORPORATED Effective Date:  
Case #: NMNM0557256 FAC ID: B Abatement Date: 06/14/00  
Form: I FAC NAME: ELLIOTT B-20 BTRY Corrected Date: 06/19/00  
Assessment: \$0 Inspector: Patricia Hutchings Followup Date: 06/19/00  
Gravity: 3 Extend Date:  
Authority Ref: 00&GO #6 III. D.3.e

Remarks Date: 05/24/00

OIL STORAGE FACILITY IS NOT EQUIPPED WITH OPERATIONAL WIND DIRECTION INDICATOR(S). INSTALL, REPAIR, OR REPLACE WIND DIRECTION INDICATOR(S) AS NECESSARY.

Office: HO ID: HO5653  
Unique INC #: PAH-007-00 Well Name:  
Well #: ID Date: 12/03/99  
Operator: GRUY PETROLEUM MANAGEMENT CO Effective Date:  
Case #: NMNM90799 FAC ID: B Abatement Date: 12/23/99  
Form: I FAC NAME: TERRA CARLSON B Corrected Date: 12/18/99  
Assessment: \$0 Inspector: Patricia Hutchings Followup Date:  
Gravity: 3 Extend Date:  
Authority Ref: 00&GO #6 D 3 e.

Remarks Date: 03/22/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

FOLLOW UP INSPECTION. WIND SOCK HAS BEEN INSTALLED AT THE TANK BATTERY., There are H2S warning signs posted at this battery but there is no wind indicator. Install a wind indicator at the battery. After completion of work notify Patricia Hutchings at the above phone number for follow up inspection.

Office: HO		ID: HO5654
Unique INC #: PAH-008-00	Well Name:	
	Well #:	
Operator: GRUY PETROLEUM MANAGEMENT CO		
Case #: NMNM90799	FAC ID: B	ID Date: 12/03/99
Form: I	FAC NAME: TERRA CARLSON B	Effective Date: 12/03/99
Assessment: \$0	Inspector: Patricia Hutchings	Abatement Date: 12/03/99
Gravity: 1		Corrected Date: 12/03/99
Authority Ref: OO&GO #3 III.A.1.b		Followup Date: 12/04/99
		Extend Date:

Remarks Date: 12/03/99

PIPELINE SEAL IS BROKEN ON OIL STORAGE TANK #74542. REPLACE THE SEAL IMMEDIATELY. NOTIFY PATRICIA HUTCHINGS AT THE ABOVE PHONE NUMBER WITH THE SEAL THAT HAS BEEN INSTALLED.

Office: JA		ID: JA1535
Unique INC #: JCC00035	Well Name: SKUNKAROMA	
	Well #: 3-19	
Operator: RANKEN ENERGY CORPORATION		
Case #: ARES12035	FAC ID:	ID Date: 08/18/00
Form: I	FAC NAME:	Effective Date: 08/24/00
Assessment: \$0	Inspector: COOPER	Abatement Date: 09/22/00
Gravity: 3		Corrected Date: 09/14/00
Authority Ref: ONSHORE ORDER #6 III 3.e.		Followup Date:
		Extend Date:

Remarks Date: 08/18/00

INSTALL A WIND DIRECTION INDICATOR (COMMERCIAL TYPE) AT WELL AS REQUIRED

Office: JA		ID: JA1534
Unique INC #: JCC00034	Well Name:	
	Well #:	
Operator: RANKEN ENERGY CORPORATION		
Case #: ARES12035	FAC ID: A	ID Date: 08/18/00
Form: I	FAC NAME: SKUNKAROMA	Effective Date: 08/24/00
Assessment: \$0	Inspector: COOPER	Abatement Date: 09/22/00
Gravity: 3		Corrected Date: 09/14/00
Authority Ref: ON SHORE ORDER #6 III 3.e.		Followup Date:
		Extend Date:

Remarks Date: 08/18/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

INSTALL A WIND DIRECTION INDICATOR (COMMERCIAL TYPE) AT FACILITY AS REQUIRED

Office: ML ID: iML2864  
Unique INC #: JB383-3 Well Name:  
Well #:  
Operator: CONTINENTAL RESOURCES INC ID Date: 06/28/00  
Case #: 142002564932 Effective Date: 06/28/00  
Form: I FAC ID: A Abatement Date: 07/28/00  
Assessment: \$0 FAC NAME: GREY BEAR/DARLENE Corrected Date: 07/05/00  
Gravity: 3 Inspector: John Bramhall Followup Date: 07/12/00  
Authority Ref: 43 CFR 3164.1 Onshore Order #6 III.D.1.c. Extend Date:  
Remarks Date: 07/03/00

Ignitor for flare stack is not sparking to ignite gas being vented to pit. Gas containing H2S must be flared. Monthly Report of Operations Form 3160 that is submitted to Minerals Management Service (MMS) needs to show the amount of gas produced, used on lease and flared/vented.

Office: ML ID: iML2771  
Unique INC #: JB366-1 Well Name:  
Well #:  
Operator: MURPHY EXPLORATION & PROD CO ID Date: 10/27/99  
Case #: 14200256CA11 Effective Date: 10/28/99  
Form: I FAC ID: A Abatement Date: 11/19/99  
Assessment: \$0 FAC NAME: #1H ZIMMERMAN Corrected Date: 11/02/99  
Gravity: 3 Inspector: John Bramhall Followup Date: 11/09/99  
Authority Ref: 43 CFR 3164.1 ONSHORE ORDER #6 III.D.1. Extend Date:  
Remarks Date: 11/02/99

NO IGNITOR ON THE FLARE STACK AT THIS COMMON CENTRAL BATTERY PIT. GAS IS BEING VENTED WITH AN AMBIENT H2S OF 121 PPM.  
GAS THAT CONTAINS H2S MUST BE BURNED. INSTALL EQUIPMENT NECESSARY TO BURN THE GAS USING A SUITABLE AND SAFE  
IGNITION.

Office: ML ID: iML2766  
Unique INC #: JB364-1 Well Name:  
Well #:  
Operator: MURPHY EXPLORATION & PROD CO ID Date: 10/28/99  
Case #: 14200256CA18 Effective Date: 10/28/99  
Form: I FAC ID: A Abatement Date: 11/08/99  
Assessment: \$0 FAC NAME: #10-1 REID Corrected Date: 11/02/99  
Gravity: 3 Inspector: John Bramhall Followup Date: 11/09/99  
Authority Ref: 43 CFR 3164.1 ONSHORE ORDER #6 III.D.1.c. Extend Date:  
Remarks Date: 11/02/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

IGNITOR ON FLARE STACK IS NOT OPERABLE. GAS AT THIS LOCATION MUST BE FLARED BECAUSE H2S = 900 PPM. REPAIR SYSTEM AS NEEDED FOR CONTINUOUS ABILITY TO FLARE THE GAS.

Office: ML ID: iML2840  
Unique INC #: JB381-2 Well Name:  
Well #:  
Operator: JN EXPL & PROD LTD PTNRSHIP ID Date: 05/18/00  
Case #: 14200256CA51 Effective Date: 05/19/00  
Form: I FAC ID: A Abatement Date: 06/21/00  
Assessment: \$0 FAC NAME: HARMON #41-18 Corrected Date: 05/25/00  
Gravity: 3 Inspector: John Bramhall Followup Date: 07/03/00  
Authority Ref: Onshore Order No. 6 III.D.3.a. Extend Date:

Remarks Date: 05/19/00

No H2S signs visible on location. Danger signs shall be posted on or within 50 feet of each production facility to alert the public of the potential H2S danger.

Office: ML ID: iML2839  
Unique INC #: JB381-1 Well Name:  
Well #:  
Operator: JN EXPL & PROD LTD PTNRSHIP ID Date: 05/18/00  
Case #: 14200256CA51 Effective Date: 05/19/00  
Form: I FAC ID: A Abatement Date: 06/21/00  
Assessment: \$0 FAC NAME: HARMON #41-18 Corrected Date: 05/25/00  
Gravity: 3 Inspector: John Bramhall Followup Date: 07/03/00  
Authority Ref: Onshore Order No. 6 III.D.2.e. Extend Date:

Remarks Date: 05/19/00

No wind indicator installed at this facility. Sock and frame laying on tubing pile by stock tanks. Called JN production supervisor at Billings about sock and sign(s) not installed. At least 1 permanent wind direction indicator shall be installed so that wind direction can be easily determined at or approaching the storage tanks.

Office: ML ID: ML2737  
Unique INC #: JB362-2 Well Name:  
Well #:  
Operator: AUTRY C STEPHENS ID Date: 09/22/99  
Case #: CANCR607 Effective Date: 10/07/99  
Form: I FAC ID: A Abatement Date: 11/07/99  
Assessment: \$0 FAC NAME: #6-12 BATTERY Corrected Date: 10/15/99  
Gravity: 3 Inspector: John Bramhall Followup Date: 10/18/99  
Authority Ref: 43 CFR 3164.1 Onshore Order #6 III.D.3.e. Extend Date:

Remarks Date: 09/28/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

No wind direction indicator. At least 1 permanent wind indicator shall be installed so that wind direction can be easily determined at or approaching the storage tank(s).

Office: ML ID: ML2792  
Unique INC #: JB375-1 Well Name:  
Well #:  
Operator: LOUIS DREYFUS NATURAL GAS CORP ID Date: 11/16/99  
Case #: CANCR689 Effective Date: 11/17/99  
Form: I FAC ID: A Abatement Date: 12/17/99  
Assessment: \$0 FAC NAME: HOLJE OIL FACILITY Corrected Date: 11/29/99  
Gravity: 3 Inspector: John Bramhall Followup Date: 11/29/99  
Authority Ref: 43 CFR 3164.1 Extend Date:  
ONSHORE ORDER #6 III.D.3.a&e.

Remarks Date: 11/19/99

H2S concentration was measured at 120 ppm in the gas stream on 11/16/99. Danger sign(s) must be posted within 50 feet of each facility and at least 1 wind direction indicator shall be installed so that wind direction can be easily determined at or approaching the facility.

Office: PD ID: PD985  
Unique INC #: 00JJ30 Well Name: B  
Well #: 144-25 ID Date: 09/01/00  
Operator: EOG RESOURCES INCORPORATED Effective Date: 09/01/00  
Case #: WYW10678 FAC ID: Abatement Date: 09/01/00  
Form: I FAC NAME: Corrected Date: 09/01/00  
Assessment: \$0 Inspector: John James Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: OSO #2 III.A.1.

Remarks Date: 09/05/00

Dart valve was closed on the rig floor

Office: PD ID: PD984  
Unique INC #: 00JJ29 Well Name: B  
Well #: 144-25 ID Date: 09/01/00  
Operator: EOG RESOURCES INCORPORATED Effective Date: 09/01/00  
Case #: WYW10678 FAC ID: Abatement Date: 09/01/00  
Form: I FAC NAME: Corrected Date: 09/01/00  
Assessment: \$0 Inspector: John James Followup Date:  
Gravity: 1 Extend Date:  
Authority Ref: OSO #2 III.A.2.h.

Remarks Date: 09/05/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

No air to the remote on floor

Office: PD ID: PD983  
Unique INC #: 00JJ28 Well Name:  
Well #:  
Operator: EOG RESOURCES INCORPORATED  
Case #: WYW10678 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: John James  
Gravity: 3  
Authority Ref: OSO #2 III.A.1.

Remarks Date: 09/05/00  
Kill line not hooked up.valve handles missing

Office: RW ID: RW2104  
Unique INC #: CT-026-R00 Well Name: DUDLEY FEDERAL  
Well #: 7-20  
Operator: DUDLEY & ASSOCIATES LLC  
Case #: WYW117374 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: 43 CFR 3162.6 (a) (b)

Remarks Date: 11/23/99  
No well identification sign on lease. Put well identification sign in a conspicuous place on the lease.

Office: RW ID: RW2105  
Unique INC #: CT-027-R00 Well Name: DUDLEY FEDERAL  
Well #: 7-20  
Operator: DUDLEY & ASSOCIATES LLC  
Case #: WYW117374 FAC ID:  
Form: I FAC NAME:  
Assessment: \$0 Inspector: THOMAS  
Gravity: 3  
Authority Ref: 43 CFR 3162..5-1 (a)(b)(c)

Remarks Date: 11/23/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Remove casing, pipe, cut off drilling line, pipe thread protectors and front end loader bucket from the drill site.

Office: TU ID: iTU19968  
Unique INC #: LK00040 Well Name:  
Well #:  
Operator: NBI SERVICES INC ID Date: 12/09/99  
Case #: 142002071424 Effective Date: 12/16/99  
Form: I Abatement Date: 01/06/00  
Assessment: \$0 FAC ID: A Corrected Date: 12/14/99  
Gravity: 3 FAC NAME: WHITE Followup Date: 12/14/99  
Authority Ref: 43CFR3162.5-3 Inspector: KEYES Extend Date:  
  
Remarks Date: 12/09/99  
Please remove water from the bermed area. When fresh water accumulates in the bermed area it must be removed for health and safety.

Office: TU ID: iTU19944  
Unique INC #: LK00016 Well Name:  
Well #:  
Operator: CRAWLEY PETROLEUM CORPORATION ID Date: 10/22/99  
Case #: 1420020762 Effective Date: 10/29/99  
Form: I Abatement Date: 11/29/99  
Assessment: \$0 FAC ID: A Corrected Date: 11/01/99  
Gravity: 3 FAC NAME: S CRY Followup Date: 11/01/99  
Authority Ref: 43CFR3162.5-3 Inspector: KEYES Extend Date:  
  
Remarks Date: 10/22/99  
The catwalk on the tank battery is missing an end rail, please install.

Office: TU ID: iTU19924  
Unique INC #: LK00002 Well Name:  
Well #:  
Operator: BECKER CLYDE M ID Date: 10/15/99  
Case #: 1420207236 Effective Date: 10/21/99  
Form: I Abatement Date: 11/21/99  
Assessment: \$0 FAC ID: A Corrected Date: 10/29/99  
Gravity: 3 FAC NAME: STANDSBLACK Followup Date: 10/29/99  
Authority Ref: 43CFR3162.5-3 Inspector: KEYES Extend Date:  
  
Remarks Date: 10/15/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

A rung on your tank battery ladder is split, please replace or repair.

Office: TU ID: TU20180  
Unique INC #: LK-00077 Well Name:  
Well #:  
Operator: MEDALLION PRODUCTION COMPANY  
Case #: OKNM74536 FAC ID: A  
Form: I FAC NAME: HERALD 2  
Assessment: \$0 Inspector: KEYES  
Gravity: 3  
Authority Ref: 43CFR3162.5-3  
Remarks Date: 08/11/00  
Please remove oil film from oil tank, ladder and catwalk.

Office: TU ID: iTU19982  
Unique INC #: LK00053 Well Name:  
Well #:  
Operator: HEGCO CANADA INCORPORATED  
Case #: OKNM78512B FAC ID: C  
Form: I FAC NAME: ALBERTA BATTER PA-B  
Assessment: \$0 Inspector: KEYES  
Gravity: 3  
Authority Ref: 43CFR3162.5-3  
Remarks Date: 01/06/00  
Please install belt guards on your pump jacks #4 and #9.

Office: TU ID: iTU19970  
Unique INC #: LK00042 Well Name:  
Well #:  
Operator: R C TAYLOR COMPANIES INC  
Case #: OKNM78521X FAC ID: A  
Form: I FAC NAME: NW CERES  
Assessment: \$0 Inspector: KEYES  
Gravity: 3  
Authority Ref: 43CFR3162.5-3  
Remarks Date: 12/10/99

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Please install an end rail on your cat walk.

Office: TU ID: iTU19936  
Unique INC #: LK00008 Well Name:  
Well #:  
Operator: CRAWLEY PETROLEUM CORPORATION ID Date: 10/22/99  
Case #: OKNM78785 FAC ID: A Effective Date: 10/29/99  
Form: I FAC NAME: BUFFALOHEAD 1 Abatement Date: 11/29/99  
Assessment: \$0 Inspector: KEYES Corrected Date: 11/01/99  
Gravity: 3 Followup Date: 11/01/99  
Authority Ref: 43CFR3162.5-3 Extend Date:

Remarks Date: 10/22/99

Railing on catwalk ladder is not anchored,Please repair.

Office: TU ID: iTU19985  
Unique INC #: DAM-02 Well Name:  
Well #:  
Operator: YARHOLA PRODUCTION COMPANY ID Date: 01/13/00  
Case #: 62849A FAC ID: A Effective Date: 01/18/00  
Form: I FAC NAME: FELIX Abatement Date: 02/13/00  
Assessment: \$0 Inspector: MELTON Corrected Date: 03/20/00  
Gravity: 3 Followup Date: 03/13/00  
Authority Ref: 43 CFR 3160 Extend Date:

Remarks Date: 01/13/00

Tank Battery has high H2S vapors at times,Wind socks,H2S warning signs,6 foot chain link fence with a locked gate needs to be installed to keep out unauthorized personnel., follow up

Office: WO ID: WO1768  
Unique INC #: 010-00-030 Well Name:  
Well #:  
Operator: MARKUS PRODUCTION INC ID Date: 02/01/00  
Case #: WYW7168 FAC ID: A Effective Date: 02/02/00  
Form: I FAC NAME: UHLS Abatement Date: 02/04/00  
Assessment: \$0 Inspector: UHLS Corrected Date: 02/05/00  
Gravity: 1 Followup Date: 02/14/00  
Authority Ref: O.O.#4 III.C.1.c. ## CFR 3164.1 Extend Date:

Remarks Date: 02/03/00

Safety and Drilling Related Violations (INCs) Issued During FY 2000  
As of March 3, 2011

Sales tanks must be equiped with a vent line valve. Requirements of Onshore Order # 4 are not being met. You have 24 hrs from receipt of this notice to correct this violation. (See photo).

Office: WO	Well Name:	ID: WO1767
Unique INC #: 010-00-029	Well #:	ID Date: 02/01/00
Operator: MARKUS PRODUCTION INC	FAC ID: A	Effective Date: 02/02/00
Case #: WYW7168	FAC NAME:	Abatement Date: 02/04/00
Form: I	Inspector: UHLS	Corrected Date: 02/05/00
Assessment: \$0		Followup Date: 02/05/00
Gravity: 1		Extend Date:
Authority Ref: O.O.#4 III.C.1.c. ## CFR 3164.1		

Remarks Date: 02/03/00

Tank #92844 thief hatch is not in the closed position. Requirements of Onshore Order # 4 and not being met. You have 24 hrs from receipt of this notice to correct this violation. (See photo).

Feb-26-01 04:44pm

From-MARATHON OIL

(June 1990)

**DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

+9155646489

T-632 P.02/05 F-647

U.S. GOVERNMENT PRINTING OFFICE: 1994-0155

Expires: March 31, 1993

**SUNDAY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.

**SUBMIT IN TRIPPLICATE**

## 1. Type of Well

<input type="checkbox"/> Oil	<input checked="" type="checkbox"/> Gas
<input type="checkbox"/> Well	<input checked="" type="checkbox"/> Well
<input type="checkbox"/> Other	

## 2. Name of Operator

Marathon Oil Company

## 3. Address and Telephone No.

P.O. Box 196168, Anchorage, AK 99519-6168, (907)561-5311

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

At surface:

✓ 1164' FNL, 1487' FWL, Sec. 34, T7N, R10W, S.M.

## 7. If Unit or CA, Agreement Designation

Beaver Creek Unit

## 8. Well Name and No.

BC-6

## 9. API Well No.

50-133-20346

## 10. Field and Pool, or Exploratory Area

Beaver Creek Field, Tyonek

## 11. County or Parish, State

Kenai Borough

## 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

- Notice of Intent  
 Subsequent Report  
 Final Abandonment Notice

## TYPE OF ACTION

- Abandonment  
 Recompletion  
 Plugging Back  
 Casing Repair  
 Altering Casing  
 Other \_\_\_\_\_

- Change of Plans  
 New Construction  
 Non-Routine Fracturing  
 Water Shut-Off  
 Conversion to Injection  
 Dispose Water

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Marathon proposes to fracture stimulate the Tyonek formation in well BC-6 in order to increase production from the existing pay.  
 Preliminary pumping work is expected to begin on March 6, 2001, but the actual fracture stimulation will probably commence around March 17. A detailed procedure and wellbore schematic is attached.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

Gary Eller

TITLE Production Engineer

DATE February 26, 2001

(This space for Federal or State office use)

APPROVED BY

TITLE

P.E.

DATE

3/5/01

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

**Well BC-6, Beaver Creek Field  
AFE 8102901  
Fracture Stimulate the Tyonek Sand**

**Purpose:** Fracture stimulate the Tyonek Sand in well BC-6 to increase production rate.

**Procedure:**

1. Lay down seamless, impermeable liner and felt on the drilling pad as per the attached schematic. The frac tanks and frac iron will be placed on one section of pad, and the flowback tanks and flowback iron will be placed on a separate section of liner.
2. Move in two 500-bbl horizontal frac tanks and spot on the liner. Prior to arrival in the field, the tanks should be hydrostatic tested and visually inspected for cleanliness, adequate access to hatches, adequate valving, and having plugs in all outlets.
3. Move in the sand silo and spot on the liner.
4. Move in the flowback manifold and the flowback tank onto the liner as per the attached diagram. The flowback tank should be at least 150-bbl capacity, closed top, and be equipped with adequate access for vessel cleaning. It should be equipped with three 602 thread-half fittings and diffuser plates where the flowback lines will tie into. The flowback manifold (see attached) is a 2", 5M, 5-way manifold. The flowlines will be 2-3/8" tubing with 602 and/or 1502 fittings. The flowline segments should have pollution containment at least at every joint. RU to the wing valve and pressure test lines to 5000 psi using diesel.
5. Load the sand silo with the designated amount and type of proppant.
6. Move-in and install 4" wooden sills around the edge of the entire lined area to provide a berm. Lap the top of the liner over the sills and tack the liner in place with strips of timbers. Leave a portion of the berm removable where the diesel tanks and frac iron will have access when necessary.
7. Fill frac tanks with the designated amount and type of diesel (initial estimate = 700 bbl). Watch for drips and leaks in the frac tanks during the loading operation. Check the tank level routinely during filling operations. Leave at least 1' of each tank unfilled. Adequate sorbents should be on hand during the filling operation, and for the remainder of the job. After releasing the diesel delivery trucks, replace wooden sills to complete the berm. Accurately record the volume of diesel in each frac tank.
8. MIRU BJ pump truck onto the tree top of BC-6. Tie-in radioactive tracer supply on the low-pressure side of the pump truck. Pressure test lines to 5000 psi. Ready equipment to record treating and falloff pressure data. Pump diesel (volume to be determined) tagged

Well BC-6  
Beaver Creek Field  
AFE 8102901  
Page 2

with radioactive tracer down the tubing of well BC-6. Cut off tracer and flush with diesel to the top perf. RDMO pump truck and tracer hand. Strap the remaining volume of diesel in the frac tanks.

9. MIRU slickline unit. Pressure test BOPE to 3000 psi. RIH with gauge ring to TD. POOH. RIH with gamma ray/CCL log to TD, and log across entire perforated section. POOH, RDMO slickline. Send log data to Anchorage engineer.
10. Reload frac tanks with diesel if needed.
11. Mob frac iron and tree saver onto liner of well BC-6. Finish installing berming material at this point if there is any remaining to be done.
12. MIRU hot oil truck. Position hot oil truck as far away from diesel frac tanks as is feasible. RU the hot oil truck to circulate diesel from one of the frac tanks. Heat the diesel in the frac tank from ambient temperature to 90° F. Repeat this process for each frac tank. RDMO hot oil truck.
13. Mob frac personnel, tree saver personnel, flowback personnel, and fire fighting personnel. Install 3½", 10K tree saver on well BC-6 and test to 9500 psi. Pump diesel based frac stimulation down well BC-6 as per separate procedure. When finished, bleed surface pressure below 4000 psi and RDMO tree saver. RDMO frac crew and frac iron. Release fire fighting crew and tree saver crew. Strap remaining volume of diesel in frac tanks. Use a roustabout crew to cleanup any diesel spillage as early as practical.
14. As soon as is practical, initiate flowback of well BC-6 through the frac manifold. Flowback should be fairly aggressive since the frac fluid will not be energized with nitrogen. Continue flowback as per instructions on the Production Engineer. When the well is cleaned up sufficiently, RDMO flowback iron. Turn well over to the Production Department to produce. Clean the flowback tank adequately for transport, and ship any exempt waste (i.e. proppant, diesel, produced water, etc.) to the G&I plant for disposal.

BC - 6

FMC Hanger (8.8 25.4, OD:10.650, ID:2.992)

Tubing (0.0-8988.0, OD:3.500, ID:2.992)

Production Casing (0.0-12410.0, OD:9.625, Wt:47.00)

Intermediate Casing (0.0-4022.0, OD:13.375, Wt:89.00)

Camco Injection Mandrel (887.5-894.5, OD:5.890, ID:2.992)

80-40 K-Anchor (5909.9-5911.0, OD:4.750, ID:3.250)  
Bakor 194 SAB 4DXS2 Packer (5911.0-6916.4, OD:8.125, ID:3.250)

Camco X Nipple (6965.9-6967.3, OD:3.850, ID:2.813)

B-15 (7010)  
 B-18 (7050)  
 B-16L (7130)  
 B-17 (7195)  
 B-18 (7260)  
 B-19 (7350)  
 B-20 (7460)  
 B-21 (7520)  
 B-23 (7620)  
 B-24 (7800)

Camco X Nipple (8931.9-8962.8, OD:4.050, ID:2.813)

Wireline Reentry Guide (8997.5-8998.0, OD:3.867, ID:2.992)

Perf (0120.0-0155.0)

U. Tyonek (9120)

Perf (9866.0-9966.0)

D-1 (9856)

Fill (10366.0-10400.0, OD:8.625)

F:11 Q 10,370' M3 (5/24/97)

Retainer (10400.0-10406.0, OD:8.981)

Retainer (11200.0-11210.0, OD:8.981)

Cement (11360.0-11446.0, OD:8.625)

Packer (11446.0-11453.0, OD:8.981)

Cement (11446.0-11560.0, OD:6.188)

Production Liner (11446.0-14980.0, OD:7.000, Wt:52.00)

Cement (14447.0-14847.0, OD:6.188)

Bridge Plug (14647.0-14653.0, OD:6.184)

Production Liner (14681.0-15889.0, OD:5.000, Wt:18.00)

Cement (15280.0-15280.0, OD:4.016)

Bridge Plug (15280.0-15286.0, OD:4.016)